Available from National Technical Information Service Springfield, Virginia 22161

# Title List of Documents made Publicly Available

June 1 - 30, 1979

Division of Technical Information and Document Control Office of Administration U.S. Nuclear Regulatory Commission Washington, D.C. 20555



# CONTENTS

Preface	ν
Airangements of Items by Docket Number	ıx
Arrangement of Docket 50 Facility Name	xix
Docketed Items	1
Low Level Radwaste Disposal Sites - Docket 27	1
Domestic Licensing of Source Material - Docket 40	1
Domestic Licensing of Production and Utilization Facilities - Docket 50	3
Domestic Licensing of Special Nuclear Material - Docket 70	231
Packaging of Radioactive Material for Transport and Transportation of Radioactive Material Under Certain Conditions - Docket 71	241
Nondocketed Items	
ACRS — Advisory Committee on Reactor Safeguards COMMISSION — NRC Commissioners CONTRACT — NRC Contracts and Modifications. FOIA — Freedom of Information Act Requests and Releases GEN TECH IS — Generic Technical Issues I&E — Inspection and Enforcement NUREG — NUREG Reports and Related Correspondence ORG — Correspondence with other organizations PR — Proposed Rule PRM — Petition for Rulemaking PROJ — Projects-Predocket Licensing PT21 — Noncompliance Reports and Related Correspondence QA999 — Quality Assurance Inspections REGGD — Regulatory Guides RES — Research and Technical Assistance Reports REVIEW GRP — NRC Research Review Groups RM — Rulemakings SECY — Position Papers Before the Commission TOPREP — Vendor Reports and Related Correspondence WASTE MGT — Nuclear Waste Management XPORTLIC — Export and Import Licenses	253 254 256 257 260 261 264 268 270 275 277 278 278 278 281 283
Personal Author Index	293
Corporate Source Index - By Corporate Types	335
Citizen Group/Individual/Media	335
Engineering/Construction/Consultants/Services	355
Educational Institutions	336

# CONTENTS (Cont'd.)

Foreign Governments and Agencies	337
Legal/Law Firms/Insurance Companies	337
Local Government and Agencies	339
Medical Institutions and Laboratories	339
Manufacturers/Equipment and Supplies	339
Professional/Industrial Institutions, Societies	341
State Governments and Agencies	341
U.S. Federal Government and Agencies	342
Utilities, Holding Companies, Investor Associations	343
Research Institutions and Laboratories	356
U.S. Nuclear Regulatory Commission Organizational Source Index 3	359
Report Number Index 3	
Appendix A - Definitions of Docket 50 Categories	
Appendix B - Definitions of Nondocketed Categories	95

#### **PREFACE**

The Title List of Documents Made Publicly Available is a monthly publication. It contains descriptions of the information received and generated by the U.S. Nuclear Regulatory Commission (NRC). This information includes (1) docketed material associated with civilian nuclear power plants and other uses of radioactive materials and (2) nondocketed material received and generated by NRC pertinent to its role as a regulatory agency. As used here, docketed does not refer to Court dockets; it refers to the system by which NRC maintains its regulatory records. This series of documents is indexed by a Personal Author Index, a Corporate Source Index, and a Report Number Index.

The docketed information includes the information formerly issued through the Department of Energy's Technical Information Center under the title *Power Reactor Docket Information* (PRDI) and, in addition, information received or generated on other uses of radioactive materials. The last issue of PRDI, published in January 1979, was an annual cumulation of the information for 1978. The *Title List* series initiated by this document replaces PRDI, which will no longer be prepared. Plans for providing microfiche of the docketed material will be announced in a future issue of the *Title List* and in other mailings and announcements.

We are making the monthly issues produced in 1979 available free to all who subscribed to PRDI in Calendar Year 1978. We are doing this to encourage your comments, criticisms, and suggestions. In particular, if there are title descriptions that are not meaningful, please let us know so that we can correct the data base. In so far as possible, we would like this document to be a valuable part of your reference material. Near the end of 1979, subscriptions will be solicited for Calendar Year 1980 at a fee yet to be established.

#### DOCKETED ITEMS

Beginning with Vol. 1, No. 4, the listings within dockets are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories are:

- A. Application/construction stage documents and correspondence
- B. Utility Preliminary Safety Analysis Report (PSAR), amendments
- C. Utility Environmental Report (ER), amendments and correspondence
- D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), and correspondence
- E. NRC Safety Evaluation Report (SER), supplements and correspondence
- F. Security, medical, emergency and fire-protection plans
- G. Adjudicatory correspondence
- H. General correspondence
- I. Financial information
- J. Insurance and indemnity information
- K. Utility Final Safety Analysis Report (FSAR) and amendments
- L. Limited work authorization and related correspondence
- M. Antitrust correspondence
- N. Antitrust hearing transcripts
- O. Advisory Committee on Reactor Safeguards (ACRS) reports and correspondence
- P. Operating license stage documents and correspondence

- Q. Inspection reports, IE Bulletins and correspondence
- R. Periodic operating reports and related correspondence
- S. Reportable occurrences, LERs and related correspondence
- T. Hearing transcripts on non-antitrust matters


Appendix A sets forth those categories and describes the materials available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the entries in the list are:

1) P. Operating license stage documents & correspondence

7904170015 Forwards info on TMI:JM Hendrie 790410 testimony, preliminary chronology of NRC actions, description of events & generic consideration

REHM, T.A. Office of the Executive Director for Operations.



- 1. NRC/PDR Document category (see Appendix A).
- 2. NRC Accession Number
- 3. Description of information contained in the document
- 4. Personal author. An asterisk in this position indicates that there is no personal author.
- 5. Corporate, agency or nonindividual source

of incident.

- 6. Date of document described
- 7. Pages in document
- 8. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or "Available at GPO."

The Docketed Items list is arranged sequentially by Docket Number, category, and then by date of principal items. Entries indented and preceded by a dash are items that were submitted as enclosures to principal items. In general, indented items are not in accession number sequence. If the docketed document has a contract (FIN) number or a formal report number, it will appear in the last line of the item following entry 5.

#### NONDOCKETED ITEMS

Beginning with Vol. 1, No. 6, the nondocketed items are divided into the categories used for filing and searching in the NRC Public Document Room. Those categories and their symbols are:

10CFR - Commission Meeting Records

ACRS - Advisory Committee on Reactor Safeguards

AGREEMENT - State Agreements and Programs

COMMISSION - NRC Commissioners

CONTRACT - NRC Contracts and Modifications

FOIA - Freedom of Information Act Requests and Releases

GEN TECH IS - Generic Technical Issues

1&E - Inspection and Enforcement

NUREG - NUREG Reports and Related Correspondence

ORG - Correspondence with other organizations

PR - Proposed Rule

PRM - Petition for Rulemaking

PROJ - Projects-Predocket Licensing

PT21 - Noncompliance Reports and Related Correspondence

٧i

QA999 — Quality Assurance Inspections
REGGD — Regulatory Guides
RES — Research and Technical Assistance Reports
REVIEW GRP — NRC Research Review Groups
RM — Rulemakings
SECY — Position Papers Before the Commission
TOPREP — Vendor Reports and Related Correspondence
WASTE MGT — Nuclear Waste Management
XPORTLIC — Export and Import Licenses

Appendix B sets forth these categories and describes the material available in each. Omission of a category in the listing for a docket indicates that no documents in that category were filed in the time period of the report.

The principal elements of the nondocketed items are:

1 NUREG – NUREG Reports and Related Correspondence

2 3 –

7901060007 NUREG/CR-0161

"Dynamic Analysis to Establish Normal Shock & Vibration Environs Experienced by Radioactive National Shipping Package." Quarterly Progress Report 780101-780331. Identifies parameters which affect normal shock & vibration environs.

FIELDS, S.R., MECH, S.J. Hanford Engineering Development Laboratory.

FIN A-2093. 78/11/30. 26pp. Available at NTIS.

7 5 8 9 10 6

- Nondocketed category
- 2. NRC Accession Number
- 3. NRC Report Number
- 4. Title and description of information contained in the document
- 5. Personal author(s). An asterisk in this position indicates that there is no personal author
- 6. Corporate, agency or other nonindividual source
- 7. Contract or financial (FIN) number (if any). If the document has a secondary report number it will appear following this entry.
- 8. Date of document described
- 9. Pages in document
- 10. If this space is blank, the document is available to the public only in the NRC Public Document Room, 1717 H St., N.W., Washington, D.C. 20555. If this space is filled, it gives other sources for copies of the document. The entry may be "Available at NRC" for sale; "Available at NTIS"; or Available at GPO."

The Nondocketed Items list is arranged sequentially by Accession Number. Indented items preceded by a dash are enclosures to unindented items.

#### NOTES:

## 1. The address for NTIS is

National Technical Information Service Springfield, Virginia 22161

To place orders for or to obtain price information about NRC publications at NTIS, either write to NTIS or call the Sales Desk at (703) 557-4650. Specify the NRC report number and title when you place your order. Publications can be charged to American Express credit cards; supply the charge-card number when placing your order.

# 2. The address for GPO is:

Superintendent of Documents Government Printing Office Washington, D.C. 20402

To place orders for or to obtain price information about NRC publications at GPO, either write to GPO or call the Inquiry Desk at (202) 783-3238. Publications can be charged to VISA or Mastercharge credit cards; supply the chargecard number when placing your order.

# 3. The address for the PDR is:

1717 H Street, N.W. Washington, D.C. 20555

To place orders, either write to the NRC PDR or call (202) 634-3274. When ordering documents listed in this publication, please identify the Document Accession Number for each citation.

Paper copy and microfiche of the documents listed in this title list may be purchased. Reproduction charges for duplication are as follows: 8¢ per page for standard size paper; 11¢ per page for oversized paper (drawings); 25¢ per microfiche for 24x diazo duplicates. A minimum charge of \$2.00 plus postage is charged for mail orders.

Please acknowledge a willingness to assume charges for all orders but do not send payments. Orders will be processed and mailed with a bill from Potomac Research, Inc.

# ARRANGEMENT OF ITEMS BY DOCKET NUMBER

Doc	eket	Name	Page	Docket	Name	Page
	27-039	Sheffield, IL., Nuclear Engineering Co., Inc.	1	50-2	Univ. of Michigan Research Reactor	3
	27-047	Barnwell, SC., Chem-Nuclear	1	50-3	Indian Point Station, Unit 1	4
		Systems, Inc.		50-5	Pennsylvania State Univ. Research Reactor	4
	27-048	Richland, WA., Nuclear Engineering Co.	1	50-10	Dresden Nuclear Power Station, Unit 1	4
	40-0299	Union Carbide Corp.	i	50-13	Babcock & Wilcox Co. Critical	5
	40-1162	Western Nuclear	1	30-13	Facility	J
	40-1341	Ford, Bacon and Davis, Inc.	1	50-18	Vallecitos Boiling Water Reactor	5
	40-2259	Pathfinder Mines Corp.	1	50-20	Massachusetts Institute of Technology Research Reactor	6
	40-3392	Allied Chemical Corp.	1	50-22	Westinghouse Test Reactor	6
	40-3453	Atlas Minerals	1			6
	40-4492	Federal American Partners	1	50-27	Washington State Univ. Research Reactor	0
	40-6659	Petrotomics Co.	2	50-29	Yankee-Rowe Nuclear Power Station	6
	40-7455	Desco Marine	2	5047	Army Materials Research Reactor	7
	40-7869	Plateau Resources, Ltd.	2	50-54	Union Carbide Research Reactor	7
	40-8027	Kerr-McGee Corp.	2	50-57	State Univ. of New York Research Reactor	7
	40-8032	Gulf Research and Development Co.	2	50.50	Texas A & M Univ. Research	7
	40-8194	Army, Dept. of	2	50-59	Reactor	,
	40-8452	Bear Creek Mining Co.	2	50-62	Univ. of Virginia Research Reactor	7
	40-8502	Wyoming Mining Corp., Irigary Mine	2	50-70	General Electric Test Reactor	8
	40-8584	Union 76 Exploration Co.	3	50-72	Univ. of Utah Research Reactor	8
	40-8602	United Nuclear Corp.	3	50-73	General Electric Nuclear Test	8
	40-8681	Energy Fuels Nuclear	3		Reactor	_
	40-8692	Cotter Corp.	3	50-77	Catholic Univ. of America Research Reactor	8
	40-8693	Ogle Petroleum, Inc.	3	50-83	Univ. of Florida Training Reactor	9
	40-8698	Plateau Resources, Ltd.	3	50-84	Univ. of California Research	
	40-8714	Cleveland Cliffs Iron Co.	3	** **	Reactor	
	40-8722	Brush-Weilman, Inc.	3	50-87	Westinghouse Critical Experim	
				50-89	General Atomic Co.	

Docket	Name	Page	Docket	Name	Page
50-94	Rockwell International Research	9	50-166	Univ. of Maryland Research Reactor	13
-0.05	Reactor	9	50-170	National Naval Medical Center	13
50-97 50-99	Cornell Univ. Zero Power Reactor  Babcock & Wilcox Test Reactor	9	50-171	Peach Bottom Atomic Power Station, Unit 1	13
50-106	Oregon State Univ.	9	50-182	Purdue Univ. Research Reactor	14
50-111	North Carolina State Univ. Research Reactor	9	50-184	National Bureau of Standards Reactor	14
50-112	Univ. of Oklahoma Research Reactor	10	50-186	Univ. of Missouri Research Reactor	14
50-113	Univ. of Arizona Research Reactor	10	50-187	Space Radiation Research Reactor	14
50-116	Iowa State Univ. Research Reactor	10	50-188	Kansas State Univ. Research Reactor	14
50-123	Univ. of Missouri Research Reactor	10	50-192	Univ. of Texas Research Reactor	14
50-124	Virginia Polytech Inst. Training Reactor	10	50-193	Rhode Island & Providence Plantations AEC	14
50-128	Texas A & M Univ, Research Reactor	10	50-199	Manhattan College Research Reactor	14
50-129	Texas A & M Univ. Research	10	50-201	West Valley Reprocessing Plant	14
50-130	Reactor  Pathfinder Atomic Plant	11	50-206	San Onofre Nuclear Station, Unit 1	15
50-131	Omaha Veterans Administration	11	50-208	Columbia Univ. Research Reactor	16
	Hospital Research Reactor		50-213	Haddam Neck Plant	16
50-133	Humboldt Bay Power Plant, Unit 3	11	50-219	Oyster Creek Nuclear Power Plant	17
50-134	Worcester Polytech Inst. Research Reactor	11	50-220	Nine Mile Point Nuclear Station, Unit 1	18
50-139	Univ. of Washington Research Reactor	11	50-223	Univ. of Lowell Research Reactor	19
50-141	Stanford Univ. Research Reactor	11	50-224	Univ. of California Research Reactor	19
50-142	UCLA Training Reactor	12	50-225	RPI Critical Experiment	19
50-146	Saxton Nuclear Experimental Facility	12	50-228	Aerotest Radiography & Research Reactor	20
50-148	Univ. of Kansas Research Reactor	12	50-237	Dresden Nuclear Power Station,	20
50-150	Ohio State Univ. Research Reactor	12	50.241	Unit 2	21
50-151	Univ. of Illinois Research Reactor	12	50-241	Mississippi State Univ. Research Reactor	21
50-155	Big Rock Point Nuclear Power Plant	12	50-243	Oregon State Univ. Research Reactor	22
50-156	Univ. of Wisconsin Research Reactor	13	50-244	Robert Emmet Ginna Nuclear Plant, Unit 1	22
50-157	Cornell Univ. Research Reactor	. 13	50-245	Millstone Nuclear Power Station, Unit 1	23
50-160	Georgia Institute of Technology	13	50-247	Indian Point Station, Unit 2	24
50-163	Research Reactor  General Atomic Co.	13	50-249	Dresden Nuclear Power Station, Unit 3	25

50-250	Turkey Point Plant, Unit 3	26	50-286	Indian Point Station, Unit 3	63
50-251	Turkey Point Plant, Unit 4	28	50-287	Oconce Nuclear Station, Unit 3	65
50-252	Univ. of New Mexico Research	30	50-288	Reed College Research Reactor	66
50-254	Reactor  Quad-Cities Station, Umt 1	30	50-289	Three Mile Island Nuclear Station, Umt 1	66
50-255	Palisades Nuclear Plant	31	50-290	Proof Test Facility	67
50-259	Browns Ferry Nuclear Power Station, Unit 1	33	50-293	Pilgrum Nuclear Power Station, Unit 1	67
50-260	Browns Ferry Nuclear Power Station, Unit 2	34	50-294	Michigan State Univ. Research Reactor	68
50-261	II.B. Robinson Plant, Unit 2	35	50-295	Zion Nuclear Power Station, Unit 1	69
50-262	Brigham Young Univ. Research Reactor	36	50-296	Browns Ferry Nuclear Power Station, Unit 3	70
50-263	Monticello Nuclear Generating Plant	36	50-297	North Carolina State Univ. PULSTAR Reactor	71
50-264	Dow Chemical Co.	37	50-298	Cooper Nuclear Station	71
50-265	Quad-Cities Station, Unit 2	37	50-298	Point Beach Nuclear Plant,	73
50-266	Point Beach Nuclear Plant, Unit 1	38	20-301	Unit 2	, 5
50-267	Fort St. Vrain Nuclear Generating Station	39	50-302	Crystal River Nuclear Plant, Unit 3	73
50-269	Oconee Nuclear Station, Unit 1	40	50-304	Zion Nuclear Power Station, Unit 2	76
50-270	Oconee Nuclear Station, Unit 2	42	50-305	Kewaunee Nuclear Power Plant	77
50-271	Vermont Yankee Nuclear Power Station	44	50-306	Prairie Island Nuclear Station, Unit 2	78
50-272	Salem Nuclear Generating Station,	45	50-309	Maine Yankee Atomic Power Plant	80
	Unit 1		50-311	Salem Nuclear Generating Station, Unit 2	83
50-274	U.S. Geological Survey Research Reactor	47	50-312	Rancho Seco Nuclear Generating Station	84
50-275	Diablo Canyon Nuclear Power Plant, Unit 1	47	50-313	Arkansas Nuclear One, Unit 1	86
50-276	Georgia Tech Research Reactor	49	50-315	Donald C. Cook Nuclear Power Plant, Unit 1	88
50-277	Peach Bottom Atomic Power Station, Unit 2	49	50-316	Donald C. Cook Nuclear Power Plant, Unit 2	89
50-278	Peach Bottom Atomic Power Station, Unit 3	51	50-317	Calvert Cliffs Nuclear Power Plant, Unit 1	90
50-280	Surry Power Station, Unit 1	52	50-318	Calvert Cliff's Nuclear Power Plant,	91
50-281	Surry Power Station, Unit 2	56	30-210	Unit 2	,,
50-282	Praine Island Nuclear Station, Unit 1	60	50-320	Three Mile Island Nuclear Station, Unit 2	0.3
50-284	Idaho State Univ. Research Reactor	62	50-321		
50-285	Fort Calhoun Station, Unit 1	62			

Docket	Name	Page	Docket	Name	Page
50-323	Diablo Canyon Nuclear Power Plant,	113	50-363	Forked River Nuclear Station, Unit 1	154
50-324	Unit 2  Brunswick Steam Electric Plant,	115	50-364	Joseph M. Farley Nuclear Plant, Unit 2	154
30-324	Unit 2		50-366	Edwin I. Hatch Nuclear Plant,	155
\$0-325	Brunswick Steam Electric Plant, Unit 1	117		Unit 2	
50-326	Univ. of California at Irvine Research	120	50-367	Bailly Generating Station	156
	Reactor		50-368	Arkansas Nuclear One, Unit 2	157
50-327	Sequoyah Nuclear Plant, Unit 1	120	50-369	William B. McGuire Nuclear Station, Unit 1	158
50-328	Sequoyah Nuclear Plant, Unit 2	121	50-370	William B. McGuire Nuclear	159
50-329	Midland Plant, Unit 1	122		Station, Unit 2	
50-330	Midland Plant, Unit 2	124	50-373	LaSalle County Station, Unit 1	160
50-331	Duane Arnold Energy Center	126	50-374	LaSalle County Station, Unit 2	161
50-332	Barnwell Reprocessing Plant	127	50-375	Nuclear Examination Reactor	161
50-333	James A. Fitzpatrick Nuclear Power Plant	127	50-382	Waterford Generating Station, Unit 3	161
50-334	Beaver Valley Power Station, Unit 1	130	50-387	Susquehanna Steam Electric Station, Unit 1	162
50-335	St. Lucie Plant, Unit 1	133	50-388	Susquehanna Steam Electric Station, Unit 2	163
50-336	Millstone Nuclear Power Station, Unit 2	134	50-389	St. Lucie Plant, Unit 2	165
50-338	North Anna Power Station, Unit 1	135	50-390	Watts Bar Nuclear Plant, Unit 1	165
50-339	North Anna Power Station, Unit 2	138	50-391	Watts Bar Nuclear Plant, Unit 2	167
50-341	Enrico Fermi Atomic Power Plant, Unit 2	140	50-394	California State Polytech College Research Reactor	168
50-344	Trojan Nuclear Plant, Unit 1	141	50-395	Virgil C. Summer Nuclear Station, Unit 1	169
50-346	Davis-Besse Nuclear Power Station, Unit 1	143	50-396	Univ. of Virginia Cavalier Reactor	169
50-348	Joseph M. Farley Nuclear Plant,	146	\$0-397	WPPSS Nuclear Project, Unit 2	169
	Unit 1	1.0	50-400	Shearon Harris Nuclear Power Plant,	170
50-352	Limerick Generating Station, Unit 1	147		Unit 1	.,.
50-353	Limerick Generating Station, Unit 2	148	50-401	Shearon Harris Nuclear Power Plant, Unit 2	171
50-354	Hope Creek Nuclear Station, Unit 1	148	50-402	Shearon Harris Nuclear Power Plant,	172
50-355	Hope Creek Nuclear Station, Unit 2	149	00 102	Unit 3	
50-356	Univ. of Illinois Lopra Research Reactor	149	50-403	Shearon Harris Nuclear Power Plant, Unit 4	172
50-358	William H. Zimmer Nuclear Station, Unit 1	149	50-404	North Anna Power Station, Unit 3	173
60.360		151	50-405	North Anna Power Station, Unit 4	173
50-360	Battelle Memorial Inst. Critical Facility	151	50-406	Tuskegee Inst. Research Reactor	174
50-361	San Onofre Nuclear Station, Unit 2	151	50-407	Univ. of Utah Research Reactor	174
50-362	San Onofre Nuclear Station, Unit 3	153	50-409	La Crosse Boiling Water Reactor	174

Docket	Name	Page	Docket	Name	Page
50-4	0 Nine Mile Point Nuclear S Unit 2	tation, 175	50-463	Fulton Generating Station, Unit 1	195
50-4		on 176	50-464	Fulton Generating Station, Unit 2	195
304	Unit 2	on, 176	50-466	Allens Creek Nuclear Station, Unit 1	195
50-4	3 Catawba Nuclear Station,	Unit 1 176	50-470	CESSAR System 80	197
50-4	4 Catawba Nuclear Station,	Unit 2 176	50-471	Pilgrim Nuclear Power Station, Unit 2	197
50-4	6 Grand Gulf Nuclear Station	on, Unit 1 177	STN-50-482	Wolf Creek Generating Station	198
50-4	Grand Gulf Nuclear Statio	on, Unit 2 178	STN-50-483	Calloway Plant, Unit 1	199
50-4	23 Millstone Nuclear Power S Unit 3	itation, 179	STN-50-484	Tyrone Energy Park, Unit 1	200
50-4	24 Alvın W. Vogtle Nuclear I	Plant, Unit 1 179	STN-50-485	Sterling Power Project, Nuclear, Unit 1	200
50-4	Alvin W. Vogtle Nuclear I	Plant, Unit 2 179	STN-50-486	Calloway Plant, Unit 2	201
50-4	33 UC-Santa Barbara Resear	ch Reactor 180	STN-50-488	Perkins Nuclear Station, Unit 1	201
50-4	34 Surry Power Station, Uni	180	STN-50-489	Perkins Nuclear Station, Unit 2	201
50-4	35 Surry Power Station, Uni	t 4 180	STN-50-490	Perkins Nuclear Station, Unit 3	202
STN-50-4	37 Floating Nuclear Plant	181	STN-50-491	Cherokee Nuclear Station, Unit 1	202
50-4	Bellefonte Nuclear Plant,	Unit 1 181	STN-50-492	Cherokee Nuclear Station, Unit 2	203
50-4	Bellefonte Nuclear Plant,	Unit 2 182	STN-50-493	Cherokee Nuclear Station, Unit 3	203
50-4	40 Perry Nuclear Power Plan	t, Unit 1 183	STN-50-495	SWESSAR-P1	204
50-4	Perry Nuclear Power Plan	t, Unit 2 183	STN-50-498	South Texas Project, Unit 1	204
50-4	43 Seabrook Nuclear Station	, Unit 1 184	STN-50-499	South Texas Project, Unit 2	206
50-4	44 Seabrook Nuclear Station	, Unit 2 185	50-500	Davis-Besse Nuclear Power Station, Unit 2	209
50-4	45 Comanche Peak Steam El Station, Unit 1	ectric 186	50-501	Davis-Besse Nuclear Power Station, Unit 3	210
50-4	46 Comanche Peak Steam El Station, Unit 2	ectric 189	STN-50-502	Haven Nuclear Plant, Unit 1	210
50-4	52 Greenwood Energy Cente	er, Unit 2	STN-50-503	Haven Nuclear Plant, Unit 2	211
50-4	53 Greenwood Energy Cente	er, Unit 3	50-504	Koshkonong Nuclear Plant, Unit 1	211
50-4	54 Byron Station, Unit 1	191	50-505	Koshkonong Nuclear Plant, Unit 2	211
50-4		192	50-506		
50-4	56 Braidwood Station, Unit	1 192	50-507		
50-4	57 Braidwood Station, Unit	<b>2</b> 193	STN-50-508		
50-4	58 River Bend Station, Unit	1 193	STN-50-509		
50-4	59 River Bend Station, Unit	2 194	50-510		
50-4	60 WPPSS Nuclear Project, 1	Jnit 1 194	50-511		
50-4	61 Clinton Power Station, U	nit 1 195	50-513		
50-4	62' Clinton Power Station, U	nit 2 195	50-514		

Docket	Name	Page	Docket	Name	Page
50-515	Pebble Springs Nuclear Plant, Unit 2	214	50-597	New Haven, Unit 2	228
STN-50-516	Jamesport Nuclear Station, Unit 1	214	50-599	Carroll Facility I	229
STN-50-517	Jamesport Nuclear Station, Unit 2	214	50-600	Carroll Facility II	230
STN-50-518	Hartsville Nuclear Plant, Unit 1	215	70-0008	Battelle Columbus Laboratorles	231
STN-50-519	Hartsville Nuclear Plant, Unit 2	215	70-0025	Rockwell International Corp.	231
STN-50-520	Hartsville Nuclear Plant, Unit 3	215	70-0027	Babcock & Wilcox Co.	231
STN-50-521	Hartsville Nuclear Plant, Unit 4	216	70-0033	Texas Instruments, Inc.	231
STN-50-522	Skagit Nuclear Power Project,	216	70-0036	Combustion Engineering, Inc.	232
WAT, U.	Unit 1		70-0041	North Carolina State Univ.	232
STN-50-523	Skagit Nuclear Power Project, Unit 2	217	70-0135	Babcock & Wilcox Co.	232
STN-50-528	Palo Verde Nuclear Station, Unit 1	217	70-0143	Nuclear Fuel Services, Inc.	232
STN-50-529	Palo Verde Nuclear Station, Unit 2	217	70-0152	Purdue University	233
STN-50-530	Palo Verde Nuclear Station, Unit 3	218	70-0364	Parks Township Site, Babcock & Wilcox Co.	233
50-537	Clinch River Breeder Reactor	218	70-0371	United Nuclear Corp.	234
50-538	Memphis State Univ. Research Reactor	218	70-0510	U.S. Coast Guard Academy	234
STN-50-546	Marble Hill Nuclear Station, Unit 1	218	70-0597	Central Michigan Univ.	234
STN-50-547	Marble Hill Nuclear Station, Unit 2	219	70-0687	Union Carbide Corp.	234
50-549	Greene County Nuclear Power Plant	220	70-0698	Waltz Mill Site, General Electric Corp.	234
STN-50-553	Phipps Bend Nuclear Plant, Unit 1	220	70-0708	EG&G, Inc.	234
STN-50-554	Phipps Bend Nuclear Plant, Unit 2	221		·	
STN-50-556	Black Fox Station, Unit 1	221	70-0734	General Atomic Co.	235
STN-50-557	Black Fox Station, Unit 2	222	70-0754	Vallecitos Nuclear Center, General Electric Co.	235
50-561	B-SAR-205	223	70-0820	United Nuclear Corp.	235
STN-50-566	Yellow Creek Nuclear Plant, Unit 1	223	70-0824	Babcock & Wilcox Co.	236
STN-50-567	Yellow Creek Nuclear Plant, Unit 2	223	70-0895	Arkansas, Univ. of	236
STN-50-568	NEP Nuclear, Unit 1	224	70-0925	Cimarron Facility, Korr-McGec Corp.	236
STN-50-569	NEP Nuclear, Unit 2	224	70-0959	Nuclear Fuel Services, Inc.	236
STN-50-574	Bagnac Nuclear Power Project	225	70-0984	Pacific Northwest Laboratory	236
STN-50-580	Erie Nuclear Plant, Unit 1	225	70-1007	General Electric Co.	236
STN-50-581	Erie Nuclear Plant, Unit 2	226	70-1100	Combustion Engineering, Inc.	230
50-588	Regodola Nuclear Power Station	226	70-1113	Goneral Electric Co.	230
50-589	Asco Fesca I Nuclear Power Plant	226	70-1143	Westinghouse Electric Corp.	23
STN-50-592	Palo Verde Nuclear Station, Unit 4	226	70-1151	Westinghouse Electric Corp.	23
STN-50-593	Palo Verde Nuclear Station, Unit 5	227	70-1193	Cimarron Facility, Kerr-McGee Corp.	23
50-596	New Haven, Unit 1	227	• •	Ommitted a memory account was a second	
					l

Docket	Name	Page	Docket	Name	Page
70-120	O Princeton Gamma-Tech	237	71-0028	Borg-Warner Corp.	242
70-120	UF <sub>6</sub> Conversion Facility, Babcock & Wilcox Co.	237	71-0034	Babcock & Wilcox Co.	242
70-122		238	71-0036	ITT Grinnell Corp.	242
70-125		238	71-0037	Navy, Dept. of	242
70 120	Exxon Nuclear Co., Inc.	242	71-0039	Walworth Co.	242
70-130	Morris Operations, General Electric Co.	238	71-0047	Capital International Airways, Inc.	242
70-130	9 Morris Operations, Sources &	238	71-0056	Philadelphia Electric Co.	242
	Standards, General		71-0059	General Electric Co.	242
70-131	9 U.S. Nuclear, Inc.	238	71-0061	Navy, Dept. of	242
70-135	51 Army, Dept. of	238	71-0068	Yankee Atomic Electric	242
70-135	59 IRT Corp.	239	71-0070	General Motors Corp.	242
70-142	26 Transnuclear, Inc.	239	71-0072	Babcock & Wilcox Co.	242
70-143	Recycle Fuels Plant, Westinghouse Electric Corp.	239	71-0074	Nuclear Welding, Inc.	242
70-14	•	239	71-0077	Midstate Testing Laboratory	242
70-14		239	71-0085	Navy, Dept. of	242
70-15		239	71-0089	Navy, Dept. of	242
70-17		239	71-0090	Combustion Engineering Co., Inc.	242
		239	71-0096	Pan American World Airways	243
70-17	•	239	71-0099	Foster Wheeler Energy Corp.	243
70-17	29 Fuel Receiving and Storage Station, Allied General Nuclear Services	239	71-0103	Twin City Testing & Engineering Laboratory	243
70-17	38 Pacific Gas & Electric Co.	239	71-0110	Buckeye Steel Castings	243
70-20	00 Mt. Sinai Hospital, Hartford, CT.	239	71-0115	Babcock & Wilcox Co.	243
70-22	17 General Atomic Co.	239	71-0119	Ingersoll-Rand Co.	243
70-24	43 Tennessee Valley Authority	239	71-0120	Daniel International Corp.	243
70-26	23 McGuire Spent Fuel Pool, Duke Power Co.	239	71-0135	Babcock & Wilcox Co.	243
70-26		241	71-0133	Metals Testing Co., Inc.	243
70-28		241	71-0137	Thayer Inspection Service, Inc.	243
70-28	•	241	71-0146	Globe X-Ray Services, Inc.	243
		241	71-0140	Peabody Testing Service	243
70-28					
70-28	•	241	71-0154	General Dynamics	243
71-00		241	71-0157	Froehling & Robertson, Inc.	243
71-00		241	71-0162	Ebasco Services, Inc.	243
71-00		241	71-0169	Florida Power & Light Co.	243
71-00	Nuclear Assurance Corp.	242	71-0174	Southern California Edison Co.	243

Docket	Name	Page	Docket	Name	Page
71-0188	Maynard Steel Casting Co.	243	71-0314	Smith-Emery Co.	245
71-0190	Texas Instruments, Inc.	244	71-0315	Radiography Inspection, Inc.	246
71-0195	Toledo Edison Co.	244	71-0316	Mason & Hanger-Silas	246
71-0202	Pacific Gas & Electric Co.	244	ar 0310	Mason Co., Inc.	246
71-0207		244	71-0318	Marathon Oil Co.	246
#1 0200	Power Co	244	71-0319	General Testing and Inspection Co.	246
71-0208	-	244	71-0320 71-0321	Pittsburgh-Des Moines Steel Co.	246
71-0213		244		Exam Co.	246
71-0220	·	244	71-0322	Control Components International	246
71-0223		244	71-0324	Allied Chemical	246
71-0225		244	71-0325	Consumers Power Co.	246
71-0229		244	71-0326	Industrial Heat Treating & Metallurgical Co., Inc.	246
71-0230	Babcock & Wilcox Co.	244	71-0327	Portland General Electric Co.	246
71-0233	O'Neill Tank Co., Inc.	244	71-4824	Model: HA-10, Babcock & Wilcox	246
71-0240	Power Authority of the State of New York	244		Co.	
71-0258	Nuclear Engineering Co., Inc.	244	71-4894	Model: NPD-1-528, Kerr-McGee Nuclear Corp.	246
71-0260	Astrotech, inc.	244	71-4949	Model: UNC-1484, Combustion	246
71-0275	Duquesne Light	244		Engineering Co., Inc.	
71-0279	Universal Testing, Inc.	245	71-4986	Model: RA-2, Exxon Nuclear Co., Inc.	246
71-0284	Ultrasonic Specialists, Inc.	245	71-5364	Model: NPI-67-0442 Neutron	246
71-0285	Bell Geophysics	245		Products, Inc.	
71-0287	Carson Non-Destructive Testing	245	71-5442	Model: LA-36, Babcock & Wilcox Co.	246
71-0289	Terradata Geophysical, Inc.	245	71-5450	Model: RCC-1, -2, -3, Westinghouse	246
71-0291	DJ Inspection Services, Inc.	245	#1 ##A = 1	Electric Corp.	• • •
71-0292	Industrial Gamma Inspection		71-5595	Model: L & M ORNL Uranium Shielded Cask, Energy, Dept. of	246
71-0294	Applied Engineering Co.	245	71-5768	Model: BB-250-2, Combustion	247
71-0295	Acurea Corp.	245		Engineering Co., Inc.	
0000	a transference Co.	245	71-5790	Model: A1-M3, Energy, Dept. of	247
		245	71-5791	Model: Al-M6, Energy, Dept. of	247
		245	71-5805	Model: Atcor VNDB Cask, Atcor, Inc.	247
71-0303	Memphis Testing Services, Inc.	245	71-5908	Model: DOT-GM Type B, Babcock	247
71-0306	Snyder Drilling-Well Servicing Co.	245		& Wilcox Co.	
71-0308	B Alaska Industrial X-Ray	245	71-5926	Model: 100, General Electric Co.	247
71-0310	Bucytus-Erie Co.	245	71-5942	Model: GE-700, General Electric Co.	247
71-0313	Precision Inspection, Ltd.	245			

Docket	Name	Page	Docket	Name	Page
71-6058	Model: B3-1, Nuclear Engineering Co.	247	71-9019	Model: BU-7, General Electric Co.	248
71-6244	Model: 6244, Chem-Nuclear Systems, Inc.	247	71-9022	Model CE-250-2, Combustion Engineering Co., Inc.	248
71-6272	Model Poly Panther, Nuclear Engineering Co.	247	71-9033	Model: 660 & 660E, Technical Operations, Inc.	248
71-6294	Model: UNC-2901, Combustion Engineering, Inc.	247	71-9044	Model: GE-1600, General Electric Co.	248
71-6375	Model PB-1, Chem-Nuclear	247	71-9065	Model: BU-4, General Electric Co.	248
,,,,,,,	Systems, Inc.		71-9070	Model. N 55, Energy, Dept. of	248
71-6387	Model 60, Battelle Memorial Institute	247	71-9079	Model: HN-100 Series 2, Hittman Nuclear & Development Corp.	248
71-6400	Model: Super Tiger, Westinghouse Electric Corp.	247	71-9080	Model: IIN-600, Ilittman Nuclear & Development Corp.	248
71-6574	Model: HN-200, Hittman Nuclear & Development Corp.	248	71-9081	Model: CSNI-1600, Chem-Nuclear Systems, Inc.	249
71-6601	Model: LL-50-100, Kem-Nuclear Systems, Inc.	248	71-9086	Model: IIN-100, Series 1, Hittman Nuclear & Development Corp.	249
71-6639	Model: MII-1 A, Army, Dept. of	248	71-9108	Model: AL-33-90, Atcor, Inc.	249
71-6679	Model: 1/2 Super Tiger, Nuclear Engineering Co.	248	71-9117	Model: RC-ΓBRTG-1000, Army, Dept, of, Ft. Belvoir	249
71-6698	Model: NFS-4, Nuclear Fuel Services, Inc.	248	71-9126	Model: 20, 20A, 50, 50A, Gamma Industries	249
71-6717	Model: 6717 B	248	71-9128	Model: C-8, Gamma Industries	249
71-9002	Model: U-10-CL, Babcock & Wilcox Co.	248	71-9132	Model: T-3, Nuclear Packaging, Inc.	249
71-9009	Model: FL-10-1, General Electric Co.	248	71-9506	Model: MS27684-2, Energy, Dept. of	249
71-9010	Model: NLI-1/2, NL Industries, Inc.	248			

# ALPHABETIC ARRANGEMENT OF DOCKET 50 ITEMS BY FACILITY NAME

Name	Docket	Page	Name	Docket	Page
Aerotest Radiography & Research Reactor	50-228	20	Browns Perry Nuclear Power Station, Unit 2	50-260	34
Allens Creek Nuclear Station, Unit 1	50-466	195	Browns Ferry Nuclear Power Station, Unit 3	50-296	70
Alvin W. Vogtle Nuclear Plant, Unit 1	50-424	179			
Alvin W. Vogtle Nuclear Plant, Unit 2	50-425	179	Brunswick Steam Electric Plant, Unit 1	50-325	117
Arkansas Nuclear One, Unit 1	50-313	86	Brunswick Steam Electric Plant, Unit 2	50-324	115
Arkansas Nuclear One, Unit 2	50-368	157	B-SAR-205	50-561	223
Army Materials Research Reactor	50-47	7	Byron Station, Unit 1	50-454	191
Asco Fesca I Nuclear Power Plant	50-589	226	Byron Station, Unit 2	50-455	192
Babcock & Wilcox Co. Critical	50-13	5	California State Polytech College Research Reactor	50-394	168
Facility	30-13	٦	Calloway Plant, Unit 1	STN-50-483	199
Babcock & Wilcox Test Reactor	50-99	9	Calloway Plant, Unit 2	STN-50-486	201
Bagnac Nuclear Power Project	STN-50-574	225			
Bailly Generating Station	50-367	156	Calvert Cliffs Nuclear Power Plant, Unit 1	50-317	90
Barnwell Reprocessing Plant	50-332	127	Calvert Cliffs Nuclear Power Plant, Unit 2	50-318	91
Battelle Memorial Inst. Critical Facility	50-360	151	Carroll Facility I	50-599	229
Beaver Valley Power Station, Unit 1	50-334	130	Carroll Facility II	50-600	230
Beaver Valley Power Station, Unit 2	50-412	176	Catawba Nuclear Station, Unit 1	50-413	176
Bellefonte Nuclear Plant, Unit 1	50-438	181	Catawba Nuclear Station, Unit 2	50-414	176
Bellefonte Nuclear Plant, Unit 2	50-439	182	Catholic Univ. of America Research Reactor	50-77	8
Big Rock Point Nuclear Power Plant	50-155	12	CESSAR System 80	50-470	197
Black Fox Station, Unit 1	STN-50-556	221	Cherokee Nuclear Station, Unit 1	STN-50-491	202
Black Fox Station, Unit 2	STN-50-557	222	Cherokee Nuclear Station, Unit 2	STN-50-492	202
Blue Hills Station, Unit 1	50-510	212	Cherokee Nuclear Station, Unit 3	STN-50-493	
Blue Hills Station, Unit 2	50-511	213			203
Braidwood Station, Unit 1	50-456	192	Clinch River Breeder Reactor	50-537	218
Braidwood Station, Unit 2	50-457	193	Clinton Power Station, Unit 1	50-461	195
Brigham Young Univ, Research	50-262	36	Clinton Power Station, Unit 2	50-462	195
Reactor			Columbia Univ. Research Reactor	50-208	16
Browns Ferry Nuclear Power Station, Unit 1	50-25 <b>9</b>	33	Comanche Peak Steam Electric Station, Unit 1	50-445	186

Name	Docket	Page	Name	Docket	Page
Comanche Peak Steam Electric Station,	50-446	189	General Atomic Co.	50-163	13
Unit 2			General Electric Test Reactor	50-70	8
Cooper Nuclear Station	50-298	71	General Electric Nuclear Test Reactor	50-73	8
Cornell Univ. Research Reactor	50-157	13	Georgia Institute of Technology	50-160	13
Cornell Univ. Zero Power Reactor	50-97	9	Research Reactor	TO 0776	
Crystal River Nuclear Plant, Unit 3	50-302	73	Georgia Institute of Technology Research Reactor	50-276	49
Davis-Besse Nuclear Power Station, Unit 1	50-346	143	Grand Gulf Nuclear Station, Unit 1	50-416	177
Davis-Besse Nuclear Power Station,	50-500	209	Grand Gulf Nuclear Station, Unit 2	50-417	178
Unit 2	<b>50.501</b>	210	Greene County Nuclear Power Plant	50-549	220
Davis-Besse Nuclear Power Station, Unit 3	50-501	210	Greenwood Energy Center, Unit 2	50-452	191
Diablo Canyon Nuclear Power Plant,	50-275	47	Greenwood Energy Center, Unit 3	50-453	191
Unit I	60 222	112	H.B. Robinson Plant, Unit 2	50-261	35
Diablo Canyon Nuclear Power Plant, Unit 2	50-323	113	Haddam Neck Plant	50-213	16
Donald C. Cook Nuclear Power Plant,	50-315	88	Hartsville Nuclear Plant, Unit 1	STN-50-518	215
Unit 1	50 216		Hartsville Nuclear Plant, Unit 2	STN-50-519	215
Donald C. Cook Nuclear Power Plant, Unit 2	50-316	89	Hartsville Nuclear Plant, Unit 3	STN-50-520	215
Dow Chemical Co.	50-264	37	Hartsville Nuclear Plant, Unit 4	STN-50-521	216
Dresden Nuclear Power Station, Unit 1	50-10	4	Haven Nuclear Plant, Unit 1	STN-50-502	210
Dresden Nuclear Power Station, Unit 2	50-237	20	Haven Nuclear Plant, Unit 2	STN-50-503	211
Dresden Nuclear Power Station, Unit 3	50-249	25	Hope Creek Nuclear Station, Unit 1	50-354	148
Duane Arnold Energy Center	50-331	126	Hope Creek Nuclear Station, Unit 2	50-355	149
Edwin I. Hatch Nuclear Plant, Unit 1	50-321	111	Humboldt Bay Power Plant, Unit 3	50-133	11
Edwin I. Hatch Nuclear Plant, Unit 2	50-366	155	Idaho State Univ. Research Reactor	50-284	62
Enrico Fermi Atomic Power Plant,	50-341	140	Indian Point Station, Unit 1	50-3	4
Unit 2	PTN 60 500	226	Indian Point Station, Unit 2	50-247	24
Erie Nuclear Plant, Unit 1	STN-50-580	225	Indian Point Station, Unit 3	50-286	63
Eric Nuclear Plant, Unit 2	STN-50-581	226	Iowa State Univ. Research Reactor	50-116	10
Floating Nuclear Plant	STN-50-437	181	James A. Fitzpatrick Nuclear Power	50-333	127
Forked River Nuclear Station, Unit 1	50-363	154	Plant	STN-50-516	214
l ort Calhoun Station, Unit 1	50-285	62	Jamesport Nuclear Station, Unit 1	STN-50-516	214
Fort St. Vrain Nuclear Generating Station	50-267	39	Jamesport Nuclear Station, Unit 2  Joseph M. Farley Nuclear Plant,	STN-50-517 50-348	146
Fulton Generating Station, Unit 1	50-463	195	Unit 1		
fulton Generating Station, Unit 2	50-464	195	Joseph M. Farley Nuclear Plant, Unit 2	50-364	154
General Atomic Co.	50-89	9	Kansas State Univ. Research Reactor	50-188	14

Name	Docket	Page	Name	Docket	Page
Kewaunee Nuclear Power Plant	50-305	77	Nine Mile Point Nuclear Station, Unit 2	50-410	175
Koshkonong Nuclear Plant, Unit 1	50-504	211	¥ 33 %	50-338	135
Koshkonong Nuclear Plant, Unit 2	50-505	211	North Anna Power Station, Unit 1		
Koshkonong Nuclear Plant, Unit 3	50-506	211	North Anna Power Station, Unit 2	50-339	138
Koshkonong Nuclear Plant, Unit 4	50-507	211	North Anna Power Station, Unit 3	50-404	173
LaCrosse Boiling Water Reactor	50-409	174	North Anna Power Station, Unit 4	50-405	173
LaSalle County Station, Unit 1	50-373	160	North Carolina State Univ. PULSTAR Reactor	50-297	71
LaSalle County Station, Unit 2	50-374	161	North Carolina State Univ. Research	50-111	9
Limerick Generating Station, Unit 1	50-352	147	Reactor		
Limerick Generating Station, Unit 2	50-353	148	Nuclear Examination Reactor	50-375	161
Maine Yankee Atomic Power Plant	50-309	80	Oconce Nuclear Station, Unit 1	50-269	40
Manhattan College Research Reactor	50-199	14	Oconee Nuclear Station, Unit 2	50-270	42
Marble IIIIi Nuclear Station, Unit 1	STN-50-546	218	Oconee Nuclear Station, Unit 3	50-287	65
Marble Hill Nuclear Station, Unit 2	STN-50-547	219	Ohio State Univ. Research Reactor	50-150	12
Massachusetts Institute of Technology Research Reactor	50-20	6	Omaha Veterans Administration Hospital Research Reactor	50-131	11
Memphis State Univ. Research Reactor	50-538	218	Oregon State Univ.	50-106	9
Michigan State Univ. Research	50-294	68	Oregon State Univ. Research Reactor	50-243	22
Reactor			Oyster Creek Nuclear Power Plant	50-219	17
Midland Plant, Unit 1	50-329	122	Palisades Nuclear Plant	50-255	31
Midland Plant, Unit 2	50-330	124	Palo Verde Nuclear Station, Unit 1	STN-50-528	217
Milistone Nuclear Power Station, Unit 1	50-245	23	Palo Verde Nuclear Station, Unit 2	STN-50-529	217
Milistone Nuclear Power Station,	50-336	134	Palo Verde Nuclear Station, Unit 3	STN-50-530	218
Unit 2			Palo Verde Nuclear Station, Unit 4	STN-50-592	226
Milistone Nuclear Power Station, Unit 3	50-423	179	Palo Verde Nuclear Station, Unit 5	STN-50-593	227
Mississippi State Univ. Research	50-241	21	Pathfinder Atomic Plant	50-130	11
Reactor			Peach Bottom Atomic Power Station, Unit 1	50-171	13
Monticello Nuclear Generating Plant	50-263	36	P <sub>1</sub>		
National Bureau of Standards Reactor	50-184	14	•		
National Naval Medical Center	50-170	13			
NEP Nuclear, Unit 1	STN-50-568	224			
NEP Nuclear, Unit 2	STN-50-569	224			
New Haven, Unit 1	50-596	227			
New Haven, Unit 2	50-597	228			
Nine Mile Point Nuclear Station, Unit 1	50-220	18			

Name	Docket	Page	Name	Docket	Page
Perkins Nuclear Station, Unit 2	STN-50-489	201	Seabrook Nuclear Station, Unit 2	50-444	185
Perkins Nuclear Station, Unit 3	STN-50-490	202	Sequoyah Nuclear Plant, Unit 1	50-327	120
Perry Nuclear Power Plant, Unit 1	50-440	183	Sequoyah Nuclear Plant, Unit 2	50-328	121
Perry Nuclear Power Plant, Unit 2	50-441	183	Shearon Harris Nuclear Power Plant, Unit 1	50-400	170
Phipps Bend Nuclear Plant, Unit 1	50-553	220	Shearon Harris Nuclear Power Plant,	50-401	171
Phipps Bend Nuclear Plant, Unit 2	50-554	221	Unit 2	30-101	111
Pilgrim Nuclear Power Station, Unit 1	50-293	67	Shearon Harris Nuclear Power Plant, Unit 3	50-402	172
Pilgrim Nuclear Power Station, Unit 2	50471	197	Shearon Harris Nuclear Power Plant,	50-403	172
Point Beach Nuclear Plant, Unit 1	50-266	38	Unit 4	50 100	
Point Beach Nuclear Plant, Unit 2	50-301	73	Shoreham Nuclear Power Station	50-322	113
Prairie Island Nuclear Station, Unit 1	50-282	60	Skagit Nuclear Power Project, Unit 1	STN-50-522	216
Prairie Island Nuclear Station, Unit 2	50-306	78	Skagit Nuclear Power Project, Unit 2	STN-50-523	217
Proof Test Facility	50-290	67	South Texas Project, Unit 1	STN-50-498	204
Purdue Univ. Research Reactor	50-182	14	South Texas Project, Unit 2	STN-50-499	206
Quad-Cities Station, Unit 1	50-254	30	Space Radiation Research Reactor	50-187	14
Quad-Cities Station, Unit 2	50-265	37	Stanford Univ. Research Reactor	50-141	11
Rancho Seco Nuclear Generating Station	50-312	84	State Univ. of New York Research Reactor	50-57	7
Reed College Research Reactor	50-288	66	Sterling Power Project, Nuclear, Unit 1	STN-50-485	200
Regodola Nuclear Power Station	50-588	226		50-335	133
Rhode Island & Providence Plantations AEC	50-193	14	St. Lucie Plant, Unit 1 St. Lucie Plant, Unit 2	50-389	165
River Bend Station, Unit 1	50-458	193	Surry Power Station, Unit 1	50-280	52
River Bend Station, Unit 2	50-459	194	Surry Power Station, Unit 2	50-281	56
Rockwell International Research Reac	tor 50-94	9	Surry Power Station, Unit 3	50-434	180
Robert Emmet Ginna Nuclear Plant,	50-244	22	Surry Power Station, Unit 4	50-435	180
Unit 1			Susquehanna Steam Electric Station,	50-387	162
RPI Critical Experiment	50-225	19	Unit 1		302
Salem Nuclear Generating Station, Unit 1	50-272	45	Susquehanna Steam Electric Station, Unit 2	50-388	163
Salem Nuclear Generating Station, Unit 2	50-311	83	SWESSAR-P1	STN-50-495	204
One 2	50-206	15	Texas A & M Univ. Research Reactor	50-59	7
	50-361	151	Texas A & M Univ. Research	50-128	10
	50-362	153	Reactor	50-129	10
	50-146	12	Texas A & M Univ. Research Reactor	30-129	10
	50-443	184	Three Mile Island Nuclear Station, Unit 1	50-289	66

Name	Docket	Page	Name	Docket	Page
Three Mile Island Nuclear Station, Unit 2	50-320	93	U.S. Geological Survey Research Reactor	50-274	47
Trojan Nuclear Plant, Unit 1	50-344	141	Vallecitos Boiling Water Reactor	50-18	5
Turkey Point Plant, Unit 3	50-250	26	Vermont Yankee Nuclear Power	50-271	44
Turkey Point Plant, Unit 4	50-251	28	Station		
Tuskegee Inst. Research Reactor	50-406	174	Virgil C. Summer Nuclear Station, Unit 1	50-395	169
Tyron Energy Park, Unit 1	STN-50-484	200	Virginia Polytech Inst. Training	50-124	10
UCLA Training Reactor	50-142	12	Reactor		
UC-Santa Barbara Research Reactor	50-433	180	Washington State Univ. Research Reactor	50-27	6
Union Carbide Research Reactor	50-54	7	Waterford Generating Station,	50-382	161
Univ. of Arizona Research Reactor	50-113	10	Unit 3		
Univ. of California at Irvine	50-326	120	Watts Bar Nuclear Plant, Unit 1	50-390	165
Research Reactor			Watts Bar Nuclear Plant, Unit 2	50-391	167
Univ. of California Research Reactor	50-84	9	Westinghouse Critical Experiment	50-87	9
Univ. of California Research Reactor	50-224	19	Westinghouse Test Reactor	50-22	6
Univ. of Florida Training Reactor	50-83	9	West Valley Reprocessing Plant	50-201	14
Univ. of Illinois Research Reactor	50-151	12	William B. McGuire Nuclear Station,	50-369	158
Univ. of Illinois Lopra Research Reacto	or 50-356	149	Unit 1		
Univ. of Kansas Research Reactor	50-148	12	William B. McGuire Nuclear Station, Unit 2	50-370	159
Univ. of Lowell Research Reactor	50-223	19	William H. Zimmer Nuclear Station,	50-358	149
Univ. of Maryland Research Reactor	50-166	13	Unit 1		
Univ. of Michigan Research Reactor	50-2	3	Wolf Creek Generating Station	STN-50-482	198
Univ. of Missouri Research Reactor	50-123	10	Worcester Polytech Inst. Research Reactor	50-134	11
Univ. of Missouri Research Reactor	50-186	14	WPPSS Nuclear Project, Unit 1	50-460	194
Univ. of New Mexico Research Reactor	50-252	30	WPPSS Nuclear Project, Unit 2	50-397	169
Univ. of Oklahoma Research Reactor	50-112	10	WPPSS Nuclear Project, Unit 3	STN-50-508	211
Univ. of Texas Research Reactor	50-192	14	WPPSS Nuclear Project, Unit 4	50-513	213
Univ. of Utah Research Reactor	50-72	8	WPPSS Nuclear Project, Unit 5	STN-50-509	212
Univ. of Utah Research Reactor	50-407	174	Yankee-Rowe Nuclear Power Station	50-29	6
Univ. of Virginia Cavalier Reactor	50-396	169	Yellow Creek Nuclear Plant, Unit 1	STN-50-566	223
Univ. of Virginia Research Reactor	50-62	7	Yellow Creek Nuclear Plant, Unit 2	STN-50-567	223
Univ. of Washington Research Reactor	50-139	11	Zion Nuclear Power Station, Unit 1	50-295	69
Univ. of Wisconsin Research Reactor	50-156	13	Zion Nuclear Power Station, Unit 2	50-304	76

# DOCKETED ITEMS

#### LOW LEVEL RADWASTE DISPOSAL SITES

DOCKET 27-039 SHEFFIELD, IL . NUCLEAR ENGINEERING CO

7906010298 Forwards attachments to "Licensees' Post-Hearing Brief on Issues Arising During Oral Arguement Before Licensing Board on 790297." which were inadvertently emitted from original submittal METTERHAHN.M J Conner, Moore & Corber 79/04/06 13pp

7906070342 Beeks to file reply to Nuclear Engineering Co 790403 post-hearing brief is issues arising during 790327 oral argument before ASLB Certificate of Svc enci SEKULER.S N Illinois, State of 79/04/11 3pp

7906270186 Reaffirms NRC 790320 order to show cause Licensee must resume responsibility for Sheffield site Order will remain in effect until issues have been resolved by ASLB CHILK, S. J. Office of the Secretary of the Commission 79706/06

7906270191 Hearing will be held before ASLB to determine whether licensee can unilaterally terminate license & application to renew license Delegates review authority to ASLAB CHILK, S. J. Office of the Secretary of the Commission 79/06/06

#### DOCKET 27-047 BARNWELL, SC , CHEM-NUCLEAR SYSTEMS

7906270817 Bubmits answers to NRC questions re license application for burial of boxes of waste containing up to 380 g U-235 REITLER.E K Westinghouse Electric Corp 79/03/20 3pp

7906070354 State of SC denial of Chem-Nuclear Sys. Inc request for receipt % burial of low power range monitors
SHEALY, H Q South Carolina, State of 79/04/10 ip

7906020173 Bubmits add1 info to support request for amend to permit burial of large boxes of U-235 wastes, in response to NRC 790223 ltr REYNOLDS, L E Chem-Nuclear Systems, Inc 79/04/11 App

# DOCKET 27-048 RICHLAND, WA . NUCLEAR ENGINEERING CO

7906270052 Forwards final response to Question 4 of Bell 790923 ltr BAER.Y S Nuclear Engineering Co , Inc (subs of Teledyne, Inc.) 79705721 lipp

#### DOMESTIC LICENSING OF SOURCE MATERIAL

DOCKET 40-0299 UNION CARBIDE CORP

7904020179 Provides info requested in 790409 talcon Discusses items which do not affect license issuance REKEMEYER, P C Union Carbide Corp 79/04/09 3pp

7906190140 Summary of 790418 meeting re issues that must be resolved prior to NRC decision on Union Carbide Corp request for authorization to operate heap leach at East Gas Hills site LINEHAN, J. Fuel Process & Fab Branch 79/05/08 2pp

#### DOCKET 40-1162 WEBTERN NUCLEAR, INC.

7906160047 Dutlines topics for discussion at 790508 meeting Topics include resising dike prior to 790715 to avoid violation of 10-ft freeboard condition & canst details of strip toe drain BOODEN.O Western Nuclear, Inc. (subs. of Phelps Dodge Corp.), 79/05/03 2pp

#### DOCKET 40-1341 FORD, BACON & DAVIS. INC

7906010324 Responds to 790308 ltr expressing concern re possible health hazards from tailings piles at inactive Edgement U mill Piles will be stabilized until they are removed & buried per docummissioning plan SCARAND,R A Division of Fuul Cycle & Material Safety 79/04/04 ip

DOCKET 40-2259 PATHFINDER MINES CORP

7906050232 Responds to NRC 790409 ltr requesting addl info re Tailings Pand 4 & Tailings Reservoir 2 Forwards "Peak Flow Estimates for Spillway of Tailings Reservoir 2 " NUGENT.E L Pathfinder Mines Corp 79/04/25 Jpp

---7906050246 "Peak Flow Estimates for Spillway of Tailings Reservoir 2 ' \* Pathfinder Mines Corp 79'04'30 App

7904040120 Responds to NRC 790410 request for additinfo to complete radiological assessment of proposed tailings area mod Forwards detailed info NUGENTE L Pathfinder Hines Corp 79/05/04 7pp

#### DOCKET 40-3392 ALLIED CHEMICAL CORP

7906190037 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
KEPPLER.J G Region 3, Chicago. Office of the Director 79/05/11
ip

7906200543 Requests add1 ref mati to enhance incident response ctr Info includes site emergency plan & implementing procedures & four sets of site maps showing environ monitoring stations KCPPLER, J O Region 3. Chicago: Office of the Director 79/05/17

7906080131 Forwards IC Circular 79-08. "Attempted Extertion - Low Enriched U " KEPPLER.J O Region 3, Chicago, Office of the Director /9/05/18

# DOCKET 40-3459 ATLAS MINERALS

7906130509 Responds to ltr re FES of Moab U mill operation Radium is leached from U ores during milling Diffusion of radium from U tailings particles is insignificant SCARRND, R A Uranium Recovery Licensing Branch 79/04/27 3pp

7906050187 Submits add1 detailed comments re FES license must comply w/half-mile buffer zone required by UT Div of Health TEMPEST.L. Utah. State of 79/05/03 2pp

#### DOCKET 40-4492 FEDERAL AMERICAN PARTNERS

7906200302 "Stack Emissions Survey, Federal American Partners, Oas Hills Mill," Jul 1978 \* Federal American Partners (Mining) 78/07/31 64pp

7906200310 "Stack Emissions Survey, Federal American Partners, Oas Hills Mill." Aug 1978 \* Federal American Partners (Mining) 78/08/31, 64pp

7906200210 "Stack Emissions Survey.Federal American Partners. Gas Hills Hill." Sept 1978 \* Federal American Partners (Mining) 78/09/30 66pp

- 7906200314 "Stact Emissions Survey,Federal American Partners,Gas Hills Hill." Oct 1978 « Federal American Partners (Hining) 78/10/31 59pp
- 7906200212 "Stack Emissions Survey, Federal American Partners, Gas Hills
- Mill." Nov 1970 \* Federal American Partners (Mining) 78/11/30 60pp
- 7906200343 "Stact Emissions Survey,Federal American Partners, Oas Hills Hill:" Dec 1978 Federal American Pertners (Mining) 78/12/31 53pp
- 7906200355 "Stack Emissions Survey, Pederal American Partners, Oas Hills
- Hill: Jan 1979 Federal American Partners (Mining) 79/01/31 58pp
- 7904200357 "Stack Emissions Survey, Federal American Partners, Gas Hills Hill," Feb 1979 \* Federal American Partners (Mining) 79/02/28 39pp
- 7906140123 Forwards requests for info identified during geotechnical engineering review of submittals re raising of Tailings Dam 2 Response requested by 790409 SCARANO, R A Radioisotopes Licensing Branch (Pre 790501) 79703/28 9pp
- 7906200306 "Stack Emissions Survey, Federal American Partners, Cas Hills
- Hill: Mar 1979

  \* Federal American Partners (Hining) 79/03/31 50pp
- 7906010293 Forwards request for additinfo re nonradiokofical impacts of anticipated mill expansion, in order to complete radiological assessment for license renewal application SCARANDLR A Uranium Recovery Licensing Branch 79/04/13 7pg 79/04/13 7op
- 7906180271 Forwards corrected Revision 2 to area-capacity curve for runioud/) rorwards corrected Hevision 2 to area-capacity curvitailings pond HEATH: A Fox Consulting Engineers & Geologists. F M Fox & Associates 79/04/18 2pp.
- 7906020123 Responds to 790413 request for info re literae renewal application Submits operating & environ data for Casper site; complete data on Gas Hills area is not yet available W/oversized framung re air quality permit amend JACKSON,F D Federal American Partners 79/05/02 Bpp
- 7906200059 Submits summary of TLD gamma survey conducted during previous twelve months to be used in conjunction w/ previously submitted info regarding scheduled 790515 meeting JACKSON,F D Federal American Partmers (Mining) 79/05/04 opp
- 7906290799 Requests addl info re hydrologic engineering
  LINEHAN, J J Uranium Recovery Licensing Branch 79/05/17 200

# DUCKET 40-4659 PETROTOMICS CO , GETTY OIL

79060404032 Requests termination of review for const mod of tailings dam raise Petrotomics Co has withdrawn mod request or ADAMQ,R A Uranium Recovery Licensing Branch 79/05/08 1p

#### ESCO MARINE

ecommissioning egal status of ir thickness 501) 79/05/03 2pp

7906200319 Discusses decommissioning plan All contaminated equipment to be transferred to proposed processing facility Decommissioning radiation surveys encl.

BEWELLIR B Plateau Resources, Ltd 79/05/00 27pp

#### DOCKET 40-8027 KERR-MCGEE CORP.

7904040395 Safety evaluation of Amend 4 to application to authorize test distribution of treated solvent extraction raffinate as fertilizer mation licensee-owned land & food chain testing of raffinate fertilizes pasture.

- 7906200581 Forwards Natl Pollution Discharge Elimination Sys permits for 140-acre & 270 acre areas per conditions outlined in ameno SHELLEY.W J Kerr-McGee Corp 79/05/09 33pp
- 7906290789 Advises of \$2,068 refund due on fee accompanying 790302 application for Amend 4 to License 8UB-1010 MILLER,W D License Fee Management Branch 79/05/23 1p
- DOCKET 40-8032 OULF RESEARCH & DEVELOPMENT CO.
- 7906140023 Requests amend to License SVA-1024 to permit simulated in-situ U leaching tests in lab LARUE, H A Gulf Research & Development Co 79/04/05 ip

#### DOCKET 40-6194 ARMY DEPT OF

- 7905140497 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-5248/79-01.
  40-8194/79-01 & 70-1351/79-01.
  MCCLINTOCK.R D Region I. Philadelphia. Office of the Director 79/05/09
- --7906140303 Responds to NRC 790330 ltr re violations noted in IE Insp Repts 30-5248/79-01, 40-8194/79-01 & 70-1351/79-01 Corrective actions installation of fence enclosing radiation area & storage of licensed matl in locked cabinet BOUMAN,E L. Arms, Dept of, Electronics Research & Development Command 79/04/11 lp
- --7906140506 Forwards notice of violation from IE lnsp Repts 30-5248/79-01,40-8194/79-01 & 70-1351/79-01 on 790306 MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director 79/03/30
- --7906:40316 Notice of violation from insp on 790306 Noncompliance noted radiation levels outside callbr facility exceeded limits & licensed matl stored in unlocked cabinet MCCLINITCK, R O Region I. Philadelphia, Office of the Director 79/03/30

#### DOCKET 40-8452 BEAR CREEK URANIUM CD

- 790602010B Forwards responses to questions re amend of license to expand mill production capacity Oversized drawings enc!
  ANDREWS.R D Rocky Mountain Energy Co 79/05/10 90pp
- 7906010295 Forwards request for add1 info to complete review of tailings mgt plan Request is mod of draft given to facility personnel during NRC 790320 site visit
  LINEHAN, J Uranium Recovery Licensing Branch 79/04/09.
- 7906:80786 Issues Amend 3 to Licente SUA-1910, authorizing mod of environ monitoring program by revising Condition 19 Meteorological monitoring station may be moved to any onsite SCARANG, R A Uranium Recovery Licensing Branch
- 7905150262 Forwards request for add1 into identified during hydrologic engineering review of Sept 1978 submittal Requests response by 790511.
  LINEHANJJ Uranium Recovery Licensing Branch 79/04/26 App
- 7906:80684 Forwards responses to Questions 1-4, submitted in NRC 740426 ltr Also forwards revision to proposed tailings mgt & reclamation plan Bix oversized drawings enci ANDRENG.R D Rocky Mountain Energy Co 79/05/17 23pp
- 7906250477 Forwards revision to Guestion 1 of licensee 790309 package of questions & responses Oversized drawing encl
  ANDREWS: R D Rocky Mountain Energy Co 79/05/17 16pp

#### DOCKET 40-8502 IRIGARY MINE, WYOMING MINING CORP

- 7905240096 Amend 1 to License SUA-134, authorizing use of calcium-magnesium carbonate/bicarbonate lixiviant, subj to specified conditions.
  SCARANG.R.A Assistant Director for Naste Hanagement (Pre 790501) 79/04/10 2pp.
- 7908200233 Bubmits rept concerning results of biweekly analyses of samples taken from monitor wells 98M-1 % 98M-7 which exceeded upper control limit values for excursion parameters measured. Corrective action overpumping SCHENDEL.K R Hyoming Mineral Corp 79/04/27 App

#### DOCKET 40-8584 UNION 76 MINERALS EXPLORATION CO

- 7906230004 Responds to 790216 request for add1 preoperational monitoring data Licensee will continue obtaining add1 info w/four mods noted, unless otherwise advised MARBHALL, J A Union Minerals 79703/27 Ip
- 7906260634 Forwards rept on testing of foundation matls & specs for License SUA-1350 Requests review of rept SCARAND.R A Uranium Recovery Licensing Branch 79/05/08 4pp
- 7906230121 Forwards rept of 790329 visit to Sweetwater U project in WY to inspect initial const operations on Ceil C of mine tailings retention basin Work is satisfactory DEPHILIPPE.A A Army, Dept of 79/05/10 5pp

#### DOCKET 40-8602 UNITED NUCLEAR CORP

7906200244 Comments on NUREO-0932 licensee should be required to fence & flag or cover acid tailings pond to prevent use of pond by wildlife.especially waterfowl All surface runoff from overburden piles should be contained by dikes DEXTER.H D Hyoming. State of 79/05/10 lp

#### DOCKET 40-8681 ENERGY FUELS NUCLEAR, INC.

- 7906180674 Forwards FES for facility (NUREG-0556)
  BCARAND,R A Uranium Recovery Licensing Branch 79/05/18 1p
- --7906180677 Forwards FES for facility (NUREQ-0556) Distribution list encl SCARANO,R A Uranium Recovery Licensing Branch 77/03/18
- 7906040358 Requests determination as to whether area south of Blanding. UT is eligible for designation as archaeological district in Natt Register 8CARANO, A Radioisotopes Licensing Branch (Pre 790501) 79/03/28 3pp
- 7906060026 Forwards archaeological survey site forms for sites 6752 & 6753 in San Juan County, UT CASUENGL. Utah, State of 79/04/23 5pp
- 7906180404 Forwards preliminary case rept for lands to be impacted by White Mesa U mill Also forwards proposal for contents of memo of agreement re mitigation of adverse effect at mill site BCARANO, R A Uranium Recovery Licensing Branch 79/04/30 10pp
- --7906180414 Believes memo of agreement will satisfy necessary mitigation under requirements of 106 review procedures KEENE.J P Utah. Blate of 79/05/03 1p
- 7906030128 FES for facility # Office of Nuclear Material Safety & Safeguards NUREG-0596 79/05/31, 350pp Available at NTIS, 11.00

#### DOCKET 40-8692 COTTER CORP

7906260557 Forwards revisions to pilot plant license application Environ & radiological monitoring section encl BMITH:T Cotter Corp. 79/05/23 9pp.

#### DOCKET 40-8693 DOLE PETROLEUM, INC

7906020184 Requests administrative amend to License SUA-1336 reducing extent of environ air particulate sampling & deleting ground water sampling program in supportive infe document CATCHPOLE, 0. J. Ogle Petroleum Inc 79/03/22 4pp

#### DOCKET 40-8698 PLATEAU RESOURCES, LTD

- 7904220135 Forwards "Contract Drawings for Stage I Tailings Impoundment & Dam. Shootering Canyon U Project" & "Stage I Tailings Impoundment & Dam Final Design Rept. Shootering Canyon U Project" dtd 790531.

  SEWELL, R B. Plateau Resources, Ltd 79/05/24 2pp
- --7906220139 "Stage I Tailings Impoundment & Dam Final Design Rept, Shootering Canyon U Project " \* Plateau Resources, Ltd. 79/05/31 100pp

- 7904070201 Protests proposed U project because of strain on public svc from increased population, threat to endangered species, adequacy of monitoring procedures, tailings containment & safeguards
  MCLAUGHLIN, D Concerned Citizens Against Proliferation of Uranium Waste 79/03/30 18pp
- 7906030104 Requests timely authorization for const of proposed facility following end of 45-day public comment period on DES HATCH.O Q Senate 79/04/23 ip
- 7906010156 Forwards applicant response to DOI comments on DES SEWELL,R B Plateau Resources, Ltd 79/05/04 56pp
- 7906190131 Forwards responses to draft comments from EPA on Shootering Project DES Suggested changes enci SEWELL.R B Plateau Resources, Ltd 79/05/09 42pp

#### DOCKET 40-8714 CLEVELAND CLIFFS IRON CO

- 7906020237 Forwards "Radiation Handbook for Cellins Draw Solution Extraction Recovery Plant" SOMERVILLE, O V Cleveland-Cliffs Iron Co 79/04/26 ip
- ---7906020238 "Radiation Handbook for Collins Draw Solution Extraction Recovery Plant" # Cleveland-Cliffs Iron Co 79/04/23 13pp
- 7906260552 Requests invoice for license fee for source matl license to be issued to Claveland Cliffs Iron Co MILLER. H O License Fee Management Branch 79/05/18 ip

#### DOCKET 40-8722 BRUSH-WELLMAN, INC

- 7906050387 Forwards request for add1 info in order to complete review of Dec 1978 application for source matl license & supporting environ rept Requests response by 790531 SCARANO, R A Uranium Recovery Licensing Branch 79/04/16 3pp
- 7906020221 Forwards responses to questions re source mati license application Oversized drawings encl
  BOWERS.M B Brush-Wellman, Inc 79/04/30 9pp
- 7906230120 Forwards 790504 ltr from A Rickers of UT Air Conservation Committee notifying that state will publish notice of intent to issue approval order for const of U recovery circuit at Delta, UT Also forwards notice from 790509 Balt Lake Tribune SCHON, R B Brush-Wellman, Inc 79/05/11 3pp
- 7906290781 Forwards State of UT notice of intent to approve const of U recovery plant in Delta.UT POWERS.M B Brush-Wellman, Inc 79/05/14 2pp

#### DOMESTIC LICENSING OF PRODUCTION AND UTILIZATION FACILITIES

- DOCKET 50-2 UNIV OF MICHIGAN RESEARCH REACTOR

  G Inspection reports, IE Bulletins & correspondence
- 7906140585 Forwards IE Insp Rept 50-002/79-01 on 790404-06 No noncompliance noted HIND, J. A. Region 3, Chicago, Bafaguards Branch 79/05/02 2pp
- --7906140391 IE Insp Rept 50-002/79-01 on 790404-06 No noncompliance noted, Major areas inspected licensee's approved security program Details withheld (ref 100FR2 790) CHRIBTOFFER, G. M. SCHEFFER, J. C. HIND, J. A. Region 3, Chicago, Bafeguards Branch. 79/04/30, 1p
- 770617005B Forwards IE Info Notice 77~12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J.O Region 3, Chicago. Office of the Director 79/05/11 ip
- 7904080184 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J. G. Region G. Chicago, Office of the Director 79/05/18, ip

# DOCKETED ITEMS

- SCKET 50-3 INDIAN POINT STATION, UNIT 1
- Security, medical, emergency & fire protection plans
- 706020078 Ack receipt of 790327 revised emergency plan Requests Class III fee MILLER.H O License Fee Hanagement Branch 29/05/08 lp
- PO&190387 Responds to 790508 ltr forwarding \$4.400 filing fee for revised emergency plan Payment made under protest Util reserves right to challenge validity of fees
  CAHLL.W J Consolidated Edison Co of New York 79/06/11 lp
- Insurance & indemnity information
- 906190256 Notifies of receipt of complaint served on Westinghouse alleging bodily injury to util employee J O'Mallon, who was splashed w/radioactive water on 760812 Suit under way ALTON.C G American Nuclear Insurers 79/06/14 1p
- '9D6220303 Forwards Amend 21 to Indemnity Agreement 8-19
  CAHILL, W. J. Consolidated Edison Co. of New York 79/06/18 3pp
- . Operating license stage documents & correspondence
- F906050419 Requests facility participate in vital area analysis & schedule site visit during week of 790506
  ECHHENGER: A Operating Reactors Branch 1 (Pre 790625) 79/04/12
- 7906210128 Forwards info re PHR feedwater lines, in response to NRC 790525 request W/15 oversized drawings CAHILL, W J Consolidated Edison Co of New York 79/06/18 40pp
- 3 Inspection reports, IE Bullatins & correspondence
- 7906:10008 Forward: IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl " No written response required GRIER, B H Region 1, Philadelphia. Office of the Director 79/04/23 1p
- 7906020081 Responds to IE Bulletin 79-07 Discusses actions taken re verification approach for UE&C-ADLPIPE-2 program CAHILL.H J Consolidated Edison Co of New York 79/04/24 7pp
- 7906070283 Responds to IE Bulletin 79-05A Facility is presently in defueling condition awaiting decision re ECCS installation Reactor design is different from current BSW reactors Info requested will be available upon decision CAHILL.W J Consolidated Edison Co of New York 79/04/26 ip
- 790608014B Responds to IE Bulletin 79-04, "Incorrect Heights for Swing Check Valves Mfg by Velan Engineering Corp " Effect of waight discrepancy negligible in every case investigated Further investigation initiated birseponse espected 790608 CAHILL, W J Consolidated Edison Co of New York 79/08/01 2pp
- 7906120132 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER.B.H Region 1, Philadelphia. Office of the Director 79/03/07 2pp
- 7906110118 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Licenses action required. GRIER, BH Region i, Philadelphia, Office of the Director 79/05/11. ip
- 7906260098 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1. Philadelphia, Office of the Director 79705/11 1p
- 7906290830 Responds to IE Bulletin 79-058 Unit i was shut down on 741031 k is in defueled condition awaiting decision reinstalletion of ECCB.Reactor design is substantially different from current BAW BURS CAHILL.W J Consolidated Edison Co of New York 79/05/14 1p
- 7906270204 Responds to IE Bulletin 79-09 Unit 1 currently shut down, awalting decision re ECCS No GE Type AK-2 circuit breakers used in safety-related sys in Unit 2
  CAMILL. H. J. Consolidated Edison Co. of New York, 79/05/17 ip
- 7906080069 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER, B. H. Region 1, Philadelphia, Office of the Director 79/05/18 | 19

- R Periodic operating reports & related correspondence
- 7906140259 Annual Environ Operating Rept 1978, Part A & Part B radiological rept, vols 1 & 2
  + Consolidated Edison Co of New York 78/12/31 223pp
- 7906190462 Forwards "Seasmic Monitoring Network." Quarterly Rept 15 for Dec 1978 - Feb 1979 CAHILL, H J Consolidated Edison Co of New York 79/06/04 1p
- --7906190466 "Seramic Monitoring Network." Quarterly Rept 15 for Dec1978-Feb 1979 Prepared by Hoodward-Clyde Consultants, Inc \* Consolidated Edison Co of New York 79/05/30 36pp
- 7906:90478 Submits May environ data specified in Section 401 certification
  HONTI,W A Consolidated Edison Co of New York 79/06/10 11pp
- 7906260004 Forwards monthly operating rept for May 1979
  GAHILL.W J Consolidated Edison Co of New York 79/06/14 1.
- --7906260006 Monthly operating rept for May 1979
  KAWULA, L. Consolidated Edison Co. of New York 79/06/05 7pp
- 7906260407 Forwards May 1979 daily tabulation of fish collection & species breakdown CAHLL, W J Consolidated Edison Co of New York 79/06/14 5pp
- DOCKET 50-5 PENNSYLVANIA STATE UNIV RESEARCH REACTOR
- J Insurance & indemnity information
- 7906150277 Forwards executed Amend 14 to Indemnity Agreement E-10 CUNNINGHAM.R 0 Pennsylvania State Univ 79/06/11 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 7906260066 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " QRIER, B H Region 1. Philadelphia, Office of the Director 79/05/11 ip
- 7906080027 Forwards [E Circular 79-08, "Attempted Extortion Low Enriched U " GRIER.8 H Region i, Philadelphia, Office of the Director 79/05/18 ip
- S Reportable occurrences. LERs & related correspondence
- 7706260467 RD on 770608 percent power meter stuck at 78% full scale & would not have scammed if power had exceeded 98% Caused by dust inside meter movement Movement cleaned & checked for proper operation

  CUNNINGHAM.R © Pennsylvania State Univ 77/06/25 ip
- 7906270251 On 790608 during routine daily reactor instrumentation checkout, discovered percent power meter stuck at 98% full scale Caused by dust inside meter movement Movement cleaned. CUNNINOHAMAR 9 Pennsylvania. Univ of 79/06/25 ip
- 7906280144 Notifies that on 79060B, during routine daily checkout of reactor instrumentation, percent power meter stuck at 9BK full power Caused by dust in meter movement Movement cleaned, thecked for proper operation & returned to svc GUNNINGHAM, R O Pennsylvania State Univ 79/06/25 ip
- 7906290398 Advises of incident reported to Region I on 790608 percent power mater stuck at 98% full scale & could have failed to perform safety function Caused by dust inside mater Meter cleaned, checked & returned to sec
- DOCKET 50-10 DRESDEN NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7906070305 Forwards request for add1 info re 790417 fire protection program
  ZIEMANN: D L Operating Reactors Branch 2 (Pre 790625) 79/05/01
  4so.
- 7906050369 Respond≤ to NRC 790501 request for add1 info re fire protection
  JANACEK, R. F. Commonwealth Edison Co 79/05/30 38pp

#### J Insurance & indemnity information

- 7704040187 Forwards executed Amends 21.11.9 & 1 to Indomnity Agreements 8-10.8-47.8-59 & 8-84.respectively POOLE.R b Commonwealth Edison Co 77/05/29 Spp
- 7904070236 Forwards Endorsements 118 & 119 to NELIA Policy NF-43 OSTER, J Commonwealth Edison Co 79/05/30 3pp
- 7906120260 Forwards Endorsements 100 & 101 to MAELU Policy MF-22 & Endorsements 49 & 90 to MAELU Policy MF-54 USTER.J Commonwealth Edison Co 79/06/07 Spp
- P. Operating license stage documents & correspondence
- 7906250108 Forwards draft evaluation of systematic evaluation program Topic XV-17 Requests review & response within 30 days ZIEMANN,D L Operating Reactors Branch 2 (Pre 790625) 79/05/09 3pp
- 7906270046 Forwards request for info re chemical decontamination of facility Three questions relate to actions taken by DGE Requests direct response to State of IL VOLLMER.R H Assistant Director for Systems Engineering 79/05/15
- ---7906270047 Requests info re proposed decontamination of facility in ref to petition to produce EI8 HANSELL,D Illinois. State of 79/04/18 2pp
- 7906200239 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of onsite & offsite environ monitoring stations & site maps used for dose determinations KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/17
- 7906040216 Forwards GE rept NEDC-24159; "Long-Torm Evaluation of Effects of Exposure to DOM NS-1 Bolvent on Stress Corrosion Cracking of Sensitized Type 304 Stainless Steel in Simulated BWR Environ: "dtd Nov 1978

  JANECEK, R F Commonwealth Edison Co 79/05/23 1p
- --7906040218 "Long-Term Evaluation of Effects of Exposure to DDW NS-1 Bolvent on Stress Corrosion Cracking of Sensitized Type 304 Stainless Steel in Simulated BWR Environ " WALTER, W. L., CORDON, O. M. General Electric Co. NEDC-24159 78/11/30 34pp
- 7906270236 Cites add1 systematic evaluation program topics that should be deleted from review re failure of Underdrain sys & interlock requirements JANECEKIR F Commonwealth Edison Co 79/06/22 ip
- G Inspection reports: IE Bulletins & correspondence
- 7906250147 Forwards IE Insp Repts 50-010/79~10,50-237/79-10 & 50-247/79-08 on 790316-30 No noncompliance noted HEIBHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Bupport Branch 79/04/23 2pp.
- --7906250153 IE Insp Repts 50-010/79-10, 50-237/79-10 \$ 50-249/79-08 on 790316-20 No noncompliance noted. Major areas inspected maint activities; plant operations & physical protection & security organization security organization SPEBBARD, R. L., MONO, M. K., REYES, L. A. Region 3, Chicago, Office of the Director. 79/04/25 7pp
- 7906290493 Responds to IE Bulistin 79-08 Forwards info re review of TMI incident, Existing line isolation not important to ECCB injection REED.C. Commonwealth Edison Co. 79/04/27. 22pp
- 7906120083 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem." No action required, REPPLER, J Q Region 3. Chicago. Office of the Director 79/05/07
- 7906110101 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics." Written response required KEPPLER, J O Region 3, Chicago, Office of the Director. 79/05/11
- 7906190078 Forwards IE Info Notics 79-12, "Attempted Damage to New Fuel Assemblies."

  KEPPLER, J. O. Region G. Chicago, Office of the Director. 79/05/11

- 7906080196 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7906130082 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/22
- 7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creak Reactor" KEPPLER, J 0 Region 3, Chicago, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906150336 Forward monthly operating rept for May 1979 STEPHENSON, B B Commonwealth Edison Co 79/06/11 1
- --7906150338 Monthly operating rept for May 1979
  CLEGZKIEHICZ, S Commonwealth Edison Co 79/06/04 35pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906190289 Forwards LER 79-001/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/06/15 in
- ---7906190294 LER 79-001/03L-O on 790518 while digging ditch for new pipe, const personnel observed water running into trench from proximity of radwaste return-to-etorage line Caused by return line to 1A storage leaking from aluminum line MANCINI.B Commonwealth Edison Co 79/06/15 ip
- U Congressional/Executive Correspondence
- 7906080005 Responds to 790404 request to review K Brey ltr on proposed chemical decontamination of facility thr was treated as request for action per 10CFR2 206 & action will be taken on patition within reasonable time period 0CBSICK.L V Office of the Executive Director for Operations 79/05/08
- --7906080007 Ack receipt of 790319 petition requesting EIS on proposed decontamination experiments designed to flush radioactive corrosion products from portions of piping Petition is being treated per 100FR2 2006 FR notice encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/04/09 2pp
- --7906080008 Request for preparation of EIS re proposed decontamination experiments designed to flush radioactive corresion products from portions of piping ROYD, R S Division of Project Management 79/04/09 ip
- ---7906080026 Forwards petition requesting that prior to use of Dow Chemical solvent to flush out piping O'BRIEN,O M House of Rep 79/04/04 ip
- --7906080032 Petition for preparation of EIS prior to use of Dow Chemical solvent to flush out corresive products from piping DREY.K Affiliation Unknown 79/03/19 Spp
- DOCKET 50-19 BABCOCK & WILCOX CO CRITICAL FACILITY

  G Inspection reports: IE Bulletins & correspondence
- 7906250436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY,J P Region 2, Atlanta, Office of the Director
- DOCKET 50-18 VALLECITOS BOILING WATER REACTOR

  J Insurance & indemnity information
- 7906260419 Forwards Endorsements 109.110 & 111 to NELIA Policy NF-1 CORREA: C Marsh & McLenon, M & H Nuclear Consultants, Inc. Div 79/05/15 App

# DOCKETED ITEMS

- DOCKET 50-20 MASSACHUSETTS INST OF TECH RES REACTOR

  J Insurance & indemnity information
- 7906130311 Forwards executed Amend 10 to Indemnity Agreement E-39 VALENTINE,K Massachusetts Institute of Technology 79/06/04 lp
- Q Inspection reports. IE Bulletins & correspondence
- 7906260037 Forwards IE Insp Rept 50-020/79 on 790314-16 No noncompliance noted BRUNNER:E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79704/16 2pp
- --7906260061 IE Insp Rept 30-020/79-01 on 790314-16 No noncompliance noted Mayor areas inspected logs & records.LERs.esperiments, operator licenses, design mods.licensee audits & action on previous insp findings
  STETKA:T F Region I, Philadelphia, Office of the Director HCGABE;E C Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/13 7pp
- 7906260059 Forwards IR Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  ORIER.B H Region 1. Philadelphia. Office of the Director 79/05/11 ip
- 7904080024 Forwards IE Circular 79-08, "Attempted Extortion ~ Low Emriched U " GRIER, B R Region I, Philadelphia, Office of the Director 79/08/18 IP

# DOCKET 50-22 WESTINGHOUSE TEST REACTOR

- Q Inspection reports. [E Bulletins & correspondence
- 7906260051 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7904080053 Forwards IE Circular 79-08, "Attempted Extortion ~ Low Enriched U " GRIER, B K Region 1. Philadelphia. Office of the Director 79/03/18 ip
- DOCKET 50-27 WASHINGTON STATE UNIV RESEARCH REACTOR

  D NRC Draft/Final Environmental Statements, suppls & correspondence
- 7906070249 Forwards corrected version of page 10 to EIS Original contained typographical errors in exponents WILSON:W E Washington State Univ 79/03/29 2pp
- Utility Final Safety Analysis Report (FSAR) & amends
- 906270183 Forwards revised SAR as part of renewal application for License R-76 Submits 790515 ltr forwarding application for renewal of license & info re application for renewal WILSON:WE Washington State Univ 79/06/21 6pp
- -7906270184 Revised SAR WILSON, W. E. Hashington State Univ 79/05/31 20Spp
- Operating license stage documents & correspondence
- 906120412 Forwards two pages to application for renewal of License R-76, erroneously omitted from 790515 submission HILSON: M.E. Mashington State Univ. 79/06/04 1p.
- -7906120415 Bubmits two pages erroneously omitted from application for renewal of License R-76.per RW Reed 790406 ltr. NYMAN.C J , SANDE.R.D., WILSON.H.E Washington State Univ 79/05/15 3pp.
- . Inspection reports, IE Bulletine & correspondence
- 906180463 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies." No written response necessary.
  ENGELERIR H Region 5, San Francisco, Office of the Director 79/05/10, 1p.

- 7904080239 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN, R H 79/05/18 16
- DOCKET 50-29 YANKEE-ROWE NUCLEAR POWER STATION
- F Security, medical, emergency & fire protection plans
- 7906/190227 Subwits add1 info to fire protaction sys re atternatives to increase pumping capacity of fire water supply Diesel-driven fire pump of sufficient capacity will be provided to meet NRC concerns
  HOODY, D E Yankee Atomic Electric Co 79/06/13 ip
- E Financial information
- 7906250267 Forwards annual cash flow info for 1979 to meet ratrospective premium guarantee requirements under Prica-Anderson Act
  SOUCY.A R Yankes Atomic Electric Co 79/06/19 4pp
- P Operating license stage documents & correspondence
- 7905290059 Responds to 790413 request re QA program Suggests revision number of YOQAP-1-A not be designated HEIDER.L H Yankee Atomic Electric Co 79/04/24 1p
- 7906230072 Disagrees W/781016 ltr supporting position that Class III license amend fee is inappropriate for 780605 Proposed Change 161 re low temp overpressure protection sys Requests payment of Class III fee within 15 days MILLER.W O License Fee Management Branch 79/05/17 2pp
- 7904270702 Requests additinform 790322 contingency plan ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 79/05/17 2pp
- 7904050274 Forwards Exxon Nuclear Co 790104 1tr which provides add1 info re Nov 1978 Core XIII fuel examinations OROGE,R R Vankee Atomic Electric Co 79/05/24 20pp
- 7906290024 Forwards draft evaluation of systematic evaluation program Topic II-2 B re obsite meteorological measurements program ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 79/05/29
- 7904080271 Submits add1 info for development of input for review of systematic evaluation program Topic III-5, A re high energy line breaks inside containment GRUCE, R H Yankse Atomic Electric Co 79/05/31 6pp.
- 7906120239 Notifies that licensed operator requalification program may not be completed by 791231 due to cancellation of license date for present reactor operator class AUTIO,H A Yankee Atomic Electric Co 79/05/31 ip
- 7906120316 Maintains that util & its Tatepayers are being penalized for obvious NRC review delinquency Forwards license amend fes under protest VANDENBURGH, D Yankee Atomic Electric Co 79/06/09 2pp
- 7906(30370 Submits \$4,000 licensee fee under protest b w/o waiver of right to claim. Believes rate payers are being penalized for NRC review delinquency
  VANDENBURGH.D Yankee Atomic Electric Co 79/06/03. 2pp
- 7906220193 Bubmits add1 info re steam generator feedwater lines, in response to 790928 request. Four oversized drawings in Central Files anily Add1 info will be forwarded ORGCE.R H Yanker Atomic Electric Co 79/06/13 ip
- 790629040B Responds to NRC 790329 ltr requesting verification of basis on which evaluation of systematic evaluation program Topic II-2 B is based. Data recorded on floppy disk rather than magnetic tape ORQCE, R H Yankee Atomic Electric Co 79/06/25 ip
- G Inspection reports, IE Bulletins & correspondence
- 7906110049 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Buppl" No written response required GRIER.B.H. Region 1. Philadelphia, Office of the Director 79/04/23 ip.

#### DOCKETED ITEMS

- 7904140143 Ack receipt of 790328 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-029/79-02 ERUNNER,E J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 79/04/26 ip
- --7906140146 Responds to NRC 790308 ltr re violations noted in IE Insp Rept 50-029/79-02 Corrective actions procedure for testing valves has been included in "Surveillance Procedure Follow 8ys " MODDY:D E Yankee Atomic Electric Co 79/03/28 2pp
- ---7906140151 Forwards IE Insp Rept 50-029/79-02 on 790213-16 & motice of violation
  BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/08 2pp
- --7906140159 Notice of violation from insp on 790213-16
  Region 1, Philadelphia, Office of the Director 79/03/07
- --7906140164 IE Insp Rept SO-029/79-02 on 790213-16 Noncompliance noted failure to exercise valves within required time period HIGGINS, J C , SMITH, T H Region 1, Philadelphia, Office of the Director CAPHTON, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch, 79/03/07 9pp
- 7906130106 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Hfg by Velan Engineering Corp " Velan valves are used in ECCS Use of corrected weights is compensated for by design code inherent conservatism OROCE:R H Yankee Atomic Electric Co 79/05/02 2pp
- 7906:B014: Forwards summary of 790306 mgt meeting Info presented during meeting resulted in withdrawal of Item B of 781222 notice of violation SMITH.O H Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 79/05/02 2pp
- ---7906:18017: Summary of 790306 mgt meeting w/util in King of Prussia,PA re computerized personnel dosimetry record sys & withdrawal of apparent item of noncompliance SMITH:0 H Region i, Philadelphia, Fuel Facility & Materials Sefety Branch 79/05/02 2pp
- 7906120206 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906:10153 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906260164 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  GRIER.B H Region i. Philadelphia. Office of the Director 79/05/11 1p
- 7906290737 Bupplements 790426 response to IE Bulletin 79-06A Mod to Tech Specs & design changes are unnecessivy MOODY.D E Yankee Atomic Electric Co 79/05/16 2pp
- 7906080112 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U." ORIER.B.H. Region 1. Philadelphia. Office of the Director 79/08/18 ip
- R Periodic operating reports & related correspondence
- 7706170313 Forwards monthly operating rept for May 1979 MODDY, D.E., Yankse Atomic Electric Co 79/06/12 1p.
- --7906190314 Monthly operating rept for May 1979
  BJOGREN.R.M Yankse Atomic Electric Co 79/06/12 6pp
- DUCKET 50-47 ARMY MATERIALS RESEARCH REACTOR
- Q Inspection reports, IE Bulletins & correspondence
- 7906260029 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  ORIER.B H Region 1, Philadelphia, Office of the Director 79/03/11 ip.

- 7906080012 Forwards IE Carcular 79-08, "Attempted Extortion Low Enriched U " ORIER.B H Region 1, Philadelphia, Office of the Director. 79/05/18 ip
- DOCKET 50-54 UNION CARBIDE RESEARCH REACTOR
- P. Operating license stage documents & correspondence
- 7906120276 Ack receipt of Amend 14 to License R-B1 Request clarification of environ considerations in Section C of safety evaluation KONNERTHIC J Union Carbide Corp 79/06/05 2pp
- @ Inspection reports: IE Bulletins & correspondence
- 7906260046 Forward: 16 Info Notice 79-12: "Attempted Damage to New Fur Assemblies " GRIER.B H Region : Philadelphia, Office of the Director 79/05/11 ip
- 7904080045 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ORIER B H Region 1, Philadelphia, Office of the Director 79/05/18 19
- DOCKET 50-57 STATE UNIV OF NEW YORK RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 77062B0153 Requests renewal of License R-77 until Jan 1, 2000 FOGEL,C N New York, State Univ of Buffalo 77/06/14 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906260060 Forwards IE Info Notice 79-12, "Attempted Damage to New Fu Assemblies " GRIER.B H Region 1. Philadelphia, Office of the Director 79/05/11, 1p
- DOCKET 50-59 TEXAS A&M UNIV RESEARCH REACTOR
- P Operating license stage documents & correspondence
- 7906050146 Forwards Amend 12 to License R-23, safety evaluation & notice of issuance 5 availability
  REID:R W Operating Reactors Branch 4 (Pre 790625) 79/04/25
- --7906050190 Amend 12 to License R-23 extending duration of license 970826 & incorporating security plan. GRIMES, B K Assistant Director for Engineers & Projects (Pra 790625) 79/04/25 27pp
- --7906050151 Safety evaluation supporting Amend 12 to License R-23 \* Office of Nuclear Reactor Regulation 79/04/25 13pp
- --7906050152 Notice of issuance & availability & negative declaratic Amend 12 to License R-23. REID.R W Operating Reactors Branch 4 (Pre 790625) 79/04/2 26p
- Q Inspection reports, IE Bulletins & correspondence
- 7906250013 Forwards IE Info Notice 79-12, "Attempted Damage to New I Assemblies " SEYFRIT,K V Region 4, Dallas, Office of the Director. 79/05/
- DOCKET 50-62 UNIV OF VIRGINIA RESEARCH REACTOR
- G. Inspection reports. IE Bulletins & correspondence
- 7906250424 Forwards IE Info Notice 79~12, "Attempted Damage to New Assemblies "
  O'REILLY, J.P Region 2, Atlanta, Office of the Director.
  79/05/10 ip

#### S Reportable occurrences, LERs & related correspondence

7906220239 RG on 790613 fuel element AN-22 was releasing low levels of fission products to reactor coolant Element was removed from core No measurable release of fission products to environ seen SHRIVER.8 L Virginia. Univ of 79/06/15 3pp

# DOCKET 50-70 GENERAL ELECTRIC TEST REACTOR

F Security, medical, emergency & fire protection plans

7906190285 Forwards revised physical security Plan Plan withheld (ref 10CFR2 790) Summarizes changes to plan CUNNINGHAM.G E 79708/07 2pp

#### J Insurance & indemnity information

7908290414 Forwards Endorsements 19.20 & 21 to MAELV Policy MF-95 CORREA.C Harsh & McLenon, M & M Muclear Consultants, Inc. Div 79/06/20 1p

#### @ Inspection reports. IE Bulletins & correspondence

7906:190020 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " ENGELMENR H Region 5. San Francisco. Office of the Director 7908:10. 15

7906080216 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/18 10

#### DOCKET 50-72 UNIV OF UTAH RESEARCH REACTOR

#### P Operating license stage documents & correspondence

7906020230 Forwards Amend 10 to License R-25, safety evaluation/environ impact appraisal & notice of issuance/negative declaration REID:R W Operating Reactors Branch 4 (Pre 790625) 79/03/02

--7906020233 Amend to to License R-25, extending OL duration until 970912 ORIMES, B % Assistant Director for Engineers & Projects (Pre 790625) 79/05/02 30pp

--7906020233 Safety evaluation & EIA supporting Amend 10 to License R-25 \* Office of Nuclear Reactor Regulation 79/05/02 13pp

--7906020236 Notice of issuance & availability of Amend 10 to License R-25 & negative declaration REID:R W Operating Reactors Branch 4 (Fre 790625) 79/05/02 2ap

#### G. Inspection reports, IE Bulletins & correspondence

7906250015 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/11

#### DOCKET 50-73 GENERAL ELECTRIC NUCLEAR TEST REACTOR

E NRC Safety Evaluation Report (BER). supple & correspondence

7906270117 Forwards responses to questions re GETR Phase II geological investigation. DARMITZEL.R M. General Electric Co .Nuclear Energy Products Div 79/06/25 33pp.

# F. Becurity: medical: emergency & fire protection plans

7906190285 Forunds revised physical security plan. Plan withheld (ref 100FR2 790). Summarizes changes to plan CUNNINGHMM. O.E. General Electric Co , Nuclear Energy Products Div 79/06/07. 2pp

#### P Operating license stage documents & correspondence

7906150146 Forwards NEDD-12724, "Requalification Program for GE Nuclear Test Reactor" CUNNINGHAM,0 E General Electric Co 79/06/08 10

7906200273 Forwards renewal application info for License R-33 BARMITZEL.R W Denoral Electric Co , Nuclear Energy Products Div 79/06/13 2pp

--7906200286 "Criticality Emergency Plan, Vallectios Nuclear Ctr "
# General Electric Co., Nuclear Energy Products Div NEDE-12610
79/03/31 18pp

--7906200289 "Radiation Emergency Plan, Vallecitos Nuclear Ctr "
# General Electric Co , Nuclear Energy Products Div NEDE-12610
78/03/31 11pp

7906200292 "Emergency Control Plan-Coneral Vallecitos Nuclear Ctr "
# Ocneral Electric Co , Nuclear Energy Products Div NEDE-12610
78/03/31 19pp

7906220235 Submits schedule for completion of financial 5 environ info 5 SAR Tech Specs re new model for natural circulation mode info submitted for 690613 renewal application for License R-33 .

CUNNINGHAM. © E General Electric Co . Nuclear Energy Products Div 79/06/19 io

7906260003 Provides financial info to demonstrate that Vallecitos fluctear Ctr has resources necessary to operate & shut down decommissioning facility DARMITZEL,R W General Electric Co , Nuclear Energy Products Div 79706/19 2pp

## G Inspection reports. IE Bulletins & correspondence

7906190020 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
ENGELXEN, R H
79/05/10 1p

7906250438 Forwards IE Insp Rept 50-073/79-01 on 790327-29, No noncompliance noted CREMS.J L. Region S. San Francisco, Reactor Operations Nuclear Support Branch 79/03/17 2pp

--7906250442 IE Insp Rept 50-073/79-01 on 790327-29 No noncompliance noted Major areas inspected facility operation, maint \$ surveillance for previous year's activities operator requalification program, procedures, logs & records CANTER, H. L. & MILLER, L. F., FAULKENBERRY, B. Region 5, San Francisco, Reactor Operations Nuclear Support Branch 79/05/16/7pp

7704080214 Forwards IE Circular 77-08, "Attempted Extortion - Low Enriched U " ENGELKEN.R H. Region 5, San Francisco, Office of the Director 79/05/18 10.

#### DOCKET 50-77 CATHOLIC UNIV OF AMERICA RESEARCH REACTOR

O Inspection reports: IE Bulletins & correspondence

7906260078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " ORIER'S H. Region i, Philadelphia, Office of the Director 79/05/11 is

7705080015 Forwards IE Circular 77-08, "Attempted Extortion - Low Enriched U " GRIER, B H Region i, Philadelphia, Office of the Director, 77/05/18 ip.

# DOCKET 50-83 UNIV OF FLORIDA TRAINING HEACTOR

J Insurance & indemnity information

7906070142 Executed Amend 9 to indemnity Agreement E-18 MCARTHUR.S C Florida, Univ of, Gainesville 79/05/23 1p

# P Operating license stage documents & correspondence

7906190286 Forwards operator requalification & recertification program DIAZ.N J , CHANIAN.M J Florida. Univ of Gainesville 79/06/08

--7906190287 Operator requalification & recertification program for 790701-810630

\* Florida, Univ of, Gainesville 79/06/08 Spp

#### G Inspection reports, IE Bulletins & correspondence

7906250422 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
O'REILLY, J P Region 2, Atlanta, Office of the Director 77/09/10 ip

# DOCKET 50-84 UNIV OF CALIFORNIA RESEARCH REACTOR

#### J Insurance & indemnity information

7906260395 Forwards executed Amend 8 to Indemnity Agreement E-16, Amend 4 to Indemnity Agreement E-58, Amend 8 to Indemnity Agreement E-53 A Amend 13 to Indemnity Agreement E-15 DENESS, 8 J California, Univ. of, Berkeley 79/06/21 5pp

#### DBCKET 50-87 WESTINGHOUSE CRITICAL EXPERIMENT

G Inspection reports, IE Bulletins & correspondence

7706190040 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11

7906080147 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" KEPPLER, J O Region 3, Chicago. Office of the Director 79/05/18

7906260203 Forwards IE Insp Rept 50-087/79~02 on 790509~10 No noncompliance noted HIND, J A Region 3, Chicago, Safeguards Branch 79/05/24 2pp

--7906260207 IE Insp Rept 50-087/79-02 on 790509-10 No noncompliance noted Major areas inspected security organization, access control, alarm sus, surveillance & sabotage protection Details withheld (ref 10CFR2 790)
CHRISTOFFER, 0 . BCHAPER, J F . HIND, J A Region 3. Chicago, Safeguerds Branch 79/05/21 1p

#### DOCKET 50-89 GENERAL ATOMIC CO

#### J. Insurance & indemnity information

7906190415 Forwards Endorsement 29 & 30 to MAELU Policy MF-59 CORREA.M A Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/14 Gpp

## G. Inspection reports, IR Bulletins & correspondence

7906190016 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies " ENGELKEN:R H Region 5: San Francisco, Office of the Director 79/05/10 ip.

7704080219 Forwards IE Circuler 79-08, "Attempted Extortion — Low Enriched U " ENGELKENR H, Region 5, San Francisco, Office of the Director 79/05/18 1p DOCKET 50-94 ROCKHELL INTERNATIONAL RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7906180436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assamblies " No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 77/05/10 ip

79060B0224 Forwards IE Circular 79-08, "Attempted Extortion ~ Low Enriched U" ENGELKER, R H Region 3, San Francisco, Office of the Director 79/05/18 to

#### DOCKET 50-97 CORNELL UNIV ZERO POWER REACTOR

@ Inspection reports, IE Bulletins & correspondence

7906260075 Forwards [E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 1p

7904080021 Forwards 1E Circular 79-08, "Attempted Extortion - Low Enriched U " GRIER, B H Region 1. Philadelphia, Office of the Director

#### DOCKET 50-99 BABCOCK & WELCOX TEST REACTOR

Q Inspection reports, 1E Bulletins & correspondence

7906250436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
O'REILLY, J.P. Region 2, Allanta, Office of the Director 79/05/10 is

#### DOCKET 50-106 GREGON STATE UNIV

Q Inspection reports. IE Bulletins & correspondence

7906180451 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/05/10 ip

7906080228 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U" ENGELKEN, R H Region 5, San Francisco, Office of the Director 790/05/19

DOCKET 90-111 NORTH CAROLINA STATE UNIV RESEARCH REACTOR

G Inspection reports, 16 Bulletins & correspondence

- 906210351 Ack receipt of 790419 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-111/79-01 50-297/79-01 & 70-0041/79-01 KENNA,H B Region 2. Atlanta, Safeguards Branch 79/05/03 ig
- -7906210354 Responds to NRC 790327 ltr re violations nated in IE Insp Repts 50-111/79-01,50-297/79-01 & 70-0041/79-01 Corrective actions form 742 prepared properly & copy for period Oct 1978 Mar 1979 forwarded to Region [I ELLEMAN, T & North Carolina State Univ 79/04/19 1p
- -7906210387 Forwards IE insp Repts 50-111/79-01.90-297/79-01 & 70-0041/79-01 on 790220-21 Notice of violation withheld (ref 100FR2 790) Region 2, Atlanta, Safeguards Branch 79/03/27 KENNA U 0
- --7906210396 IE Insp Repts 50-111/79-01.50-297/79-01 & 70-0041/79-01 on 790220-21 Noncomplishee noted failure to measure & rept accountability values reproduction & consumption of SNM Details withheld (ref 10CFR2 790) TODD.6 A . WILLIAMS.9 H Region 2. Atlanta, Office of the Director 79/03/08 ip
- 1908250414 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies 0'REILLY, J P 79/05/10 1 Region 2. Atlanta. Office of the Director

# DOCKET 30-112 UNIV OF OKLAHOMA RESEARCH REACTOR

- J. Insurance & indemnity anformation
- 7906(50343 Executed Amend 9 to Indomnity Agreement E-26 SALTZMAN.J Antitrust & Indomnity Group 79/06/11
- l'Inspection reports: IE Bulletins & correspondence
- '906250014 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT.K V Region 4. Dailas, Office of the Director 79/05/11
- MCKET 50-113 UNIV OF ARIZONA RESEARCH REACTOR
- l'Inspection reports, lE Bulletins & correspondence
- '906180458 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN.R H Region 5. San Francisco, Office of the Director
- '904080232 Forwards lE Circular 79-08. "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5. San Francisco, Office of the Director 79/05/18
- DOCKET 50-116 IGHA STATE UNIV RESEARCH REACTOR
- / Insurance & indemnity information
- 7900120366 Requests confirmation of understanding of effect of indamity coverage under Agreement E-5 of Price-Anderson Act re decommissioning activities of Kaiser Engineering Inc Hogan & Hartson 79/06/07 Jpp

- 7906080186 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U ' Region 3: Chicago, Office of the Director 79/05/18 10
- 7906260622 Ack receipt of IE Circular 79-08 Will review security procedures for all low enriched U matl presently on hand PLANJE, T J Missouri, Univ. of 79/05/22 ip
- DOCKET SO-124 VIRGINIA POLYTECH INST TRAINING REACTOR G Inspection reports, IE Bulletins & correspondence
- 7904020174 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-124/79-02 O'REILLY, J P Region 2: Atlanta. Office of the Director 79/05/10 2pp
- --7906020178 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 50-124/79-2 Corrective actions all procedures being rewritten & monthly reactor operator meetings held PARKINSON. TF Virginia Polytechnic Institute & State Univ 79/04/18 3pp
- --7906020183 Forwards 1E Insp Rept 50-124/79-02 on 790130-0202 & notice occupants recognize any Rept 30-124//9-02 on /90130-0202 & of violation
  LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7906020197 Notice of violation from insp on 790130-0202
  \* Region 2, Atlanta, Office of the Director 79/03 79/03/23 2pp
- --7906020191 IE Insp Rept 50-124/79-02 on 790130-0202 Noncompliance noted failure to document licensed reactor operator re qualification records & failure to provide & maintain procedures in conducting operations
  JULIAN.C A . SAUER.R C Region 2, Atlanta, Office of the
  Director MARTIN.R D Region 2, Atlanta, Reactor Operations
  Nuclear Support Branch 79/03/23 lipp
- 7906250421 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " Region 2, Atlanta, Office of the Director 79/05/10
- DOCKET 50-128 TEXAS AM UNIV RESEARCH REACTOR
- P Operating License stage documents & correspondence
- 7906190270 Submits addl info re Tech Spec change request to allow radiography of explosive math, in response to NRC 790607 RANDALL, J D Texas A & M Univ 79/06/13 3pg
- O Inspection reports. IE Bulletins & correspondence
- 7906250013 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies ' SEYFRIT, K V Region 4. Dallas, Office of the Director 79/05/11
- DOCKET 50-129 WEST VIRGINIA UNIV RESEARCH REACTOR
- J Insurance & indemnity information
- 7906190371 Executed Amend 9 to Indemnity Agreement E-27 SALTZMAN,J Antitrust & Indemnity Oroup, 79/06/13 ip
- P Operating license stage documents & correspondence
- 7906070240 Requests temporary extension of License R-52 to allow time for decommissioning & amending of License C 4 to permit transfer of fuel to swittably licensed party SLACKIS T., KOPPELMAN,R Hest Virginia Univ 79/05/30 ip
- 7906190251 Requests that License R-58 be extended temporarily for 12 months, to allow time for decommissioning Also requests that Condition C 4 be amended to allow transfer of fuel to auitably party SLACK, S. T. KOPPELMAN, R West Virginia Univ 79/09/30 ip
- Q Inspection reports, IE Bulletins & correspondence
- 7906250418 Forwards IE Info Notice 79-12, "Attempted Demage to New Fuel Assemblies "
  D'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10

DOCKET 50-130 PATHFINDER ATOMIC PLANT

- G Inspection reports, IE Bullatins & correspondence
- 7906290125 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI incident CRANE.P A Pacific Gas & Electric Co 79/05/01 5pp

DOCKET 50-131 OMAHA VET ADMIN HOSP RESEARCH REACTOR

G Inspection reports. IE Bulletins & correspondence

7906250003 Forwards IE Info Notice 79-12, "Attempted Damage to New Fwel Assemblies"
SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/11

DOCKET 50-133 HUMBOLDT BAY POWER PLANT, UNIT 3

- **Q** Adjudicatory correspondence
- 7906040384 Holds proceedings in abeyance until 791001 Licensee shall furnish rept re status of guologic invetigation within ten days after receipt of order & every 60 days thereafter LUTCH, E Atomic Bafety and Licensing Board Panel 79705/07 1p
- O Inspection reports, IE Bulletine & correspondence
- 7906140399 Schedule for responses to IE Bulletins 79-02 & 79-03 will be submitted after resolution of seismic issues currently being studied CRANE.P A Pacific Gas & Electric Co 79/04/25 1p
- 7904130132 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required. ENGELERN.R H Region 5, San Francisco, Office of the Director 79/05/02 ip
- 7906120047 Forwards IR Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/09/07 1p
- 7906180479 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN.R H Region 5. Ban Francisco. Office of the Director 79/05/10 10
- 7906110070 Forwards IE Builetin 79-10, "Requalification Training Program Statistics " Written response required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/08/11 ip
- 7906080241 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN,R H Region 5, San Francisco, Office of the Director, 79/05/18, ip
- 7904130042 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licenses action required ENDELKEN.R H Region 5, San Francisco, Office of the Director 79/05/22 Ip
- 7906180373 Forwards IE Bulletin 79-12, "Short Period Screm at BWR Facilities "Licensee action required ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/31. 1p
- R Periodic operating reports & related correspondence
- 7906150288 Forwards monthly operating rept for May 1979 WEEKS,E D Pacific Oas & Electric Co 79/06/07 1p
- --7906130290 Monthly operating rept for May 1979.

  OETTY, B C Pacific Gas & Electric Co. 79/05/31 App.
- S Reportable accurrences, LERs & related correspondence
- 7905040360 PNO-79-67AI summary of info re nuclear incident as of 790428 Describes plant & environ status

  # Office of Inspection & Enforcement 79/04/28 2pp

- 7906180219 Forwards PNO-79-67AN ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/14 10
- 7906180265 Forwards PNO-79-67AO ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/21 1p
- 7906180338 Forwards PNO-79-67AP ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/22 1p
- 7906180364 Forwards PND-79-67AQ ENGELMEN, R H Region 5, San Francisco, Office of the Director 79/05/30 1p
- 7906190519 Forwards LER 79-003/03L-0 CRANE,P A Pacific Oas & Electric Co 79/06/12 1p
- --7906190525 LER 79-003/03L-0 on 790513 fire water sys header low pressure switch APS-18 started fire pumps at 41 psig instead of 45 psig Caused by drift & close differential setting Setpoint adjusted Switch will be replaced CHAFFEE,R 8 Patific Gas & Electric Co 79/06/12 1p
- 7906270221 Forwards LER 79-004/03L-0 CRANE, P A Pacific Gas & Electric Co 79/06/15 1p
- --7906270223 LER 79-004/03L-0 on 790516 refueling bldg ventilation supported to butterfly valve stem Procedures improved for attachment of arm to stem REDEKER, S. J. Pacific Gas & Electric Co. 79/06/15. App
- DOCKET 50-134 WORCESTER POLYTECH INST RESEARCH REACTOR
  P Operating license stage documents & correspondence
- 7906230054 Responds to LC Wilbur 790423 request re renewal of License R-61 which will expire 791123 Submits specific items that will be reviewed prior to license renewal REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/14
- Q Inspection reports. IE Bulletins & correspondence
- 7906260063 Forwards IE Info Notice 79-12, "Attempted Damage to New Fue Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 10
- 7904080037 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" ORIER.B H Region I, Philadelphia, Office of the Director 79/05/18 1p

DOCKET 50-139 UNIV OF WASHINGTON RESEARCH REACTOR

- Q Inspection reports, IE Bulletins & correspondence
- 7906180462 Forwards IE Info Notice 79-12, "Attempted Damage to New Fue Assemblies " No written response necessary ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/10.
- 7906080238 Forwards 1E Circular 79-08, "Attempted Extortion Low Enriched U" ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/09/18. 1p
- DOCKET 50-141 STANFORD UNIV RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 7906150355 Forwards IE Insp Rept 50-141/79-01 on 790131 & 0313 No noncompliance noted BQQK.H E Region 5. Ban Francisco, Fuel Facility & Materials Safety Branch 79/03/27 2pp
- --7904150357 IE Insp Rept 50-i41/79-01 on 790131 & 0313 No noncompliar noted Major areas inspected facility that previously housed pool type research reactor CURTIS, J R Region 5, San Francisco, Office of the Director BUOK, H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/03/27 3pp

DOCKET 50-142 UCLA TRAINING REACTOR
J Insurance & indemnity information

7706260395 Forwards executed Amend 8 to Indemnity Agreement E-16, Amend 4 to Indemnity Agreement E-58, Amend 8 to Indemnity Agreement E-53 & Amend 13 to Indemnity Agreement E-15 DENESS, 8 J California, Univ of, Berteley 79/06/21 5pp

P Operating license stage documents & correspondence

7906150402 Requests renewal of License R-71 due to expire on 800331 CATTON, I California, Univ of, Los Angeles 79/05/25 ip

@ Inspection reports. IE Bulletins & correspondence

7906180454 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/10 ip

7904080234 Forwards IE Circular 79-08, "Attempted Extortion - Lew Enriched U "
ENOELKEN,R H Region 9, San Francisco, Office of the Director 79/09/18 1p

DOCKET 50-146 SAXTON NUCLEAR EXPERIMENTAL FACILITY
H General correspondence

7906210003 Ack receipt of 790411 request to witness facility insp Licensee, not NRC, has authority to allow reporters to be present Protocol/waiver agreement for accompaniment of NRC insp encl SNYDER.O.L. Region I, Philadelphia. Office of the Director 79/06/19 3pp

J Insurance & indemnity information

7906120297 Forwards Endorsement 71 to ANI Policy NF-107
MONTGOMERY, C R Saxton Nuclear Experimental Corp 79/06/07 2pp

DOCKET 30-148 UNIV OF KANSAS RESEARCH REACTOR
J Insurance & Indomnity Information

7906270210 Forwards Amend 9 to Indemnity Agreement E-21 MALLENSECK, C A Kansas, Univ of 79/06/20 2pp

Q Inspection reports, IE Bulletins & correspondence

7904230007 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" SEYFRIT.K V Region 4. Dallas. Office of the Director 79/05/11 ip

DOCKET 30-130 ORIO STATE UNIV RESEARCH REACTOR

G inspection reports, IE Bullatins & correspondence

790619004B Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/11

7906080174 Forwards IE Circular 79-08, "Attempted Extertion - Low Enriched U" KEPPLER: J G Region 3. Chicago: Office of the Director 79/05/18

DOCKET 50-151 UNIV OF ILLINGIS RESEARCH REACTOR

J Insurance & indemnity information

7906200455 Executed Amend 12 to Indomnity Agreement E-20 BALTIMAN, J. Antitrust & Indomnity Group 79/06/14 ip

Q. Inspection reports, IE Bulletins & correspondence

7906190062 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

KEPPLER, J. O Region G. Chicago, Office of the Director 79/05/11

790A080181 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " KEPPLER.J O Region 3. Chicago, Office of the Director 79/05/18 19

DOCKET 50-155 BIG ROCK POINT NUCLEAR PLANT

F Security, medical, emergency & fire protection plans

7906040189 Requests addl info re fire protection insulation on cabling in recirculating gump area Evaluation of need for protective insulation on recirculating pump area cabling & associated valve operators to be completed by 790615

BIXEL, D.A. Consumers Power Co. 79/05/30 ip

7906200172 Discusses need for fire protective insulation on cables & valve operators in recirculating pump room Insulation not necessary
HOFFMANN.D P Consumers Power Co 79/06/15 4pp

P Operating license stage documents & correspondence

7906210134 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station numbers of onsite & offsite environ monitoring stations & maps used for offsite dose determination XEPPLER. J 0 Region 3. Chicago, Office of the Director 79/05/17

7906190174 Submits response to 790607 rapid response questions re effluent monitoring sys HOFFMAN, D.P. Consumbrs Pauer Co. 79/06/14 4pp

790626D188 Corrects 790614 response to questions re effluent monitoring sys BIXELD A Consumers Power Co 79/06/22 1p

7906260194 Forwards comments re systematic evaluation program deletions proposed in NRC 790416 ltr BIXEL,D A Consumers Power Co 79/06/22 3pp

7906280]63 Forwards request for change to Tech Specs, permitting mod of spent fuel storage pool by addition of storage racks BIXEL.D A Consumers Fower Co 79706/26 5pp

@ Inspection reports. IE Bullatins & correspondence

7906140611 Forwards IE Insp Rept 50-195/79-06 on 790403-06 No noncompliance noted HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/04/14 2pp

--7906140616 IE Insp Rept 50-155/79-06 on 790403-06 No noncompliance noted Major areas inspected preparation for refueling processipre-fuel handling activities, fuel handling activities to mod of containment supply ventilation valve STRECTER. J F, REVES. L Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/13 5pp

7906210329 Forwards IE Insp Rept 50-155/79-01 on 790214-16 & 0403 No noncompliance noted FIGRELLI,O Region 3. Chicago, Reactor Construction & Engineerin Bupport Branch 79/04/18 2pp

--7706210334 (E Insp Rept 50-155/79-01 on 770214-16 & 0403 No noncompliance noted, Major areas inspected safety-related hangers & mechanical snubbers observation of installation conditions & review of previous license surveillance YIN, I T, DANIELSON.D H Region 3. Chicago, Office of the Director 77/04/16 4pp

7906020047 Responds to IE Bulletin 79-07 re seismic analyses Dynamic analyses of piping were performed by reactor vendor & A/E Requested info will be submitted in one month BIXEL.D. A Consumers Power Co 79/04/24 ip.

7906050430 Notifies that preliminary review of 790201 description of inservice test program for pumps & valves & request for relief from specific ASME code requirements is complete. Forwards questions & comments ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 79/04/2: 8pp.

7906020163 Responds to LE Bulletin 79-04 re incorrect weights for swilcheck valves afg by Velan Engineering Corp Velan valves not in use BIXEL.D A Consumers Power CO 79/05/01, ip.

- 7906140246 Forwards response to IE Bulletin 79-08 Reviews procedures for dealing w/TMI-2 incident circumstances
  BIXEL.D.A Consumers Power Co 79/05/04 13pp
- 7706120098 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07 to
- 7906080093 Forwards IE Insp Rept 50-155/79-05 on 790326-30 Notice of Violation withheld (ref 100FR2 790)
  HIND. J A Region 3, Chicago, Safeguards Branch 79/05/09 2pp
- --7904080101 IE Insp Rept 50-155/79-05 on 790326-30 Noncompliance noted nonconformance in lighting access control-vital areas & access control-search Details withheld (ref IOCFR2 790) HADEDA.T J. HOWELL, J C. HIND, J A. Region i. Philadelphia, Bafeguards Branch 79/05/04 2pp
- 7906110096 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics "Written response required KEPPLER.J O Region 3, Chicago. Office of the Director 79/05/11
- 7906190088 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906080200 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " KEPPLER.J O Region 3, Chicago. Office of the Director 79/05/18
- 7906230045 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers Describes preventative maint program BIXEL.D A Consumers Pawer Co 79/05/21 2pp
- 7906130074 Porwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Bafety Rys " Licensee action required KEPPLER.J G Region 3, Chicago. Office of the Director 79/05/22
- 7904200103 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/29
- 8 Reportable occurrences, LERs & related correspondence
- 7906120160 Bubmits info re control rod drive housing penetration design for leakage discovered during 790420 hydrostatic testing & reported in LER 79-18 on 790502 Describes additecting to be parformed Moyersized drawing BIXEL.DA Consumers Power Co. 79/06/07 Spp
- 7906260353 Forwards LER 79-020/01T-0 BIXEL,D A. Consumers Power Co 79/06/22. 1p
- --7906260377 LER 79-020/01T-0 on 790609 vibration heard in primary sys w/recirculation pump in svc Discovered diffuser dislodged in pump i inlet & loose diffuser in pump 2 inlet Caused by failure of bolts holding diffuser for reasons unknown a Consumers Power Co. 79/06/22 2pp
- DOCKET 50-156 UNIV OF WISCONSIN RESEARCH REACTOR
- G. Inspection reports. IE Bulletins & correspondence
- 7906190056 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."

  KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11
- 7904080191 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U "
  KEPPLER. J. O Region 3, Chicago, Office of the Director 79/05/18
  ip.
- DOCKET 50-157 CORNELL UNIV RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 7908280075 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."
  ORIER. B. H Region 1, Philadelphia, Office of the Director 77/05/11 1p.

- 7906080021 Forwards IE Circular 79~08, "Attempted Extortion Low Enriched U " GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/18 ip
- DOCKET 50~160 GEORGIA INST OF TECH RESEARCH REACTOR
- J Insurance & indemnity information
- 7906270209 Forwards Amend 12 to Indeminty Agreement E-30 WILBON, J W Georgia Institute of Technology 79/06/22 2pp
- G Inspection reports. IE Bulletins & correspondence
- 7906250413 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " O'REILLLY,J P Region 2. Atlanta. Office of the Director 79/05/10 lp
- DOCKET 50-163 GENERAL ATOMIC COMPANY
- J Insurance & indomnity information
- 7906190415 Forwards Endorsement 29 & 30 to MARLU Policy MF-59 CORREALM A Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/06/14 3ps
- G Inspection reports, IE Bulletins & correspondence
- 7906190016 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  ENGELKEN,R H Region S, San Francisco, Office of the Director 79/05/10 in
- 7906080219 Forwards IE Circular 79-08, "Attempted Extortion Low Enrichad U " ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/18 io
- DUCKET 50-166 UNIV. OF MARYLAND RESEARCH REACTOR
- J Insurance & indemnity information
- 7906130319 Forwards executed Amend 9 to Indemnity Agreement E-22 TOLL. J S Maryland. Univ of 79/06/07 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906260062 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies," ORIER.8 H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906080034 Forwards IE Circular 77~08. "Attempted Extertion Low Enriched U."
  QRIER.8 H Region 1. Philadelphia. Office of the Director 79/05/18 ip

#### S Reportable occurrences, LERs & related correspondence

7906040341 Forwards LER 78-011/047-0 COONEY, M J Philadelphia Electric Co 78/03/07 2pp

--7706040345 LER 78-011/04T-O on 780223 approx 40 gailons tight diesel fuel oil drained into discharge canal Caused by valve left open after use Spillage stopped upon discovery, cleanup initiated & valve locked to control use COUNEY, M J Philadelphia Electric Co 78/03/07 lp

#### DOCKET 50-182 PURDUE UNIV RESEARCH REACTOR

F Security, medical, emergency & fire protection plans

7906120180 Forwards modified physical security plan Plan withheld (ref 10CFR2 790) CLIKEMBN.F M Purdue Univ 79/06/09 1p

# G Inspection reports, IE Bulletins & correspondence

7906080123 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE insp repts
HIND, J A Region 3, Chicago, Safeguards Branch 79/05/08 1p

--7906080130 Responds to NRC 790326 itr re violations noted in IE insprepts Corrective actions withhald (ref 10CFR2 790) CLIKEMAN.F M Purdue Univ 79/04/19 2pp

7906;9005; Forwards IE Info Notice 79-12. "Attempte6 Damage to New Fuel Assemblies"
KEPPLER.J 0 Region 3, Chicago, Office of the Director 79/05/11

7906080176 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18

# DOCKET 50-184 NATIONAL BUREAU OF STANDARDS REACTOR

G inspection reports, IE Bulletins & correspondence

7908260026 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
GRIER.B H Region 1. Philadelphia, Office of the Director 79/05/11 in

7906080014 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched V" ORIER:8 H Region 1: Philadelphia: Office of the Director 79/05/18 10

#### DOCKET 50-186 UNIV OF MISSOURI RESEARCH REACTOR

O Inspection reports, IE Bulletins & correspondence

DOCKET 50-188 KANSAS STATE UNIV RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

7906250006 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/11

DOCKET 50-192 UNIV OF TEXAS RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

7906250012 Forwards LE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" SEYRIT, K V Region 4. Dallas. Office of the Director 79/05/11

DOCKET 50-193 RHODE ISLAND & PROVIDENCE PLANTATIONS AEC

7908260025 Forwards [E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1. Philadelphia. Office of the Director 79/05/11 1p

DOCKET 50-199 MANHATTAN COLLEGE RESEARCH REACTOR

@ Inspection reports, IE Bulletins & correspondence

7906260080 Forwards IE Info Notice 79-12, "Attempted Damage to New Fue Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 1p

7906080022 Forwards IE Circular 79-08. "Attempted Extortion - Low Enriched U " CRIER.8 H Region 1. Philadelphia. Office of the Director 79/03/18 ip

#### DOCKET 50-201 WEST VALLEY REPROCESSING PLANT

H General correspondence

7906210261 Responds to 790124 ltr re effects of radioactive waste on bodies of water surrounding NY State & effects of stored wastes on environ RDUSE.L C Fuel Reprocess & Recycle Branch 79/04/20 Opp

---7906210266 Requests info re environ effects of radolactive wastes at plant site ECKERHAN.H Affiliation Unknown 79/01/24 1p

790622D142 Ack receipt of 790309 ltr & 790326 telcon Buggests use of local PDR to obtain info Melcomes attendance at moetings between NRC & vendor Forwards safety evaluation re fuel receipt & storage area M/o encl HAUOHNEY.C T Fuel Process & Feb Branch 79/05/04 3pp

7906220471 Forwards requested info re discovery of pan defect at Nuclear Fuel Svcs.Inc.summary of NRC 790123 meeting re pan defect & summary of NRC 790327 meeting re investigation & evaluation of defect W/o encl HAUGHNEY.C J Fuel Reprocess & Recycle Branch 79/05/QB 3pp

#### P Operating license stage documents & correspondence

7906050362 Responds to 790321 telegram requesting NRC presence at 790404 hearing Bince tank safety investigation is continuing, final conclusions about safety margins for tanks cannot be made.

DIRCKS, M. J. Office of Nuclear Material Safety & Safeguards 79/04/02 2pp.

---7906050370 Requests NRC appear before 790404 legislative commiss: energy sys hearing to discuss safety questions re high lavel radioactive waste tanks operated by licensee HOYT.W B New York, State of 79/03/21 lp.

7906250220 Ack receipt of documents re condition of high level liquests storage sqs at West Valley, NY facility.
HDYT, W. B. New York, State of 79/04/16 ip

- 7906250049 Summary of 790215 meeting w/NFG in Silver Spring.MD re offerts to process technical data useful for future contamination b decommissioning b present efforts to investigate BD-2 pan defect HAUGHNEY.C J Fuel Reprocess & Recycle Branch 79/05/01
- 7904250069 Notification of 790516 meeting w/NY State Energy R&D Authority & NFS to discuss progress of efforts re technical info for future decontamination & to investigate 8D2 pan defect.
  - HAUGHNEY, C J Fuel Reprocess & Recycle Branch 79/05/01 2pg
- 7906230179 Summary of 790501-02 meeting w/NFS at West Valley.NY facility to obtain site data on safety of high level waste storage CLARK.A T Fuel Process & Fab Branch 79/05/08 3pp
- 7704280485 Forwards UCRL-52575, "Structural Analyses of Fuel Receiving Station Pool at NFS Reprocessing Plant, West Valley, NY" & topical rept evaluation W/790307 comments from WJ Hall of NM Newmark Consulting Engineering Svcs ROUSE, L. C Fuel Reprocess & Recycle Branch 79/05/14 Spp
- --7906250487 "Structural Analysis of Fuel Receiving Station Pool at NFS Reprocessing Plant/West Valley.NY "
  DONG, R O Lawrence Livermore Laboratory NRC-03-78-150
  UCRL-52575 78/05/05 62pp Available at NTIS
- 7906250489 Topical rept evaluation of UCRL-52575. "Structural Analyses of Fuel Receiving Station Pool at NFS Reprocessing Plant.
  West Valley.NY "

  Fuel Reprocess & Recycle Branch 79/05/14 4pp
- 7906210129 Discusses NRC 790329 & 0123 memos re defect in pan under high level liquid waste tank at reprocessing plant.in response to Jan 1979 request ROUSE.L C Fuel Reprocess & Recycle Branch 79/05/21 2pp
- O Inspection reports, IE Bulletins & correspondence
- 7906260040 Forwards IE Info Notice 79~12, "Attempted Damage to New Fuel Assemblies " CRIER, B H Region i, Philadelphia, Office of the Director 79/05/ii ip
- BOCKET SO-206 SAN UNDFRE NUCLEAR STATION, UNIT 1

  P Operating license stage documents & correspondence
- 7906040424 Forwards draft evaluation of systematic evaluation program Topic XV-19 re LOCA resulting from spectrum of postulated pipting breaks within reactor coolant pressure boundary Requosts input within 30 days ZIEMANN,D L Operating Reactors Branch 2 (Pre 790625) 79/03/15
- 790.6080233 Forwards draft evaluation of systematic evaluation program Topic IV-1 A. "Operation W/Less Than All Loops in Svc "Reguests review & response within 30 days ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 79/04/30 12bo
- 7906060283 Forwards comments on systematic evaluation program Topic VI-10 B, "Shared Engineered Safety Features. Onsite Emergency Power & Svc Sys for Multiple Unit Stations"

  HAYNES.J G Southern California Edison Co 79/05/17 2pp
- 7906060271 Offers no comments on NRC redraft evaluation of systematic evaluation program Topic IV-1 A Proposed Tech Spec changes to be submitted by 790608 HAYNES.J O Southern California Edison Co 79/05/25 ip
- 7906040167 Forwards corrections to Figures 6 2 2 2 3 5 2-2 repergranization changes Figures supersede corresponding figures of Proposed Change 77
  BASKIN, K P Southern California Edison Co 79/05/31 3pp
- 7906140468 Forwards Amend 80 to License DPR-13 consisting of proposed Tech Specs Change 80
  DRAKE, J H Southern California Edison Co 79/06/11 1p
- ---7906140472 Amend 80 to License DPR-13, consisting of proposed Tech Specs Change 80 to restrict operation w/less than all reactor coolent loops in svc Certificate of Svc encl \* Southern California Edison Co. 79/06/08 10pp

- 7906220358 Forwards info requested in NRC 781208 itr re systematic evaluation program Topic VIII-4 re electrical penetrations of reactor containment HAYNES.J O Southern California Edison Co 79/06/15 13pp
- @ Inspection reports, IE Bullatins & correspondence
- 7906200134 Responds to NRC 790411 ltr re violation noted in IE Insp Rept 50-206/79-04 Corrective actions three design changes have been reviewed by all licensed operators MDDREJ B Southern California Edison Co 79/05/01 2pp
- ---7906200141 Forwards 1E Insp Rept 50-206/79-04 on 790216 % 03±3-15 % notice of violation CREWS.JL Region 5. San Francisco. Office of the Director 79/04/11 2pp
- --7906200144 Netice of violation from insp on 790216 & 0313-15 \* Region 5, San Francisco, Office of the Director 79/04/11 1p
- --7906200149 IC Insp Rept 50-206/79-04 on 790216 % 0313-15
  Nuncompliance noted failure of reactor operator retraining
  program to review facility design changes
  CANTER, H L , JGHNBON, P
  Director FAULKENBERRY, B
  Region 5, San Francisco, Office of the
  Operations Nuclear Support Branch 79/04/11 Spp
- 7906210348 Responds to IE Bulistin 79-06A & Revision & Operating personnel have been instructed that pressurizer level indications may not provide reliable transient or accident conditions IE bulletins re TMI are distributed for review DRAKE.J H Southern California Edison Co 79/05/03 13pp
- 790612003; Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/07 ip
- 7906270126 Recommends that NRC study potential use of nuclear instrumentation (source & intermediate) to determine eristence of voids re IE Bullettin 79-066. Revision I WILLIAMS.FJ Division of Project Management 79/05/09 ip
- 7906180481 Forwards [E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELMEN.R H Region 3. Gan Francisco. Office of the Director 79/05/10 to
- 7906110075 Forwards IE Bullstin 79-10, "Requalification Training Program Statistics " Written response required ENGELKEN,R H Region S. San Francisco, Office of the Director 79/05/11 1p
- 7906250453 Forwards IE Insp Rept 50-206/79-06 on 790410-11 No noncompliance noted CREMS.J.L. Region 5. San Francisco, Reactor Operations Nuclear Support Branch 79/05/11 2pp
- --7906230472 IE Insp Rept 50-206/79-06 on 790410-11 No moncompliance noted Major areas inspected verification of IE Bulletin 79-09A; examination of licensee plant review of features similar to THI design CANTER, H L , FAULKENBERRY, B Region 5, San Fiancisco, Reactor Operations Nuclear Support Branch 79/05/10 3pp
- 7906080243 Forwards IE Circular 79-08, "Attampted Extertion Low Enriched U " ENGELKEN,R H Region S. San Francisco, Office of the Director 79/05/18
- 7906130047 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/22 is
- 7904200034 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Ogster Creek Reactor" ENBELKEN,R H. Region 5, San Francisco, Office of the Director 79705/29 10
- R. Periodic operating reports & related correspondence
- 7906130289 Forwards monthly operating rept for May 1979 CURRAN, J M Southern California Edison Co 79/06/06 1p

- --7906130291 Honthly operating rept for May 1979
  RODRIGUEZ.J P Bouthern California Edison Co 79/06/06 Spp
- B Reportable occurrences, LERs & related correspondence
- 7906180225 Forwards PNO-79-67AN ENGELKEN, R H Region 5. San Francisco: Office of the Director, 79/05/14 ip
- 7906180273 Forwards PNG-79-67AG ENGELKEN,R H Region 5. Ban Francisco: Office of the Director 79/08/21 1p
- 7906180341 Forwards PNO-79-67AP ENGELKEN.R H Region 5. San Francisco: Office of the Director 79/05/22 1p
- 7906180360 Forwards PNO-79-67A0 ENGELKEN,R H Region 5, San Francisco. Office of the Director 79/05/30 1p.
- 7906220314 Forwards LER 79-010/01T-0
  MODRE, J B Southern California Edison Co 79/06/15 1p
- --7906220325 LER 79-010/017-0 on 790605 radiography revealed linear indications in steam generator feedwater notice during maint outage Caused by stress assisted corrosion Reducers replaced & welds redone CURRAN, J M Southern California Edison Co 79/06/15 ip
- 7906200345 Responds to NRC 790525 request Forwards three oversized drawings, "Steam Generator Notice to Piping Insp & Corrective Action." & "Susceptability to Steam Generator Freedwater Line Water Hammer Events."

  HAYNES, J G Southern California Edison Co 79/06/18 12pp
- --7906200347 Interim rept "Steam Generator Nozzle to Piping Snep & Corrective Action"

   Southern California Edizon Co 79/06/13 2ipp
- --7906200351 "Susceptability to Steam Generator Feedwater Line Water Hammer Events" \* Southern California Edison Co 77/12/31 Spp
- 7906220402 Forwards LER 79-009/017-0 MCORE.J B Bouthern California Edison Co 79/06/18 2pp
- --7906220404 LER 79-008/01T-0 on 790604 during maint outage:18 defective tubes discovered in steam generator A Caused by corrosion of area of tubesheet Defective tubes plugged CURRAN, J. M. Southern California Edison Co. 79/06/18 3pp
- 7906220335 Forwards LER 79-009/01T-0 HOORE, J B Southern California Edison Co 79/06/19 3pp
- ---7906220346 LER 79-009/017-0 on 790605 snubber failure discovered during functional testing Caused by water hammer from misadjustment of feedwater regulating valve control circuit.Control circuit repaired & readjusted CURRAN.J M Southern California Edison Co 79/06/19 ip

DOCKET 50-208 COLUMBIA UNIV. REBEARCH REACTOR

G. Inspection reports, lE Bulletins & correspondence

-8 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel les "
slobie. Office of the Director

#### J Insurance & indemnity information

- 7906190424 Forwards Endorsements 55 & 56 to MAELU Policy MF-39
  CONNELL, T Connecticut Yankse Atomic Power Co 79/06/12 3p;
- 77062604B0 Forwards Endorsements 60 & 61 to NELIA Policy NF-151 BEGER, R M Northeast Utilities 77/06/22 3pp
- P Operating license stage documents & correspondence
- 7906050224 Forwards draft evaluation of systematic evaluation program Topic IV-1 A. "Operation W/Less Than All Luops in Syc "Requests review & response within 30 days IIEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 79/05/07 6pp
- 7906250185 Notification of 790516 meeting w/util in Bethesda, MD to discuss Haddam Neck geologic issues WAMBACH, T V Operating Reactors Branch 2 (Pre 790625) 79/05/14 1p
- 7905200272 Notification of 790522 meeting w/util in Silver Spring.MD to discuss App I Tech Specs
  WANDACH.T V Operating Reactors Branch 2 (Pre 790625) 79/05/17
- 7706050313 Proposes min of two licensed reactor operators be stationed in main control rooms at all times, one of whom has direct responsibility for feedwater sys COUNSIL-M G Connecticut Yankee Atomic Power Co 77/05/31 2pp
- 79060B0262 Requests amend to License DPR-61, revising Tech Specs Sections 3 B & 4.8 re limiting conditions for operation & surveillance requirements for auxiliary feedwater sys COUNBIL.W G Connecticut Yankee Atomic Power Co 79/06/01. 7pp
- 7706220286 Bubmits info requested by V Stello 770025 ltr re design, fabrication history & insp of feedwater lines Response includes all info available; util has no plans to provide 60-day suppl COUNGIL.W G Connecticut Yankes Atomic Power Co 77/06/18 54pp
- Q Inspection reports: IE Bullstins & correspondence
- 7905110010 Forwards IE Bulletin 79-09B, "Nuclear Incident at THI-Buppi" No written response required ORIER.B H. Region i, Philadelphia, Office of the Director 79/04/23 ip
- 7906030278 Forwards response to IC Bulletin 79-07 re seismic stress analysis of safety-related piping Dynamic analyses were not used COUNSIL, N. O. Connecticut Yankes Atomic Power Co. 79/04/24 App.
- 7905120039 Ack receipt of 790404 ltr informing NRG of steps taken to correct violations noted in IE Insp Rept 50-213/79-04
  BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/03, Ip
- ---7706120050 Responds to NRC 790307 itr re violations noted in IE Insp. Rept 50-213/79-04 Corrective actions. Hestinghouse will be instructed to include revision page in core refueling procedure COUNCIL. N.O. Connecticut Yankes Atomic Power Co. 79/04/04 2pp
- --7906120035 Forwards IE Imap Rept 50-213/79-04 on 790212-14 t notice violation.
  BRUNNER.E.J Region 1, Philadelphia, Reactor Operations Nuclea Support Branch 79/03/07. 2pp
- --7904120061 Notice of violation from insp on 790212-14.

  \* Region I. Philadelphia, Reactor Operations Nuclear Bupport Brench 79/03/06, 1p.
- ---7906120066 IE Insp Rept 30-213/79-04 on 790212-14. Noncompliance note failure to maintain typed revised refueling procedure FP CYM RB.
  KALMAN,O., REKITO,W., CAPHTON,O.L. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/06 7pp
- 7906120134 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." Ne action required. ORIER, B.H Region 1. Philadelphia, Office of the Director 79/05/07, 2pp.

- 79G6iiOli9 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required GRIER B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906260099 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 (p
- 7906290732 Responds to IE Quiletin 79-06A.Revision i Plans to propose Tech Sper mod limiting conditions of operation re turbine cycle Change will specify operability requirements for both auxiliary feedwater pumps

  CDUNSIL.H G Connecticut Yankee Atomic Power Co 79/05/14 2pp
- 7906290355 Discusses licensee response to IE Bulletin 79-06A,Revision I Recommends mgt consider assessing current licensee operator understanding of TMI incident HILLIAMS.F J Division of Project Management 79/05/15 ip
- 7906080071 Forwards It Circular 79-08, "Attempted Extortion Low Enriched V " GRIER.B H Region 1, Philadelphia, Office of the Director 79/03/18 10
- 7904270812 Submits additinfo to 790424 response to IR Builetin 79-06A Revision I Discusses void formation in RCS review of containment isolation design & overpressure protection sys SWITZER D C Connecticut Yankee Atomic Power Co 79/05/18 6pp
- 7906290742 Responds to IE Builstin 79-10: "Requalification Training Program Statistics" Forwards util requalification training program statistics
  CQUNSIL:NO Connecticut Yankee Atomic Power Co 79/05/24 3pp
- 7906200106 Forwards "Inservice Insp Rept" conducted by Westinghouse in Feb-Har 1-79
  GRAVES:R H Connecticut Yankse Atomic Power Co 79/06/13 ip
- --7906200110 "Inservice Insp Rept "
  \* Connecticut Yankee Atomic Power Co 79/03/18 325pp
- R Periodic operating reports & related correspondence
- 7906130389 Forwards monthly operating rept for May 1979
  GRAVES.R H Connecticut Yankee Atomic Power Co 79/06/12 ip
- --7906150391 Monthly operating rept for May 1979
  \*\* Connecticut Yankee Atomic Power Co 79/06/12 Bpp
- DOCKET 50-219 OYSTER CREEK NUCLEAR POWER PLANT

  J Insurance & Indomnity information
- 7906150328 Forwards Endorsements 65 \$\tau\$ 66 to ANI Policy NF-164 GERETY.H F GPU Service Corp 79/06/11 3pp
- P Operating license stage documents & correspondence
- 79060R0142 Discusses actions agreed to in 790423 & 23 telcons between IR Finfrock of util & JM Allan of NRC Region I Topics include status & rate of improvement of facility radiation protection program GRIER, B H Region 1. Philadelphia. Office of the Director 79/04/25 | 3pp
- 7906140595 Confirms 790503 telcon w/JI Allen re 790502 event b present status of facility Reactor will remain in cold shutdown condition until NRC examines safety limits ORIER.B H Region I, Philadelphia, Office of the Director 79/05/03 lp
- 7904010233 Notification of 790509 meeting w/util.GE & Exxon in Bethesda,Md to resolve NRC concerns about returning facility to power following 790502 events that allowed water in vessel to decrease below LoLalo limit NOMICKI.S J Operating Reactors Branch 2 (Pre 790625) 79/05/08
- 7906250405 Chart of radiological tests performed on water samples on 790305

  \* Region 1, Philadelphia, Office of the Director 79/05/08 4pp
- 7906250320 Summary of 790509 meeting w/util & consultants re 790502 events resulting in low low water level alarm Attendance list & agenda encl NOWICKI, S J Operating Reactors Branch 2 (Pre 790625) 79/05/17 23ec.

- 7905040174 Responds to 790418 itr requesting comments on NRC evaluation of systematic evaluation program licensing requirements for station battary tests
  FINFROCK I R Jersey Central Power & Light Co 77/05/25 ip
- 7906090319 Forwards OL Change Request 71.adding info to SER for fire protection program W/supporting documentation
  FINFROCK.IR Jersey Central Power & Light Co 79/06/01 14pp
- 7906070259 Forwards Tech Spec Change Request 69 for App A to provisional License DPR-16, for section 3, 1, 3 6, 4 6 % 6 Requests incorporation of Tech Spec changes one year after approval Appropriate fee % Certificate of Syc encl FINFROCK, I R Jersey Central Power & Light Co 79/06/01 2pp
- --7904070262 Tech Spec Change Request 69 re protective instrumentation requirements radioactive effluents & radiological environ menitoring program
  FINFRCCK: R Jersey Central Power & Light Co 79/06/01 24pp
- 7906200209 Submits Tech Spec Change Request 66, Revision 1, revising high radiation area info submitted 780912 FINFROCK. IR Jersey Central Power & Light Co 79/06/15 7pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906110014 Forwards IE Bulletin 79-05B. "Nuclear incident at TMI-Suppl" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/23 ig
- 7906020076 Responds to IE Bulletin 79-08 re BWR-related events identified during TMI-1 event Schedule of completion dates for all corrective actions will be available by 790511 FINROCK, IR Jersey Central Power & Light Co 79/04/25 10pp
- 7906050006 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Util has 4-inch valves w/Class 150 pressure rating installed in fuel pool cooling sys GRIER B H Region 1, Philadelphia, Office of the Director 79/05/01 Opp
- 7906130162 Forwards IF Circular 79~07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required GRIER B H Region 1. Philadelphia. Office of the Director 79/05/02 1p
- 7906:20162 Forwards IR Enfo Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required CRIER.B H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 7706290813 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-219/79-05 BRUNNER,E J Region i. Philadolphia, Reactor Operations Nuclear Support Branch 79/05/09 ip
  - Support Branch 79704704 mpp
- --7906299828 Natice of violation from insp on 790227-0302 & 0305-06 \* Region 1. Philadelphia. Office of the Director 79/04/02 2pp
- --7906270833 IE Insp Rept 50-219/79-05 on 790227-0302 % 0305-06 Noncompliance noted storeroom did not meet requirements of N45 2 2 % station procedures KEMBELD V. NAPUDAG & KISTER, H B Region 1, Philadelphia, Office of the Director 79/04/02 16pp
- 7906:10122 Forwards IE Bulletin 79-10, "Requalification Training Propram Statistics " Written response required QRIER,B H Region 1, Philadelphia, Office of the Director 79/03/11 1p
- 7906260112 Forwards 1E Info Notice 79-12. "Attempted Damage to New | Assemblies " GRIER.B H Region 1. Philadelphia, Office of the Director 79/03/11 ip

- 7906080084 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/18 1p
- 7906260967 Responds to IE Bulletin 79-10 Forwards statistical info re operator requalification training program FINFROCK, I R. Jersey Central Power & Light Co 79/05/24 3pp
- 7906150189 Advises that revision of inservice insp program will be submitted for approval by 790908 Review indicates no conflict between program & Tech Spec requirements FINFROCK, I R Jersey Central Power & Light Co 79/06/08 1p
- R Periodic operating reports & related correspondence
- 7906210155 Forwards monthly operating rept for May 1979 ROSS:D A Jersey Central Power & Light Co 79/06/14 [
- --7906210196 Monthly operating rept for May 1979 MCCLAIN.C M Jersey Central Power & Light Co 79/06/12 14pp
- B Reportable occurrences. LERs & related correspondence
- 7906040251 Forwards LER 78-021/017-0 ROSS, D.A. Jersey Cantral Power & Light Co. 78/10/30 1p
- --7906040293 LER 78-021/01T-0 on 781010 while performing inservice insp.
  discovered through wall crack on spanger pipe Caused by
  methods used to install spanger pipe Corrective action will
  be determined after full investigation
  RQBS,D A Jersey Central Power & Light Co 78/10/30 2pp
- 7906110191 Forwards LER 79-014/03L-0 FINFROCK, I R Jersey Cantral Power & Light Co 79/06/05 ip
- --7906:10195 LER 79-016/03L-0 on 790506 during surveillance test, inclator condenser isolation sensor setpoint A measured two inches of excess water Caused by instrument drift in excess of design accuracy Button was recalibre to put back in svc ROSS, D.A. Jersey Central Power & Light Co. 79/06/05 3pp
- --7904200396 RO 50-219/79-20-IP on 790613 second containment integrity was not maintained for it minutes Caused by simultaneous opening of both reactor bldg railroad doors Door components repaired MCNAIR:R C Jersey Central Power & Light Co 79/06/14 2pp
- 7906200397 Forwards LER 79-018/03L-0 ROSS:D A Jersey Contral Power & Light Co 79/06/15 1p
- --7906200400 LER 79-018/03L-0 on 790517 snubber 51/21.core spray sys 11.
  had signs of grease on alemite fitting on accumulator Cause
  unknown but appears related to rigorous syc conditions
  Shubber replaced
  RUSS.D A Jersey Central Power & Light Co 79/06/15 Gpp
- 7906200412 Forwards LER 79-017/03L-0 ROSS.D A Jersey Central Power & Light Co 79/08/15 1p
- --7906200419 LER 79-017/OSL-O on 790517.during routine surveillance of core spray sys II.parallel isolation valve V-20-21 failed to operate Caused by circuit breaker contacts making poor contact in "B" phase, creating overcurrent Part replaced ROSS, D A Jersey Central Pawer & Light Co 79/06/69 3pp
- 7906280119 Forwards LER 79-019/03L-0 ROSS.D A Jersey Central Power & Light Co 79/04/2! ip
- --7906280122 LER 79~019/03L~0 on 790326 reactor high pressure isolation condenser initiation switch RE-15A tripped at 3 psig greater than specified Caused by instrument repeatability RE-15B roset to trip at 1,06B psig ROSB,D A Jersey Central Power & Light Ca 79/06/21 3pp.
- 7906290701 Responds to 790315 ltr to UK Hendrie Facility was shut down by NRC 790313 order, due to questions re-ability of piping sus to withstand earthquakes Situation will be reviewed & plant returned to operation as soon as possible DENTON: H R Office of Nuclear Reactor Regulation 79/03/04 (p

- --7908270706 Expresses concerns re shutdown of facility Prolonged layest of plant employees could have adverse effect on town of Gawego.NY fitzOffBONS.J E Oswego.NY 79/03/15 ip
- P Operating license stage documents & correspondence
- 7906230029 Forwards Amend 30 to License DPR-69, safety evaluation & notice of issuance & availability IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79703/26 2pp
- --7908250032 Amend 30 to License DPR-63 revising Tech Specs to delete stress-corrosion tracking surveillance program IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625) 79/03/24 App
- --7906250036 Safety evaluation supporting Amend 30 to License DPR-63
  \* Operating Reactors Branch 3 (Pre 790625) 79/03/26 is
- --7908250040 Notice of issuance & availability of Amend 30 to License PPR-63 IPPOLITO, Y A Operating Reactors Branch 3 (Pre 790625)
- 7906290584 Forwards application to amend License DPR-63
  THOMAS,E B LeBosuf, Lamb, Leiby & MacRao 79/06/28 Opp
- --7906290590 Requests amend to License DPR-63 re Tech Spocs for fuel cladding & fuel rod Forwards proposed Tech Specs changes & NEDO-24189 DISC.D P Niagara Mohawk Power Corp 79/06/27 9pp
- --7906290600 "Extended Load Line Limit Analysis.License Amend Gubmittal (Cycle 6)," prepared by GE \* Duquesne Light Co NEDQ-24185 79/06/28 14pp
- G Inspection reports, IE Bulletins & correspondence
- 7906110022 Forwards IE Bulletin 79-05D, "Nuclear Incident at THI-Suppl "No written response required GRIER.B H Region 1, Philadelphia, Office of the Diroctor 79/04/23 ip
- 7906020239 Forwards responses to IE Bulletin 79-08 addressing concerns of events re BWRs identified during TMI incident SCHNEIDER.R R Niagara Mohawk Power Corp 79/04/24 20pp
- 7906060131 Forwards responses to IE Bulletin 79-07 Discusses methods used in seismic analysis of safety-related piping, program listings & program verification SCHNEIDER, R. R. Niagara Mohawk Power Corp 79/04/25 7p
- 7906040029 Responds to IE Bulistin 79-04, "Incorrect Heights for Ewing Check Valves Mfg by Velan Engineering Corp." No such valves are in use in Sessmic Category I piping sys.

  SCHNEIDER, R. R. Niagara Mohawk Power Corp. 79/05/01 ip
- 7905130165 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Stt Resulted in Reactor Power Increase " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/02 tp
- 7905120177 Forwards IE Info Notice 79-11, "Lower Reactor Vestal Issas Insulation Bupport Problem" No action required GRIER, B.H. Region 1. Philadelphia, Office of the Director 79/05/07 2pp
- 7906:10142 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required CRIER,B H Region 1, Philadelphia, Office of the Director 79/05/ii ip
- 7908280128 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuet Assemblies " GRIER, B.H Region 1, Philadelphia, Office of the Director 79/09/11 ip
- 7906290BOO Submits info supplementing 790424 response to IE Sulletin 79-08 re effects of TMI incident on BMRs SCHNEIDER RR Niagara Mohawk Power Corp 79/05/14 App

- 7906290679 Ack receipt of 790502 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-220/79-06
  BRUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/05/17 lp
- --79062906B6 Responds to NRC 790412 ltr re violations noted in IE Insp Rept 50-220/79-06 Corrective actions one individual performing insp to ensure completeness Individual advised that quality-related insp should be reviewed by another BCHNEIDER.R R Niagara Mohauk Power Corp 79/05/02 lp
- --7906290692 Forwards IE insp Rept 50~220/79-06 on 790305-08 % notice of violation
  BRENNER.E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/12 2pp
- --7906290697 Notice of violation from insp on 790309-08
  \* Region 1, Philadelphia, Office of the Director 79/04/04
- --7906290704 IE Insp Rept 50-220/79-06 on 790305-08 Noncompliance nated failure to follow insp procedures
  KALMAN,G , SMITH.T , CAPHTON,D L Region 1. Philadelphia.
  Reactor Operations Nuclear Support Branch 79/04/04 Spp
- 7904080096 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/18 | 19
- 790615040B Responds to IE Builetin 79-07 Forwards addl info on reanalysis of seven safety-related piping sys Teledyne Engineering Sycs rept. "Verification & Gualification of IMRPIPE Computer Program" & printouts encl
  DISS.D P Niagara Mohawk Power Corp 79/06/12 5pp
- 7906260400 Notifies insp of pumps & valves has been added to inservice insp program implementation date is Dec 1979 Associated piping & instrument drawing will be available at site on 7906420 RHODE, C K Riagara Mohawk Power Corp 79/06/20 1p
- R Periodic operating reports & related correspondence
- 790&050207 Forwards "1978 Nine Mile Point Aquatic Ecology Studies Rept." in response to NRC 790228 Itr & Tech Spec reporting requirements ECHNEIDER R R Niagara Mohawk Power Corp 79/05/29 19
- ---7906050211 "1978 Nine Mile Point Aquatic Ecology Studies Rept"

  \* Niagara Mohawk Power Corp 79/05/31 500pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906010214 RO 79-12 on 790523 during insp.concrete anchor bolts discovered to be loose &/or improperly installed Pull test program implemented & deficient bolts to be repaired or raplaced PERKING, T. J. Niagara Mohawk Power Corp. 79/08/23 1p
- 7906110178 Forwards LERs 79-008/03L-0 & 79-009/03L-0 BCHNCIDER:R R Niagara Mohawk Power Corp 79/06/05 1p
- ---7906110181 LER 79-009/03L-0 on 790310 during refusiting outage. containment spray heat exchangers 112 & 121 failed leak rate test Caused by tube leaks Tubes plugged DUDA,E Niagara Mohawk Power Cotp 79/05/31 ip
- --7906110184 LER 79-Q07/03L-0 on 790510 during refueling outage. Site Operations Review Committee failed to review temporary change to maint procedure NI-MP-7 11 within 7-day limit Change subsequently reviewed,

  DUDA: E Niagara Mohawk Power Corp 79/05/31 ip
- 7906130005 Forwards LER 79-012/01T-0 SCHNEIDER,R R Niagara Mohawk Power Corp 79/06/06 1p
- --7906130006 LER 79-012/01T-0 on 790823 concrete anchor bolt deficiencies & missing swismic restraints were discovered on Class I seismic piping sys. Caused by incorrect installation Concrete anchor bolt repair program will be completed by 791231 DUDA.E. Niagara Mohawk Power Corp 79/05/31. 6pp
- 7906180487 Forwards LER 79-013/03L-0 SCHNEIDER, R R Niagara Mohawk Power Corp 79/06/12 1p

- --7906180492 LER 79-013/03L-0 on 790525 Site Operations Review Committe failed to review temporary changes to three instrument surveillance procedures within required 7-day period Review has since taken place 5 approvals received DUDA: E Niagara Mohawk Power Corp 79/06/12 ip
- 7904220405 Forwards LER 79-014/02L-0 LEMPGES, T. E. Niagara Mohawk Power Corp. 79/04/15 1p.
- --7906220408 LER 79-014/03L-0 on 790319 during refueling outage,core spray sys enubber 40-KS-10 found inoperable Caused by worn piston seals on core spray snubber resulting in loss of fluid from snubber Seals replaced & snubber reinstalled DUDA.E Niagara Mohawk Power Corp 79/06/14 1p
- 7906220412 Forwards LER 79-011/03L-0 LEMPGES.T E Niagara Mohawk Power Corp 79/06/15 lp
- --7906220417 LER 79-011/03L-D on 790517 during refueling outage, discovered that radiographer received overexposure of 3,790 millirems for second quarter 1979 Cause unknown 5 under investigation Discovsed further in 790615 ltr to NRC DUDA.E Niagara Mohawk Power Corp 79/06/14 ip
- ---7906220424 Submits rept of individual amployee overexposure to radiation General inability to adhere to radiation work permit may have contributed to overexposure Dosimeter & film data encl Case reported in LER 79-011/03L-0

  LEMPGES, T E Niagara Mohawk Power Corp 79/06/15 5pp
- DOCKET 50-223 UNIV OF LOWELL RESEARCH REACTOR

  G Inspection reports. IE Bullstins & correspondence
- 7906260070 Forwards IE Info Notice 79-12, "Attempted Damage to New Fue Assemblies "
  ORIER B H Region i, Philadelphia, Office of the Director 79/05/11. 10
- 7906080031 Forwards IE Gircular 79-08, "Attempted Extortion Low Enriched U " GRIER.B H Region i. Philadelphia. Office of the Director 79/05/18 1p
- DOCKET 50-224 UNIV OF CALIFORNIA RESEARCH REACTOR

  J Insurance & Indemnity information
- 7904260395 Forwards executed Amend B to Indemnity Agreement E-16, Amend 4 to Indemnity Agreement E-58, Amend B to Indemnity Agreement E-53 Amend 13 to Indemnity Agreement E-15 DENESS, B J Catifornia, Univ of Berkeley 79706/21 5pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906180496 Forwards IE Info Notice 79-12, "Attempted Damage to New Fur Assemblies " No written response necessary ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/10 10
- 7906080233 Forwards 1E Circular 79-08, "Attempted Extertion Low Enriched U " ENGELKEN, R H Region 5, Ban Francisco, Office of the Director 79/05/18 1p
- R Periodic operating reports & related correspondence
- 7906120351 Forwards Annual Operating Rept 1978 LIM.T H California, Univ of Berkelay 79/03/25 ip
- --7906120383 Annual Operating Rept 1978 LIM.T H California, Univ of, Barkeley 79/05/07 13pp
- DUCKET 50-225 RPT CRITICAL EXPERIMENT
- Q Inspection reports. IE Bulletins & correspondence
- 7906260065 Forwards IE Info Notice 79-12, "Attempted Damage to New Fu Assemblies " CRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906080029 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" GRIER, B H. Region 1, Philadelphia. Office of the Director 79/08/18 ip

- DOCKET 50-228 AEROTEST RADIOGRAPHY & RESEARCH REACTOR O Inspection reports. IE Bulletins & correspondence
- 7906180443 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 29/05/10
- 7906080215 Forwards IE Circular 79-08, "Attempted Extortion Low Region 5. San Francisco. Office of the Director ENGELKEN R H 79/05/18
- DOCKET 50-237 DRESDEN NUCLEAR POWER STATION. UNIT 2 G Adjudicatory correspondence
- 7906010131 Forwards 790316 order re shipment of spent fuel, admitting contentions similar to those at issue in present proceeding as oatters in controversey ROISMAN, A Z Natural Resources Defense Council 79/03/20 1p
- 7906070346 Hemo re standing & contentions of intervenors State of IL. NRDC & Citizens for Better Environ following 790201 special prehearing conference on spent fuel storage MILKOLLIN.G L Atomic Safety and Licensing Board Pane) 79/04/19
- 7906210357 Forwards representative matl prepared by Citizens for Better Environ & NRDC to disclose interest in issue of nuclear
- power ROISMAN, A Z Natural Resources Defense Council 79/05/03 60pp
- 7906210337 Forwards representative matl prepared by Citizens for Better Environ & NRDC to disclose interest an issue of muclear power ROISMAN.A Z Natural Resources Defense Council 79/05/03 60pp
- 7906210337 Hotion for reconsideration of 790419 memo & order following special prehearing conference Objects to admission of Contention 5 re specific threats to irradiated fuel in transit Certificate of Svc encl GODDARD.R J Branch 2 79/05/04 3pp
- --7906210359 Would not oppose admission of Contention & if revised to conform w/Contention & as admitted in Duke Power proceeding re-security of spent fuel in transit GODDARD.R J Branch 2 79/04/06 2pp
- 7705210359 Would not oppose admission of Contention 5 if revised to conform w/Contention 5 as admitted in Duke Power proceeding re-security of spent fuel in transit GODDARD, R J Branch 2 79/04/06 2pp
- 7906210252 Applicant motion for reconsideration of 790417 meno & order of clarification of 780419 order re physical security of SMI Buyporting documentation & Certificate of Svc enci STEPTOE, P Isham, Lincoln & Beale 79/05/07 14pp
- 7906020092 Orants NRC 790504 motion suggesting alternative language for Contantion & Denies licensee motion to reconsider admissibility of Contentions & 21 HILHOLLIN.O L Atomic Safety and Licensing Board Panel 79/05/16
- 7906220465 Concludes NRBC & Cititens for Better Environ have standing based on criteria of ALAB-535 Both have established interest in nuclear power issues & are authorized to represent members in proceedings MILHOLLIN.G L Atomic Safety and Licensing Board Panel 79/05/29.
- J. Insurance & indemnity information
- 7906040187 Forwards executed Amends 21, 11, 9 & 1 to Indemnity Agreements 8-10, 8-47, 8-59 & 8-84, respectively POOLE, R D Commonwealth Edison Co. 79/05/29 Hpp.
- P. Operating license stage documents & correspondence
- 7906070351 Responds to 7805[1 itr Requests add1 info re review of proposed spent fuel pool mod Util should provide info within 30 days of receipt of itr.

  ILEMANN.D L. Operating Reactors Branch 2 (Pre 790625) 79/04/23

- 7906070008 Forwards Amend 43 to provisional License DPR-19, safety 200
- --7906070010 Amend 43 to provisional License DPR-19 authorizing operation w/160 B:B R fuel assemblies incorporating revised operating limits to reflect plant specific analyses for Reload 4 & modifying License Condition 3 F VOLLHER:R H Assistant Director for Systems Engineering 79/04/24 35pp
- --7906070013 Safety evaluation supporting Amend 43 to provisional License DPR-19 \* Office of Nuclear Reactor Regulation 79/04/24 13pp
- -- 7906070015 Notice of issuance & availability of Amend 43 to provisional License DPR-19 ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/04/24 200
- 7906050039 Responds to 790318 ltr requesting add1 info re spont fuel storage at six nuclear power plants near Lake MI & forwards local PDR roster for states bordeing on Lake MI DENTON.H R Office of Nuclear Reactor Regulation 79/04/25 7pp
- --7908050043 Requests to be notified when current requests for license amends to store addl quantities of spent fuel at Kewaunes, Point Beach, Cook & Zion are granted SCHAEFER, J Lake Michigan Federation 79/03/18 2pp
- 7906200239 Requests two controlled copies of site emergency plants implementing procedures site maps showing location & grid station number of ensite & offsite environ monitoring stations & site maps used for dose determinations

  KEPPLER, J 0 Region 3, Chicago, Office of the Director 79/05/17
- 7906280263 Forwards draft evaluation of systematic evaluation program.
  Topic III-10 C re-surveillance requirements on BWR
  recirculation pump discharge values
  ZIEMANN, D L. Operating Reactors Branch 2 (Pre-790625) 79/05/24
- 770A050371 Responds to NRC 770423 request for add1 info re spent fuel pool and Forwards spent fuel storage module sultability study Enci drawing available in Central Files only JANACEK, RF Commonwealth Edison Co 77/05/30
- 7906210220 Forwards "Reactor Containment Bldg Integrated Leak Rate STEPHENSON, B B Commonwealth Edison Co 79/06/13 1p
- --7906210230 "Reactor Containment Bldg Integrated Leak Rate Test" for 790421-23 \* Commonwealth Edison Co 79/04/21 53pp
- 7906210190 Requests inclusion in dockets of NEDC-21944-P, "One Quarter Scale Pressure Suppression Pool Swell Test Program Plant Unique Tasts." JANECEK, R F Commonwealth Edison Co 79/06/15
- 7906270236 Cites add1 systematic evaluation program topics that should be delated from review re failure of underdrain sys & interlock requirements.

  JANECEK.R F Commonwealth Edison Co 79/06/22 ip
- @ Inspection reports. IE Bulletins & correspondence
- 7906250147 Forwards IE Insp Repts 50-010/79-10, 50-237/79-10 5 30-249/79-08 on 790316-30 No noncompliance noted HEISHMANR F Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/04/25 2pp.
- --7906230133 IE Insp Repts 50-010/79-10.50-237/79-10 & 50-249/79-00 on 790316-20 No noncompliance noted Major areas inspected maint activities.plant operations & physical protection & security organization security organization BPESSARD, R L., WINNG/M, K, REYEB, L, A. Region G, Chicago, Office of the Birector 79/04/25, 9pp.
- 7906250165 Forwards IE Insp Rept 50-237/79-08 on 790329-30 & 0411-13 No FIGRELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 77/04/25, 2pp. .

aradica area de la Laberta

- --7906250172 IE Insp Rept 50-237/79-05 on 790329-30 & 0411-13 No noncompliance noted Major areas inspected licenses surveilance of safety-related hangers & snubbers including applicable procedures YIN, I T , DANIELSON, D H Region 3, Chicago, Office of the Director 79/04/23 6pp
- 7906290493 Responds to IE Bullatin 79-08 Forwards into re review of TMI incident Existing line isolation not important to ECCS injection REED.C Commonwealth Edison Co 79/04/27 22pp
- 7906260630 Forwards IE Insp Repts 30-237/79-11 to 50-249/79-09 on 790413.21-23 to 27 No noncompliance noted HEISHMAN,R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 79/05/03 2pp
- --7906260633 IE Insp Repts 30-237/79-11 & 30-249/79-09 on 790413,21-23 & 27 No noncompliance noted Major areas inspected integrated lask test & licensee action on previously identified item of noncompliance REYES,L A: DETTENMEIER,R: STREETER,J F Region 3, Chicago, Office of the Director 79/05/03 App
- 7906:120083 Forwards IE info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 10
- 7904110101 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
  ip
- 7904080194 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U"
  KEPPLER, J G Region 3, Chicago. Office of the Director 79/05/18
- 790A1300B2 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22
- 7906230079 Bubmits corrected copy of page 6 of Insp Repts 50-273/79-11 \$ 50-249/79-09 HEISHMAN.R f Region 3. Chicago. Reactor Operations Nuclear Support Branch 79/05/23 2pp
- 7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Greek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/03/29
- R Periodic operating reports & related correspondence
- 7906150336 Forward monthly operating rept for May 1979 STEPHENSON:8 B Commonwealth Edison Co 79/06/11 1p
- --7906180338 Monthly operating rept for May 1979
  CLEBZKIEWICZ,8 Commonwealth Edison Co 79/06/04 35pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906050350 Forwards LER 79-028/03L-0 ETEPHENSON: 8. B. Commonwealth Edison Co 79/05/24. 1p
- --7906050353 LER 79-028/03L-0 on 790508.N2 line low temp alarm received & frost found on inerting line.A0-2-1601 & inerting line failed leak rate test Caused by failure of temp recorder at N2 vaporizer
  PARCELL Commonwealth Edison Co 79/05/25 lp
- 7906050245 Forwards LER 79-032/03L-0 STEPHENSON, B. B. Commonwealth Edison Co. 79/05/30 1p
- ---7906050248 LER 79-032/03L-O on 790501 intermediate range monitors in trip sys found downscale during rod pulls to heating power, resulting in manual half-scram, Caused by faulty connector & loose input connector HOLLAND.P. Gommonwealth Edison Co. 79/05/30 ip

- /906090268 Forwards LER 79-027/03L-0 STEPHENSON,8 B Commonwealth Edison Co 79/05/30 1p
- --7905050269 LER 79-027/03L-0 on 790302 during startup,main turbine tripped on high water level Caused by packing leak on isolation valve for PS-263-60B Packing adjusted, tested & sys I fineup returned to normal HOLLAND,P Commonwealth Edison Co 79/05/30 2pp
- 7906040278 LER 79-012 has been voided # Commonwealth Edison Co 79/06/01 ip
- 7906040293 LER 79-011 has been voided \* Commonwealth Edison Co 79/06/01 1p
- 7906040297 LER 79-007 has been voided \* Commonwealth Edison Co 79/06/01 1
- 7906040301 LER 79-006 has been voided \* Commonwealth Edison Co 79/06/01
- 7906120310 Forward's LER 79-029/03L-0 STEPHENSON, B B Commonwealth Edison Co 79/06/05 ip
- --7906120313 LER 79-027/03L-0 on 770508 DIS 1400-3, pressure switch 2-1430-1466D failed to trip Caused by sticky plunger in pressure switch Suitch removed cleaned & reset to trip at 94 5 pais increasing SMITH.OL Commonwealth Edison Co 79/06/05 ip
- 7904200404 Forwards LER 79-002/01X-1 STEPHENSON, B B Commonwealth Edison Co 79/06/05 ip
- ---7906200409 LER 79-002/01X-1 on 790103 during normal operation, HPCI turbine failed to start during quarterly flow test Gaused by partial engagement of interlock dump valve operating lever Lever adjusted HPCI started to verify operability PARCELL Commonwealth Edison Co 79/06/05 2pp
- 7906120376 Forwards LER 79-031/031-0 STEPHENSON, B B Commonwealth Edison Co 79/06/07 1p
- --7906120385 LER 79-031/03L-0 on 790509 crack found on 201 feedwater emergency spill to condensor line % crack located on pipe to condensor weld Caused by mechanical failure Cracked portion removed & rewelded

  JANSEN.T Commonwealth Edison Co 79/06/07 ip
- 7906200370 Forwards LER 79-034/01T-0 STEPENSON, B B Commonwealth Edison Co 79/06/12 1p
- --7906200371 LER 79-034/01T-0 on 790530 diesel generator failed to sta during operability test Caused by failure to engage of lower air start bendix gear, Grar aligment will be checked after diesel generator tests. CHAN.J Commonwealth Edison Co 79/06/12 2pp
- 7906220282 Forwards LER 79-041/03L-0 STEPHENSON.B B Commonwealth Edison Co 79/06/15 1p
- --7906220271 LER 79-041/03L-0 on 790606 28 recirculation motor general set field circuit breaker tripped open Caused by failure of potential transformer in voltage regulator circuit Transformer replaced DUNBAR.J Commonwealth Edison Co. 79/06/15 19
- 7906220365 Forwards LER 79-037/03L-0 GTEPHANSON: B B Commonwealth Edison Co 79/06/15 ip
- ---7906220373 LER 79-039/03L-0 on 790528 125 volt dc switch 2.reserve bus 22, was opened causing trip of 282 recirculation motor generator set oil pump Gaused by inadvertent opening of switch Switch marked to caution against opening AMMER.A A Commonwealth Edison Co 79/06/15 ip
- DOCKET 30-241 MISSISSIPPI STATE UNIV RESEARCH REACTOR

  J Insurance & indomnity information
- 7906080274 Forwards executed Amend 9 to Indemnity Agreement E-46 PRICE,8 Hississippi State Univ 79/05/29 2pp

DOCKET 50-243 OREODN STATE UNIV RESEARCH REACTOR

G Inspection reports, IE Bulletins & correspondence

7906:80451 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necestary ENGELKEN:R H Region 5, Ban Francisco, Office of the Director

7906080228 Forwards 1E Circular 79-08, "Attempted Extortion - Low Enriched U " ENGELXEN,R.H Region 5, San Francisco, Office of the Director 79/08/18 18

# 8 Reportable occurrences, LERs & related correspondence

7906280132 RO on 790607 shutdown margin of TRIGA reactor was \$0.48, nine cents less than Tech Spect Limitation of \$0.57 Upon discovery, two fuel elements were moved & shutdown margin went up to \$0.74

WAND, C. H. Gregon State Univ. 79/06/19 7pp

DOCKET 50-244 ROBERT EMMET GINNA NUCLEAR PLANT. UNIT 1
F. Security, medical, emergency & fire protection plane

7906050058 Forwards replacement pages to security plan evaluation rept supporting issuance of Amend 25 to License BPR-18 on 790222 Pages withheld (ref 10CFR2 790)
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/05/14

7906220272 Notifies replacement of computer room ceiling is dalayed until 790831.
WHITE, D Rochester Gas & Electric Corp 79/06/14 19

#### J Insurance & indemnity information

7906190368 Forwards Endorsements 49.50 & 51 to MASLU Policy MF-47 & Endorsements 60 & 61 of NELIA Policy NF-170 MKITErL, D Rochester Gas & Electric Corp 79/06/14 6pp

# P. Operating License stage documents & correspondence

7906260087 Bummary of 790410-ii meeting w/util at site re systematic evaluation program Topic III-6.seismic design SHEA: J J Operating Reactors Branch 2 (Pre 790625) 79/04/30.

7906050359 Forwards Offsite Bose Calculating Hanual HHITE, L B. Rochester Oas & Electric Corp. 79705/29 1p

~~7906050360 Offsite Dose Calculating Manual \* Rochester Gas & Electric Corp 79/05/29. 33pp

7906:20406 Responds to Item III-i of NRC questions re design & const for systematic evaluation program selemic review Discussed details of block walls throughout plant. Two oversized drawings encil
WHITE, L. D. Rochester Gas & Electric Corp. 79/06/06 20p.

7906130193 Forwards application for amend to License DPR-18. FAROM.R.S. LeBosuf, Lamb. Leiby & MacRae. 79/06/11 4pp

7906270434 Notifies Revision 6 to Suppl IV of full-term license application will be submitted in early July, as requested by NRC 790605 ltr Revision 6 will exclude Reg Guids 1 94 from 1 lating of ANSI stde WHITE.L D Rochester Qus & Electric Corp 79/06/25 1p

## G Inspection reports. IE Bulletins & correspondence

7906260504 Forwards IE Insp Rept 50~244/79~06 on 790310-13 No noncompliance noted BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 Zpp 1

:

---7908260509 IE Insp Rept 50--244/79-06 on 790310-13 No noncompliance noted Major areas inspected witness of core reload activities witness of outage maint activities k review of pipe support & restraint surveillance program KEINIO,R R , RAYNOND,N J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 lipp

7906110045 Forwards IE Bulletin 79-058. "Nuclear Incident at TMI-Buppl" No written response required GRIER.B H Region 1. Philadelphia, Office of the Diractor 79/04/RJ ip

7904080143 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Confirms capability of plant to withstand seismic avent WHITE-L D Rochester Gas & Electric Corp 79/04/25 4pp

7706020217 Responds to IE Builetins 79-06A & 79-06A. Revision I. "Review of Operational Errors & Sys Misalignments Identified During TMI-2 Incident " Plant procedures are being reviewed & updated HHITE.L D Rechester Gas & Electric Corp 77/04/28 17pp

7906070261 Forwards response to IE Bulleith 79-04, "Incorrect Weights for Swing Valves Hfg by Velan Engineering Corp " Valves used insafety-related sys are in close proximity to pipe supports.No mods planned HHITE/L D Rochester Oas & Electric Corp 79/04/30 Spp.

7906120201 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H. Region 1, Philadelphia, Office of the Director 79/05/07, 2pp

7905:10149 Forwards IE Bullstin 79-10, "Requalification Training Program Statistics " Written response required ORIER, B.H Region 1. Philadelphia, Office of the Director 79/09/11 ip

7906260160 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " ORIER,B H Region 1, Philadelphia, Office of the Director

7906080106 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " GRIER, B H. Region i, Philadelphia, Office of the Director 79/03/18. ip

7906270200 Responds to IE Bullstins 79-06A & 79-06A. Revision 1 No Tach Spec changes required at this time. Change will be requested when design 5 safety evaluations are prepared. WHITE. L. D Rochester Gam & Electric Corp 79/05/18 In

## S Reportable occurrences, LERs & related correspondence

7906030438 Confirms 790416 telcon to W Raymond reporting LER-79-09, boric acid storage tanks out of spec for vol & weight of boric acid. Orderly load reduction & batching operations commenced tanks within specs.

ENON, B. A. Rochester Qas & Electric Corp. 79/04/16 1p

7906020061 Confirms 790420 telcon W/H Lasurus re LER 79-10. horic acid storage tanks out-of-apac for vol & weight, Orderly load raduction initiated to restors tanks to required specs, SNOW, S. A. Rochester Ome & Electric Corp. 79/04/20, ip

7906290195 Confirms 790510 discussion w/D Beckman re LER 79~011 New valve internals being mfg to correct problem Will be available in June
8NOH:B.A. Rochester Oas & Electric Corp. 79/05/11. ip.

7906250233 Forwards LER 79-012/01T-0, WHITE:L.D. Rochester Gas & Electric Corp. 79/06/20 ip.

- --7906250253 LER 79-012/01T-0 on 790606 during inservice insp. identified piping supports for safety equipment not built per Yech Spec drawings Caused by Inadequate control on const installation Supports corrected BODINE, J C Rochester Gas & Electric Corp 79/06/20 2pp
- DOCKET 50-245 HILLSTONE NUCLEAR POWER STATION, UNIT 1

  1. Financial information
- 7906200374 Forwards annual financial repts for owner-licensees O'CONNOR.L A Northeast Utilities 79/06/15 3pp
- --7706200375 Annual Financial Rept 1978

  \* Western Massachusetts Electric Co 79/12/31 17pp
- ---7906200376 Annual Financial Rept 1978 \* Hartford Electric Light Co 79/12/31 21pp
- ~-7906200377 Annual Financial Rept 1978 \* Connecticut Light & Power Ca 79/12/31 21pp
- J Insurance & indemnity information
- 7906190293 Forwards Endgrsements 54 5 55 to MAELU Policy MF-52 CDNNELL.T Northeast Nuclear Energy Co (Northeast Utilities) 79/06/12 3pp
- 7906270241 Forwards Endorsements 59 & 60 to NELIA Policy NF-173 SEGER, R M Northeast Nuclear Energy Co (Northeast Utilities) 79/06/21 3pp
- 7406280091 Forwards Endorsements 79 \$ 60 to ANI Policy NF-173 SEGER.R M Northeast Utilities 79/06/21 1p
- P Operating license stage documents & correspondence
- 7706230305 Forwards Mar 1979 "Thermal Plume Study "COUNSIL.W O Northeast Utilities 79/04/18 1p
- --7906250306 "Thermal Plume Study." Mar 1979
  \* Northeast Utilities 79/03/31 350pp
- 790&0201&& Notification of 790517-18 meeting w/util to discuss systematic evaluation program Topic III-5 A, "Effects of Pipe Break on Structure.Sys & Components Inside Containment" SHEA.J J Operating Reactors Branch 2 (Pre 790&25) 79/04/20
- 7706050234 Requests NEDE-21878-P. "Mark I Containment Program." be included in docket Rept transmitted by GE on 770226 COUNSIL.W O Northeast Utilities 77/05/29 ip
- 7906290012 Forwards Amend 61 to License DPR-21, safety evaluation to notice of issuance travailability
  21EMANN.D t. Operating Reactors Branch 2 (Pre 790625) /9/05/29
- --7906290018 Amend &1 to License DPR-21 authorizing use of 148 Bx8R type fuel assemblies, changing safety limit min critical power ratio to 1 07 & changing max average planar linear heat generation limits
  VOLLMER,R H Assistant Director for Systems Engineering 79/05/27 34pp
- --7706270019 Safety evaluation supporting Amend 61 to License DPR-21
  \* Operating Reactors Branch 4 (Pre 770625) 79/05/29 11pp
- --7906290021 Notice of issuance & availability of Amend 61 to License DPR-21 TIEMANN,D L Operating Reactors Branch 2 (Pre 790625) 79/05/29 3pp
- 7906230152 Bubmits agenda & other info re 790628-29 meeting on systematic evaluation program Topic III-6. "Seismic Design "Forwards draft "seismic Review of Unit for Systematic Evaluation Program ZIEMANN: D L Operating Reactors Branch & (Pre 790625) 79/05/30
- --7906230134 Draft "Beismic Review of Unit for Systematic Evaluation Program Phase 1 Rept " # Office of Nuclear Reactor Regulation 79/03/13 187pp

- 7906150337 Responds to NRC 770418 ltr re systematic evaluation program Topic VIII-3 A.station battery testing Draft assessment of plant surveillance requirements is substantially correct COUNSIL:N 0 Northeast Utilities 79
- G Inspection reports, IE Bulletins & correspondence
- 7906010043 Forwards IE Insp Repts 50-245/78-41 & 50-336/78-38 on 781106-1207 No noncompliance noted BRUNNER.E.J Region 1, Philadelphia, Office of the Director 79/03/21 2pp
- --7906010047 IE Insp Repts 50-245/78-41 & 50-336/78-38 on 791106-1207 No noncompliance noted Mayor areas inspected accessible portions of Unit 1 reactor, turbine & radwaste bldgs. Unit 2 auxiliary & turbine bldgs & radiation protection
  SHEDLOSKY.J T Region 1. Philadelphia, Office of the Director MCCABE, E C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/03/20 24pp
- 7906040371 Responds to 1E Bulletin 79-03 re ASME SA-312 stainless steel pipe mfg by Youngstown Welding & Engineering Co Piping not in use or planned for use COUNSIL,₩ G Northeast Utilities 79/04/16 ip
- 7906260546 Forwards IE Insp Repts 50-245/79-04 % 50-336/79-02 on 790210-0316 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16 2pp
- --7906260551 IE Insp Repts 50-245/79-04 & 50-336/79-02 on 790210-0316 No noncompliance noted Major areas inspected accessible portions of Unit 1 reactor, turbine & radwaste blogs, Unit 2 encl. auxiliary & turbine blogs SHEDLOEKY, J T . RAYMOND, W J . MCCABE, E C Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16
- 7906110019 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl " Ne written response required GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906080042 Responds to IE Bulletin 79-07 re seismic stress analyses of safety-related piping Seismic design methods will be reviewed by NRC within framework of systematic evaluation program \* COUNSIL.N Q Northeast Utilities 79/04/24 Bpp
- 7906140481 Responds to IE Bulletin 79-08, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "Reactor vessel water in BMR is continuously munitored by seven indicators or recorders COUNSIL.W O Northeast Utilities 79/04/24 App
- 7906140222 Responds to IE Bulletin 79-04, "Incorrect Heights for Swing Check Valves Mfg by Velan Engineering Corp " Three seismic Category I piping sys utilize valves No drawing discrepancies exist re valve weights
  COUNSIL,W Q Northeast Utilities 79/04/30 ip
- 7906130164 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required GRIER. B H. Region 1. Philadelphia. Office of the Director 79/05/02 19
- 7906150200 Ack receipt of 790412 itr informing NRC of steps taken to correct violations noted in IE Imap Repts 50-245/79-03 & 50-336/79-03
  SMITH, G H Region i, Philadelphia, Fuel Facility & Materials Safety Branch. 79/05/03 lp
- --7906150205 Responds to NRC 790320 itr re viciations noted in IE Insp Repts 50-249/79-03 & 50-336/79-03 Corrective actions 38-ft, 6-inch elevation immediately posted W/sign bearing radiation caution symbol COUNSIL.W O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/12 2pp
- --7906150209 Forwards IC Insp Repts 50-249//9-03 & 50-336/79-03 on 790212-15 & notice of violation SMITH.0 H Region i. Philadelphia, Fuel Facility & Materials Safety Branch 79/03/20 3pp
- --7906150210 Notice of wiolation from insp on 790212-15

  \* Rugion i, Philadelphia, Fuel Facility & Materials Bafety
  Branch 79/03/16 ip

- ---7906150213 |E Insp Repts 50-245/79-03 & 50-336/79-03 on 790212-15
  Noncompliance noted failure to post radicactive matls
  storage area as required
  YUMAS, O P. CROCKER, H Region 1, Philadelphia, Fuel Facility
  & Materials Safety Branch 79/03/16 & pp
- 7904:20176 Forwards IE Info Notice 79-11. "Louer Reactor Vessel Head Insulation Support Problem " No action required ORIER, B H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 790611013B Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required CRIER.B M Region 1, Philadelphía, Office of the Director 79/05/11 1p
- 7906260124 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " GRIER.B H Region 1. Philadelphia. Office of the Director 79/05/11 1p
- 7906080091 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER: B H Region 1, Philadelphia, Office of the Director 79/05/18 ip
- 7906:50208 Forwards add1 response to IE Sulletin 79-07 re seismic stress analysis of safety-related piping Reanelysis performed for max calculation stresses & restraint loading of safety-related piping COUNSIL.N O Northeast Utilities 79/06/06 Bpp
- 7906250282 Forwards add1 response to IE Bulletin 79-07 re mods to control rod drive exhaust line & 1-002 bypass line piping Sys found acceptable for continued use COUNSIL.W Q Northeast Utilities 79/06/15 2pp
- R Periodic operating reports & related correspondence
- 7904180522 Forwards monthly operating rept for May 1979 OPEKA. J Northeast Utilities 79/06/11 ip
- ---7906180527 Monthly operating rept for May 1979 YOUNG.R Northeast Utilities 79/06/08 5pp
- S Reportable occurrences, LERs & related correspondence
- 7906040310 Forwards RG-78-9/3L FERLANDLE J Northeast Nuclear Energy Co (Northeast Utilities) 78/04/25 ip
- --7906040314 RQ-78-9/3L on 780403 while performing surveillance (steam tunnal high temp functional & calibr) on steam tunnel temp swiftches one swiftch tripped at setpoint higher than that specified in Tech Spec Caused by setpoint drift PRZEKOP.P J Northeast Nuclear Energy Co (Northeast Utilities) 78/04/23 2pp
- 7904040353 RO-78-20/IP on 781010 during normal plant operation, unused chloride capacity of one full flow on line demineralizers was less than 30 lb min OPEMA.J F Northeast Utilities 78/10/10 [p
- 7906040234 Cancels RO-78-20/1P, submitted on 781010 Unused chloride capacity of full flow demineralizar meets Tech Spec requirements
  OPEKA, J. F. Northeast Utilities 78/10/11 ip
- 7905120357 Forward's LER 79-013/03L-0 OPEKA.J F Northeast Utilities 79/06/05 ip

1

4 11

|:

11

, ij

- --7906120362 LER 79-013/03L-0 on 790508 oragen pressure 603 5 check for source range monitors not completed for 24-h period Surveillance overlooked Checklist added to indicate requirement of procedure YOUNG,R H Northeast Utilities 79/06/03, 2pp.
- 7906140398 Forwards LER 79-014/03L-0 OPEKA, J.F. Northeast Utilities 79/06/07, 1p
- --7906140401 LER 79-014/03L-0 on 790511: during audit of refuel outage surveillances, source range monitor functional surveillance was inadvertently overlooked Caused by failure of monitor functional to be listed in refueling chacklist.

  YOUNG:R, H. Northeast Utilities 79/06/07 3pp.

- 7906250278 Submits addl info to LER 79-04/03L Control rod 92-07 declared inoperable on 790125 Many fragments of broken source holder were retrieved All fragments have been removed OPEKA-J F Northeast Utilities 79/06/14 3pp
- 7906290242 Forwards LER 79-019/03L-0 OFEKA, J. F. Northeast Utilities 79/06/25 1p
- --7906290283 LER 79-015/03L-0 on 790528 during refueling no control fil out-block occurred when refuel bridge was over core w/fuel assembly loaded grapple Caused by worn track Limit switch Switch replaced & surveillance procedure changed YOUNG, R H Northeast Utilities 79/06/22 3pp
- DOCKET 50-247 INDIAN POINT STATION, UNIT 2
- C Utility Environmental Report (ER), amends & correspondence
- 7906190253 Forwards "1976 Year-Class Rept for Muttiplant Impact Study of Hudson River Estuary " Affidavit of Svc encl ZARAKAS.P Consolidated Edison Co of New York 79/06/15 Spp
- --7906190237 "1976 Year-Class Rept for Multiplant Impact Study of H.4k\*\*
  River Estuary." prepared by TX Instruments
  \*\* Consolidated Edison Co. of New York 79/05/31 550pp
- F Security, medical, emergency & fire protection plans
- 7906020078 Ack receipt of 790327 revised emorgency plan Requests Class III fee
  HILLER, H.O. License Fee Management Branch 79/05/00 1p
- 7906190387 Responds to 790508 ltr forwarding \$4,400 filing fee for revised emergency plan Payment made under protest Util reserves right to challenge validity of fees CAHILL-W J Consolidated Edison Co of New York 79/06/11 lp
- J Insurance & indemnity information
- 7905190255 Notifies of receipt of complaint served on Westinghoves alleging bodily injury to util employee J D'Mallon, who was aplashed w/radioactive water on 750812 Suit under way ALTON.C G American Nuclear Insurers 79705/14 tp
- 7906220303 Forwards Amend 21 to Indemnity Agreement B-19
  CAHILL, H J Consolidated Edison Co of New York 79/06/18 3pp
- P Operating license stage documents & correspondence
- 7906050417 Requests facility participate in vital area analysis & schedule site visit during week of 790506 BCHMEMCER.A Operating Reactors Branch 1 (Pre 790625) 79/04/12 2pp
- 7906250033 Summary of 790908 meeting w/Consolidated Edison Cp of Nr & Power Authority of State of NY re auxiliary feedwater sys & related station areas
  OLSHANLL N Operating Reactors Branch 1 (Pro 790623) /9/05/14
  App
- 7905040183 Summarizes actions taken as result of 790525 conference call re support adequacy for piping sys Reanalysis of 44 supports indicated acceptability. w/loads well within allowable limits CAHILL. H. J. Consolidated Edison Co. of New York 79/05/28 2pp
- 7906070275 Forwards Westinghouse rept. "Fracture Toughness & Design Considerations for Addressing Lamellar Tearing of Steam Generator & Reactor Coolant Support Matl " Rept withheld (ref 10CFR2 790) CAMILL.W J Consolidated Edison Co of New York 79/05/31 ip
- ---7906070281 Requests withholding from public disclosurs of util resemble NRC request for info re fracture toughness & potential for tearing of steam generator & reactor coolant gump support mat!

  WIESEMANN.R. A. Westinghouse Electric Corp. 79/04/26 2pp

- 7906060129 Forwards application for amend to License DPR-26 ZARAKAB.P Consolidated Edison Co of New York 79/06/04 2pp
- --7904060133 Application for amend to License DPR-26 changing Tech Specs to permit waiving turbine stop & control rod closure test during end-of-cycle operation \* Gonsolidated Edison Co of New York 79/06/04 7pp
- 7906110243 Forwards "Efficiency of one Square Meter Epibenthic Sled for Collecting Young-of-the-Year Striped Bass.White Perch & Atlantic Tomcod in Hudson River Estuary, 1978 " H/JR Jannarone 790606 affidavit Certificate of Svc encl CAHILL.W J Consolidated Edison Co of New York 79/06/06 Spp
- 7904210128 Forwards info re PHR feedwater lines, in response to NRC 790525 request W/15 oversized drawings CAHILL, W J Consolidated Edison Co of New York 79/06/18 40pp
- 7906110255 "Efficiency of One Square Meter Epibenthic Bled for Collecting Young-of-the-Year Striped Bass, White Perch & Atlantic Tomcod in Hudson River Estuary, 1978 " \* Teras Instruments, Inc. 79/06/30 19pp
- 9 Inspection reports, IE Bulletins & correspondence
- 7906110008 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl " Na written response required ORIER, B H Region I, Philadelphia, Office of the Director 79/04/23 ip
- 770A0200B1 Responds to IE Bulletin 79-07 Discusses actions taken re verification approach for UE&C-ADLPIPE-2 program CAHILL, N J Consolidated Edison Co of New York 77/04/24 7pp
- 7906010215 Forwards response to Revision 1 to IE Bulletin 79-06A, re-THI incident CANILL, U J Consolidated Edison Co of New York 79/04/26 66pp
- 7906080148 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Effect of weight discrepancy negligible in every case investigated Further investigation initiated response expected 790608 CAHILL, N.J. Consolidated Edison Go. of New York 79/05/01 2pp
- 7906120152 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER: BH Region 1, Philadelphia, Office of the Director 79/05/07 2pp.
- 7906110118 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Licensee action required ORIER.3 H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906260078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906270204 Responds to IE Bulletin 79-09 Unit 1 currently shut down, awaiting decision re ECCS No GE Type AK-2 circuit breakers used in safety-related sys in Unit 2 CAHILL: W J Consolidated Edison Co of New York 79/09/17 1p
- 7906080069 Forwards IE Circular 79~08. "Attempted Extortion ~ Low Enriched U " GRIER: B H Region 1, Philadelphia, Office of the Director. 79/03/18. ip
- 7906230090 Summary of 790317 meeting w/Consolidated Edison Co of NY, Power Authority of Blaate of NY & United Engineers & Constructors, Inc to discuss licensee response to IE Bulletin 79-07. "Seismic Bress Analysis of Bafaty-Related Piping "OLSHAN, L N Operating Reactors Branch i (Pre 790625) 79/05/18
- 7906010267 Forward supplemental response to IE Bulletin 79-07 reconfirmatory reanalysis of pressurizer relief line 70, using UE&C-ADLPIPE-2 dynamic seismic computer codr ZARAKABJP. Consolidated Edison Go of New York 79/05/25 5pp
- R Periodic operating reports & related correspondence
- 7906140257 Annual Environ Operating Rept 1978. Part A & Part Bradiological rept. vols: 1 & 2 \* Consolidated Edison Co of New York 78/12/31, 223pp

- 7906190462 Forwards "Seismic Monitoring Network." Guarterly Rept 15 for Dec 1978 - Feb 1979 CAHILL.W J Consolidated Edison Co of New York 79/06/04 1p
- --7904190466 "Beismic Monstoring Network," Guarterly Rept 15 for Dec1978-Feb 1979 Prepared by Woodward-Clyde Consultants.inc \* Consolidated Edison Co of New York 79/09/30 36pp
- 7906190478 Submits May environ data specified in Section 401 certification MONTI, WA Consolidated Edison Co of New York 79/06/10 11pp
- 7906260004 Forwards monthly operating rept for May 1979
  CAHILL, W J Consolidated Edison Co of New York 79/06/14 ip
- --7706260006 Monthly operating rept for May 1979 KANULA, L. Consolidated Edison Co. of New York 79/06/05 7pp
- 7906260407 Forwards May 1979 daily tabulation of fish collection & species breakdown
  CAMILL W J Consolidated Edison Co. of New York 79/06/14 Spo
- S Reportable occurrences, LERs & related correspondence
- 7906040284 Forwards LER 78-020/04T-0 CAHILL.W J Consolidated Edison Co of New York 78/08/14 ip
- ---790A040291 LER 78-020/04T-0 on 780428 activity of water sample taken from Camp Field Resevoir on 780327 exceeded ten times historical level Caused by non-representative sampling technique & adverse meteorological conditions
  MASCIULLI Consolidated Edison Co of New York 79/06/09 ip
- --7906040298 Discusses anomalous measurement of radioactivity at environ water sampling location Probably caused by fallout from Chinese weapons test & other factors yielding non-representative sample Technique to be changed CAHILL, W.J. Consolidated Edison Co. of New York 78/06/09 3pp
- Q Adjudicatory correspondence
- 7906010131 Forwards 790316 order re shipment of spent fuel, admitting contentions similar to those at issue in present proceeding as matters in controversey ROISHAN, A Z Natural Resources Defense Council 79/03/20 ip
- 7906070346 Memo re standing % contentions of intervenors State of IL. NRDC & Citizens for Better Environ following 790201 special prehearing conference on spent fuel storage.
  MILHOLLIN.0 L Atomic Bafety and Licensing Board Panel 79/04/19
- 7906210337 Forwards representative matl prepared by Citizens for Better Environ & NRDC to disclose interest in issue of nuclear power. ROISMAN, A Z. Watural Resources Defense Council 79/05/03 60pp
- 7906210337 Motion for reconsideration of 790417 memo & order following special prehearing conference Objects to admission of Contention 6 re specific threats to irradiated fuel in treasatt Certificate of Syc encl.

  ODDDARD, R. J Branch 2 79/05/04 3pp
- --7906210399 Would not oppose admission of Contention 6 if revised to conform w/Contention 6 as admitted in Duke Power proceeding re-security of spent fuel in transit GODDARD:R J. Branch 2 79/04/06 2pp
- 7706210252 Applicant motion for reconsideration of 770417 memo & order of clarification of 780419 order re physical security of SNM Supporting documentation & Certificate of Svc encl STEPTOE.P Isham, Lincoln & Beals, 79705707 14pp.
- 7906020052 Grants NRC 790504 motion suggesting alternative language for Contention & Denies licensee motion to reconsider admissibility of Contentions & 3 11 MILHOLLIN, 0 L Atomic Safety and Licensing Board Panel, 79/05/16.
- 7906220465 Concludes NRDC & Citizens for Better Environ have standing based on criteria of ALAB-935 Both have established interest in nuclear power issues & are authorized to represent members in proceedings.
  MILHOLLIN-0 L Atomic Safety and Licensing Board Panel. 79/05/29

#### J Insurance & indemnity information

7906040187 Forwards executed Amends 21,11,9 & 1 to Indemnity Agreements B-10,8-47,8-59 & B-84, respectively PODLE,R D Commonwealth Edison Co 79/05/29 Epp

### P Operating license stage documents & correspondença

7906070351 Responds to 780511 ltr Requests add1 info re review of proposed spent fuel pool mod Util should provide info within 30 days of receipt of 1tr
ZIEMANN.D L Operating Reactors Branch 2 (Pre 790625) 79/04/23

7906200239 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of onests & offsite environ monitoring stations & site maps used for dose determinations, KEPPLER, J G. Region 3. Chicago, Office of the Director 79/05/17

7904050371 Responds to NRC 790423 request for add1 info re spent fuel pool mod Forwards spent fuel storags module suitability study Enci drawing available in Central Files only JANACEK.R F. Commonwealth Edison Co 79703730. 63pp

7906200335 Responds to IE Hulletin 79-01 Forwards info re environ qualification of Class IE equipment required to function under accident conditions & info re use & maint of ASCD solenoid valves.

REED, C Commonwealth Edison Co 79/06/14 39pp.

7906210190 Requests inclusion in dockets of NEDE-21944-P, "One-Quarter Scale Pressure Suppression Pool Swell Test Program, Plant Unique Tasts "
JANECEK-R F Commonwealth Edison Ca 79/06/15 ip

## G Inspection reports, IE Bulletine & correspondence

7906230147 Farwards IE Insp Repts 50-010/79-10,50-237/79-10 & 50-247/79-08 on 790316-30. No noncompliance noted MEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Bupport Branch 79/04/23 2pg

--7906250153 IE Insp Repts 50-010/79-10.50-237/79-10 & 50-249/79-08 on 790316-20 No noncompliance noted Major areas inspected maint activities, glant operations & physical protection & tecurity organization.

SPESSARD.R.L., WONO, H.K., REYES.L.A. Region 3, Chicago, Office of the Director 79/04/25 9pp.

7906290493 Responds to IE Bullstin 79-08 Forwards into re review of TMI incident Existing line isolation not important to ECCB injection.
REED. C Commonwealth Edison Co 79/04/27 22pp

7906260630 Forwards IE Insp Repts 50-237/79-11 & 50-249/79-09 on 790453.21-23 & 27 No noncompliance noted HEIGHMAN, R. F. Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/05/03 2pg

--7906260633 IE Insp Repts S0-237/79-11 & S0-249/79-09 on 790413,21-23 & 27 No noncompliance noted Major areas inspected integrated leak test & Licensee action on previously identified item of noncompliance.

REVES.L A . DETTENMEIER.R., STREETER.J F Region 3, Chicago. Office of the Director 79/05/03 App

7906120083 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07

7906110101 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J. O Region 3, Chicago, Office of the Director. 79/05/11, is.

7906190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies,"
KEPPLER: J O Region 3, Chicago, Office of the Director 79/03/11.

7906080196 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U "

KEPPLER: J. O Region G. Chicago, Office of the Director 79/03/18

7906130082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Davice in Circuit Breakers for Engineered Safety Sys." Licenses action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 is

7905230079 Submits corrected copy of page 6 of Insp Repts 50-273/79-ii \$ 50-249/79-09 MEISHMAN.R F Region 3: Chicago, Reactor Operations Nuclear Support Branch 79/05/23 2pp

7906200080 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Dyster Greek Reactor" KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/29

### R Pariodic operating reports & related correspondence

7906130336 Forward monthly operating rept for May 1979 STEPHENSON, B B Commonwealth Edison Co 79/06/11 1

--7904:30338 Monthly operating rept for May 1979
CLEBIXIEWICZ.S Commonwealth Edison Co 79/06/04, 35pp

8 Reportable occurrences, LERs & related correspondence

7906040319 LER 79-002 has been voided \* Commonwealth Edison Co 79/06/01 1p

7906180512 Forwards LER 79-013/03L-0 81EPHENSON, B 9 Commonwealth Edison Co 79/06/07 1a

---7906180815 LER 79-013/03L-0 on 790601 during helf-core screm testing, control rod driveling 0-5 (26-19) became uncoupled from control rod when withdrawn beyond position 48 Caused by inner fitter becoming detached HAXWELL.D C Commonwealth Edison Co 79/06/07 ip

7906190418 Forwards LER 79-010/03L-0 STEPHENSON.B 8 Commonwealth Edison Co 79/06/12 1p

--7906190432 LER 79-010/03L-0 on 790815 offgae log rad monitor 1703 3A drifted high & triped on Hi Hi offgae activity Caused by resistor adjustment controlling filament current on log feedback diode Monitor repaired & will be tested monthly KORCHYNEKY. H. Commonwealth Edison Co 79/06/12 ip

7906190437 Farwards LER 79-011/03L-0 STEPHENSON, 9 B Commonwealth Edison Co. 79/06/12 1p

--7906190447 LER 79-011/03L-0 on 790517 intermediate range monitor 17 tripped above Tech Spec max. Caused by instrument drift Monitor readjusted bunBAR.J Commonwealth Edison Co 79/06/12, 1p

7906270152 Forwards LER 79-012/03L-0 STEPHENSON B B Commonwealth Edison Co 79/06/18 19.

--/906270158 LER 79-012/03L-0 on 790524 downscale rod block tripped at 4/125 of full scale, rather than at 5/125 as per Tech Apeca Caused by electronic instrument drift Intermediate range monitor readjusted to 6/125 decreasing DUNBAR.J Commonwealth Edison Co 79/06/18 1p

DOCKET 50-250 TURKEY POINT PLANT, UNIT 3

F Security, medical, emergency & fire protection plans

7906020205 Informs that Compensatory measures are acceptable & will ramain in effect until modified amended security plan is fully implemented. IE should be notified when compensatory measures are discontinued.

8CHMENGER: A Operating Reactors Branch 1 (Pre 790623). 79/04/30-205.

#### G. Adjudicatory correspondence

7908070225 Request by util that NRC deny MP Oncavage 790209 petition for hearing on proposed repairs to steam generators.Notice of appearance of MA Bauser & NA Coll on behalf of util encl Affidavits of GD Whittler & HD Mantz H/Certificate of Bvc BAUSER, M A Lowenstein, Newman, Reis, Akelrad & Toll COLL, N A Steel, Hector & Davis 79/03/09, 20pp.

--7906070226 Urges repair of steam generator tube plugging Alternate methods of repair to be considered are lower section replacement & place retubing NRC to make early determinations of repair reviews by 781015 UHRIG:R E Florida Power & Light Co 77/09/20 2pp

## H General correspondence

- 7906260007 Requests that M Oncavage petition to intervene be granted BEERMANN.T : GATES.R S . GILDEMEISTER.D Affiliation Unknown 79/05/01 7pp
- 7906070337 Requests that NRC grant MP Oncevage potition for hearing & intervention in steam generator repair program NOBLES.T. SCHNEIDER.S. GRETH.R Affiliation Unknown 79/04/27 500

#### M Antitrust correspondence

- 7904040418 Response of util in opposition to FL Cities' motion for antitrust hearing & motion for consolidated hearings Certificate of Svc encl BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/13 Son
- P Operating license stage documents & correspondence
- 7906050019 Responds to 780319 ltr requesting ref to specific QA program used to meet requirements of 10CFR71 51 Revision 2 to topical QA rept is in effect for Turkey Point & FSAR QA program is in effect for Bt Lucía
  UHRIG:R E Florida Power & Light Co 79/04/23 ip
- 7906020246 Forwards Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHMCNCER. A Operating Reactors Branch 1 (Pre 790625) 79/04/24
- --7906020247 Amends 47 & 37 to Licenses DPR-31 & DPR-41, respectively, changing control rod group insertion limits SCHWENCER. A Operating Reactors Branch ( Pre 790625) 77/04/24 | 12pp
- --7906020248 Safety evaluation supporting Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively \* Office of Nuclear Reactor Regulation 79/04/24 2pp
- --7906020249 Notice of issuance t availability of Amends 47 to Licenses DPR-31 to DPR-41, respectively SCHENCER, A Operating Reactors Branch 1 (Pre 790625) 79/04/24 2pp
- 7906250391 Forwards Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability
  SCHWENGER, A Degrating Reactors Branch I (Pre 790625) 79/05/04
- --7906250393 Amends 48 & 40 to Licenses DPR-31 & DPR-41.respectively. revising Tech Specs to require actuation of safety injection based on two of three channels of low pressurizer pressure SCHMERNEER.A Operating Reactors Branch ( (Pre 790625) 79/05/04 7 pp
- ---7906250401 Safety evaluation supporting Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/09/04 3pp
- ---7906250403 Notice of Issuance & availability of Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively SCHWENCER.A Operating Reactors Branch 1 (Pre 790625) 79703704 2pp
- 7906210101 Forwards safety evaluation for steam generator repair program SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/14 2pp
- --7906210102 Safety evaluation for steam generator repair program found acceptable.

  \* Office of Nuclear Reactor Regulation 79/05/14 41pp
- 7906180796 Requests Close I & III amend fees within 14 days in connection w/781211 application for Tech Spec changes reoperability & survaillance of overpressure mitigating sys MILLER: W U License Fee Management Branch 79

- 7906270540 Notification of 790527 meeting w/util in Bethesda.MD to discuss containment purge & related equipment ORDIENHUIS.M Operating Reactors Branch 1 (Pre 790625) 79/05/23 2pp
- 7906060274 Forwards requested fee for 790326 license amend UHRIG.R E Florida Power & Light Co 79/05/29 1p
- 7906060277 Forwards requested fee for 790521 license amend UHRIG.R E Florida Power & Light Co 79/05/29 1p
- 7906130207 Bubmits figure of max predicted heat flux (Fq) for Cycle 6. based on 18-case analysis of ECCS UHRIG.R E Florida Power & Light Co 79/06/08 2pp
- 7904130235 Provides add1 info re costs of limiting containment gurges during high power operations Util attempting to resolve issues raised in NRC 781128 itr Combined containment purges in interim to be limited to 200-h/year

  UHRIO,R E Florida Power & Light Co 79/06/08 2pp
- 7906190266 Submits add1 info re proposed radiological effluent Tech Specs in response to 790522 request UHRIO.R E Florida Power & Light Co 79/06/15 ip
- 7906220184 Submits info re feedwater line design & fabrication history requested by 790828 ltr Remaining info will be forwarded by 790730
  UHRIO.R E Florida Power & Light Co 79/06/19 5pp
- 7906250349 Forwards "Reactor Containment Bldg Integrated Leak Rate Test Rept " UHRIG,R E Florida Power & Light Co 79/06/20 1p
- --7904250350 "Reactor Containment Bldg Integrated Leak Rate Test Rept " \* Florida Power & Light Co 79/03/20 176pp
- G. Inspection reports, IE Bulletins & correspondence
- 7906200487 Forwards IE Insp Repts 50-250/79-09 & 50-251/79-09 on 790313-19 No noncompliance noted LEWIS.R C Region 2, Atlanta. Reactor Operations Nuclear Support Branch 79/04/13 2pp
- --7906200490 IE Insp Repts 50-250/79-09 t 50-251/79-09 on 790313-19 No moncompliance noted Major areas inspected safety-related piping support, restraint surveillance program & containment integrated leakage rate testing BRODKS,E H , ORAHAM,M J Region 2. Atlanta, Office of the Director MARTIN,R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 4pp
- 7906/30494 Responds to IE Bulletin 79-09 Status rept re Youngstown Welding & Engineering Co pipe will be sent no later than 790831
- UHRIO,R E Florida Power & Light Co 79/04/17. ip
- 7906020186 Forwards response to IE Bulletins 79-06 & 79-06A Personnel w/operational responsibilities have completed relevant instructional sessions Operation w/operative level bistables tripped is undesirable INDIA 8 E Florida Power & Light Co 79/04/24 110
- Repts 50-250/79-04 & 50-251/79-04 Corrective actions memo written re proper procedure for signing out rod warmers. UHRIO,R E Fiorida Power & Light Co 79/04/11 2pp
- --7906070368 Forwards IE Insp Repts 50-220/79-04 & 50-251/79-04 on 790206-09 & notice of violation MURPHy.C E Region 2, Atlanta, Office of the Director 79/03/16 2pp
- --7906070372 Notice of violation from insp on 790206-09
  \* Region 2. Atlanta. Office of the Director. 79/03/15 ipp
- --7906070375 IE Insp Rept 50-250/79-04 & 50-251/79-04 on 790206-09 Noncompliance noted infraction in welding mat1 control BLAKE:J J, CONLON:T E Region 2: Atlanta: Office of the Director 79/04/15 4pp

- 7906250452 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10
- 7906110063 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 19
- 7906260290 Responds to IE Bulletin 79-09 re GE Model AK-2 circuit breakers No such circuit breakers currently installed in UHRIO.R E Florida Fower & Light Co 79/05/22 1p
- 7906260354 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Rapts 50-250/79-10 & 50-251/79-10 50-251/79-10 BUTHERLAND.J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/05/22 ip
- --7906260358 Responds to NRC 790423 ltm re violations noted in [E Insp Repts 50-250/79-10 & 50-251/79-10 Corrective actions all health physics shift supervisors instructed to ensure respirator decontamination UHRIGAR E Florida Power & Light Co 79/05/10 3pp
- --7706260493 Forwards IE Insp Repts 50-250/79-10 & 50-251/79-10 on 790319-23 & notice of violation SUTHERLAND.JT Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/04/23 2pp
- --7906260495 Natice of violation from insp on 790319-23
  \* Region 2, Atlanta, Office of the Director 79. 79/04/20 10
- --7906260501 IE Insp Repts 30-250/79-10 & 50-251/79-10 on 790319-23 Noncompliance noted failure to post airborne radioactivity area & loose contamination on respirators ZAVADOEKI, R W, VRAY, J W, OIDSON, A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/20 11pp
- /906260602 Ack receipt of 790514 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-12 & 50-251/79-12 LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support 50-251//7 LEWIS.R C Rev 79/05/22 1 p
- --7904260609 Responds to NRC 790420 ltr re violations noted in \$E Insp Rept 50-250/79-12 & 50-251/79-12 Corrective actions appropriate level channels will be placed in tripped condition when deviation acceptance criteria is exceeded a Fiorida Power & Light Co 79/05/14 2pp
- --7906260611 Forwards IE Insp Repts 50-250/79-12 \$ 50-251/79-12 on 790312-15 & notice of violation LEMIGER C Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch 79/04/20 2pp
- --790626061R Notice of violation from insp on 790312-15
  \* Region 2. Atlanta, Office of the Director 79, 79/04/20 10
- --7906260614 IE Insp Rept 90-250/79-12 & 50-251/79-12 on 790312-21 Noncompliance noted failure to take corrective action on unsatisfactory instrumentation channel check VERDERYIE H., CANTRELLIF E. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 4pp
- i Periodic operating reports & related correspondence
- 7906010262 Submits supplementary rept to Annual Nonradiological Environ Monitoring Rept 1770 UHRIGARE Florida Power & Light Co 79/05/11 2pp
- 3 Reportable occurrences, LERs & related correspondence
- 7906120338 Forwards LER 79-014/Q3L-0 SCHMIDT: A D Florida Power & Light Co. 79/05/24, ip.
- --7906120344 LER 79-014/03L-O on 790424 "ready to start" light on B amergency diesel generator engine control panel failed Gaused by vibration of lamp socket Tests under way to determine if neon unit would be better suited JAMES, D K Florida Pawer & Light Co 79/05/24 2pp
- '906120348 Forwards LER 79-015/03L-0 SCHMIDT, A D Florida Power & Light Co 79/05/24 ip.

- --7906120352 LER 79-015/03L-0 on 790426 B emergency diesel generator failed loading acceptance criteria Caused by cracked half-inch nipple to fuel pump which resulted in partial fuel starvation Nipple replaced & old nipple reanalyzed JAMES.D K Florida Power & Light Co 79/03/24 lp
- 7906120354 Forwards LER 79-016/03L-0 SCHMIDT, A D Florida Power & Light Co 79/05/29 1p
- --7906120363 LER 79-016/03L=0 on 790429 high level alarm annunciated Caused by instrument drift of Tech Spec min & high level alarms & digital level indicator transducer Instruments recalibr SCHOPPMAN, M A Florida Power & Light Co 79/05/29 2pg
- 7906200365 RO 250-79-20 on 790531 emergency diesol generator tripped at result of lockout relay operation Cuased by faulted exciter power transformer YAEGER Florida Power & Light Co 79/06/01
- 7906180613 Forwards LER 79-020/01T-0 SCHMIDT,A D Florida Power & Light Co 79/06/11 1p
- --7906180620 LER 79-020/01T-0 on 790326 during load test emergency diesel generator tripped Caused by design error which led to overheating of exciter power transformer Transformer replaced & plant change/mod implemented SCHOPPMAN.M A Florida Power & Light Co 79/06/11 Spp
- U Congressional/Executive Correspondence
- 7903300226 Informs of attempt to reschedula review of topical rept re
  NRC approved use of Fox Industries no-slip couplers for
  reinforcing steel bars Assures that review is not
  prerequisite for NRC product use
  DENTON.H R Office of Nuclear Reactor Regulation 79/03/08 2pp
- ~~7903300235 Requests response to complaint re NRC regulations & IVA contract award for reinforcing steel bars splicing matl at Yellow Creef plant FOX.C J Foxboro Co 79/02/05 ip
- --7903300243 Forwards ltr written to TVA re violation of NRC regulations in granting award of contract for renar splicing matl to TVA FOX.C J Foxboro Co 79/02/02 3pp
- 7906070045 Discusses constituent's support of MP Oncavage request for NRC to hold public hearings on planned steam generator repairs
  PEPPER:G House of Rep 79/05/01 ip
- 7906260596 Provides addi info re D Browning info request re FL nuclear power situation Discusses wastes produced by FL plants, effluents released & consequences of possible accident COSSICK.L V Office of the Executive Director for Operations gqE. 79/05/17
- --7706260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply MICA, D A House of Rep. 79/04/05 2pp
- --7906260593 Ack receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards instructions to operators re steps to prevent occurrence like TMI & JM Hendrie 790410 testimany to Subcommittee on Nuclear Regulation W/o encl KAHMERER: C Office of Congressional Affairs 79/04/18 1p
- DOCKET 50-251 TURKEY POINT PLANT, UNIT 4
- F Security, medical, emergency & fire protection plans
- 7706020203 Informs that Compensatory measures are acceptable & will remain in effect until modified amended security plan is fully implemented IE should be notified when compensatory measures are discontinued SCHWENCER, A. Operating Reactors Branch 1 (Pre 790425) 79/04/30
- G Adjudicatory correspondence
- 7906070225 Request by util that NRC deny MP Oncavage 790209 petition for hearing on proposed repairs to steam generators Notice of appearance of MA Bauser & NA Coll on behalf of util enci. Affidavits of GD Whittier & HD Mantz. W/Certificate of Svc BAUSER, M. A Lowenstein, Newman, Reis, Arelrad & Toll COLL, N A Steel, Hector & Davis 79/03/09 20pp.

- --7906070226 Urges repair of steam generator tube plugging Alternate methods of repair to be considered are lower section replacement & place retubing NRC to make early determinations of repair reviews by 781015 UHRIG.R E Florida Power & Light Co 77/09/20 2pp
- H General correspondence
- 7906260007 Requests that M Uncavage patition to intervene be granted BEERMANN, T , GATES, R S , GILDEMEISTER, D Affiliation Unknown 79/05/01 7pp
- 7906070337 Requests that NRC grant MP Oncavage petition for hearing & intervention in steam generator repair program NOBLES.T., SCHNEIDER,S., GRETH,R. Affiliation Unknown 79/04/27 Son
- M Antitrust correspondence
- 7906040418 Response of util in apposition to FL Cities' motion for antitrust hearing & motion for consolidated hearings Certificate of Svc encl BOUKNIGHT. J A Lowenstein. Newman. Reis, Axelrad & Toll 79/04/13
- P Operating license stage documents & correspondence
- 7906050019 Responds to 780319 ltr requesting ref to specific GA program used to meet requirements of IOCFR71 51 Revision 2 to topical GA rept is in effect for Turkey Point & FRAR GA program is in effect for St Lucie UMRIO.R E Fiorida Power & Light Co 79/04/23 1p
- 7906020246 Forwards Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/04/24
- --7905020247 Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively, changing control rad group insertion limits
  SCHWENCER.A Deperating Reactors Branch 1 (Pre 790625)
  79704/24 12pp
- ---7906020248 Safety evaluation supporting Amends 47 % 39 to Licenses DPR-31 % DPR-41, respectively \* Office of Nuclear Reactor Regulation 79/04/24 2pp.
- --7906020249 Notice of issuance & availability of Amends 47 & 39 to Licenses DPR-31 & DPR-41, respectively BCHWENCER, A Gperating Reactors Branch 1 (Pre 790625) 79704724 2pp
- 7906250391 Forwards Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively, safety evaluation & notice of issuance & availability SCHWENGER, A Operating Reactors Branch ( (Pre 790628) 79/05/04 2Pp
- --7906250395 Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively, revising Tech Specs to require actuation of safety injection based on two of three channels of low pressurizer pressure SCHMEROER, A. Operating Reactors Branch, 1 (Pre 790625) 79/05/04 78p
- --7906230401 Safety evaluation supporting Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively SCHWENCER, A Operating Reactors Branch 1 (Prs 790625) 79/05/04 Opp
- ---7906280403 Notice of issuance \$ availability of Amends 48 & 40 to Licenses DPR-31 & DPR-41, respectively.
  SCHWENCER.A. Operating Reactors Branch 1 (Pre 790625)
  79705704, 2pp
- 79062:0101 Forwards safety evaluation for steam generator repair program SCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/14 2Dp
- --7906210102 Safety evaluation for steam generator repair program,Program found acceptable \* Office of Nuclear Reactor Regulation 79/05/14 41pp
- 7906180796 Requests Class I & III amend fees within 14 days in connection w/781211 application for Tach Spec changes reoperability & surveillance of overpressure mitigating sys.
  MILLER.W G License Fee Hanagement Branch. 79/05/17. ip

- 7906290540 Notification of 790529 meeting w/util in Bethesda.MD to discuss containment purge & related equipment GROTENHUB.M Operating Reactors Branch 1 (Pre 790625) 79/05/23 200
- 7906040135 Responds to NRC review of 790518 license amend & forwards graph of max predicted Eq generated for Cycle & based on IB-case analysis UKRIGG RE Florida Power & Light Co 79/05/29 2pp
- 7906060274 Forwards requested fee for 790326 license amend UHRIG.R E Florida Power & Light Co 79/05/29 ip
- 7906060277 Forwards requested for for 790521 license amend UHRIO.R E Florida Power & Light Co 79/05/29 19
- 7906080296 Forwards \$4,000 fee for approval of 790518 request UKRIO,R E Florida Power & Light Co 79/05/29 2pp
- 7906130239 Provides add1 info re costs of limiting containment purges during high power operations Util attempting to resolve issues raised in NRC 781128 Itr Combined containment purges in interim to be limited to 200-h/year UHRIG.R E Florida Power & Light Co 79/04/08 2gg
- 7906190266 Submits additinfo re proposed radiological effluent Tech Specs in response to 790522 request UHRIG.R E Florida Power & Light Co 79/06/15 ip
- 7906220184 Submits info re feedwater line design & fabrication history requested by 790525 ltr Remaining info will be forwarded by 790730 URRIG.R E Florida Power & Light Co 79/06/19 5pp
- Q Inspection reports. IE Bullatins & correspondence
- 7906200487 Forwards IC Insp Repts 50-250/79-09 \$ 50-251/79-09 on 790313-19 No noncompliance noted LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/13 2pp
- --7906200490 IE Insp Repts 50-250/79-09 & 50-251/79-09 on 790313-19 No nancompliance noted Major areas inspected safety-related piping support, restraint surveillance program & containment integrated leakage rate testing DRODKS,C H , ORAMAM.M J Region 2. Atlanta. Office of the Director MARTIN,R D Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/04/12 4pp
- 7906130434 Responds to IE Bulletin 79-03 Status rept re Youngstown Welding & Engineering Co pipe will be sent no later than 790531 URRIO:R E Florida Power & Light Co 79/04/17 1p.
- 7706020186 Forwards response to IE Bullstins 79-06 & 79-06A Personnel w/operational responsibilities have completed relevant instructional sessions Operation w/pressurizer level bistables tripped is undestrable UHRIQ:R E Florida Power & Light Co 79/04/24 ligh
- 7906070332 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-04 & 50-251/79-04 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/05/03 ip
- --7906070363 Responds to NRC 790316 ltr re violations noted in IE Insp Repts 80-280/79-04 & 50-231/79-04 Corrective actions memo written re proper procedure for signing out rod warners UHRIG:R E Florida Power & Light Co 79/04/11 2pp
- ---790607036B Forwards IE Insp Repts 50-220/79-04 & 50-251/79-04 on 790206-09 & notice of violation MURPHY.CE Region 2, Atlanta, Office of the Director 79/03/16 2pp
- --7906970372 Notice of violation from insp on 790206-09
  Region 2. Atlanta. Office of the Director 79/03/15 ipp.
- --7906070375 IE Insp Rept 50-250/79-04 & 50-251/79-04 on 790206-09 Noncompliance noted infraction in welding math control. BLAKELU J. CONLON, TE Region 2, Atlanta, Office of the Director 79/04/15 4pp
- 7906250452 Forwards IE Info Notice 79-12: "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2: Atlanta: Office of the Director.
  79/05/10. ip

- 7906110063 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required. D'REILLY, J P. Region 2, Atlanta, Office of the Director. 79/05/11. ip.
- 7906260290 Responds to IE Bulletin 79-09 re QE Model AK-2 circuit breakers No such circuit breakers currently installed in units UHRIO.R E Florida Power & Light Co 79/05/22 Ip
- 7906260334 Ack receipt of 790510 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-250/79-10 & 30-231/79-10 SUTHERLAND. J T Region 2, Atlants, Fuel Facility & Materials Safety Branch 79/05/22 ip
- --7906260358 Responds to NRC 790423 ltr re violations noted in IE Inep Repts 50-250/79-10 & 50-251/79-10 Corrective actions all health physics shift supervisors instructed to ensure respirator decontamination UHR10.R.E Florida Power & Light Co 79/05/10 3pp
- --7904260493 Forwards IE Insp Repts 50-250/79-10 & 30-251/79-10 on 790319-23 & notice of violation.
  SUTHERLAND, J T Region 2. Atlantar Fuel Facility & Haterials Safety Branch. 79/04/23 2pp
- --7906260495 Notice of violation from insp on 790319-23
  Region 2. Atlanta, Office of the Director 79/04/20 ip
- --7906260501 IE Insp Repts 50-250/79-10 & 50-251/79-10 on 790319-23 Noncompliance noted failure to post airborne radioactivity area & loose contamination on respirators ZAVADOSKI.R W. KRAY.J W. OIBSON.A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/20 lipp
- 7904260602 Ack receipt of 790514 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-250/79-12 k 50-251/79-12.

  LEWIS-R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/22
- --7906280609 Responds to NRC 790420 ltr re violations noted in IE Insp. Rept 50-250/79-12 & 50-251/79-12 Corrective actions appropriate level channels will be placed in tripped condition when deviation acceptance criteria is exceeded # Florida Power & Light Co. 79/05/14 2pp
- --7906260611 Forwards IE Insp Repts 50-250/79-12 & 50-251/79-12 on 790312-15 & notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch. 79/04/20 2pp
- --7906260612 Notice of violation from inep on 790312-15
  \* Region 2, Atlanta, Office of the Director 79/04/20 ip
- --7906260614 IE Insp Rept 50-250/79-12 & 50-251/79-12 on 790312-21
  Noncompliance noted failurs to take corrective action on
  unsatisfactory instrumentation channel check,
  VRRDERYLE H., CANTRELLE S., Region 2, Atlanta, Reactor
  Operations Nuclear Support Branch 79/04/19 4pp.
- R Periodic operating reports & related correspondence
- 7906010262 Submits supplementary rept to Annual Nonradiological Environ Monitoring Rept 1978 UHRIG.R E Florida Power & Light Co 79/05/11 2pp.
- S Reportable occurrences. LERs & related correspondence
- 7906140384 RO 251-79-07 on 790519 pipe support in charging pump room inoperable Full rept & corrective action to be submitted in response to IE Bulletin 79-02, "Pipe Support Base Plate Designs Using Concrete Expansion Anchor Bolts "YAEGER, M. K. Florida Power & Light Co. 79/05/21. 1p.
- 7906180510 Forwards LER 79-007-017-0. 8CHMIDT.A D Florida Power & Light Co 79/06/04 ip
- --7906180511 LER 79-007/01T-O on 790519 inoperable pipe support 4-VCH-105 reported by imap team. Cause unknown. Pipe support to be restored per approved procedures.

  BCHOPPMAN.M.A. Florida Power & Light Co 79/06/04 ip

- U Congressional/Executive Correspondence
- 7903300226 Informs of attempt to reschedule review of topical rept re NRC approved use of Fox Industries no-slip couplers for reinforcing steel bars Assures that review is not prerequisite for NRC product use. DENTON, HR Office of Nuclear Reactor Regulation 79/03/08 2pp
- --790300235 Requests response to complaint re NRC regulations & TVA contract award for reinforcing steel bars splicing matl at Yellow Creek plant FOX.C J Forboro Co 79/02/05 ip
- --7903300243 Forwards ltr written to TVA re violation of NRC regulations in granting sward of contract for renar splicing matl to TVA FOX.C J Foxboro Co 79/02/02 3pp
- 7906070045 Discusses constituent's support of MP Oncavage request for NRG to hold public hearings on planned steam generator repairs PEPPER.C House of Rep 79/05/01 ip
- 7906260586 Provides addl info re D Browning info request re FL nuclear power situation Discusses wastes produced by FL plants, affluents released & consequences of possible accident 90SSICK.1 V Office of the Executive Director for Operations 79/05/17. 3pp
- ---7906260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary into for reply HIGA: D.A House of Rep. 79/04/05 2pp
- --7906260593 Ack receipt of 790405 ltr re D Browning info request re FL nuclear power situation Forwards instructions to operators re steps to prevent occurrence like THI & JM Hendrie 790410 testimony to Bubcommittee on Nuclear Regulation W/o encl KAMMERER. C Office of Congressional Affairs 79/04/18 lp
- DOCKET 50-232 UNIV OF NEW MEXICO RESEARCH REACTOR
  J Insurance & indemnity information
- 7906220243 Forwards Amend 10 to Indemnity Agreement E-47 PERGVICH, J. New Merico, Univ. of 79/06/18 2pp
- Q Inspection reports. IE Bulletine & correspondence
- 7906250009 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assamblies."

  BEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/11 ip
- DOCKET 50-254 GUAD-CITIES STATION, UNIT 1

  Q. Adjudicatory correspondence
- 7906010131 Farwards 790316 order re shipment of spent fuel, admitting contentions similar to those at issue in present proceeding as matters in controversey.

  ROISHAN, A. Z. Natural Resources Defense Council, 79/03/20 1p.
- 7906070346 Hemo re standing & contentions of intervenors State of IL.
  NRDG & Citizens for Setter Environ following 790201 special
  prehearing conference on spent fuel storage.
  MILHOLLIN.O L. Atomic Safety and Licensing Board Panel 79/04/19
  1200.
- 7906210357 Forwards representative mat1 prepared by Citizens for Better Environ & NRDC to disclose interest in issue of nuclear power ROISMAN.A.Z. Natural Resources Defense Council. 79/05/03. 60pp
- 7906210337 Motion for reconsideration of 790419 memo & order following special prehearing conference. Objects to admission of Contention 6 re specific threats to irradiated fuel in transit Certificate of Svc encl.

  GODDARD.R. J Branch 2 79/05/04. 3pp
- ---7906210359 Would not oppose Admission of Contention 6 if revised to conform w/Contention 6 as admitted in Duke Power proceeding re-security of spent fuel in transit.
  OODDARD, R. J. Branch 2 79/04/06, 2pp.

- 7706210232 Applicant motion for reconsideration of 770417 memo & order of clarification of 780419 order re physical security of SMM Supporting documentation & Certificate of Svc enci STEPTOE.P Isham. Lincoln & Beale 79/05/07 14pp
- 7906020052 Grants NRC 790504 motion suggesting alternative language for Contention & Denies licensee motion to reconsider admissibility of Contentions 6 % ii MILHOLLIN.O.L Atomic Safety and Licensing Board Panel 79/05/16
- 7906220465 Concludes NRDC & Citizens for Better Environ have standing based on criteria of ALAB-335 Both have established interest in nuclear power issues & are authorized to represent members in proceedings
  MILHOLLIN.G L Atomic Safety and Licensing Board Panel 79/05/29

# J Insurance & indemnity information

- 7906040187 Forwards executed Amends 21,11.7 % 1 to Indemnity Agreements 8-10,8-47,8-59 % B-84, respectively POOLE,R D Commonwealth Edison Co 79/05/29 8pp
- 7906120260 Farwards Endorsements 100 & 101 to MAELU Policy MF-22 % Endorsements 49 & 30 to MAELU Policy MF-54 OSTER, J Communicalth Edison Ca 79/06/07 5pp
- P Operating license stage documents & correspondence
- 7906200237 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of onsite & offsite environ monitoring stations & site maps used for dose determinations

  KEPPLER, J 0 Region 3, Chicago, Office of the Director 79/05/17
- 7906200335 Responds to 1E Builetin 79-01 Forwards info re environ qualification of Class IE equipment required to function under accident conditions & info re use & maint of ASCO solenoid valves
  REED.C Commonwealth Edison Co 79/06/14 39pp
- 7906210190 Requests inclusion in dockets of NEDE-21944~P, "One-Guarter Scale Pressure Suppression Pool Swell Test Program Plant Unique Tests " JANECEK,R F Commonwealth Edison Co 79/06/13 1p
- @ Inspection reports. IE Bulletins & correspondence
- 7906230017 Forwards IE Insp Repts 30-254/79-05 & 50-265/79-05 on 790207-08.15-16.21-22.28 & 0301-02 & notice of violation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 77/03/13 2pp
- --7906250020 Notice of violation from insp on 790207-08,15-16,21-22,28 & 0301-02 \* Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/07 ip
- --7906280026 IE Insp Repts 50-254/79-05 & 50-265/79-05 on 790207-08.
  15-16,21-22,28 & 0301-02 Noncompliance noted inadequate positive control over high radiation area CHRISSOTIMOS, N Region 3. Chicago. Reactor Operations Nuclear Support Branch RIDEN.H D., SPESSARD, R L Region 3, Chicago. Office of the Director 79/03/07 App
- 7906020048 Forwards IE Insp Repts 50-254/78-10 & 50-265/79-08 on 781101-03,07-08 & 790202 No noncompliance noted HIND, J A Region 3, Chicago, Office of the Director 79/04/03 200
- --7906020054 IE Insp Repts 50-254/78-10 & 50-265/79-08 on 781101-03,07-08 & 790202 No noncompliance noted Major areas inspected firearms qualifications for security personnel FOBTER.J.E. MADEDA.T J. DDNAHUE.J F Region 3, Chicago, Office of the Director 79/03/29 18pp
- 7904020011 Ack receipt of 790405 ltr informing NRC of staps taken to correct violations noted in IE Insp Rept 50-234/79-08 HEISHMAN,R F Region 3. Chicago, Office of the Director 79704/27 ip.
- --7906020014 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 30-254/79-08 Corrective actions special test written to secure drywell cooler dampers in open position REED.C. Commonwealth Edison Co. 79/04/05 3pp

- 7906290493 Responds to IE Bulletin 79-08 Forwards info re review of TMI incident Existing line isolation not important to ECCS injection REED: C Commonwealth Edison Co 79/04/27 22pp
  - 77/04/2/ 22db
- 7906120083 Forwards LE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J C Region 3. Chicago. Office of the Director 79/05/07 ip
- 7906180039 Forwards IE Insp Repts 50-254/79-i1 to 50-265/79-09 on 790416-20 Notice of violation withheld (ref 10CFR2 790) HINDrJ A Region 3. Chicago. Safaguards Branch 79/09/10 2pp
- --7906180045 IE Insp Repts 90-254/79-11 & 50-265/79-09 on 790416-20 Details withhald (ref 10CFR2 790) BELANGER, J. L. CHRISTOFFER, G. Region 3, Chicago, Office of the Director HIND, J. A. Region 3, Chicago, Safeguards Branch 79/05/08
- 7906i10101 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics " Written response required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 79/05/11
- 7906190078 Forwards TE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J 9 Region 3. Chicago, Office of the Director 79/05/11
- 7904080194 Forwards (E Circular 79-08, "Attempted Extortion Low Enriched U" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 79061300B2 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J Q Region 3. Chicago, Office of the Director 79/05/22
- 7906200080 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906190246 Monthly operating rept for May 1979 MANNUM, D Commonwealth Edison Co 79/06/05 25pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906060240 Forwards LER 79-009/03L-0
  KALIVIANAKIS,N Commonwealth Edison Co 79/05/11 ip
- ---7906060245 LER 79-009/03L-0 on 790429 while measuring MSIV limit switc trip positions.10 of 12 switches were set greater than 10% of MSIV closure Caused by lack of precise field calibr of exact limit switch trip point Special procedure developed VAHRENWALD. J Commonwealth Edison Co 79/05/11 2pp
- 7906270202 Forwards LER 79-019/03L-0 KALIVIANAKIS:N Commonwealth Edison Co 79/06/15 ip
- --7906270205 LER 79-019/03L-0 on 790524 vacuum breaker 1-1601-32D fa to give closed indication Caused by binding on valve stem not allowing disk to shut Defective bushing & end packing on valve stem replaced LEECH.% Commonwealth Edison Co 79/06/15 3pp

DOCKET 50-255 PALISADES NUCLEAR PLANT
O Adjudicatory correspondence

- 7906200098 Requests opportunity to testify at 790509 replacement hearing in St Joseph MI WOOD, H Affiliation Unknown 79/05/01 ip
- 7906210247 Applicant answer opposing Great Lakes Energy Alliance 79(
  response Response does not cure defects found in earlier
  submission Alliance petition to intervene should be denied
  Gentificate of Svc encl
  MILLER,M I Isham, Lincoln & Beale. 79/05/04 11pp

- 7906270810 Advises of recent abnormal events Two piping support sys found w/o adequate safety margin Plant will remain shut down until mods completed 01385.HE isham, Lincoln & Beale 79/05/04 lp
- 7906230409 States key issues for consideration at 790909 prehearing conference NRC should provide funds to intervenor so latter may exercise legal rights & assist ASLB in finding of facts Certificate of Svc encl
  SINCLAIR
- J Insurance & indemnity information
- 7906070133 Forwards Endorsements 55 & 54 to MAELU Policy MF~50 FOSTER, 8 C Consumers Power Co 79/05/30 3pp
- 7906080173 Forwards executed Amend 9 to Indemnity Agreement E-42 LEAVITY, J B Rensselaer Polytechnic Inst 79/06/01 2pp
- P. Operating license stage documents & correspondence
- 7906050227 Forwards draft evaluation of systematic evaluation program Topic VV-19, "LOCA Resulting from Spectrum of Postulated Breaks Hithin Reactor Coolant Pressure Boundary " Requests response within 30 days 2IEMANN,D L Operating Reactors Branch 2 (Pre 790629) 79/04/30
- 7905020155 Notification of 790507 meeting w/otil to discuss saismit design analysis concern & plans for performing reanalyses SILVER, R.D. Operating Reactors Branch 2 (Pre 790525) 79/05/04 ip
- 7906250028 Forwards Amend 48 to License DPR-20 & notice of issuance & availability
  ZIEHANN, D L Operating Reactors Branch | (Pre 790625) 79/05/15
- --7906250031 Amend 48 to License BPR-20 authorizing entry to high radiation area w/use of monitoring device ZIEMANN, D L Gerating Reactors Branch 2 (Pre 790625) 79705/15 7pp
- --7906250035 Notice of issuance & availability of Amend 48 to License DPR-20 ZIEKANN.D L Operating Reactors Branch 2 (Pre 790625) 79705715 2pp.
- 7906210134 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station numbers of posite & offsite environ monitoring stations & maps used for offsite dose detarmination KEPPLER, J. O Region 3. Chicago. Office of the Director 79/05/17 to
- 7906060236 Discusses interpretation of Tech Spec Section 3 lie refailure of data logger 3 ensuing required power reduction Tech Spec Implies 2-h period for repair of failed data logger HOFFMAN, D.P. Consumers Power Co. 79/06/01 1p
- 7906110165 Discusses mode of operation of auxiliary feedwater sys to be incorporated into plant operating procedures by 790615 HOFFMAN.D.P Consumers Power Co 79/06/05 Ip
- 7906110140 Submits proposed Cycle 4 startup physics program HOFFMAN, D. P. Consumers Power Co. 79/06/06 2pp
- 7906:20172 Forwards request for change to facility Tech Specs. Change will provide for improved physics testing & delete portion no longer applicable
  HOFFMAN.D.P Consumers Power Co. 79/06/07 7pp.
- 7906130002 Responds to NRC 790416 itr Tech Space change requested to overpressure protection; awaiting NRC approval Approved security plan new meeting 10CFR70.35. HOFFMAN.D.P. Consumers Power Co 79/06/08 ip
- 7906130137 Forwards mat! requested in NRC 790529 ltr re systematic evaluation program salamic review M/o encl HOFFMANN.D.P. Consumers Power Co 79/06/08 1p.
- 7906140375 Forwards Revision 2 to "Palisades Plant Steam Generator Repair Rept," containing responses to 790417 & 19 requests for addl info. Requests authorization to use listed code cases during repairs.
  HOFFMANN.D.F. Consumers Power Co. 79/06/11 27pp.

- 7906190174 Submits response to 790607 rapid response questions re effluent monitoring sys HOFFMAN, D.P. Consumers Power Co. 79/06/14 4pp
- 7906290290 Forwards drawings of reactor vessel supports, in response to 790614 telcon request & 790613 internal memo addressing remaining questions M/a drawings FIELDS.H Consumers Power Co 79/06/14 3pp
- 7906220190 Forwards add1 info re cracking in feedwater lines, in response to 790525 request Stress & fatious analysis & welding details will be provided prior to 790730 HQFFHAN, D P Consumers Power Co 79/06/19 7pp
- 7706260181 Answers NRC 770620 question re disposal of spent resint Spent powdered ion-exchange resins from plant feedwater purity sys will be handled as radioactive waste 2 shipped to licensed waste disposal site HOFFMAN, D P Consumers Power Co 77/06/22 1p
- 7906240188 Carrects 790614 response to questions re effluent monitaring sys sys BIXEL.D A Consumers Power Co 79/06/22 ip
- @ Inspection reports. IE Bullstine & correspondence
- 7906020047 Responds to IE Bullstin 79-07 re seismic analyses Dyramic analyses of piping were performed by reactor vendor & A/E Requested info will be submitted in one month BIXEL.D A Consumers Power Co 79/04/24 lp
- 7906250176 Forwards IE Insp Rept 50-255/79-05 on 790321-23 & 27-29 No noncompliance noted HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/25 2pp
- --7906250183 IE Insp Rept 3D-255/79-05 on 790321-23 & 27-29 No moncompliance noted Major areas inspected operations, reportable events licensee action on previously indentified items & spent fuel rack mods
  JURGENSEN.B L . MARNICK, R F Region 3, Chicago, Office of the Director 79/04/24 7pp
- 7906020160 Responds to IE Bulletin 79-04 No Velan swing check valves greater than or equal to 3-inch diameter in use HOFFMAN, D.P. Consumers Power Co. 79/05/01 1p
- 7906120098 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J G Region G. Chicago, Office of the Director 79/05/07
- 7906110096 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11
- 790419008B Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/11
- 7906290778 Responds to IE Builetin 79-07 No OE Type AK-2 circuit breakers are used or planned for use in safety-related sys at plant HOFFRAN, D P Consumers Power Co 79/05/17 2pp
- 7906080200 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U"
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/18
- 7906130094 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER: J G. Region 3: Chicago, Office of the Director 79/05/22 14
- 7906200103 Forwards IE info Notice 79-13, "Indication of Low Water Level in Dyster Greek Reactor" KEPPLER.J.O Region 3. Chicago, Office of the Director 79/05/29
- R Pariodic operating reports & related correspondence
- 7906130020 Forwards monthly operating rept for May 1979 ADAMS, W.E. Consumers Power Co. 79/06/05 ip.

- --7906130031 Monthly operating rept for May 1979 BODTKE,P J Consumers Power Co 79/06/03 4pp
- S Reportable occurrences, LERs & related correspondence
- 7906010239 Forwards LERs 79-022/03L-0 & 79-021/03L-0 H0FFMAN, D P Consumers Power Co 79/05/25 ip
- --7906010248 LER 79-022/03L-0 on 790426 during routine surveillance of safety-related snubber, 5-9 (main steam line) had no visible oil level Dil leakage from snubber caused by failed O-ring, attributed to old age Ring replaced a Consumers Power Co 79705/25 ip
- --7906010252 LER 79-021/03L-0 on 790427 during routine surveillance of safety-rolated snubbers, S-44 (LPIS pump discharge) had no visible oil level Oil leakage from snubber caused by failed O-ring, attributed to al6 age Ring replaced, \* Consumers Power Co 79/05/25 ip
- 7704080308 Forwards 770511 Natl Pollution Discharge Elimination System concempilance notification re excessive neutralizer tank discharge HOFFRAN, D.P. Consumers Power Co. 77/05/31 1p
- --790A0B0310 Natl Pollution Discharge Elimination Bys 790507 noncompliance notification re excessive neutralizer tank discharge Gaused by operating errors Discharge procedures discussed w/operators FODES,R L Consumers Power Co 79/05/11 1p
- 7906220267 Forwards LER 79-023/03L-0 HOFFMAN, D P Consumers Power Co 79/06/18 ip
- --7906220269 LER 79-023/03L-0 on 790318 leak in regenerative heat exchanger (E-54) shell side vent line resulted in degradation of chemical 3 vol control sys Caused by high porosity in weld Weld ground out & repaired \* Consumers Power Co 79/04/18 19
- DOCKET 50-259 BROWNS FERRY NUCLEAR FOWER STATION, UNIT 1
- J Insurance & indemnity information
- 790601027B Forwards executed Amends 12 & 3 to Indemnity Agreements B-52 & B-82: respectively PARRIS. H 9 Tennessee Valley Authority. 79/05/29 2pp
- 7906080229 Forwards Endorsaments 40 & 41 to MAELU Policy MF-66 FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/04. 3pp
- P Operating license stage documents & correspondence
- 7906190134 Forwards Amends 50.44.22 to License DPR-33,DPR-52 & DPR-68, respectively, safety evaluation & notice of issuance & availability re mods to standby gas treatment sys IPPOLITO, T. A Operating Reactors Branch 3 (Pre 790625) 79/05/04. 3pp
- --7906190139 Amends 50,44 & 22 to Licenses DPR-33, DPR-52 & DPR-68, respectively, modifying electrical controls & instrumentation for standby gas treatment sys IFPOLITO.TA Operating Reactors Branch 3 (Pre 790623) 79/05/04 20pp.
- --7906190145 Bafety evaluation supporting Amends 50,44 & 22 to Licenses DPR-33 & DPR-52 & DPR-68, respectively \* Operating Reactors Branch 3 (Pre 790625) 79/05/04 Spp
- ---7906190160 Notice of issuance of Amends 50,44 & 22 to Licenses DPR-33, DPR-52 & DPR-69, respectively IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625), 79/03/04 2pp
- 790A180705 Delays review of proposed hydrostatic pressure testing program & relief from testing requirements of ABME code Section XI until Class III license fee has been remitted DIGOS,R M. Office of Administration 797O5/10 ip
- 7905080090 Ack receipt of 790416 request re proposed pump & valve testing program & relief from testing requirements of ASME code. Action fells in fee Class III) single safety issue involved DIGOBER. M. Office of Administration 79/05/11 ip

- --7706250094 Amends 51,45 & 23 to Licenses DPR-33, DPR-52 & DPR-69, respectively, authorizing change of power supply for cortain low pressure coolant injection valves IPPOLITO, T A Operating Reactors Branch 3 (Pre 770625) 77/05/11 600
- ~~7906250099 Safety evaluation supporting Amends 51,45 & 23 to Licenses DPR-33,DPR-52 & DPR-68,respectively \* Operating Reactors Branch 3 (Pre 790625) 79/05/11 10pp
- --7906250103 Notice of issuance & availability of Amends 51:45 & 23 to Licenses DPR-33,DPR-52 & DPR-48:respectively IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79/05/11 2pp
- 7906190301 Forwards general info re purge operations & analysis of purge valve operability GILLELAND, J E Tennessee Valley Authority 79/06/12 21pp
- 7906210195 Forwards "Secondary Containment Leak Rate Test.70-Day Rept " OILLELAND, J E Tennessee Valley Authority 79/06/19 ip
- --7906210197 "Secondary Containment Leak Rate Test, 90-Day Rept "
  « Tennessee Valley Authority 79/05/11 26pp
- ⊕ Inspection reports, IE Bullotins & correspondence
- 7906180710 Forwards IE Insp Repts 50-259/79-08,50-260/79-08 & 50-296/79-08 on 790205-0302 No noncompliance nated LEWIS.R C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/27 2pp
- --7906180714 IE Insp Repts 50-257/79-08,50-260/79-08 & 90-296/79-08 on 790205-0302 No noncompliance noted Major areas inspected ROs,plant decatering & fire protection sys & plant physical protection SULLIVAN,R F , DANCE.H C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/26 5pp
- 7906070378 Responds to IE Bulletin 79-07 Forwards results of seismic stress analysis of safety-related piping OILLELAND, J E Tennessee Valley Authority 79/04/24 3pp
- 7906290503 Responds to IE Bulletin 79-08 Forwards results of investigation re operational errors & sys misalignments identified during TMI incident OILLELAND. JE Tennessee Valley Authority 79/04/24 14pp.
- 7906130151 Forwards IE Circular 79-07, "Unexpected Speed Increa Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required 0\*REILLY-JP Recion 2. Atlanta, Office of the Director 79/05/0
- 7906210399 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-260/79-06, 50-269/79-06 & 50-296/79-06 LEWISR C Region 2, Atlanta, Reactor Operations Nuclear Bugport Branch 79/05/09 lp
- 7906110066 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/09/11 ip
- 7906140450 Forwards addl response to IE Bulletin 79-04 re incorrect valve weights.Reactor core isolation cooling piping reanalyzed using correct weight of Velan swing check valves GILLELAND.J E Tennessee Valley Authority. 79/05/11 Bpp
- 7906290715 Responds to IE Bulletin 79-09 re GE Type AK-2 breakers Breakers used in safety-related sys at plantinone found equipped w/undervoltage trip device OILLELAND, J. E Tennessee Valley Authority 79/05/21 5pp
- R Periodic operating reports & related correspondence
- 7906150279 Forwards monthly operating rept for May 1979 DEWEASE, J G Tennessee Valley Authority 79/06/11. 1p

- --7906150283 Monthly operating rept for May 1979
  DEWEASE, J Q Tennessee Valley Authority 79/05/31 34pp
- 7906220367 Forwards revision to "Environ Radioactivity Levels Annual Rept 1978" to supersede rept issued 790427 Revision corrects some radioactive levels Conclusions in original rept are still vakid
  OILLELAND.JE Tennessee Valley Authority 79/06/18 ip
- ---7906220374 "Environ Radioactivity Levels, Annual Rept 1978," revised version \* Tennessee Valley Authority RH-79-3-BF2 78/12/31 48pp
- DOCKET 50-260 BROWNS FERRY NUCLEAR POWER STATION, UNIT 2
- J Insurance & indemnity information
- 7906010278 Forwards executed Amends 12 & 3 to Indemnity Agreements B-52 & B-82; respectively PARRIES, H O Tennessee Valley Authority 79/03/29 2pp
- 7906080229 Forwards Endorsements 40 & 41 to MAELU Policy HF-66 FIELDER.J March & McLenon, H & H Nuclear Consultants, Inc. Div 79/06/04 3pp
- P Operating license stage documents & correspondence
- 7906040033 Requests add1 info to complete review of changes to Tech Specs re startup test program IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79704/23 3pp
- 7904190134 Forwards Amends 50,44,22 to License DFR-33,DFR-52 & DFR-68,respectively,safety evaluation & notice of issuance & availability re mods to standby gas treatment sys IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/03/04 3pp
- --7906190139 Amends 50, 44 & 22 to Licenses DPR-33,DPR-52 & DPR-68, respectively, modifying electrical controls & instrumentation for standby gas treatment sys IPPOLITIO.TA Operating Reactors Branch 3 (Pre 790625) 79705704 20pp
- --7906190145 Safety evaluation supporting Amends 50,44 & 22 to Licenses DPR-33 & DPR-82 & DPR-68 respectively \* Operating Reactors Brench 3 (Pre 790625) 79/05/04 Spp
- 7905080090 Ack receipt of 790415 request re proposed pump & valve testing program & relief from testing requirements of ASME code. Action falls in fee Class III single safety issue involved DIGOSER M Office of Administration 79/05/11 1p
- 7906250068 Forwards Amends 51,45 & 23 to Licenses DPR-33,DPR-52 & DPR-6B,respectively, safety evaluation & notice of issuance & availability | PPDLITQ,T A | Operating Reactors Branch 3 (Pre 790625) 79/05/11, 2pp
- --7906250094 Amends 31, 45 & 23 to Licenses DPR-33, DPR-52 & DPR-68, respectively, authorizing change of power supply for certain low pressure coolant injection valves, IPPOLITO T A Operating Reactors Branch 3 (Pre 790625) 79/05/11 6pp
- --7906250099 Safety evaluation supporting Amends 51,45 & 23 to Licenses DPR-33,DPR-52 & DPR-68,respectively \* Operating Reactors Branch 3 (Pre 790625) 79/05/11 10pp.
  - G Notice of issuance & availability of Amenda 51,45 & 23 to s DPR-33, DPR-52 & DPR-68 respectively OrT. A Operating Reactors Branch 3 (Pre 790625) 1 20p
    - ds general info re purge operations & analysis of rability.
      Tennessee Valley Authority 79/06/12. 21pp
    - ds "Secondary Containment Leak Rate Test, 90-Day Rept " Tennessee Valley Authority, 79/06/19, ip

- ~-7904210199 "Secondary Containment Leak Rate Yest.90-Day Rept "
  \* Tennesses Valley Authority 79/05/11 26pp
- G Inspection reports. IE Bulletins & correspondence
- 7906180710 Forwards IE Insp Repts 30-259/79-08, 50-260/79-08 & 50-276/79-08 on 790205-0302 No moncompliance noted LEHIG.R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 2m
- ---7906180714 IE Insp Repts 30-259/79-08.50-260/79-08 & 30-296/79-08 on 790205-0302 No noncompliance noted Major areas inspected ROs, plant dewatering & fire protection sys & plant physical protection SULLIVAN,R F, DANCE,H C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/26 5pp
- 7906070378 Responds to IE Bulletin 79-07 Forwards results of seismic stress analysis of sefsty-related piping QILLELAND.J E Tennessee Valley Authority 79/04/24 3pp
- 7906290503 Responds to IE Bulietin 79-08 Forwards results of Investigation re operational errors & sys misalignments identified during TMI incident OILLELAND. J E Tennessee Valley Authority 79/04/24 14pp
- 7906130151 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/02 ip
- 7906210399 Ack receipt of 790418 ltr informing NRC of staps taken to correct violations noted in IE Insp Repts 50-260/79-06. 50-229/79-06 & 50-296/79-06 LEWIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/09 ip
- 7906110066 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Hritten response required O'REILLY, JP Region 2, Atlanta, Office of the Director 79/03/11 ip
- 7906140450 Forwards addl response to IE Bulletin 79-04 re incorrect valve weights Reactor core isolation cooling piping reanalyzed using correct weight of Velan swing check valves. OllLELAND.J E Tennessee Valley Authority 79/03/ii 8pp
- 7906290715 Responds to IE Bulletin 79-09 re GE Type AK-2 breakers Breakers used in safety-related sys at plantrnone found equipped w/undervoltage trip device OILLELAND, J E Tennessee Valley Authority 79/05/21 5pp
- R. Periodic operating reports & related correspondence
- 7906150279 Forwards monthly operating rept for Hay 1979 DEWEASE, J G Tennessee Valley Authority 79/06/11 1p
- --7906150283 Monthly operating rept for May 1979
  DEWEASE, J G Tennessee Valley Authority 79/05/31, 34pp
- 7906220369 Forwards revision to "Environ Radioactivity Levels.Annual Rept 1978" to supersede rept issued 790427 Revision corrects some radioactive levels Conclusions in original rept are still valid OILLELAND.J E Tennessee Valley Authority 79/06/18 1p
- --7906220374 "Environ Radioactivity Levels, Annual Rept 1978," revised version 
  \* Tennessee Valley Authority RH-79-3-RF2 78/12/31 48pp.
- 8 Reportable occurrences, LERs & related correspondence
- 7906010207 Forwards LER 79-006/03L-0. FOX: H S. Tennessee Valley Authority 79/05/24 ip.
- --7906010210 LER 79-006/03L-O on 790427 prior to refueling shutdown, drywell prepurge tritium sample not taken Caused by lack of understanding between operational & lab personnel Operating instructions amended to prevent recurrence \* Tennessee Valley Authority 79/03/24. ip
- 7906140322 RO 50-260/79-011 on 790526 rod inadvertently pulled three notches during attempt to reach criticality Cause not established Operator interviewed.

  DEMEASE:H G Tennessee Valley Authority 79/05/30 1p.

- 7906120329 Forwards LER 79-011/01T-0 FOX: H S Tennessee Valley Authority 79/06/06 10
- --7906120330 LER 79-011/01T-0 on 790526 while pulling control rods first rod 26-27 in group 3 was inadvertently withdrawn three rod 26-27 in group 3 was inadvertently withdrawn thre notches Caused by unexplained factors Procedures were
  - Tennessee Valley Authority 79/06/06 2pp
- 7906120384 Forwards LER 79-009/03L-0 FOX.H S Tennessee Valley Authority 79/06/06 1p
- ~~7906120387 LER 79~009/03L-0 on 790510 scram accumulator level switch LB-2-85-34 for control rod drivelines 58-39 & 58-19 failed to give annunciation for high accumulator level Caused by switch failure

  \* Tennessee Valley Authority 79/06/06 2pp
- 7906130286 Forwards LER 79-010/03L-0 FOX:H S Tennessee Valley Authority 79/06/07 ip
- --7906130288 LER 79-010/03L-0 on 790510 residual heat removal sys snubber came apart upon removal for testing Caused by piston unscrewing from rod after locking key vibrated loose Snubber replaced & other snubber tested

  \* Tennessee Valley Authority 79/06/07 2pp
- 7906290142 Forwards LER 79-012/03L-0
  FOX: H S Tennessee Valley Authority 79/06/26 in
- --7906290152 LER 79-012/03L-0 an 790528 during post-refueling startup testing of RCIC turbine, electronic overspeed device could not be reset Caused by failure of electronic overspeed device, Airpax Model F68 406 Overspeed device replaced \* Tennessee Valley Authority 79/06/26 2pp
- 7906290159 Forwards LER 79-014/01T-0 FGX:H S Tennessee Vallay Authority 79/06/26 1p
- --7906270187 LER 79-014/01T-0 on 790526 during cold shutdown for refueling local leak rate was found to exceed Tech Spec levels Caused by deterioration of valve seats in main steam, ventilation, feedwater & RCIC sys Valves repaired \* Tennessee Valley Authority 79/06/26 4pp
- DECKET 50-261 H B ROBINSON PLANT, UNIT 2 F Security, medical, emergency & fire protection plans
- 7906120231 Forwards amend to 790317 request to revise fire protection Tech Specs Encl revised pages correct typographical b numbering errors & change specs re reactor containment UTLEY.E E Carolina Power & Light Co 79/06/07 opp
- Q Adjudicatory correspondence
- 7706230180 Forwards 751017 Amend 13.751203 Amend 15.761203 Amend 25 & 770107 & 770211 Itrs to clarify SER Suppl 2 N/o enc1 LEMIS.8 H Branch 2 77/05/02 2pp
- 7906210274 Applicant motion to dismiss proceeding Disposition of power increase safety aspects should be governed by 10CFR2 760 Urges that date be set for NRC response to amend issue Certificate of Syc encl TROMBRIDGE.O F Shaw Pittman, Potts. & Trowbridge 79/05/08 4pp
- 7904220452 Grants extension until 790530 for NRC to respond to 790522 applicant motion to dismiss proceedings re OL amend application Atomic Bafety and Licensing Board Panel 79/05/25 ip
- J. Insurance & indemnity information
- 7904080177 Forwards executed Endorsements 58,59 \$ 40 to NELIA Policy NF-180 GRAHAM,W E Carolina Power & Light Co 79/06/01 4pp
- P Operating license stage documents & correspondence
- 7906200298 Discusses review of 790315 submittal re acceptability of proposed isolation valve seal water sys Proposed sys is acceptable & can be used in future Type C tests Safety tion encl EER.A. Operating Reactors Branch 1 (Pre 790625) 79/04/23 SCHWENCER, A. 2pp.

- -- 7906200300 Safety evaluation of isolation valve seal water sys Sys Operating Reactors Branch 1 (Pre 790625) 79/04/23 2pp
- 7906040126 Forwards Amend 37 to License DPR-23 & notice of issuance & availability BCHWENCER, A Operatino Reactors Branch 1 (Pre 790625) 79/04/30
- --7906040130 Amend 37 to License DPR-23, changing Tech Specs to incorporate NRC-requested changes re qualifications of environ & radiation control supervisor SCHWENCER.A Operating Reactors Branch | (Pre 790625) 79/04/30
- -- 7906040133 Notice of issuance & availability of Amend 37 to License BCHWENCER, A Operating Reactors Branch 1 (Pre 790625) 79/04/30
- 7906130157 Forwards safety evaluation for Amend 36 to License DPR-23 SCHWENGER, A Deprating Reactors Branch 1 (Pre 790625) 79/05/01
- 7906260190 Summary of 790510 mesting w/util re auxiliary feedwater sys & mods required of non-B&W plants in light of TMI-2
  TRANMELL,C M Operating Reactors Branch 1 (Pre 790625)
  79/05/18 Spp
- 7906080291 Forwards license amend for radiological effluent Tech Specs
  UTLEY/E E Carolina Power & Light Co 79/05/3t 10
- --7906080293 License amend for radiological effluent Tech Specs \* Carolina Power & Light Co 79/05/31 62pp
- 7906200356 Forwards add1 info requested on 790521 Info is to be used to prepare basis for continued plant operation in light of TMI-2 event UTLEV.E E Caroline Power & Light Co 79/06/15 13pp
- 790626053B Responds to 790525 data request re feedwater lines Preliminary examination shows cracks exist in inlet lines Planned mods to sys will delay useful response to further info requests until completion UTLEY.E E Carolina Power & Light Co 79/06/20 1p
- O Inspection reports, IE Bulletins & correspondence
- 7906040019 Forwards response to IE Dulletin 79-06A, "Operational Errors & Sys Misalignments Identified During TMI Incident "
  Detailed procedure changes will be developed to address problem of overriding of automatic actuation
  FURR.B J Carolina Power & Light Co 79/04/24 20pp
- 7906250440 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P 79/05/10 1p Region 2. Atlanta, Office of the Director
- 7906110039 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 ip
- 7906250111 Updates info re admitting addl NRC inspector to facility Forwards vital area accoss list Requests site orientation re badge issuance, escort duties & emergency evacuation for individuals listed O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/18 200
- R Periodic operating reports & related correspondence
- 7906110166 Forwards monthly operating rept for May 1979 BANKS, H R Carolina Power & Light Co 79/06/08 1p
- --7906110167 Monthly operating rept for Hay 1979
  WATFORD, M L Carolina Power & Light Co 79/06/04 4pp
- S Reportable occurrences. LERs & related correspondence
- 7906070194 Forwards LER 79-014/03L-0 BANKS:H R. Garolina Power & Light Co 79/06/04 ip

- --7906070200 LER 79-014/03L-0 on 790305 during fuel shuffle operation, distector voltage was lost on N-32 source range detector Gaused by power supply switchover of instrument buss 2 from MCC-9 to inverter A Operations personnel to be instructed STARKETER B Carolina Power & Light Co 79/06/04 2pp
- 7906070251 Forwards LER 79-015/03L-0 BANKS: HR Garolina Power & Light Co 79/06/04 1p
- --7906070265 LER 79-015/03L-O on 790505 during refusiing high leakage detected in penetration pressurization sys Caused by failure of purge valve to seat properly Seat adjusted STARKEY-R B Carolina Fower & Light Co 79/06/04 2pp
- 7906140494 Notifies that reactor containment bldg integrity was breached when employee opened inner air lock when outer door was not sealed due to faulty mechanism No release was made since containment purge was in progress

  STARKEY.R B , ROBINSON.H B Carolina Power & Light Co 79/06/04
- 7906180501 Forwards LER 79-016/01T-0 BANKS,H R Carolina Power & Light Co 79/06/13 tp
- --7906180506 LER 79-016/01T-0 on 790603 w/plant in hot shutdown, reactor containment integrity was breached Caused by sheared bolt in personnel air lock door interlock mechanism Sheared bolt replaced b interlock returned to svc STARKEY, R B Carolina Power b Light Co 79/06/13 2pp
- 7906270174 Forwards LER 79-017/01L-0
  BANKS.H R Carolina Power & Light Co 79/06/25 1p
- --7906270176 LER 79-017/01L-0 on 790611 leak assumed to be in excess of O 35 gallons/minute identified in one tube of C steam generator No cause identified Leak repaired by explosive tube plugging STARKEY, R B Carolina Power & Light Co 79/06/25 2pp

# BOCKET \$0-262 BRIGHAM YOUNG UNIV RESEARCH REACTOR J Insurance & Endemnity Information

- 7906200353 Forwards executed copy of Amend 9 to Indemnity Agreement E-50 VISICK, H H Brigham Young Univ 79/06/13 2pp
- G Inspection reports, IE Bulletins & correspondence
- 7906250008 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/11

# DOCKET 50-263 MONTICELLO NUCLEAR GENERATING PLANT F Security, medical, emergency & fire protection plans

- 7906130202 Forwards supplemental info for physical security plan re implementation statum Info withheld (ref 10CFR2 790) MAYER:L O Northern States Power Co 79/06/08 1p
  - eption to safety evaluation Submits review of al Laboratory 79/06/20 3pp
    - Remaining issue does
- 7906070032 Forwards BAND77-1927, "Transport of Radionuclides in Urban Environs: Working Draft Assessment." SECY-78-311.dtd 780614, & SECY-78-311A.dtd 781109 W/o encl LEWIB.B H. Branch 2 79/03/30. 2pp,
- P Operating license stage documents & correspondence
- 7906200451 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite environ monitoring stations & site maps used for offsite dose determinations or evacuation

  MEPPLER, J. 0 Region G. Chicago, Office of the Director 79/05/17 ip.

- 7906200517 Discusses results of 790507-11 insp re implementation of parts of approved security plan Plan should be implemented in accordance w/encl ltr Ltr withheld (ref 100FR2 790) KEPPLER, J Q Region 3. Chicago. Office of the Director 79/05/}8
- 7906120340 Provides supplemental info re containment purging during normal plant operation, in further response to NRC 781129 ltr HAYER, L O Northern States Power Co 79/06/07 3pp
- O Inspection reports, IE Bulletins & correspondence
- 7906050046 Forwards IE Insp Rept 50-269/78-21 on 781024-25 & 790227-20 No nancompliance noted FigRELLI, 0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906050051 IE Insp Rept 50-263/78-21 on 791024-25 % 790227-28 No noncompitance noted Major areas inspected inservice insp & main steam equalizer piping mod WILLIAMS.C C . DANIELSON. D H Region 3, Chicago, Office of the Director 79/03/29 6pp
- 7904070018 Forwards IE Bulletin 79-08, "Events Relevant to BWRs
  Identified During TMI Incident " Licensee action required
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/04/14
- 7906250121 Forwards IE Insp Rept 50-263/79-03 on 790327-29 No noncompliance noted DAVIS:A D Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- --7906250125 [E Insp Rept 50-263/79-03 on 790327-29 No noncompliance noted Hajor areas inspected administrative & mgt control sys. QA & control in sampling & analytical measurements & licensee internal audits ESSIG.TH. GESTMANN, M J Region 3. Chicago, Office of the Director 79/04/24 App
- 790A020157 Responds to IE Bulletin 79-01 Switches similar to NAMCO Model SL3B2M are used at facility but do not perform safety functions Environ qualification data and MACHTEZ.L J Northern States Power Co 79/04/30 Spp
- 7906020130 Responds to IE Bullotin 79-04 Velan swing check valves are installed on offgas sys Velan Engineering Corp will determine weights & transmit info to Westinghouse in approx two weeks
  WACHTER.L J Northern States Power Co 79/05/01 ip
- --7906020131 Responds to 1E Bulletin 79-04 Velan valve weights were incorrect but have been reanalyzed in compliance w/bulletin No mod required Tabulation of valve use encl WACHTER.L. J. Northern States Power Co. 79/05/01 4pp
- 7906040378 Responds to IE Bulletin 79-08 Actions have been initiated re review of TMI containment isolation design auxiliary heat removal systreactor vessel water & plant operating procedures WACHTER.L J Northern States Power Co 79/05/01 8pp
- 7906130138 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required KEPPLER.J O Region 3. Chicago. Office of the Director 79/05/02
- 7906120121 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/07 ib
- 7906110106 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics " Written response required KEPPLER.J. O Region 3. Chicago: Office of the Director 79/05/11 to
- 7906190099 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11
- 7906260305 Forwards IE Insp Rept 50-263/79-04 on 790425-27 & notice of violation HIND, J A Region 3, Chicago, Safeguards Branch 79/05/16 2pp

- --7906260306 Notice of violation from insp on 790425-27
  \* Region 3. Chicago. Office of the Director 79/05/10 in
- --7906260312 IE Insp Rept 50-263/79-04 on 790425-27 Noncompliance noted reporting unirradiated SNM as irradiated in cooling under composition of ending inventory Details withheld (ref 10CFR2 790)
  FINLEY, A G , PATTERSON, J P , HIND, J A Region 3, Chicago, Safegyards Branch 79/05/16 1p
- 79060B0204 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7906130109 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Bys " Licensee action required KEPPLER, J 0 Region 3, Chicago, Office of the Director 79/05/22
- 7906200131 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7706120375 Forwards monthly operating rept for May 1977 MAYER, L O Northern States Power Co 79/06/07 ip
- --7906120378 Monthly operating rept for May 1979 MYRABO, A L. Northern States Power Co. 79/06/04 4pp

#### DOCKET 50-264 DOW CHEMICAL CO

- @ Inspection reports. IE Bulletins & correspondence
- 7906140194 Forwards IE Insp Rept 30-264/79-01 on 790411-12 No noncompliance noted HIND, J A Region 3, Chicago, Bafeguards Branch 79/09/04 2pp
- --7906140200 IE Inep Rept 30-264/79-01 on 790411-12 No noncompliance noted Major areas inspected security plan Details withheld (ref 10CFR2 790)

  MADEDA: T J Region 3. Chicago. Office of the Director HOHELL: J C : HIND: J A Region 3. Chicago. Safeguards Dranch 79703/03 ip
- 7906190042 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J G Region 3, Chicago, Office of the Director 79/09/11
- 77060B0134 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/18

## DOCKET 50-265 GUAD-CITIES STATION, UNIT 2

## 9 Adjudicatory correspondence

- 7906010131 Forwards 790316 order re shipment of spent fuel, admitting as matters in controversy contentions similar to those at issue in present proceeding ROIGHAN, A Z Natural Resources Defense Council 79/03/20 1p
- 7906070346 Memo re standing & contentions of intervenors State of IL, NRDC & Citizens for Better Environ following 790201 special grehearing conference on spent fuel storage MILHOLLIN.C. L. Atomic Bafety and Licensing Board Panel 79/04/19 1209
- 7906210337 Forwards representative math prepared by Citizens for Better Environ & NRDC to disclose interest in issue of nuclear power ROIEMAN, A. Z. Natural Resources Defense Council 79/05/03 60pp
- 7906210337 Mation for reconsideration of 770419 memo & order following special prehearing conference. Objects to admission of Contention 6 re specific threats to irradiated fuel in transit Certificate of 8vc ent. OCOBARD, R J. Branch 2 79/05/04 3pp

- 7906210339 Would not oppose admission of Contention 6 if revised to conform w/Contention 6 as admitted in Duke Power proceeding re security of spent fuel in transit GDDDARD, R J Branch 2 79/04/06 2pp
- 7906210252 Applicant motion for reconsideration of 790417 memo & order of clarification of 780419 order re physical security of SMM Supporting documentation & Certificate of Svc encl STEPTOE.P Isham, Lincoln & Beale 79/05/07 14pp
- 7906020032 Orants NRC 790504 motion suggesting alternative language for Contention 6 Denies licensee motion to reconsider admissibility of Contentions 6 & 11 MILHOLLIN, O. L. Atomic Safety and Licensing Board Panel 79/05/16 4pp
- 7906220463 Concludes NRDC & Citizens for Better Envir have standing based on criteria of ALAB-535 Both have established interest in nuclear power issues; both are authorized to represent their members in proceedings
  MILHOLLIN, O. L. Atomic Safety and Licensing Board Panel 79/05/29.

# J Insurance & indemnity information

- 7906040187 Forwards executed Amends 21,11.9 & 1 to Indemnity Agreements B-10,8-47,8-59 & 8-84, respectively POOLE.R D Commonwealth Edison Co 79/05/29 8pp
- P Operating license stage documents & correspondence
- 7906200239 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of onsito & offsite environ monitoring stations & site maps used for dose determinations

  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/17
- 7906200335 Responds to IE Bulletin 79-01 Forwards info re environ qualification of Class IE equipment required to function under accident conditions & info re use & maint of ASCO solenoid valves

  REED: C Commonwealth Edison Co 79/06/14 39pp
- 7906210190 Requests inclusion in dockets of NEDE-21944-P. "One-Quarter Bcale Pressure Suppression Pool Swell Test Program Plant Unique Tests " JANECEK.R F Commonwealth Edison Co 79/06/15 1p
- G Inspection reports, IE Bulletins & correspondence
- 7908250017 Forwards IE Inap Repts 50-254/79-05 & 50-265/79-05 on 790207-08, 15-16, 21-22, 28 & 0301-02 & notice of violation HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/13 2pp
- ---7906250020 Notice of violation from insp on 790207-08,15-16,21-22,28 & 0301-02

  \* Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/03/07 19
- --7906250026 IE Insp Repts 50-254/79-05 % 50-265/79-05 on 790207-08, 15-16,21-22,28 % 0301-02 Noncompliance noted inadequate positive control over high radiation area CHRISSOTIMOB,N Region 3, Chicago, Reactor Operations Nuclear Support Branch RIDEN;M D , SPESSARD, R L Region 3, Chicago, Office of the Director 79/03/07 6pp
- 7906020048 Forwards IE Insp Repts 50-254/78-10 & 50-265/79-08 on 781101-03,07-08 & 790202 No noncompliance noted HIND J. A Region 3, Chicago, Office of the Director 79/04/03 2pp
- --7906020054 IE Insp Repts 50-254/78-10 & 50-265/79-08 on 781101-03,07-08 & 790202 No noncompliance noted Major areas inspected firearms qualifications for security personnel FORTER.J E. HADEDA.T J. DONAMUE.J F Region 3, Chicago, Office of the Director 79/03/29 18pp
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessal Head Insulation Support Problem " No action required KEPPLER, J. O Region 3, Chicago, Office of the Director 79/05/07
- 7906180039 Forwards IE Insp Repts 50-254/79-11 & 50-265/79-09 on 790416-20 Notice of violation withheld (ref 10CFR2 790) HIND.J A Region 3. Chicago, Safeguards Branch 79/05/10 2pp

- -- 7906180045 IE Insp Repts 50-254/79-11 & 50-265/79-09 on 790416-20
  Details withheld (ref 10CFR2 790)
  BELANGER, J L . CHRISTOFFER, 0 Region 3, Chicago, Office of the
  Director HIND, J A Region 3, Chicago, Bafeguards Branch
  79/05/08 [D
- 7906110101 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190078 Forwards [E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER: J G Region 3, Chicago: Office of the Director 79/05/11
- 7906080196 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18 ip
- 7906130082 Forwards IE Bulletin 79-1t. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/22 ip
- 7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/29
- R Pariodic operating reports & related correspondence
- 7906190246 Monthly operating rept for May 1979 HANNUM, D Commonwealth Edison Co 79/06/05 25pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906220381 Forwards LER 79-010/03L-0 KALIVIANAKIS N Commonwealth Edison Co 79/06/12 ip
- --7906220386 LER 79-010/03L-0 on /90514 2A fuel pool radiation monitor failed upscale & failed again on 790601 & 02 Caused by failure of GM-tube in sensor conventor unit Tube finally replaced w/Amperex 18529
  VAHRENWALD, J. Commonwealth Edison Co. 79/06/12 1p
- 7906220359 Forwards LER 79-009/03L-O Corrects docket number of original forwarding ltr KALIVIANAKIS.N Commonwealth Edison Co 79/06/13 1p
- 7906270215 Forwards LER 79-011/03L-0 KALIVIANAKIS,N Commonwealth Edison Co 79/06/14 ip
- --7706270217 LER 79-011/03L-0 on 790521 three cables not installed in accordance w/drawings Caused by error in cable routing during initial const Reroute of cables will take place during Nov 1979 refueling outage
  WILLEMSEN.B. Commonwealth Edison Co. 79/06/14 2PP
- DOCKET 50-266 POINT BEACH NUCLEAR PLANT, UNIT 1
- F. Security, medical, emergency & fire protection plans
- 7706200166 Documents DJ Ivey 770608 telcon w/JS Berggren re util security plan. Encl withhold (ref 100FR2 770)
  REED,O A Wisconsin Electric Power Co 77/06/11 ip
- H General correspondence
- 7906040199 Responds to 790228 ltr transmitting petition on NRC-imposed gatehouse security processing of regular plant employees Discusses means of dealing w/specific concerns Codes of Federal Regulations except encil FELTON. J. M Division of Rules and Records 79/04/13 4pp
- --7704040203 Returns 770228 patition, re-gatehouse security for plant employees & proposed response Advises treatment as petition for rulemaking under 10CFR2 206 REIS.E.J. Branch 3 77/03/22 ip
- J Insurance & indomnity information
- 7906070193 Forwards executed Endorsements 57,58 & 59 to NELIA Policy NF-178,& Endorsements 48,49 & 50 to HAELU Policy MF-53 DUNDAS,W.J Wisconsin Electric Power Go 79/05/31 7pp

- P Operating license stage focuments & correspondence
- 7906200312 Summary of 790424 meeting w/util & Westinghouse in Bethssda.

  MD re dash pot end cap cracks on Westinghouse DB-50 & DB-75
  air circuit breakers List of attendees, schematic design &
  tripping characteristics encl
  TRAMMELL.C M Operating Reactors Branch 1 (Pre 790623)
  77/05/02 7pp
- 7906230925 Forwards Amends 38 & 43 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability
  8CHMENCER.A Deerating Reactors Branch 1 (Pre 790625) 79/05/11 2pp
- --7906250326 Amends 38 % 43 to Licenses DPR-24 % DPR-27, respectively, requiring actuation of safety injection, revising opening logic for pressurizer power operated relief valves % modifying power supplies

  SCHWENCER.A Operating Reactors Branch 1 (Pre 790625)

  79/05/11 14pp
- --7906250327 Safety evaluation supporting Amends 38 % 43 to Licenses PPR-24 & DPR-27, respectively SCHHENCER.A Operating Reactors Branch 1 (Pre 790625) 79703711 5pp
- --7906250328 Notice of issuance & availability of Amends 38 & 43 to Licenses DPR-24 & DPR-27, respectively 8CHWENCER.A Operating Reactors Branch ( Pre 790628) 79/05/11 2pp
- 7905200330 Summary of 790511 meeting w/util in Bethesda,MD ra auxiliary feedwater sys List of attendees & matl discussed encl TRANKELL,C M Operating Reactors Branch 1 (Pre 790625) 79/05/15 4pp
- 7904210324 Requests two controlled copies of site emergency plan / implementing procedures site maps showing location & grid station numbers of onsite & affisite environ monitoring stations / maps used for affisite dose determinations KEPPLER. J Q Region 3, Chicago, Office of the Director 79/03/\$7
- 7906190315 Bubmits response to 790607 questionnaire re monitoring noble gaseous affluents
  BURSTEIN:8 Wisconsin Electric Power Co 79/06/12 3pp
- 7905220181 Submits info re feedwater lines to steam generator in response to 790525 request Feedwater pipe to feedwater noith welds to be examined for tracking during first week of Jul 1979
  FAY.C W Misconsin Electric Power Co 79/06/20 8pp
- 7906290257 Submits responses to 790619 telcon inquiries re reactor vessel support structures One oversized drawing encl BURSTEIN,8 Wisconsin Clectric Power Co 79/06/25 Spp.
- Q Inspection reports, IE Bulletins & correspondence
- 7906020133 Responds to IE Bulletin 79-07 Four cases associated w/gaseous & liquid radwaste sys at plant have been reanalyzed All pipe strosses & support & constraint loads are within acceptable limits
  BURSTEIN.S Misconsin Electric Power Co 79/05/02 1p
- 7904040027 Responds to IE Bulletin 79-04 re weights of swing check valves Forwards list of piping sys where valves are installed. Results of review to be provided when available BURSTEIN, S. Wisconsin Electric Power Co. 79/05/02, 3pp
- 7906120132 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/07
- 7906050120 Ack receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/79-02 & 50-301/79-01.

  HIND, J A Region 3, Chicago, Bafeguards Branch 79/05/08 ip

- --7906050122 Responds to NRC 790302 ltr re violations noted in IE Insp. Repts 50-266/79-02 & 50-301/79-01 Corrective actions withheld (ref 190FRZ 790) BURRITEIN. B Hisconsin Electric Power Co 79/03/23 4pp
- 7906110110 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190106 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11
- 7906080207 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7906130120 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " License
- action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 10
- 7706200142 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor" KTPPLER, J G Region 3, Chicago, Office of the Director 77/05/29
- R Periodic operating reports & related correspondence
- /906190319 Forwards monthly operating rept for May 1979 DURSTEIN, B Wisconsin Electric Power Co 79/06/08
- --7706190321 Monthly operating rept for May 1979 \* Wisconsin Electric Power Co 79/06/05
- 8 Reportable occurrences. LERs & related correspondence
- 7906060297 Forwards LER 79-008/01T-0
  BURSTEIN, 8 Wisconsin Electric Power Co 79/05/21 tp
- --7904060260 LER 79-008/01T-0 on 790502 remote possibility exists for simultaneous safety injection in both units, which could result in emergency diesel overloading Pressurizer logic & power supplies changed BURETELIN S Wisconsin Electric Power Co 79/05/21 App
- 7906060250 Forwards LER 79-009/01T-0 BURSTEIN, B. Wisconsin Electric Power Co 79/05/23 1p
- --770A060251 LER 79-009/01Y-0 on 770510 during hydrostatic test of fire water sys.compression fitting failed Caused by broken flange Flange replaced BURBIEIN/G Wisconsin Electric Power Co 79/05/23 2pp
- DOCKET 50-267 FORT ST VRAIN NUCLEAR GENERATING STATION F Security, medical, emergency & fire protection plans
- 7906:180534 Updates installation status of security sys hardware Util will be extending compensatory measures Sys will need to be returned for complete rebuilding WORKEHBOURG. D W Public Service Co of Colorado 79/06/07 ip
- 7906190395 Informs of completed installation of third phase of permanent improved fire detection & protection sys & permanent alternate cooling method

  SMART.F E. Public Service Co of Colorado 79/06/14 1p
- 7906270139 Discusses evaluation of STS on fire protection Tech Spec revision will be based on util format rather than referencing existing procedures Formal Tech Specs will be submitted by middle of Aug 1979 WAREHBOURG, D Public Service Co of Colorado 79/06/21 1p
- H General correspondence
- 7906250041 Confirms 790521 telcon re proposed ofc space for IE inspector at facility.Forwards sketch of desired electrical outlet telephone outlet & wall locations MADERNO.L. Region 4, Dallass Reactor Operations Nuclear Support Branch. 79/05/22 2pp

- J Insurance & indemnity information
- 7906190415 Forwards Endorsement 29 & 30 to MAELU Policy MF-59 CORREA,M A Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/14 3pp
- 7906220340 Forwards Endorsements 48 & 49 to ANI Policy NF-192 & Endorsements 42 & 43 to MAELU Policy MF-69 HOCK.D D Public Service Co of Colorado 79/06/14 5pp
- P Operating license stage documents & correspondence
- 7906050417 Responds to D Warenbourg notification that facility does not intend to install region restraint devices into core during refueling outage Necessary that core support block also be inspected
  SPEIS.T P Advanced Reactors Branch 79/04/06 2pp
- 7906110040 Notifies that two Class II amends contained in 790402 application will be considered as single Class II amend Controller has authorized refund of \$1,200 HILLER.W O License Fee Hanagement Branch 79/05/11 1p
- 7906270270 Submits evaluation of 771220 GLP-5588, "Safety Analysis -Use of H-451 Graphite in Ft St Vrain Fuel Elements "
  Responses to NRC questions provide reasonable assurance that
  fuel substitution is viable
  GAMMILL. WP Assistant Director for Standard & Advanced Reactors
  79/05/21 2pp
- 7906220433 Submits questions & comments pertaining to review of SAR, "Use of UC-2 Fissile Fuel Particles on Fuel Element," GA-LTR-23 GAMMILL, W P Assistant Director for Standard & Advanced Reactors 79/05/29 600
- 7706060206 Forwards Cycle 2 base reactivity curve WAREMBOURG, D Public Service Co of Colorado 79/05/30 2pp
- 7906120196 Responds to NRC 790406 Itr requesting add1 info to verify that only modest number of fluctuations would be initiated FULLER, J K Public Service Co of Colorado 79/06/01 12pp
- 7906070187 "Incore Insp Region 35 % Region 13 Care Support Block " MEYER.R J Office of Inspection & Enforcement 79/06/05 100pp
- 7906120342 Forwards "Initial Approach to Power Tests (B-Series)." Interim Rept 11.790222-0522 WAREMBOURG.D Public Service Co of Colorado 79/06/06 1p
- ---7906120346 "Initial Approach to Power Tasts (B-Beries)." Interim Rept 11,790222-0522 \* Public Service Co of Colorado 79/05/22 2pp
- 7906190501 Requests extension to 790614 for temporary relief from Tech Spec LCO 3 10 due to delays in NRC operator examinations & receipt of snubber parts WAREMBOURG, D W Public Service Co of Colorado 79/06/11 ip
- 7906220295 Forwards RT-486 test procedure re fluctuation monitoring instrumentation, including instrumented control rod drives WAREMBOURG, D. W. Public Service Co. of Colorado 79/06/11 18pp
- 7906190336 Submits revised schedule for completing evaluation of Category II & III items re Tech Spec setpoints due to unforseen delays
  SWART,FE Public Service Co of Colorado 79/06/12 2pp
- 7906210141 Forwards response to 790929 Questions GA-LTR-23 to facilitate review of UC-2 fissile fuel FISHER, C.R. General Atomic Co. (subs. of Gulf Oil Corp.) 79/06/13
- 790622030B Clarifies main steam temp limits originally specified in 1tr ref P-7909A Results of fluctuation tests at each power level will be forwarded upon completion WAREMBOURG, D W Public Service Go of Colorado 79/06/15 Spp.
- 7906260443 Forwards table of noble gas monitors
  WAREMBOURG, D. W. Public Service Co. of Colorado. 79/06/15 2pp
- 7906270267 Submits specific disposition of three open items in manual valve study re closed valves, instrument root valves & stored gas sys Review complete Rise-to-power program is proceeding
  SWART,F, E Public Service Co of Colorado 79/06/15 3pp

- 7906290419 Forwards application for amend to App A of Tech Specs 4 4 1 re voltage sensing delays
  MILLEN.C K Public Service Co of Colorado 79/06/19 lp
- --7906290426 Application for amend to App A of License DPR-34 changing Tech Specs re voltage sensing delay MILLEN.C K Public Service Co of Colorado 79/06/19 4pp
- @ Inspection reports. IE Bulletins & correspondence
- 7906180132 Forwards IE Insp Rept 50-267/79-06 on 790318-23 No noncompliance noted MADSEN,G L. Region 4. Ballas, Reactor Operations Nuclear Support Branch 79/04/05 2pp
- --7906180137 IE insp Rept 50-267/79-06 on 790318-23 No noncompliance noted Major areas inspected refueling & maint procedures DICKERGON.M W. TESTERMAN.T F Region 4, Dallas. Office of the Director 79/04/05 App
- 7906120075 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT, K V Region 4. Dallas, Office of the Director 79/05/07 10
- 7906110088 Forwards LE Bulletin 79-10, "Requalification Training Program Statistics " Written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/11
- 790A250025 Forwards IR info Notice 79-12, "Attempted Damage to New Fuel Assemblies " REYFRIT, K V Region 4, Dallas, Office of the Director 79/05/11
- 7906200043 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Oyster Creek Reactor" SEYFRIT.R V Region 4. Dailas, Office of the Director 79/05/29
- 7906070182 Forwards "Incore Insp Region 35 & Region 13 Core Support Black" SWART.F & Public Bervice Co of Colorado 79/06/05 1p
- 7906130344 Forwards addl info to JK Fuller 790313 ltr Discusses DOE-funded program re tube corrosion monitoring data FULLER, J K Public Bervice Co of Colorado 79/06/05 6pp
- R Periodic operating reports & related correspondence
- 7906010217 Forwards Interim Rept 10, "Initial Approach to Power Tests (B-Series), " 781122-790222

  WAREMBOURG, D Public Service Co of Colorado 79/05/21 ip
- --7906010223 Interim Rept 10. "Initial Approach to Power Tasts (B-Series)." 781122-790222

  \* Public Service Co of Colorado 79/05/21 2pp
- 7704120155 Forwards monthly operating rapt for May 1979.
  WAREMBOURG, D. Public Service Co. of Colorado. 79/06/03 ip
- ~~7906120161 Monthly operating tept for May 1979
  GAHM. J W. Public Service Co of Colorado 79/06/01 6pp
- 7906190299 Forwards monthly operating rept for Apr 1979
  WAREMBOURG. D Public Service Co. of Colorado 79/06/53 Ip
- ~-7906190302 Monthly operating rept for Apr 1979
  GAHM.J W Public Service Co of Colorado. 79/04/30 988
- 8 Reportable occurrences, LERs & relateo correspondence
- 7906180148 rorwards PNO-79-67AM.
  MADSEN.O.L. Region 4, Dallas, Reactor Operations Nuclear Support
  Branch 79/05/09, 1p.
- 7906180202 Forwards PNO-79-67AN
  MADSEN.O.L Region 4. Dallas, Reactor Operations Nuclear Support
  Branch. 79/03/16 10
- 7906180301 Forwards PND-79-67AO & AP.
  MADSEN.O L. Region 4, Delias, Reactor Operations Muclear Support
  Branch. 79/05/24 ip

- 7906120405 Forwards LER 79~016/01T-0
  WAREHBOURG, D Public Service Co of Colorado 79/06/01 1p
- --7906120409 LER 79-016/01T-0 on 790521 punch gap of PCRV rupture disc R-11702 found out of tolerance w/vendor specs Caused by Undocumented change of punch gap specs Tolerances returned to original specs QANH, J N Public Service Cd of Colorado 79/06/01 5pp
- 7906120410 Forwards LER 79-015/03L-Q HAREHBOURG,D Public Service Co of Colorado 79/06/06 1p
- --7906120414 LER 79-015/03L-0 on 790507 during routing survaillance testing setpoint of PCRV rupture disc M-11702 found to be B26 paig Caused by calibr drift Disc recalbr OAIM, J W Public Service Co of Colorado 79/06/06 4pp
- 7906130001 Interim Rept 11. "Initial Approach to Power Test (D-Serses), " 79022-0522 Public Service Co of Colorado 79/06/06 2pp
- /906260433 Forwards LER 79-004/03L-1 WAREMBOURG(D) Public Service Go of Colorado 79/06/19 Ip
- ~~7906260437 LER 79~004/03L~1 on 790201 during normal operation, conling tower bloodown exceeded 3 79 million gallons/day Caused by fallure to properly rept events due to incorrect completion of surveillance forms forms changed & personnel instructed OAHM.J W Public Bervice Co of Colorado 79/06/19 app
- DOCKET 50-249 OCONEE NUCLEAR STATION, UNIT 1
- O Adjudicatory correspondence
- 7905040224 Orders licenses to take immediate action to modify feedustar sys 5 operating procedures to that down certain units until completion of mods & to undertake long-term mods as specified
  CHILK, S. J. Office of the Secretary of the Commission 79/05/07
- 790622016A Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation Also forwards "Effect of Closing Oconee Nuclear Plants on Ability to Meet Bummer Peak Demands"
  HFISR.E R Union of Concerned Scientists 79/05/10 in
- --7905220168 UCS petition for immediate reconsideration of errors of 790508 order & for immediate shutdown of Units 1 & 2
  HEISS.E R Union of Concerned Scientists 79/05/10 App
- --7706220170 "Effect of Closing Ocones Nuclear Plants on Ability to Meet Summer Peak Demands " TAYLOR.V Union of Concerned Scientists 79/05/09 10pp
- 7906210254 Forwards Attachment A to V Taylor statement which was appended to VCS patition for immediate reconsideration of errors of 790508 order for immediate shutdown of facility HEISS-E R. Sheldon, Harmon & Roteman 79/05/15 ip
- --7906210286 Details analysis of DOR info on reserve margins for summer 1777 estimated to be affected by shutdown of BSW plants KENNEKE.A Office of Policy Evaluations 79/04/24, ip
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 BANDERS, F D. Duke Power Co. 79/06/08, 5pp.
- O Advisory Committee on Reactor Safeguerds reports & correspondence
- 7906180383 Forwards ECCS enalysis of smell breaks in conjunction w/
  smergency feedwater flow feitures Operator has 20 minutes to
  re-establish feedwater flow prior to come uncovery
  BATES.A ACRS Advisory Committee on Reactor Safeguerds 79/03/03
- P Operating license stage documents & correspondence
- 7906270065 Forwards 790514 inspector findings re changes to plant procedures resulting from NRC 790507 ander Procedures of order t operator understanding deemed adequate, MGSELEY, N.C. Office of Inspection & Enforcement. 79/05/17 1p

- --790627006B Confirms procedural changes resulting from NRC 790507 order \$ operator understanding of changes JAPE, F Region 2. Atlanta, Office of the Director 79/05/14
- 7906070238 Submits proposed Tech Specs revisions re surveillance stds to suppl 761001 & 770708 submittals PARKER: W O Dute Power Co 79/05/30 13pp
- 7706050327 Responds to 770518 request Forwards emergency feedwater flow test procedure
  PARKER, W D Duke Power Co 77/06/01 1p
- --7906050329 Emergency feedwater flow test procedure \* Duke Power Co 79/05/31 12pp
- 7906150267 Advises that hydrostatic test required by 1974 ASME Boiler & Prossure Vessel Code is impractical Util will follow 1977 edition requirement Requests notification if unacceptable PARKER, W D Duke Power Co 79706/11 2pg
- 7906190261 Responds to NRC 790518 ltr requesting schedule by 790618 completion of long-term mods described in Section 2 of NRC 790507 order All efforts satisfactorily executed PARKER, W O Duke Power Co 79/06/14 ip
- 7906220283 Forwards responses to NRC 790525 ltr re feedwater lines Diagrams enci PARKER: W O Duke Power Co 79/06/18 66pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906290288 B&W site inspector daily rept on 790407 Plant status reactor operating at 90% power for repairs to condenser tubes Testing continues to determine leak source COTTLE. H . ABHCNDEN. J Region 2. Atlanta, Office of the Director 79/04/07 3pp
- 7906290174 B&W site inspector daily rept on 790408 Plant status units 1 & 3 operating at 100% Unit 2 at 70% Hunting condenser tube leak on Unit 2 reported, COTTLE W Region 2, Atlanta, Office of the Director 79/04/08 2np
- 7906270048 B&W site inspector daily rept on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 2 COTTLE.H ASHENDEN.M C Region 2. Atlanta. Office of the Director 79/04/09 2pp
- /906290519 B&W site inspector daily rept on 790410 Plant status all reactors at full power w/all engineering safety feature sys in svc.
  JAPE,F , ASHENDEN,M C , FORD,E P Region 2, Atlanta, Office of the Director 79/04/10 2pp
- 7906270087 B&W site inspector daily rept on 790411 Plant status reactor at full power w/no known problems Training instructors scheduled for B&W simulator training on 790418

  JAPE, F. Region 2, Atlanta, Office of the Director 79/04/11
- 7906290562 B&W site inspector daily rept on 790412 Plant status all units running at full power Bys alignment verified for accessible components on weegency feedwater sys COTTLE, FORD Region 2, Atlanta, Office of the Director 79/04/12 200
- 7906290135 D&W site inspector daily rept on 790413 Plant status, all reactors at full power w/no engineering safety feature equipment out of svc & no major maint COTILE, BELIBLE, G A , MODN, R T Region 2, Atlanta, Office of the Director 79/04/13 2pp
- 7906290429 BtW site inspector daily rept on 790414 Plant status Unit 2 operating at 82% power. Units 1 & 3 at full power No major maint scheduled & all major equipment is operational BELIFIEC. A. MOON, B. Region 2. Atlanta, Office of the Director 79/04/14 2pp
- 7906290480 B&W site inspector daily rept on 790415 Plant status all units at 100% power w/no engineered safety feature equipment out of syc & no major maint scheduled BELIELE, G A , MOON, H T Region 2, Atlanta, Office of the Director 79/04/15 ip

- 7906290598 B&H site inspector daily rept on 790417 Plant status all units at 100% power No major engineering safety feature sys equipment out of svc JAPE.F Region 2. Atlanta, Office of the Director 79/04/17 ip
- 7906110062 Responds to 1E Bulletin 79-05B Reactor protective sus high RCS pressure setpoint has been lowered to not greater than 2.300 psig pressurizer power operated relief value setpoint raised to 2.430 psig PARKER.W O Duke Power Ca 79/04/21 1p
- 7906290456 BBW site inspector daily rept on 790420 Plant status Units 1 % 3 at 100% power Unit 2 reduced to 92% due to water leak in turbine condenser bor JAPE.F Region 2, Atlanta. Office of the Director 79/04/20 ip
- 7906120291 Notifies that response to IE Bulletin 79-04 re Velan check valves will be submitted no later than 790530 PARKER.W O Duke Power Co 79/05/02 ip
- 7906040421 Supplements response to Item 3 of IE Bulletins 79-05 & 79-05A re licensed shift operators completing B&W simulator training PARKER.W O Dute Power Co 79/05/04 ip
- 790&200265 Ack receipt of IE Insp Repts 50-269/79-11,50-270/79-11 \$ 50-287/79-11 on 790301-29 No proprietary info PARKER, W 0 Dute Power Co 79/05/09 ip
- --7906200270 Forwards IE Insp Repts 50-269/79-11.50-270/79-11 & 50-287/79-11 on 790301-29 No noncompliance noted LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Gupport Branch 79/05/01 2pp
- --7906200279 IE Insp Repts 50-269/79-11.50-270/79-11 & 50-297/79-11 on 790301-29 No noncompliance noted Major areas inspected plant operations, fallowup of info notices, physical security & LER JAPE, F Region 2, Atlanta, Office of the Director CANTRELL,FS Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/28 Spp
- --7906200277 IE Insp Repts 50-269/79-11.50-270/79-11 b 50-287/79-11 on 790301-29 No noncompliance noted Major areas inspected plant operations, followup of info notices, physical security & licensee event rept JAPE, F Region 2, Atlanta, Office of the Director 79/04/28 6pp
- 7906250443 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" O'REILLY,J P Region 2. Atlanta. Office of the Director 79/05/10 1p
- 7906110060 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required D'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/11 1p
- 7906260242 Ack receipt of 790322 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 30-269/79-01, 50-270/79-01 t 50-287/79-01 O'REFLIXIJP Region 2. Atlanta. Office of the Director. 79/05/11 ip
- --7906260244 Supplements util 790322 itr responding to item of noncompliance noted in IE Insp Repts 50-269/79-01. 50-270/79-01 & 50-289/79-01 Util will submit RDs within 30 days of discovery of event PARKER. # 0 Duke Power Co 79/05/05 ip
- ---7904240230 Responds to NRC 790227 ltr re-violations noted in IE Insp. Repts 50-267/79-01, 30-270/79-01 & 50-267/79-01 Disputes item of noncompliance relate submittal of RD Due date fell on holiday PARKER, W O Duke Power Co 79/03/22 2pp
- --7906260259 Forwards IE Insp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 on 790131-0201 & notice of violation LEWIS.R C Region 2. Atlanta. Office of the Director 79/02/27 200
- --7906260264 Notice of violation from insp on 790131-0201 # Region 2. Atlanta. Office of the Director 79/02/26 ip
- --7906260271 IE insp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 on 790131-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event COTTLE, H T. GANTRELL, F S. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/02/26 App

- 7906290829 Forwards response to IE Bulletin 79-09 re QE Type AK-2/2A circuit breakers in safety-related sys Tuo are used as control rod drive ac primary trip breakers & four are used in dc holding power supplies PARKER, W O Dute Power Co 79/05/16 2pp
- 7906270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Bulletin 79-050
  HILLIAMS.F J Division of Project Management 79/05/18 3pp
- 7906120225 Informs of B&W 790322 notification that operator for valve 2HP-20 inside Unit 2 cotainment bldg did not meet environ qualification requirements Unit 1 continued to operate Unit 2 valve replaced PARKER, W Q Duke Power Co 79/06/05 2pp
- R Periodic operating reports & related correspondence
- 7906210149 Forwards monthly operating rept for May 1979 PARKER.W O Duke Power Co 79/06/15 1p
- --7905210153 Monthly operating rept for May 1979 REAVIS, J A Duke Power Co 79/06/15 17pp
- 790628014B Forwards correction sheets to monthly operating cept for May 1979
  PARKER.W () Duke Power Co 79/06/25 ip
- ~-7906280151 Correction sheats to monthly operating rept for May 1979
   Duke Power Co 79/05/31 App
- 5 Reportable occurrences. LERs & related correspondence
- 7906140333 RO 269/79-13 on 790307 quadrant power tilt was beyond error-adjusted steady state limit Caused by power increases after emergency feedwater pump flow stability test Power reduced to evaluate tilt VITO,D J Duke Power Co 79/05/07 19
- 7906140360 RD 269/79-16 on 790524 2.335 gallons unsampled water released from laundry & hot shaver tank Caused by incorrect valve lineup Released water sampled & proper pumping resumed VITO.D J Duke Power Co 79/05/24 ip
- 7906130320 Forwards LER 79-015/01T-0 PARKER.W 0 Duke Power Co 79/06/07 1p
- ---7906130324 LER 79-015/01T-0 on 790524 laundry % hot shower A tank discharged w/o being sampled Caused by personnel error Responsible parties counseled LEHIS-S R Duke Power Co 79/06/07 3pp
- 7906290314 Forwards LER 79-015/01T-1 PARKER W O Duke Power Co 79/06/25 to
- --7906290323 LER 79-018/01T-1 on 790824 laundry & hot shower tank A discharged prior to sampling Caused by personnel error Personnel counseled tanks & related equipment marked & procedures revised LEWIS: S R Ocorgia Power Co 79/06/25 3pp
- T Hearing transcripts on non-antitrust matters
- 7705110205 Transcripts of 770518 meeting in Washington, DC re-briefing on Oconee order Pp 1-88 Meeting exhibits encl HENDRICK, J. H. . GILINSKY, V. . KENNEDY, R. T. . Commission 77/05/18 10/App.
- 7706200360 Transcript of 790518 public meeting in Washington, DC re brisfing by NRC on Oconea order Pp 1-88 \* Office of the Executive Legal Director 79/05/18 89pp
- U Congressional/Executive Correspondence
- 7906260541 Responds to 790423 ltr re B Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FES H/o encl GDSSIGN.L V. Office of the Executive Director for Operations 79/05/15 2pp
- --7906260344 Requests info re radiological impact of nuclear power plant cooling on drinking water in ref to SL Austin inquiry LENT, N.F. House of Rep. 79/04/23, 29p

- DOCKET 50-270 OCCHEE NUCLEAR STATION, UNIT 2
- @ Adjudicatory correspondence
- 7906040224 Orders lirensee to take immediate action to modify feedwater sys & operating procedures, to shut down certain units until completion of mods & to undertake long-term mods as specified
  CHILK, S. J. Office of the Secretary of the Commission 79/05/07
- 7906220164 Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation Also forwards "Effect of Closing Oconee Nuclear Plants on Ability to Meet Summer Peak Demands"

  WEISS,E R Union of Concerned Scientists 79/05/10 1p
- ---770.6220168 UCS patition for immediate reconsideration of errors of 770508 order & for immediate shutdown of Units 1 & 2 HEISS,E R Union of Concerned Scientists 77/03/10 4pp
- --7906220170 "Effect of Closing Oconee Nuclear Plants on Ability to Meet Summer Peak Demands " TAYLOR,V Union of Concerned Scientists 79/05/09 10pp
- 7906210254 Forwards Attachment A to V Taylor statement which was appended to UCS petition for immediate reconsideration of errors of 790508 order for immediate shubdown of facility MEISS.E R Sheldon. Harmon & Roisman 79/05/19 ip
- --7906210256 Details analysis of DDE info on reserve margins for summer 1979 estimated to be affected by shutdown of BBM plants KENNEKE, A Office of Policy Evaluations 79/04/24 1p
- J insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS, F D Duke Power Co 79/06/08 5pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7905180583 Forwards ECCS analysis of small breaks in conjunction of emergency fredwater flow failures Operator has 20 minutes to re-establish feedwater flow prior to core uncovery BATES: A ACRS Advisory Committee on Reactor Safeguards 79/05/03
- P Operating license stage documents & correspondence
- 7906270065 Forwards 790514 inspector findings re changes to plant procedures resulting from NRC 790507 order Procedures of order & operator understanding desmed adequate MOSELEY, N C Office of Inspection & Enforcement 79/05/17 ip
- --7906270068 Confirms procedural changes resulting from NRC 790507 order & operator understanding of changes JAPE, F Region 2. Atlanta, Office of the Director 79/05/19
- 7906070238 Submits proposed Tech Spacs revisions re surveillance stds to suppl 761001 & 770708 submittals PARKER, W O Dute Power Co 79705/30 13pp
- 7906050327 Responds to 790518 request Forwards emergency feedwater flow test procedure PARKER, W O Duke Power Co 79/06/01 1p
- ---7906050329 Emergancy feedwater flow test procedure \* Duke Power Co 77/05/31 12pp
- 7906150267 Advises that hydrostatic test required by 1974 ABME Boiler & Pressure Vessel Code is impractical Util will follow 1977 edition requirement Requests notification if unacceptable PARKER-W 0 Duke Power Co 79/06/11 2pp
- 7906190261 Responds to NRC 790318 ltr requesting schedule by 790618 completion of long-term mods described in Bection 2 of NRC 790307 order All efforts satisfactorily executed PARKER, W Q Duke Power Ca 79/06/14 lp.
- 7906220283 Forwards responses to NRC 790525 itr re feedwater lines Blagrams and I PARKER N O Duke Power Co 79/06/18 66pp

- Q Inspection reports, IE Bulletins & correspondence
- 7906290288 D&W site inspector daily rapt on 790407 Plant status reactor operating at 90% power for repairs to condenser tubes Tasting continues to determine leak source COTTLE:W. ASHENDEN.J. Region 2. Atlanta, Office of the Director 79/04/07 3pp
- 7906270174 BAW site inspector daily rept on 790408 Plant status units 1 % 3 operating at 100%; Unit 2 at 70% Hunting condenser tube leak on Unit 2 reported COTTLE: W Region 2. Atlanta. Office of the Director 79/04/08
- 7906290048 USH sits inspector daily rept on 790407 Plant status all reactors at full power Condenser leak has been corrected on Unit 2 COITLE.W , ASHENDEN.M C Region 2, Atlanta, Office of the Director 79/04/09 2pp
- 7906290519 BBW site inspector daily rept on 790410 Plant status all reactors at full power w/all engineering safety feature mys in myc JAPE,F, ASHENDEN,M C, FORD,C P Region 2, Atlanta, Office of the Director 79/04/10 2pp
- 7906270087 B&W site inspector daily rept on 790411 Plant status reactor at full power w/no known problems Training instructors scheduled for B&W simulator training on 790418

  JAPE.F Region 2. Atlanta, Office of the Director 79/04/11

  2pp
- 7906270362 B&W eite inspector daily rept on 790412 Plant status all units running at full power Sys alignment votified for accessible components on emergency feedwater sys COYLC, FORD Region 2, Atlanta, Office of the Director 79/04/12 20p
- 7906290195 B&W site inspector daily rept on 790419 Plant status all reactors at full power w/no engineering safety feature equipment out of sec & no major maint COTTLE, BCLISLC, 0. A. MOUN, R T Region 2, Atlanta, Office of the Director 79/04/13 2pp.
- 7906290429 BAW site inspector daily rept on 790414 Plant status Unit 2 operating at 82% power. Units 1 & 3 at full power No major maint scheduled & all major equipment is operational BELISLE.A. MOON. B. Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7906270480 D&W site inspector daily rept on 790415 Plant status all units at 100% power w/no engineered safety feature equipment out of svc & no major maint scheduled DELISECT A. MOON, B T Region 2. Atlanta, Office of the Director 79/04/15 1p
- 7706270578 D5W sits inspector delly rept on 770417 Plant status all units at 100% power No major engineering safety feature sys equipment out of syc JAPE.F. Region 2. Atlanta, Office of the Director 77/04/17 1p
- 7906110062 Responds to IC Bulletin 79-050 Reactor protective sys high RCS pressure setpoint has been lowered to not greater than 2,300 psig/pressurizer power operated relief value setpoint raised to 2,450 psig PARKER, H O. Duke Power Co 79/04/21 ip
- 7906290486 BAW eite inspector daily rept on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 92% due to water leak in turbine condenser box DAPE/F Region 2. Atlanta, Office of the Director 79/04/20 ip
- 790612027; Natifies that response to 1E Bulletin 79-04 re Velan check valves will be submitted no later than 790530. PARKER: H O Duke Power Co 79/05/02 ip
- 7906040421 Supplements response to [tem G of IE Bulletins 79-05 & 79-05A re licensed shift operators completing B&W simulator training PARKER, W. O. Duke Power Co. 79/05/04 1p
- 7906200265 Ack receipt of IE Insp Repts 50-269/79-11,50-270/79-11 & 50-287/79-11 on 790301-29. No proprietary info PARKER, W O Duke Power Ga 79/05/09 ip
- --7906200270 Forwards IE Insp Repts 50-269/79-11.50-270/79-11 & 50-287/79-11 on 790301-29 No nuncompliance noted LEMIS.R.C. Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/05/01 2pp

- --7906200279 IE Insp Repts 50-269/79-11, 50-270/79-11 & 50-287/79-11 on 790301-29 No noncompliance noted Major areas inspected plant operations, followup of info notices, physical security & LER JAPE, F Region 2, Atlanta, Office of the Director CANTRELL, F 8 Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/28 6pp
- 7906250443 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 ip
- 7906110060 Forwards IE Bulletin 77~10, "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/11 Ip
- 7906260242 Ack receipt of 790322 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-267/79-01, 50-270/79-01 & 50-287/79-01 O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/11 1p
- --7906260244 Supplements util 770322 ltr responding to item of noncompliance noted in IE Insp Repts 50-269/79-01, 50-287/79-01 Util will submit ROs within 30 days of discovery of event PARKER.W O Duke Power Co 79/05/05 ip
- ---7706260250 Responds to NRC 790227 Itr re violations noted in IC Insp Repts 50-269/79-01,50-270/79-01 & 50-207/79-01 Disputes item of noncompliance re late submittal of RD Due date fell on heliday PARKER, W O Duke Power Co 79/03/22 2pp
- --7906260257 Forwards IE Insp Repts 50-267//7-01, 50-270/77-01 & 50-287/77-01 on 790131-0201 & notice of violation LEMIB.R C Region 2, Atlanta, Office of the Director 79/02/27
- --7906260264 Notice of violation from insp on 790131-0201
  \* Region 2, Atlanta, Office of the Director 79/02/26 1p
- --7904260271 IE Insp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 on 790131-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event COTTLEAN T. CANTRELL.F S. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/02/26 App
- 7706290829 Forwards response to IE Bulletin 79-09 re GE Type AK-2/2A circuit breakers in safety-related sys Two are used as control rod drive ac primary trip breakers & four are used in dc holding gower supplies PARKER, W O Duke Power Co 79/05/16 2pp
- 7706270120 Requests info re manual trip on low pressur stated in Item 4F of IE Builetin 79-05D. WILLIAMB F J Division of Project Man

- 7906290829 Forwards response to LE Bulletin 79-09 re GE Type AK-2/2A circuit breakers in safety-related sys Tuo are used as control rod drive ac primary trip breakers & four are used in dc holding power supplies PARKER, W O Duke Power Co 79/05/16 2pp
- 7905270120 Requests info re manual trip on low pressurizer level, as stated in Item 4F of IE Bulletin 79-05B WILLIAMS, F J Division of Project Management 79/05/18 3pp
- 7906120225 Informs of B&H 790322 notification that operator for valve 2HP-20 inside Unit 2 cotainment bldg did not meet environ qualification requirements Unit 1 continued to operate: Unit 2 valve replaced PARKER, H O Duke Power Ca 79/06/05 2pp
- R Periodic operating reports & related correspondence
- 7906210149 Forwards monthly operating rept for May 1979 PARKER, W O Duke Power Co 79/06/15 1p
- --7906210153 Monthly operating rept for May 1979 REAVIS.J A Duke Power Co 79/06/15 17pp
- 7906280148 Forwards correction sheets to monthly operating rept for May 1979
  PARKER, H O Duke Power Co 79/06/25 Lp
- --7906280151 Correction sheets to monthly operating rept for May 1979
  \* Duke Power Co 79/05/31 4pp
- S Reportable occurrences, LERs & related correspondence
- 7906140353 RO 269/79-13 on 790307 quadrant power tilt was beyond error-adjusted steady state limit Caused by power increases after emergency feadwater pump flow stability test Power reduced to evaluate tilt VITO.D J Duke Power Co 79/05/07 1p
- 7906140360 RO 269/79-16 on 790324 2,335 gallons unsampled water released from laundry & hot shaver tank Caused by incorrect valve lineup Released water sampled & proper pumping resumed VITO, D J Duke Power Co 79/05/24 ip
- 7906130320 Forwards LER 79-015/017-0 PARKER, W D Duke Power Co 79/06/07 ip
- ---7906130324 LER 79-015/01T-0 on 790524 laundry & hot shower A tank discharged w/o being sampled Caused by personnel error Responsible parties counseled LEWIS, S.R. Duke Power Co. 79/06/07 3pp
- 7906290314 Forwards LER 79-015/01T-1 FARKER.W D Duke Power Co 79/06/28 1p
- --7906290323 LER 79-015/017-1 on 790524 laundry & hot shower tank A discharged prior to sampling Gaused by personnel error Personnel counseled tanks & related equipment marked & procedures revised . Georgia Power Co 79/06/25 App

t matters

- DOCKET 50-270 DOCHEE NUCLEAR STATION, UNIT 2
- G Adjudicatory correspondence
- 7906040224 Orders licensee to take immediate action to modify feedwater sys & operating procedures, to shut down certain units until completion of mods & to undertake long-term mods as specified CHILK/S J Office of the Secretary of the Commission 79/05/07
- 790&220164 Forwards petition for reconsideration of 790507 order permitting Units 1 & 2 to remain in operation Also forwards "Effect of Closing Oconee Nuclear Plants on Ability to Meet Summer Peak Demands"
  WEISSER Union of Concerned Scientists 79/05/10 1p
- --790622016B UCS petition for immediate reconsideration of errors of 790508 order & for immediate shutdown of Units 1 & 2 WEIGS, E R Union of Concerned Scientists 79/03/10 App
- --/906220170 "Effect of Closing Oconoe Nuclear Plants on Ability to Meet Summer Peak Demands " TAYLURLY Union of Conterned Strentists 79/05/09 10pp
- 7906210254 Forwards Attachment A to V Taylor statement which was appended to UCS petition for immediate reconsideration of errors of 790508 order for immediate shutdown of facility WEISS,E R Sheldon, Harmon & Roisman 79/05/15 ip
- --7906210256 Details analysis of DOE info on reserve margins for summer 1979 estimated to be affected by shutdown of B&W plants KENNEKE, A Office of Policy Evaluations 79/04/24 ip
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS.F D. Duke Power Co. 79/06/08 5pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906180583 Forwards ECCS analysis of small breats in conjunction w/ amergency feedwater flow failures Operator has 20 minutes to re-establish feedwater flow prior to core uncovery BATES.A AGRS - Advisory Committee on Reactor Safeguards 79/05/03
- P Operating license stage documents & correspondence
- 7906270065 Forwards 790514 inspector findings re changes to plant procedures resulting from NRC 790507 order Procedures of order 5 operator understanding deemed adequate MOSELEY.N C Office of inspection & Enforcement 79/05/17 lp
- --7906270068 Confirms procedural changes resulting from NRC 790507 order to operator understanding of changes
  JAPE, F. Region 2. Atlanta, Office of the Director 79/05/14
  ip
- 7906070238 Bubmits proposed Tech Specs revisions re surveillance stds to suppl 761001 & 770708 submittals

## O Inspection reports. IE Bulletins & correspondence

- 7906290288 BAW site inspector daily rept on 790407 Plant status reactor operating at 90% power for repairs to condensor tubes Testing continues to determine leak source COTILE, W. ASHENDEN, J. Region 2, Atlanta, Office of the Director 79/04/07 3pp
- 7906290174 B&W site inspector daily rept on 790408 Plant status units 1 & 3 operating at 100% Unit 2 at 90% Hunting condenser tube leak on Unit 2 reported COTTLE: W Region 2, Atlanta, Office of the Director 79/04/08
- 7906290048 BbW site inspector daily rept on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 2 COTTLE,W , ASHENDEN,M C Region 2, Atlanta, Office of the Director 79/04/09 2pp
- 7906290319 BbW site inspector daily rept on 790410 Plant status all reactors at full power w/all engineering safety feature sys in svc JAPE.F., ASHENDEN,M.C., FORD.E.P. Region 2, Atlanta, Office of the Director. 79/04/10 2pp
- 7906270087 BbW site inspector daily rept on 790411 Plant status reactor at full power w/no known problems Training instructors scheduled for BbW simulator training on 790418

  APE. F Region 2. Atlanta. Office of the Director 79/04/11
- 7906270562 BAW site inspector daily rept on 790412 Plant status all units running at full power Bys alignment verified for accessible components on emergency feedwater sys COTYLE, FORD Region 2, Atlanta, Office of the Director 79/04/12 200
- 7906270139 B&W site inspector daily rept on 790413 Plant status all reactors at full power w/no engineering safety feature equipment out of syc & no major maint COTTLE. BELISLE, G A . MOON, R Y Region 2. Atlanta, Office of the Director 79/04/13 2pp
- 7906290429 BEW site inspector daily rept on 790414 Plant status Unit 2 operating at B2X power.Units 1 & 3 at full power No major maint scheduled & all major equipment is operational. BELIBLE, A · MODN.B Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 790A290A00 B5W site inspector daily rept on 790A15 Plant status all units at 100% power w/no engineered safety feature equipment out of svc & no major maint scheduled BELIBLE, Q.A., MOCN, B T. Region 2, Atlanta, Office of the Director 79/04/15 ip
- 7906290598 B&W site inspector daily rept on 790417 Plant status.all units at 100% power No major engineering safety feature sys equipment out of svc JAPE, F Region 2, Atlanta, Office of the Director 79/04/17 ip
- 7906110062 Responds to IE Bulletin 79-058 Reactor protective sys high RCB pressure setpoint has been lowered to not greater than 2,300 psigipressurizer power operated relief value setpoint raised to 2,450 psig.

  PARKER.W O Dute Power Co 79/04/21 ip
- 7906290436 B&W site inspector daily rept on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 92% due to water laak in turbine condenser box JAPEJF, Region 2, Atlanta, Office of the Director 79/04/20 1p
- 7906120291 Notifies that response to IE Bulletin 79-04 re Velan check valves will be submitted no later than 790530. PARKER: N. O. Duke Power Ca. 79/05/02 ip
- 7906040421 Supplements response to Item 3 of IE Bulletins 79-05 & 79-05A re licensed shift operators completing B&W simulator training PARKER, M. D. Duke Power Co. 79/05/04 ip
- 7906200265 Ack receipt of IE Insp Repts 50-269/79-11,50-270/79-11 & 50-287/79-11 on 790301-29 No proprietary info PARKER, W C Duke Power Co. 79/05/09 ip
- --7906200270 Forwards IE Inep Repts 50-269/79-11,50-270/79-11 & 50-287/79-11 on 790301-29 No noncompliance noted LEMIB.R.C Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/05/01 2pp

- --7906200279 IE Insp Repts 50-269/79-i1, 50-270/79-i1 & 50-287/79-i1 on 790301-29 No noncompliance noted Hajor areas inspected.plant operations, followup of info notices, physical security & LER JAPE.F Region 2. Atlanta, Office of the Director CANTRELL.F S Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/28 6pt
- 7906230443 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/10 1p
- 7906110060 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY.J P Region 2. Atlanta. Office of the Director 79/05/11 Ip
- 7906260242 Act receipt of 790322 itr informing NRC of steps taken to correct viplations noted in IE Insp Repts 50-269/79-01. 50-270/79-01 \$ 50-287/79-01 O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 ip
- --7906260244 Supplements util 790322 ltr responding to item of noncompliance noted in IE lasp Repts 50-267/79-01.
  50-270/79-01 & 50-287/79-01 Util will submit ROs within 30 days of discovery of event PARKER.W O Duke Power Co 79/05/05 ip
- --7906260290 Responds to NRC 790227 itr re violations noted in IE Insp Repts 50-269/79-01,50-270/79-01 & 30-287/79-01 Disputes item of noncompliance re late submittal of RD Due date fell on holiday PARKER, W O Duke Power Co 79/03/22 2pp
- --7906260259 Forwards IE Insp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 on 790131-0201 & notice of violation LEWIS:R C Region 2. Atlanta. Office of the Director 79/02/27
- --7906260264 Notice of violation from insp on 790131-0201
  \* Region 2. Atlanta, Office of the Director 79/02/26 1p
- --7904260271 IE Insp Repts 50-269/79-01.50-270/79-01 % 50-287/79-01 on 790131-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event COTTLE, & T. CANTRELL, F S. Repion 2. Atlanta, Reactor Operations Nuclear Support Branch 79/02/26 App
- 7906290829 Forwards response to IE Bulletin 79-09 re GE Type AK-2/2A circuit breakers in safety-related sys Two are used as control rod drive ac primary trip breakers > four are used in dc holiding power supplies
  PARKER, W O Duke Power Co 79/05/16 2pp
- 7906270120 Requests info re manual trip on low pressurizer level, as stated in Item 4F of IE Bulletin 79-058
  WILLIAMB, FJ Division of Project Management 79/05/18 3pp
- 7906120225 Informs of BBW 790322 notification that operator for valve 2HP-20 inside Unit 2 cotainment bldg did not meet environ qualification requirements Unit 1 continued to operate: Unit 2 valve replaced PARKER, W O Duke Power Co 79/06/05 2pp
- R Periodic operating reports & related correspondence
- 7706210149 Forwards monthly operating rept for May 1979 PARKER, W O Duke Power Co 79/06/15 1p
- --7906210153 Monthly operating rept for May 1979 REAVIS. J A Duke Power Co 79/06/15 17pp
- 7906280148 Forwards correction sheets to monthly operating rept for May 1779.
  PARKER M. O. Duke Power Co. 79/06/25 ip
- ---7906280151 Correction wheets to monthly operating rept for May 1979
  # Duke Power Co 79/05/31 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906140360 RQ 269/79-16 on 790524:2:335 gallons unsampled water released from laundry & hot shaver tank. Caused by incorrect valve lineup Released water sampled & proper pumping resumed VITO.D J Duke Power Co 79/05/24 ip

- 7906130320 Forwards LER 79-015/01T-0 PARKER, W D Duke Power Co 79/06/07 1p
- --7906130324 LER 79-015/017-0 on 790524 laundry & hot shower A tank discharged w/o being sampled Caused by personnel error Responsible parties counseled LEW15.5 R Duke Power Co 79/06/07 3pp
- 7906260529 Forwards LER 79-003/03L-0 PARKER.W D Duke Power Co 79/06/21 ip
- ---7906260833 LER 79-003/03L-0 on 790822 reactor protection sys channel D determined to be above specified limit of 4 psig Caused by setpoint drift Switches recalibr for setpoint of 3 5 psig Will be verified at 6-month intervals LEWIS.5 R Duke Power Ca 79/06/21 3pp
- 7906290314 Forwards LER 79-015/01T-1 PARKER: W D Duke Power Co 79/06/25 1p
- --7906290323 LER 79-015/017-1 on 790524 laundry & hot shower tank A discharged prior to sampling Caused by personnel error Personnel counseled, tanks & related equipment marked & procedures revised LEWIS,S R Georgia Power Co 79/06/25 3pp
- T Hearing transcripts on non-antitrust matters
- 7906110205 Transcripts of 790518 meeting in Washington, DC re briefing on Oconee order Pp 1-88 Meeting exhibits encl HENDRICK, J M . GILINSKY, V . KENNEDY, R T Commission 79/05/18 106pp
- 7906200560 Transcript of 790518 public meeting in Washington,DC re briefing by MRC on Ocones order Pp 1-88 \* Office of the Executive Lagal Director 79/05/18 89pp
- U Congressional/Executive Correspondence
- 7906260541 Responds to 790423 itr re S Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FES W/o enct GDSICK.L V Office of the Executive Director for Operations 79/05/15 2pp
- --7904260544 Requests info re radiological impact of nuclear power plant cooling on drinking water in ref to SL Austin inquiry IEMI.N F House of Rep. 79/04/23 2pp

- 790,6010055 Summary of 790420 meeting w/util in Bethesda. HD re modified radiological effluent Tech Specs ROOMEY.V t. Operating Reactors Branch 3 (Pre 790625) 79/04, 2pp
- 7906270275 Ack receipt of 790328 ltr objecting to Class III fee requested in NRC 790316 ltr Fee is due within 15 days ofthin receipt of ltr MILLER. W O License Fee Management Branch 79/03/25 2pp
- 7906260232 Responds to 790302 request for exemption from Type A test frequency as required by 10CFRSO AJ. Section III A 6(b) Request denied Test needed to verify completeness of corrective action plan GRIMES. B Assistant Director for Engineers & Projects (Pre 790623) 79705730 2pp
- 7906180243 Defers submission of requested Class III fee for propose License Change 74. Suppl 1/as matter still under legal review Response to be filed by 790629 VANDENBURGH.D Vermont Yankee Nuclear Power Corp 79/06/12 1p
- Q Inspection reports. IE Bulletins & correspondence
- 7906260171 Forwards [E Insp Rept 50-271/79-06 on 790320-23 No noncompliance noted BRUNNER, E.J. Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- --7908260175 IE Insp Rept 50-271/79-06 on 790320-23 No noncompliance noted Major areas inspected fuel shuffling program to activities, plant uperations, planned startup testing prugram to station personnel change MCCABE.E C . STETKA.T F Region 1, Philadelphia, Office of the Director 79/04/19 Bpp
- 7906110046 Forwards IE Bulletin 79-03B, "Nuclear Incident at THI-Buppi" No written response required GRIER.B H Region i, Philadelphia, Office of the Director 79/04/23 lp
- 7906050281 Responds to IE Bulletin 79~0B re items identified during THI~2 event Ali vessel level instrumentation was reviewed, appropriate procedures are being revised % Containment air dilution sys installed MOODY.DE Vermont Yankee Nuclear Power Corp 79/04/27 App
- 7906140328 Responds to IE Bulletin 79-07 re ssismic stress analysis of safety-related piping No analysis using mothod listed in Item I has been identified Investigation continuing MODDY.D E Vermont Yankee Nuclear Power Corp 79/04/27 2pp
- 7906130i14 Responds to IE Bulietin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " No such valves are in use in seismic Category I piping sys GROCE:R H Vermont Yankee Nuclear Power Corp 79/05/02 lp
- 7906130177 Forwards IC Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Fower Increase " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 79/05/02 ip
- 7906180141 Forwards summary of 790306 mgt maeting Info presented during meeting resulted in withdrawal of Item 8 of 781222 notice of violation SMITH.0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- --7906180171 Summary of 790306 mgt meeting w/util in King of Protsie.PA
  re computerized personnel desimetry record sys & withdrawal
  of apparent item of noncompliance
  SMITHO H Region 1. Philadelphia. Fuel Facility & Materials
  Safety Branch 79/09/02 2pp
- 7906140535 Forwards vessel level indication drawing as addl info to 790427 response to IE Bulletin 79-QB GROCE.R H Vermont Yankse Nuclear Power Corp 79/05/04 2pp
- 7906120205 Forwards IE Info Notice 79-11, "Lower Reactor Vassel Head Insulation Support Problem" No action required GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906:10:50 Forwards IE Bullatin 79-10, "Requalification Training Program Statistics " Written response required GRIER, B H Region i, Philadelphia, Office of the Director 79/09/11 19

- 7906260163 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.B H Region I. Philadelphia. Office of the Director 79/09/11 1p
- 7906290806 Responds to IF Bulletin /9-09 GE Type AK-2 circut breakers are used on 480 voit safety-related switchgears
  MOODY, D E Vermont Yankee Nuclear Power Corp 79/05/17 3pp
- 7906080111 Forwards IE Circular /9-08, "Attempted Extertion Low Enriched U" ORIER,D H Region 1, Philadelphia, Office of the Director 79/05/18 1p
- 7906260564 Responds to IC Dulletins 78-12.12A & 128 Submits results of records search for spec of weld matl used for fabrication of reactor pressure vessel ROGOV.D E Vermont Yankes Nuclear Power Corp 79/09/25 2pp
- 7906290096 Requests roling from certain programmatic requirements of ASME Section XI to inservice insp program until 800130 Wencl record of changes & table of contents for program. Tech Specs & reliaf request basis GROCER II Vermont Yankee Nuclear Power Corp. 79/06/25 App
- R Periodic operating reports & solated correspondence
- 7906190305 Forwards monthly operating rept for May 1979 HOODY, D.C. Vermont Yankes Nuclear Power Corp. 79/06/12 1p
- --7906190311 Monthly operating rept for May 1979 SUGOREN,R M Vormont Yankee Nuclear Power Corp 79/06/12 App
- 8 Reportable accurrences, LFRs & related correspondence
- 7706040255 Forwards LLR 78-007/03L-0 CONHAY,W F Vermont Yankas Nuclear Power Corp 78/04/28 1p
- --7906040238 LFR 78-009/03L-0 on /80331 during control red testing, rod block monitor A was hypassed several times Caused by supervisory misunderstanding Hisunderstanding clarified & precautionary procedures added CONMAY.W F Vermont Yankee Nuclear Power Corp. 78/04/28 2pp
- DOCKET 50-272 SALEM NUCLEAR GEN RATING STATION, UNIT 1
- 7906010140 Opposes licensee's motion for summary judgment Licensee has not carried burden of proof-nor shown that contentions are unconvincing Affidavit & Certificate of Eve encl MACARTOR. J D Boloward, Elate of 79703/20 4pp
- 7904010099 Memo by intervenors Colemans in opposition to licensee's motion for summary judgment statement by intervenors of mati facts in dispute re-intervenors' Contention 2 Affildavit of QC Minor & Certificate of \$900 encl VAN NESS:8 C. ONBDORF.K A New Jersey, State of 79/03/29 30p
- 7906030345 Confirms 790329 order outlining schedule of 790502 evidentiary hearing Adds three questions re incident at TMI for discussion at hearing HILHOLLIN, Q L Atomic Bafety and Licensing Board Panel 79/04/18 2pp
- 7906020252 Uutling of intended cross-examination by util.contingent upon dental of util 790423 objections to intervenor's profferred testimony Cartificate of Svc enci METTERHARN, M. J. Conner, Moore & Corber 79/04/25 10pp
- 79040403BB Outline of areas of cross-examination submitted per 790329 pretrial order Cartificate of Svc encl MACARTOR, J D Dalaware, State of 79/04/25 3pp
- 7706180441 Responds to ABLB 770418 order Forwards RE Webb 770227 testimony re-accident hazards of spent fuel storage, on behalf of intervenor Lower Alloways Greek Township, PA Certificate of 8 vc encl VALORE, C. Valore, C 77/04/25 6pp
- --7906180455 Testimony re ABLB 790418 order Quantion 3 Spent fuel storage is unsafe.accidents are possible & potential harm is extreme Reactor must be closed down Prof qualifications enci HEBB:R E Affiliation Unknown 79/02/27. 37pp.

- 7906200611 Outlines of cross-examination of Colemans on Contentions 2 & 6 re spent fuel assemblies testing of boral matl in environ & outline of cross-examination of Lower Alloways Creek on Contention 1 re spent fuel pool W/Certificate of Svc QNSDORFF.K A New Jarsey, State of 79/04/25 4pp
- 7906020072 Advises that WB Nechodom of Exxon Nuclear Corp will replace JH Riddle on licensee's witness panel Prof qualification of WS Nechodom encl WETTERHAWN.M J Conner, Moore & Corber 79/04/26 3ap
- 7906180B07 Responds to request made during limited appearance in proceeding Forwards 10CFR? 5 regulations defining procedures for document requests M/o encl MOGRE, J E Branch 2 797/04/27 ip
- --7906180816 Responds to request made during limited appearance in proceeding Reed rept is proprietary Forwards IOCFR2 7960(b))(6), defining individuals w/access to proprietary info W/o encl MOORE.J E Branch 2 79/04/27 2pp
- 7906010284 Notifies that evidentiary hearing reconvenes on 790710 in Salem, NJ Testimony to be offered at hearing shall be filed by 790619
  MILHOLLIN, O. L. Atomic Safety and Licensing Noard Panel 79/05/14
- 7906170006 Erratum to 790514 notice of hearing
  MILHOLLIN, C. Atomic Safety and Licensing Soard Panel 79/09/17
  1p
- J Insurance & indemnity information
- 7906120211 Forwards Endorsements 27.28 & 29 to MAELU Policy MF-90 CORREA,C Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79706/04 App
- 7706260368 Forwards executed Amend 6 to Indomnity Agreement B-74 ORIFFITHS, R Public Service Electric & Gas Co of New Jersey 79/06/20 3pp
- P Operating license stage documents & correspondence
- 7906060270 Forwards requested info re main feedwater events, pressurizer heaters & steam generator schematic diagram LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 79/05/23 4pp
- 7906250196 Notification of 790525 meeting w/Nestinghouse & util in Bethesda, MD to discuss surface damage observed at fuel assemblies
  ZECH-0 0 Operating Reactors Branch 1 (Pre 790625) 79/05/25
- 7906190201 Forwards request for emend to License DPR-70 to change Tech Specs for diesel generator breaker trip protection Contificate of Svc & fee encl LIBRIZZI,F P Public Bervice Electric & Gas Co of New Jersey 79/06/14 Spp
- --7906190216 Requests amend to License DPR-79 to change Tech Specs re diesel generator breaker trip protection \* Public Service Electric & Qas Co of New Jersey 79/06/14 2pn
- 790622036: Bubmits info requested by NRC 790525 ltr ru power feedwater lines design & Fabrication history BCHNEIDER, F W Public Service Electric & Qas Co of New Jersey 79706/14 33pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906110039 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppi." No written response required ORIER, B H Region i, Philadelphia, Office of the Director 79/04/23 ip
- 7906120081 Requests extension until 790504 to respond to IE Bulletin 79-07 SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey
- 790&020193 Responds to IE Bulletin 79-06A Special task force established to coordinate review % understanding of TMI-2 event Appropriate procedural revisions being prepared Supplemental response will be made prior to 790531 SCHNCIDER, FW Public Service Electric & Gas Co of New Jersey 79/04/25 23pp

- 7904040078 Ack receipt of 790328 itr informing NRC of steps taken to correct violations noted in IE insp Rept 50-272/79-03
  CARSON.R T Hagion 1. Philadeiphia, Reactor Construction & Engineering Support Branch 79/04/25 ip
- --7906040079 Responds to NRC 790308 ltr re violations noted in IE Insp. Rept 50-272/79-03 Corrective actions fire watch posted at open penetration, penetration sealed & cables rerouted properly SCHNEIDER, F. W. Public Service Electric & Gas Co. of New Jersey 77/03/28 3pp
- --79060400Bi Forwards IE Insp Rept 50-272/79-03 on 790130-0201 & 05 & notice of violation
  CARLESON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/08 2pp
- --7906040083 Notice of violation from insp on 790130-0201 \$\dot 05 \$\display \text{Region i, Philadelphia, Reactor Construction \$\delta \text{Engineering} \text{Support Branch 79/03/08 2pp}
- --790&040089 IE insp Rept 50-272/79-03 on 790130-0201 & 05 Noncompliance noted unsealed penetration & failure to meet controls & verification for associated circuit GALLINA.C O Region 1, Philadelphia, Office of the Director Region 1, Philadelphia, Safeguards Branch CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/08 14pp
- 790&0703B9 Responds to IE Bulletin 79-04 re seismic Category 1 piping sys w/3.4 or 6-inch diameter valves Heights for 6-inch valves have been corrected; awaiting confirmation of 3 % 4-inch weights from Velan SCHNEIDER; FW Public Service Electric & Gas Co of New Jersey 79/04/30 3pp
- 7906120197 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required CRIER. B H Region 1. Philadelphia, Office of the Director 79/08/07 2pp
- 7906110148 Forwards IE Bulletin 79~10. "Requalification Training Program Statistics " Written response required GRIER.B M Region 1. Philadelphia. Office of the Director 79/05/11 ip
- 7906260149 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  GRIER. B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906276204 Responds to IE Builetin 78-128. "Atypical Weld Matl in Reactor Pressure Vessel Welds " Requests extension of response due date to 791031
  SCHNEIDER, F W Public Service Electric & Gas Co of New Jersey 79/05/14 to
- 7906080104 Forwards IE Circular 79-08, "Attempted Extortion Low Enricked U " GRIER.B H Region i, Philadelphia, Office of the Director 79/05/18 is

- 7906260418 Forwards operating rept for industrial waste treatment plant for Hay 1979
  MIDURA, H J Public Service Electric & Gas Co of New Jersey
  79/06/12 2pp
- 7906260349 Forwards discharge monitoring repts for May 1979 MIDURA:H J Public Bervice Electric % Gas Co of New Jorsey 79/04/19 15pp
- S Reportable occurrences. LERs > related correspondence
- 7906040336 Forwards RD 78-20/04L L1BRIZZI.F P Public Service Electric % Gas Co of New Jersey 78/04/04 ip
- --7906040340 RO 78-20/04L on 780217 required weakly river water samples for bigcide determinations not taken during Junes Sept or Dec 1977 Caused by personnel error Personnel reinstructed CCQLEY,D E. HELLER, B. J. Public Service Electric & Gas Co. of New Jersey. 78/04/04. 2pp
- 7906040260 Forwards RO 78-23/04T LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 78/04/17 1p
- --7906040271 RQ 78-23/04T on 78041A milk sample had I-131 concentration which exceeded ten times control station concentration Probably caused by Chinese weapon test rather than misoperation of facility ALLMAN.N C Public Service Electric & Oas Co of New Jersey 78/07/18 2pr
- 7906040275 Forwards LCR 78-022/01T-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 78/04/17 ip
- --7904040277 LER 78-022/01T-O on 780404 Fischer & Porter 1082476 transmitters for coolant low flow monitoring had high output deviation during squamic test Caused by vibration of mounting plate Design change initiated BFENCERT L Public Service Electric & Gas Co of New Jersey 78/04/17 3pp
- 7705040170 Confirms 780404 telcon advising of RO Instrument panels containing reactor coolant low flow transmitters could fail during design base seismic event Corrective action will be required
  HELLER.H J Public Service Electric & Gas Co of New Jersey 77/04/04 ip
- 7906050283 Forwards RO 79-40/04L LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 79/05/24 ip
- --770A050294 RO 77-40/04L on 770425 liquid waste disposal RMS monitor channel IRIS failed routine channel calibr check Caused by failed tube in channel detector causing detector output to increase by factor of 2 Detector replaced KAPPLE.A W Public Service Electric b Gas Co of New Jersey 77/03/24 ip
- 7906040303 LER 78-046 number not used \* Public Service Electric & Qas Co of New Jersey 79/05/29 1p
- 7906080289 Forwards LER 79-027/01X-1 LIBRIZZI.F P Public Service Electric & Gas Co of New Jersey 79/06/01 1p
- --7906050291 LER 79-027/01X-1 on 790325 while providing backup protection to Hope Greek, facility fresh water tanks were below Tech Spec required levels Caused by poor communications between facilities Water level restored KAPPLE.A W Public Service Electric & Gas Co of New Jersey 79/06/01 ip
- 7906030301 Forwards LER 79-038/01X-1 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 79/06/01 1p
- --7906050304 LER 79-035/01X-1 on 790405 during cold shutdown; w/fire pump 1 out of svc.fire pump 2 did not start when header pressure dropped to 75 16 psi. Pump started manually Caused by weak cell in A & B batteries KAPPLE.A W Public Service Electric & Qas Co of New Jersey 79/06/01 ip
- 7906050339 Forwards LER 79-044/03L-0 LIBRIZZI.F P Public Service Electric & Gas Co. of New Jersey, 79/06/01, ip

- --7908050340 LER 79-044/03L-0 on 790506 during refueling operations, 20 fuel assemblies were identified as having cracked dented or torn grid straps Corrective action will be taken after evaluation complete Cause not known at present time KAPPLE, A W Public Service Electric & Oas Co of New Jersey 79/06/01 2pp
- 7906070268 Confirms 790601 verbal rept to E Brunner, advising of potential RU Linear cracking observed on pump impeller Spare impeller was tested & also showed cracks Impellers being sent to vendor for testing MIDURA.H J Public Service Electric & Oas Co of New Jersey 79/06/01 ip
- 7906110226 Forwards LER 79-043/017-0 LIBRIZZI.E P Public Service Electric & Oas Co of New Jersey 79/06/05 ip
- --7906110231 LER 79-043/01T-0 on 790522 auxiliary feedwater pumps discharge valves demand reduction to OX Caused by deficient surveillance procedure immediate change initiated to leave demand signal at normal value KAPPLE, A W Public Service Electric & Oas Co of New Jersey 79/06/05 3pp
- 7906180585 Forwards LER 79-045/01T-0 LIBRIZZI.F P Public Bervice Electric & Gas Co of New Jersey 79/06/14 ip
- --7906180593 LER 79-048/01Y-O on 790601 component cooling pump impellers contained linear tears & porosity in vane connection to outer geriphery Gause being investigated Defective impellers will be replaced W/stainless steel components KAPPLE,A W Public Service Electric & Gas Co of New Jersey 79/06/14 3pp
- 7906200407 Ferwards LER /9-042/03L-0 LIBRIZZI,F P Public Service Electric & Gas Co of New Jersey 79/06/15 3pp
- --7906200414 LER 79-042/03L-O on 790517 during refueling operations four non-functional fire barriers were identified Caused by personnel error in that deficient penetrations were not noted during Nov 1778 insp Penetrations properly sealed KAPPLE, A W Public Bervice Electric & Gas Co of New Jersey 79/06/15 ip
- T Hearing transcripts on non-antitrust matters
- 7904090420 Errata to hearing transcript on facility application HILKOLCIN, G L Atomic Safety and Licensing Board Panel 79/03/30
- DDCKET 50-274 U S OEOLOGICAL SURVEY RESCARCH REACTOR
  Q Inspection reports. IE Bulletins & correspondence
- 7906010285 Forwards IE Insp Rept 50-274/79-02 on 790319-0322 No noncompliance noted HADBENIO L Branch 79/04/10 2pp
- --7906010291 IE Insp Rept 50-274/79-02 on 790319-0319 Na noncompliance noted Major areas inspected organization, safety committee reviews & audits; operations & maint records & new experiments re reactor operation MADBEN, 0 L., EVERETT, R J Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/12 7pp
- 7906250004 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  SEYFRIT.K.V Region 4, Dallas, Office of the Director 79/05/11
- DOCKET 50-275 DIABLO CANYON NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 7906080211 Summary of 790418 meeting w/util re radiological efficient Tech Specs BUCKLEY.B C Light Water Reactors Branch 1 79/05/08 5pp
- 7906250113 Requests addl info for review re environ qualification of balance of plant equipment, fault current protection for containment penetrations, ventilation & auxiliary feadwater eys, fire protection & inservice testing STOLZ, J.F. Light Water Reactors Branch 1. 79/05/16 7pp

- 7906250160 Requests addl info re instrumentation qualification of Barton transmitters STOLZ-JF Light Water Reactors Branch 1 79/05/25 App
- 7906150416 Forwards repts re ventilation sys electromechanical devices auxiliary feedwater valve motor operators environ qualification of conduits & fuel transfer tubes in response to 790911 request CRANE, P. A. Pacífic Gas & Electric Co. 79/06/11 20pp
- ---7906150420 "Gualification Type Test Rept Limitorque Valve Actuators for Class IE Svc Outside Primary Containment" HESS.T. DENKOWSKI, H., FORMICA:C Limitorque Corp. 79/05/02 6600
- --7906150422 "Rept of Seismic Test on SMC-04 Valve Control (Std) "
  \* Pacific Gas & Electric Co 79/03/30 72pp
- --7906150424 "Qualification Rept for Conductor Modules for AK Nuclear One Unit 2 " FEDERICK, H C Limitarque Corp IPS-409 79/03/09 37pp
- 7906190453 Bubmits addl info re environ qualification of Barton pressure & differential pressure transmitters CRANE,P A Pacific Gas & Electric Co 79/06/14 lp
- 7906200464 Forwards response to 790314 request for add1 info re main steam line break inside containment W/proprietary & nonproprietary versions of "Equipment Qualification" & applications for withholding proprietary info CRANE.PA Pacific Gas & Electric Go 79/06/14 19
- --7906200472 Application for withholding proprietary info from public disclosure Forwards proprietary & nonproprietary versions of Hestinghouse rept. "Equipment Gualification" CRANE,P A Pacific Gas & Electric Co 79/06/14 2pp
- --7906200480 Nonproprietary version of "Equipment Qualification "
  \* Westinghouse Electric Corp 79/06/20 23pp
- 7906180521 Forwards changes to input parameters to correct logic error reported in Westinghouse App K ECCS model Change accounts for heating effect of irrcalou-water reaction CRANE.P A Pacific Gas & Electric Co 79/06/15 3pp
- G Adjudicatory correspondence
- 7906020063 Requests status of GL BROWN, J P | Worthern California Ecumenical Council | 79/03/21 1p
- ---7906020067 Requests alternate power sources & conservation measures in CA.in lieu of issuing CP BROWN.J P Northern California Ecumenical Council 79/02/16 1p
- 7906180253 Requests halt to nuclear plant const \* Affiliation Unknown 79/04/02 1p
- --7906180259 Recommends postponement of DL issuance until earth safety factor is guaranteed BATES.T H , KAPILOFF.L , GACH.H California. State of 7' 30p
- --7906180267 Forwards constituent itr re facility const near gr fault Requests any info dealing w/matter ANDREWS.M House of Rep 79/03/23 ip
- --7906180274 Expresses concern re reactor const near active ge fault LENABURG.S D Affiliation Unknown 79/03/18 1p
- --7906180284 Opposes nuclear facility const PETERS,M Affiliation Unknown 79/04/02 ip
- ---7906180293 Oppnses const of facility near active geologic fa SILDER.R Affiliation Unknown 79/04/02 ip
- --7706180309 Requests facility const crase due to possible hea hazards REYNOLDB.J , REYNOLDB.P Affiliation Unknown 79/03/31
- --7906180317 Requests facility const casse
  WERSTER Affiliation Unknown 79/04/02 ip

- --7906180328 Requests facility const cease due to radiation hazards KAMERER, D. J. Affiliation Unknown 79/04/03 1p
- ~~7904(80333) Expresses concern over const of facility
  MCCARTHY, K J . CAROTHERS, J Affiliation Uninoun 79/04/02 2pp
- 790514001B Board notification semiscale experiment S-A7-6 Unanticipated results re-cladding temp require further study to determine safety significance Certificate of Svc encl # Hearings Division 77/04/05 54pp
- 7906070327 Motion by joint intervenors Scenic Shoreline Preservation Conference. San Luis Obispo Mothers for Peace, S Silver, Ecology Action Club & JJ Forster for withholding of CP Certificate of Svc enci FLEISCHAKER, D S Fleischater, D S PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/04/12 Spp
- 7706010059 Responds to 790331 ltr concerning unresolved questions about low level radiation & nuclear waste disposal Util will submit plans for increasing spent fuel pool storage capacity in near future VASSALLO, D B Assistant Director for Light Water Reactors 79/05/02 200
- 7906020118 Responds to ltr expressing opposition to plant operation because of proximity to active earthquake fault & problem of disposal of wastes Board is in process of preparing decision re-plant licensing

  BOYD.R S Division of Project Management 79/05/04 2pp
- 7906010341 Request by joint intervenors that ASLB reopen evidentiary hearings to address Class 9 accidents & emergency planning in alternative, seets directed certification on related questions Certificate of Svc encl FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/03/09 lipp
- 7906280013 Forwards attachments & errata sheet to joint intervenors 790509 request to reopen or, in alternative, request for directed certification Certificate of Svc encl FLEISCHAKER, D.S. Fleischaker, D.S. 79/05/10 10pp
- --7905280015 Errata sheet to joint intervenors 790507 request to reapen or, in alternative, request for directed certification FLEISCHAKER, D & Fleischaker, D & 79/05/10 2pp
- 7906200238 Comments on Governor EG Brown 790804 ltr to UN Hendrie Request for extraordinary action of singling out plant for suspension of licensing proceedings is unsubstantiated BGNNER, J.F. Pacific Gas & Electric Co. 79705/11 2pp
- 7906220491 Responds to 790420 & 26 lits re opposition to facility const near Hosqr: fault No evidence generated in ASLB hearings for earthquakes at Hosqr: greater than 7 5 DENTON, H R Office of Nuclear Reactor Regulation 79/05/14 2pp
- 7906260067 Defers ruling on reopening evidentiary hearings until NRC completes rept on effects of THI on proceeding Other parties will be provided opportunity to respond to rept BOWERS, E.S. Atemic Safety and Licensing Board Panel 79/06/05
- H General correspondence
- 7908080039 Requests that earthquake potential be considered before granting CP OREEVER.R Affiliation Unknown 79/03/17 Spp
- 7906010297 Discusses reasons for delays in facility const completion. In response to 790328 ltr of concern Verification of ability of plant to withstand possible earthquake is main cause of delay

  BENTON.H R Office of Nuclear Reactor Regulation 79/04/20 2pp
- --7904010299 Requests info re delays in completion of const of facility Continued delays only preclude use of alternate energy sources to conserve oil WADEKAMPER.D Affiliation Unknown 79/03/28 ip
- 7906040101 Objects TH Bates 790405 Itr supporting postponement of DL issuance Supports development of nuclear power CASTALDO, V.F. Affiliation Unknown 79/04/26 Ip
- --7906040111 Requests OL be denied due to proximity to earthquake zone, %LINE,J. WATERHOUSE,H. WATERHOUSE,E. Affiliation Unknown 79/04/26 3pp

- 7906070401 Responds to 790328 ltr re-potential for delays in issuance of OL decision in order to satisfy antinuclear minority groups concerned re-plant ability to withstand affect of earthquakes

  BOYD, R.S. Division of Project Management 79/04/27 2pp
- --7906070405 Comments on granting of OL operation of plant should not ta further postponed to satisfy anti-nuclear minority MILLER.P C Affiliation Unknown 79/03/28 1p
- 7705130252 Requests that CA Public Utils Commission withhold issuance of "certificate of necessity" for plant until Santa Barbara County can devise emergency evacuation plan MCDERMOTT, D Affiliation Unknown 77/05/01 ip
- 7906070308 Act receipt of 790323 itr re S Lenaburg correspondence Forwards info giving brief history & status of licensing process H/o encl KAMMERER, C Office of Congressional Affairs 79/05/02 ip
- 7906140329 Discusses potential for delays in issuance of decision on OL, in order to satisfy antinuclear minority groups BDYD,R S Division of Project Management 79/05/04 2pp
- 7906180172 Responds to 790413 ltr re safety considerations involved in OL issuance VASSALLO,D B Assistant Director for Light Water Reactors 79/05/10 2pp
- 7906190123 Responds to 790317 itr re issuance of CP Forwards info re structural design, inflation allowances for decommissioning costs, waste storage, low level radiation effluents & transport of spent fuel BOYD, RS Division of Project Management 79/05/15 App
- Q Inspection reports. IE Bulletins & correspondence
- 7906160042 Forwards IE Insp Rept 50-275/79-09 on 790328-0406 No noncompliance noted Rept withheld (ref 10CFR 790) NDRDERHAUGL R Region 5, San Francisco, Safeguards Branch 79/05/02 200
- 7906120047 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/07 1p
- 7906180479 Forwards IE Info Notice 79-12, "Attempted Damage to New Fiel Assemblies " No written response necessary EMBELKEN R H Region 5, San Francisco, Office of the Director 79/05/10 ip
- 7906080241 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/18 in
- 7906130041 Forwards LE Bullotin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 20/08/20 to
- 7906180374 Forwards IE Bulletin 79-12, "Short Period Scram at BHR Facilities " No written response necessary ENGELMERNR H Region 5, Ban Francisco, Office of the Director 79/03/31 1p
- 8 Reportable occurrences, LERs & related correspondence
- 7906180219 Forwards PNO-79-67AN ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/14 10
- 7906180265 Forwards PNO-79-67AO ENGELKEN: R H Region 5, San Francisco. Office of the Director 79/05/21 1p
- 7906180338 Forwards PNO-79-67AP ENGELKEN:R H Region 5, San Francisco, Office of the Director 79/05/22 is
- 7906180364 Forwards PNO-79-67AQ ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 79/03/30 ip

- 79061303B3 Responds to 790501 itr Details corrective actions for two items of noncompliance re bolting of unistrut saddle brackets & non-Class I conduit crossing over Class I equipment CRANE.P A Pacific Gas & Electric Co 79/06/04 3pp
- U Congressional/Executive Correspondence
- 7906080199 Forwards ltr from constituent containing Santa Barbara.CA Board of Supervisors resolution that NRC defer final action re license application until adequate safety checks have been completed

been completed LAGOMARSING.R J House of Rep 79/04/24 2pp

- 7906290228 Responds to 790424 ltr forwarding J Schlesinger 790418 ltr re Banta Barbara. CA Board of Supervisors resolution urging NRC to defer final licensing action on facility until safety can be assured GOSSICK.L V Office of the Executive Director for Operations 79/05/23 2pp
- DOCKET 50-276 GEORGIA TECH RESEARCH REACTOR

  J Insurance & indemnity information
- 7906270209 Forwards Amend 12 to Indeminty Agreement E-30 WILSON, J W Georgia Institute of Technology 79/06/22 2pp
- Q Inspection reports, IE Builetins & correspondence
- 7906250413 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  O'REICLY J P Region 2. Atlanta. Office of the Director 79/05/10 in
- DOCKET 50-277 PEACH BOTTOM ATOMIC POWER STATION, UNIT 2

  f Security, medical, emergency & fire protection plans
- 7906260023 "Fire Protection in Operating Nuclear Power Stations, Peach Bottom Units 2 & 3 SER Review " HALL.R E., MACDOUGALL.E A Brookhaven National Laboratory 7906260023 79704/06 4pp
- O Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO, U F Hearings Division 79/04/02 2pp
- --7905210050 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790405 CHRIBTENDURY, E Hearings Division 79/03/26 34pp
- 7906180656 Motion for reconsideration of ALAB-540 & severence from consolidation established by ALAB-540 Admits issues not raised by any party & departs from "lead case" procedure previously adopted Certificate of Svc encl CONNER, T B Conner, Moore & Corber 79/05/02 15PP
- 7906210093 NRC motion for summary disposition re radon issue was in arror. ALAB-340 consolidated only 5 of 16 cases Denies NRC motion re parties in other proceedings W/Certificate of Svc DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/05/25 3pp
- 7906230107 Request by utils that ABLAB grant summary disposition of all issues in consolidated radon proceeding Utils seek decision as matter of lawing genuing issue as to matl facts SILBERG, J A Shaw, Pittman, Potts, & Troubridge VOIGHT. H H LeBocuf, Lamb, Latby & MacRae CUNNER, T B Conner, Moore & Corber 79/05/25. App
- --7906230110 Statement of mati facts is radon proceedings, for which there is no genuine issue to be heard Discusses alleged Deficiencies 1-7.7-18.20-24 & 26 Affidavit of MI Goldman & supporting documentation encl BILBERG, J.A. Bhew, Pittman, Potts, & Trowbridge VDIGHT, H. LeBoguf, Lamb, Leiby & MacRae CUNNER, Y.B. Conner, Moore & Corber 77/05/25 36pp
- --7906230112 Supplements MI Goldman 790525 affidavit & utils 790409 memo re radon emissions & de minimus approach Discusses alleged Deficiencies 2:9.16 & 21 Seeks motion for summary disposition Certificate of Svc encl SILBERG, J. A. Shaw, Pittman, Potts, & Troubridge VDIGHT, H. LeBoeuf, Lamb, Letby & MacRae CONNER, T. B. Conner, Moore & Corber 79/05/25 19pp

- P Operating license stage documents & correspondence
- 7906250074 Forwards Amends 52 % 52 to Licenses DPR-44 % DPR-56 respectively. & notice of issuance % availability IPPOLITO, T A Greating Reactors Branch 3 (Pre 790625) 79/05/03 2pp
- --7906250079 Amends 52 & 52 to Licenses DPR-44 & DPR-56 respectively, substituting two new conditions re thermal discharge iPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79/05/03 10pp
- --7906250083 Notice of issuance & availability of Amends 52 & 52 to Licenses DPR-44 & DPR-5& respectively IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79/05/03 2pp
- 7906290665 Forwards Amends 53 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability IPPCLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/23 3pp
- --7906290670 Amends 53 to Licenses DPR-44 % DPR-56 IPPOLITO T A Operating Reactors Branch 3 (Pre 790625) 79/05/23 4pp
- --7906290677 Safety evaluation supporting Amends 33 to Licenses DPR-44 DPR-96 Departing Reactors Branch 3 (Pre 790625) 79/05/23 B9pp
- ---79062906B3 Discusses safety evaluation rept review re facility fire protection Proposed mods represent significant increase in level of protection MALL-R E Brookhaven National Laboratory 79/04/06 3pp
- --7906290700 Notice of issuance & availability of Amend 53 to License: DPR-44 & DPR-56 IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79705/23 2pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906110029 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 ip
- 7906110026 Responds to IE Bulletin 79-07 re seismic stress analysis o safety-related piping Plant did not use specified computer codes for seimic stress analysis DALTROFF.S L. Philadelphia Electric Co. 79/04/24 4pp
- 7906020241 Submits info in response to IE Bulletin 79-08 Discusses methods used in seismic analysis of safety-related piping, program listing b program verification GALLAGHER, J W Philadelphia Electric Co 79/04/25 14pp
- 7906:30:12 Responds to IE Bulletin 79-04, "Incorrect Heights for Swing Check Valves Mfg by Velan Engineering Corp " Valves are used as inboard & outboard containment isolation valves Complete response will be forwarded by 7903:1

  DALTROFF, S. L. Philadelphia Electric Co. 79/05/01 3pp
- 7906:130170 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Cenerator Set Resulted in Reactor Power Increase "No written response required ORIER.B H Region I. Philadelphia. Office of the Director 79/05/02 ip
- 7906120188 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H Region I, Philadelphia. Office of the Director 79/05/07 2pp
- 7906110146 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required QRIER.B H Region i, Philadelphia, Office of the Director 79/05/11 ip
- 7906260139 Forwards IE Info Notice 79-12, "Attempted Damage to New F Assemblies " ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906270193 Responds to 1E Bulletin 79-09 No GE Type AK-2 circuit breakers in use or planned for use in safety-related sys DALTROFF, S L Philadelphia Electric Co 79/05/14 ip

- 7906080102 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " GRIER, B H Region I, Philadelphia, Office of the Director 79/05/18 ip
- R Periodic operating reports & related correspondence
- 7906180530 "Post-Operational Rept 11 on Ecology of Concuengo Pond" for Philadelphia Electric Co 79/03/31 258pp
- 7906150335 Forwards onlysron surveillance & special study program rept, "PBAPS-Preoperational Rept 11 on Ecology of Conceings Pond for July-Dec 1978," prepared by RMC-Ecological Div W/o encl HILLSEY, W B Philadelphia Electric Co 79/06/07 1p
- 7906140221 Forwards "Environ Radiation Monitoring Program" for 1978 Rept 36 & "Radiological Regional Environ Monitoring Program" for 1978, Rept 4 for 1978, Rept 4
  WILLEEY, W B Philadelphia Electric Co 79/06/08 1p
- --7906140228 "Environs Radiation Monitoring Program" for 1978.Rept 36. prepared by Interex Corp \* Philadelphia Electric Co 79/05/31 116pp
- --7906140235 "Radiological Regional Environ Monitoring Program," 1978 Rept (4, prepared by Radiation Mgt Corp \* Philadelphia Electric Co 79/05/31 128pp
- 7906140455 Forwards "Thermal & Biological Monatoring Programs" Monthly Repts 67.68 & 67 for Jan.Feb & Mar 1979 respectively WILLBEY,W B Philadelphia Electric Co 79/06/08 ip
- --7906140459 "Thermal & Diological Munituring Programs," Monthly Rept 67. Jan 1979
  \* Philadelphia Electric Co 79/06/08 2pp
- --7906140463 "Thermal & Biological Munituring Programs," Monthly Rept 60. Feb 1979 Philadelphia Electric Co 79/05/08 2pp
- --7906140466 "Thermal & Biological Monitoring Programs." Monthly Rept 69, Mar 1979 \* Philadelphia Electric Co 79/06/08 31pp
- 7906140243 Forwards "Thermal & Biological Monitoring Programs," Monthly Rept 70, Apr 1979 WILLSEY, W B Philadelphia Electric Ca 79/06/11 ip
- -- 7906140247 "Thermal & Biological Monitoring Programs," Monthly Rept 70. Apr 1979 \* Philadelphia Electric Co 79/04/30 10pp
- 7906190329 Forwards monthly operating rept for May 1979 COONEY, M J Philadelphia Electric Co 79/06/11 1p
- --7906190331 Monthly operating rept for May 1979
  ALDEN,W M Philadelphia Electric Co 79/06/10 10pp
- S Reportable occurrences, LERs & related correspondence
- 7906040341 Forwards LER 78-011/04T-0 COUNEY:M J. Philadelphia Electric Co 78/03/07 2pp
- --7905040345 LER 78-011/04T-0 on 780223 approx 40 gailons light diesel fuel oil drained into discharge canal Gaused by Valvs left open after use Bpillage stopped upon discovery cleanup initiated & valve locted to control use GUONEY. M J Philadelphia Electric Cd 78/03/07 ip
- 7906040246 RO 2-78-38/IP on 780908 unconformed calculations show 000000000 Nu & (0-30), on inboard reactor water cleanup systemation on inboard reactor water cleanup systemation valve MO-15 during DBE Caused by use of erroneous screleration rate on valve LLRICH, W T Philadelphia Ejectric Co 78/09/11 2pp
- 7906040256 RO 1-78-38/IP on 780908, analysis by A/E on reactor water cleaning piping in drywell resulted in redution in acceleration valves Addl restraint will be installed on Unit 2 during present refusing outage.

  ULLRICH.W T Philadelphia Electric Co. 78/09/12 tp
- 7906040367 Forwards LER 78-038/017-0 COUNEY, M. J Philadelphia Electric Co 78/09/22 3pp

- --7906040348 LER 78-038/017-0 on 780908 one point on piping dutboard MG-12-15 had stress during DBE above code allowable Restraint to be added to code COONEY: H J Philadelphia Electric Co 78/09/22 1p
- 7906040920 Forwards LFR 78-043/03L-0 COUNEY, M J Philadelphia Electric Co 78/11/17 3pp
- 7906040329 LER 78-043/03L-0 on 781019 snubber 23HBS-38 found w/unacceptable bleed rates & locking velocities Caused by clogged bleed orifices & low ambient temp during tosts 8afety-related snubbers tested regaired & recallb COONEY, M J Philadelphia Electric Co 78/11/17 ip
- 7906070370 RO 3-79-12/1P on 790326 gaseous release rate exceeded allowable Tech Specs limits for instantaneous release rate Caused by lack of proper procedure lead to valving errors Procedures will be revised & valves clearly identified ULLRICH, H T Philadelphia Electric Co 79/03/27 2pp
- 7906070210 Forwards LER 79-011/017-0
  COONEY, M J Philadelphia Electric Co 79/03/29 4pp
- --790A070215 LER 79-011/01T-0 on 790302 engineering review determined recertain containment isolation valves incapable of closing against LOCA pressure Caused by design oversight Future mod to expand "valve open" alarm to include seal low pressure COONEYM J Philadelphia Electric CO 79/03/29 tp
- 7906040034 RD 2-79-16/1P on 790411 engineering review of plant valve lineups indicated seismically qualified emergency sucwater eys connected to heat exchanger in nonseismically qualified sys Caused by personnel error ULLRICH, W T Philadeiphia Electric Co 79/04/12 2pp
- 7905270064 RD 2-79-24/10 control rod driveline return line outside containment support Seismic support calculations in response of IE Bulletin 79-04 indicate support for piping unsatisfactory
  ULRICH.W T Philadelphia Electric Co 79/05/17 2pp
- 7906040309 Forwards LER 79-023/04T-0 COONEY.M J Philadelphia Elactric Co 79/05/25 2pp
- --7906040316 LER 79-023/04T-0 on 790515 routine pH analysis of \*\*\*\*\*\*
  plant effluent identified pH of 5 8 which exceeded Toch
  Specs Caused by air blower failure which allowed dissolved
  ovgen to drop to 0 & aeration tank to become anaerobic
  COONEY, H J Philadelphia Electric Co 79/05/25 ip
- 7906070252 LER 79-019/03L-0 on 790501 during surveillance testing of normally open primaly containment isolation valves four oxygen analyzer sys isolation valves failed to close Gaused by binding of pistons in valve bodies Valve parts rebuilt COUNEY, M J Philadelphia Electric Co 79/05/30 ip
- 7906070303 LER 79-022/03L-0 on 790313 fire hose notiles were missing from two hose stations in turbine bldg Cause not noted Noziles replaced & wrench tightened to inhibit removal COUNEY, M J Philadelphia Electric Co 79/05/31 ip
- 7906080287 Forwards LER 79-024/017-0
  COUNEY, M J Philadelphia Electric Co 79/06/01 2pp
- --7906080289 LER 79-024/01T-0 on 790517 support for control rod drivent new return line outside containment does not meet selsmic requirements Seismically qualified pipe support designs completed Mods to designs scheduled to begin 790601 COUNEY.M J Philadelphia Electric Co 79/06/01 Ip
- 7906080270 LER 79-020/03L-0 on 790503 solution temp in standby liquid control sys found to be 2 F less than Tech Spec requirement for existing boron concentration Caused by incorrect acceptable temp controller setpoint range COUNEY, M J Philadelphia Electric Co 79/06/01 1p
- 7906110172 Forwards LER 79-025/017-0 COONEY, M. J. Philadelphia Electric Co. 79/06/04 2pp
- --7905110174 LER 79-025/01T-0 on 790518 E-2 diesel tripped causing half-scram b half-isolation on Unit 3 Caused by loss of control oil from diesel governor Cracked pipe fitting was COONEY, M J Philadelphia Electric Co 79/06/04 1p
- 7906200422 Forwards LER 79-026/01T-0 COUNEY, M J. Philadelphia Electric Co 79/06/08 2pp

## DOCKETED ITEMS

- ~-7906200425 LER 79-026/01T-0 on 790524 during startup offgas stack radiation monitors were inoperable for 9-h,dup to failure of operating sample pump Caused by broken belt Belt replaced GODNEY,M J Philadelphia Electric Co 79/06/08 ip
- 7906260283 LER 79-027/03L-0 on 790321 reactor water cleanup inboard isolation valve failed to automatically isolate in test Caused by misaligned limit switch on valve Switch adjusted & maint procedure strengthened COONEY, N. J. Philadelphia Electric Co. 79/06/20 1p
- 7906260253 LER 79-029/03L-0 on 790524 firewatch patrol was not conducted while fire detection sys was out of svc for const Caused by failure in communications Procedures changed COONEY, M. J. Philadelphia Electric Co. 79/06/22 ip
- 7906280116 Forwards LER 79-028/03L-0 CODNEY, M J Philadelphia Electric Co 79/06/22 2pp
- --7906280118 LER 79-028/03L-0 on 790324 redundant low level HPCI start signal from L6L-2-3-72C found inoperable Caused by human error Field willing & connection frowing were corrected & investigation of event is being performed by engineering GA COONEY.M J Philadelphia Electric Co 79/06/22 1p
- DOCKET 50-278 PEACH BOTTOM ATOMIC POWER STATION, UNIT 3
  F Security, medical, emergency & fire protection plans
- 7706260023 "Fire Protection in Operating Nuclear Power Stations,Peach Bottom Units 2 % 3 SER Review " HALL:R E , MACDOUGALL:E A Brookhaven National Laboratory 7706260023 77/04/06 4pp
- Q Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 GCINTG, U F Hearings Division 79/04/02 2pp
- --790210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 CHRISTENDURY.E Hearings Division 79703/26 34pp
- 7906180696 Motion for reconsideration of ALAB-540 & severence from consolidation established by ALAB-540 Admits issues not raised by any party & departs from "lead case" procedure previously adopted Certificate of Svc encl
  CONNER, T B Conner, Moore & Corber 79/05/02 15PP
- 7706210095 NRC motion for summary disposition re radon issue was in error, ALAB-540 consolidated only 5 of 16 cases Denies NRC motion re parties in other proceedings W/Certificate of Svc DUFLO, M C Atomic Safety and Licensing Appeal Panel 29/05/25
- 7906230107 Request by utils that ABLAB grant summary disposition of all issues in consolidated radon proceeding Utils seek decision as matter of lawing genuine issue as to matl facts
  BILBERG.J A. Shaw, Pittman, Potts, & Trowbridge VDIOHT.H H
  LeBoeuf, Lamb, Leiby & MacRae CONNER.T B Conner, Moore & Corber
  79/09/23 4pp
- --7906230110 Statement of mat! facts re radon proceedings for which there is no genuine issue to be heard Discusses alleged Deficiencies 1-7.9-18,20-24 & 26 Affidavit of H1 Onidman & supporting documentation enc!

  SILBERO.J A Shaw, Pittman, Potts, & Trowbridge VOIGHT, H. H LeBoevf, Lamb, Leiby & MacRae CONNER, T B Conner, Moore & Corber 79/05/25 36pp
- --7906230112 Supplements MI Goldman 790525 affidavit & utils 790409 memo re radon emissions & de minimus approach Discusses alleged Deficiencies 2,9,16 & 21 Beeks motion for summary disposition Certificate of Svc encl SILBERG, J. A. Shaw, Pittman, Potts, & Trowbridge VDIOHT,H H LeBower, Lamb, Leiby & MacRae GONNER,T B. Conner, Moore & Corber 79/05/25, 19pp
- P Operating license stage documents & correspondence
- 7906230074 Forwards Amends 52 % 52 to Licenses DPR-44 % DPR-56, respectively, % notice of issuance & availability. IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625). 79705703 2pp

- --7906250079 Amends 52 & 52 to Licenses DPR-44 & DPR-56, respectively, substituting two new conditions re thermal discharge IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/03/03 10pp
- --7906230083 Notice of Issuance & availability of Amends 52 % 52 to Licenses DPR-44 & DPR-56, respectively IPPOLITO,TA Operating Reactors Branch 3 (Pre 790625) 79/05/03 2pp
- 7906290665 Forwards Amends 53 to Licenses DPR-44 & DPR-56, safety evaluation & notice of issuance & availability IPPOLITO, T A Decrating Reactors Branch 3 (Pre 790625) 79/05/23 3pp
- --7906290670 Amends 53 to Licenses DPR-44 & DPR-56 IPPOLITO, T A Deprating Reactors Branch 3 (Pre 770625) 79/05/23 4pp
- --7906290677 Safety evaluation supporting Amends 53 to Licenses DPR-44 & DPR-56 B Operating Reactors Branch 3 (Pre 790625) 79/05/23 87pp
- --7906290483 Discusses safety evaluation rept review re facility fire protection Proposed mods represent significant increase in level of protection HALL,R E Brookhaven National Laboratory 79/04/06 3pp
- ---7906270700 Notice of issuance & availability of Amend 53 to Licenses DPR-44 & DPR-56 IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625) 79/05/23 2pp
- 7906260334 Forwards proposed insp program for feedwater noizles & mod program for control rod driveline return lines to be implemented during Fail 1979 refueling outage DALTROFF, S.L. Philadelphia Electric Co. 79/06/22 2pp
- --7906260341 Proposed insp program for feedwater noitles \* Philadelphia Electric Co DPE-21-579 79/05/25 LOpp
- Q Inspection reports. IE Bulletins & correspondence
- 7906110029 Forwards IE Bulletin 79-038, "Nuclear Incident at TMI-Suppl " No written response required GRIER.B H Region 1, Philadelphia. Office of the Director 79/04/23 ip
- 7906110026 Responds to IT Bulletin 79-07 re salsmir stress analysis of safety-related piping Plant did not use specified computer codes for seimic stress analysis
  DALTROFF, S L Philadelphia Electric Co 79/04/24 4pp
- 7906020241 Submits info in response to IE Buliet; methods used in seismic analysis of safety-rel program listing & program verification GALLAGHER, J W Philadelphia Electry

- 7906080102 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U "
  ORIER, B H Region 1. Philadelphia, Office of the Director 79/03/18 ip
- A Periodic operating reports & related correspondence
- 7906180530 "Post-Operational Rept 11 on Ecology of Conowingo Pohd" for Jul-Dec 1978 
  Philadelphia Electric Co 79/03/31 258pp
- 7906:50335 Forwards environ surveillance & special study program rept.
  "PBAPS-Praoperational Rept 11 on Ecology of Concuring Pond
  for July-Dec 1978," prepared by RMC-Ecological Div M/o encl
  MILLEEY.W 8 Philadelphia Electric Co 79/06/07 1p
- 7906140221 Forwards "Environ Radiation Monitoring Program" for 1978 Rept 36 & "Radiological Regional Environ Monitoring Program" for 1978.Rept 4 WILLSEY,W B Philadelphia Electric Co 79/06/08 ip
- --7906140228 "Environs Radiation Monitoring Program" for 1978, Rept 36, prepared by Interex Corp 4 Philadelphia Electric Co 79/05/31 116pp
- ~~7906140233 "Radiological Regional Environ Monitoring Program." 1978 Rept 14, prepared by Radiation Mgt Corp \* Philadelphia Electric Co 79/05/31 128pp
- 7906140455 Forwards "Thermal & Biological Monitoring Programs" Monthly Repts 67.68 & 49 for Jan.Feb & Mar 1979, respectively WILLSEY,W B Philadelphia Electric Co 79/06/08 ip
- --7906:40459 "Thermal & Biological Monitoring Programs," Monthly Rept 67. Jan 1979 \* Philadelphia Electric Co 79/06/08 2pp
- --7906140463 "Thermal & Biological Monitoring Programs," Monthly Rept 68, Feb 1979 \* Philadelphia Electric Co 79/06/08 2pp
- ~~7906140466 "Thermal & Biological Monitoring Programs," Monthly Rept 69.
  Mar 1979
  \* Philadelphia Electric Co 79/06/09 3ipp
- 7706140243 Forwards "Thermal & Biological Monitoring Programs," Monthly Rept 70.4pr 1979. WILLEEY, H B Philadelphia Electric Co 79/06/11 1p
- WILLSEY, W B Philadelphia Electric Co 79/06/11 1p
- --7906140247 "Thermal & Biological Monitoring Programs," Monthly Rept 70-Apr 1979 \* Philadelphia Electric Co 79/04/30 10pp
- 7904190329 Forwards monthly operating rept for May 1979 COONEY, M. J. Philadelphia Electric Co. 79/06/11 ip
- --7906190331 Monthly operating rept for May 1979 ALDEN: W. M., Philadelphia Electric Co., 79/06/10 10pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906040246 RO 2-78-38/IP on 780908 unconformed calculations show excessive accelerations on inboard reactor water cleanup systicolation valve Mo-15 during DBE Caused by use of erroneous acceleration rate on valve ULLRICH-W T Philadelphia Electric Co 78/09/II 2pp
- 7906040236 RO 1-78-38/IP on 780908 analysis by A/E on reactor water cleaning piping in drywell resulted in redution in acceleration valves. Add restraint will be installed on Unit 2 during present refueling outage.

  ULLRICH.W T Philadelphia Electric Co. 78/09/12 ip
- 7906040367 Forwards LER 78-038/01T-0 CODNEY,M J Philadelphia Electric Co 78/09/22 3pp.
- --7906040368 LER 78-038/01T-0 on 780908 one point on piping outhoard MO-12-15 had stress during DBE above code allowable Restreint to be added to code COUNEY. H J Philadelphia Electric Co. 78/09/22, ip
- 7906070370 RO 3-79-12/1P on 790326; gaseous release rate exceeded allowable Tech Specs limits for instantaneous release rate Gaused by lack of proper procedure lead to valving errors Procedures will be revised & valves clearly identified ULLRICH,W T. Philadelphia Electric Co 79/03/27. 2pp.

- 7906070210 Forwards LER 79-011/01T-0 COUNTY M J Philadelphia Electric Co 79/03/29 4pp
- --7906070215 LER 79-011/01T-0 on 790302 engineering review determined certain containment isolation valves incapable of closing against LOCA pressure Caused by design oversight future and to expand "valve open" alarm to include seal low pressure COONEY, M J Philadelphia Electric Co 79/03/29 Ip
- 79D6040034 RO 2-79-16/1P on 790411 engineering review of plant valve lineups indicated seismically qualified emergency svc water sys connected to heat exchanger in nonseismically qualified sys Caused by personnel error ULLRICH.W T Philadelphia Electric Co 79/04/12 2pp
- 7906270064 RO 2-79-24/10 control rod driveling return line outside containment support Beismic support calculations in response of IE Bulletin 79-04 indicate support for piping unsatisfactory ULRICH.W T Philadelphia Electric Go 79/05/17 2pp
- 7906080287 Forwards LER 79-024/01T-0 CODNEY,M J Philadelphia Electric Co 79/06/01 2pp
- ---79060B02B9 LER 79-024/01T-0 on 790317 support for control rod drive
  line return line outside containment does not meet seismic
  requirements Seismically qualified pipe support designs
  completed Mods to designs scheduled to Begin 790601
  COONEY, M. J. Philadelphia Electric Co. 79/06/01 lp
- 7906110172 Forwards LER 79-025/017-0 COUNEY, H J Philadelphia Electric Co 79/06/04 2pp
- --7906110174 LER 79-025/01T-0 on 790518 E-2 diesel tripped causing half-scram & half-isolation on Unit 3 Caused by loss of control oi) from diesel governor Cracked pipe fitting was replaced COUNEY,M J Philadelphia Electric Co 79/06/04 ip
- 7906200422 Forwards LER 79-026/01T-0 COUNEY.H J Philadalphia Electric Co 79/06/08 2pp
- --7906200425 LER 79-026/01T-0 on 790524 during startup offgas stact radiation monitors were inoperable for 9-h due to failure of operating sample pump Gaused by broken belt Belt replaced COUNEY, H J Philadelphia Electric Go. 79/06/09, ip
- 7906260272 LER 79-015/03L-0 on 790523 automatic depressurization sys A auto blowdown timer trip setting found I3-s less than Tech Spec min Caused by setpoint drift of time delay relay Relay readjusted tested & returned to evo CQONEY.M J Philadelphia Electric Co 79/06/20 ip
- 7906260294 LER 79-014/03L-0 on 790522 offsite source breaker 8U25 tripped on low air pressure Caused by short circuit in light socket & dirty contacts on voltage relay Relay contacts cleaned & socket removed pending replacement.

  CDONEY.M J Philadeiphia Electric Ca 79/06/20 ip

DOCKET 50-280 SURRY POWER STATION, UNIT 1

- Q. Adjudicatory correspondence
- 7906040415 Orders extension until 790515 for NRC to review 790201 denial of enforcement action CHILK, S. J. Office of the Secretary of the Commission 79/04/13
- 7906040434 Grants NRC extension until 790624, for review of 790201 denial of enforcement action CHILK, S. J. Office of the Secretary of the Commission 79/03/15
- H General correspondence
- 7905230047 Responds to 790313 ltr re shutdown of five nuclear power plants because of seismic concerns Beismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA, Plant review is being expedited DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/09 19
- --7906230050 Expresses concern re shutdown of five reactors for seisminerations Action essures energy crisis Plant overhaul is more appropriate during refueling shutdown. Benefits of nuclear power outweigh seismic risks BIMPSON, R. E. Affiliation Unknown, 79/03/15 2pp

- 7906210418 Responds to 790319 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation w/no threat to public health & safety DENTON, H R Office of Nuclear Reactor Regulation 79/05/16 2pp
- ~-7906210424 Comments on NRC capricious b cavalier acts Requests immediate reversal of unwise decision to shut down five plants Suggests more rational approach to improbable safety concerns in future HARCUS, G H Affiliation Unknown 79/03/19 2pp
- 7906270008 Responds to 790314 1tr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON:# R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7706270013 Comments on 770313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in region SHITM-B N Affiliation Unknown 77/03/14 ip
- 7906270020 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake iones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270028 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region HERRIMANIC P Affiliation Unknown 79703/21 2pp
- 7906270035 Responds to 790403 ltr re 790313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake cones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270042 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned FULLER, W R Affiliation Unknown 79/04/03 3pp
- 7906270053 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake tones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270056 Comments on 790313 orders shutting down five northeastorn US nuclear power plants Economic consequences for Maine, as well as power shortages, override slim prospect of earthquakes Plants should be reopened SULLIVAN, J F Affiliation Unknown 79/03/21 1p
- 7906270060 Responds to 790327 itr re 790313 orders shutting down fave nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270066 Comments on 790313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its antinuclear attitudes
  GUIMBY.L Affiliation Unknown 79/03/27 ip
- /906270069 Responds to 790323 ltr re 790313 orders shutting down five nuclear powel plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake ignes encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270073 Comments on 790313 olders shutting down five northeastern UB nuclear power plants Plants should be reopened immediately, due to economic prospects of plant closings SAUNDERB, J A Affillation Unknown 79/03/23 ip
- 7906270076 Responds to 790322 ltr to President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake Zones encl DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7905270080 Responds to 790328 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R. Office of Nuclear Reactor Regulation 79/05/17 Spp

- --7906270082 Comments on 790313 orders shutting down five northeastern US nuclear power plants Chance of earthquake is too low to risk economic upheavel caused by closing of plants LEMB.P F Affiliation Unknown 79703/28 ip
- 7906270007 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending reaview of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake zones enci
- --7906270091 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MCGONAGLE,W F Affiliation Unknown 79/03/15 1p
- 7906270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 Spp
- --7906270099 Comments on 790313 olders shutting down five northeastein US nuclear power plants Decision was extremely ill-conceived MARPLE.W W Affiliation Unknown 79/03/17 Ip
- 7906270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear gower plants pending review of analysis techniques used in seismic desingn of safety-related piping Maps of northeastern US earthquare zones enci DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270114 Comments on 790313 orders shutting down five northeastern Us nuclear power plants Decision was economically ill-conceived WODDMAN.N P Affiliation Unknown 79/03/14 1p
- 7906270119 Responds to 790322 Itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake iones encl
  DENION.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7706270122 Comments on 770313 orders shutting down five northeastern US nuclear power plants Dacision was economically ill-conceived & represents flagrant federal govt overprotection through regulatory process
  BEANE, V E Affiliation Unknown 77/03/22 ip
- 7905270124 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquare zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270127 Comments on 790313 orders shutting down five northeastern UF nuclear power plants Becision was economically ill-conceived Affiliation Unknown 79/03/20 1p
- 7906270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7905270133 Comments on 790313 orders shutting down five northeastern U nuclear power plants Decision was poorly timed & economically (il-conceived KOVLOVRIS, G E Affiliation Unknown 79/03/17 ip
- 7906270143 Responds to 790313 htr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --790627014& Comments on 790313 orders shutting down five northeastern U nuclear power plants Decision was economically ill-conceived Requests date of last recorded earthquakes COFFIN.W S Affiliation Unknown 79/03/13 ip
- 7906270151 Responds to 790322 Itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-reslated piping Maps of northeastern US earthquake Iones enci DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pg
- ---7906270155 Comments on 790313 orders shutting down five northeastern t nuclear power plants Decision was ill-conceived, considering current energy crisis KRETZSCHMAR, W Affiliation Unknown 79/03/22 ip.

- 7906270263 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones enci
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270264 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived DEHEULLERE H Affiliation Unknown 79/03/23 4pp
- 7906270265 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US eartbquale zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270266 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was overprotective act KATZENSTEIN.R L Affiliation Unknown 79/03/15 2pp
- 7906270267 Responds to 790325 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquafe zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270268 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived ELLIS:R C Affiliation Uninown 79/03/25 lp
- 7906210433 Responds to 790314 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited # disciplined manner, to return plants to operation w/no threat to public health to safety DENTON, HR Office of Nuclear Reactor Regulation 79/05/21 5pp
- --7706210441 States that NRC overreacted in closing five nuclear plants Comments on impact of NRC action W/770315 forwarding ltr to JM Hendrie re shutdown of plants HENRY-T P Affiliation Unknown 77/03/14 2pp
- 7906270821 Responds to telcon re NRC order to shut down five nuclear plants because of seismic concerns Analysis techniques used in plant design were inappropriate Piping sys failure could cause LOCA
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 tp
- J. Insurance & indemnity information
- 7906120324 Endarsement 41 to NELIA Policy MF-57 OERAB.T Mutual Atomic Energy Liab(11ty Underwriters 79/05/10
- 7906120331 Endorsement 42 to MAELU Policy MF-57 OEROS.T Mutual Atomic Energy Liability Underwriters 79/05/10
- 7906070306 Requests replacement copy of signed originals of Amend 8 to Indemnity Agreement 8-45, which will be executed & returned to NRC as requested STALLINGS.C M Virginia Electric & Power Co 79/05/31 ip
- P Operating license stage documents & correspondence
- 7906010279 FDIA request for all records & communications re shutdown of five nuclear plants
  CASSAN, V J Power Authority State of New York 79/03/16 2pp
- 7906:30026 Delineates criterion to develop plant-specific info packages on site visits RUSSELL.W T. Office of Nuclear Reactor Regulation 79/04/11. 2pp
- 7905020125 Forwards 790405 1tr from J Allen of North Anna Environ Coalition requesting revocation of OLs Ltr is being treated as request for action per 100FR2 205 Also forwards FR notice. Ltr not enci DENTON: H R Office of Nuclear Reactor Regulation 79/05/04 lp.
- ---790A0R0190 Notice of 790405 North Anna Environ Coalition request for NRC to revoke ULs due to alleged nonconformance of estimated peak fuel cladding temps w/stds of 10CFR50 46(6)
  DENTON: H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 790625033! Forwards Amends 49 & 48 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability, SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/09 3pp

- --7908250332 Amends 49 & 48 to Licanses DPR-32 & DPR-37, respectively, revising Teck Spec limits for total nuclear peaking factor
  VOLLMER.R H Assistant Director for Bystems Engineering 79/05/09 18pp
- --7906250333 Safety evaluation supporting Amends 49 % 4B to Litenses DPR-32 & DPR-37, respectively a Assistant Director for Systems Engineering 79/05/09 App
- 7906260110 Summary of 790503 meeting w/util in BethesdarMD re-mod & testing for emergency buses NEIOHBORS, J D Operating Reactors Branch 1 (Pre 790625) 79/05/09 2pp
- 7906250194 Summary of 790503 meeting w/util in Bethesda,MD re proposal to start up facility while pipe stress analyses are being completed MEIGHBORS,D Decrating Reactors Branch 1 (Pre 790625) 79/05/11
- 7906260107 Summary of 790503 meeting w/util re steam generator & reactor coolant pump supports insps SNAIDER, R P Operating Reactors Branch 1 (Pre 790625) 79/05/11 4pp
- 7906230091 Forwards memos discussing B McDermott concerns re shutdown of B&W plants
  ROSS D F Division of Project Management 79/09/17 ip
- --7906250101 Requests assessment of safety of continued operation of \$% reactor based on performance of relief & safety valves, performance of HPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation ROS6.D Division of Project Management 79/05/08 2pp
- --7906230106 Discusses safety assessment of D&W plants in response to 790508 memo B&W plants should be shut down until reanalysis has been completed re-core cooling in natural circulation, small break LOCAs & ECCS
  HCDERMOTT.R J Quality Assurance Branch 79/05/14 70p
- --7906230112 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown HAABS, W P Quality Assurance Branch 79/05/15 2pp
- --7906250114 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown BKDYHOLT.D J Assistant Director for Quality Assurance & Operations 79/05/15 2pp
- 7906290709 Lists subj of 790514 & 18 info requests re amplified response spectra using soil structure interaction Response should be completed by 790523
  STELLO.V Division of Operating Reactors 79/05/18 Spp
- 7906010273 Denies FOIA request for Oibbon 790314 & Thompson 790315 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants Info withheld (ref FOIA Exemption 5) FELTON, J M Division of Rules and Records 79/05/21 4pp
- 7906290559 Notification of 790524 meeting w/util in Bethesda.MD to discuss pipe stress analysis for facility NEIOMBORS.J D Operating Reactors Branch 1 (Pre 790625) 79/05/21 2pp
- 7906290642 Discusses containment depressurization LAINAS.G Plant Systems Branch 79/05/22 3pp
- 7906250039 Discusses position re use of soil structure interaction for seismic pipestress analyses being performed. Approves methodology, provided that seismic stresses calculated are increased by factor of 1 5
  EIBENHUT, D. 

  Assistant Director for Bystems Engineering 79/03/25

## DOCKETED ITEMS

- 7906130224 Forwards "Verification of NUPIPE-II for Analysis of Nuclear Piping Bys NSC" & "Quadrex-NUPIPE Response Spectrum Analysis Mathods & Computer Listing," in response to NRC 790402 ltr Requests withholding Guadrex (ref 10CFR2 790)
  STALLINGS, C M Virginia Electric & Power Co 79/05/30 Bpp
- 790&050323 Discusses 770110 rept "GA Program, Operations Phase "
  Requests exception from ANSI N45 2 4 & N45 2 8 paragraphs re
  calibr control & equipment test Discusses proposed
  alternative
  BAUM, E A Virginia Electric & Power Co 79/05/31 2pp
- 7906050363 Forwards results of steam generator & preventative plugging program Unit operation can be safely extended for seven months, per util 790406 request BTALLINGS, C M Virginia Electric & Power Co 79/05/31 ip
- ---7906050367 Steam generator tube insp & preventative plugging program
  \* Virginia Electric & Power Co 79/04/30 16pp
- 7906070293 Forwards "Rept on Reanalysis of safety-related Piping Sys, Unit 1," in response to NRC 790313 order to show cause Piping sys only slightly impacted by reanalysis Requests immediate startup of Unit 1 SPENCER, W C Virginia Electric & Power Co 79/06/05 App
- --7906070298 "Rept on Reanalysis of Safety-Related Piping Sys.Unit 1 "
  \* Virginia Electric & Power Co 79/06/05 100pp
- 7906110194 Forwards "Soil Structure Interaction Rept "
  SPENCER.W C Virginia Electric & Power Co 79/06/08 1p
- ---7906110197 "Soil Structure Interacction Rept "
  \* Virginia Electric & Power Co 79/06/08 200pp
- 7906130332 Forwards addition to 790605 rept on reanalysis of safety-realted piping sys Appreciable broak location changes are not antecipated SPENCER.W C Virginia Electric & Power Co 79/06/08 18pp
- 7906150160 Provides addl info to suppl 790605 rept re reanelysis of safety-related piping sys Details stress problems which require hardware mod Mod to be completed by 790620 BPENCER.W C Virginsa Electric & Power Co 79/06/12 2pp
- 7906200102 Submits response to 790613 request for add1 info re pipe stress reanalysis effort, including functional description of support types, schedule for info & reactor coolant pressure boundary support info EPENCER.W C Virginia Electric & Power Co 79/06/15 Upp
- 7906210210 Bubmits add1 info re facility emergency power sys electrical load analysis.sys mod 5 testing procedures Forwards "Add1 Info for 480 Volt Emergency Power Bys Mod" 5 "Electrical Load Analysis for 480 Volt Emergency Power Bys "
  BTALLINOB.C M Virginia Electric & Fower Co 79/06/18 2ipp
- ---7906210214 "Addl Info for 480 Volt Emergency Power Sys Mod "

  \* Virginia Electric % Power Co 79/06/08 21pp
- ---7906210216 "Electrical Load Analysis for 480 Volt Emergency Power Sys "

  Virginia Electric & Power Co 79/05/17 42pp
- 7906220260 Submits updated Table 1 to 790615 submission delineating status of supports associated w/reactor coolant pressure boundary Discusses add1 mods presently required SPENCER,W C Virginia Electric & Power Co 79/06/19 3pp
- 7906250311 Forwards add1 info re PWR feedwater lines in response to NRC 790825 request Util 771202 ltr & NRC 780607 ltr re feedwater lines encl STALLINOS.C M Virginia Electric & Power Co 79/06/20 6pp
- --7906250347 Discusses status of util study of plant feedwater sys water hammer potential BTALLINGB.C M Virginia Electric & Power Co 77/12/02 5pp
- --7906250351 Accepts util provisions for minimizing possibility of water hammer events due to rapid steam condensation in feedwater sys.

  BCHMENGER.A. Operating Reactors Branch 1 (Pre 790625)
  78706/07 7pp
- 7906290327 Clarifies causes for hardware mods identified in earlier submittals of 790605,12 % 19 in response to NRC 790621-22 review of pipe stress reanalysis SPENCER, M G Virginia Electric & Power Co 79/06/25. 6pp.

- Q Inspection reports, IE Bulletins & correspondence
- 7906070072 Forwards IE Insp Repts 50~280/79~ii ½ 30~281/79~i3 on 790226~0302 No noncompliance noted SUTHERLAND.J T Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/03/29 2pp
- ---7906070076 IE insp Repts 50-280/79-11 % 50-281/79-13 on 790226-0302 noncompliance noted Major areas inspected respiratory protection ALARA program & training GIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Safei Branch 79/03/29 7pp
- 7906180673 Forwards IE Insp Repts 50-280(79-12 % 50-281/79-15 on 790306-09 No noncompliance noted SUTHERLAND, J T Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/03/29 2pp
- ---7906180680 IE Insp Repts 50-280/79-12 & 50-281/79-15 on 790306-09 No noncompliance noted Major areas inspected occupational exposure areas special dosimetry, use of temporary containments & training EMALD.5 C , WRAY, J R Region 2. Atlanta, Office of the Director GIBSON, A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 6pp
- 7906110068 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/05/11 ip
- 790620013B Ack receipt of 790420 ltm informing NRC of steps taken to correct violations noted in IE insp Repts 50-280/79-09 % 50-281/79-10
  BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 lp
- --7906200143 Responds to NRC 790328 ltr re violations noted in IE Insp Repts 50-280/79-09 & 50-281/79-10 Corrective actions loose containment screen installed all radiation area barricades locked & lead removed from RRR sys STALLINGS.C M Virginia Electric & Power Co 79/04/20 7pp
- ---7906200146 Forwards IE insp Repts 50-280/79-09 \$ 50-281/79-10 on 790212-16 \$ notice of violation O'REILLY.J P Region 2. Atlanta, Office of the Director 79/03/28 2pp
- --7906200172 Notice of violation from insp on 790212-16
  \* Region 2. Atlanta, Office of the Director 79/03/28 3pg
- ---7904200160 IE Insp Repts 50-280/79-09 % 50-281/79-10 on 790212-14 Noncompliance noted containment sump trash screen not installed, failure to post %/or barricade high radiation areas & failure to label contaminated waste drums EWALDS C , COLLINB,D M Region 2, Atlanta, Office of the Director OIBSON:AF Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/20 tipp
- 7906190191 Ack receipt of 790504 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-15 & 50-281/79-21 LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Suppor-Branch 79/05/17 ip
- ---7906190194 Responds to NRC 790406 ltr re violations noted in [E Ins, Repts 50-280/79-19 & 50-281/79-21 Corrective actions annunciation procedure changed operators instructed to report events & fire watch posted STALLINOS.C.M Virginia Electric & Power Co. 79/05/04 3pp
- --7706170178 Forwards IE Insp Repts 30-280/79-15 & 30-281/79-21 on 770205-0316 & notice of violation. LENIS.R C Region 2: Atlanta, Reactor Operations Nuclear Support Branch 77/04/06 2pp
- ---7906190208 Notice of violation from insp on 790205-0316
  \* Region 2, Atlanta, Office of the Director. 79/04/06 ip.
- --7906190213 IE Insp Repts 50-280/79-15 & 50-281/79-21 on 790205-0316
  Noncompliance noted failure to follow annunciator procedure
  & failure to establish fire watch on nonfunctional
  electric penetration fire barriers
  BURKE.D J Region 2. Atlanta, Office of the Director,
  CANTERLL,F B Region 2. Atlanta, Reactor Operations Nuclear
  Bupport Branch 79/04/01 5pp
- 7906060124 Responds to NRC 790510 itr re violations noted in IE Insp Repts 50-280/79-18 & 50-281/79-26 Corrective actions tents inspected & acceptance label affixed & copy of procedure HP-BGRP-10 placed in reading file BTALLINOS. C. M. Virginia Electric & Power Co 79/05/31 '4pp

- 7906290537 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-09 & 50-281/79-09 SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/07 ip
- --7906290552 Responds to NRC 790515 ltr re violations noted in IE Imsp Repts 50-280/79-09 & 50-281/79-09 Corrective actions labeling of containers of radioactive matl STALLINGS.C M Virginia Electric & Power Co 79/05/29 2pp
- 7906180536 Responds to IE Bulletin 79-01 Forwards "Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Environ Gualification Requirements " STALLINOS.C M Virginia Electric & Power Co 79/06/14 1p
- --7706180538 "Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Environ Gualification Requirements "Environmentally unqualified valves have been or will be replaced \* Virginia Electric & Power Co 77/06/14 2pp
- 7906270121 Responds to IE Bulletin 79-01. "Environ Gualification of Class IE Equipment" Suspected solenoid valves will be upgraded or replaced as soon as possible STALLINOS.C M Virginia Electric & Power Co 79/06/25 25pp
- R Periodic operating reports & related correspondence
- 7906180517 Forwards monthly operating rept for May 1979 STALLINGS.C M Virginia Electric & Power Co 79/06/13 tp
- --7906180520 Monthly operating rept for May 1979
  COSTELLO.D J Vinginia Electric & Power Co 79/06/04 40pp
- S Reportable occurrences. LERs & related correspondence
- 7906030309 Forwards LER 79-019/03L-0 STALLINGS.C M Virginia Electric & Power Co 79/05/31 tp
- --7906050312 LER 79-019/03L-0 on 790510 while securing purging operations, valve MOV-100D did not close Caused by bearing failure w/resultant gear malfunction Parts replaced & valve returned to svc STEMART: W L Virginia Electric & Power Ca 79/06/01 2pp
- 7906190399 RO on 790606 abnormal degradation of cable insulation in emergency power sys battery charges Cause unknown but manufacturer will be contacted STEWART. H. Virginia Electric & Power Co 79/06/06 Lp
- 7906200398 Forwards LER 79-020/017-0 STALLINOS,C M Virginia Electric & Power Co 79/06/18 ip
- ---7706200405 LER 79-020/01T-0 on 770606 abnormal degradation of cable insulation on emergency power sys battery charger discovered at cold shutdown Caused by constant high pressure environ Cable will be replaced w/cables of higher tolerance STEWART, W L Virginia Electric & Power Co 77/06/18 2pp.
- U Congressional/Executive Correspondence
- 7906110367 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific consideration for seismic events HENDRIE: J M Commission 79/05/21 2pp
- --7906110378 Ack receipt of VA congressional delegation 790319 itr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for satismic events HENORIE.J M. Commission 79/05/21 2pp
- --7906110380 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities. Steps have been taken re review of pipe stress reanalyses. Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906:10:382 Ack receipt of VA congressional delegation 7903:9 itr re shutdown of facilities Steps have been taken re review of pipe stress rannalyses. Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp

- --79061103B5 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selmic events HENDRIE: J M Commission 79/05/21 2pp
- --7906110387 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110390 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE-J M Commission 79/05/21 2pp
- --7906110394 Ack receipt of VA congressional delegation 790319 ltrite shutdown of facilities Steps have been taken re-review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J.M. Commission 79/05/21 2pp HENDRIE, J M
- --7906110397 Ack receipt of VA congressional delegation 790319 ltm re shutdown of facilities Steps have been taken re review of pipe atress reanalyses Discusses site-specific considerations for seismic events HENDRIE: J M Commission 79/05/21 2pp
- --7906110400 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reamalyses Discusses site-specific considerations for seismic events KENDRIE, J K Commission 79/05/21 2pp
- --7906110400 Forwards draft of proposed responses to 790319 itr from VA congressional delegates re pipe stress analysis at facility DENTON, H.R. Office of Nuclear Reactor Regulation 79/05/01 \$2
- --7906110411 Requests expedited review of piping stress reanalyses.
  Independent from review of other three plants shut down for
  seismic-related issues
  BUTLER, C H. DANIEL, R W. HARRIS, H E. House of Rep. 79/93/19

# DOCKET 50-281 SURRY POWER STATION, UNIT 2

- G Adjudicatory correspondence
- 7906040415 Orders extension until 790315, for NRC to review 790201 denial of enforcement action CHILK.S J. Office of the Secretary of the Commission 79/04/13
- 7906040434 Grants NRC extension, until 790624, for review of 790201 denial of enforcement action CHILK, S.J. Office of the Secretary of the Commission 79/05/15
- H General correspondence
- 7906230047 Responds to 790313 ltr re shutdown of five nuclear youer plants because of seismic concerns Beismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA Plant review is being expedited
  DENTON-HR Office of Nuclear Reactor Regulation 79/05/09 1p
- ---7906230050 Expresses concern re shutdown of five reactors for seism reasons Action assures energy crisis Plant overhaul is more appropriete during refueling shutdown Benefits of nuclear power outweigh seismic risks
  SIMPSON, R E Affiliation Unknown 79/03/15 2pp
- 790621041B Responds to 790319 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited D disciplined manner to return plants to operation w/no threat to public health b safety DENTON, H R, Office of Nuclear Reactor Regulation 79/05/16 2pp
- --790b210424 Comments on NRC capricious & cavalier acts Requests immediate reversal of unwise decision to shut down five plants Suggests more rational approach to improbable safety concerns in future
  MARCUS.O H Affiliation Unknown 79/03/19 2pp

- 7906270008 Responds to 790314 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270013 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in region SMITH.B N Affiliation Unknown 79703/14 1p
- 7906270020 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270020 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region HERRIMAN.C P Affiliation Unknown 79/03/31 2pp
- 7906270035 Responds to 790403 ltr re 790313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquate zones encl
  DENYON.H R Office of Nuclear Reactor Regulation 77/05/17 3pp
- --7906270042 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned FULLER.W R Affiliation Unknown 79704703 3pp
- 7908270053 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake idnes encl
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270036 Comments on 790313 orders shutting down five northeastern US nuclear power plants Economic consequences for Mainer as well as power shortages, override slim prospect of carthquakes Plants should be reopened GULLIVAN. J F Affiliation Unknown 79/03/21 1p
- 7906270060 Responds to 790327 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl

  BENTON-H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270066 Comments on 790313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its antinuclear attitudes GUJHBY, L Affiliation Unknown 79/03/27 ip
- 7906270059 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7905270073 Comments on 770313 orders shutting down five northeastern US nuclear power plants Plants should be reopened immediately, due to economic prospects of plant closings SAUNDERG. J. A. Affiliation Unknown 79703/23 ip
- 7906270076 Responds to 790322 ltr to President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl. DENTON. H R Office of Nuclear Reactor Regulation 79/05/17 Spp
- 7906270080 Responds to 790328 ltr re 790313 orders shutting down five nuclear gower plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquaks zones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7904270082 Comments on 790313 orders shutting down five northeastern US nuclear power plants Chance of earthquake is too low to risk economic upheaval caused by closing of plants
  LEMIS.P F Affiliation Unknown 79/03/28 ip
- 7906270087 Responds to 790315/ltr re 790313 orders shutting down five nuclear power plants pending reaview of analysis techniques used in seismic desing of eafsty-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R. Office of Nuclear Reactor Regulation 79/05/17 3pp

- ---7906270091 Comments on 790313 orders shutting down five northeastern US nuclear power plants, Decision was extremely fil-conceived MCGONAGLE, W.F. Affiliation Unknown 79/03/15 lp
- 7906270095 Responds to 790317 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270099 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MARPLE, W.W. Affiliation Unknown 79/03/17 ip
- 7906270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in selsmic desingn of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 Spp
- 7906270119 Responds to 790322 ltr re 790313 orders shutting down five nuclear power glants pending review of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquate zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7706270124 Responds to 790324 1tr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeestern US earthquake zones encl
  DENTON; HR Office of Nuclear Reactor Regulation 79705/17 App
- 7906270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending roview of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON:# R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270135 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ill-conceived KOVLOVRIS.O E Affiliation Unknown 79/03/17 ip
- 7906270143 Responds to 790313 ltr re 790313 orders shutting down five nuclear gower plants pending review of analysis techniques used in selsmic design of safety-related piping Maps of northeastern US carthquake zones encl.

  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7908270151 Responds to 790322 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in selsmic design of safety-related piping Maps of northeastern US earthquake zones enci
- --7906270155 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-conceived.considering current energy crisis KRETZECHMAR.W Affiliation Unknown 79/03/22 is

- --7906270268 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived
  - Affiliation Unknown 79/03/25
- 7906210433 Responds to 790314 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to raview situation in expedited & disciplined manner to return plants to operation w/no threat to public health & safety DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 5pg 79/05/21 500
- ~~7905210441 States that NRC overreacted in closing five nuclear plants Comments on impact of NRC action H/790315 forwarding ltr to JM Hendric re shutdown of plants HENRY,T P Affiliation Unknown 79/03/14 2pp
- 7905290821 Responds to telcon re NRC order to shut down five nuclear plants because of seismic concerns Analysis techniques used in plant design were inappropriate Piping sys failure could DENTON, H R Office of Nuclear Reactor Regulation 79/05/24 1p
- J Insurance & indemnity information
- 7906120324 Endorsement 41 to NELIA Policy MF-57
  GERAS.T Mutual Atomic Energy Liability Underwriters 79/05/10
- 7906120331 Endorsement 42 to MAELU Policy MF-57 GEROS. T Mutual Atomic Energy Liability Underwriters 79/05/10
- 7906070306 Requests replacement copy of signed originals of Amend 8 to Indemnity Agreement 8-45, which will be executed & returned to NRC as requested STALLINGS, C M Viro Virginia Electric & Power Co 79/05/31 1p
- P Operating license stage documents & correspondence
- 79040(0279 FDIA request for all records & communications re shutdown of five nuclear plants GASSAN, V J Power Authority State of New York 79/03/16 2pp
- 7905:30026 Delineates criterion to develop plant-specific info packages on site visits RUSSELL.W T Office of Nuclear Reactor Regulation 79/04/11 2pp
- 7906020125 Forwards 790405 ltr from J Allen of North Anna Environ Goalition requesting revocation of OLs Ltr is being treated as request for action per 10CFR2 206 Also forwards FR notice Ltr not encl DENTON, H.R. Office of Nuclear Reactor Regulation 79/05/04 ip
- --7904020130 Notice of 790405 North Anna Environ Coalition request for NRC to revoke OLs due to alleged nonconformance of estimated peak fuel cladding temps w/stds of 10CFR50 46(b)
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 7906250331 Forwards Amends 49 & 48 to Licenses DPR-32 & DPR-37, respectively, safety evaluation & notice of issuance & availability Operating Reactors Branch I (Pre 790625) 79/05/09 Зрр
- ---7906250332 Amends 49 & 48 to Licenses DPR-32 & DPR-37, respectively, revising Tech Spec limits for total nuclear peaking factor VOLLMER.R H Assistant Director for Systems Engineering 79/05/09 18pp
- --7904250333 Safety evaluation supporting Amends 49 % 48 to Licenses DPR-32 & DPR-37, respectively \* Assistant Director for Systems Engineering 79/05/09 6pp
- --7906250334 Notice of issuance & availability of Amends 49 & 48 to Licenses DPR-32 & DPR-37, respectively SCHMENCER.A Operating Reactors Branch 1 (Pre 790625) 79/05/09 3pp.
- 7906260107 Summary of 790503 meeting w/util re steam generator b reactor coolant pump supports ineps. SNAIDER, R. P Operating Reactors Branch 1 (Pre 790625) 79/05/11

- 7906250091 Forwards memos discussing B McDermott concerns re shutdown of B&W plants
  ROSS.D F Division of Project Management 79/05/17 10
- --7906250101 Requests assessment of safety of continued operation of Bly reactor based on performance of relief & safety valves, performance of HPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation ROSS, D Division of Project Management 79/05/08 2pp
- --7906250106 Discusses safety assessment of B&W plants in response to 790508 memo B&W plants should be shut down until reanalysis has been completed re core coming in natural circulation, small break LOCAS & ECCS

  HCDERMOTT.R J Quality Assurance Branch 79/05/14 7pp
- --7906250112 Discusses B McDermott 790514 memo re safaty of B6H plants Disagrees w/B McDermott position favoring shutdown HAASS,W P Quality Assurance Branch 79/05/15 2pp
- ---7906250114 Discusses B McDermott 790514 memo re safety of BbH plants Disagrees w/B McDermott position favoring shutdown SKDVHDLT-D J Assistant Director for Guality Assurance & Operations 79/05/15 2pp
- 7906110446 Notification of 790522 meeting w/util & S&W to discuss pipe stress analysis & review soil structure interation analyses
  NEIOHBORS, J D Operating Reactors Branch 1 (Pre 790625) 79/05/18
- 7906290709 Lists subj of 790514 & 18 info requests re amplified response spectra using soil structure interaction Response should be completed by 790523

  STELLO, V Division of Operating Reactors 79/05/18 3pp
- 7906010273 Denies FOIA request for Gibbon 790314 & Thompson 790315 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants Info withheld (ref FOIA Exemption 5)
  FELYON, J M Division of Rules and Records 79/05/21 4pp
- 7906290642 Discusses containment depressuritation LAINAS,O Plant Systems Branch 79/05/22
- 7906230039 Discusses position re use of soil structure interaction for seismic pipestress analyses being performed Approves methodology, provided that seismic stresses calculated are increased by factor of 1.5 EISENHUT.D G. Assistant Director for Systems Engineering 79/05/25
- 7905130224 Forwards "Verification of NUPIPE-II for Analysis of Nuclear Piping Sys NSC" > "Quadrex-NUPIPE Response Spectrum Analysis Methods > Computer Listing." in response to NRC 790402 ltr Requests withholding Quadrex (ref 10CFR2 790) STALLINGS.C M Virginia Electric > Power Co 79/05/30 8pp
- 7706050318 Requests amend to QL in form of proposed Tech Spec Change 78 Forwards required LOCA-ECCS analysis results supporting full-rated power operation after replacement of steam generators STALLINGS.C M Virginia Electric & Power Co 79/05/31 46pp
- 7706050323 Discusses 770110 rept "GA Program, Operations Phase 'Requests exception from ANSI N45 2 4 % N45 2 8 paragraphs recalibr control & equipment test Discusses proposed alternative
  BAUK, E A Virginia Electric & Power Co 77/05/31 2pp
- 7906070295 Forwards "Rept on Reanalysis of safety-related Piping Sys.
  Unit 1." in response to NRC 790313 order to show cause
  Piping sys only slightly impacted by reanalysis Requests
  immediate startup of Unit 1
  GPENCER.W C Virginia Electric & Power Co 79/06/05 4pp Virginia Electric & Power Co 79/06/05 4pp
- --7706070298 "Rept on Reanalysis of Safety-Related Piping Sys,Unit 1 "
   Virginia Electric & Power Co 79/06/05 100pp
- 7906:10194 Forwards "Soil Structure Interaction Rept SPENCER, W C Virginia Electric & Power Co 79/06 79/06/08 1p
- --7906110197 "Soil Structure Interacction Rept "
  \* Virginia Electric & Power Co 79/06/08 79/06/08 200pp
- 7906130352 Forwards add1 info to 790605 rept on reanalysis of safety-realted piping sys Appreciable break location changes are not antecipated BPENCER, W. C. Virginia Electric & Power Co. 79/06/08 18pp

- 79G6150160 Provides add1 info to suppl 790605 rept re reanalysis of nafety-related piping sys Details stress problems which require hardware mod Mod to be completed by 790620 SPENCER.W C Virginia Electric & Power Co 79/06/12 2pp
- 7906200102 Submits response to 790613 request for addl info re pipe stress reanalysis effort including functional description of support types schedule for info % reactor coolant pressure boundary support info SPENCER. W C Virginia Electric & Power Go 79/06/15 Bpp
- 7906210210 Submits add1 info re facility emergency power sys electrical load analysis, sys mod & testing procedures Forwards "Add1 info for 480 Volt Emergency Power Sys Mod" & "Electrical toad Analysis for 480 Volt Emergency Power Sys "
  STALLINGS, C M Virginia Electric & Power Co 79/06/18 21pp
- --7906210214 "Addi Info for 480 Volt Emergency Power Sys Mad "
   Virginia Electric & Power Co 79/06/08 21pp
- --79062(0216 "Electrical Load Analysis for 480 Volt Emergency Power Sys "

  \* Virginia Electric & Power Co 79/05/17 42pp
- 7906220268 Supmits updated Table 1 to 790615 submission delineating status of supports associated w/reactor coolant pressure boundary Discusses add mods presently required SPENCER,W C Virginia Electric & Power Co 79/06/19 App
- 79062503i1 Forwards add1 info re PHR feedwater lines, in response to NRC 790525 request Util 771202 ltr & NRC 780607 ltr re feedwater lines encl BTALLINGB.C M Virginia Electric & Power Co 79/06/20 6pp
- •
- --7706250347 Discusses status of util study of plant feedwater sym water hammer potential STALLINGS.C K Virginia Electric & Power Co 77/12/02 5pp
- --7906250351 Accepts util provisions for minimizing possibility of water hammer events due to rapid steam condensation in feedwater sys SCRWENCER.A Operating Reactors Branch 1 (Pre 790625) 78/06/07 7pp
- 7906290327 Clarifies causes for hardware mods identified in earlier submittals of 790605.12 & 19 in response to NRC 790621-22 review of pipe stress reanalysis EPENCER.N C Virginia Electric & Power Co 79/06/25 6pp
- Q Inspection reports, IE Bullatins & correspondence
- 7906070072 Forwards IE Insp Repts 50-280/79-11 % 50-281/79-13 on 790226-0302 No noncompliance noted BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- ---7906070076 IE Insp Repts 30-280/79-11 & 30-281/79-13 on 790226-0302 No noncompliance noted Major areas inspected respiratory protection.ALARA program & training GIBSON.A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 7pp
- 7706180673 Forwards IE Insp Repts 50-280/79-12 & 50-281/79-15 on 790306-09 No noncompliance noted SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Eafety Branch 79/03/29 2pp
- --7906180680 IE Insp Repts S0-280/79-12 & S0-281/79-15 on 790306-09 No noncompliance noted Major areas inspected occupational exposure areas, special dosimetry, use of temporary containments & training EWALD, S C , WRAY, J R Region 2, Atlanta, Office of the Director OIBSON, A F Region 2, Atlanta, Fuel Facility & Materials Gafety Branch 79/03/29 App
- 7906200609 Farwards IE Insp Rept 50-281/79-19 on 790313-16 No nancompliance noted BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 79/04/09 2pp
- --7906200617 IE insp Rept 50-281/79-19 on 790313-16 No noncompliance noted Major areas inspected radiological controls & radiation dosimetry associated w/steam generator replacement project

  JENKINS, G. P. JACKSON, L. L. Region 2, Atlanta, Office of the Director OIBSON, A.F. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/09 4pp

- 7906070118 Forwards IE Insp Rept 50-281/79-18 on 790313-16 No noncompliance noted MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/04/10 2pp
- --7906070121 IE Insp Rept 50-281/79-18 on 790313-16 No noncompliance noted Major areas inspected steam generator repair procedures work activities, records & general containment work activities BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch ANO, W P Region 2, Atlanta, Dffice of the Director 79/04/10 4pp
- 7906210402 Forwwards IE Insp Rept 50-281/79-17 on 790313-16 No noncompliance noted HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906210409 IE Inp Rept 50-281/79-17 on 790313-16 No noncompliance noted Major areas inspected const status.QA audits.licensee action on previous insp findings & observation of safety-related work activities
  WILCOX.J D Region 2. Atlanta. Office of the Director HERDIA R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/10 App
- 7906260197 Forwards IE Insp Rept 50-281/79-22 on 790402-05 No noncompliance noted MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/23
- --7906260201 IE Insp Rept 50-281/79-22 on 790402-05 No noncompliance noted Major areas inspected const status re steam generator replacement HERDT.A R , WILCOX.J D Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 4pp
- 7906260599 Forwards IE lnsp Rept 50-281/79-23 on 790402-05 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/26 2pp
- --7906260603 IE Insp Rept 50-281/79-23 on 770402-05 No noncompliance noted Major area inspected steam generator replacement welding activities
  CROMLEV.B R Region 2. Atlanta. Office of the Director CONLON.T E Region 2. Atlanta. Reactor Construction 5 Engineering Support Branch 79/04/25 Spp
- 7906110068 Forwards IE Bullotin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY, P Region 2, Atlanta, Office of the Director 79/05/11 ip
- 7904200138 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-280/79-09 \$ 50-281/79-10 SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/15 ip
- ---7906200143 Respands to NRC 790328 ltr re violations noted in IE Insp Repts 50-280/79-09 % 50-281/79-10 Corrective actions loose containment screen installed all radiation area barricades locked & lead removed STALLINGS.C M

- --7906250137 Forwards IE Insp Rept 50-281/79-14 on 790306-09 & notice of violation MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 2pp
- --7906250142 Notice of violation from insp on 790306-07

  \* Region 2. Atlanta. Office of the Director 79/03/29 ip
- --7906250146 IE Insp Rept 50-281/79-14 on 790306-09 Noncompliance noted inadequate records for nitrogen purge steam generator idwar assemblies WILCOX,T D Region 2. Atlanta, Office of the Director HERDT,A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/29 4pp
- 7906190191 Act receipt of 790504 ltr informing NRC of steps taten to correct violations noted in IE Insp Repts 50~280779-15 & 50~281779-21 LEWIS,R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/05/17 1p
- --7906190194 Responds to NRC 790406 ltr re violations noted in IE Insp Repts 50-280779-15 & 50-281779-21 Corrective actions annunciation procedure changed operators instructed to report events & fire watch posted STALLINGS.C M Virginia Electric & Power Co 79705/04 3pp
- --7906190198 Forwards IE Insp Repts 50-280/79-15 & 50-281/79-21 on 790205-0316 & notice of violation LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/06 2pp
- --7906190208 Notice of violation from insp on 790205-0316 \* Region 2, Atlanta, Office of the Director 79/04/06 ip
- --7906190213 IE Insp Repts 50-280/79-15 & 50-281/79-21 on 790205-0316
  Noncompliance noted failure to Follow annunciator procedure
  & failure to establish fire watch on nonfunctional
  electric penetration fire barriers
  BURKE.D J Region 2. Atlanta, Defice of the Director
  CANTRECL.F S Ragion 2. Atlanta, Reactor Operations Nuclear
  Support Branch 79/04/01 Spp
- 7906060124 Responds to NRC 790510 ltr re violations noted in IE Jiss Repts 50-280/79-18 % 50-281/79-26 Corrective actions tents inspected & acceptance label affixed & copy of procedure HP-68PP-10 placed in reading file STALLINGS.C M Virginia Electric & Power Co 79/05/31 4pp
- 7906290537 Ack receipt of 790529 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-280/79-09 & 50-281/79-09 BUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/06/07 ip
- --7906290552 Responds to NRC 790513 ltr re violations noted in [E Insp Repts 50-280/79-09 & 50-281/79-09 Corrective actions labeling of containers of radioactive matl. STALLINOS.C H Virginia Electric & Power Co 79/05/29 2pp
- 7906180536 Responds to IE Builetin 79-01 Forwards "Failure of Sciencid Operated Valves to Meet IE Builetin 79-01 Environ Qualification Raquirements " STALLINGS.CM Virginia Electric & Power Co 79/06/14 ip
- --7905180538 "Failure of Sciencid Operated Valves to Meet IE Bulistin 79-01 Environ Qualification Requirements "Environmentally unqualified valves have been or will be replaced \* Vinginia Electric & Power Co 79/06/14 2pp
- 7906270121 Responds to IE Bulletin 79-01. "Environ Qualification of Class IE Equipment" Buspected solenoid valves will be upgraded or replaced as soon as possible BTALLINOS.C M Virginia Electric & Power Co 79/06/25 25pp
- R. Periodic operating reports & related correspondence
- 7906180517 Forwards monthly operating rept for May 1979
  STALLINOS, C. M. Virginia Electric & Power Co. 79/06/13 ip.
- --7906180520 Monthly operating rept for May 1979 CODTELLO, O. J. Virginia Electric & Power Co. 79/06/04 40pp
- S. Reportable occurrences, LERs & related correspondence
- 7906140415 Provides info on potential significant deficiency reported on 790325 re missing threads in bolt hole on pad of Steam Generator 2973 All steam generator feet helicoits replaced STALLINGS, C. H. Virginia Electric & Power Cq. 79/05/31 2pp

- 7906200398 Forwards LER 79-020/01T-0 STALLINGS, C M Virginia Electric & Power Co 79/06/18 1p
- --7906200405 LER 79-020/01T-0 on 790606 abnormal degradation of cable insulation on emergency power sys battery charger discovered at cold shutdown Caused by constant high pressure environ Cable will be replaced w/cables of higher tolerance STEMART.W L Virginia Electric & Power Co 79/06/18 2pp
- U Congressional/Executive Correspondence
- 7906110367 Acr receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific consileration for seismic events HENDRIE. J M. Commission 79/05/21 2pp
- ~~7906110378 Ack receipt of VA congressional delegation 790319 ltr ce shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906110380 Ack receipt of VA congressional delegation 790319 ltr resolutions of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selsmic events
  HENDRIE, J M Commission 79/05/21 2pp
- ---7906110382 Ack receipt of VA congressional delegation 790319 ltr ye shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE: J M Commission 79/05/21 2pp
- --7906110385 Ack receipt of VA congressional delegation 790319 ltr re shutdown of Facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selsmic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110387 Ack receipt of VA congressional delegation 790317 ltr re shutdown of facilities Steps have been taken re review of pipe itress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906110390 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for setanic events HENDRIE, J M Commission 79/03/21 2pp
- --7906110394 Ack receipt of VA congressional delegation 790319 itr to shutdown of facilities Steps have been taken re review of pipe stress reamelyses Discusses site-specific considerations for selsmic events HENDRIC.J M Commission 79/05/21 2pp
- --7906110397 Ack receipt of VA congressional delegation 790319 ltr resolution of facilities Stops have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events
  HENDRIE: J H Commission 79/05/21 2pp
- --7906110400 Ack receipt of VA congressional delegation 790319 itr reshutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selsmic events
  HENDRIE, J M Commission 79/05/21 2pp
- --7906110408 Forwards draft of proposed responses to 790319 ltr from 10 VA congressional delegates re pipe stress analysis at facility
  DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/01 5pp
- ---7906:10411 Requests expedited review of piping stress reanalyses, independent from review of other three plants shut down for seismic-related issues
  BUTLER.C M., DANIEL.R W., HARRIS,H E. House of Rep. 79/03/19
- DUCKET 50-282 PRAIRIE ISLAND NUCLEAR STATION, UNIT 1
- J Insurance & indemnity information
- 7906130312 Forwards Endorsements 42 & 43 to NELIA Policy NF-197 JUHN8UN,R Q Worthern States Power Co. 79/06/07 3pp

- 7906210237 Forwards Endorsements 38 & 39 to HAELU Policy MF-68 JCHNSON,R G Northern States Power Co 79/06/15 3pp
- P Operating license stage documents & correspondence
- 7906130057 Forwards Amends 36 & 30 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/01
- --7906130061 Amends 36 & 30 to Licenses DrR-42 & DPR-60, respectively, revising Tech Specs to require actuation of safety injection based on 2 out of 3 channels of low pressurizer pressure SCHMENCER, A Operating Reactors Branch 1 (Pre 790625) 79/05/01 9pp
- --7904130042 Safety evaluation supporting Amends 36 \$ 30 to Licenses DPR-42 & DPR-60, respectively + Office of Nuclear Reactor Regulation 77/05/01 4pp
- --7704130064 Notice of issuance & availability of Amends 36 & 30 to Licenses DPR-42 & DPR-60, respectively BCHHENCER.A Uperating Reactors Branch 1 (Pre 790625) 79705/01 2pp
- 7706120094 Forwards safety evaluation for mod to safety injection actuation sys
  LAINAS.O Plant Systems Branch 77/05/03 2pp
- --7706120101 Safety evaulation supporting mod to safety injection actuation sys

  \* Plant Systems Branch 79/05/03 2pp
- 7906280038 Discusses review of info re rod bank exchange method to verify shutdown margin for two loop Westinghouse NSSS Approves method as alternative to boron exchange provided certain conditions are met SCHMENCER.A Operating Reactors Branch 1 (Pre 790625) 79/05/15
- 7906200451 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite environ monitoring stations & site maps used for offsite dose detarminations or evacuation

  KEPPLER, J 0 Region 3, Chicago, Office of the Director 79/05/17
- 7906050270 Forwards amend application for Licenses DPR-42 & DPR-60, in response to NRC 781115 ltr
  HAYER.L O Northern States Power Co 79/06/01 1p
- --7906090292 Application for amend to Licenses DPR-42 & DPR-60 WACHTER,L J. Northern States Power Co 79/06/01 62pp
- 7906140443 Forwards "Process Control Program for Waste Solidification" & Offsite Dose Calculation Manual MAYER: L D Northern States Power Co 79/06/07 ip
- --7906140448 "Process Control Program for Waste Solidification "
  \* Northern States Power Co 79706/01 11pp
- --7906140451 Offsite Dose Calculation Manual
  \* Northern States Power Co 79/06/01 111pg
- 7906190342 Forwards Revision 2 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Request for Relief from ASME Code Section XI Requirements"

  HAYER: L Q Northern States Power Co 77/06/08 2pp
- ---7906190349 Revision 2 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Request for Relief from ABME Code Section XI Requirements " a Northern States Power Co 79/06/08. 66pp
- 7906220357 Submits info re facility feedwater line design: fabrication, insp & operating history MAYERL D. Northern States Power Cp. 79/06/19. 20pp
- G Inspection reports: IE Builetins & correspondence
- 7906060093 Responds to NRC 790215 ltr re violations noted in IE Insp Rept 50-282/79-01 & 50-306/79-01. Corrective actions: design change has been implemented to assure problems are quickly identified & corrected HACHTER, L J Northern Etates Power Co 79/03/08 5pp

- 7906040062 Responds to IE Bulletin 79-07 ADLEPIPE computer code used by Fluor Svcs. Inc for seismic analysis of one safety in jection line Analysis repeated using PIPESTRBS design found satisfactory WACMTER.L J. Northern States Power Co. 79/04/24 3pp
- 7906260321 Forwards IE Insp Repts 30-282/79-08 \$ 50-306/79-07 on 790212-16 \$ 0314-16 \$ notice of violation HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/04/25 2pp
- --7906260326 Notice of violation from insp on 790212-16 % 0314-16 \* Region 3. Chicago, Office of the Director 79/04/19 ip
- --7906260330 IE insp Repts 50-282/79-08 & 50-306/79-07 on 790212-16 & 0314-16 Noncompliance noted delayed conduct of fire sys surveillance MCGREGOR, L G , SMITH, J D , STREETER, J F Region 3, Chicago, Office of the Director 79/04/19 9pp
- 7906260545 Forwards IE Insp Repts 50~202/79-09 & 50~306/79-09 on 790301-31 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/30 2pp
- --7906260353 IE Insp Repts 50-282/79-09 % 50-306/79-08 on 790301-31 No noncompliance noted Major areas inspected plant operations, radiation protection, maint, security, insp of new fuel & contingency planning FEIERABEND. C D . DANIELS.FT . WARNICK, R F . Region 3, Chicago, Office of the Director 79/04/23 Spp
- 7906260621 Forwards IE Insp Rept 50-282/79-10 on 790411-12 No noncompliance noted FIORELLIG Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/30 Zpp
- --7906260624 IE Insp Rept 50-282/79-10 on 790411-12 No noncompliance noted Major areas inspected GA/GC program implementing procedures, observation of work activities & nondestructive examinations data
  WARD. B LIVERIORE. D H Region 3, Chicago, Office of the Director 79/04/27 6pp
- 7706020151 Responds to IC Bulletin 79-04 Velan valve weights were incorrect but have been reanalyzed in compliance w/bulletin No mod required Tabulation of valve use encl MACHTER, L. J. Northern States Power Co. 79705/01 App
- 7906120121 Forwards |E Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/07
- 7906110106 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER.J & Region 3, Chicago, Office of the Director 79/05/11

- 7906200131 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/29
- 7906290649 Ack receipt of 790518 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-202/79-08 & 50-306/79-07
  HEISHMAN,R F Region J. Chicago, Reactor Operations Nuclear Support Branch 79/05/29
- --7906290475 Responds to NRC 790425 ltr re violations noted in IE Insp Rept 50-282/79-08 & 50-306/79-07 Corrective actions detector testing begun 781108 & completed 781228 WACHTER, L. J. Northern States Power Co. 79/05/18 2pp
- 7906260471 Forwards "Inservice Insp Examination Summary." 790407-25 MAYER.L O Northern States Power Co 79/06/22 1p
- --7706260476 "Inservice Insp Examination Summary," 790407-29
  HANSEN D B . ANDERSON.R W Northern States Power Co 79/05/08
  127pp
- R Periodic operating reports & related correspondence
- 7906030324 Submits May 1979 Environ Event Rept 79-04 re cooling tower operations
  WARD.E C Northern States Power Co 79/06/01 1p
- 7905140227 Forwards monthly operating repts for May 1977 MAYER, L. O. Northern States Power Co. 79/06/(1 ip
- --7906140234 Monthly operating root for May 1979 HUNSTAD: A A Northern States Power Co 79/06/01 4pp
- --7906140239 Monthly operating rept for May 1979
  HUNSTAD, A. A. Northern States Power Co. 79/06/01 4pp
- S Reportable occurrences, LERs & related correspondence
- 7906040322 LER 79-001 has been voided \* Northern States Power Co 79/06/01 1p
- 7906140369 Environ Event Rept 79-04 in May 1979 plant circulating water sys in partial recycle mode had excessive average daily blowdown flow for 17 days Caused by accommodation of cooling tower maint b proper cooling water temps WARD: E C Northern States Power Co 79/06/01 ip
- 7906:50339 RO 79-19 dynamic loading during post-LOCA flow before valve closure was not included in original stress analysis of Henry Pract containment purge valves All purge valves administratively controlled to assure closure TIERNEY.F P Northern States Power Co 79/06/07 1p
- 7906220356 Forwards LER 79-019/01T-0 MAYER: L D Northern States Power Co 79/06/20 1p
- ~-7906220362 LER 79-019/01T-0 on 790606 containment purge & inservice purge isolation valves had not been dynamically analyzed for post-LOCA flow induced stresses Caused by design Valves put under strict administrative control HUNSTAD.A A Northern States Power Co 79/06/20 1p
- 7906270161 Forwards LER 79-017/03L-0
  MAYER, L. D. Northern States Power Co. 79/06/22 1p.
- --7906270165 LER 79-0t7/O3L-0 on 790525 both source range channels lost for three menutes when all power range channel control power fuses were pulled, Caused by procedure error Fuses reinstalled b procedure changed HUNSTAD.AA Northern States Power Co 79/06/22 ip
- DOCKET 50-284 IDAHO STATE UNIV RESEARCH REACTOR

  G Inspection reports: IE Bulletins & correspondence
- 7906250010 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

  BEYFRIT,K. V Region 4, Dallas. Office of the Director 79/05/11
  18

- DOCKET 50-285 FORT CALHOUN STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7906260173 Forwards modified physical security plan in response to NRC 790511 request Plan withheld (ref 10CFR2 790) SHORT.T E Omaha Public Power District 79/06/19 1p
- I Financial information
- 7906130316 Forwards info re vital area access control info deemed "commercial or financial info." per 10CFR9 5(a)(4) Info withheld tref 10CFR2 7905 SHORT.T E Qmaha Public Power District 79/06/06 1p
- P Operating license stage documents & correspondence
- 7906040033 Forwards safety evaluation of postulated fuel handling accident in reactor containment bldg
  REID.R W Operating Reactors Branch 4 (Pre 790625) 79/04/27
- 7905250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants
  THABANI.A C Reactor Systems Branch 79/05/02 43pp
- 7905230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors
  THADANI,A C Reactor Systems Branch 79/05/09 ip
- 7906290660 Notification of 790525 meeting w/util in Bethesda. HD to discus surveillance capsule test results which indicate integrated flux in reactor vessel of 2 5 times flux instially calculated ERICKSON.P B Operating Reactors Branch 4 (Pre 790625) 79/05/22 2pp
- 7906050355 Forwards revised design description for mod re steel frame near diesel fire pump fuel storage tank SHORT.T E Omaha Public Power District 79/05/23 10pp
- 7906050346 Forwards add1 info re technical bases for calculations, ability of util to catagorize safety injection pump room ventilation as engineered safety feature & effect upon indine capiling in event of ventilation sys failure SHORT. T E Omaha Public Power District 79/05/24 24pp
- 7906060278 Responds to 790515 ltr re failure of safety-related electrical equipment to meet environ qualification criteria Forwards documentation demonstrating that subj solenoid valves do not jeopardice public safety EHDRY.T E Omaha Public Power District 79/05/29 5pp
- 7906060275 Forwards responses to questions re plant instrumentation & controls
  SHORT, T E Omaha Public Power District 79/05/30 11pp
- 7906(300): Forwards responses to NRC 7905(8 questions Loss of main feedwater pumps occurred twice in past three years Unit has automatic isolation actuation sys Appropriate pumps used to remove liquid waste
  SHORT, T E Omena Pumpic Power District 79/05/31 Spp
- 7906120224 Forwards design description for review of fire protection safety evaluation Proposes mod to reduce probability of lube oil fire in containment bidg Four oversized drawings encl SHORT.T E Compha Public Power District 79/06/06 13pp
- 7906150313 Forwards into re gas effluent monitoring sys, in response to 790607 telcon SHORT.T E Omaha Public Power District 79/06/08 3pp.
- 7906250288 Forwards info re radiation doses from equipment hatch during normal operation & after LOCA/in response to 780426 request.
  SHORT/T E Omaha Public Power District 79/06/14 22pp
- 7906260168 Ack receipt of NRC 790525 request for info re main feedwater at facility Forwards responses to questions & drawings SHORT: TE : Omaha Public Power District 79/06/18 25pp
- A Inspection reports, IE Bulletins & correspondence
- 7906210010 Forwards IE Insp Rept 30-285/79-06 on 790405 No noncompliance noted MADSEN O.L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/18 2pp

- --7906210018 IE Insp Rept 50-285/79-06 on 790409 No noncompliance noted Hajor areas inspected previously identified insp findings & LER 78-040 IAPIA-J I , ROSENBERG, A B , HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 3pp
- --7906210022 Forwards corrected pages of IE Insp Rept 50-285/79-06 Biscusses errors made HADSEN.G L Region 4, Dalias, Reactor Construction & Engineering Support Branch 79/04/26 ip
- 7905120072 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required SEYFRIT.K V Region 4, Dailas, Office of the Director 79/05/07
- 7906110086 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Hritten response required SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/11
- 7908250024 Forwards 1E Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " SEYFRIT, K V Region 4. Dallas. Office of the Director 79/05/11
- 7905120387 Responds to NRC 790517 request Forwards add1 info re unqualified limit switches supporting 790515 response to IE Bulletin 79-01 SHDRT.T E Omaha Public Power District 79/06/06 9pp
- 7906190491 Responds to IE Bulletin 79-01 re environ qualification of safety-related electrical equipment Forwards relevant info SHDRT T E Omaha Public Power District 79/06/13 22pp
- 790622036B Notifies that as of 790617 at least two operators per shift will be designated to initiate 5 verify auditary feedwater flow to steam generators during transients or accidents Modifies grevious response to IE Bulletins 79-06 5 79-06B SHORT, T E Omaha Public Power District 79/06/15 2PP
- R Periodic operating reports & related correspondence
- 7705120335 Forwards monthly operating rept for May 1979 SHORT, T E Omaha Public Power District 79/06/07 ip
- --7906120336 Monthly operating rept for May 1979 HICKLE, B J Omaha Public Power District 79/06/07 9pp
- S Reportable occurrences, LERs & related correspondence
- 7906180146 Forwards PNO-79-67AM MADSEM.O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/09 1p
- 7906210435 Forwards rept on potentially hazardous condition discovered during performance check of analysis performed on safeguards piping sys

  DERIENZA,P,P Qibbs & Hill, Inc. (subs. of Dravo Corp.) 79/05/11
- 7906180198 Forwards PNO-79-67AN
  MADBEN.O L. Region 4. Dellas, Reactor Operations Nuclear Support
  Branch 79/05/15 1p
- 7906180297 Forwards PNO-79-67AO & AP MADSEN.O L Region 4, Dallas. Reactor Operations Nuclear Support Branch 79/05/24 ip
- --7905040294 LER 79-014/01T-0 on 790515 ABCO solenoid valves lacked sufficient environ qualification data Gaused by inadequate specs during design & installation period Valves will be replaced following 1980 refueling outage HUELLER.R. Omaha Public Power District 79/05/16 7pp
- --790&05033B LER 79-003/03L-1 on 790127 during containment pressure release.containment air monitor readings were abnormally low. Caused by closed isolation valves Containment ventilation valves were closed & pressure valves opened. GATES. © Omena Public Power District 79/03/29 3pp

- 7906050320 Forwards LER 79-016/01T-0 ANDREWS R L Omaha Public Power District 79/05/30 ip
- --7906030321 LER 79-016/01T-0 on 790517 testing on first removed irradiated surveillance capsule showed higher than predicted not ductifity transition temp new pressure Temp limitation curves have been developed KELL000.R Dmaha Public Power District 79/05/30 4pp
- DOCKET 50-284 INDIAN POINT STATION, UNIT 3
- C Utility Environmental Report (ER), amends & correspondence
- 7906190233 Forwards "1976 Year-Class Rept for Multiplant Impact Study of Hudson River Estuary " Affidavit of Svc encl ZARAKAS.P Consolidated Edison Co of New York 79/06/15 Spp
- --7906190257 "1976 Year-Class Rept for Multiplant Impact Study of Hudson River Estuary," prepared by TX Instruments \* Consolidated Edison Co of New York 79/05/31 550pp
- F Security, medical, emergency & fire protection plans
- 7906190364 Forwards revised responses to request for add! info re fire protection program administrative controls

  EARLY,P J Power Authority State of New York 79/06/12 4pp
- 7906260428 Forwards revised response to NRC 781023 request re site boundary dose determination from radioactive releases due to fire in drumming station

  EARLY.P J Power Authority State of New York 79/04/21 App
- O Adjudicatory correspondence
- 7904190291 Requests NRC update distribution list VJ Casson reglaces LR Bennett as counsel for util EARLY.P J Power Authority State of New York 79/04/12 lp
- J Insurance & indemnity information
- 7906190236 Notifies of receipt of complaint served on Westinghouse alleging bodily injury to util employee J O'Mallon.who was splashed w/radioactive water on 760812 Suit under way ALTON.C O American Nuclear Insurers 79/06/14 19
- 7906220303 Forwards Amené 21 to Indemnity Agreement 8-19 CAHILLIN J Consulidated Edison Co of New York 79/06/18 3pp
- P Operating license stage documents & correspondence
- 7906150227 Forwards listing of docketed info describing 6A program EARLY.P J Power Authority State of New York 79/04/30 3pp
- 7704040144 Ack receipt of 770327 emergency plan submittal Requests Class III fee MILLER.H O License Fee Management Branch 79/05/08 ip
- 7908250033 Summary of 790508 meeting w/Consolidated Edison (
  Power Authority of State of NV re auxiliary feedwater sus
  related station areas
  DLSHAN: L N Operating
  6pp
- 7906i1044i Notification of 790522 meeting w/Consolidated Edison Co of NY & Power Authority of NY to discuss seismic analyses & follow up 790517 meeting CLEHAN, L Operating Reactors Branch 1 (Pre 790625) 79/05/17
- 7906:110245 Forwards "Efficiency of one Square Meter Epibenthic Sled for Collecting Young-of-the-Year Striped Bass, White Perch & Atlantic Tomcod in Hudson River Estuary, 1978." H/JR Jannarone 790606 affidavit Centificate of Svc encl CAHILLIN J Consolidated Edison Co of New York 79/06/06, Spp
- 7906180393 Forwards "Cycle 3 Refueling Outage Work List."
  EARLY.P J Power Authority State of New York 79706/13 3pp
- --7906180410 "Cycle 3 Refueling Outage Work List "
  \* Power Authority State of New York 79/06/13 13pp.

- 7906190506 States that analysis performed to demonstrate unlimited purging & continuous pressure relief will not interfere w/proper operation of ECCS EARLY.F J Power Authority State of New York 79/06/14 4pp
- 7906260143 Forwards "Post-Accident Honstering Instrumentation"
  Satisfies commitment by util in 781013 ltr to survey
  existing IP3 fixed & portable instrumentation
  EARLY, P J Power Authority State of New York 79/06/21 36pp
- 7904(10255 "Efficiency of One Square Mater Epidenthic Sled for Collecting Young-of-the-Year Striped Basss, White Perch & Atlantic Tomcod in Hudson River Estuary, 1978 " \* Toxas Instruments, Inc 79/06/30 19pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906110024 Forwards IE Bulletin 79-05B. "Nuclear Incident at TMI-Suppl " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 79/04/23 ip
- 790&070204 Forwards responses to IE Bulletin 79-07 Discusses methods used for seismic analysis & design of reactor coolant loop SCHMIEDER.J R Power Authority State of New York 79/04/24 7pp
- 7906140326 Responds to IE Builetin 79-03 re use of ASME SA-312 Type 304 or other welded pipe made by Youngstown Welding & Engineering Co No Youngstown piping has been used in safety-related sys
  BAYNE.J P Power Authority State of New York 79/04/24 tp
- 7906040014 Forwards responses to IE Bulletin 79-06A. Items 1-12 As result of TM1 incident procedures have been tightened, personnel reinstructed & safety checks performed BAYNE.J P Power Authority State of New York 79/04/26 20pp
- 7906130122 Forwards computer code listing as addl response to IE Bulletin 79-07 Requests withholding (ref 10CFR2 790) H/a encl BCHMIEDER, J. R. Power Authority State of New York 79/04/26 Bpp
- 7906120034 Notifies that ressponse to IE Bulletin 79-04 will be submitted by 790601, due to extensive work required EARLY.P J. Power Authority State of New York 79/05/01 ip
- 7906120107 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER.B H Region 1. Philadelphia. Office of the Director 79705/07 2pp
- 7906140508 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers Breakers not utilized in safety-related cys BAYNE, J P Power Authority State of New York 79/05/07 1p
- 7906110144 Forwards [E Bulletin 79-10, "Requalification Training Program Statistics " Written response required ORIER, B H Region i. Philadelphia. Office of the Director 79/05/11 ip
- 7906260132 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906080097 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER.B H Region 1, Philadelphia, Office of the Director 79/03/18 1p
- 7906250090 Summary of 790517 meeting w/Consolidated Edison Co of NY. Power Authority of State of NY & United Engineers & Constructors, Inc to discuss licensee response to IE Bulletin 79-07. "Seismic Stress Analysis of Safety-Related Piping" OLSHAN, L N. Operating Reactors Branch I (Pre 790625) 79/05/18400
- 7906010186 Responds to IE Bullstin 79-07. "Seismic Stress Analysis of Safety-Related Piping " All piping supports evaluated % found within allowable limits and the Property P
- 7906070246 Provides supplemental response to IE Builetin 79-07 Provides (info to support continued operation during reanalysis of selemic piping stresses. Reanalysis to be completed by 790701 EARLY, P. J. Power Authority State of New York '79/05/31 20pp

- 7906120266 Responds to IE Bulietin 79-07 re pipe stress reanalysis Forwards weekly status rept as of 790604 EARLY.P J Power Authority State of New York 79/06/06 2pp
- 7906120374 Provides revised responses to IE Bulletin 79-06A.Revision I Responses result from 790530 meeting w/Westinghouse & NRC in Bethesda.MD to discuss operating procedures for caping w/transients & accidents BAYNE, J P Power Authority State of New York 79/06/06 3pp
- 7906130275 Responds to IE Bulletin 79-07 re pipe stress reanalysis Forwards weekly status rept as of 790609 EARLY.P J Power Authority State of New York 79/06/11 2pp
- 7906260430 Submits revised responses to IE Gulletin 79-06A, Revision 1 Original responses to bulletin encl BAYNE, J. P. Power Authority State of New York 79/06/20 9pp
- 7906260461 Forwards weekly status reptcas of 790614.on pipe stress reanalysis, in response to IE Bulletin 79-07
  EARLY, P. J. Power Authority State of New York 79/06/20 2pp
- 7906280082 Forwards weekly status of work as of 790622 per IE Bulletin 79-07 re pipe stress reanalysis EARLY,P J Power Authority State of New York 79/06/25 2pp
- R Periodic operating reports & related correspondence
- 7906140259 Annual Environ Operating Rept 1978, Part A & Part B radiological reptivols 1 & 2

  \* Consolidated Edison Co of New York 78/12/31 223pp
- 7906190462 Forwards "Seismic Monitoring Network." Guarterly Rept 13 for Dec 1978 - Feb 1979 GAMILL, M.J. Consolidated Edison Co. of New York 79/06/04 Lp
- --7906190466 "Seismic Monitoring Network." Guarterly Rept 15 for Dec1978-Feb 1979 Prepared by Woodward-Clyde Consultants, Inc \* Consolidated Edison Co of New York 79/05/30 36pp
- 7906/90478 Submits May environ data specified in Section 401 certification MORTILL A Consolidated Edison Co of New York 79/06/10 lipp
- 7906200368 Forwards monthly operating rept for May 1979
  BAYNE, J P Fower Authority State of New York 79/06/14 1p
- --7906200369 Monthly operating rept for May 1979
  CONNELL,C Power Authority State of New York 79/06/04 6pp
- 7706260407 Forwards May 1979 daily tabulation of fish collection & species breakdown CAHILL.W J. Consolidated Edison Co of New York 79/06/14 5pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906040232 Forwards LFR 78-025/03L~0 BAYNE,J P Power Authority State of New York 78/09/26 1p
- --7904040318 LER 78-025/03L-0 on 780831 excessive hoise from svc water pump 35 observed at 90% power Main pump shaft broken, disabling one of three header pumps Caused by bearing failures Pump secured & header redirected GUMSLE.F. H Power Authority State of New York 78/09/26 1p
- 7906040347 LER 78-034/03L-0 on 781027 increase in plant vent radio gas monitor observed Caused by leakage of charging pump plunger 31 Plunger & packaging for Union Pump QX-000 Guintuple: replaced Plunger raturned to operable status OWBLE.F W Power Authority Stata of New York 78/11/17 2pp
- 7906040313 LER 78-036 number not used, \* Pawer Authority State of New York 79/05/29 1p
- 7906190264 Forwards LER 79-005/03L-1 BAYNE, J P Power Authority State of New York 79/06/15 19
- --7906190267 LER 79-005/03L-1 on 790405 svc water pump 34 was removed from svc due to low discharge pressure Caused by broken main pump shaft which disabled i of 3 essential header pumps Svc water pump was replaced & new bearings installed GUMBLE: F Power Authority State of New York 79/06/15 2pp

- 7906280110 Describes LER 79-006/01T-0 on 790621 error found in analysis of high energy line breaks inside containment Change in reactor trip setpoint in effect
  BAYNE, J P Power Authority State of New York 79/06/22 2pp
- DOCKET 50-207 OCONEE NUCLEAR STATION, UNIT 3
- Q Adjudicatory correspondence
- 7908040224 Orders licensee to take immediate action to modify feedwater sys & operating procedures to shut down certain units until completion of mods & to undertake long-term mods as specified CHILK, S J Office of the Secretary of the Commission 79/05/07
- 14ap
- J Insurance 5 indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS,F D Duke Power Co 79/06/08 5pp
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906:80383 Forwards ECCS analysis of small breaks in conjunction w/ emergency feedwater flow failures Operator has 20 minutes to re-establish feedwater flow prior to core uncovery BAYES, A ACRS Advisory Committee on Reactor Safeguards 79/05/03
- P Operating license stage documents & correspondence
- 7906270065 Forwards 790514 inspector's findings re changes to plant procedures resulting from 790507 order Procedures of 790507 order to operator's understanding of procedures are deemed Office of Inspection & Enforcement 79/05/17 1p
- --7906270068 Confirms procedural changes resulting from NRC 79507 order & operators' full understanding of those changes

  JAPE,F Region 2. Atlanta, Office of the Director 79/05/14
- 7906060229 Confirms info submitted 790330 re OL amend requested to support operation through Cyclo 5 Physics test will be conducted according to guidelines submitted on 780922 & PARKER. W C Duke Power Co 79/05/29 1p
- 7908070238 Submits proposed Fech Specs levisions re surveillance stds to suppl 761001 & 770708 submittals PARKER.H O Duke Power Co 79/05/30 13pp
- 7906050327 Responds to 790518 request forwards emergency feedwater flow test procedure FARKER, W O Duke Power Co 79/06/01 1p
- --7906050329 Emargancy feedwater flow test procedure Duke Power Co 79/05/31 12pp
- 7406150267 Advises that hydrostatic test required by 1974 ABME Boiler & Pressure Vessel Code is impractical Util will follow 1977 edition requirement Requests notification if unacceptable PARKER: N O Duke Power Go 79/06/11 2pp
- 7906190261 Responds to NRC 790518 ltr requesting schedule by 790618 completion of long-term mods described in Section 2 of NRC 790507 order All efforts satisfactorily executed PARKER.W D Duke Power Co 79706/14 ip
- 2906220283 Forwards responses to NRC 790525 ltr re feedwater lines Diagrams encl PARKER.W Q Duke Power Co 79/06/18 66pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906270288 B&W site inspector deily rept on 790407.Plant status reactor operating at 90% power for repairs to condenser tubes. Testing to determine leak source continues. COVILE.W. Region 2. Atlanta. Office of the Director. 79/04/07
- 7905290174 B&W sits inspector daily rept on 790408 Plant status units 1 & 3 operating at 100%/Unit 2 at 90% Hunting condenser tube leak on Unit-2 reported.

  COTTLE:W Region 2, Atlanta. Office of the Director 79/04/08

- 7906290048 BWW site inspector daily rept on 790409 Plant status all reactors at full power Condenser leak has been corrected on Unit 2 COTTLE, W Region 2. Atlanta. Office of the Director 79/04/09
- 7906270519 80W site inspector daily rept on 790410 Plant status all reactors at full power w/all engineering safety feature sys in sve JAPE, F Region 2, Atlanta, Office of the Director 79/04/10
- 7906290087 BLW site inspector daily rept on 790411 Plant status reactor at full power w/no known problems Training instructors scheduled for BAW simulator training 790418

  JAPE.F Region 2. Atlanta, Office of the Director 79/04/11
- 7904290562 BLW sate inspector daily rept on 790412 Plant status all units running at full power Bys alignment verified for accessible components on Emergency Feedwater Bys COTTLE Region 2. Atlanta, Office of the Director 79/04/12
- 7906270130 BtH site inspector daily rept on 790413 Plant status 747 power w/one reactor coolant pump secured to prevent seal degradation Outage scheduled for 790424 MCHENRY, T J Region 2. Atlanta. Office of the Director 79/04/13
- --7906290135 B/W site inspector daily rept on 790413 Plant status all reactors at full power w/no engineering safety feature equipment out of svc & no major maint COTTLE Region 2. Atlanta. Office of the Director 79/04/13
- 7906290429 BbW site inspector daily rept on 790414 Plant status Unit 2 operating at 82% power. Unit's 1 & 3 at full power No major maint scheduled & all major equipment is operational BELISLE.A Region 2. Atlanta. Office of the Director 79/04/14
- 7906290480 BW sits inspector daily rept on 790415 Plant status all units at 100% power w/no engineered safety feature equipment out of svc & no major maint scheduled BELISLE.0 A Region 2. Atlanta. Office of the Director 79/04/19
- 7906290998 BbH site inspector faily rept on 790417 Plant status all units at 100% power No major engineering safety feature sys equipment out of svc Region 2. Atlanta, Office of the Director 79/04/17 1p
- /906110062 Responds to IE Bulletin 79-05B Reactor protective sys high RCS pressure setpoint has been lowered to not greater than 2,300 psigipressurizor power operated relief value setpoint raised to 2,400 psig PARKER, W O Duke Power Co 79/04/21 1p
- 7906290456 BbW site inspector daily rept on 790420 Plant status Units 1 & 3 at 100% power Unit 2 reduced to 92% due to water look in turbine condenser box JAPE,F Region 2. Atlanta. Office of the Director 79/04/20 ip
- 7906120291 Notifies that response to IE Bulletin 79-04 re Velan check valves will be submitted no later than 790530 PARKER:W O Duke Power Co 79/05/02 ip
- 7906040421 Supplements response to Item 3 of IE Bulletins 79-05 & 79-05A re licensed shift operators completing B&W simulator training PARKER, H O Duke Power Co 79/05/04
- 7906200265 Ack receipt of IE insp Repts 50-269/79-11.50-270/79-11 & 50-287/79-11 on 790301-29 No proprietary info PARKER.W 0 Duke Power Co 79/05/09 1p
- --7906200270 Forwards IE Insp Repts 50-267/77-11,50-270/79-11 & 50-287/79-11 on 790301-29 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/01. 2ap
- --7906200279 IE Insp Repts 50-269/79-11.50-270/79-11 & 50-287/79-11 on 790301-29 No noncompliance noted Major areas inspected plant operations followup of info notices playsical security & LER. JAPE, F Region 2. Atlanta. Office of the Director CANTRELL, F B Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/2B App
- 7906250443 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies,"
  D'REILLY, JP Region 2, Atlanta, Office of the Director 79/05/10

- 7906110060 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY.J P Region 2. Atlanta, Office of the Director 79/05/11 ip
- 7906260242 Ack receipt of 790322 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-01, 50-287/79-01 D'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/81 ip
- --7906260244 Supplements util 790322 ltr responding to item of noncompliance hoted in IE Insp Repts 50-269/79-01, 50-270/79-01 & 50-287/79-01 Util will submit ROs within 30 days of discovery of event PARKERNU D Dute Power Co 79/05/05 ip
- --7906240250 Responds to NRC 790227 ltr re violations noted in IE Insp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 Disputes item of moncompliance re late submittal of RO Due date fell on holiday PARKER, W O Duke Power Co 79/03/22 2pp
- --7908260259 Forwards IE Insp Repts 50-269/79-01, 50-270/79-01 & 50-289/79-01 on 790131-0201 & notice of violation LEWIS.R C Region 2. Atlanta, Office of the Director 79/02/27
- --7706260264 Notice of violation from insp on 790131-0201

  Region 2, Atlanta, Office of the Director 79/02/26 (p
- ---7906260271 IE Insp Repts 50-269/79-01,50-270/79-01 % 50-287//9-01 on 790131-0201 Noncompliance noted failure to submit written repts within 30 days of discovery of event COTTLE.N T , CANTRELL.F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/02/26 4pp
- 7906270827 Forwards response to 1E Bulletin 77-07 re GE Type AK-2/2A circuit breakers in safety-related sys Two are used as control rod drive ac primary trip breakers 2 four are used in dc holding power supplies PARKER. W 0 Duke Power Co 77/05/16 2pp
- 7905270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Bulletin 79-058
  WILLIAMS,F J Division of Project Management 79/05/18 3pp
- R Periodic operating reports & related correspondence
- 7706210149 Forwards monthly operating rept for May 1979 FARKER, W Q Duke Power Co 77/06/15 ip
- --7906210153 Monthly operating rept for May 1979 REAVIS.J A Duke Power Co 79/06/15 17pp
- 7906280148 Forwards correction sheets to monthly operating rept for May 1979 PARKER.W O Duke Power Co 79/06/25 ip
- --7906280151 Correction sheets to monthly operating rept for May 1979

  \* Duke Power Co 79/05/31 4pp
- Y Hearing transcripts on non-antitrust matters
- 7906110205 Transcripts of 790518 meeting in Hashington.DC re briefing on Oconee order Pp 1-88 Meeting exhibits encl HENDRICK.J M , GILINGKY.V , KENNEDY.R T Commission 79/05/18

- DOCKET 50-288 REED COLLEGE RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 7906:180447 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "No written response necessary ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/10 ip
- 7906080230 Forwards IE Circular 79-08, "Attempted Extertion Low Enriched U " ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/18 to
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7906010212 Forwards description of test to be performed on asbestos board fire barriers protecting cable trays & conduits to comply wifire protection SER. Item 3 2 2. cable separation Results will be submitted by 790715 HERBEIN.J Q Metropolitan Edison Co 79/05/18 7pp
- 7706260204 Responds to 770518 ltr re extra procautionary measures for area transmission sys Adequate sources of power are available for operation of unit
  VOLLMER/R H Assistant Director for Este Analysis 77/05/19 1p
- --7906260208 Requests end of extra precautionary measures taken to assure adequate power to plants
  ARNGLD,R C General Public Utilities 79/05/18 1p
- --7908280211 Notifies that precautionary measures taken to maintain power supply are no longer necessary Personnel on standby at switching station are needed elswhere Forwards outline of electrical sys
  HERTS,R W General Public Utilities 79/05/03 3pp
- 7906060264 Responds to 790330 ltr re fire protection program of cable separation info lequested was submitted in 790310 ltr Fire barriers to be modified per test results
  HERBEIN, J Q Metropolitan Edison Co 79/05/24 lp
- 7906120373 Conveys results of field survey to determine fire resistance rating of unlabeled fire doors Forwards 79030B consultant rept Requests concurrence re replacement & labeling of fire doors HERBEIN.J Q Metropolitan Edison Co 79/06/07 4pp
- I Financial information
- 7906120372 Forwards "Annual Financial Rept 1978" HERBEIN, J O Metropolitan Edison Co 79/06/07 ig
- --7906120380 "Annual Financial Rept 1978 "

  \* Metropolitan Edison Co \* OPU Service Corp 78/12/31 119pp
- J Insurance & indemnity information
- 7906210204 Forwards Endorsement 34 to MAELU Policy MF-73 GERETY: H F GPU Service Corp 79/06/15 2pp
- 7906250274 Forwards supplemental limit of liability endorsement to Policy NF-220, effective 790501 Supplemental limit does not apply to events re 790328 TMI incident
  BARDES, C R American Nuclear Insurers 79/06/18 3pp
- P Operating license stage documents & correspondence
- 7903210263 Amend 49 to License DPR-50 & Amend 9 to DPR-73, incorporating modified amended physical security plan into license REID,R W Operating Reactors Branch 4 (Pre 790625) 79/02/23 4pp.
- 7904270044 Forwards info on TMI incident followup actions by NRC, in response to 790412 memo MILLER: H O License Fee Management Branch 79/04/13 Spp
- 7906290022 Describes major drawbacks to locating sampling sinks for both units in same room.Unit 2 sink must be moved & all existing lines flushed before Unit 1 can be supported DUBIEL.R W Metropolitan Edison Co 79/04/24 2pp

- 7908220189 Forwards update of health physics status of facility Info was sent to LV Gossick for use in memo to NRC KINNEY, H W Region 1, Philadelphia. Office of the Director 79/05/07 3pp
- 7904070150 Confirms 790515 telcon w/J Holman & M Beers TMF training dept intends to resume licensed operator requalification program on 790521 MilleR, G P Metropolitan Edison Co 79/05/15 lp
- 7906200296 Discusses 791201 util response to NRC 781016 ltr re handling of heavy load within fuel handling bdlg Util response inadequate Definition of special areas re load handling requires analysis & Tech Spec changes

  REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/17
- 7906210008 Discusses operational-related problem re startup Shortly after 1976 unit outage, leak developed in decay heat removal sys which was apparently never permanently repaired YUHAS, G.P. Region 1. Philadelphia, Office of the Director 79/05/17 lp
- 7906250152 Advises that proposed reduction in frequency of core flow rate verification is acceptable REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/17
- 7906010213 Forwards "B&W 177 Fuel Assembly Owners' Group Asymmetric LOCA Loads Evaluation Program.Phase 2" % "B&W 177 Dunars' Oroup Rept for Asymmetric LOCA Loads Evaluation.Phase 2 " HERBEIN-J G Metropolitan Edison Co 79/05/18 19
- --7906010218 "BUW 177 Fuel Assembly Dwners Group Asymmetric LOCA Loads Evaluations Program Phase 2." dtd 790410 Metropolitan Edison Co 79/04/10 9pp
- --7906010229 "B&W 177-Fuel Assembly Dwners Group Assumptions Methodology & Acceptance Criteria Rept for Asymmetric LOCA Loads Evaluation.Phase 2 " \* Matropolitan Edison Co 9AW-1538 79/04/30 37pp
- 7904040231 Notifies of discharge of 7.400 gallons of water on 790514 & 7.100 gallons of water on 790515 Water released to influent of mechanical draft cooling tower discharge, bypassing waste TROFFER. Q J Metropolitan Edison Co 79/05/24 2pp
- 7908280077 Notifies info requested by 790502 ltr re adequaty of station electric distribution sys voltage will be provided by 790801 HERBEIN. J G Metropolitan Edison Co 79/04/25 ip
- 7906290608 Forwards info in response to 790825 ltr ro feedwater line cracking Addi info will be submitted by 790727 HERBEIN.J G Metropolitan Edison Co 79/06/26 lipp
- Q Inspection reports. IE Bulletins & correspondence
- 7906200334 Forwards IE Insp Repts 50-289/79-08 & 50-320/79-07 on 790319-23 & 26 No noncompliance noted BRUNNER, E J Region I, Philadelphia, Reactor Operations Nuclear Eupport Branch 79/04/20 2pp
- ---7906200337 IE Insp Repts 50-289/79-08 & 50-320/79-07 on 790319-23 & 26
  No noncompliance noted Major areas inspected previous insp
  findings, selected licensee events & licensee followup to
  prompt RO
  HAVERKAMP, D. R. KEIMIQ, R. R. Region 1, Philadælphia, Reactor
  Operations Nuclear Support Branch 79/04/19 10pp
- 7906110016 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " No written response required CRIER, B H Region 1, Philadelphia, Office of the Director 79/04/23, 1p
- 7906070237 Responds to IE Bulletin 79-04 requesting review to determine if Velan swing check valves are installed in seismic Category I piping sys Valves not installed or scheduled to be installed at facility HERBEIN. J O Metropolitan Edison Co 79/05/01 1p
- 7906120169 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER.B H Region I. Philadelphia. Office of the Director 79/09/07. 2pp

- 7906110133 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics " Written response required GRIER, B.M. Region I, Philadelphia, Office of the Director 79/03/11 ip
- 7906260119 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  GRIER, B H Region 1: Philadelphia: Office of the Director
  77/05/11 1p
- 790A080087 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched V " ENTERNOOD "
  GRIER. B H Region 1, Philadelphia, Office of the Director
  79/05/18 in
- 7906270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Bullotin 79-058
  MILLIANS, F J Division of Project Management 79/05/18 Spp
- 7906150324 Forwards results of steam generator eddy current tube 11150: performed 790225-0308 during 1779 refueling outage HERBEIN.J G Metropolitan Edison Co 79/06/08 2pp
- 7906270011 Lists IE bulletins issued since TMI incident which have been withheld due to lack of available util resources GRIER.B H Region 1. Philadelphia. Office of the Director 79/06/08 2pp
- S Reportable occurrences, LERs & related correspondence
- 7906040326 Forwards LER 78-009/03L-0 HERBEIN, J G Metropolitan Edison Co 78/04/03 tp
- ---7906040331 LER 78-009/03L-0 on 780315 dc breaker CB3 failed to trip on one of several tests Caused by apparent binding of breaker operating linkage Binding may have been due to insufficient exercise of breaker % for lack of maint MITCHELL.D G Metropolitan Edison Co 78/04/03 2pp
- 790604024; Farwards LER 78-011/03L-0 HERBEIN, J 0 Metropolitan Edison Co 78/04/17 1p
- --790A040244 LER 78-011/03L-0 on 780318 during visual testing, one snubber had no fluid in reservoir Caused by pinched rod wiper seal Snubber will be replaced b refilled HITCHELL,D O Metropolitan Edison Co 78/04/17 2pp
- /906070366 RO 79-09/ip on 790327 during surveillance of turbing driven emergency seed pump.pressure regulating value MS-V-6 was found manually closed Unit was in hot shutdown Valve was opened & pump successfully tested SEELINGER.J L Metropolitan Edison Co 79/04/11 is

- 7906110060 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required D'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 10
- 7906260242 Ack receipt of 790322 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-269/79-01.
  50-270/79-01 & 50-287/79-01

  O'REILLY, J P. Region 2. Atlanta, Office of the Director 700/00/11
- --7906260244 Supplements util 790322 Itr responding to item of noncompliance noted in IE Insp Repts 50-269/79-01. S0-270/79-01 & 50-287/79-01 Util will submit RDs within 30 days of discovery of event PARKER, NO Duke Power Co 79/03/05 1p
- --7906260250 Responds to NRC 790227 itr re violations noted in EE lasp Repts 50-269/79-01.50-270/79-01 & 50-287/79-01 Disputes item of noncompliance re late submittal of RO Due date fell on holiday PARKER.H O Duke Power Co 79/03/22 2pp
- --7906260257 Forwards IE Insp Repts 50-269/79-01,50-270/79-01 \$
  50-287/79-01 on 790131-0201 & notice of violation
  LEMIS.R C Region 2, Atlanta, Office of the Director 79/02/27
  200
- --7906260264 Notice of violation from insp on 790131-0201 \* Region 2, Atlanta, Office of the Director 79/02/26 ip
- --7906260271 IE Insp Repts 30-269/79-01.50-270/79-01 & 50-287/79-01 on 790f31-0201 Noncompliance noted failure to submit written repts within 3D days of discovery of event COTTLE-W T . CANTRELLE S Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/02/26 4pp
- 7906290829 Forwards response to IE Bulletin 79-09 re GE Type AK-2/2A circuit breakers in safety-related sys Two are used as control rod drive ac primary trip breakers & four are used in dc holding power supplies
  PARKER, W O Duke Power Co 79/05/16 2pp
- 7906270120 Requests info re manual trip on low pressurizes level as stated in Item 4F of IE Bulletin 79-058
  WILLIAMB:F J Division of Project Management 79/05/18 3pp
- R Periodic operating reports & related correspondence
- 7906210149 Forwards monthly operating rept for May 1979 PARKER, W O Duke Power Co 79/06/15 1p
- --7906210153 Monthly operating rept for May 1979 REAVIS.J A Duke Power Co 79/06/15 17pp
- 7906280148 Forwards correction sheets to monthly operating rept for May 1979
  PARKER, M O Duke Power Co 79/06/25 ip
- --7906280151 Correction sheets to monthly operating rept for May 1979
  \* Duke Power Co 79/05/31 4pp
- T Hearing transcripts on non-antitrust matters
- 7906110205 Transcripts of 790518 meeting in Washington, DC re briefing on Oconee order Pp 1-88 Meeting exhibits encl HENDRICK, J M . GILINSKY, V . KENNEDY, R T Commission 79/05/18 106pp
- 7906200560 Transcript of 79051B public meeting in Washington.DC rebriefing by NRC on Oconee order Pp 1-EB \* Office of the Executive Legal Director 79/05/18 B9pp
- U Congressional/Executive Correspondence
- 7906260541 Responds to 790423 itr re S Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FES W/o encl GOSSICK/L V Office of the Executive Director for Operations 79/05/15 2pp
- --7906260344 Requests info re radiological impact of nuclear power plant cooling on drinking water in ref to SL Austin inquiry LENT.NF House of Rep. 79/04/23 Zpp

- DOCKET 50-288 REED COLLEGE RESEARCH REACTOR
- @ Inspection reports: IE Bulletins & correspondence
- 7906180447 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "No written response necessary ENGELKEN.R H Region 5, San Francisco. Office of the Director 79/03/10 lp
- 790608023D Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/18 1p
- DOCKET 50-289 THREE MILE ISLAND NUCLEAR STATION, UNIT (
  F Security, medical, emergency & fire protection plans
- 7906010212 Forwards description of test to be performed an asbestos board fire barriers protecting cable trays & conduits to comply w/fire protection SER. Item 3 2 2, cable separation Results will be submitted by 790715

  HERBEIN, J O Metropolitan Edison Co 79/05/18 7pp
- 7906260204 Responds to 790518 Itr re extra precautionary measures for area transmission sys Adequate sources of power are available for operation of unit VOLLMER.R H Assistant Director for Sits Analysis 79/05/19 sp
- ~~7906260208 Requests end of extra precautionary measures taken to assure adequate power to plants
  ARNOLD.R C General Public Utilities 79/05/18 1p
- --7906260211 Notifies that precautionary measures taken to maintain power supply are no longer necessary Personnel on standby at switching station are needed elswhere Forwards outline of electrical sys
  WERTS,R W general Public Utilities 79/05/03 3pp
- 7906080264 Responds to 790330 ltr re fire protection program of cable separation info requested was submitted in 790318 ltr Fire barriers to be modified per test results

  HERBEIN, J 0 Metropolitan Edison Co 79/05/24 ip
- 7906120373 Conveys results of field survey to determine fire resistance rating of unlabeled fire doors Forwards 790308 consultant rept Requests concurrence re replacement & labeling of fire doors HERBEIN, J O Metropolitan Edison Co 79/06/07 App
- I Financial information
- 7906120372 Forwards "Annual Financial Rept 1978" HERBEIN, J G Metropolitan Edison Co 79/06/07 ip
- --7906120380 "Annual Financial Rept 1978 "

  \* Metropolitan Edison Co \* GPU Service Corp 78/12/31 119pp
- J Insurance & indemnity information
- 7906210204 Forwards Endorsement 34 to MAELU Policy MF-73 GERETY, H F GPU Service Corp 79/06/15 2pp
- 7906230294 Forwards supplemental limit of liability endorsement to Policy NF-220. effective 790301 Supplemental limit does not apply to events re 790328 TMI incident BARDES, C.R. American Nuclear Insurers 79/06/18 3pp
- P Operating license stage documents & correspondence
- 7903210263 Amend 49 to License DPR-90 & Amend 9 to DPR-73, incorporating modified Amended physical security plan into license REIO, R. W Operating Reactors Branch 4 (Pro 790625) 79/02/23 4pp.
- 7904270044 Forwards info on TMT incident followup actions by NRC in response to 790412 memo HILLER, N. O License Fee Management Branch 79/04/13 3pp
- 7906290022 Describes major drawbacks to locating sampling sinks for both units in same room Unit 2 sink must be moved & all existing lines flushed before Unit 1 can be supported DUBIEL,R M Metropolitan Edison Co 79/04/24 2pp

- 7902220189 Forwards update of health physics status of facility Info was eent to LV Gossick for use in memo to NRC KINNEY,W W Region 1. Philadelphia, Office of the Director 79/05/07 3pp
- 790A070150 Confirms 790515 telcon w/J Holman & M Beers TMI training dept intends to resume licensed operator requalifiction program on 790521
  MILLERY, O P Metropolitan Edison Co 79/05/15 lp
- 7908200298 Discusses 781201 util response to NRC 781016 ltr re handling of heavy load within fuel handling bdig Util response inadequate Definition of special areas re load handling requires analysis & Tech Spec changes
  REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/17
- 7906210008 Discusses operational-related problem re startup Shortiy After 1976 unit outage leak developed in decay heat removal sys which was apparently never permanently repaired YURAS,O P Region 1. Philadelphia. Office of the Director
- 7704250152 Advises that proposed reduction in frequency of core flow rate verification is acceptable REID.R N Operating Reactors Branch 4 (Pre 790425) 79/05/17
- 7704010213 Forwards "B&W 177 Fuel Assembly Clumers' Group Asymmetric LOCA Loads Evaluation Program Phase 2" & "B&W 177 Clumers' Group Rept for Asymmetric LOCA Loads Evaluation.Phase 2 " MERBEIN.J G Metropolitan Edison Co 79705/18 ip
- --7906010218 "B&H 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluations Program Phase 2," dtd 790410 Metropolitan Edison Co 79/04/10 9pp
- --79060[0227 "B&W 177-Fuel Assembly Owners Group Assumptions, Methodology & Acceptance Criteria Rept for Asymmetric LOCA Loads Evaluation, Phase 2 " Petropolitan Edison Co BAW-1538 79/04/30 37pp
- 7904049231 Notifies of discharge of 7,400 gallons of water on 790514 b 7,100 gallons of water on 790515 Water released to influent of mechanical draft cooling tower discharge bypassing waste treatment sys TROFFER.G J Motropolitan Edison Co 79/05/24 2pp
- 7906280077 Notifies info requested by 790502 ltr re adequacy of station electric distribution sys voltage will be provided by 790801 HERBEIN, J G Metropolitan Edison Co 79/06/25 1p
- 7906290608 Forwards info in response to 790525 itr re feedwater line cracking Addi info will be submitted by 790727 HERBEIN, J G Metropolitan Edison Co 79/06/26 lipp
- G Inspection reports: IE Bulletins & correspondence
- 7906200334 Forwards IE Insp Repte 50-289//9-08 & 50-320/79-07 on 790319-23 & 26 No noncompliance noted ERUNNER, E J Region 1, Philadelphia, Reactor Operations Nuclear Bupport Branch 79/04/20 2pp
- --7908200339 IE Insp Repts 50-289/79-08 & 50-320/79-07 on 790319-23 & 28 No noncompliance noted Major areas inspected previous insp fundings, selected licensee events & licensee fallowup to prompt RO HAVERKAMP.D R , KEIMIO.R R Region 1. Philadelphia, Reactor Garrations Nuclear Sugport Branch 79/04/19 10pp
- 7906110016 Forwards IE Bullatin 79-09B, "Nuclear Incident at IMI-Suppl " No written response required ORIER, B H Region I, Philadelphia, Office of the Director 79/04/23 ip
- 7906070237 Responds to IE Bulletin /9-04 requesting review to determine if Velan swing check valves are installed in seismic Category I piping sys Valves not installed or scheduled to be installed at facility MERBEIN. J G Metropolitan Edison Co 79/05/01 ip
- 79D&1201&9 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER.8 H Region 1. Philadelphia. Office of the Director 79/05/07 2pp.

- 7906110135 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics " Written response required GRIER:8 H Region 1. Philadelphia. Office of the Director 79/05/11 1p
- Assemblies " Region 1, Philadelphia, Office of the Director 79/05/11 lp 7906260119 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
- 7906080087 Forwards IE Circular 79-08, "Attempted Extortion Low ORIER, BH Region I, Philadelphia, Office of the Director 79/05/18 ip
- 7906270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Bulletin 79-05B HILLIAMS,F J Division of Project Management 79/03/18 Jpp
- 7906150324 Forwards results of steam generator eddy current tube insp. performed 770225-0308 during 1977 refueling outage HERBEIN,J G Metropolitan Edison Co 79/06/08 2pp
- 7906270011 Lists IE bulletins issued since TMI incident which have been withheld due to lack of available util resources GRIER.B H Region I, Philadelphia, Office of the Director 79/06/08 2pp
- S Reportable occurrences, LERs & related correspondence
- 7906040326 Forwards LER 78-009/03L-0 HERBEIN, J C Metropolitan Edison Co 78/04/03 1p
- --7906040331 LER 78-009/03L-0 on 780315 dr breaker CB3 failed to trip on one of several tests Caused by apparent binding of breaker operating linkage Binding may have been due to insufficient exercise of breaker &/or lack of maint MITCHELL, D G Metropolitan Edison Co 78/04/03 2pp
- 7906040241 Forwards LER 78-011/03L-0 HERBEIN, J C Hetropolitan Edison Co 78/04/17 1p
- --7906040244 LER 78-011/03L-0 on 780318 during visual testing one snubber had no fluid in reservoir Caused by pinched rod wiper seal Snubber will be replaced b refilled MITCHELL,D G Metropolitan Edison Co 78/04/17 2pp
- 7906070366 RO 79-09/1p on 790327 during surveillance of turbine driven emergency seed pump, pressure regulating value MS-V-6 was found manually closed Unit was in hot shutdown Valve was opened & pump successfully tested SEELINGER.U. L. Metropolitan Edison Co 79/04/11 ip

- P Operating license stage documents & correspondence
- 7906260095 Notification of 790518 meeting w/util re status of seismic reanalysis per IE Bulletin 79-07
  RANNON J N Operating Reactors Branch 3 (Pre 790625) 79/05/17
- 7906120434 Notifies that current plans do not call for installation of containment atmospheric control sys Plans to submit summary description of proposed sys & proposed schedule of implementation by 79015
  ANDGONINI.O C Boston Edison Co 79/06/06 1ρ
- Q Inspection reports, IE Bulletins & correspondence
- 790614009B Forwards [E Insp Rept 50-293/79-03 on 790213-16 No noncompliance noted BRUNNERLE J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/26 2pp
- --7906:40113 [E Insp Rept \$0-293/79-03 on 7902:3-:6 No noncompliance noted Major areas inspected licensee action on previous insp findings ARCHITZEL.R Region i, Philadelphia, Office of the Director MCCABE.E C Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/23 Spp
- 79060B0100 Responds to 1E Bulletin 79-03 re weld defects in ASME SA-312 Type 304 stainless steel pipe spools Plant does not use subj spools ANDOGNINI, G C Baston Edison Co 79/04/17 1p
- 7906110006 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" No written response required ORIER, B. H. Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906070002 Responds to IE Bulletin 79-07 Discusses methods of analysis, program listings, program verification & plan of action & impact Computer code listing encl
  ANDGONINITO C Boston Edison Co 77/04/24 3pp
- 7906020200 Forwards response to 1E Bulletin 79-08, Items 1 -10 Response to Item 11 will be made within 30 days fraining program is being established Lista all vessel level instrumentation
  ANDOGNINI.G C Boston Edison Co 79/04/25 15pp
- 7906090435 Respond to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Lists installed valves by sys, number of valves & valve size ANDBONINI, O C Boston Edison Co 79/03/01 3pp
- 7906130161 Forwards IE Circulai 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 79/05/02 ip
- 7906120149 forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required CRIER, B H Region I. Philadelphia. Office of the Director 79/05/07 2pp
- 7906110115 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required ORIER.B H. Region 1, Philadelphia. Office of the Director 77/03/11 ip
- 7906260091 Forwards IE Info Notico 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906250300 Notification of 790516 meeting w/utils in Bethesda.MD to discuss status of seismic reanalysis per IE Bulletin 79-07 HANNON, J Decrating Reactors Branch 3 (Pre 790625) 79/05/15
- 7704270106 Bubmits addl response to IE Bulletin 79-04 Beismic & weight load safety assured per recalculations
  ANDOGNINI.G.C Boston Edison Co 79/05/17 2pp
- 7906090059 Forwards lE Circular 79-08, "Attempted Extortion Low Enriched U " ORIER.B H Region 1, Philadelphia, Office of the Director 79/05/18. ip

- 7906290775 Responds to IE Bulletin 79-10, "Requalification Training Program Statistics " Forwards util requalification training program statistics
  ANDOGRINI, G C Boston Edison Co 79/05/24 2pp
- 79060B0258 Responds to 790524 telcon request Forwards supplementary info re response to IE Bulletin 79-07 % snubber design ANDOGNIN1,G C Boston Edison Co 79/05/25 10pp
- 7906250286 Responds to IE Bulletins 79-01 % 79-01A re safety-related ASCO solenoid valves five such valves in use Analysis showed valves not unqualified Valves should not be subj to 24-h reporting ANDOGNINI.G C Boston Edison Co 79/06/15 2pp
- R Periodic operating reports & related correspondence
- 7906190248 Forwards montrily operating rept for May 1979 MCGUIRE, P.J. Philadelphia Electric Co. 79/06/11 tp
- --7906190250 Manthly operating rept for May 1979
  WHITNEY, G C Boston Edison Co 79/06/07 App
- S Reportable occurrences, LERs & related correspondence
- /906040212 Forwards LER 78-004/03L-0 MCGUIRE,P J Boston Edison Co 78/02/14 1
- ~~7906040217 LER 78~004/03L-0 on 780109 main steam line low pressura switches found to actuate at approx 35 psig below Tech Spec requirements Caused by limited setpoint drift Existing surveillance program considered adequate MATHIS.C J Boston Edison Co 78/02/16 Ip
- 7706120300 Forwards LER 79-018/01T-1 MCGUIRE,P J Boston Edison Co 79/06/06 1p
- --7906120305 LER 79-018/017-1 on 790519 recirculation pump started w/delta temp between loops greater than 50 F & reactor coolant temp greater than 212 F Caused by failure to follow station operating procedures & temp monitors MATHIS,C J Boston Edison Co NRC 79/06/06 ip
- DUCKET 50-294 MICHIGAN STATE UNIV RESEARCH REACTOR
- J Insurance & indemnity information
- 7906010206 Executed Amend 9 ta Indomnity Agreement 6-51 BALTZMAN, J Antitrust & Indomnity Group 79/05/18 ip
- a inspection reports, IC Builetins & correspondence
- 7906010078 Forwards IE insp Rept 50-294/79-03 on 790327-28 Notice of Violation withheld (ref 10CFR2 790)
  HIND, J A Region 3. Chicago, Diffice of the Director 79/04/30 2pp
- --7906010079 IE Insp Rept 50-294/79-03 on 79032/-28 Noncompliance noted re keys, locks & hardware Details withheld (ref 10CFR2 790) CHRISTOFFER Region 3, Chicago, Office of the Director HIND, J A Region 3, Chicago, Safeguards Branch 79/04/30 1p
- 7905190060 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11 ip
- 7904080172 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/18
- S Reportable occurrences, LERs & related correspondence
- 7905290444 Advises of incident on 790613 fuel temp indication dropped to zero during full power operation Caused by failure of thermocouples in 85 serial number 7833 fuel element Meter connected to other fuel element CARRICK, J Michigan State Univ 79/06/22 1p

- GOCYET 50-295 Zion Nuclear Power Station, UNIT 1

  F Security, medical, emergency & fire protection plans
- 750&120240 Forwards status rept of unfinished mod required to improve level of fire protection All mods completed except for gas suppression sys,fire doors & reactor toolant pump REED.C Commonwealth Edison Co 79706706 Bpp
- G Adjudicatory correspondence
- 7903210375 Informs of document containing info patentially relevant to issue of sabotage of spent nuclear fuel & of NRC assessment of info to be made available GODBARD.R J Branch 2 79/02/26 2pp
- 7905080128 Forwards M Resnikoff 790409 itr re testimony in proceedings SEKULER. S N lilinois, State of 79/04/12 2pp
- 7906040145 Notifies that hearing will be held at Zion.IL on 790611-15, & 790620-23.if needed Limited appearances will be received on 790611 LUTON.E Atomic Safety and Licensing Board Panel 79/04/23 ip
- 7708010266 Answers NRC 770409 interrogatories Add1 info will be filed when available Certificate of Svc enc1
  SEKULER.S N 111:nois, State of 79/04/27 6pp
- 7706190091 Complaint for injunctive relief in City of Lancaster v NRC filled in DC US District Court Seeks enjoiment of radioactive discharge CIMA, T Concerned Citizens of Lake County, IL 79/05/03 ip
- 7906280137 Forwards ASLB 790418 order in which questions of proposed mods were added in light of TMI incident If similar questions are to be considered in current proceeding. State of IL prepared to submit testimony SEXULER. S N Illinois. State of 79/03/08 ip
- 7704270613 Stipulation between NRC & intervenor State of IL NRC withdraws motion for summary disposition of Contention 2(d) State, in turn, withdraws contention but reserves right to submit testimony on all alternatives W
- 7904260214 Orders time change for 790611 evidentiary hearing Hearing will start at 2 PM instead of 9 AM LUTON.E Atomic Safety and Licensing Board Panel 79/06/04 ip
- 79062700B1 Notice of reconstitution of ASLR JF Wolf replaces E Luton as Chairman LAZO.R M Atomic Safety and Licensing Appeal Panel 79/06/05 ip
- J Insurance & indemnity information
- 7905040187 Forwards executed Amends 21.11.9 % 1 to Indemnity Agreements B-10.8-47.8-59 % B-84, respectively PCOLE.R D Communusalth Edison Go 79/05/29 8pp
- 7906200290 Forwards Endorsements 41 % 42 to MAELU Policy MF-64 OSTER, J Commonwealth Edison Co 79/06/12 3pp
- P Operating license stage documents & correspondence
- 7906180707 "In-Plant Source Term Measurements at Zion Station "DYER.N C , BUNTING,R L , CRONCY,S T, EQ & G, Inc NUREG/CR-0715 79/02/28 400pp Available at NTIS
- 7906200959 Forwards Amends 47 & 44 to Licenses BPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability SCHMENCER, A Operating Reactors Branch 1 (Pre 790629) 79/04/09.
- --7906200565 Safety evaluation supporting Amends 47 & 44 to Licenses DPR-39 & DPR-48 respectively 4 Operating Reactors Branch 1 (Pre 790625) 79/04/09 3pp
- 7905180782 Forwards FR notice of proposed issuence of amends to facility OL SCHMENCER.A Operating Reactors Branch 1 (Fre 790625) 79/04/27

- 7908200239 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station number of unsite & offsite environ monitoring stations & site maps used for dose determinations REPPLER, J O Region 3, Chicago, Offsice of the Director 79/05/17
- 7906070192 Accepts Revision 7 to Addendum 1 of CE-1-A Revision discusses organizational changes in GA program RASSE NP Quality Assurance Branch 79706/06 1p
- 7706200335 Responds to TE Bulletin 79-01 Forwards info re environ qualification of Class IE equipment required to function under accident conditions & info re use & maint of ASCO solenoid valves

  REFD.C. Commonwealth Edison Co. 77/06/14 39nn
- 7906250293 Forwards info re PWR feedwater lines, in response to V Stello 790528 request Ten oversized drawings in Central Files REED, C Commonwealth Edison Co 79/06/19 14pp
- 790A270179 Notifies of necessity of eramination of feedwater lines to determine mods J-tubes will be installed in seven steam generators Evaluation of setpoint of water actuation will determine revision
  REED, C. Commonwealth Edison Co. 79/06/20 4pp
- G Inspection reports. IE Bulletins & correspondence
- 7904020055 Forwards IE Insp Repts 50-295/79-03 & 50-304/79-03 on 790312-16 No noncompliance noted DAVIS.A B Region 3. Chicago. Fuel Facility & Materials Safety Branch 79/04/05. 2pp
- --7904020065 IE Insp Repts 50-295/79-03 % 50-304/79-D3 on 790312-16 No noncompliance noted Major areas inspected emergency planning activities including generating stations emergency plan & confirmatory measurements insp

  GEGTMANN, M J . EBS10.T H Region 3. Chicago. Office of the Director 79/04/03 iOpp
- 7906040045 Forwards IE Insp Repts 50-299/79-02 \$ 50-304/79~02 on 790306-07 \$ 27-28 No noncompliance noted FIORELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906040052 IE insp Repts 50-295/79-02 t 50-304/79-02 on 770306-07 t 27-28 No noncompliance noted Major areas inspected steam generator snubbers, pipe snubber installation, review of licensee records, mechanical snubber tests to unresolved (tems YIN, I T. DAMIELEON, D.H. Region 3, Chicago, Office of the Director 79/04/05 6pp
- 7906120083 Forwards IE Info Notice 77-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/09/07
- 7906140253 Responds to JE Bulletin 77-04 Lists Velan Engineering Corp valves identified as having incorrect weight values in seismic piping analysis
  REED.C Commonwealth Edison Co 79/05/07 3pp
- 7906110101 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER.J 9 Region 3, Chicago, Office of the Director 79/05/11
- 7906190078 Forwards IC Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11
- 7906230118 Provides add1 info to 790427 ltr Responds to IE Bulletin 79-06A Updated Items 4 & 12 re identification of valves having control switches are returnable to pre-TMI incident position Plan to use hydrogen recombiner units REED:C Toledo Edison Co 79/05/17 3pp
- 7906090196 Forwards IE Circular 77-08, "Attempted Extortion Low Enriched U " KEPPLER: J O Region 3, Chicago, Office of the Director 79/05/18
- 7904130082 Forwards IE Bulletin 79-11, "Faulty Overcorrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee Action required KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/22

- 7906200080 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J.G. Region 3. Chicago, Office of the Director 79/05/29
- R Perfodic operating reports & related correspondence
- 7906290122 Forwards "Environ Monitoring in Lake Mi." for Jan 1970-Sept 1978 HANDKE.N E Commonwealth Edison Co. 79/06/01 ip
- --7906290127 "Environ Monitoring in Lake MI." for Jan 1970-Sept 1968.by Marleton Environ Sciences Corp \* Commonwealth Edison Co 79/06/01 513pp
- 7906120343 Forwards monthly operating rept for May 1979 WANDKE,N E Commonwealth Edison Co 79/06/08 lp
- --7906120349 Monthly operating rept for May 1979
  JEFFERS, J. Commonwealth Edison Co. 79/06/08 lipp
- S Reportable occurrences, LERs & related correspondence
- 7906040272 Forwards LER 79-032/03L-0
  WANDKE, N E Commonwealth Edison Co 79/05/18 1p
- --7905060295 LER 79-032/03L-0 on 790420 blower tripped on containment vent particulate monitor, resulting in low flow Caused by thermal overload due to dust blocking pump vent Vent cleaned 5 monitor tested 5 returned to svr
- 7706040325 LER 79-001 has been voided \* Commonwealth Edison Co 79/06/01
- 7906040327 LER 79-010 has been voided \* Commonwealth Edison Co 79/06/01 10
- 7906040330 LER 79-014 has been voided \* Commonwealth Edison Co 79/04/01 1p
- 7906110129 LER 79-012 has been voided \* Commonwealth Edison Co 79/06/01
- 7906140416 Forward's LER 79-012/99X-0 WANDKE, N E Commonwealth Edison Co 79/06/01 ip
- --7906140418 LER 79-012/99X-0 on 790327 safety injection initiated due to HI steam flow signal coincident w/low steam pressure bistables tripped for surveillance testing Gaused by setpoint dropping to 40% during inadvertant reactor trip JOOSTEN.J Commonwealth Edison Co 79/06/01 4pp
- 7906270207 Forwards LER 79-019/99x-0 WANDKE,N E Commonwealth Edison Co 79/06/15 1p
- --7906270208 LER 79-019/99x-0 on 790316 inadvertent safety injection occurred from false steam pressure differential signal in loop B.initiated by waterhammer in IC feedwater line Caused by false signal ASCO solenoid valve replaced "DOSTEN, J K Commonwealth Edison Co 79/06/15 3pp
  - 70212 Forwards LER 79-040/03L-0 DXE.N E Commonwealth Edison Co 79/06/19 1p
  - 5270214 LER 79-040/03L-0 on 790523 during periodic testing, steamline solution signal developed on train A MSIV IB failed to lose. Caused by do solenoid directional control valve ticking in de-energized position Valve replaced TLNICOFF, M A Commonwealth Edison Co 79/06/19 ip
  - 70162 Forwards LER 79-041/03L-0 KE:N E Commonwealth Edison Co 79/06/21 1p
  - 270164 LER 79-041/O3L-O on 790522 during normal operation essurizer spray valves opened to 50% demand & RCB pressure creased below Tech Spec limit Caused by operator bumping identionmeter on pressurizer master controller NGER-K A Commonwealth Edison Co 79/06/21 1p
  - ring transcripts on non-antitrust matters
  - 0554 Transcript of 790611 hearing in Zion, IL Pp 288-481 .J., REMICK, F.J., LITTLE, L.W. Atomic Safety and Licensing Board l. 79/06/11 19pp

- 7906260558 Transcript of 790612 hearing in Zion, IL, Pp 482-701 HOLF, J., REMICK, F.J., LITTLE, L. W. Atomic Safety and Licensing Board Panel 79/06/12 219pp
- 7906270560 Transcript of 790613 hearing in Zion, IL re spent fuel poolerpansion Pp 702-955
  HOLF, J., REMICK, F. J., LITTLE, L. H. Atomic Safety and Licensing Board
  Panel 79/06/13 253pp
- 7906290047 Transcript of 790614 meeting in Zion, IL Pp 956-1194 WDLF,J , REMICK,F J , LITTLE,L W Atomic Safety and Licensing Board Panel 79/06/14 240pp
- 7906290082 Transcript of 790615 hearing in Zion, IL Pp 1195-1365 Testimony & qualifications of JE Draley enci HOLF, J., REMICK, F. J., LIITLE, L. W. Atomic Safety and Licensing Board Panel 79/06/15 200pp
- BOCKET 50-296 BROWNS FERRY NUCLEAR POWER STATION, UNIT 3 J Insurance & indemnity information
- 7906080229 Forwards Endorsements 40 & 41 to MAELU Policy MF-66 FIELDER, J. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div. 79/06/04 3pp
- P Operating license stage documents & correspondence
- 7906190134 Forwards Amends 50, 44, 22 to License DPR-33, DPR-52 % OPR-68, respectively, safety evaluation & notice of issuance & availability re-mods to standby gas treatment sys IPPOLITO, T.A. Operating Reactors Branch 3 (Pre 790625) Зор 79/05/04
- --7906190139 Amends 50.44 & 22 to Licenses DPR-33.DPR-52 & DPR-68, respectively, modifying electrical controls & instrumentation for standby gas treatment sys IPPOLITO.T A Operating Reactors Branch 3 (Pre 790625) 79/05/04 20pp
- --7906190145 Safety evaluation supporting Amends 50,44 & 22 to Licenses DPR-33 & DPR-52 & DPR-68 respectively

  \* Operating Reactors Branch 3 (Pre 790625) 79/05/04 5pp
- --7906190160 Notice of issuance of Amends 50.44 & 22 to Licenses DPR-33. DPR-52 & DPR-68, respectively IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625) 79705704 Rep
- 79062500B8 Forwards Amends 51.45 & 23 to Licenses DPR-33.DPR-52 & DPR-6B; respectively, rafety evaluation & notice of issuance & availability IFPOLITO, T A Operating Reactors B; anch 3 (Pre 790625) 79/05/11 200
- --7906250094 Amends 51.45 & 23 to Licenses DPR-33, DPR-52 & DPR-68. respectively, authorizing change of power supply for certain low pressure colant injection valves IPPOLITO FA Operating Reactors Branch 3 (Pre 790625) 79/05/11 6pp
- --7906250099 Safety evaluation supporting Amends 51,45 & 23 to Licenses DPR-33,DPR-92 & DPR-68,respectively & Operating Reactors Branch 3 (Pre 790625) 79/05/11 lOpp
- ---7906250103 Notice of issuance & availability of Amends 51,45 & 23 to Licenses DPR-33, DPR-52 & DPR-68, respectively IPPOLITO,T A Operating Reactors Branch 3 (Pre 790625) 79/05/11 2pp
- 7906120378 Forwards addit revisions & relief requests to inservice pump & value testing program Revisions are based on review of facility design for compatability w/ASME Section XI requirements GILLELAND, J.E. Tennessee Valley Authority 79/04/04 7pp
- 7906190301 Forwards general info re purge operations & analysis of purge valve operability of CILLELAND. J E Tennessee Vailey Authority 79/06/12 21pp
- 7906210195 Forwards "Secondary Containment Leak Rate Test, 90-Day Rept "OILLELAND, J E Tennossee Valley Authority 79/06/19 ip
- --7906210199 "Becondary Containment Leak Rate Test.90-Day Rept " \* Tennessee Valley Authority 79/05/11 26pp

| |

f,

- @ Inspection reports, IF Bulletins & correspondence
- 7906180710 Forwards IE Insp Repts 50-259/79-08,50-260/79-08 & 50-296/79-08 on 790209-0302 No noncompliance noted LEMB,R C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 2pp
- --7904180714 IE Insp Ropts 50-239/79-08, 50-260/79-08 & 50-276/79-08 on 790208-0302 No nancompliance noted Major areas inspected ROs, plant dewatering & fire protection sys & plant physical protection SULLIVAN.R F. DANCE.H C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/26 Spp
- 7906070378 Responds to IE Bulletin 79-07 Forwards results of seismic stress analysis of cafety-related piping dillerand, J E Tennessee Valley Authority 79/04/24 3pp
- 7706130151 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/02 in
- 7906210397 Ack receipt of 770418 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-260/79-06. 30-269/79-06 & 50-296//9-06 LEUIS.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/09 1p
- 7906110066 Forwards II Dulletin 19-10, "Requalification Training Program Statistics" Written response required d'AEILLY, J.P. Region 2. Atlanta, Office of the Director 79/09/11 1p
- 7906;40.45D Forwards add1 response to IE Bulletin 79-04 re incorrect valve weights Reactor core isolation cooling piping reanalyzed using correct weight of Volan swing theck valves OILLELAND.JE Tennessee Valley Authority 79/05/11 Bpp
- 7905290715 Responds to 16 Builstin 79-09 to GE Type AK-2 breakers Breakers used in safety-related eys at plant, none found equipped w/undervultage trip device OfficeLAND, J E Tennossee Valley Authority 79/05/21 Spp
- R Periodic operating reports & related correspondence
- 7906150279 Forwards monthly operating rept for May 1979
  DEHEASE, J O Tennesses Valley Authority 79706/11 1p
- --7906150283 Monthly operating rept for May 1979
  DENEASE, J. O. Tonnessee Valley Authority 79/05/31 34pp
- 7906220369 Forwards revision to "Frviron Radioactivity Levels, Annual Rept 1978" to supersede rept issued 790427 Revision corrects some radioactive levels Conclusions in original rept are still valid
  011.LELAND, J. E. Tennessee Valley Authority 79/06/18 1p
- --7906220374 "Environ Radioactivity Levels, Annual Rept 1978," revised version
   Tennessee Valley Authority RH-79-3-8F2 78/12/31 48pp
- 8 Reportable accurrences, LERs & related correspondence
- 7906120377 Forwards LCR 79-006/03L-0
  FDX:H S Tennessos Valley Authority 79/06/05 1p
- --7906120381 LER 79-006/03L-0 on 790307 observed erratic indication of torus hydrogen sensor H2M-76-38 Caused by defective sensor Fart replaced

  # Tennessee Valley Authority, 79/06/05 2pp
- DOCKEY BO-297 NORTH CAROLINA STATE UNIV PULSTAR REACTOR

  1 Inspection reports, IE Bulletins & correspondence
- 7906070DB1 Ack receipt of 790417 ltr informing NRC of steps taken to torrect violations noted in IE Insp Repts 50-111/79-02 & 50-297/79-02 LEMISrR.C Region 2. Atlanta, Bafeguards Branch 79/04/27 ip

- --7906070083 Responds to NRC 790403 ltr re violations noted in IE Insp Repts 50-111/79-02 & 50-297/79-02 Corrective actions procedures for reporting component failures to higher officers will be implemented by 790511 ELLEMAN.T S North Carolina State Univ 79/04/17 2pp
- --7906070087 Forwards IE Insp Repts 50-111/79-02 & 50-297/79-02 on 790313-16 & notice of violation LEMIS.R C Region 2, Atlanta, Safeguards Branch 79/04/03 2pp
- --7906070090 Notice of violation from insp on 790313-16
  \* Region 2, Atlanta, Office of the Director 79/04/02 ip
- --7904070095 IE Insp Repts 80-111/79-02 & 50-297/79-02 on 790313-16
  Noncompliance noted failure to develop procedures required
  to establish 10CFR21 program & failure to document &
  approve temporary procedure change
  DANCE.H C Region 2. Atlanta, Safeguards Branch JULIAN, C A
  HCHENRY, T J Region 2. Atlanta, Office of the Director
  79/04/02 7pp
- 7904210331 Ack receipt of 790419 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-111/79-01 50-297/79-01 & 70-0041/79-01 Region 2, Atlanta, Safeguards Branch 79/05/03 1p
- --7906210354 Responds to NRC 790327 ltr re violations nated in IE Insp Repts 50-111/79-01,50-297/79-01 & 70-0041/79-01 Corrective actions Form 742 prepared properly & copy for period Oct 1978 - Mar 1979 forwarded to Region II ELLEMAN, T S North Carolina State Univ 79/04/19 10
- --7906210389 Forwards IE Insp Repts 50-111/79-01.50-297/79-01 & 70-0041/79-01 on 790220-21 Notice of violation withheld (ref 10CFR2 790) KENNA,U B Region 2, Atlanta, Bafeguards Branch 79/03/27 200
- --7906210396 IE Insp Repts 50-iii/79-01.50-297/79-01 & 70-0041/79-01 on 790220-21 Noncompilance noted failure to measure & rept accountability values re production & consumption of SNM Details withheld (ref 10CFR2 790) TODD,0 A , WILLIAMS,0 H Region 2, Atlanta, Office of the Director 79/03/08 ip
- 79G6250414 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 is

# DOCKET 50-298 COOPER NUCLEAR STATION J Insurance & indemnity information

- 7906260537 Forwards Endorsements 36 & 37 to MAELU Policy MF-70 PILANT, J M Nobrasta Public Power District 79/06/20 3pp
- P Operating license stage documents & correspondence
- 7906140324 Notification of 790510 meeting w/util & Nuclear Power Consultants, Inc. to discuss responses to 790313 GA questions.
  ROONEY, V L Operating Reactors Branch 3 (Pre 790625) 79/05/01
- 7906260126 Forwards Amend 54 to License DPR-46, safety evaluation & notice of issuance & availability
  1PPOLITO T. A Operating Reactors Branch 3 (Pre 790625)
  79/05/23 3pp.
- --7906260333 Amend 56 to License DPR-46 adding conditions for completion of mods & implementation of administrative controls for fire protection IPPOLITOLT A Operating Reactors Branch 3 (Pre 790625) 79705/23 2pp
- --7906260141 Fire protection safety evaluation supporting Amend 56 to License DPR-46 \* Office of Nuclear Reactor Regulation 79/05/23 53pp
- ---7906260148 Notice of issuance & availability of Amend 56 to License DPR-46 [PPDLITO.T A Operating Reactors Branch 3 (Pre 790625) 79/09/23 2pp
- 7906050270 Forwards addl info & revision to 790109 QA program for operation, per Section 8 of FBAR Amend 39 PILANT, J M Nebraska Public Power District 79/05/25 App

- --7906050271 Addl into & revision to 770109 QA program for operation

  \* Nebraska Public Power District 77/05/25 14PP
- 7906060148 Porwards "Proposed Radiological Effluent Tech Specs."
  "Offsite Dose Assessment Manual" & "Radiological Environ
  Monitoring Manual"
  PILANT, J. M. Nebraska Public Power District 79/05/25 Opp
- --7906060151 "Proposed Radiological Effluent Tech Specs"

  \* Nebraska Public Power District 79/06/06 63pp
- --7906060155 "Offsite Dose Assessment Manual"

  \* Nebraska Public Power District 79/06/06 80pp
- --7906060159 "Radiological Environ Monitoring Manual " # Nebraska Public Power District 79/06/06 40pp
- 7906050272 Forwards results of analysis performed by GE to suppression pool temp transients Will revise station operating procedure by 790615 to depressurite reactor vessel PILANT, J M Nebraska Public Power District 79/05/29 44pp
- 7906)20257 Requests that NEDD-24612, "Yent Header Deflector Load Definition," be included in docket PILANT, J. M. Nebraska Public Power District 79/06/01 1p
- 7906190392 Requests that NEDE-25090-P. NEDE-21471-2 & NEDE-14537-P be included in docket Repts were transmitted to NRC by GE.in support of facility containment avaiuation program PILANT. J M Nebraska Public Power District 79706/11 2pp
- 790629028! Requests radiological Tech Specs, by revised to allow personnel access to deinerted drywell for insp & probable repair of defective transient incore probe guide tube Repair work will take place during June plant shutdown P[LANY.] M Nebraska Public Power District 79/06/21 4pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906040205 Responds to IE Bulletin 79-03 Util has no intention of using ASME SA-12 Types 304 & 316 stainless steel pipes spools mfg by Youngstown Helding & Engineering Co PILANT, J M Nebraska Public Power District 79/04/12 1p
- 7906260180 Forwards IE Insp Rept 50-298/79-06 on 790326-28 No noncompliance noted MADSEN.G L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/19 2pp
- --7906260186 [E Insp Rept 50-298/79-06 on 790326-28 No noncompliance noted Major areas inspected document control, corporate level QA audits, offsite review committee function & offsite support staff
  CONSTABLE. Q L , JOHNSON, E H , MADSEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/18 7pp
- 7906110053 Responds to IE Bulletin 79-07, "Seismic Stress Analysis of Safety-Related Piping " Re-evaluation of safety relief valve discharge piping will be completed by approx 790521 Forwards summary of verification programs PILANT, J K Nebraska Public Power District 79/04/24 6pp
- 7906290341 Responds to IE Bulletin 79-00 Forwards results of review of BMR sys designs & operational procedures
  PILANT, J M Nebraska Public Power District 79/04/25 4pp
- 7906070373 Responds to IE Bulletin 79~04. "Incorrect weights for Swing Check Valves Mfg by Velan Engineering Corp " One piping sys in 4eismic Category I is affected PLANT.J M Nebraska Public Power District 79/05/01 App
- 7906130137 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Sat Resulted in Reactor Power Increase " No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/02 is
- 7906it0043 Responds to IE Bulletin 79-09. "Failure of QE Type AK-2 Circuit Breakers in Safety-Related Sys." OE Type AK-2 circuit breakers are not in use or planned for use at facility PILANT, J M Nebraska Public Power District 79/05/04 ip
- 7904120071 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRITIK V Region 4, Dalias, Office of the Director, 79/05/07

 $\| u_{i,j} - 1 \|_{L^{\infty}(\mathbb{R}^n)} \leq \frac{1}{n} \varepsilon$ 

La diamenta

- 7906110084 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 79/05/11
- 7906250023 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/11
- 7906250115 Discusses IE effort to develop insp method to evaluate procedural deficiencies that can lead to increased human error Site will be visited by contractor to obtain info for review HADSEN, G. E. Region 4, Dallas, Reactor Operations Nuclear Support Reactor 79/05/23 10
- 790220004: Forwards IC Info Notice 79-13, "Indication of Low Nater Level in Dyster Creek Reactor" SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906130294 Forwards monthly operating rept for May 1979 LESSOR.L C Nebraska Public Power District 79/06/04 1p
- --7906130297 Monthly operating rept for May 1979 BORER,F J Nebraska Public Power District 79/06/04 4pp
- S Reportable occurrences, LERs > related correspondence
- 7906180145 Forwards PNO-79-67AM MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/05/09 ip
- 7906180196 Forwards PNO-79-67AN
  MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support
  Branch 79/05/15 1p
- 7906080251 Forwards LER 79-008/03L-0 LESSOR.L C Nebraska Public Power District 79/05/18 2pp
- --7706080252 LER 79-008/OSL-0 on 770420 broaker IFA failed to trip when control switch operated to trip Caused by failure of auxiliary switch contact mounted inside breaker IFA to make proper electrical contact Breaker inspected & cleaned BEDNAR, LF Nebraska Public Power District 79/05/18 ip
- 7904080235 Forwards LER 79-009/03L-0 LESSOR,L C Nebraska Public Power District 79/05/22 3pp
- --7906080236 LER 79-009/03L-0 on 790430 four penetrations found leaking excessively during local leak rate test Caused by defects in limitorque operator torque switch, seal rings & check valves All defects repaired PHILLIPS.D L. Nebraska Public Power District 79/05/22 1p
- 7906080253 Forwards LER 79-011/03L-0 LESSOR.L C Nebraska Public Power District 79/08/23 2pp
- --7906080254 LER 79-011/03L-0 on 790424 reactor water cleanum MO-18 contactor failed to close manually during cold shutdown Caused by failure of auxiliary contact mechanism Repairs completed per IE Bulletin 78-05 SCHEER.J L Nebraska Public Power District 79/05/23 ip
- 7906080309 Forwards LER 79-010/03L-0 LESSOR.L C Nebreska Public Power District 79/05/23 2pp
- --,706080311 LER 79-010/03L-0 on 790424 surface linear indication found in weld RA3-CF-13 main steam to A & B RHR heat exchangers & HPCI turbine Caused by welding error Defect removed BOAN,P F Nebraska Public Power District 79/05/23 1p
- 7904080280 Forwards LFR 78-034/03X-1 LESSOR.L C Nebraska Public Power District 79/03/24 2pp
- --7906080286 LER 78-034/03X-1 on 781111 during performance of withdrawal control rod operability, control rod 30-31 was found uncoupled from control rod drive Caused by improper assembly of uncoupling of control rod drive Unit was replaced BALLINGER.P Nebraska Public Power District 79/05/24 1p
- 7906180295 Forwards PND-79-67AD & AP MADSEN.Q L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/24 ip

- EGCKET 50-301 POINT BEACH NUCLEAR PLANT, UNIT 2

  F Securate, medical, emergency & fire protection plans
- 7906200164 Documents DJ Ivey 790608 telcon w/JS Berggren re util security plan Encl withheld (ref 10CFR2 790) FEED,O A Wisconsin Electric Power Co 79/06/11 ip
- H Qeneral correspondence
- 7906040199 Responds to 790228 ltr transmitting petition on NRC-imposed gatehouse security processing of regular plant employees
  Discusses means of dealing w/spocific concerns Codes of
  Federal Regulations excerpt encl
  FELTON.J M Division of Rules and Records 79/04/13 4pp
- --7906040203 Returns 790228 petition.re gatehouse security for plant employees & proposed response Advises treatment as petition for rulemaking under 10CFR2 206
  REIS,E J Branch 3 79/03/22 1p
- J Insurance & indemnity information
- 7708070193 Forwards executed Endorsements 57,58 & 59 to NELIA Policy NF-178.& Endorsements 48,49 & 50 to MAELU Policy MF-53 DUNDAS,H J Wisconsin Electric Power Co 79/05/31 7pp
- P. Operating license stage documents & correspondence
- 7908200312 Summary of 770424 meeting w/util & Hestinghouse in Bethesda, KD re dash pot end cap cracks on Westinghouse DB-50 & DB-75 aftr circuit breakers list of attendees, schematic design & tripping characteristics encl IRAMHELL C M Operating Reactors Branch 1 (Pre 790825) 79705/02 7pp
- 7906200330 Summary of 770511 meeting w/util in Bethesda.HD re auxiliary feedwater sys List of attendees & matl discussed encl TRAMHELL.C M Operating Reactors Branch 1 (Pre 770625) 79/03/15 4pp
- 7908250056 Summary of 790512 meeting w/Northern States Power Co re auxiliary feedwater sys & related areas GRUTENHUIS.M Operating Reactors Branch 1 (Pre 790825) 79/05/16 App
- 790A210324 Requests two controlled copies of gite emargency plan & implementing procedures, site maps showing location & grid station numbers of dosite & offsite environ monitoring stations & maps used for offsite dose determinations KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/17
- 7906190315 Submits response to 790607 questionnaire re monitoring nable gaseous efficients
  BURBEIN.S Wisconsin Electric Power Co 79/06/12 3pp
- 7906220181 Submits info re feedwater lines to steam generator in response to 790525 request Feedwater pipe to feedwater nozzle welde to be examined for cracking during first week of Jul 1979
  FAY.C W Hisconsin Electric Power Co 79/06/20 Bpp
- 7906290237 Bubmits responses to 790619 telcon inquiries re reactor vessel support structures One oversized drawing encl BURSTEIN B Hisconsin Electric Power Co 79/06/25 3pp
- Inspection reports, IE Bullatins & correspondence
- 7906210311 Forwards IE Insp Rept 50-301/79-05 on 790327-28 & 0405 No noncompliance noted FIORELLI.O. Region 3. Chicago, Reactor Construction & Engineering Support Branch 77/04/18 2pp
- --79062[0317 IE Insp Rept 50-301/79-03 on 790327-28 & 0405 No noncompliance noted Major areas inspected GA/GC programs, [mplementing procedures, work activities & various data review HILLIAMS.C.C., DANIELSON,D.H. Region 3, Chicago, Office of the Director. 79/04/17 App
- 7906020133 Responds to IE Bulletin 79-07 Four cases associated w/gaseous & liquid radwaste sys at plant have been reanalyzed All pipe stresses & support & constraint loads are within acceptable limits
  BURBTEIN.8 Wisconsin Electric Power Go 79/05/02 is

- 7906040027 Responds to IE Bulletin 79-04 re weights of swing check valves Forwards List of piping sys where valves are installed Results of review to be provided when available BURSTEIN,S Nisconsin Electric Power Co 79/05/02 App
- 7906020182 Discusses faulty overcurrent trip delay devices in engineered safety feature circuit breakers Forwards draft bulletin.util's notification.Westinghouse press release. Westinghouse technical Euletin & AEC operations bulletin EISENHUT,D 9 Assistant Director for Systems Engineering HANAUER.8 Office of the Executive Director for Operations 79/03/04 14pp
- 7906120132 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J 9 Region 3. Chicago. Office of the Director 79/05/07
- 7906050120 Ack receipt of 790323 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-266/79-02  $\uptheta$  50-301/79-01 HIND.J A Region 3, Chicago, Safeguards Branch 79/05/08 1p
- --7906030122 Responds to NRC 790302 itr re violations noted in IE lnsp Repts 50-266/79-02 \$ 50-301/79-01 Corrective actions withheld (ref 10CFR2 790) BURSTEIN, S Wisconsin Electric Power Co 79/03/23 App
- 7906110110 Forwards IE Sulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190106 Forwards IE info Notice 79-12. "Attempted Damage to Now Fuel Assemblies" KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11
- 7906080207 Forwards 1E Circular 79-08, "Attempted Extortion Low Enriched V" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7906130120 Forwards IE Buitetin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " License action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/22
- 7906200142 Forwards IE info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906190319 Forwards monthly operating rept for May 1979 BURSTEIN,S Wisconsin Electric Power Co 79/06/08 1
- ---7906190321 Monthly operating rept for May 1979
  \* Wisconsin Electric Power Co 79/06/05 9pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906060257 Forward

#### J Insurance > indemnity information

- 7906190457 Forwards Endorsements 25.26 & 27 to MAELU Policy MF-91 DUCK, J R Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/12 Gpp '
- P Operating license stage documents & correspondence
- 7906180571 Notification of 790501 meeting w/util in Bethesda.MD to discuss details of safety concerns at facility resulting from TMI-2 accident NELSON.C C Operating Reactors Branch 4 (Pre 790625) 79/04/30
- 7906250156 Responds to 790329 ltr re proposed mods to reactor coolant flow sensing sys Forwards safety evaluation mods Mods must be implemented prior to restart from current refueiing outage REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/L1
- ---7906250162 Safety evaluation supporting mod of design of redundant instrument sensing lines for reactor coolant flow preating Reactors Branch 4 (Pre 790625) 79/05/11 2pp
- 7906270023 Summary of 790517 Affirmation Session 79-13 in Washington. DC Orders to shot down reactor for reasons of increased safety & reliability were approved CHILKS J. Office of the Secretary of the Commission 79/05/17
- 7906270274 Notifies that review of 790228 submittal re Cycle 2 reload requires addl info REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/23 App
- 7904080285 Forwards add1 info re Cycle 2 5 physics startup questions.in response to 790523 request STEMART.W P Florida Power 5 Light Co 79/05/31 9pp
- 7906110152 Submits plans to implement permanent solution to ECCS small breaks analysis problem Requests elemption be granted to provisions of IOCFRSO 46 to operate at licensed core thermal power until 790806
  STEWART, W P Florida Power Corp 79/06/05 6pp
- 7906120278 Forwards Tech Specs Figure 2 1-1 & Bases Figures 2 1, redrawn on graph paper. 6 Figures 3 1-9 & 3 2-2 redrawn to more accurately depict break points on respective curves BRIGHT,R M Florida Power Corp 79706/06 5pp
- 7904120386 Responds to NRC 780202 ltr Discusses new design for reactor cavity annulus seal ring support sys Bescribes interim operating procedure until new sys installed STEWART: W P Florida Power & Light Co 79/06/06 3pp
- 7906120236 Forwards revised response to 790331 submittal of add1 info re physics startup test program STEMART.W P Florida Power Corp 79/06/08 3pp
- 7906220204 Forwards comparison between key parameters used in B&W small breaks analyses & actual parameters of facility, in response to NRC review team request B&W analysis applicable to facility
  STEMARTUR P Florida Power Corp. 79/06/15 388
- 7906260220 Ack receipt of NRC 790525 request for add1 info re feedwater lines for plant steam generators W/15 oversized drawings SYEWART,W P Florida Power Corp 79/06/19 Hgp
- 7906280120 Forwards revised design mods to reactor trip on loss of feedwater flow or turbine trip Completes util responses to NRC review team concerns re design changes proposed in 790501 ltr STEWART, W P Florida Power Corp 79/06/22 30pp
- G Inspection reports, LE Bulletins & correspondence
- 7906290302 BbW site inspector daily rept on 790407 Plant status reactor operating at 75% power ω/all emergency safety features in svc. Refueling outage scheduled for 790423 MCHENRY, T.J., QUICK Region 2. Atlanta. Office of the Director 79/04/07 2pp
- 7906290169 BAW site inspector daily rept on 790408 Plant status reactor operating at 75% capacity w/one coolant pump shut down due to seal leakage
  MCHENRY.T J., QUICK Region 2. Atlanta, Office of the Director, 79/04/08 2pp

- 7906290055 BBW site inspector daily rept on 790409 Plant status reactor operating at 75% w/one coolant pump shut down due to leaky seal Refueling outage scheduled for 790424 MCHENRY, T J , QUICK Region 2. Atlanta, Office of the Director 79/04/09 2pp
- 7906270099 BBN site inspector daily rept on 790411 Plant status reactor at 75% power w/one coolant pump shut down due to leaky seal MCHENRY, T J , MCDONALD Region 2, Atlanta, Office of the Director 79/04/11 2pp
- --7906290120 BbW site inspector daily rept on 790411 Plant status reacter at full power operating w/pressurizer relief valve blocking valve closed due to leak through pressurizer relief valve JUNNSON A. MILLERL J. HORN, A Region 5, San Francisco, Office of the Director 79/04/11 2pp
- 7906290557 B&W site inspector daily rept on 790412 Plant status reactor at 75/ power w/one reactor coolant pump secured due to suspect seal MCHENRY, T J Region 2. Atlanta, Office of the Director 79/04/12 2pp
- 7906290130 BPW site inspector daily rept on 790413 Plant status 74% power w/one reactor coolant pump secured to prevent seal degradation Outage scheduled for 790424 MCHENRY, T J Region 2, Atlanta, Office of the Director 79/04/13 200
- 7906290436 B5W site inspector daily rept on 790414 Plant status reactor operating at 75, power w/one coolant pump shut down to prevent seal depradation No major equipment out of svc MCHENRY, T Region 2. Atlanta, Office of the Director 79/04/14
- 7906290473 BEH site inspector daily rept on 790415 Plant status reactor at 75% w/one coolant pump secured to prevent seal degradation No major equipment out of svc NCHENRY, T Region 2, Atlanta, Office of the Director 79/04/15 2pp
- 7906290619 BAW site inspector deally rept on 790417 Plant status power at 74% w/one coolant pump secured to prevent seal degeneration No major equipment out of commission MCHENRY, T Region 2. Atlanta, Office of the Director 79/04/17 in
- 7906110064 Responds to IE Bulletin 79-038 Calibr of reactor protection sys has been revised by power operated relief valve has been isolated Will advise of findings when review of pressurizer operation is completed STEWART.N P Florida Power Corp 79/04/22 2pp
- 7906290450 BbW site inspector daily rept on 790420 Plant status power at 74% w/one reactor collant pump secured to prevent seal degradation No major equipment out of svc MCHENRY,T J. PRICE, B S. Region 2. Atlanta, Office of the Director 79/04/20 1p
- 7906050065 Ack receipt of 790504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-12
  LENIS, R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/09 ip
- --7906030164 Responds to NRC 790411 ltr re violations noted in IE Insp Rept 50-302/79-12 Corrective actions fuel handling procedure FP-302 will be revised into three separate procedures STEWART, W.P. Florida Power Corp. 79/05/04 2pp
- --7906050107 Forwards IE Insp Rept 50-302/79-12 on 790307-09 & notice of violation
  LEMIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/11 2pp
- --7906050114 Notice of violation from insp on 790307-09
  \* Region 2. Atlanta, Office of the Director 79/04/10 ip
- --7906050121 IE Insp Rept 50-302/79-12 on 790307-09 Noncompliance noted inadequate fuel handling procedure BURNETT.P T . GRAHAM.M J Region 2. Atlanta, Office of the Director MARTIN.R D Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/10 App
- 7906250450 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  0'REILLY,J P Region 2. Atlanta, Office of the Director 79/05/10 1p.

- 7906110061 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required G'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/11 1p
- 7906180359 Ack receipt of 790409 ltr informing NRC of steps taken to correct violation nated in IC Insp Rept 30-302/79-08 LEWIB.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/11 1p
- --7906180366 Responds to NRC 770323 ltr re violation noted in [E Insp Rept 50-302/79-08 Corrective actions door w/3-h rating ordered Tentative installation date is 790601 STEMART,W P Florida Power Corp 79/04/09 lp
- --7906180372 Forwards IE Insp Rept 50-302/79-08 on 790212-16 & notice of violation LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7906180376 Notice of violation from insp on 790212-16 Region 2. Atlanta, Office of the Director 79/03/23 lp
- --7906180408 IE insp Rept 50-302/79-08 on 790212-16 Nancompliance noted failure to control & provide fire door on record storage vault GUICK,D R , BELISLE,O A Region 2, Atlanta, Office of the Director DANCE,H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23, 7pp
- 7906290146 Responds to IE Bulletin 79-05A Forwards info relevant to design of BWRs & events surrounding TMI incident STEWART,W P Florida Power Corp 79/05/12 18pp
- 7906270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Hulletin 79-05H HILLIAMS.F.J Division of Project Management 79/03/IB 3pp
- 7906290739 Submits add1 info to 790416 response to IE Bulletin 79-03 Section of 10-inch Schedule 10 stainless steel pipe gurchased for use from Youngstown Helding & Engineering Co STEMART.W P Florida Power Corp 79/05/18 2pp
- 7906260313 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-302/79-10 SUTHERLAND, J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/05/21 ip
- ---7906260515 Responds to NRC 790410 ltr re violations noted in IE Insp Rept 30-302/79-10 Corrective actions efforts under way to reduce possibility of equipment failure STEWART,W P Florida Power & Light Co 79/04/23 App
- --7906260516 Forwards IE Insp Rept 50-302/79-10 on 790313-16 & notice of violation SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Haterials Safety Branch 79/04/10 2pp
- --7906260517 Notice of violation from insp on 790313-14
  \* Region 2. Atlanta. Office of the Director 79/04/10 19
- ---7906260321 IE Insp Rept 50-302/79-10 on 790313-16 Noncompliance noted failure to implement environ monitoring & surveillance program & failure to approve contractor procedures to implement nonrudimentary monitoring programs. CUNINNOHAM. A L HUFMAN.J W Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 Spp
- 7906280093 Forwards response to IE Bulletin 79-058 re generic design for implementation of safety-grade reactor trips into reactor protection sys Changes to Tech Specs will be submitted following issuance of SER STEWART, W. P. Florida Power & Light Co 79/05/21 SBpp
- 7706270726 Responds to IE Bulletin 79-07 re GE Type AK-2 circuit breakers Circuit breakers of this type are used in control rad forive control sys STEWART.W P Florida Power Carp 79/05/21 2pp
- 7906290730 Responds to IE Builetin 79-10 re requalification training program statistics Forwards format of annual examination STEMART.W P Florida Power Corp 79/05/21 3pp
- 7906220201 Forwards add1 info to Items 1.2 & 6 of IE Bulletin 79-058, in response to C Nelson request STEMART, W P Florida Power Corp 79/06/15 3pp

- R Periodic operating reports & related correspondence
- 7906200267 Forwards monthly operating rept for May 1979 STEWART, W P Florida Power Corp 79/06/12 1p
- --7906200271 Monthly operating rept for May 1979 STEPHENSON:W A Florida Power Corp 79/06/03 Spp
- S Reportable occurrences, LERs & related correspondence
- 7906120399 Forwards LER 79-030/03L-0 STEWART,W P Florida Power Corp 79/06/06 ip
- --7906120407 LER 79-050/03L-0 on 790510 count-rate amplifier & rate of change amplifier for nuclear source range instrument NI-2 found inoporable Caused by amplifiers being out of tolerance due to instrument drift Amplifiers recalbr & returned to svc COOPER.J Florida Power Corp 79/06/04 2pp
- 7906130014 Forwards LER 79-049/03L-0 STEWART, W P Florida Power Corp 79/06/06 1p
- --7906:30017 LER 79-049/03L-0 on 790509 count-rate amplifier & rate of change amplifier for nuclear source range instrument NI-1 were inoperable Caused by amplifiers being out of tolerance due to instrument drift Amplifiers becalabr COOPER.J Florida Power Corp 79/06/04 2pp
- 7706180505 Forwards LER 79-052/03L-0 STEWART, W P Florida Power Corp 79/06/11 1p
- --7906180508 LER 79-032/03L~0 on 770516 in Mode 6.diasel driver fire svc pumps discovered to be out of svc Caused by diesel manufacturer representative boing unfamiliar w/approved plant procedures Personnel instructed COUPER.J Florida Power Corp 79/06/07 2pp
- 790619029B Forwards LER 79-031/03L-0 STEWART.W P Florida Power Corp 79/06/11 1p
- --7906190303 LER 79-031/03L-0 on 790516 while performing daily shutdown surveillance EP-301.fire svc tank level discovered to be 3.600 gallons below min allowed Caused by improper design Alarm setpoint raised to Tech Bpec Limit COOPER.J Florida Power Corp 79/06/05 2pp
- 7906250296 Forwards LER 79-053/03L-0 STEWART.W F Florida Power Corp 79/06/20 1p
- --7906250298 LER 79-053/03L-0 on 790523 while performing operability of boron injection sources & pumps, heat trace recorder failed rendering boron injection inoperable Caused by loose drive cord Cord refinstalled & recorder returned to svc COOPER, J Florida Pawer Corp 79/06/13 2pp
- 7906280142 Forwards LER 79-054/01T-0 STEWART,W P Florida Power & Light Co 79/06/25 ip
- --7906280146 LER 79-054/01T-0 on 770615 cracks in 4.160 volt emergency sys nonsegregated bus insulation sleeving observed Caused by incompatibility between Leran sleeving matl & Versa-Fab varnish tape Cracks repaired w/recommended tape COOPER.J Florida Power Corp 77/06/15 2pp
- U Congressional/Executive Correspondence
- 7906260586 Provides addl info re D Browning info request re FL nuclear power situation Discusses wastes produced by FL plants, effluents released & consequences of possible accident 008816KL V Office of the Executive Director for Operations 79/05/17 Gpp
- ---7906260590 Forwards D Browning 790404 questions re FL nuclear power situation Requests necessary info for reply MICA:D A House of Rep. 79/04/05 2pp
- ~-7906260593 Ack receipt of 790405 itr re D Browning info request re FL nuclear power situation Forwards instructions to operators re where to prevent occurrence like TMI & JM Hendrie 790410 testimony to Subcommittee on Nuclear Regulation 8/2 encl KAMMERER.C Office of Congressional Affairs 79/04/18 ip

- DOCKET 50-304 ZION NUCLEAR POWER STATION, UNIT 2

  F Security, medical, emergency & fire protection plans
- 7906120240 Forwards status rept of unfinished mod required to improve level of fire protection All mods completed except for gas suppression sys, fire doors b reactor coolant gump REED. C Commonwealth Edison Co 79/06/06 Bpp
- Q Adjudicatory correspondence
- 7903210375 Informs of document containing info potentially relevant to issue of sabotage of spont nuclear fuel b of NRC assessment of info to be made available GUDDARD.R J Branch 2 79/02/26 2pp
- 7904080128 Forwards M Resnikoff 790409 ltr re testimony in proceedings SEKULER.S N | [litnois, State of 79/04/12 2pp
- 7906040145 Notifies that hearing will be held at Zion, R. on 790611-15, 5 790620-23, if needed Limited appearances will be received on 790611 LUTON.E Atomic Safety and Licensing Board Panel 79/04/23 lp
- 7906010266 Answers NRC 790409 interrogatories Add1 info will be filed when available Certificate of Evc enci SEKULER: S N Illinois. State of 79/04/27 épp
- 7706190091 Complaint for injunctive relief in City of Lancaster v NRC filed in DC US District Court Seeks enjoinment of radioactive discharge CIMA: T Concerned Citizens of Lake County, IL 77/05/03 1p
- 7906280159 Forwards ASLB 790418 order in which questions of proposed mods were added in light of TMI incident If similar questions are to be considered in current proceeding. State of IL prepared to submit testimony BEKULERIS & Illinois, State of 79/05/08 lp
- 7706270613 Stipulation between NRC % intervenor State of IL NRC withdraws motion for summary disposition of Contention 2(d) State, in turn-withdraws contention but reserves right to submit testimony on all alternatives M/Certificate of Svc QCLDBERG, S C Branch 2 SEKULER, S N Illinois, State of 77/03/15 3pp
- 7706260214 Orders time change for 770611 evidentiary hearing Hearing will start at 2 PM Instead of 9 AM LUTON:E Atomic Safety and Licensing Board Panel 77/06/04 lp
- 79062740081 Notice of reconstitution of ASLB JF Wolf replaces E Luton as Chairman LAZD.RM Acomic Safety and Licensing Appeal Panel 79/06/05 1p
- J Insurance & indemnity information
- 7706040187 Forwards executed Amends 21.11.7 % I to Indemnity Agreements B-10.8-47.8-59 & B-84.respectively POOLE.R D Communication Edison Co 79/05/29 Spp
- P Operating license stage documents & correspondence
- 7906180707 "In-Plant Source Term Measurements at Zion Station "DYER.N.C., BUNTING.R.L., CRONEY.S T EQ & 0, Inc. NUREG/CR-0715 79/02/28 400pp Available at NTIS
- 7906200959 Forwards Amends 47 & 44 to Licenses DPR-39 & DPR-48, respectively, safety evaluation & notice of issuance & availability SCHWERKER, A Operating Reactors Branch ( (Pre 790625) 79/04/09 200
- ---7906200565 Safety evaluation supporting Amends 47 & 44 to Licenses
  DPR-39 & DPR-48, respectively
  \* Operating Reactors Branch 1 (Pre 790625) 79/04/09 3pp
- 7906180782 Forwards FR notice of proposed issuance of amends to facility OL.

  SCHWENGER: A Operating Reactors Branch I (Pre 790625) 79/04/27
  2pp.
- --7906180790 FR notice of proposed issuance of amends to facility OL BCHWENGER, A Operating Reactors Branch 1 (Pre 790625) 79704727 Spp

- 7906060273 Determines that 790426 RO rs instrument bus 2011 on "dirty power" is not reportable WANDKE, N E Commonwealth Edison Co 79/05/07 ip
- 7906200239 Requests two controlled copies of site emergency plans & implementing procedures site maps showing location & grid station number of onsite & offsite environ monitoring stations & site maps used for dose determinations

  KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/17
- 7906070192 Accepts Revision 7 to Addendum 1 of CE-1-A Rovision discusses organizational changes in QA program HAASS,W P Guality Assurance Branch 79/06/06 1p
- 7906200335 Responds to IE Bulletin 79-01 Forwards info re environ qualification of Class IE equipment required to function under accident conditions & info re use & maint of ABCO solenoid valves

  REED, C Commonwealth Edison Co 79/06/14 39pp
- 7906250293 Forwards info re PHR feedwater lines, in response to V Stello 790925 request Ten oversized drawings in Central Files REED.C Commonwealth Edison Co 79/06/19 14pp
- 7906270179 Notifies of necessity of examination of feedwater lines to determine mods J-tubes will be installed in seven steam generators Evaluation of setpoint of water actuation will determine revision
  REED, C. Commonwealth Edison Co. 79/06/20 4pp
- O Inspection reports. IE Bulletins & correspondence
- 7906020055 Forwards IE Insp Repts 50-295/79~03 & 50-304/79-03 on 790312-16 No noncompliance noted DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/05 2pp
- --7904020065 IE Insp Repts 50-295/79-03 & 50-304/79-03 an 790312-16 No noncompliance noted Major areas inspected emergency planning activities including generating stations emergency plan & confirmatory measurements insp
  OESTHANN.M J. CSSIG.T H. Region 3. Chicago, Office of the Director 79/04/03 10pp
- 7906040045 Forwards IE Insp Repts 50-295/79-02 & 50-304/79-02 on 790306-07 & 27-28 No noncompliance noted FIORELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906040052 IE Insp Repts 50-295/79-02 & 50-304/79-02 on 790306-07 & 27-28 No noncompliance noted Major areas inspected steam generator snubbers, pipe snubber installation, review of licensee records, mechanical snubber tests & unresolved items YIN, I T , DANIELBON, D H Region 3, Chicago, Office of the Director 79/04/05 app
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vossel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07
- 7906140253 Responds to IE Bulletin 79-04 Lists Velan Engineering Corp valves identified as having incorrect weight values in seismic piping analysis REED.C Commonwealth Edison Co 79/05/07 3pp
- 7906110101 Forwards IE Builetin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/11
- 7905190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  KEPPLER, J G Region 3, Chicago, Office of the Director. 79/05/11
  1p
- 7906230118 Provides add1 info to 790427 ltr Responds to IE Bulletin 79-06A Updated Items 4 & 12 rs identification of valves having control switches are returnable to pre-TMI incident position Plan to use hydrogen recombiner units REED.C Toledo Edison Co 79/05/17 3pp.
- 79060B0196 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U." KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/18 1p.

36130082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Carcuit Breakers for Engineered Safety Sys " Licensee Action required \*\*EPPLER.J G Region 3. Chicago. Office of the Director 79/05/22 to

VAZODO80 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor" KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/29

Periodic operating reports & related correspondence

06290122 Forwards "Environ Monitoring in Lake MI," for Jan 1970-Sept 1978 MANDKE,N E Communucalth Edison Co 79/06/01 1p

7906290127 "Environ Monitoring in Lake MI," for Jan 1970-Sept 1968, by Haileton Environ-Sciences Corp • Commonwealth Edison Co 79/06/01 513pp

06120349 Forwards monthly operating rept for May 1979 RANDME, N E Commonwealth Edison Co 79/06/08 1p

7706120349 Monthly operating rept for May 1979 JEFFERS, J Commonwealth Edison Co 79/06/08 11pp

Reportable occurrences. LERs & related correspondence

06050282 Forwards LER 79-031/03L-0 VANDKE,N E Communueaith Edison Co 79/05/17 ip

7908080284 LER 79-031/03L-0 on 790417 three inoperable snubbers were found Caused by hydraulic fluid loss in two & physical disconnection at piston rod end in third Periodic inspendanced from yearly to six months
WENNERHOLM.J Commonwealth Edison Co 79/05/17 3pp

04060223 Forwards LER 79-029/03L-0
HANDKE-N E Commonwealth Edison Co 79/05/22 is

7906060226 LER 79-029/03L-0 on 790423 during change of startup batteries on 2C CS pump, spray sys was inadvertently rendered inoperable w/o performing required surveillance Caused by personnel error in operating multi-position switch KRAWCIAK.A T Commonwealth Edison Co 79/05/22 ip

36140554 Forwards LER 78-077/03L-0 NAVDME: N E Commonwealth Edison Co 79/05/29 ip

790&1405&1 LER 78-077/O3L-0 on 780901 isolation valve 2FCV-PR24A failed to remain open causing containment particulate & gas monitors 2RE0011 & 2RE0012 to become inoperable Caused by misaligned limit switch Switch adjusted UGOLINE.D J Commonwealth Edison Co 79/05/29 ip

DA1403A7 Forwards LER 79-033/03L-0
#ANDKE:N E Commonwealth Edison Co 79/05/31 19

7996140372 LER 79-033/03L-0 on 790508 condenser air ejector rod monitor 2RE0015 sporadically alarmed high while reading below alarm setpoint 5 then falied low Gaused by defective low voltage power supply Power replaced TRZYNA, 9 Commonwealth Edison Co 79/05/31 ip

0614D511 Forwards LER 78-078/03L-0. HANDKE,N E. Commonwealth Edison Co. 79/05/31 1p

7706140521 LER 78-078/03L-0 on 780521 status lights for high steam flow would not remain energized when radiographic test push button was depressed Caused by defective transistors 05 & 07 in module (Model 411004-004)
CAMPBELL, J Commonwealth Edison Co 79/05/31 ip

06040333 LER 79-003 has been yolded • Commonwealth Edison Co 79/06/01

08040334 LER 79-005 has been voided • Commonwealth Edison Co 79/06/01 1

06040337 LER 79~011 has been voided + Commonwealth Edison Co 79/06/01 i

0å110126 LER 79-001 has been voided ∍ Commonwealth Edison Co. 79/06/01. 1p

05110133 LER 79-006 has been voided, s Commonwealth Edison Co 79/06/01, 1p 7906110163 LER 79-007 has been voided
\* Commonwealth Edison Co 77/06/01

7906140389 Forwards LER 79-034/03L-0 HANDKE,N E Commonwealth Edison Co 79/06/01 ip

--7906140376 LER 79-034/03L-O on 790511 following testing of O deisel generator starting air sys leak bled down starting air receivers Caused by loose cap screws holding valve seat to seat retainer Valve seat replaced & fastened correctly RRAWCZAK.A T Commonwealth Edison Co 79/06/01 1p

7905220395 Folwards LER 78-079/03X-1 Update notes rept number change from 78-077 to 78-079
HANDKE,N E Commonwealth Edison Co 79/06/05 1p

~~7706220453 LER 78~079/03X-i on /80901 valve 2FCV-PR24A did not remain open after containment isolation test.causing particulate 1 gas monitors to be inoperable Caused by misaligned limit switch Switch Switch Sultch adjusted UGDLINI.D J Commenumealth Edison Co 79/06/05 ip

7906220390 Forwards LER 79-032/03L-0
WANDKE N E Commonwealth Edison Co 79/06/07 1p

--7906220394 LER 79-032/03L-0 on 790508 after reactor trip. Train A reactor trip breaker failed to open Caused by plunger out of adjustment in undervoltage to:1
ARDER.K.J. Commonwealth Edison Co. 79/06/07 ip

7906220399 Forwards LER 77-010/03L-0 WANDXE,N E Commonwealth Editon Co 79/06/07 1p

--7906220401 LER 77-010/03L-0 on 770327 reactor tripped & breaker train A failed to open Breaker taken to shop & tested No cause found Breaker reinstalled & verified operable CAMPBELL.J Commonwealth Edison Co 79/06/07 1p

T Hearing transcripts on non-antitrust matters

7906260554 Transcript of 790611 hearing in Zion iL Pp 200-481 WOLF, J , REMICK, F J , LITTLE, L W Atomic Bafety and Licensing Board Panel 79/06/11 19pp

7906260558 Transcript of 790612 hearing in Zion. IL Pp 482-701 WOLF.J., REMICK.F.J., LITTLE.L.W. Atomic Safety and Licensing Board Panel 79/06/12 219pp

7906290560 Transcript of 790613 hearing in Zion. IL re spent fuel pool expansion Pp 702-955
MOLF.J., REMICK.F.J., LITTLE.L.W. Atomic Safety and Licensing Board Panel 79706/13 253pp

7906290047 Transcript of 790614 meeting in Zion. IL Pp 956-1194 WOLF. J. REMICK. F. J. LITTLE. L. W. Atomic Safety and Licensing Board Panel 79/06/14 240pp

7906290082 Transcript of 790615 hearing in Zion. IL Pp 1195~1265 Tastimony & qualifications of JE Draley encl. WOLF, J., REMICK, F. J., LITTLE, L. W. Atomic Safety and Licensing Board Panel 79/06/15 200pp

DOCKET 50-305 KEWAUNEE NUCLEAR POWER PLANT

O Adjudicatory correspondence

7906080054 Requests NRC authorization to issue notice of hearing on NRC order imposing civil monetary penalties for incident repotential high radiation exposure W/draft notice of hearing & 790315 request for hearing KELLY, J & Office of the General Counsel SECY-A-79-31 79/04/04, 79p

7706230165 Forwards notices of appearance & documents ref in 790501 notice of hearing
LIEBERMAN, J Rulemaking & Enforcement Division 79/05/03 5pp

7906230075 Notice of appearance on behalf of util Certificate of Svc enci KRANE/S E Folsy & Lardner 79/05/24 3pp

7906230077 Answer to 790430 notice of hearing Util will appear before administrative law judge & present evidence No matl facts are in dispute No violations occurred & no civil penalties can be imposed Certificate of Svc encl
KEANE,8 E . BAKER,D A Foley & Lardner 79/05/24 4pp

- 7906270277 Orders prehearing conference for 790621 to discuss simplifying issues amending pleadings obtaining stipulations & admissions identifying witnesses & setting hearing schedule SHITH, [ H Atomic Safety and Licensing Board Panel 79/06/05 ip
- J Insurance & indemnity information
- 7906200281 Forwards Endorsements 45 % 46 to NELIA Policy NF-204 MATHEWS, E R Wisconsin Public Service Corp 79/06/11 3pp
- 7906190401 Forwards Endorsement 36 & 37 to MAELV Policy MF-71
  MATHEWS, E R Wisconsin Public Service Corp 79/06/15 3p
- P Operating license stage documents & correspondence
- 7905210378 Forwards Amend 30 to License DPR-43. safety evaluation & notice of issuance & availability
  SCHWENCER.A Operating Reactors Branch 1 (Pre 790625) 79/05/07
- --7906210385 Amend 30 to License DPR-43, revising Tech Specs to permit waiving turbine stop & governor valve testing at end of cycle CHWENCER, A Operating Reactors Branch 1 (Pre 770629) NAC 79/05/07
- --7906210388 Safety evaluation supporting Amend 30 to License DPR-43 \* Office of Nuclear Reactor Regulation 79/03/30 3pp
- --7906210393 Notice of issuance & availability of Amend 30 to License DPR-43 SCHWENCER, A 79/05/07 Operating Reactors Branch 1 (Pre 790625)
- 7906200317 Approves util evaluation of postulated fuel handling accident submitted 790328 Forwards safety evaluation supporting util conclusions
  SCHWENCER: A Operating Reactors Branch I (Pre 790625) 79/05/09
- ---7906200321 Safety evaluation supporting util conclusions of postulated fuel handling accident inside containment

  \* Operating Reactors Branch 1 (Pre 790623) 79/05/09 4pp
- 7906260092 Summary of 790509 meeting w/uts1 re auxiliary feedwater sys & related station areas OLSHAN¢L N Operating Reactors Branch 1 (Fre 790625) 79/05/(4
- 7906250191 Discusses review of rod bank exchange method to verify shutdown margin for two loop Wastinghouse NSSS Approves method as alternative to boron exchange method provided conditions are met R.A Operating Reactors Branch 1 (Pre 790625) 79/05/15 certain SCHWENCER, A
- 7906200245 Requests two controlled copies of site emergency plant COMMUNITY NEGLECTS AND CONTROLLED COPIES OF SIZE EMBERGERS PLANT implementing procedures, site maps showing location & grid station numbers of envison monitoring stations onsite & offsite & site maps used for offsite determintion

  KEPPLER, J G Region 3: Chicago, Office of the Director 79/05/17
- 7906180503 Forwards revised proposed Amend 35 to License DPR-43 to change Tech Specs re RCS overgressure protection at low MATHEWS.E R Wisconsin Public Service Corp 79/06/15 8pg
- G Inspection reports. IE Bulletins & correspondence
- 7906120279 Forwards reponses to IE Bulletin 79-06A:Revision 1, re review of operating procedures in light of TMI incident Emergency procedures reviewed by special team Proposal to trip level bistables does not provide greater safety MATHEMS,E R. Wisconsin Public Service Corp. 79/04/30 Sepp.
- 790&120134 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07
- 7906110112 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/08/11

- 7906190108 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies ' Region 3, Chicago, Office of the Director 79/05/11 1 m
- 7906230116 Responds to IE Bulletin 79-09 GE AK-2 circuit breakers are not in use at facility
  MATHEWS.E R Wisconsin Public Service Corp 79/05/16 1p
- 7906080209 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7706220110 Forwards IE Insp Rept 50-305/79-04 on 770423-27 Notice of violation withheld (ref 10GFR2 770)
  HIND, J.A. Region 3. Chicago, Office of the Director 77/05/18
- --7906220119 IE Insp Rept 50-305/79-04 on 790423-27 Noncompliance noted six items identified relative to physical barriers, access control-identification authorization b badging Details withheld (ref 10CFR2 790)
  CREED, J. R., MADEDA, T. J., HIND, J. A. Region G., Chicago, Office of the Director 79/05/17 1p
- 7906:130121 Forwards IE Bulietin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys "Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 10 1p
- 7906220487 Responds to request for info re IE Bulletins 78-12,12A & 12B Westinghouse is unable to provide requested info re atypical weld matl until end of Sept Requests extension of submittal date to 791031 MATHEWS.W R Wisconsin Public Service Corp 79/05/23 1p
- 7906200145 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/29
- 7906080314 Submits info on operator requalification training program, in response to IE Bulletin 79-10 MATHEWS,E R Wisconsin Public Service Corp 79/05/31 3pp
- S Reportable occurrences. LERs & related correspondence
- 7906060205 Forwards LERs 79-007/03L-0 % 79-008/03L-0 MATHEWS, E R Wisconsin Public Service Corp 79/03
- --7706060208 LER 77-007/03L-0 on 770501 during full power operation surveillance testing one of six containment pressure transmitters was out of calibr Caused by instrument drift RUITER O H Wisconsin Public Service Corp 77/05/31 1p
- --7906060220 LER 79-00B/03L-0 on 790903 one train of heat tracing piping between BA transfer pumps common discharge header >> BA filter found to be inoperable during installation Caused by open circuited connector Failed heat tracer repaired RUITER,O H Wisconsin Public Service Corp 79/05/31 ip
- 7906280075 Forwards LERs 79-009/03L-0 & 79-010/03L-0 MATHEWS, E R Wisconsin Public Service Corp 79/06/25 1p
- --7906280080 LEM 79-009/03L-0 on 790526 condensate storage tank level drawn below Tach Spac limit during normal shutdown Occurs routinely during certain hot shutdown conditions. No further corrective action necessary RUITER.O H Wisconsin Public Service Corp 79/06/25 Ip
- --- 7906280086 LER 79-010/03L-0 on 790827 auxiliary bldg special ventilation zone boundary foor found blocked open Caused by failure to post proper notice on door Notice subsequently RUITER, G. H. Wisconsin Public Service Corp. 79/06/25 1p
- DOCKET 50-306 PRAIRIE ISLAND NUCLEAR STATION, UNIT 2 J Insurance & indemnity information
- 7706130312 Forwards Endorsements 42 % 43 to NELIA Policy NF-197 JOHNBON: R G Northern States Power Co 79/06/07 3pp
- 7906210237 Forwards Endorsements 38 % 39 to MAELU Policy MF-68 JOHNSON R 0 Northern States Power Co 79/06/13 3pp

- P Operating License stage documents & correspondence
- 7706130057 Forwards Amends 36 & 30 to Licenses DPR-42 & DPR-60, respectively, safety evaluation & notice of issuance & availability
  SCHAERKERA Operating Reactors Branch 1 (Pre 790625) 79/05/01
  - Sbb

    SchMEKCRI's Oberstlud Kearfors Blauch I (Lie 140952) 1410210
- --7906130061 Amends 36 & 30 to Licenses DPR-42 & DPR-60, respectively, revising Tech Spacs to require actuation of safety injection based on 2 out of 3 channels of low pressurizer pressure SCHWENCER.A Operating Reactors Branch 1 (Pre 790625) 79/03/01 900
- --7706130062 Bafety evaluation supporting Amends 36 & 30 to Licenses DPR-42 & DPR-60, respectively • Office of Nuclear Reactor Regulation 79/05/01 App
- --7906130066 Notice of issuance t availability of Amends 36 & 30 to Licenses DPR-42 to DPR-60, respectively SCHMENCER.A Operating Reactors Branch 1 (Pre 790625) 79/09/01 2pp
- 7705120094 Forwards safety evaluation for mod to safety injection actuation sys LANNAS.C Plant Systems Branch 79/05/03 2pp
- --7906/20101 Safety evaulation supporting mod to safety injection
  - actuation sys
    Plant Systems Branch 79/05/03 2pp
- 770&25003B Discusses review of info re rod bank exchange method to verify shutdown margin for two loop Westinghouse NSSS Approves method as alternative to boron exchange, provided certain conditions are met SCH-MENCER.A Departing Reactors Branch 1 (Pre 790625) 79/08/15 200
- 7906200451 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite environ monitoring stations & site maps used for offsite dose determinations or evacuation REPPLER, J G Region 3, Chicago, Office of the Director 79/05/17 to
- 7706050290 Forwards amend application for Licenses DPR-42 & DPR-60-in response to NRC 781115 ltr AAVER.L O Northern States Power Co 79/06/01 1p
- --7906050292 Application for amend to Licenses DPR-42 & DPR-60 WACHTER.t. J Northern States Power Co 79/06/01 & 62pp
- 7706140443 Forwards "Process Control Program for Waste Solidification" & Offsite Dose Calculation Manual MAYER.L O Northern States Power Co 79/06/07 1p
- --7906140448 "Process Control Program for Waste Solidification "
  \* Northern States Power Co 79/06/01 lipp
- ~~7906140451 Offsite Dose Calculation Manual
  → Northern States Power Co 79/06/01 111pp
- 7906190342 Forwards Revision 2 to "AEME Code Section XI Inservice Insp & Testing Program 5 Info Required for NRC Review of Request for Relief from ASME Code Section XI Requirements " MAYER.L O Northern States Power Co 79706/08 2pp
- --7906190349 Revision 2 to "ASME Code Section XI Inservice Insp & Testing Program & Info Required for NRC Review of Request for Relief from ASME Code Bection XI Requirements "

  \* Northern States Power Co 79/06/09 66pp
- 7906220357 Bubmits info re facility feedwater line design. fabrication. insp & operating history MAYER.L O Northern States Power Co 79/06/19, 20pp
- O Inspection reports, IE Bulletins & correspondence
- 7904040093 Responds to NRC 790215 ltr re violations noted in IE Insp Rept 50-282/79-01 & 50-306/79-01 Corrective actions design change has been implemented to assure problems are quickly identified & corrected WACKIER.L.J Northern States Power Co 79/03/08 Spp.

- 7904040042 Responds to IE Bulletin 79-07 ADLEPIPE computer code used by Fluor Sycs, inc for seismic analysis of one safety injection line Analysis repeated using PIPESTRSS; design found satisfactory HACHTER, L. J. Northern States Power Co. 79/04/24 3pp
- 7904260321 Forwards IE Insp Repts 50-282/79-08 & 50-306/79-07 on 790212-16 & 0314-16 & notice of violation HEISHMAN,RF Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/04/25 2pp
- --7906260326 Notice of violation from insp on 790212-16 % 0314-16 \* Region 3, Chicago, Office of the Director 79/04/19 to
- --7906260330 IE Insp Repts 50-282/79-08 & 50-306/79-07 on 790212-16 & 0314-16 Noncompliance noted delayed conduct of fire Mys surveillance McGREGOR.L G . SMITH.J D . STREETER.J F Region 3. Chicago. Office of the Director 79/04/19 9pp
- 7906260345 Forwards IE Insp Repts 50-202/79-09 & 50-306/79-00 on 790301-31 No noncompliance noted HEISHMAN,R F Region 3. Chicago. Reactor Operations Nuclear Support Branch 79/04/30 2pp
- ---7906260553 IE Insp Repts 50-282/79-09 & 50-306/79-08 on 790301-31 No nuncompliance noted Major areas inspected plant operations, radiation protection, maint, security, insp of new fuel & contingency planning FEIERABEND.C D. D. DANIELS.F T. WARNICK.R F. Region 3. Chicago, Office of the Director 77/04/23 Spp
- 7906020151 Responds to IE Bulletin 77-04 Veian valve weights were incorrect but have been reanalyzed in compliance w/bulletin No mod required Tabulation of valve use encl MACHTER.L J Northern States Power Co 79/05/01 4pp
- 7906120121 Forwards IE Info Notice 79~11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J & Region 3, Chicago, Office of the Director 79/05/07
- 7906110106 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190099 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11
- 7906140171 Supplements 790414 response to IF Bulletin 79-07 Bubmits addl info re computer codes for seismic analysis MACHFERL J Northern States Power Co 79/05/15 2pp
- 7906270023 Forwards licensee responses to IE Bulletin 79-06A VARQA, S.A. Light Hater Reactors Branch 4 79/05/17 1p
- --7906270029 Responds to IE Bulletin 79-Q6A, Revision 1 re revision of emergency procedures for coping w/transients & accidents WACHTER, L. J. Northern States Power Co. 79/04/30 7pp
- 7906080204 Forwards IE Circular 79-08, "Attempted Extertion Low Enriched U " KEPPLER,J G Region 3, Chicago, Defice of the Director 79/09/18
- 7906290752 Responds to IE Bulletin 79-06A. Revision 1 Change to Tech Specs issued 790501 to modify safety injection logic to two out of three low pressurizer pressure Mod of logic made 790502 on Unit 1 & 790508 on Unit 2 WACHTER.L.J Northern States Power Co 79/05/18 1p
- 7906130109 Forwards IE Bulletin 79-il, "Faulty Overcurrent Trip Device in Circuit Breekers for Engineered Safety Sys " Licensee action required KEPPLER.J O Region 3. Chicago. Office of the Director 79/05/22
- 7906200131 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creak Reactor." KEPPLER, J 9 Region 3, Chicago, Office of the Director 79/05/29 in
- 7906290649 Ack receipt of 790518 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-282/79-08 & 50-306/79-07
  HEISHMAN, R F Region 3. Chicago: Reactor Operations Nuclear Support Branch 79/05/29 ip

- --7906290475 Responds to NRC 790425 ltr re violations noted in IE Insp Rept 50-282/79-08 & 50-306/79-07 Corrective actions detector testing begun 781108 & completed 781228 WACHIER.L J Northern States Power Co 79/05/18 2pp
- R Periodic operating reports & related correspondence
- 7904050324 Bubmits May 1979 Environ Event Rept 79-04 re cooling tower operations
  WARD, E.C. Northern States Power Co. 79/06/01
- 7906140829 Forwards monthly operating repts for May 1979 MAYER, L. O. Northern States Power Co. 79/06/11 1p
- ---7906140234 Monthly operating rept for May 197
  HUNSTAD, A A Northern States Power Co 79 79/06/01 4pp
- --7906140239 Monthly operating rept for May 1979 HUNSTAD.A A Northern States Power Co 79/06/01 4pp
- S Reportable occurrences, LERs & related correspondence
- 7906040338 LER 79-002 has been voided \* Northern States Power Co 79/04/01 ip
- 7906050316 Forwards LER 79-015/03L-0
  MAYER, L D Northern States Power Co 79/06/01 1p
- ---7906090317 LER 79-015/03L-0 on 790504 during gower operation, nuclear power range channel 2043 failed low, due to loss of high voltage Caused by failure of high voltage regulated source Model UPMS-X54M Power supply replaced HUNSTAD, A A Northern States Power Co 79/06/01 1p
- 7906140369 Environ Event Rept 79-04 in May 1979 plant circulating water sys in partial recycle mode had excessive average deily blowdown flow for 17 days Caused by accommodation of cooling tower maint to proper cooling water temps
  WARD.E C Northern States Fower Co 79/06/01 lp
- 7906120364 Forwards LER 79-016/03L-0
  MAYER, L D Northern States Power Co 79/06/07 tp
- --7906120368 LER 79-016/03L-0 on 790309 during audit of surveillance program found that reactor vessel injection isolation valve test SP 2159 had not been done Caused by failure to enter test on computer surveillance schedule HUNSTAD.A A Northern States Power Co 79/06/07 ip
- 7906150339 RO 79-19 dynamic loading during post-LOCA flow before valve closure was not included in original stress analysis of Henry Pratt containment purge valves All purge valves administratively controlled to assure closure TIERNEY,FP Northern States Power Co 79/06/07 ip
- BOCKET 50-309 HAINE YANKEE ATOMIC POWER PLANT
- @ Adjudicatory correspondence

ŀ

п

- - inates NRC 790313 order requiring plant shutdown Util util & S&W indicate mods completed

    of Nuclear Reactor Regulation 79/05/24 6pp
- H General correspondence
- 7908080173 Responds to Itr re Maine Yankee shutdown. Info partially withheld.name & address of recipient (ref FOIA Exemption 6) BRADFORD.P A Commission 79/03/29 ip
- 7908060178 Responds to 790328 ltr re Maine Yankee shutdown info partially withheld:name & address of recipient (ref FOIA Exemption 6) BRADFORD.P A Commission 79/04/02 ip
- 7906060179 Responds to 790331 1tr re deceptive statements made by utils Info partially withheld name & address of recipient (ref FQIA Exemption 6)
  BRADFORD P A Commission 79/04/04 ip

- --7906060183 Suggests NRC investigate utils' deceptive statements info partially withheld name & address of author (ref FGIA Exemption 6) \* Affiliation Unknown 79/03/31 ip
- 7906060252 Responds to ltr re Maine Yankee shuldown Info partially withheld name & address of recipient (ref FOIA Exemption 6) BRADFORD, P A Commission 79/04/10 ip
- 7906060128 Responds to 790409 itr re 790417 earthquake in ME Earthquake not reportable, based on current info
  EISENHUT.D C Division of Operating Reactors 79/04/30 2pp
- 7906230047 Responds to 790313 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA Plant review is being expedited DENTON:HR Office of Nuclear Reactor Regulation 79/05/09 ip
- ---790A230050 Expresses concern re shutdown of five reactors for seismic reasons Action assures energy crisis Plant overhaul is more appropriete during refueling shutdown Benefits of nuclear power outweigh seismic risks
  SIMPSON.R E Affiliation Unknown 79/03/15 2pp
- 7906210418 Responds to 790319 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to aperation w/no threat to public health & safety DENTON, HR Office of Nuclear Reactor Regulation 79/05/16 2pp
- -- 7906210424 Comments on NRC capticious & cavalier acts Requests ruariveze comments on NMC capricious & caveller acts Requests immediate reversal of unuise decision to shut down five plants Suggests more rational approach to improbable safety concerns in future
  MARCUS, Q H Affiliation Unknown 79/03/19 2pp
- 790627000B Responds to 790314 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in sesenic design of safety-related piping Maps of northeastern US earthquake zones encl
- ---7906270013 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in region SMITH.B N Affiliation Unknown 79/03/14 ip
- 7906270020 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake iones encl
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/17 3pg
- ---7906270028 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region HERRIMAN.C P Affiliation Unknown 79/03/31 2pp
- 7706270035 Responds to 770403 ltr re 770313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US sathquake zones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7706270042 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned FULLER.W R Affiliation Unknown 79/04/03 3pp
- 7906270053 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTGN:HR Office of Nuclear Reactor Regulation. 79/05/17 Spp
- --7906270036 Comments on 790313 orders shutting down five northeastern US nuclear power plants Economic consequences for Maine, as well as power shortages, override slim prospect of earthquakes Plants should be reopened SULLIVAN, J.F. Affiliation Unknown 79703/21 ip
- 7906270060 Responds to 790327 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techiques used in seismic design of safety-related piping Maps of northeastern US earthquake zones enci
- ---7906270066 Comments on 790313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its antinuclear attitudes GUIMSY,L Affiliation Unknown 79/03/27. ip

- 7708270069 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US anthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270073 Comments on 790313 orders shutting down five northeastern US nuclear power plants Plants should be reopened immediately, due to economic prospects of plant closings SANDERS, J A Affiliation Unknown 79/03/23 ip
- 7906270076 Responds to 790322 ltr to President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 Spp
- PROEZ7008D Responds to 79032B ltr re 790313 orders shutting down five nuclear power plants panding review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTEM: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270082 Comments on 790313 orders shutting down five northeastern US nuclear power plants Chance of earthquake is too low to risk economic upheaval caused by closing of plants LEWIS,PF Affiliation Unknown 79/03/28 ip
- 7FOA27BOB7 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending reaview of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake iones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270071 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MCGONAGLE, W F Affiliation Unknown 79/03/15 ip
- 7904270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northrestern US earthquake zones encl
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/17 Spp
- --7906270099 Comments on 790313 orders shutting down five northeastorn US nuclear power plants Decision was extremely ill-conceived KARPLE.H H Affiliation Unknown 79/03/17 ip
- 7906270107 Responds to 790314 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in setsmic desingn of safety-related piping Maps of northeastern US earthquake zones encl
  DENION:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270114 Comments on 790313 orders shutting down five northeastern Us nuclear power plants Decision was economically 111-conceived MODDMAN-W P Affiliation Unknown 79/03/14 ip
- 7905270119 Responds to 790322 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in selamic desing of safety-related piping Maps of northestern US earthquake zones encl
  DENION, HR Office of Nuclear Reactor Regulation 79/05/17 3pp.
- --7906270122 Comments on 770313 orders shutting down five northeastern UB nuclear power plants Decision was economically ill-conceived & represents flagrant federal govt overprotection through regulatory process

  BEANE,V.E. Affiliation Unknown 79/03/22. Ip
- 7906270124 Responds to 790324 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern UE earthquake zones encl.

  DENTON, H.R. Office of Nuclear Reactor Regulation 79/05/17. 3pp.
- --7905270127 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was sconomically ill-conteived.
  RICHARDS.W J Affiliation Unknown 79/03/20. 1p
- 7906270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending raview of analysis techniques used in satismic design of safety-related piping. Haps of northeastern US earthquake zones encl
  BENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 Spp.

- --790A270135 Comments on 790313 orders shutting down five northeastern US nuclear gower plants Decision was poorly timed & economically ill-conceived KOVLOVRIS.O E Affiliation Unknown 79/03/17 ip
- 7906270143 Responds to 790313 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquate zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270146 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived Requests date of last recorded earthquakes COFFIN.W S Affiliation Unknown /9/03/13 ip
- 7906270131 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-rolated piping Haps of northeastern US marthquake innes encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270155 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-conceived considering current energy crisis
  KREYZSCHMAR.W Affiliation Unknown 79/03/22 ip
- 7906270263 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in setsion of safety-related piping Maps of northeastern US earthquake zones enci
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270264 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically ill-conceived DEHEULLE:E H Affiliation Unknown 79/03/23 4pp
- 7906270265 Responds to 790315 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in selsmic design of safety-related piping Maps of northwestern UE earthquake iones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270266 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was overprotective act KATZENSTEIN:R L Affiliation Unknown 79/03/15 2pp
- 7906270267 Responds to 790325 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquafe cones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7904270268 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was economically (li-conceived ELLIB.R C. Affiliation Unknown 79/03/25 Ip

7904210433 Responds to five nuclear power expedited & disc' operation w/no DENTY 700

DENTON: H R. Office of Nuclear Reactor Regulation 79/05/24 1p

## P Operating license stage documents & correspondence

- 7906010279 FOIA request for all records & communications re shutdown of five nuclear plants
  CASSAN, V. J. Power Authority State of New York. 79/03/16 2pp
- 7906130026 Delineates criterion to develop plant-specific info packages on site visits RUSSELL,W T. Office of Nuclear Reactor Regulation 79/04/11. 2pp

- 7906160052 Notification of 790501 meeting w/util in Bethesda MD to discuss studies done in support of SHOCK-1 computer code application
  NELSON.C C Operating Reactors Branch 4 (Pre 790625) 79/04/30
- 7905250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants
  THADANIA C Reactor Systems Branch 79/05/02 42pp
- 7905230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors THADANI,A C Reactor Systems Branch 79/05/09 1p
- 7906230101 Forwards discussion of conservatisms in plant seismic design, estimate of manpower & cost for seismic reanalysis, proposed order terminating shutdown of safety evaluation. Show cause order satisfied Continued shutdown not required DENTON.H R Office of Nuclear Reactor Regulation 79/05/16 27pp
- 7906250091 Forwards memos discussing B McDermott concerns to shutdown of B&W plants ROS&D F Division of Project Management 79/05/17 1p
- ---7906250101 Requests assessment of safety of continued operation of B&W reactor based on performance of relief & safety valves, performance of HPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation ROSS, D Division of Project Management 79/05/08 2pp
- ---7906250106 Discusses safety assossment of B&W plants in response to 790508 memo B&W plants should be shut down until reanalysis has been completed re core cooling in natural circulation small break £0048 & ECCS MCDERMOTT.R J Quality Assurance Branch 79/05/14 7pp
- --7906250112 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown HAASB.W P Quality Assurance Branch 79/05/15 2pp
- --7904280114 Discusses 8 McDermott 790514 memo re safety of BbW plants Disagrees w/B McDermott position favoring shutdown SKOVHOLT,D J Operations 79/05/15 2pp
- 7906010273 Dunies FOIA request for Globum 790314 & Thompson 790315 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants info withheld (ref FOIA Exemption 5)
  FELTON, J M Division of Roles and Records 79/05/21 4pp
- 7906060074 Comments on PSAR Requests description of seismic analysis & design procedures for Class II structures, components, & equipment Requests further explanation how earthquake effects combine w/stress of operating & accident loads NEWMARK, N M N M Newmark Consulting Engineering Services 68/03/20 7pp
- 7906250133 Responds to 790319 itr re shutdown of facility Decision about possible resumption of operations will be made following NRC consultation b concurrence DENTON:HR Office of Nuclear Reactor Regulation 79/05/21 4pp
- --7906250135 Urges NRC to cancel order to shut down facility DURR.R P Affiliation Unknown 79/03/19 1p
- 7706050322 Requests postponoment of 790601 meeting w/NRC to discuss program for reanalysis of seismic Category I piping sysusing current piping analysis program, pending completion of ongoing SHOCK-O/NUPIPE-SW comparison analysis QROCE.R H Maine Yankse Atomic Power Co 79/05/29 ip
- 7906110270 Forwards monpropriatary & proprietary versions of "Description & Listing of C-E SHAKE Computer Code "Proprietary version withheld (raf 10CFR2 770) Affidavit ancl SCHERER: A E C-E Power Systems. 79/06/04 Spp
- ---7906110293 Nonproprietary version of "Description & Listing of C-E BHAKE Code " \* C-E Power Systems 79/06/30 3pp
- 7906:300:00 Forwards details of steam generator feed ring, full load trips to date, steam generator level traces to info refeedwater regulating valvs closure times Oversized drawing encl
  FRIZZLE, C D Maine Yankee Atomic Power Co. 79/06/06 App.

- 7906150162 Submits summary of evaluation of design change which will isolate component cooling to reactor coolant pumps on containment spray actuation signal Proposes to implement change during neit refueling outage

  ORGCE, R H Maine Yankee Atomic Power Co 79/06/08 4pp
- 7906220196 Submits addl info re steam generator feedwater piping, in response to 790525 request Oversized drawing in Central Files only Addl info will be forwarded GROCE, R H Maine Yankse Atomic Power Co 79/06/18 ip
- @ Inspection reports. IE Bulletins & correspondence
- 7906110049 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Suppl " No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906140180 Ack receipt of 781219 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/78-20
  MARTIN: H G Region 1. Philadelphia, Safeguards Branch 79/04/24
  3pp
- ---7906140185 Forwards IE Insp Rept 50-309/78-20 on 781016-20 Notice of violation Withheld (ref 10CFR2 790) HARTIN,W O Region 1, Philadelphia, Safeguards Branch 78/11/24 2pp
- --7906140193 IE Insp Rept 90-309/78-20 on 781016-20 Noncompliance noted imadequate searches of personnel Details withheld (ref 10CFR2 790) SHEPHERDLR E Region 1, Philadelphia, Office of the Director DEVLIN.J W Region 1, Philadelphia, Safaguards Branch 789/1/14 10
- 7906130119 Responds to IE Bulletin 79-04. "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Five subj valves are in use Effects of corrected weights are being evaluated ORGCE, R H Maine Yanfer Atomic Power Co 79/05/02 2pp
- 7906:80141 Forwards summary of 790306 mgt meeting Info presented during meeting resulted in withdrawal of Item B of 781222 notice of violation SMITH, OH Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- --7906180171 Summary of 79030A mgt meeting w/util in King of Prussia.PA re computerized personnel dosimetry record sys & withdrawal of apparent item of noncompliance GMITH.G H Region 1. Philadelphia. Fuel Facility & Materiais Safety Branch 79/05/02 2pp
- 7906120282 Forwards supplemental info re IE Bulletin 79-06B. "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "Describes justification for delay in addressing bulletin JOHNSON, W P Maine Yankse Atomic Power Co 79/05/04 Bpp.
- 7906120171 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required GRIER.B H Region i, Philadelphia, Office of the Director 79/05/07 2pp
- 7906270032 Requests review of encl C-E 790420 response to IE Bulletin 79-06B re TMI-related matters ROSS.D F Division of Project Management 79/05/08 27pp
- 7906120232 Ack receipt of 790420 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-309/79-02.
  BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch 79/09/09 ip
- --7906120241 Responds to NRC 790929 ltr re violations noted in IE Insp Rept 50-309/79-02. Corrective actions review of administrative procedures currently under way MODDY:D E Maine Yankee Atomic Pawer Co 79/04/20 2pp.
- --7906120244 Forwards IE Insp Rept 50-309/79-02 on 790306-09 & notice of violation BRUNNER.E.J Region i. Philadelphia. Reactor Operations Nuclear Support Branch 79/03/29 2pp
- --7706120248 Notice of violation from insp on 790306-09.

  Region I. Philadelphia. Office of the Director 79/03/27.
  2pp

- --7906120251 IE Insp Rept 50-309/79-02 Nancompliance noted failure to adhere to administrative controls BAUNACK, W H Region 1. Philadelphia, Office of the Director KISTER, W B Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/27 App
- 7706110137 Forwards IE Bullstin 79-10, "Requalification Training Program Statistics " Written response required CRIER.3 H Region 1. Philadelphia. Office of the Director 79/03/11 ip
- 7906260121 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906270105 Submits addl response to IE Bulletin 79-068 Mod to Tech Specs unnecessary MOODY,D E. Maine Yankee Atomic Power Co. 79/05/14 1p
- 7705080888 Forwards 1E Circular 79-08. "Attempted Extortion Low Enriched U " GRIER.B H Region i. Philadelphia. Office of the Director 79/05/18 1p
- 7706010184 Submits rept we arror in setpoints used in steam generator low pressure trip bistables No impact on limiting transient analysed in safety analysis Detailed review of effect to be forwarded within two weeks HOGD:EC Maine Yankew Atomic Power Co 79/05/25 ip
- P Periodic operating reports & related correspondence
- 7905190306 Forwards monthly operating rept for May 1979
  MODDY, D.E. Haine Vankee Atomic Power Co. 79/06/12 1p
- --7906190308 Monthly operating rept for May 1979
  SUDORENLR M Maine Yankee Atomic Power Co 79/06/12 5pp
- S Reportable occurrences, LERs & related correspondence
- 7904010286 Forwards LER 79-010/03X-1
  WOOD,E C Maxme Yankes Atomic Power Co 79/05/23 1p
- --7904010259 LER 79-010/03/-1 on 790315 corrects statement contained in LER 79-010/03L-0 Contrary to statement, release did occur & was reported in LERs 79-008/03L-0 & 79-009/03T-0 AMBERSON, P L Maine Yankee Atomic Power Co 79/05/23 2pp
- 7906120411 Forwards LER 79-013/03L-0
  40000E C Maine Yankse Atomic Power Co 79/06/05 1p
- --7906120416 LER 79-013/03L-0 on 790526 reactor protection sys channel D low flow trip bistabale actuated at 24% out of spec in nonconservative direction Gaused by defective bistable Spare unit installed & callbr ANDERSON, P. L. Maine Yankeo Atomic Power Co. 79/06/05 ip
- 7905120322 Forwards LER 79-012/017-0 W000:E C Maine Yankee Alomic Power Co 79/06/06 [p
- --7906120323 LER 79-012/01T-0 on 790524 reactor protection sys low pressure trip bistables in error set at 415 psig Caused by incorrectly transposing data transmitter callbr sheets to procedure Ealibr sheets to procedure Callbr sheets & procedures being revised # Haine Yankes Atomic Power Co 79/06/06 Epp
- DOCKET 50-311 BALEM NUCLEAR GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7904i10056 Trip rapt of 790226-28 visit to plant to conduct onsite review of qualifications methods & procedures for Seismic Category i mechanical components electrical instrumentation. control equipment & supporting structures
  CHEN.P Y. Mechanical Engineering Branch 79/04/23 10pp
- 7908140228 Notification of 790809 meeting w/util in Bethesda.MD to discuss qualification program DROMERICK.A Light Water Reactors Branch 3 79/05/04. 3pp
- 7906060247 Notifies of completion of const & pre-occupational testing Requests issuance of OL in order to proceed w/initial fuel loading & startup.

  SMITH.R. I Public Service Electric & Gas Co of New Jersey 79/03/30 ip.

- J Insurance & indemnity information
- 7906120211 Forwards Endorsements 27,28 & 29 to MAELU Policy MF-90 CORREA,C Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/06/04 App
- P Operating license stage documents & correspondence
- 7906060270 Forwards requested info re main feedwater events, pressurizer heaters & steam generator schematic diagram LIBRIZZI,F.P Public Service Electric & Gas Co. of New Jersey 79/05/23 6pp
- O Inspection reports. IF Bulletins & correspondence
- 7906010040 Forwards IE Insp Rept 50-311/79-15 on 790222 Na noncompliance noted HARTIN.W G Region i, Philadelphia, Office of the Director 79/03/30 ≥pp
- --7906010041 IE Insp Rept 50-311/79-15 on 790222 No noncompliance noted Major areas inspected preoperational fuel receipt & storage practices, pracedures & records SHITH, Q C. JOYNER, J H. Region 1, Philadelphia, Safeguards Branch 79/03/20 3pp
- 7906140632 Forwards IE Insp Rept 50-311/79-19 on 790307-08 No noncompilance noted CARLSON,R T Region 1, Philodelphia, Rvactor Constinction & Engineering Support Branch 79/04/06 2pp
- --7906140635 IE Insp Rept 50-311/79-19 on 790307-08 No noncompliance noted Major areas inspected licensee action on previous const insp findings
  TOTH, A D. MCGAUGHY, R W. Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/Q5 Spp
- 7906180413 Forwards IE Info Notice 79-10. "Noncomforming Pipe Support Strute" No written response necessary CRIER, B K Region i. Philadelphia. Office of the Director 79/04/16 ig
- 7906250476 Forwards IE Insp Rept 50-311/79-18 on 790313-16 & 20 No noncompliance nuted BRUNNER,E J Region I, Philadelphia, Reactor Operations Nuclear Support Dranch 79/04/16 2pp
- --7906280478 IE Insp Rept 50-311/79-18 on 790313-14 & 20 No noncompliance noted Major areas inspected preoperational test program, test procedure review & verification, test regults evaluation & startup test program BETTENHAUSEN, L., FASANJ, A.N., CAPHTON, D.L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/13 12pp
- 7906260491 Forwards IE Insp Rept 80-311/79-21 on 790316,22-23 No noncompliance noted BRUNNER,E J Region 1, Philadelphia. Reactor Operations Nuclear Support Branch 79/04/20 2pp
- ---7906260499 IE Insp Rept 50-311//9-21 on 790316,22-23 No noncompliance noted Major areas inspected containment & radiation process munitors 2811.28126 & 28128 & startup test program, including test procedure review & verification CAPHTON, D. L. PAOLINA, R. BETTENHAUSEN, L. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/19
- 7906(10037 Forwards IE Bulletin 79-058, "Nuclear incident at TMI-Buppl" No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/23 ip
- 7906120081 Requests extension until 790804 to respond to IE Bulletin 79-07
  SCHNEIDER: F. W. Public Service Electric & Gas Co. of New Jersey 70/04/24
- 7908020193 Responds to IE Builetin 79-06A Special task force established to coordinate review & understanding of TMI-2 event Appropriate procedural revisions being prepared Supplemental response will be made prior to 790531 SCHNEIDER;F W Public Service Electric & Gas Co of New Jersey 79/04/25 23pp
- 7906070389 Responds to IE Bulletin 79-04 re meismic Category 1 piping sym w/3,4 or 6-inch diameter valves Weights for 6-inch valves have been corrected awaiting confirmation of 3 & 4-inch weights from Velan 6CHNEIDER,F W Public Bervice Electric & Gas Co. of New Jersey 79/04/30 Spp

- 7706120194 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER, BH Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906260151 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  GRIER, B H Region 1, Philadelphia. Office of the Director 79/05/11 1p
- 7906270206 Responds to IE Bulletin 78-128, "Atypical Weld Matt in Reactor Pressure Vessel Welds " Requests extension of response due date to 791031 SCHNEIDER,F W Public Service Electric & Gas Co of New Jarsey 79/05/14 ip
- 7906200394 Forwards supplemental response to IE Bulletin 79-01 & 79-01A List of qualification documentation & other data encl Safety-related solenoid valves used in containments have been replaced SCHNEIDER, FW Public Bervice Electric & Gas Co of New Jersey 79/06/15 4pp
- R Periodic operating reports & related correspondence
- 7906240417 Forwards wastewater treatment rept for May 1979 MIDURAH G Public Service Electric & Gas Co of New Jersey 79/04/07 2pp
- 7906260418 Forwards operating rept for industrial waste treatment plant for May 1979
  MIDURA, H J Public Service Electric & Gas Co of New Jersey
  79/06/12 2pp
- 7906260349 Forwards discharge monitoring repts for May 1979 MIDURA, H J Public Service Electric & Gas Co of New Jarsey 79/06/19 15pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906070268 Confirms 790601 verbal rept to E Brunner, advising of potential RO Linear cracking observed on pump impeller Spare impeller was tested & also showed cracks Impellers being sent to vendor for testing H1DURA; H J Public Service Electric & Gas Co of New Jersey 79706/01 1p
- DOCKET 50-312 RANCHO SECO NUCLEAR GENERATING STATION
- P Adjudicatory correspondence
- 7906050195 Itemizes structural changes for shutdown condition until all changes are made Long-term mode to be implemented as soon as possible CHILK'S J. Office of the Secretary of the Commission 79/05/07 Bod.
- '996250232 Requests formal hearings re shutdown, mod & reopening of facility CHRISTOPHERSON, REISS, J Friends of the Earth 79/05/15 14pp
- | Quneral correspondence

Comment of Comments

- 906260073 Patitions for formal hearings re plant shutdown, mod  $\epsilon$  respecting VANDERVELDEN, M , REISS, J , CHRISTOPHERSON Friends of the Earth 79/03/15 | 13pg
- 906290854 Responds to 7904i1 ltr on reactor safety, clarifying concerns re Davis-Besse shutdown & geologic faults near Diablo Canyon EIBENHUT.D 0 Division of Operating Reactors 79/05/22 2pp
- Insurance & indemnity information
- 706070144 Forwards Endorsements 31-34 & 37 to HAELU Policy MF-75 & Endorsements 38-40 to MAELU Policy NF-212 MATTIMOE.J.J Bacramento Municipal Utility District 79/05/29, 7pp
- Operating license stage documents & correspondence
- \*\*ObiteOO49 Notification of 790504 meeting w/util in Bethesda. MD to discuss plant mod required by NRC order resulting from TMI-2 event.

  OARNER.E. Operating Reactors Branch 4 (Pre 790625) 79/05/03

- 7906040146 Ack receipt of 790430 ltr claiming exemption from Class III fee for proposed Tech Specs Amend 63 Submittal is not exempt from fee since NRC review effort is required MILLER.W O License Fee Management Branch 79/05/14 2pp
- 7906120320 Submits post-TMI training quiz for facility personnel \* Sacramento Municipal Utility District 79/05/22 2pp
- 7906120315 Confirms 770523 telcon re past turbing & feedwater initiating events installation of direct reactor trip on turbine would result in decrease of 5-s before expected high pressure trip RDDRIGUEZ,R J Sacramento Municipal Utility District 79/05/24
- 7906190335 Forwards summary of 790923 turbine & foodwater initiating events installation of direct reactor trip on trip will result in decrease of five plus seconds before normally expected high pressure trip RODRIGUEZ, R J Sacramento Municipal Utility District 79/05/24
- 7906060287 Submits add1 status of actions info as required by Commission Order No 7590-01 Auxiliary feedwater flow values are within acceptable limits Reactor trip on loss of main feedwater or turbine trip is functional MAYTIMDE, J J Sacramento Municipal Utility District 79/05/29 1p
- 7906050279 Confirms 790507 ropt, "Evaluation of Transient Behavior & Small Reactor Coolant Gys Breaks in 177-Fuel Assembly Plant," was based on actual parameters Submits table comparing parameters used in analysis HATTIMOE, J J Sacramento Municipal Utility District 79/05/30
- 7906120246 Forwards info in response to 790923 telcon Auxiliary feedwater sys flow will be initiated automatically in case of feedwater loss Flow provided by one auxiliary feedwater pump is sufficient to maintain plant in safe condition TAYLOR, J R Babcock & Wilco: Co 79/09/30 3pp
- 790m120268 Provides auxiliary feedwater test specs to verify design flow rate to each steam generator at design back pressure & to verify ability to establish flow rate w/both auxiliary feedwater valves electrically failed CUDRER P Sacramento Municipal Utility District 79/05/30 ip
- 7906120326 Describes design change to provide control-grade trip of reactor on generator/turbine trip &/or loss of main feedwater

  CUBRERF Sacramento Municipal Utility District 79/05/30 Spp
- 7906120275 Rasponds to S Israel 790601 ltr Forwards graphs re diesel generator loads during May 1974 safety features test RODRIQUEZ,R J Sacramento Municipal Utility District 79/06/06
- 7906190441 Notifies that submission of revised radiological effluent Tech Specs is delayed until 790715 MATTIMOE.J J Sacramento Municipal Utility District 79/06/06 ip
- 7906220345 Forwards info requested on 790525 re feedwater piping Diagram of steem generator sys. feedwater line diagram & isometric drawings encl Weldings of feedwater piping done w/gas tungsten arc & shielded metal-arc processes.

  MATTIMOE, J J Sacramento Municipal Utility District 79/06/15 1000.
- G Inspection reports, IE Bulletins & correspondence
- 7906260526 Forwards IE Insp Rept 50-312/78-20 on 781116,28-30 & 1206,15 & 18 No noncompliance noted CRENG.JL Region 5. San Francisco. Reactor Operations Nuclear Support Branch 78/12/27 2pp
- ~~7906260947 IE Insp Rept 50-312/78-20 on 781116.28-30 & 1206.15 & 18 No noncompliance noted Major areas inspected refueling activities.maint.pipe support & restraint sys.followup on previous insp findings & plant operations
  JOHNBON.A.D., HILLER.L.F., Region 5. Ban Francisco, Office of the Director FAULKENDERRY,B Region 5. Ban Francisco, Reactor Operations Nuclear Support Branch 78/12/27 App.

- 7905290263 85W site inspector daily rept on 770407 Plant status reactor eperating at full power w/no known problems Major student deagnstration expected 770408 tANYER.H · CARLEGON.J Region 5. San Francisco, Office of the Director 77/04/07 2pp
- 7706270184 B&W site inspector daily rept on 770408 Plant status reactor operating at full power w/no known problems Antinuclear demonstration expected on 770408
  JOHNSON P, HCRN,A Region 5, San Francisto, Office of the Director 77/04/08 2pp
- 7705290071 B&W site inspector daily rept on 790409 Plant status reactor at full power w/no known problems
  JOHNSON,P , HORN,A Region 5, San Francisto, Office of the Director 79/04/09 2pp
- 7706990510 B&W site inspector daily rept on 790410 Plant status reactor at 75% power w/one coolant pump shut down due to seal leakage constant at 2 1 gallons per minute MCHENRY. T J . QUICK Region 2. Atlanta, Diffice of the Director 79/04/10 2pp
- --7706290543 BbW site inspector daily rept on 790410 Plant status reactor operating normally at full power Honthly surveillance of diesel generator B completed HILLER. I. NORN. A Region 5. San Francisco, Office of the Director 79/04/10 2pp
- 7906010250 Forwards IE Insp Rept 50-312/79-06 on 790320-23 % 29 No noncompliance noted BOOK, K & Region 5, Ban Francisco, Fuel Facility & Materials Safety Branch 79/04/12 2pp
- --7708010254 IE Insp Rept 50-312/79-06 on 770320-23 & 29 No noncompliance noted Major areas inspected licensee action on previous findings, radioactive wasts sys, QC of analytical measurements & independent insp effort THOMAS.R D . BOOK.H E Region 5, Ban Francisco, Office of the Director 79/04/12 Bpp
- 7905270153 B&W site inspector daily rept on 790413 Flant status reactor at full power w/no known problems Verified accuracy of containment isolation valve lineup procedures w/P&ID JOHNSONA A MILLER.L Region 5, San Francisco. Office of the Director 79/04/13 1p
- 7905290445 B&W site inspector daily rept on 790414 Plant status reactor operating at full power w/no known problems No major daint or surveillance scheduled

  JBHSON,A , MILLER,L Region S. San Francisco, Office of the Director 79/04/14 2pp
- 7906290489 8&W site inspector daily rept on 790418 Plant status reactor operating at full power w/no known problems No significant maint scheduled OCHNEONA in MILLER, L. Region 5. San Francisco, Office of the Director 79/04/15 2pp
- 7904290134 Responds to IE Bulletin 79-03A Forwards info re review of operating procedures
  MATTIMOE, J. J. Sacramento Municipal Utility District 79/04/16
  7pp
- 7908290987 8&W site inspector daily rept on 790412 Plant status reactor at full power w/no known problems, no major maint planned & no engineering safety features out of svc JOHNSON, A. MILLER, L. Region 5, San Francisco, Office of the Director 79/04/12 2pp
- 7908290638 86W site inspector daily rept on 790417.Plant status.reactor at full power w/no significant maint or surveillance tcheduled MANSON, A. JOHNSON, P. Region 5. San Francisco, Office of the Director 79/04/17 2pp
- 7906020088 Responds to IE Bulletin 79-058 re setpoint changes in reactor protection sys MATTIMGE, J J. Sacramento Municipal Utility District. 79/04/22 1p
- ---7904020090 Comments on IE Bulletin 79-05 Discusses operator control valuationatic actions of engineered safety features MATTIMDE.J. J. Sacramento Municipal Utility District 79/04/13
- --7706020092 Bubmits partial response to IE Bullatins 79-05 & 79-05A re review of TMI accident chronology to preclude similar recurrences. MATTIMOE, J. Bacramento Municipal Utility District 79/04/11

- 7906140190 Forwards IE insp Rept 50-312/79-04 on 790226-0302 No noncompliance noted CREMS.J L Region 5. San Francisco, Reactor Operations Nuclear Support Branch 79/04/25 2pp
- 7906140205 IE Insp Rept 50-312/79-04 on 790226-0302 No noncompliance noted Major areas inspected surveillance test program SHAFER, W D . JOHNSON A D . WITT, K Region 5. San Francisco. Office of the Director 79/04/24 Spp
- 7906290471 BbW site inspector daily rept on 790420 Plant status reactor operating at full power w/no known problems All engineering safety features operational Next outage scheduled 790512 JOHNSON,P, MORRILL,P Region 5, San Francisco, Office of the Director 79/04/20 2pp
- 7906290132 Responds to IE Bulletin 79-038 Forwards into re procedures & methods for maintaining natural circulation MATTIMOE, J. J. Sacramento Municipal Utility District 79/05/02
- 7906120053 Forwards IE lnfo Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/05/07 1p
- 7906260531 Forwards IE Insp Rept 50-312/79-07 on 790331-0504 No noncompliance noted CREMB.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 79/05/09 2pp
- --7906260543 IE lnsp Rept 50-312/79-07 on 790331-0504 No moncompliance noted Major areas inspected plant operations & IE buildtins or TM1-2 incident
  JOHNSON.A . JOHNSON.P . FAULKENBERRY, B Region 5. Ban
  Francisco, Reactor Operations Nuclear Support Branch 79/05/08
- 7906180484 Forwards IE Info Notice 79~12. "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN R H Region 5. San Francisco. Office of the Director 79/05/10 10
- 7906110077 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics" Whitten response required ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/11 1p
- 7706080244 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/08/18 1p
- 7906270120 Requests info re manual trip on low pressurizer level as stated in Item 4F of IE Bulletin 79-05B
  WILLIAMS.F J Division of Project Management 79/05/18 Spp
- 7906130053 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Bafety Sys " Licenses action required EMGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/22 to
- 7906200058 Forwards IE Info Natice 79-13, "Indication of Low Water Level in Dyster Creek Reactor " ENGELKEN.R H Region 5, San Francisco, Office of the Director 79705/29 1p
- 7906180375 Forwards IE Bulletin 79-12, "Short Period Scram at BWR Facilities " No written response nocessary ENGELKEN,R H Region 5, San Francisco, Office of the Director, 79/03/31 ip
- R. Periodic operating reports & related correspondence
- 7906190252 Forwards monthly operating rept for May 1979 RODRIQUELR J Sacramento Municipal Utility District 79/06/07, ip
- ---7906190254 Monthly operating rept for May 1979. COLCHEGO.R W Sacramento Municipal Utility District. 79/05/31
- 8 Reportable occurrences: LERs & related correspondence
- 7906180228 Forwards PNO-79-67AN
  ENGELKEN:R H Region 5: San Francisco: Office of the Director: 79/05/14 1p

- 7906180275 Forwards PNO-79-67AO ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/21. 1p.
- 7904180347 Forwards PNU-79-47AP ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/03/22. ip
- 7906180370 Forwards PNO-79-67AQ ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/30. ip
- 7906180559 Forwards LER 79-005/03L-0
  MATTIMOE.J J Sacramento Municipal Utility District 79/06/11 1p
- --7906180561 LER 79-805/03L-0 on 790509 two inaccessible safety sys hydraulic snubbers were inoperable Cause unknown One snubber rebuilt & tested; other snubber refilled CGLOMBO,R W Sacramento Municipal Utility District 79/06/11
- 7906190510 Forwards LER 79-001/041-0 MATTIMOE.J J Sacramento Municipal Utility District 79/06/13
- --790&190516 LER 79-001/041-0 on 790529 plant liquid effluent ph exceeded B 5 limit Probably caused by error band associated w/ph alarm setpoint Investigation feasibility of reducing error band GQLOMBO,R W Sacramento Municipal Utility District 79/06/13 ip
- DOCKET 50-313 ARKANBAS NUCLEAR ONE, UNIT 1
- F. Becurity: medical, emergency & fire protection plans
- 7906270147 Responds to 790613 ltr re GA section of fire protection plan. Util has met guidelines of "Nuclear Plant Fire Protection Function Responsibilities. Administrative Controls & GA "No changes planned TRIMBLE, D C Arkansas Power & Light Co 79/06/18 2pp
- 9 Adjudicatory correspondence
- 7906120030 Orders licenses to maintain facility in shutdown condition until specified actions are satisfactorily completed Licenses may request hearing w/respect to order within 30 days. Raquest may not stay affectiveness of order GHILKUS J. Office of the Secretary of the Commission 79/05/17 7pp.
- 7906230129 Orders prompt actions to be taken re design mods & changes in operating procedures Unit shall be shut down until factory completion of actions Long-term mods accomplished promptly

  S. J. Office of the Secretary of the Commission 79/05/17
  - s shutdown of facility until satisfactory completion of of operation procedures evaluation of fures & personnel compliance w/approved

- 7906110443 Notification of 790521 meeting w/util in Bethesda, MD to discuss current voltage analysis relating to loading ST-1 for acceptability w/General Design Criteria 17 VIBSING, G S Operating Reactors Branch 4 (Pre 790625) 79/05/18
- 7905040267 Bubmits info re feedwater & turbine trips resulting in reactor trips & emergency feedwater flow test following startup TRIMBLE, D C Arkansas Power & Light Co 79/05/23 2pp
- 7906290292 Forwards Amend 43 to License DPR-51, safety evaluation & notice of issuance & availability
  REID.R W Operating Reactors Branch 4 (Pre 790625) 79/05/23
- --7906290300 Amend 43 to License DPR-51 revising Tech Specs to reflect plant operating limits for fuel loading to be used in Cycle 4 & adding addl smoke/heat detectors & fire suppression sys REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/23 29se
- ---7908290304 Safety evaluation supporting Amend 43 to License DPR-51

  \* Operating Reactors Branch 4 (Pre 790825) 79/05/23 10pp.
- --7906290308 Notice of issuance & availability of Amend 43 to License DPR-51. REID.R.H Operating Reactors Branch 4 (Pre 790625) 79/05/23 200
- 7706070138 Responds to NRC questions in 770523 meeting re analysis of diesel generator pickup, emergency feedwater flow indication, autostart annunciation in control room & permanent operator training steff Two oversized drawings and TRIMBLE, D C Arkansas Power & Light Co. 79/05/24 7pp
- 7906060258 Responds to NRC questions resulting from 790517 order.
  Two operators will be stationed in central room at
  all times until electric emergency feedwater pump is
  permanently connected to vital power
  TRIMBLE.D C Arkansas Power & Light Ca 79/05/29 ip
- 7905080306 Discusses mod of operating guidelines for small breaks HPI must remain in operation until LPIS is in operation & flowing in excess of 1,000 gallons/minute in each line & stable for 20 minutes
  TAYLOR:J H Babcock & Wilcox Co. 79/05/30 2pp
- 7906:10145 Forwards proposed changes to Tech Specs limiting conditions for operation related to anticipatory reactor trip on loss of main faedwater % or turbine trip CAVANAUGH, H Artenses Power & Light Co 79/06/06 9pp
- 7906120367 Supplements 790516 submittal which proposed changes to Tech Specs Suppl restructures spec requirements re automatic actuation of pumps & block valves Also revises surveillance requirements CAVANAUOH.W Arkensas Power & Light Co. 79/06/08 7pp
- 7906190240 Forwards APL-TOP-1A.Revision 3, "GA Manual Operations," util Position 421 58 re grout matl testing & addl info on Position 421.60 re physical properties of reinforcing steel TRIMBLE, D C Arkansas Power & Light Co. 79706/11. 4pp.
- --7906190245 "OA Manual Operations," Revision 5 CAVAMAUGH.W Arkansas Power & Light Co APL-YOP-1A. 79/08/11, 120pp
- 7906150306 Submits response to 790602 order re review of plant procedures & methods of developing procedures CAVANAUGH. H Arkansas Power & Light Co 79/06/12 3pp
- 7906180468 Responds to NRC 790602 order to review safety procedures & mathods for development Appropriate steps will be taken to ansure personnel adherence to proper procedures & avoid bypassing procedures scieded in 790602 CO CAVANAUGH.W Arkansas Power & Light Co 79/06/12 3pp
- 7905200360 Submits info re design changes in emergency feedwater automatic actuation logic & flow control valve hand switches in control room, addi operator training & procedural changes TRIMBLE.D C Artansas Power & Light Co. 79/06/13 4pp

- 7906200214 Forwards oversized drawings of corrected feedwater lines to steam generator, including results of stress analysis tests & details of welding processes used in making nozzle-to-pipe, pipe-to-sparger & pipe welds, in response to 790525 request TRIMBLE, D C Arkansas Power & Light Co 79/06/18 19pp
- 7702270115 Submits add1 info re gaseous affluent monitoring sys.in response to 790615 request Discusses location of effluent agnitoring sys detectors, range of scintillation detectors & mail detectable palease rate
  7RIMBLE.D C Arkansas Power & Light Co 79/06/22 lipp
- @ Inspection reports. IE Builetins & correspondence
- 7902150023 Forwards IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790212-0318 & notice of violation MADSENO L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/04/04 2pp
- --7905150045 Notice of violation from insp on 790212-0318
  Region 4. Dailas, Office of the Director 79/04/04 ip
- --7906150055 IE Insp Repts 30-313/79-06 & 30-36B/79-06 on 790212-0318 Noncompliance noted inadequacy of control of non-Class IE test equipment HESTERHANL TF. JOHNSON, W D. SPANGLER, R G Region 4. Dallas, Office of the Director 79/04/03 18pp
- 7908290087 B&W site inspector daily rept on 790409 Plant status reactor in cold shutdown for refueling Review of emergency feedwater sys identified problem areas w/suction valves

  Region 4. Dallas. Office of the Director 79/04/09 2pp
- 7906270534 BtW site inspector daily rept on 790410 Plant status reactor in refueling dutage Low pressure turbine motor is being replaced steam generator eddy current tested & design change made to enhance ECCS following small break JOHNSON.W D Region 4, Dallas, Office of the Director 79/04/10
- 7906050213 Requests addl 30 days to respond to IE Bulletin 79-03 re welding piping manufactured by Youngstown Welding & Engineering Records are currently being searched/response to be submitted by 790514 TRIMBLE.D C Arkansas Power & Light Co 79/04/12 1p
- 7905290113 B&W site inspector daily rept on 790411 Plant status reactor in refueling outage Operator training completed Reactor startup scheduled for 790504

  JOHNSON, M Region 4, Dallas, Office of the Director 79/04/11

  209
- 7904290581 B&W site inspector daily rept on 790412 Plant status reactor shut down for refueling Revision in progress to emergency feedwater sys. JOHNEON:W D Region 4. Dallas, Office of the Director 79/04/12
- 7906290147 B&W site inspector daily rept on 790413. Plant status reactor shut down for refueling Initial training requirements of IE Bulletin 79-05A have been completed JOHNSON, W. Region 4. Dallas, Office of the Director 79/04/13 Jpp
- 7908270827 BbW site inspector daily rept on 790417 Plant status reactor in refueling shutdown Discussed proposed design change isolating nonessential valves on low RCB pressure SPANCER, R G , RELLEY, D. L. Region 4, Dallas, Office of the Director 79/04/17 3pp
- 7906290467 BtW site inspector daily rept on 790420 Plant status shut down for refueling, which is now complete Heatup scheduled for 790430 SPANGLER, R.O Region 2. Atlanta, Office of the Director 79704/20 2pp
- 7906070374 Responds to IE Dulletin 79-04 re use of Velan swing check valves Higher weights were used in seismic analysis; analyses are conservative
  TRIMBLE, D.C. Arkansas Power & Light Co. 79/04/27 2pp
- 7906040149 Ack receipt of 790321 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-04 & 50-388/79-04 MADSEN, O.L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/04/30 ip

- --7906040152 Responds to NRC 790228 ltr re violations noted in IE Insp Repts 50-313/79-04 & 50-368/79-04 Corrective actions all effluent monitors to be calibr by 790401 TRIMBLE.D C Ariansas Power & Light Co 79/03/21 2pp
- --7906040136 Forwards IE Insp Repts 50-313/79-04 % 50-368/79-04 on 790203-09 % notice of violation MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/02/28 2pp
- --7906040160 Notice of violation from insp on 790203-09
  \* Region 4. Dallas, Office of the Director 79/02/25 ip
- --7906040162 IE Insp Repts 50-313/79-04 & 50-368/79-04 on 790205-09 Noncompliance noted failure to callbr effluent monitors MURRAY, B Region 4, Dallas, Office of the Director BROWN, G D Region 4, Dallas, Fuel Facility & Materials Safety Branch 79/02/25 4pp
- 7906040209 Responds to IE Bulletin 79-03 Bome ABME BA-312 Type 304 langitudinal welded pipe mfg by Youngstown Helding & Engineering Co installed in safety-related sys Examination program being developed TRIMBLE, D C Arkansas Power & Light Co 79/05/04 Ip
- 7906070181 Responds to IE Bultetin 79-058 re ECCS Describes revised procedures for maintaining natural circulation during unplanned total loss of forced circulation TRIMBLE, D.C. Arkansas Power & Light Co. 79/05/04 Lipp
- 7906120063 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/07
- 7906270140 Requests criteria for continued operation of charging pump per IE Bulletin 79-068 HILLIAKS:FJ Division of Project Management 79/03/08 ip
- 7906110083 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required SEVFRIT, K V Region 4, Dallas, Office of the Director 79/05/11 ip
- 7906250016 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  SEYFRIT, K V Region 4. Dailas. Office of the Director 79/05/11
  1p
- 7906270034 Forwards IE Region IV evaluation of licensee response to IE Bulletin 79-05B VARQA,S A Light Water Reactors Branck 4 79/05/11 ip
- --790627003B Evaluates licensee 790504 response to IE Bulletin 79-05B re revision of procedures for matural circulation & engineered safety features actuation MADSEN, 0 L. Region 4, Dallas, Reactor Operations Nuclear Bupport Branch 79/05/10 2pp
- --7906270041 Forwards response to IE Bulletin 79-058 re revisions of procedures & training operation gersonnel on establishina & maintaining natural circulation
  TRIMBLE.D C Arkansas Power & Light Co 79/05
- 7906270120 Requests info re manual trip on low presu stated in Item 4F of IE Bulletin 79-05B WILLIAMS: F J Division of Project Management. 7
- 7906270513 Supplements 790411 response to IE Bulleti commitments to anticipatory reactor trips Forwards indicating trip on low steam generator level would be anticipatory H/proposed safety evaluation progr TRIMBLE, D. C. Arkenses Power & Light Co. 79/05/21
- 7904260530 Ack receipt of 790423 ltr informing NRC c correct violations noted in IE Insp Repts 50-313/7 50-366/79-05 Requests addl info re steps taken to recurrence of two items of noncompliance MADERN G L. Region 4. Dallas, Reactor Operatic Branch 79/05/22 ip
- 7906200039 Forwards IE Info Notice 79-13, "Indicatic Level in Oyster Creek Reactor" SEVFRIT,K V Region 4, Dallas, Office of the D
- 7906210229 Responds to IE Bulletin 79-11.No Westingle circuit breakers are used in safety-related Class circuits.
  TRIMBLE, D. C. Arkansas Power & Light Co. 79/06/1

- R Periodic operating reports & related correspondence
- 7906130214 Notifies that unit is shut down during Apr 1979; no impingment monitoring rept necessary TRIMBLE,D C Arkansas Power & Light Co 79/06/01 1p
- 7906190262 Forwards monthly operating rapt for May 1979 TRIMBLE.D C Arkansas Power & Eight Co 79/06/14 1
- --7906190265 Monthly operating rept for May 1979
  SHIVELY,C N Arkansas Power & Light Co 79/06/14 4pp
- B Reportable occurrences, LERs & related correspondence
- 790608029B RO 50-313/79-03 on 790425 leak in 1-inch drain socket weld discovered in B decay heat loop discharge in reactor bldg during cold shutdown Guyse unknown Drain line to be replaced Rept to follow O'HANLON, J.P. Arkansas Power & Light Co. 79/04/26 1p
- 7906180142 Forwards PNO-79-67AM MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/09 ip
- 7906180192 Forwards PNO-79-67AN

  MADSEN.G L Region 4. Dallas, Reactor Operations Nuclear Support

  Branch 79/05/16 1p
- 7906180291 Forwards PND-79-67AO & AP MADSEN/O L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/24 1p
- 7906180598 Forwards LER 79-005/03L-0 TRIMBLE.D C Arkansas Power & Light Co 79/06/12 1p
- --7906180607 LER 79-003/03L-0 on 790524 during leak rate testing, penetration V-1 leaked in excess of 50,000 cubic cm/minute Caused by buildup of boric acid crystals on valve seating surfaces Repairs made & penetrations retested SHIVELY.C N Arkansas Power & Light Co 79/06/12 1p
- 7906250265 Forwards LER 79-006/01T-0
  TRIMBLE, D C Arkansas Power & Light Co 79/06/20 ip
- --7906250266 LER 79-006/01T-0 on 790607 vendor notified util of possibility that turbocharger thrust boaring could be damaged under certain repeat start operating modes Procedures modified & improved tube all sys being designed SHIVELY.C N Arkansas Power & Light Co 79/06/20 4pp
- BOCKET 90-315 DONALD C COOK NUCLEAR POWER PLANT, UNIT 1

  G Adjudicatory correspondence

- --7904290100 Notice of issuance & availability of Amends 28 % 10 to Licenses DPR-58 & DPR-74.respectively SCHWENCER.A Operating Reactors Branch 1 (Pre 790625) 79/03/02 2pp
- 7906200460 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite % offsite environ monitoring stations & site maps used for offsite dose determinations or evacuation
  KEPPLER, J. G. Region 3. Chicago. Office of the Director 79/05/17 ip
- 7906070151 Comments on meeting to be hold to provide HI citizens w/better understanding of proposed spent fuel storage expansion
  CAIN.J T Hichigan. State of 79/05/18 1p
- 7906i30287 Suppl to 790104 itr re containment purging during normal plant operation Requests continuation of review of Tech Spec change request for Unit 2, to permit unrestricted purging DOLANJE Indiana & Michigan Power Co 79/06/08 9pp
- 7906260421 Responds to NRC 790611 request for info re feedwater line cracks Forwards 10CFR50 59 evaluation & special procedure guide for feedwater line data collection Commits to periodic ropts, testing & surveillance programs
  HUNIER.R 5 American Electric Power Co., Inc. 79/06/15 30pp
- 7906220293 Submits add1 info requested after review of AEP NRC 00186A, dtd 790504, NRC 790619 telcon re reanalysis of pressurizer surge line
  HERING,R F Indiana & Michigan Power Co 79/06/20 3pp
- 7906250291 Provides info on PMR feedwater lines in response to V Stello 790525 request DOLAN.J E Indiana & Michigan Power Co 79/06/21 16pp
- O Inspection reports, IE Bulletins & correspondence
- 7906040049 Responds to IE Bulletin 79-03 No Type 304 Stainless Steal piping mfg by Youngstown Wolding & Engineering Co is in use or planned for use in facility safety sys DOLAN.J E American Electric Power Co , Inc 79/04/17 2pp
- 7906140603 Forwards IE Insp Repts 50-315/79-07 & 50-316/79-06 on 790419-20 Notice of violation withheld (ref 10CFR2 790) HEISHMAN.R F Region 9, Chicago, Reactor Operations Nuclear Support Branch 79/05/02 2pp
- --7906140609 IE Insp Repts 50-315/79-07 & 50-316/79-06 on 790419-20
  Noncompliance noted failure to maintain isolation zone
  Details withheld (ref 100FR2 790)
  BAKER, R R : MARNICK, R F Region 3, Chicago, Reactor Operations
  Nuclear Support Branch 79/04/20 ip
- 7906120114 Forwards IC Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 ip
- 706/40500 Responds to IE Bulletin 79-04 re incorrect weights of swing check valves made by Velan Engineering Corp Addl weight will not adversely affect capability to withstand seismic event MALONEY, 0 P Indiana & Michigan Power Co 79/05/08 Spp
- 706110094 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11 ip
- 706190076 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/11 Ip
- 706270128 Responds to IE Bulletin 79-09 GE AK-2 circuit breaker not in use in safety-related sys. DOLANJ E Indiana & Michigan Power Co 79/05/15 ip
- 706080203 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/18
- 706220257 Responds to NRC 790504 itr re-due dats for responses to IE Bullatins 78-12,12A & 12B Requests extension to 790702 due to delays encountered in obtaining info re-atypical weld matl from suppliers
  DOLAN, J E Indiana & Michigan Power Co 79/05/21 2pp

- 7706130079 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required " Region 3, Chicago, Office of the Director 79/05/22
- 77:0626:074 Ack receipt of 770426 ltr informing NRC of steps taken to correct violations noted in IE lnsp Repts 50-315/79-03 & 50-315/79-03 DAVIS.A B Region 3, Chicago, Office of the Director 77/05/23
- --7906260093 Responds to NRC 790328 Itr re violations noted in IE Insp Rept; 50-315/79-03 & 50-316/79-03 Corrective actions evacuation drill successfully performed on 790428 OCLAM J E Indiana & Michigan Power Co 79/04/24 1p
- 7736260337 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-04 & 50-316/79-04
- Region 3, Chicago, Reactor Operations Nuclear 79/05/24 1p Support Branch
- --7406220344 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-315/79-04 & 50-316/79-04 Corrective actions withheld (ref IOCRR2 790) DOLAN, J E Indiana & Michigan Power Co 79/05/23 1p
- 77052Q0125 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" FEPPLER.J G Region 3, Chicago, Office of the Director 79/05/29
- 7508030266 Responds to IE Builetin 79-06A, "Review of Operational Everys & Sys Misalignments Identified During TMI Incident " Forwards proposed Tech Specs implementing design changes Class III amend fee encl 5004AM.JE Indiana & Michigan Power Co 79/06/06. App
- --7908080267 Tech Specs implementing design changes to delete low pressurizer water level coincidence logic for safety injection actuation & to convert to two-out-of-three channel logic on low pressurizer pressure only a Indiana & Michigan Power Co 79/06/06 12pp
- 9 Periodic operating reports 5 related correspondence
- 7705120219 Forwards monthly fish impingement repts for Jan. Feb & Mar SHALLER, DV Indiana & Michigan Power Co 79/06/05 16pp
- 7906190272 Forwards monthly operating rept for May 1979 SMALLER,D V Indiana & Michigan Power Co 79/06/13 ip
- --7905190296 Monthly operating rept for May 1979
  QILLETT,W T . LEASE.R B . SVENBBON,B A Indiana & Michigan Power
  Co 79705/04 Spp
- S Reportable occurrences, LERs & related correspondence
- 7906110235 Forwards LER 79-033/03L-0 SHALLER D V Indiana & Michigan Power Co 79/06/04 1p
- --7906110239 LER 79-033/03L-0 on 790308 monthly functional tests for Containment area monitor; containment atmosphere-particulate & containment atmosphere-gaseous monitors were not performed Gaused by daily assignment error. BEELMAN.T P Indiana & Michigan Power Co 79/06/04 2pp
- 7906150329 Forwards LER 79-019/017-0
  BDLAN.J E Indiana & Michigan Power Co 79/06/07 3pp
- --7906630334 LER 79-019/01T-0 on 790519 cracks found in 16-inch feedwater stages adjacent to north welds caused buildup of nonradicactive water in containment sump Caused being determined. Elbows in generators being replaced.

  SHALLER, D. V. Indiana & Michigan Power Co 79/06/08 16pp
- U Congressional/Executive Correspondence
- 7908290672 Requests public hearing re application to increase waste storage capacity at facility Every effort should be made to consider all views Request for add1 waste storage confirms doubte re ability to handle waste problem LEVIN:C Senate 79/05/09. ip.

- 7906070288 Forwards 790909 itr to JM Handrie re hearings & increased radwaste storage LEVIN,C Senate 79/05/10 ip
- --7906070290 Requests NRC hold public hearings re util application to increase nuclear waste storage capacity LEVIN.C Senate 79/05/09 ip
- DOCKET 50-316 DONALD C COOK NUCLEAR POWER PLANT, UNIT 2 H General correspondence
- 7904030409 Requests public hearing prior to NRC authorization for increase in storage capacity of spont nuclear fuel assemblies
  VOITA, J.F. Affiliation Unknown 79/04/13 19
- P Operating license stage documents & correspondence
- 7906290080 Forwards Amends 28 & 10 to Licenses DPR-58 & DPR-74, respectively, safety evaluation & notice of issuance & availability SCHWENCER, A Operating Reactors Branch 1 (Pre 790525) 79/05/02
- --790629008B Amends 28 & 10 to Licenses DPR-58 & DPR-74, respectively, authorizing deletion of installed part-length rods & eliminating all ref to rods from Tech Specs SCHHENCER.A Operating Reactors Branch i (Pre 790625) 79/03/02 54pp
- --7906290092 Safety evaluation supporting Amends 28 % 10 to Licenses DPR-38 % DPR-74, respectively \* Operating Reactors Branch 1 (Pre 790625) 79/05/02 3pp
- --7906290100 Notice of insuance & availability of Amends 20 & 10 to Licenses DPR-50 & DPR-74 respectively SCHHENCER.A Operating Reactors Branch 1 (Pre 790625) 79/05/02 2pp
- 7906200460 Requests site emergency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite environ monitoring stations & site maps used for offsite dose determinations or evacuation KEPPLER. J G Region 3: Chicago. Office of the Director 79/05/17
- 7706070151 Comments on meeting to be held to provide MI citizens w/batter understanding of proposed spent fuel storage expansion CAIN, J.T. Michigan, State of 79/05/18 ip
- 7905130287 Suppl to 790104 ltr re containment purging during normal plant operation Requests continuation of review of Tech Spec\_change request for Unit 2, to permit unrestricted purging DOLAN, J E Indiana & Michigan Power Co 79/06/08 9pp
- 7906260421 Responds to NRC 770611 request for info re feedwater line cracks Forwards 10CFR50 59 evaluation & special procedure guide for feedwater line data collection Commits to periodic repts testing & surveillance programs HUNTER.R S American Electric Power Co . Inc 79/06/15 GOpp
- 7906220293 Submits add1 info requested after review of AEP, NRC, O0186A, dtd 790504, & NRC 790619 telcon re reanalysis of pressurizer surge line HERING:R F Indiana & Michigan Power Co 79/06/20 Spp
- 7906250291 Provides info on PWR feedwater lines in response to V Stello POLAN, J E Indiana & Michigan Power Co 79/06/Rt 16pp
- G Inspection reports, IE Bulletins & correspondence
- 7906040049 Responds to IE Bulletin 79-03 Ng Type 304 Stainless Steel piping mgg by Youngstown Welding & Engineering Co is in use on planned for use in facility safety sys
  DDLAM.J E American Electric Power Co , Inc 79/04/17 2pp
- 7906140603 Forwards IE Insp Repts 50-315/79-07 & 50-316/79-06 on 790419-20 Notice of violation withheld (ref 100FR2 790) HEISHMAN,R F Region 3. Chicago, Reactor Operations Nuclear Support Branch. 79/05/02 2pp

## DOCKETED ITEMS

- ---7904140409 IE Insp Repts 50-315/79-07 & 50-316/79-06 on 790419-20
  Noncompliance noted failurs to maintain isolation zone
  Details withheld (ref 100FR2 790)
  BAKER, K R . MARNICK, F Region 3, Chicago, Reactor Operations
  Nuclear Support Branch 79/04/20 1p
- 7906120114 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/07 in
- 7906140500 Responds to IE Bulletin 79-04 re incorrect weights of swing check valves made by Velan Engineering Corp Addl weight will not adversely affect capability to withstand seismic event MALONEY, O P Indiana & Hichigan Power Co 79/05/OB 5pp
- 7906ii0094 Forwards IE Bulletin 79-io. "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3. Chicago. Office of the Director 79/05/11
- 7906190076 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J.O. Region 3, Chicago, Office of the Director 79/05/11
- 7904270128 Responds to IE Bulletin 79-09 OE AK-2 circuit breaker not in use in safety-related sys DOLAN:J E. Indiana & Michigan Power Co 79/05/15 ip
- 7904080203 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " KEPPLER.J O Region 3. Chicago, Office of the Director 79/05/18
- 7906220257 Responds to NRC 790504 Itr re due date for responses to IE Bulletins 78-12, 12A & 128 Requests extension to 790702 due to delays encountered in obtaining info re atypical weld matl from suppliers DOLAN.J.E Indiana & Michigan Power Co 79705/21 2pp
- 7906130079 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/22 ip
- 7906260074 Act receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-03 & 50-316/79-03 DAVIS.A B Region 3. Chicago, Office of the Director 79/05/23
- ---7706260083 Responds to NRC 770328 ltr re violations noted in IE Insp. Repts 50-315/77-03 & 50-316/77-03. Corrective actions. evacuation drill successfully performed on 770428 DDLAN.J E Indiana & Michigan Power Co 77/04/26 ip
- 7906260337 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-315/79-04 & 50-316/79-04 HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/05/24.
- --7906260344 Responds to NRC 790322 ltr re violations noted in IE Insp Repts 50-315/79-04 & 50-316/79-04 Corrective actions withheld (ref 10CFR2, 790), DDLAN.J E Indiana & Michigan Power Co 79/05/23 ip
- 7908200126 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J O Region 3, Chicago, Office of the Director 79/03/29
- 7906080266 Responds to IE Bulletin 79-06A: "Review of Operational Errors & Sys Missignments Identified During TMI Incident "Forwards proposed Tech Specs implementing design changes Class III amend fee encl DOLAN, J. E. Indiana & Michigan Power Co 79/06/06 App.
- ---7906080267 Tech Specs implementing design changes to delete low pressurizer water level coincidence logic for safety injection actuation & to convert to two-out-of-three channel logic on low pressurizer pressure only.

   Indiana & Michigan Power Co 79/06/06 12pp
- R. Periodic operating reports & related correspondence

... . .! .....

7906120219 Forwards monthly fish impingement repts for Jan,Feb & Mar 1979. SHALLER,D,V, Indiana & Michigan Power Go 79/06/05 lópp.

- 7906190241 Forwards monthly operating rept for May 1979 SHALLER, D. V. Indiana & Michigan Power Co. 79/06/13 ip
- --7906190243 Monthly operating rept for May 1979
  GILLETT.W T Indiana & Michigan Power Co 79/06/04 Bpp
- 8 Reportable occurrences. LERs & related correspondence
- 7906010194 Forwards LER 79-018/03L-0 SHALLER,D V Indiana & Michigan Power Co 79/05/23 ip
- --7906010197 LER 79-018/03L-0 on 790423 during investigation of periodic alarms for steam generator high steam line flow.controller 2 PY 3058 tourbine impulse pressure) was in manual control Caused by controller not being returned to automatic RISCHLING.J L Indiana & Michigan Power Co 79/05/23 2pp
- 7906150329 Forwards LER 79-019/01T-0
  DOLAN, J E Indiana & Michigan Power Co 79/06/07 Spp
- ---7906150334 LER 79-019/01T-O on 790519 cracks found in 16-inch feedwater elbows adjacent to norrle welds caused buildup of nonradioactive water in containment sump Caused being determined Elbows in generators being replaced SHALLER, D V Indiana & Michigan Power Co 79/06/08 16pp
- 7906190295 Forwards LER 7Y-019/01X-1 BHALLER.D V Indiana & Michigan Power Co 79/06/11 1p
- --7905190297 LER 79-019/01X-1 on 790319 small leaks found in feedwater piping to steam generator No further description SHALLER, D V Indiana & Michigan Power Co 79/06/08 ip
- 7906210201 Discusses five deficient transmitters installed in steam generator water level narrow range channels Parts have been returned to Westinghouse for recalibr.

  DOLANGUE Indiana & Michigan Power Co 79/06/15 2pp
- U Congressional/Executive Correspondence
- 7906290672 Requests public hearing re application to increase waste storage capacity at facility Every effort should be made to consider all views. Request for addi waste storage confirms doubts re ability to handle waste problem LEVIN:C Senate 79/05/09 1p
- 7906070288 Forwards 790509 ltr to JM Hendrie re hearings & increased radwaste storage.
  LEVIN. C Senate 79/05/10 ip
- ---7906070290 Requests NRC hold public hearings re util application to increase nuclear waste storage capacity LEVIN.C. Senate 79/05/09. 19
- DOCKET 50-317 CALVERT CLIFFS NUCLEAR POHER PLANT. UNIT 1

  F Security, medical, emergency & fire protection plans
- 790622032B Comments on fire protection safety evaluation Recommendations of consultants are adequadely reflected Proposed fire protection will give reasonable assurance that health & safety of public will not be endangered HALL, R. E. Brockhaven National Leboratory, 79/06/05 4pp.
- P Operating license stage documents & correspondence
- 7905040400 Forwards safety evaluation of proposed design mod to plant 125 volt dc eqs.
  LAINAS, 0. Plant Bystems Branch 79/04/30 2pp
- ---7906040405 Safety evaluation of proposed design mod of plant 125 volt dc sys Accepts proposed change \* Plant Systems Branch 79/04/30, 6pp
- 7906250151 Summary of 790517 meeting w/util in Bethesda,MD re auxiliary feedwater sys & related areas CONNER,E L Operating Reactors Branch 4 (Pre 790625), 79/05/24 4pp
- 7906010247 Forwards revision to Section 10 of fourth cycle reload amend application Revision covers startup & hot functional testing, initial criticality, low power physics testing & acceptance criteria LUNDVALL: A E Baltimore Gas & Electric Co 79/05/29 5pp

```
TIMO4024B Forwards proprietary & nonproprietary versions of CEN-111(B). "Sleeved Fuel Assembly Insp Results at Calvert Cliffs Unit 1" W/affidavit requesting withholding of froprietary version LUNDVALL.A E Baltimore Oas & Electric Co 79/05/31 5pp
                                                                                                                                                                                                  7906260093 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
Assemblies "
ORIER B K Region 1. Philadelphia, Office of the Director
79/05/11 ip
                                                                                                                                                                                                  7706080066 Forwards IE Circular 79-08, "Attempted Entertion - Low Enriched U"
--7904040230 "Sleeved Fuel Assembly Insp Results at Calvert Cliffs
Unit 1," nonproprietary version
4 C-E Power Systems CEN-111(8)-NP 79/05/31 28pp
                                                                                                                                                                                                       CRIER'S H Region 1. Philadelphia, Office of the Director 79/05/18 1g
POSIZOZAS Ack receipt of NRC 790524 comments ro util actions in response to IE Bullatin 79-06B Clarifies actions re fersonnel training void formation containment isolation, reactor coolant yum operation by sys operability reactor coolant yum operation by sys operability iUNIDVALL.A E Baltimore Gas & Electric Co 79/06/05 App
                                                                                                                                                                                                 7906150366 Notifies that ASCO solmoid valve used to operate containment purge valves does not meet post-accident environ qualification per IE Bulletins 79-01 & 79-01A LUNDVALLIA E Baltimore das & Electric Co 79/06/13 ip
                                                                                                                                                                                                  ---7906150369 Responds to IE Bulletins 79-01 % 79-01A Forwards rept
summarizing environ qualification data ASCO solonoids are
used for containment purge valves Will prohibit operation
until solenoid valves replaced M/o encl
LUNDVALLA E Baltimore Cas & Electric Co 79/06/13 2pp
705150141 Submits responses to NRC 790607 questions re gaseous
effluent monitoring sys
WillE,H B Baltimore Gas & Electric Co 79/06/12 6pp
9382102B3 Discusses agreement woutil to provide care for patients from facility Commitment does not include radiation accident victims Requests info re pipusician training requirements, radiation offils & accident guidelines
JACOBS. J P Calvert Memorial Hosp FR, Maryland 79/06/15 1p
                                                                                                                                                                                                  R Periodic operating reports & related correspondence
                                                                                                                                                                                                  7906250262 Forwards monthly operating repts for May 1979
MERSON 6 D Baltimore Gas & Electric Co 79/06/15
138220231 Forwards Amend 57 to application for OL re sita emergency
plan.
LUNDVALL, A E Baltimore Gas & Electric Co 79/06/15 7pp
                                                                                                                                                                                                    --7906250263 Monthly operating repts for May 1979
MERSONS D Baltimore Cas & Electric Co 79/06/15 13pp
POS2BOLGS Submits additinfore manual bypasses of actuation syssignals, in response to NRC telcon request Clarifies items identified during investigation of safety actuation circuits incorporating manual override features
LUNDVALL, A.E. Baltimore Oas & Electric Co. 79/06/21 2pp
                                                                                                                                                                                                  S Reportable occurrences, LERs & related correspondence
                                                                                                                                                                                                  790604019! Forwards LER 78-001/03L-0
DOUGLASS.R M Baltimore Gas & Electric Co 78/01/09 1p
                                                                                                                                                                                                  --7906040202 LER 78-D01/03L-0 on 771210 azimuthal power tilt exceeded

Yech Specs limits Caused by positive bias being estimated

slightly below value of 0 020 Proposed Tech Spec change

submitted to permit use of addl incore detector segments

RUSSEL.L B Baltimore Gas & Electric Co 78/01/09 2pp
Inspection reports, IE Bulletins & correspondence
NAOZD199 Responds to IE Bullotín 79-03 re ASME SA-312 stainless steel
fips spools Forwards info on application of Youngstown
Welding & Engineering Co pipe matl supplied to facility
LUNDVALL.A E Baltimore Gas & Electric Co 79/04/16 3pp
                                                                                                                                                                                                  7706070296 Forwards LER 79-018/04T-0
RUSSELL,L B Baltimore Gas & Electric Co 79/05/31 1p
Oblicoof Forwards IE Bulletin 77-05B, "Nuclear Incident at TMI-Suppl" No written response required CRIER, BH Region 1. Philadelphia. Office of the Director 79/04/23 1p
                                                                                                                                                                                                  ---7906070301 tER 79-018/04T-0 on 790517 dyster samples showed Ag-liOm at 88 plus or minus 5% pci/kg & decreasing May be caused by depuration No corrective action required EHERTS.R F Baltimore Gas & Electric Co 79/05/31 2pp
06120285 Forwards reponses to IE Bulletin 79-07, "Seismic Stress
Analysis of Safety-Related Piping " None of methods
specified were used in design of facility Lists computer
codes & verification methods
LUNDVALL,O E Baltimore Gas & Electric Co 79/04/24 2pp
                                                                                                                                                                                                  7906080247 Forwards LER 79-015/03L-0
RUSSELL,L 3 Baltimore Qas & Electric Co 79/06/04 1p
                                                                                                                                                                                                  --7906080248 LER 79-015/03L-0 on 790507 low pressure safety injection pump stopped for 15 minutes due to spurious recirculation actuation signal Gaused by voltage transient Test procedures
06130215 Ack receipt of 790419 itr informing NRC of steps taken to
correct violations noted in IE Insp Repts 50-317/79-02 &
30-3187/79-03
NARTIN-N O. Region i, Philadelphia, Safeguards Branch 79/04/30
                                                                                                                                                                                                            revised
DAVIS,M , MIERNICKI.M J Baitimore Gas & Electric Co 79/06/04
790&150218 Responds to NRC 790330 ltr re violations noted in IE lasp
Repts 50-317/79-03 & 50-318/79-03 Corrective actions
withheld (ref 10CFR2 790)
EVANS.V R Baltimore Oas & Electric Co 79/04/19 ip
                                                                                                                                                                                                  7906140348 Forwards LET 77 007 001 0
7908150219 Forwards IE Insp Repts 50-317/79-03 & 50-318/79-03 on
790206-08 Notice of violation withheld (ref 10CFR2 790)
MARTIN.W C Region 1, Philadelphia, Safeguards Branch
79/03/30 2pp
7906150222 IE Insp Repts 50-317/79-03 & 50-318/79-03 on 790206-08
Noncompliance noted detection aids inadequate Details
withheld (ref 100FR2 790)
ROGEREM 4 DEULIN, J. MARTIN, W. Region 1, Philadelphia,
Safeguards Branch 79/03/29 1p
                                                                                                                                                                                                      w/feedwater piping Forwards isometric drawings of reeswater
Lines in containment & all pipe supports & results of stress
analyses for feedwater lines
LUNDVALL,A E Baltimore Gas & Electric Co 79/06/19 App
06140498 Responds to IE Bulletin 79-09 re failure of GE Type AK-2
ircuit breakers in safety-related sys Breaker used in
eactor ewitch gear
uppDVALL.A E Baltimore Oas & Electric Co 79/05/05 2pp
                                                                                                                                                                                                  2 TIRU ,TRAIR SALVERT CLIFFS NUCLEAR POWER PLANT, UNIT 2
                                                                                                                                                                                                  F Security, medical, emergency & fire protection plans
```

0.120150 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required RIER.B H Region 1. Philadelphia, Office of the Director 19/05/07 2pp

06110116 Forwards IE Bulletin 79-10. "Requalification Training program Béatistics " Written response required. Region 1. Philadelphia, Office of the Director '19/05/11. Ip

7905220328 Comments on fire protection safety evaluation Recommendations of consultants are adequadely reflected Proposed fire protection will give reasonable assurance that health & safety of public will not be endangered HALL, R.E. Brootheven National Laboratory. 79/06/05 4pp

- P Operating license stage documents & correspondence
- 790604000 Forwards safety evaluation of proposed design mod to plant 125 volt do sys
  LAINAS, 0 Plant Systems Branch 79/04/30 200
- --7906040405 Safety evaluation of proposed design mod of plant 125 volt dc sys Accepts proposed change \* Plant Systems Branch 79/04/30 App
- 7906230151 Summary of 790517 meeting w/util in Bethesda, HD re auxiliary feedwater sys % related areas CONNER, E.L. Operating Reactors Branch 4 (Pre 790623) 79/05/24
- 7906120265 Ack receipt of NRC 790524 comments re util actions in response to IE Bulletin 79-068 Clarifies actions re personnel training, vaid formation containment (solation, reactor coalant pump aperation & sys operability LUNDVALL, A E. Baltimore Gas % Electric Co 79/06/05 App
- 7906150141 Submits responses to NRC 790607 questions re gaseous affluent monitoring wys MYLIE, H B Baltimore Gas & Electric Co 79/06/12 App
- 79062:0285 Discusses agreement w/util to provide care for patients from facility Commitment does not include radiation accident victims Requests info re physician training requirements, radiation drills & accident guidelines

  JACOBS. J P Calvert Memorial Hosp FR. Maryland 79/06/15 lp
- 7906220331 Forwards Amend 57 to application for CL:re site emergency plan LUNDVALL:A E Baltimore Gas & Electric Co 79/06/15 7pp
- 7906280135 Submits add1 info re manual bypasses of actuation sys signals, in response to NRC telcon request Clarifies items identified during investigation of safety actuation circuits incorporating manual override features LUNDVALL, A E Baltimore Gas & Electric Co 79/06/21 2pp
- G Inspection reports. If Bulletins & correspondence
- 7904020199 Responds to IE Bulletin 79-03 re ASME SA-312 stainless steel pipe spools Forwards info on application of Youngstown Welding & Engineering Co pipe matl supplied to facility LWNDVALL.AIE Baltimore Gas & Electric Co 79/04/16 3pp
- 7906110007 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " No written response required ORIER,B H Region 1, Philadelphia, Office of the Director

- 7706110116 Forwards IE Bulletin 77-10, "Requalification Training Program Statistics " Written response required ORIER.B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906260093 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.B H Region I, Philadelphia. Office of the Director 79/05/11 ip
- 7906080066 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched V " GRIER, B H Region 1. Philadelphia, Office of the Director 79/05/18 ip
- 7906150366 Notifies that ASCO solencid valve used to operate containment purge valves does not meet post-accident environ qualification per IE Bulletins 79-01 & 79-01A LUNDVALL.A E Baltimore Gas & Electric Co 79/06/13 ip
- --790619036B Responds to IE Dulletins 79-01 % 79-01A Forwards rept summarizing environ qualification data, ASCO solenoids are used for containment purge valves Will prohibit operation until solenoid valves replaced W/o encl LUNDVALL.A E Baltimore Gas & Electric Co 79/06/13 2pp
- R Periodic operating reports & related correspondence
- 7706250262 Forwards monthly operating repts for May 1979 MERSON: S D Baltimore Gas & Electric Co 79/06/15 ip
- --7906250263 Monthly operating repts for May 1979
  MERSON, S D Baltimore Gas & Electric Co 79/06/15 13pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906040354 Forwards LER 78-030/03L-0 DOUGLASS,R M Baltimore Gas & Electric Co 78/09/26 ia
- --7906040337 LER 78-030/03L-0 on 780828 discovered control element assembly motion inhibit not operable for position deviation Caused by bad K2 relay on relay card Relay replaced & motion inhibit returned to svc CARROLL.J T. MIERNICK:M J Baltimore Qas & Electric Ca 78/09/24 19
- 7904010200 Forwards LER 79-014/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 79/05/25 1p
- --7904010207 LER 79-014/03L-0 on 790520 while inserting Oroup 5 control element assemblies.CEA 34 dropped to bottom of core Caused by spike in 15 volt power supply Design mod to be installed during next refueling outage
  DAVIG.S M , MIERNICKI.M J Baltimore Gas & Electric Co 79/05/25
- 7704030263 Forwards LER 79-013/03L-0 RUSSELL,L B Baltimore Gas & Electric Co 79/05/25 ip
- -7906050265 LER 79-015/03L-0 on 790519 containment air lock outer door air leekage discovered to be in excess of Tech Spec limits Caused by failed door gasket New gaskets installed & door latch rollers adjusted LAOIEMBKI, J B. MIERNICKI, M J Baltimore Gas & Electric Co 79/05/25 1p
  - .060289 Forwards LER 79-017/03L-0 ISSELL, L B Baltimore Qas & Electric Co 79/05/31 1p
  - '06060288 LER 79-017/03L-0 on 790320 during surveillance testing diesel generator 21 failed to start upon actuation of remote start switch Gaused by normally de-energized low speed raley being energized during initial test CARROLL.J T. Baltimore Gas & Electric Co 79/05/31 2pp
  - 070294 Forwards LER 79-018/04T-0 SBELL,L B Baltimore Gas & Electric Co 79/05/31 1p
  - 06070301 LER 79-010/04T-0 on 790317 oyster samples showed Ag-110m at 80 plus or minus 5% pci/kg & decreasing May be caused by depuration. No corrective action required EHERTS.R F Baltimore Oas & Electric CD 79/05/31 2pp
  - 220315 Responds to V Stello 790525 ltr re possible design problem feedwater piping Forwards isometric drawings of feedwater nes in containment & all pipe supports & results of stress aliyes for feedwater lines
    NDVALL-A E Baltimore Cas & Electric Co 79/06/19 6pp

- 7906250271 Forwards LER 79-020/03L-Q RUSSELL.L B Baltimore Gas & Electric Co 79/06/19 1p
- --7906250273 LER 79-020/03L-0 on 790602 during safety injection tank maintraafety injection tank 22B docreased to 185 inches at 1730 Caused by seat leakage on 22B safety injection tank ecceeding leaking expectations Valve will be repaired CARROLL, J T Baltimore Gas & Electric Co 79/06/19 ip
- 7906260338 Forwards LER 79-018/03L-0 RUSSELL-L B Baltimore Gas & Electric Co 79/06/21 ip
- --7905260348 LER 79-018/03L-0 on 790527 4 kV feedwater breaker 152-240t tripped open causing loss of power to 4 kV bus 24 Caused by spurious signal or momentary loss of power to ESFAS IB logic cabinet 2068L No further action required DAVIS.8 M , MIERNICKI.M J Baltimore Gas & Electric Co 79/06/21
- 7908260439|Forwards LER 79-019/03L-0 RUSSELL.L. B Baltimore Qas & Electric Co 79/06/21 1p
- --7906260482 LER 79-019/03L-0 on /90525 during performance of surveillance testing, engineered safety features actuation sys module SIAS B-B failed to actuate at 1,730 Cause unstated Module replaced
  CARROLL, J T , MIERNICKI, M J Baltimore Gas & Electric Co
  79/06/21 1p
- DOCKET 50-320 THREE MILE ISLAND NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7906290189 Discusses enci B&W responses to NRC request for info re gameric issues identified in answers to BSAR-241 first round questions TEDESCO.R L Assistant Director for Plant Systems 76/04/08 1p
- --7906290227 Requests that B&W submit detailed responses re generic items applicable to B&W plants currently in CP & post-CP stage of review IPPOLITO, T A Electric, Instrumentation & Control Systems Branch, 75/02/24 App
- ---7905270233 Requests addl generic info re B&W's integrated ccontrol sys & steam line break inside containment GCHMENCER, A Division of Reactor Licensing (NRR-1975 only). 75/04/04 3pp
- --7906290248 Responds to NRC 750404 ltr re generic B&W design info Discusses each requested item & parameters employed in completing response to NRC request BUHRKE, K E Babcock & Wilcox Co 75/05/29 2pp
- --7906290259 Discusses Item 3 in NRC 750404 ltr re main steam line break inside containment & engineered safety features actuation SUHRKE, K E Babcock & Hilcox Co 75/07/29 2pp
- --7906290273 Discusses Item 6 in NRC 750404 ltr re ECCB actuation prior to reactor trip SUNRKE, K E Babcock & Wilcox Go 75/09/13 App
- --7906290207 Discusses Items 1,2 & 5 in NRC 750523 ltr re integrated control sys, safaty-related sys & protection against loss of reactor coolant flow due to electrical grid frequency transients

  BUHRKE, K E Babcock & Wilcox Co 75/12/30 lipp
- --7906290298 Confirms 740419 telcon that B&W will incorporate automatic auxiliary feedwater initiation sys into design to meet requirements of IEEE-279. MALLAY, J F Babcock & Wilcox Co 74/04/24 ip
- --7906270309 Discusses 730131 telcon w/R Edwards re secondary system equipment which B&W assumes to be available during LOCA.

  DAVIB: D. K. Atomic Energy Commission (Pre 1975) 73/02/08 ip
- --7906290318 Minutes of 700225 meeting w/8&W re systematic failures of 8&N reactor protection sys
  IPPOLITO.T.A Atomic Energy Commission (Pre 1975) 70/04/16
- C Utility Environmental Report (ER), amends & correspondence
- 7908230149 Draft "BbW 205-Decay Heat Removal After Small Break." \* Babcock & Wilcox Co 77/04/30 124pp

- F Security, madical, emergency & fire protection plans
- 7904100012 Notifies that fire test of full scale vertical cable tray array was conducted on 780915 at UL Mods to certain NRC fire protection criteria may be necessary

  DENTON: H R Office of Nuclear Reactor Regulation 78/09/29 Zpp
- 7908220192 Forwards info re emergency planning insps STOHR, J.P. Region I. Philadelphia, Office of the Director 79/05/09 2pp
- 7906220145 Discusses removal of matl from within THI-protected area Matl can only be removed under health physics personnel EXECUTE LIMROTH, D F Metropolitan Edison Co 79/05/17 4pp
- 7906260204 Responds to 790518 ltr re extra precautionary measures for area transmission sys Adequate sources of power are available for operation of unit
  VULLMER.R H Assistant Director for Site Analysis 79/05/19 ip
- ---740626020B Requests and of extra precautionary measures taken to assure adequate power to plants
  ARNOLD.R C General Public Utilities 79/05/18 ip
- ~-7906260211 Notifies that precautionary measures taken to maintain power supply are no longer necessary Personnel on standby at suitching station are needed elswhere Forwards outline of electrical sys WERTS.R W General Public Utilities 79/05/03 Jpp
- 7906290432 Forwards memo re fire protection & security deficiencies at TMI Requests scheduling of necessary insp effort GRIER.B H Region 1, Philadelphia. Office of the Director 79/05/21 jp
- --7906270440 Forwards memo raising questions refire protection & security deficiencies at TMI-2 Requests action MOSELEY, N C Division of Reactor Operations Inspections 77/05/14 1p
- 7906220095 Special operating procedures & emergancy procedures, for 790430-0604 Office of Nuclear Reactor Regulation 79/06/04 800pp
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO.JF Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 CRESTENBURY.E Hearings Division 79703/26 34pp
- 7905140018 Board notification semiscale experiment 8-A7-6 Unanticipated results re cladding temp require further study to determine safety significance Certificate of Svc enci # Hearings Division 79704/05 54pp

- 790622006B Plaintiff's first set of interrogatories in Civil Action 79-1185, UB District Court for Eastern District, PA JOHNSRUD, J H Affiliation Unknown 79/05/18 17ap
- 7906290091 Complaint for injunctive relief in City of Lancaster v #RC filed in DC US District Court Seets enjoinment of radioactive discharge.
  LEFEVER.D E. MATTSON, C. W. Barley, Snyder, Cooper & Barber WILMARTH, A.E. Arent, Fox. Kintner, Plotkin & Kahn 79/05/20 SOpp
- 7906060142 Order requiring preservation of all records re TMI by all parties directly involved w/util Records are to be preserved intact until released by NRC authorities or order CHILK, S J Office of the Secretary of the Commission 79/05/22.
- 7906260297 Bummary of meeting w/NRC solicitor to discuss action of City of Lancaster,PA KNIOHTON,O K Engineering Branch 79/05/22 2pp
- 7706260304 Answers to interrogatories submitted by City of Lancaster. PA.including activity level & isotopic content of water KNIOHTON. © Engineering Branch 79/05/24 33pp
- --7906260308 Interrogatories for NRC Affidavits are requested to answer questions on activity level & isotopic content of water, how quantities are established, monitoring sys & history of discharges 
  \* Lencaster, PA 79/05/22 2pp
- 7906270206 Affidavit re TMI-2 health & safety impact Util not prepared to respond promptly to accident, esposure info is inconsistent & exposure increases w/distance from plant.

  KEPFORD, C Citizens for Safe Environment 79/05/24 App
- 7906210095 NRC motion for summary disposition re radon issue was in error. ALAB-540 consolidated only 5 of 16 cases Denies NRC motion re parties in other proceedings. W/Cestificate of Svc DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/05/25.
- 7906230107 Request by utils that ABLAB grant summary disposition of all issues in consolidated radon proceeding. Utils seek decision as natter of lawino genuine issue as to mati facts
  BILBERO: J A Shaw. Pittman, Potts, & Trowbridge VOIOHT, H H
  LeBoeuf, Lamb. Leiby & MacRae CONNER, T. B Conner, House & Corber 77/05/25. 4pp.
- --7906230110 Statement of math facts re radon proceedings for which there is no genuine issue to be heard. Discusses alleged Deficiencies i-7.9-18,20-24 & 26 Affidavit of HI Goldman & supporting documentation encl.

  SILBERO. J A Shaw, Pittman, Potts, & Trowbridge VOIGHT, HH LeBosuf, Lamb, Leiby & MacRae CONNER, T B Conner, Moore & 79/03/25. 36pp

- 7906190482 Confirms verbal request for PA Energy Dept to continue to collect & collate all TMI environ sampling data from all federal agencies & PA Dept of Environ Resources GERUSKY.T M Pennsylvania. State of 79/04/06 1p
- 7906290240 Discusses problems encountered w/overheating of low & high pressure injection pumps when auxiliary feedwater sys is started MARTIN.R E Division of Systems Bafety 79/04/08 ip
- 7906070001 Requests arrangements be made for medical sycs required during TMI Info partially withheld social security number of individual (ref FOIA Exemption 6) BEARD.) T Plant Systems Branch. DENTON.H R Office of Nuclear Reactor Regulation 79/04/09 1p
- 7906060137 Responds to ltr re TMI Info partially withheld name & address of recipient (ref FQ1A Exemption 6)
  BRADFORD, P A Commission 79/04/11 1p
- 7906010109 FOIA request for transcripts of investigatory interviews w/control room personnel involved in TMI incident MINARCIN.P Pennsylvania Illustrated, Inc., 79/04/12 ip
- 7906060163 Responds to ltr re TMI Info partially withheld name & address of recipient (ref FDIA Exemption 6).

  BRADFORD,P A Commission 79/04/12 ip
- 7906060167 Responds to 790328 Itr re TMI Info partially withheld, name & address of recipient & portion of document unrelated to TMI (ref FOIA Exemption 6) BRADFORD, P A Commission 79/04/12 2pp
- 7706130469 Responds to 790316 ltr to R Ryan which expressed concern for difficulty in trying to obtain info re facility shutdown ORIER.B H Region 1. Philadelphia. Office of the Director 79704/12 2pp
- 7906060202 Comments on test for radiation exposure performed at request of individual who traveled by train past TMI on 790328 Info partially withheld name & address of person (ref FOIA Exemption 6)
  GUAIFE.M A Nebraska. Univ of, Radiation Health Center 79/04/13
- 7904200439 Provides info re activities while at TMI-2, for 790330-0407 Critical of lack of coordination between procedure writers, B&W & util support personnel VERDERY,E H Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/13 2pp.
- 7906060225 Forwards names to be added to 790413 list for rediction work permit training list of individuals qualified for unescorted badges Info partially withheld Social Security numbers (ref FDIA Exemption 6)
  SHITH.0 H Office of Inspection & Enforcement 79/04/14. Spp.
- 7906220209 Requests that encl notice be published in 790423 FR. FRALEY.R F. ACRB Advisory Committee on Reactor Bafeguards 79/04/19 2pp
- 7906070379 Ack receipt of 790413 ltr commenting on financial responsibility of nuclear facility owners re TMI-2 incident SNYDER.O L Region i, Philadelphia, Office of the Director 79704/20 ip
- --7906070380 Requests financial responsibility for YMI-2 incident be placed on Metropolitan Edison & stockholders ZEITLIN,H Affiliation Unknown, 79/04/13 2pp
- 7906130089 Acks receipt of 790416 ltr commenting on inadequate supply of water BNYDER, O.L. Region i, Philadelphia, Office of the Director, 79/04/20, ip
- --7906130093 Comments on plant licensing & inadequate water supply. BALDABSARI.J.A Affiliation Unknown 79/04/16 2pp
- 7906120005 Ltrs from citizens expressing opinions we nuclear power. GORDON, D Affiliation Unknown 79/04/24 25pp.
- 7906220129 Accepts proposal of periodic briefing sessions between involved agencies Group must first designate responsibility for routine & emergency environ activities HENDRIE. J M. Commission. 79/05/02 ip.

- 904220063 Confirms request for PA National Guard helicopter & pilot for TMI aerial monitoring SMITH-Q H Region I, Philadelphia, Office of the Director 79/03/QQ 1p
- 90:22015: Discusses NRC health physics staffing W/info re water sampling & soil waste shipments SMITH.GH Region : Philadelphia. Office of the Director 79/05/11 Bpp
- 905250395 Offers help in conducting studies re emergency evacuation plans Discusses prior experience in crisis relocation field Forwards prof qualifications of staff DZURIK.A A Contingency Planning Associates 79/05/14 7pp
- '706010107 Denies FOIA request for transcripts of interviews w/TMI control room personnel (ref FOIA Examption 7)
  FELTON. J H Division of Rules and Records 79/05/21 ip
- 1906220072 Forwards name of contractor from whom trailer was rented Asis whether NRC intends to pay rental for location of trailer FABIAN. B F Metropolitan Edison Co 79/05/23 1p
- FCS260492 Responds to citizen ltrs expressing views on nuclear power & closing of B&W reactors Describes NRC actions replant modernocedure revisions & addl personnel training DENTON, HR Defice of Nuclear Reactor Regulation 79/05/25 26pp
- 1906280322 Responds to Citizen ltrs expressing views on nuclear power & closing of 1840 reactors Describes NRC actions replant mods, procedure revisions & addl personnel training DENTON, HR Office of Nuclear Reactor Regulation 79/05/25 79/05/25 Bipp
- 790525052B Responds to citizen ltrs to JM Hendrie expressing views on nuclear power & closing of BBW reactors Describes NRC actions re procedure revisions & addl personnel Training
  DENTGN, H R. Office of Nuclear Reactor Regulation 79/05/25 57pp
- 7905270006 Responds to citizen ltrs to UM Hendrie re nuclear power & closing of B&W meactors Describes NRC actions re revising operating procedures, plant mods & addit personnel training BENTON, H R Office of Nuclear Reactor Regulation 79/05/25 29pp
- 7906270009 Responds to citizen telegrams expressing opinion on nuclear power & closing of B&W reactors Decribes NRC actions te revising operating procedures, plant mods & addl personnel telegrams. training DENTON.H R. Office of Nuclear Reactor Regulation 79/08/25 12pp
- 7906270019 Responds to citizen postcards expressing opinions on nuclear power & closing of B&H reactors Describes NRC attions re revising operating procedures & plant mads DENTON, H R Office of Nuclear Reactor Regulation 79/05/25
- 7996290016 Responds to citizen ltrs expressing views on nuclear power † TKI incident Results of NRC investigation will be disseminated to public when completed DENION, R R Office of Nuclear Reactor Regulation 79/05/25 78pp
- 7706290138 Responds to citizen ltrs to President Carter re nuclear power & closing of 8½W reactors Describes NRC actions re revising operating procedures; plant mods & add personnel DENTON, H. R Office of Nuclear Reactor Regulation 79/05/25 21pp
- 7906280500 Supports continued operation of nuclear plants, in sgite of TMI-2 incident Past record of safe operation does not warrant negative actions
  LAYZARI.A Affiliation Unknown 79/05/29 2pp
- 7906290770 Ack receipt of 790412 itr to JM Hendrie supporting nuclear power plant operation As result of TMI.emergency planning will take on greater emphasis RYAN.R.O. Office of State Programs 79/05/29 5pp
- --7906290785 Comments on UM Hendrie testimony before 0 Hart committee re IMI Smaller towns than Harrisburg could not be evacuated in one hour. RANDALL-M.S. Affiliation Unknown 79/04/12 2pp
- 7906060254 Expresses appreciation for suggestions to help improve conditions at TMI DENTON: HR Office of Nuclear Reactor Regulation 79/05/30. ip
- ~~7906080262 Offers suggestions to release gas bubble pressure. Info partially withheld, home telephone number (ref FOIA Exemption 6). ALLEN.R. Affiliation Unknown 79/03/31 1p

- 7906120419 Eipresses concern re sabotage of nuclear power plants JONES.T Affiliation Unknown 79/06/05 ip
- I Financial information
- 7906120372 Forwards "Annual Financial Rept 1978"
  HERBElN.J G Metropolitan Edison Co 79/06/07 1p
- --7906120380 "Annual Financial Rept 1978 " \* Metropolitan Editon Co / GPU Service Corp 78/12/31 119pp
- J Insurance & indemnity information
- 790629036B Discusses effact of classifying THI-2 incident as estraordinary nuclear occurrence, which would trigger waiver of defenses under Price-Anderson Act SHAPAR, H K Office of the Executive Legal Director 79/03/28 ip
- 7906290177 Discustes record of TMI-related action re insurance for 790328-0401 BALTZMAN, J Antitrust & Indemnity Group 79/04/27 lipp
- 7906010193 Discusses facility Policies NF-220 & MF-73:Secondary Financial Binders EB-65 & EX-65 reliability limits as result of TMI incident CARRIER.W C American Nuclear Insurers 79/05/29 2pp
- 7906150258 Provides updated info re wage loss claims & evacuation claims from 790521 0606 Forwards form "Final Settlement Resume" for use in cunnection w/wage loss evaluation CARRIER.W C American Nuclear Insurers 79/06/12 2pp
- 7906210204 Forwards Endorsement 34 to MAELU Policy MF~73 GERETY: H F GPU Service Corp 79/Q6/15 2pp
- 7906280126 Addresses reinstatement of Pools' liability policy for Metropolitan Edison Co Matter still under consideration w/carrier to supply current claim expense figures PRODM, B C American Nuclear Insurers 79/06/22 ip
- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906220434 Requests publication by 790403 of encl FR notice re ACRS 790405-09 meeting FRALEY.R F Office of the Executive Director for Operations FRALEY.R F 19
- ~~7906220439 Notification of 790405-09 meeting w/ACRS in Washington, DC to discuss TMT incident CHILKIS J Office of the Secretary of the Commission 79/03/29
- 7906220237 Ferwards list of recipients of 790328 FR notice re ACRB subcommittee 790404 meeting on TMI \* Division of Operating Reactors 79/03/30 2pp
- --7906220274 Forwards FSAR Chapter 5.Reactor Coolant Sys.& Chapter 6. Contingency Safety Features.W/a encl WEISSBERG.8. Office of State Programs 79/04/04 1p
- 7906130285 Lists preliminary thoughts on lessons learned from TMI-2 PALLADIND, N J. ACRS Advisory Committee on Reactor Safeguards 79/04/08 1p
- 7906130452 Forwards Questions & answers for hearing backup book to be grovided for chairman. W/ACRS concerns to TMI MIRAGLIA, F. J. Office of Nuclear Reactor Regulation 79/04/09
- 7906250058 Requests publication by 790412 of encl FR notice re ACRS Act Hoc Subcommittee 790423-24 meeting FRALEY, RF ACRS Advisory Committee on Reactor Safeguards 79704070 1p
- ---7906250066 Natification of 790423-24 meeting w/ACR6 Ad Hoc Subcomm 1 to an Angeles. CA to discuss TMI accident.

  CHILKIB J Office of the Sucretary of the Commission 79/04/10.
- 7906130451 Forwards highlights of 790405-07 228th ACRS meeting re TMI & other facilities CRUCKER, L. P. Division of Project Management 79/04/10 4pp

- 7906250071 Requests publication, by 790412, of enclifk notice re ACRS 790416-17 meeting FRALEY, R.F. Office of the Executive Director for Operations 79704/10 1p
- --7906250085 Notification of 790416-17 ACCRS meeting in Washington.DC to discuss TMI incident CHILK.S J. Office of the Secretary of the Commission 79/04/10 Spo
- 7904250127 Forwards FR notice of ACRS meetings on 790416-17 & 790423-24 meetings to discuss TMI incident

  \* ACRS Advisory Committee on Reactor Safeguards 79/04/11 3pp
- 7906180646 Submits draft trip rept of RF Fraley 790412 visit to TNI~2 Preliminary primary comiant analysis for 790411 sample & preliminary description of events at TMI encl FRALEV.RF ACRS - Advisory Committee on Reactor Safeguards 79/04/15 36pp
- 7906270001 Discusses ACRS recommendations contained in 790407,18 & 20 Itrs re TMI investigation
  HELTEMES.C J Standardization Branch 79/04/20 Bpp
- 7906130262 Confirms 790403 telcon re resource impact assessment in light of TMI incident Details FY79 immediate & followup effort & FY80 followup effort MCKINNEY, R E ACRS - Advisory Committee on Reactor Safeguards 79/04/26 ip
- 7906130270 Requests copy of normal shutdown procedures including going to natural circulation & chronology of events re THI incident MCCRELEGE, T © ACRS Advisory Committee on Reactor Safeguards 79/04/24 10
- 7906130274 Describes differences in BAW piping arrangements connecting pressurizer to hot leg Level piping may cause problem similar to that at TMI PLESSET.M S ACRS Advisory Committee on Reactor Safeguards 79/04/26 1p
- 7906130283 Notifies that repts by Industrial Advisory Group on Recovery Operations at TAI are available for ref MCCRELESS, T G ACRS — Advisory Committee on Reactor Safeguards 79/04/26 ip
- 7906180600 Forwards preliminary sequence of events at TMI for first 22-h of incident Describes distribution of Metropolitan Edison Go shutdown procedures MCCRELESS.T O ACRS Advisory Committee on Reactor Safeguards 79/04/26 ip
- --7706180608 Forwards preliminary sequence of events at TMI for first 22-h of incident Sequence reconstructed from available data sources LCNO,R L GPU Service Corp 79/04/16 15pp
- 7906130215 Forwards HPPSS presentation package, "TMI Incident & Its Impact on SPPSS Projects." MCKINLEV.J C ACRS - Advisory Committee on Reactor Safeguards 79/05/01 ip
- --7906130220 WPPSS presentation package, "TMI Incident & Its Impact on WPPSS Projects"

  COCKRELL, R G Washington Public Power Supply System 79/04/13
- 7906130254 Compares Chinese bomb test I-131 fallout in PA to that from TMI-2 Highest I-131 in milk from TMI-2 was 42 picocuries MULLER, R ACRS Advisory Committee on Reactor Safeguards 79/05/01
- 7906130199 Forwards PJ Persiani 790501 memo re TMI, presenting model for estimating fuel assembly damage LIPINSKI.W C Argonne National Laboratory 79/05/02 1p
- --7906130205 Summarizes views on sequence of events re fuel element behavior & consequent core conditions to be expected. Presents model of probable core demage Testimony encl PERGIANI, P J Argonne National Laboratory 79/05/01 4pp
- --7906130211 Testimony before Senate Subcommittee on Nuclear Regulation on 790430 re PA Public Util Commission actions following TMI incident.
  ODDE, W.W. Pennsylvania, State of. 79/04/30 23pp

- 7906180592 Highlight of Senate Subcommittee on Nuclear Regulation 790430 third hearing on TMI-2 Hitness list encl ALDERHAN.H ACRS - Advisory Committee on Reactor Safeguards 79/05/02 20pp
- 7906180617 Summary of 790501 meeting w/C-E in Bethesda.MD re effect of INI transients on C-E plants Vugraphs encl QUITTECHREIBER ACRS - Advisory Committee on Reactor Safeguards 79705702 15pp
- 7906180622 Forwards addl info items received during Ad Hoc Subcommittee on TMI Incident 790430-0501 meeting MAJOR:R K ACRS Advisory Committee on Reactor Safeguards 79/05/02 1p
- --7906180627 Summary of 790411-12 meeting w/C-E in Bethesda, MD re corrective actions for C-E NSSS plants as result of TMI incident ROSS, D F Division of Project Management 79/04/12 Spp
- --7906180631 Summary of 790418 meeting w/B&W in Bethesda.MD re natural circulation in 8&W reactors
  RGSS.D F Division of Project Management 79/04/24 13pp
- --7906180637 Summary of 790411 meeting w/Westinghouse in Bethesda. MD re short-term corrective actions for Westinghouse NSSS plants as result of TMI incident RUSS.DF Division of Project Management 79/04/12 App
- 7906260103 Forwards tentative schedule for continuation of 790430-0501 TMI-2 Accident Implications Subcommittee meeting on 790509 MAJOR.R K ACRS Advisory Committee on Reactor Safeguards 79/05/03 , 3pp
- 7906270084 Forwards final agenda for ACRS 229th meeting on 790510-12 CRDCKER.L P Division of Project Management 79/05/04 1p
- --7906270145 Final agenda for ACRS 229th meeting on 790310-12 \* Division of Project Management 79/05/02 4pp
- 7906130259 Forwards two NRC repts re ACRS activities related to TMI W/o enci VORESS, H E ACRS - Advisory Committee on Reactor Safaguards 79/05/07 lp
- 7906180006 Forwards presentation slides shown at NRC 790803 briefing re-personnel exposures Reading of 1.200 millirem/h reported 600 feet over site Adjacent island had 900 millirems MULLERR ACRS Advisory Committee on Reactor Safeguards 79705/07 18pp
- 7906180649 Forwards H Etherington's preliminary appraisal of TMI incident ETHERINOYON,H ACRS - Advisory Committee on Reactor Bafeguards 79/05/07 9pp
- 7906130266 Summary of 229th ACRS meeting on 790509 re TMI-2 MAJOR.R.K ACRS - Advisory Committee on Reactor Safeguards 79/05/09 2pp
- 7906220096 Forwards notice of meeting for publication in FR by 790516 CHILK.B J Office of the Secretary of the Commission 79/05/10 ip
- ~~7906220103 Notification of 790331~0601 meeting w/ACRE in Washington, DC to discuss implications of TMI MOYLE, J C ACRS ~ Advisory Committee on Reactor Bafeguards 79703710 2pp
- 7905220322 Lists proposed assignments & priorities re implications of THI incident

  \* ACRS Advisory Committee on Reactor Safeguards 79/05/10 23pp.
- 7906220329 Summarizes recommendations & comments of ACRS subcommittee re long-term effects of TMI (ncident, as presented by Okrant on 790510
- # ACRS Advisory Committee on Reactor Safeguards 79/05/10 2pp
- 7906270044 Discusses 790514 meeting w/D Major of ACRS re review of B&N operating plants
  HELTEMES C J Standardization Branch 79/05/14 [p
- 7905220165 Summary of 790510 masting w/Ofc of Executive Director for Operations & Director of NRC Program Ofcs re TMI-2 activities BATES, A. ACRS Advisory Committee on Reactor Safeguards 79/05/13 26se.

- --7906220174 Indicates that R Pollard will not attend 229th ACRS meeting, but will respond to 790427 ltr. FRALEY.R F ACRS Advisory Committee on Reactor Safeguards 77/09/15
- 7906050070 Interim Rept 3 on TMI-2 submits recommendations re reactor pressure vessel level indication, operator training. LER evaluation, operating procedures & eletric power supply CARBON. M W ACRB Advisory Committee on Reactor Safeguards 79/03/16 6pp
- 7906070136 Interim Rept 2 on TMI supplements response to V Gilinsky 790418 request re natural circulation procedures, pressurizer heaters, saturation conditions 5 core exit thermocouples CARBON. H W ACR8 Advisory Committee on Reactor Safeguards 79/05/16 4pp
- 7906270070 Forwards summary of ACRS 227th meeting on 790510-12 re TMI THOMAS.C Q Light Water Reactors Branch 1 79/05/16 2pp
- --7906270104 Bummary of ACRS 227th masting on 790510-12 rs implications of THI accident

  \* Light Water Reactors Branch 1 79/05/12 4pp
- 7906070053 Requests comments re ACRS 790407.18 \$ 20 ltrs containing recommendations on TMI incident Response requested by 790528
  - ROSB.D F Division of Project Management 79/05/17 3pp
- 7906070055 Requests comments ACR8 790407-18 b 20 ltrs containing recommendations on TMI incident Response requested by 790523
- Division of Project Management 79/05/17 3pp 7905070036 Requests comments re ACRS 790407.18 & 20 ltrs containing recommendations on TMI-2 incident Response requested by 790923
- Division of Project Management 79/05/17 3pp ROSS, D F
- 7906070061 Requests comments re ACRS 790407.18 \$ 20 itrs containing recommendations on TMI-2 incident Response requested by 790523. 8058 D F Division of Project Management 79/05/17 3pp
- 7905130197 Summary of NRC 790517 meeting re-preliminary chronology of THI event Chronology encl TAM: P ACRS Advisory Committee on Reactor Bafeguards 79/05/17
- 790A180702 Notice of ACR8 790606-07 meeting in Middletown, PA to discuss technical details of TMI incident HOYLE, J C ACR8 Advisory Committee on Reactor Bafeguards 79703717 3pp

4900

- 7906270022 Discusses Michelson 790510 & 11 comments at ACRS meeting re break analysis & transient sequences HELTEMES.C J Brandardization Branch 79/05/17 13pp
- 7905200029 Summary of AGRS 790510~12 meeting re circumstances relating to accident at TMI CARBUN.M.W ACRB Advisory Committee on Reactor Safeguards 79708/16 4pp.
- --7906200035 Summary of ACRS 790510-12 meeting re review of accident at CARBON, M W Office of Public Affairs 79/05/16 6pp
- ---7906200050 ACRS recommendation that NRC consider establishing quantitative safety goals for overall safety of nuclear reactors, Congress & public should comment on pian CARBON. M W Office of Public Affairs 79/05/16 lp.
- 7906070062 Requests comment re ACRS 790407.18 & 20 itrs containing recommendations on TMI-2 incident Response requested by 790529
  - RDBB.D F Division of Project Management 79/05/22 3pp
- 770611001B Requests comment by 770529 on encl add1 ACRS 770516 recommendations re fMI-2 incident ROSS, D. F. Division of Project Management 77/05/23 13pp
- 7906110025 Requests comment by 790527 on encl add1 ACRS 790516 recommendations re TMI-2 incident ROSB, D. F Division of Project Management 79/05/23 13pp
- 7906110028 Requests comment by 790829 on encl add1 ACRS 790816
  recommendations re TMI-2 incident.
  ROBB.D.F Division of Project Management 79/05/23 13pp

- 7906110035 Requests comment by 790529 on encl addl ACRS 790516 recommendations re TMI-2 incident RDSS.D F Division of Project Management 79/05/23 13pp
- 7906110032 Requests comment by 790527 on encl add1 ACRS 790516 recommendations or Thi-2 incident ROSS D F Division of Project Management 79/05/23 App
- P Operating license stage documents & correspondence
- 7906290176 Revised unesecuted draft of notice of incident on 790328 CHILK: 5 J Office of the Secretary of the Commission 79/03/28
- 7906130441 Incident mgt ctr morning rept for 790329 Info includes dose rates
  MARTIN, J Division of Site Safety & Environmental Analysis
  79/03/29 14pp
- 7906250316 Submits IE mgt ctr morning rept at 6 30 AM Discusses radioactivity distribution Info partially withheld home telephone numbers (ref FOIA Exemption 6) MARTIN, J Division of Site Safety & Environmental Analysis 79/03/29 16pp
- 7906260488 Requests status rept Forwards questions re design similarities to TMI AMEARNE, J F Commission 79/03/29 2pp
- 7906200462 Forwards compilation of TMI-2 sequence of events, background info & history CREMB.J L Region 5. San Francisco. Reactor Operations Nuclear Support Branch 77703/31 10pp
- 7906210103 Notifies of NRC request that mobile Rawinsonde be deployed to Harrisburg airport as soon as possible BARNEY,W S Commerce.Dept of National Oceanographic & Atmospheric Adminstration 79/03/31 ip
- 7906210104 Requests one mobile Rawinsonde station w/expendables for six days at six runs per day be alerted for movement to notice Harrisburg airport BARNEY/H S Commerce.Dept of.National Oceanographic & Atmospheric Adminstration 79/03/31 ip
- 7906060242 Summary of 790401 meeting w/General Public Utils & others re status of TMI-2 incident Info partially withheld home telephone numbers (ref FOIA Exemption 6) \* Office of Nuclear Reactor Regulation 79/04/01 7pp
- 7906130496 Forwards summary info re calculations of THI gas bubble BERGER, D. W. Babcock & Wilcox Co 79/04/02 9pp
- 7906200097 Notifies that tesk group has been established to evaluate generic implications of feedwater transients in B&W-designed reactors
  DAVIS: D K Systematic Evaluation Programs Branch (Pre 790625)
  79/04/02 ip
- 7906200430 Lists iodine & carbon levels of milk samples GROVE-W R Health, Education & Welfare. Dept of 79/04,G2 14pp
- 7906210127 Forwards description of IE enforcement actions re B&W reactors other than TMI Inspectors must assure that licensees fulfill NRG bulletin provisions DAVIB.J 0 Office of Inspection & Enforcement 79/04/02 2ep
- 7906270010 Forwards draft reply to J Califano 790401 memo re registry of workers at TMI DAVIB.J G Office of the Executive Director for Operations 79/04/02 2pp
- 7906130357 Provides info on sample results from weste storage tanks WENSLANSKI.F Region 5, San Francisco, Office of the Director 79/04/03, ip
- 7906:304:5 Forwards recommendations sent by Westinghouse to owners of Westinghouse PWRs in light of TMI incident THORNBURG.H D Office of Inspection & Enforcement 79/04/03 6pp
- 7906i304i7 Notifies that Susquehanna River sample collected 790402 has been reanalyzed & previously reported value could not be confirmed 1-13i not present in river at that time MARTIN.A Health, Education & Welfare, Dept of 79/04/03 is

- 7906130486 Analysis of Busquehanna River water samples for I-131 on 790402 No I-131 found MARTIN.A Health, Education & Welfare, Dept of 79/04/03 1p
- 7906130491 Forwards status of operating plants
  BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear
  Bupport Branch 79/04/03 2pp
- 7906130492 Data re background levels of Sr & Cs in milk for Philadelphia & Pittsburgh REGNIER, J Environmental Protection Agency 79/04/03 1p
- 7906210207 Provides info re man-rem exposure from THI-2 incident Lists add1 data required to complete analysis Draft request for data encl QUSBICK.L V Office of the Executive Director for Operations 79/04/03 5pp
- 7906130438 Provides guidance re procurement support for TMI COBB.L. I. Office of I&E. Executive Officer for Management & Analysis 79/04/04 2pp
- 7906210135 Forwards recent FBI communication to be disseminated to direct NRC employees only W/o enc)
  BRADY,R J. Office of Administration 79/04/04 1p
- 7906:130423 Notifies that bulietins are being sent to all licensees of nuclear power plants incorporating steam supply sys designs identical to that of TMI facility HENDRIE, J M Commission 79/04/05 2pp
- 790&130457 Provides rough estimate of source term from all data collected to date
  LEE.J. Division of Site Safety & Environmental Analysis 79/04/05
- 7906210124 Discusses logistical support for personnel assigned to TMI-2 site.
  GDSSICK.L V. Office of the Executive Director for Operations
  79/04/03 Ip
- 7906260069 Discusses questions re Nucleonics Week 790405 article, "Persistent NRC Inspector Had Already Raised TMI-Related Gafety Issues "Answers needed for Hart subcommittee # Office of Inspection & Enforcement RC 79/04/05 2pp
- 7906070030 Forwards 790328-0406 notes re handling of TM1 accident Info partially withheld home telephone number (ref FOIA Exemption 6) # Office of Nuclear Reactor Regulation 79/04/06 57pp
- 7906130301 Forwards data re operation of reactor coolant pump motors at reduced speed, which is applicable to TMI TAYLOR, J H Babcock & Wilcox Co. 79/04/06 3pp
- 7906130362 Requests radiation monitor recorder charts to establish time sequence for escape of radiation
  KIRKPATRICK, D Office of Inspection & Enforcement 79/04/06 Spp
- 7906190427 Requests arrangements to airlift four safety filters from State of HA to Harrisburg.PA airport & then truck filters to THI HEONER, J Office of Inspection & Enforcement. 79/04/06 1p
- 7906210186 Lists weekend schedule for manning operations ctr THOMPSON,D Office of I & E Executive Officer for Operations Support. 79/04/06. 1p.
- 7906210420 Second round of util interviews re TMI incident, \* Metropolitan Edison Co 79/04/06 108pp
- 7906220033 Discusses use & specs of hydrogen high pressure storage tanks & hydrogen Corblin compressors requested by NRC for TMI-2 Matl available for immediate delivery.

  HCCLURE, L L Consumer Fuels: Inc 79/04/06 ip
- 7906210188 Discusses NRC request to airlift filters from state of WA to TML-2, 41te.
  OD881CK.L.V. Office of the Executive Director for Operations, 79704/07. 1p.
- 7906250097 Forwards info re notification sys for TMI incident. HUFHAM.J.W Region 2: Atlanta: Office of the Director 79/04/07 3pp
- 7906070007 Provides procedures to assure coordination of natl lab support for NRC activities at THT-2, per 790407 discussions. Forwards H Bixby's log of active & completed lab inputs. HATTBON, R. J. Division of Systems Safety 79704/08. ip.

- 7906130489 Summary of 790407 site visit to obtain better understanding of situation, overall response to event, onsite capabilities & activities BNIEZEK, J H Division of Fuel Facility & Materials Safety 79/04/08 2pp
- 7906210174 Confirms request to transfer radioactive samples from TMI-2 to Oak Ridge.TN & Aiken.BC 90SBICK.L V Office of the Executive Director for Operations 79/04/08 Ip
- 7906130455 Responds to 8 Conver telcon request for info re Region III initial notification of licensees & govt officials re TMI incident KEPPLER.J G Region 3, Chicago, Office of the Director 79/04/09
- 79061304B1 Requests comments on review of action items from 79040B technical mgt meeting STELLO,V Division of Operating Reactors 79/04/09 26pp
- 7906270014 Discusses manning of NRC operations ctr during controlled preparation for natural convection cooling DAVIS.J O Office of Inspection & Enforcement 79/04/10 Ip
- 7906210029 Provides info re activities while at TMI-2 for 790331-0409 Critical of NRC intra agency conflicts & util indocisiveness on corporate personnel level SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/11
- 7706210191 Confirms request to locate & arrange for railway cars to store low level waste from TMI-2 OOSBICK,L V Office of the Executive Director for Operations 79/04/11 ip
- 7904270001 Recommends that all Boards be provided info contained in DB Vassallo 790403 & 0409 memos re TMI incident. STELLO.V Division of Operating Reactors 79/04/12 ip
- 7904270234 Forwards Bethesda.MD duty roster for TMI.to support site operations coverage for Easter weekend CASE.E G Office of Nuclear Reactor Regulation 79/04/12, 2pp.
- 7906070054 Forwards handwritten notes re boron concentration at TMI-2for 790331-0412 Info partially withheld home telephone
  numbers (ref FOIA Exemption 4)
  \* Office of Nuclear Reactor Regulation 79/04/12, 14pp
- 7906200413 Tabulates NRC personnel exposures at TMI to 790411 Info partially withheld names of individuals (ref FOIA Exemption 6).
  SLOBODIEN, M J Region i. Philadelphia, Office of the Director 79/04/12. 1p.
- 7906210265 Forwards chart of tasks performed by Div of Technical Info & Document Control, in response to TMI incident.

  BEBAW.W.J Technical Information & Document Control 79/04/12
- 7906210267 Responds to 790305 request for info re emergency preparedness NRC engaged in study of products containing radioactive matis. SCHHARTIS A Assistant Director for Program Development. 79/04/12 2pp
- 7904270044 Forwards info on TMI incident followup actions by NRC, in response to 790412 memo MILLER.H D License Fee Hanagement Branch. 79/04/13. 3pp
- 7906070234 Confirms NRC request to transport radioactive sample by sir to Idaho Fails, Idaho from TMI Info partially withheld contractor contact home phone number(ref FOIA Examption 6) OBSE(KL, V Office of the Ejecutive Director for Operations 79/04/13. 1p.
- 7706130342 Provides alternatives to duplicating master recording tapes of TMI incident.
  WEISS, B M Office of Inspection & Enforcement. 79/04/13, 2pp
- 7906210269 Expresses gratitude to Univ for meteorological data provided during TMI incident FAIROBENT, J E. Hydrology Meteorology Branch, 79/04/13 2pp
- 7906250100 Forwards rept on penetration availability using instrument outside containment.

  HERACLIA.F. J. Assistant Director for Engineers & Projects (Pre 790625). 79/04/13. App.

- 7905250107 Forwards analytical results for primary coalant, including Bettie enalysis, for 790329 to 0410 MIRAGLIAF J Assistant Director for Engineers & Projects (Pre 790625) 79/04/13 2pp
- 7908260469 Discusses mechanical condition of TMI core Rob ballooning leading to rupture expected in highest power areas of many or all fuel robs
  MARRIOTT.P W Industry Advisory Group 79/04/13 8pg
- 7906070016 Comments on existing situation re FDIA TMI requests recommends NRC response to requests Info partially withheld lentactive recommendations (ref FDIA Exemption 5) BICKWITIL Office of the General Counsel 79/04/14 7pp
- 7904220226 Forwards JQ Herbein 790411 ltr & RJ Mattson 790411 memore criteria for use of steam generator for short-term & intg-term cooldown MIRAGLIAn FJ Assistant Director for Engineers & Projects (Pre 790625) 79/04/14 ip
- /906070006 Bubmits NRC personnel exposures at TMI.to 790413 Info partially withheld identification of individuals (ref FOIA Exemption 6) SLOBODIEN.M J Office of Inspection 5 Enforcement 79/04/16 ip
- 7996130495 Bampling summory for "Operation Ivory Purpose" for 7904(1,12 & 16 = Environmental Protection Agency 79/04/16 7pp
- /906200408 Tabulates NRC personnel exposures at TMI to 790415
  Info partially withheld names of individuals (ref FUIA
  Exemption 6)
  GLOBODIEN,M J Region 1, Philadelphia, Office of the Director
  79704/16 to
- 7904200445 Describes personnel understanding of role of Ofc of Mgt & Program Analysis in organizing TM1 documents
  GONVER.S: Office of Management and Program Analysis 79/04/16 ip
- 7904260513 Forwards article re TMI incident, received from F Von Hippel on 790412 H/b encl
  EISENHUT, D O Assistant Director for Equations Engineering 79/04/17
- 7904270331 Forwards summary of 790417 planning meeting MIRAOLIA.F J Office of Nuclear Reactor Regulation 79/04/17 15pp
- 7906060228 Forwards list of remaining Special Instrumentation Ordup tasks Info partially withheld home telephone numbers (ref FOIA Exemption 6) ACKERMANNIN J Becial Instrument Ordup 79/04/17 2pp
- 7905210276 Forwards FR notice re change of meeting of ACRS Ad Hoc subcommittee on THI \* ACRS - Advisory Committee on Reactor Safeguards 79/04/17 200
- --7906210279 Notice of meeting of 790423-24 meeting of ACRS Ad Hoc Bubcommittee on TM1 in Los Angeles, CA CHILK. B J Office of the Secretary of the Commission 79/04/13
- 7905130485 Forwards revised 790410 work schedule for Incident Response Ctr
  MOBELEY,N C Division of Reactor Operations Inspections 79/04/18
  500.
- 7906200392 Provides info re activities while at TMI-2, for 79030-0406 Environ survey team limited by lack of proper equipment ANDREWS, D L. Region 2, Atlanta, Puel Facility & Materials Safety Branch 79/04/18 2pp
- 7906200402 Provides info re activities while at TMI-2.for 790330-0409. Licenses control of raduaste was effective for liquids JACKSGIN, L. L. Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/04/18 2pp
- 7908200448 Forwards environ monitoring notes re TMI-2 event MERR: W Office of State Programs 79/04/18. 20pp
- 7906200483 Submits outline notes for TMI-2 indine rept KERR, W C. Office of State Programs 79/04/18 3pp
- 7906210026 Provides into re activities while at TMI-2, for 790390-0413 Not involved w/licenses or in-glant operations WOODRUFF, R L Region 2, Atlanta, Fuel Facility & Materials Safety Branch, 79704/18, 2pp.

- 7906210077 Responds to request for summary of experiences at Incident Response Ctr after THI-2 incident Forwards selected conversations from 790330 telephone tapes
  BASSETT.H S Office of Management and Program Analysis 79/04/18
  7pp
- 7906210100 Forwards informal notes to TMI incident, including milk monitoring data LUBENAU.J 0 Office of State Programs 79/04/18 94pp
- 7906210208 Discusses discharge water sample analysis procedures for 1-131 PORT. B Porter-Oerti Consultants, Inc. 79/04/10 ip
- 7904210270 Forwards FR notice re corrected schedules of ACRS meetings
   Office of Nuclear Reactor Regulation 79/04/18 2pp
- --7906210272 Notice of proposed meetings of ACRS
  CHILKS J Office of the Secretary of the Commission 79/04/17
  Son
- 7905040321 Forwards info requested by O Chipman re dose rate at top of containment
  MIRAGLIA.F J Technical & Administrative Support Branch
  79704/19 2pp
- 790606019; Forwards four labs' results of toron measurement of 790411 primary sys sample (non-pressurized) info partially withheld home telephone numbers (ref FDIA Exemption 6) TELPORD, J 7 Division of Operating Reactors 79/04/19 3pp
- 7906070004 Forwards status of natl labs work requests made since 79040 Info partially withheld home telephone numbers of contractor contacts (ref FOIA Exemption 6) LANNING,W D Division of Reactor Safety Research 79/04/19
- 7906200421 Provides info re activities while at TMI-2, for 790330-0406 Region II response to crisis was excellent critical of Ctr for Disease Control & NIOSH personnel exceeding HEM mandate GIBSON, O.T Region 2. Atlanta, Office of the Director 79/04/19 200
- 7906210016 Provides info re activities while at TML-2.for 790329-0411 Util radwaste operations very good under circumstances Commends liquid radwaste supervisor ZAYADOSKIR W Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/04/19 2pp
- 7906210114 Forwards list of background mat1 for President's Commission on TKI GORNELL,E K Office of the Executive Director for Operations 79/04/19 2pp
- 7905040311 Discusses White House memo & dual roles assigned to NRC & EPA in monitoring long-term radiation at TKI-2 SHAPAR,H K Office of the Executive Legal Director 79/04/20 3pp
- 7906200388 Provides info re activities while at TMI-2.for 790330-0412 Observed licensee resentment towards NRC doubts NRC ability to make snap decisions during fast moving events HINCMLEV.D O Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/20 1p
- 7906200426 Provides info re activities while at TMI-2, for 790403-17 Duties included monitoring of plant status & operator actions BETTENHAUSEN, L. Region 1, Philadelphia, Office of the Director 79/04/20 ip
- 7906200434 Provides info re activities while at TMI-2.for 790330-0412 All NRC personnel were dedicated & prof WESSMAN.R # Region 2. Atlanta, Office of the Director 79/04/20 to
- 7906210067 Summary of 790412 mreting w/PA Health Dept in Harrisburg, PA to discuss strategy for evaluation of TKL-2 health impact COLDBMITH, R Radiological Health Standards Branch 79/04/20
- 7906210075 Bubmits record of actions re TMI-2 event Wisummary of operations ctr audio tape for 790410 & preliminary chronology CONVER, 8, Office of Management and Program Analysis 79/04/20
- 7906210113 Ack receipt of NRC bulletins re TMI incident Priority info needed to alert Italian public of possible consequences & impact on nuclear power in Italy ZAFFIRO,C Italy 79/04/20 ip.

- 7906210232 Provides summary of activities while at TMI-2 for 790404-16 Operations at site were well organized & coordinated FRIEDMAN. L Region 1. Philadelphia. Office of the Director 79704/20 ip
- 7906290399 Provides summary of activities while assigned to TMI-2 site BISSETT-P H Region 1, Philadelphia, Office of the Director 79/04/20  $\,$  1p
- 790622008B Forwards handbooks of govt acronyms which may be useful in efforts w/Presidential Investigating Committee W/o enci SAVOLAINEN, A W Technical Information & Document Control 2006
- 7905040336 Provides cost for reproduction of TMI-2 FSAR Lists
  recipients who requested copies since incident
  BEBAH, N J Fechnical Information & Document Control 79/04/24
- 7905040435 Forwards calculated dose rate from condensate polisher demineralizers
  MIRACLIA:F J Technical & Administrative Support Branch
  79/04/24 2pp
- 7905070029 Forwards requested updated primary conlant sample analyses MIRAGLIA.F J Technical & Administrative Support Branch 79/04/24 4pp
- 7906070037 Forwards C Stoiber draft testimony for President's Commission on TMI Requests comments info partially withheld draft testimony (ref FOIA Exemption 5) BICKHIT.L. Office of the General Counsel 79/04/24 tp
- 7906220067 Responds to 790405 & 11 Itrs to JM Hendrie Investigation of TMI is in initial stages Response to editorials must await outcome of review INGRAM: F. Office of Public Affairs 79/04/24 lp
- --790A220069 Forwards CBS editorial re nuclear power in CA Invites NRC to prapare reply statement for broadcast MARGALITH.J CBS News, CBS. Inc 79/04/11 4pp
- ~-7906220079 Forwards CBS news editorial re nuclear power plants in CA Invites NRC to prepare reply statement for broadcast MARQALITH,J CBS News, CBS, Inc. 79/04/05 4pg
- ~7906220083 Forwards CBS news editorial re economics of nuclear power Invites NRC to grapare replay statement for broadcast MARGALITH.J CBS News. CBS. Inc. 79/04/13 4pp
- 7906260058 Requests personnel engaged in THI to Log 790328-0401 actions, if already logged in incident response ctr DENTON.H R. Office of Nuclear Reactor Regulation 79/04/24 ip
- 7906290022 Describes major drawbacks to locating sampling sinks for both units in same room Unit 2 sink must be moved & all existing lames flushed before Unit 1 can be exponented

- 790507008B Comments on discussions w/S Benjamin of AP & Atty General of NY re clarification of 790413 core damage assessment & basic tutorial info on fission products
  MEYER.R O Core Performance Branch 79/04/26 ip
- 7906020168 Summarizes 790420 visit to BNL to discuss progress on BSS-FY79 reactor physics technical assistance program Forwards results of study of boron calculations DUNEFELD:M Division of Bystems Safety 79/04/26 5pp
- 7906200428 Provides info re activities while at TMI-2, for 790330-0411 Critical of duplication of affort between IE & Ofc of Nuclear Reator Regulation
  DYER, J A Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 2pp
- 7906210006 Provides info re activities while at TMI-2, for 790330-0418 Raises questions re reliability of licenses health physics operations TROUP, C.L. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 3pp
- 7906210009 Provides info re activities while at TMI-2.for 790330-0413 Critical of poor communications between util employee & NRC in-plant health physics inspectors PERROTTIO J Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- 7906210021 Provides info re activities while at TMI-2.for 790330-0413 Contact w/licensee was minimal YOUNG.H H Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- 7906280130 Notifies of reduction of routine changeout frequency of Eberline HPR-219 from once every 4-h to once every 24-h, effective midnight on 790426 PORTER.S Parter-Gentz Consultants, Inc 79/04/26 1p
- 7906290025 Forwards suppl to 790423 memo establishing task force for natural circulation initiation New members are added to task force ARNOLD, R C Hetropolitan Edison Co 79/04/26 ip
- 7906290226 Discusses decontamination work inside plant Was cautioned by Waste Management Group not to use inorganic solvents because of possible impact to activated charcoal filters COBEAN.W R Metropolitan Edison Co 79/04/26 ip
- 7906290321 Discusses interim procedure for notifying states of planned shipments of radwaste from TMI KERR, Q W Assistant Director for State Agreements Programs 79/04/26 Ip
- 7906130390 Forwards personal records re TMI Info includes 790329 morning rept.calculations of man-rems & beta dose rate at surface of equipment in contact w/primary cobling water MARTIN.J A Accident Analysis Branch 79/04/27 38pp
- 7906130394 Provides personal log of communications re TMI as requested in HR Denton 790424 memo COFFMAN.F D Division of Operating Reactors 79/04/27 ip
- 79062100B1 Responds to 790416 memo Notifies that only NRC actions performed for TMI-2 event were LER file searches
  KIRK, I. A. Office of Management and Program Analysis 79/04/27 ip
- 7906210223 Provides summary of activities while at TMI-2.for 790427-0504 Contact w/licensee was minimal HOLOBY.D J Office of Inspection & Enforcement 79/04/27 Ip
  - 'O6250110 Discusses President's Commission on TMI & Rept to President by Interagency Review Group on Nuclear Waste Mgt, Mar 1979 Requests info from Manitoba Bar LAPLEUR, J.D Office of International Programs 79/04/27 2pp
  - 7906250116 Request by Manitoba Bar Association for terms of ref for President's Commission & Rept to President by Intergency Review Group on Nuclear Waste Mgt. Mar 1979 BEROH. B G Canada 79/04/12 1p
  - 06260474 Bubmits items of possible concern for inclusion in orders to 84W plant licensees Forwards 780330 PNO re reactor trip & subsequent blowdown at TMI-2 AHEARNE. J F Commission 79/04/27 ip
  - 7906260478 PNO 780329 reactor trip & subsequent blowdown w/emergency sys actuation Caused by lose of vital bus Power eventually restored to bus STERNBERT.D M Region 2. Atlanta. Office of the Director. 78/03/30. 1p

- 7906280125 Submits parallel waste processing strategy as part of recovery plan XRAFT, S Gilbert Associates, Inc. 79/04/27 10pp
- 7906290301 Comments on proposed specs provided on 790423 Aithough specs are directed to current plant status, comments are directed for use in long-term cooling mode
  SCINTO, J F Hearings Division 79/04/27 10pp
- 7906290307 Discusses analysis of charcoal from TMI-2 auxiliary bldg filters Indication of transuranics detected Addl counting will resolve questions re isotopes present VOLLMER.R H Assistant Director for Systems Engineering 79/04/27
- 7906280123 Recommends that Metropolitan Edison Co continue to ship radwaste to State of WA Bill before state legislature prohibiting shipments will probably not pass COLING.J T Effluent Treatment Systems Branch 79/04/28 ip
- 790606024: Forwards updated lists of NRC personnel who require access to TMT site Info partially withheld Social Security numbers (ref FOIA Exemption 6) SMITH, 6 H, MCOSCAR, J J Office of Inspection & Enforcement 79/04/29 Spp
- 7906070049 Forwards notes on TMI-related telcons for 790328-0429 Info partially withheld home telephone numbers (ref FOIA Elemption 6) YOUNOF Office of State Programs 79/04/29 Spp
- 7906290051 Forwards analysis of charcoal from auxiliary bldg filters as followup to R Vollmes 790427 memo COLLING, J T Effluent Treatment Systems Branch 79/04/29 ip
- 7905290296 Discusses reanalysis of charcoal adsorbers from TMI Charcoal contaminated W/Pu-239 possibly as result of Chinese bamb tests Presence of Cr-51 confirmed COLLINS, J Y Effluent Treatment Systems Branch 79/04/29 1p
- 7906200073 Forwards notes prepared in conjunction w/early TMI actions
  Info includes notes on emergency procedures Info partially
  withheld home telephone numbers (ref FOIA Examption 6)
  IEDESCO.R L Assistant Director for Reactor Safety 79/04/30
  4669
- 7906200454 Provides info re activities while at TMI-2, for 790405-19 Critical of problems in communication & long delay in obtaining analyses of samples EMALD, S C Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/30 2pp
- 7906200494 Discusses restrictions on use of masks w/matl surveillance assembly 88182 cartridges during decontamination of auxiliary 15et bldg SMITH-0 H Office of Inspection & Enforcement 79/04/30 ip
- 7906210071 Discusses staff response to 790413 LV Gossick memo re TMI-2 incident record of actions Memos have been prepared & will be forwarded MALLER,N Office of Management and Program Analysis 79/04/30 1p
- 7904220124 Forwards analysis of licensee dosimetry data for 790401-30 Total man-rem for period was 131 7 SLOBODIEN,H J Region 1, Philadelphia, Office of the Director 79/04/30 1p
- 7906220207 Forwards calibr procedures & setpoints re TMI-2 alternate vent radiation monitors i-8 PORTER,S W Porter-Gerti Consultants. Inc. 79/04/30 Spp
- 7906260260 Submits EPA environ data from 790423-29 BDRES.R Region 1, Philadelphia, Office of the Director 79/04/30, 1p
- 7906280143 "Coating Test Rept"
  KOVACH,8 L Nuclear Consulting Services, Inc NUCON 61C616/01
  79/04/30 5pp
- 7906280242 Agendas & notes taken during various meetings on 790430 to discuss plant status

  \* Office of Nuclear Reactor Regulation 79/04/30 5pp
- 7906130392 Forwards personal records of TMI activities, as requested in HR Benton 790424 memo.
  READ: J Division of Bite Safety & Environmental Analysis
  79705/01 3ipp.

- 790620045B Provides info re activities while at ICII-2, for 790412-24 Critical of util health physics operations KAHLE.J B Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/05/01 3pp
- 7906220229 Forwards news releases re TMI b shutdown of five plants [nfore TMI was made available to press at press ctr in Middletown PA ti/o encl MILEG.C Office of Public Affairs 79/05/01 1p
- --7906220232 Requests list of news releases to TMT incident & shutdown of five power plants Forwards copy of article intended for Manchester Union Leader re TMT & nuclear accidents OILMAN.L Affiliation Unknown 79/04/18 App
- 7906260327 Recommends changes in TMI-2 operating point WILGON, R F GPU Service Corp 79/05/01 2pp
- 7906270141 Forwards info re 790328 exposures of personnel investigating leakage of radwaste info partially withheld names, social security numbers, birthdates (ref FOIA Exemption 6) HERBEIN.J O Metropolitan Edison Co 79705/01 Spp
- 7906280173 Forwards "Plant Mods for Achieving Cold Shutdown, May 1979 "
  prepared by Technical Review Group, as app to safety
  evaluation
  NOVAK, T M Office of Nuclear Reactor Regulation 79/05/01 ip
- --7906280176 "Plant Mods for Achieving Cold Shutdown May, 1979" prepared by Technical Review Group \* Office of Nuclear Reactor Regulation 79/05/31 66pp
- 7906290320 Discusses TMI-2 "Criteria for Loss of Offsite Balance of Plant Electrical Power, Revision 1"
  CRONEDEROGE, D K 0PU Service Corp 79/05/01 Spp
- 7906050067 Discusses adequacy of station electric distribution sys voltages in light of NRC 770602 generic ltr & 780916 event at AR Nuclear One Requests plant electric sys review VAGSALLO,D D Assistant Director for Light Water Reactors 79/05/02 Bpp
- 7906200037 Summarizes info obtained from BEW re TMI incident, in response to HR Denton 790424 memo Info partially withheld home telephone number (ref FOIA Exemption 6) CHERNY-F C Hechanical Engineering Branth 79/05/02
- 7906200390 Provides info re activities while at TMI-2, for 790412-24 Meakness exists in area of sample coordination ALLEN,J R Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/05/02 2pp
- 7906200473 Provides info re TMI-2 activities on 790413 \$ 25,per Region I Announcement 79/20 Licensee making effort to apply GA \$ GC to ongoing mods TRIPP, LE Region I, Philadelphia, Reactor Construction \$ Engineering Support Branch 79/05/02 2pp
- 7906210203 Provides summary of activities while at TMI-2, for 790420-28 Contact w/licenses was minimal BHAUB,E T Office of Inspection & Enforcement 79/05/02 3pp
- 7906210219 Provides summary of activities while at T O410 Critical of breakdown in administrative proce health physics during initial phase of incident NIMITZ, L. Region i, Philadelphia, Office of t 79/05/02 3pp
- 7906260327 Revises RF Wilson 790501 recommendations a operating point KEATEN, RW QPU Service Corp. 79/05/02 ip
- 7706270035 Describes organization of dept to impleme in response to TMI # Office of Inspection & Enforcement. 79/05/02
- 7906290413 Forwards info re calibr procedures & setp alternate vent radiation monitors Data is to be co hourly Paint source calibr complete PORTER, B W Metropolitan Edison Co 79/05/02 &
- --7906290423 Discusses TMI-2 Effluent Monitors 1,2,0 PORTER,S W Porter-Gertz Consultants, Inc. 79/
- ---7906290428 Discusses setpoints for Victoreen 5 mor duct) Forwards setpoints SLABACK, L A Metropolitan Edison Co 79/05/01.

- 7906200393 Provides info re activities while at TMI-2, for 790412-27 Procedures & calculations should be eramined before using sample results for health physics activities BROWN, R. Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/05/03 ip
- 7906210024 Ack receipt of EPA 790502 ltr re submission to EPA of NRC environ data rhrough 790415 Info requested is delayed until 790525 due to heavy workload SMITH.O H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/05/03 ip
- --7906210028 Requests info re monitoring activities in support of TMI, in areas of air, milk, water, dosinmetry, whole body or thyroid counting & soil & vegatation samples BRETTHAUER.E Environmental Protection Agency 79/05/02 ip
- 7906210143 Describes required periodic instrument readings & transmission of readings SYREETER.J Region 1. Philadelphia. Office of the Director 79/05/03 2pp
- 7906210277 Accepts position of investigator for Region II.as offered in 790411 ltr MARSH.R J Region 3. Chicago, Office of the Director 79/05/03 io
- 7906220212 Forwards JM Hendrie & DG Eisenhut 790410 testimony before Senate Nuclear Regulation Subcommittee & General Public Util's 790416 memo re sequence of events W/o encl GGRNELLE K Office of the Executive Director for Operations 79/05/03 | 2pp
- ~~7906220217 Forwards NRC testimony & transcript of ACRS hearing on Contention B Also forwards 790430 ltr to TH Pigford listing records on TMI & J9 Davis 790420 memo W/o encl CORNELL, E K Office of the Executive Director for Operations 79/05/04 | 1p
- --7906220221 Notification of NRC 790503 meeting in Washington, DC to discuss plans for TMI investigation Forwards general counsel 790414 draft policy statement W/o encl CRNELL, E. K. Office of the Executive Director for Operations FITZGERALD, J. Office of the General Counsel 79/05/03 lp
- 7906280182 Forwards "Transition to Natural Circulation at THI-2 " Rept is intended to document discussions on natural circulation KULYNCH.O E Batcot & Wilcor Co 79705/03 19pp
- 7905290014 Summary of 790902 meeting w/Waste Mgt Group & NRC re charcoal filter tray storage plan MGCONNELL.J F Metropolitan Edison Co 79/05/03 2pp
- 7906290106 Submits chart illustrating allowable operating envelope for reactor vessel NDT limits NEHTON,0 G Office of Inspection \$ Enforcement 79/05/03 ip
  - resents primary coolant analysis results from ORNL sample 790411 Pu content is 0 29 parts per billion > is 110 parts per billion T Effluent Treatment Bystems Branch 79/05/03 ip
  - orwards calculations by Butler Milstead & Shapaker. b or 790328-0415 Containment Systems Branch (fre 790101) 79/05/04
- 7906210226 Provides summary of activities while at TMI-2, for 790329-0405 & 0416-0501 Critical of confusion surrounding approval of emergency & operating procedures JOHNBON, J.R. Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/04 3pp
- 7906210228 Provides summary of activities while at TMI-2, for 790504-11 Contact w/licensee was minimal DELLA RATTA:A Diffice of Inspection & Enforcement 79/05/04 1p
- 7905210281 Forwards JM Hendrie ltr to JP Swed of Radio Info Ctr for Blind,in response to 790420 ltr W/o enc1 INGRAM,F Office of Public Affairs 79/05/04 1p
- ---7906210272 Comments on JM Hendrie quotation in 790423 issue of Newswask Forwards J Koch 790420 ltr to Newsweek editors, addressing identical concern ROCH, J Affiliation Unknown 79/04/20 2pp
- 7906220077 Fowards component histories
  BEEMAN.R P Metropolitan Edison Co 79/05/04 3pp

- 7906220236 Responds to encl JH Smylie 790419 ltr to JM Hendrie Forwards JM Hendrie Itr to American Newspaper Publishers Association & description of nuclear liability insurance H/o encl INGRAN, F Office of Public Affairs 79/05/04 ip
- ~~7906220240 Requests explanation of JM Hendrie statement of opposition to freedom of press, as quoted in NY Times Also requests info reliability for nuclear accidents
  SMYLIE: J H Affiliation Unknown 79/04/19 ip
- 7906220276 Responds to encl TP Henry 790416 ltr to JM Hendrie Forwards JM Hendrie ltr to American Newspaper Publishers Association re Hartford Courant article W/o encl INGRAM,F Office of Public Affairs 79/05/04 lp
- --7906220279 Forwards editorial from 790416 edition of Hartford Courant which criticises UM Hendrie Urges response to various charges & insimuations HENRY: TP Affiliation Unknown 79/04/16 2pp
- 7906270148 Summary of 790426 meeting w/BbW re analytical methods used for analysis of small break accidents & loss of feedwater transients
  JENSEN, W.L. Analysis Branch 79/05/04 42pp
- 7906290391 Provides summary of activities while assigned to TMI-2 site COHER.: I Region 1. Philadelphia. Office of the Director 79/05/04 lp
- 7906210017 Discusses concerns re const planned around auxiliary decay heat removal sys Questions ability of const to withstand aircraft impact ampact Region 1. Philadelphia. Office of the Director 79/05/05 10
- 7706210243 Estimates TMI-2 release for 790328-0430 at 16 cubic inches W/T Jackson calculations STOHR-J P Region I, Philadelphia, Office of the Director 79703705 2pp
- 7906220311 Lists NRC Health Physicists who are qualified instructors per 790413 memo Requests notification of security personnel SMITH.O H Region i, Philadelphia. Office of the Director 79/05/05 ip
- --7906220317 Forwards list of NRC personnel who have completed radiation work permit training or equivalent & have been instructed in THI site-specific procedures
  BHITM O H Office of Inspection & Enforcement 79/04/13 1p
- 7906280216 Presents design criteria for temporary onsite staging area for solid radioactive waste COLLINS.J T Effluent Treatment Systems Branch 79705/05 3pp
- 7906210144 Suggests steps be taken to ensure that hourly readings are taken & transmitted in timely manner to IE Environ Group Recommends readings every half-hour PERROTTI.D Region 1. Philadelphia, Office of the Director 79/05/06 1p
- 7906210282 Notifies that hourly readings & alerts from TMI are not being tranmsmitted in accordance w/J Streeter memo Steps should be taken to insure hourly readings PERROTTI.D J Region 1. Philadelphia. Office of the Director 79/05/06 ip
- 7906080019 Notice of ACRS 790416-17 meeting in Washington DC to discuss TMI incident CHILK-8 J Office of the Secretary of the Commission 79/05/07 5pp
- 7706130376 Forwards two memos re branch involvement w/incident JACKSON,R & Geosciences Branch 79/05/07 1p
- 7906210145 Discusses anticipated irregularity of periodic effluent monitor readings due to readout location reading conversion effort & personnel task priority conflicts
  7 Region 1. Philadelphia. Office of the Director 79/05/07 1p
- 7906210212 Provides summary of activities while at TMI-2, for 790328-0421 Critical of breakdown in communications re health activities SLOBDIEN, M J Region 1. Philadelphia, Office of the Director 79/05/07 2pp
- 7906210215 Provides summary of activities while at TMI-2, for 790328-0409 Contact w/licensee was minimal SHITH:R H. Region i. Philadelphia, Office of the Director 79/05/07 2pp

- 7906210224 Provides summary of activities while at TMI-2.for 790329-0412 Critical of licenses's initial reaction to emergency, particularly re sample collection ACKSON-T J Office of Inspection & Enforcement 79/05/07 2pp
- 7706210280 Notifies of dolays in readouts for airborne effluent monitor Delays will cease when new local readouts are installed & operative Office of Inspection & Enforcement 79/05/07 ip
- 7906220189 Forwards update of health physics status of facility Info was sent to LV Gossick for use in memo to NRC KINNEY:N W Region 1. Philadelphia. Office of the Director 79705/07 Jpp
- 1706280164 Forwards supplemental recommendation to Step B of G Kunder 1790507 memo re changes in operating point WILSON, R F GPU Service Corp 77/05/07 ip
- 7906280167 Notifies that level in 0 steam generator should be 95% setpoint & generator should remain isolated Procedure EP-34 governs use of 0 generator MILEON, R. F. GPU Service Corp. 79/03/07 ip
- 7905280170 Forwards revision b additions to RF Wilson 790501 memors recommended changes in operating point Items replace or modify Steps 1-5 in memows. Below. RF GPU Service Corp 79/05/07 3pp
- 7906270363 Discusses Change 1 to interim procedure for notifying state agencies of shipments of TMI radwaste MERR, Q K Assistant Director for State Agreements Programs 79703/07 3pp
- 7906290405 Forwalds 790503 "Technical Rept on Reactor Coolant Letdown Sys " Regt based on B&W 790422 "Letdown Sys Design Statement " CRONEDERGER, D K. GPU Service Corp. 79/05/07 S3pp
- 7906200447 Provides info re activities while at TMI-2, for 790417-0501 Critical of emphasis placed on individual's ofcimore NRC team offort needed YELLEOGR'P J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/06 1p
- 7906210111 Forwards executive summary re TMI-2 liquid & gas releases for 770328 incident PORTER.8 W Porter-Gertz Consultants. Inc. 77/05/08 7pp
- 7905270149 Status rept for 790507 RDSS.D F Division of Project Management 79/05/08 5pp
- 7906280162 Forwards complets compilation of emergency & special operating procedures 790327-0508 Procedures are categorized by present status WILEOM, R.F. GPU Service Corp. 79/05/08 6pp
- 7906200239 Forwards results of electrical methods to measure water level in reactor bidg MENJEL.T C GPU Bervice Corp 79/05/08 ip
- 7904280240 Describes method & procedure of determining water level between 8 ft 4 inches & 10 ft 8 inches by meggering electrical penetrations
  MENZEL, T C OPU Service Corp 79/05/08 ip
- 7905280241 Forwards chart of megger leads to motor operated valves info to be used to determine water level in reactor blog MENIEL, T C. GPU Service Corp 79/05/08 2pp
- 7905290403 Provides summary of activities while assigned to TMI-2 site Comments on licensee & NRC operations MADDEN.W J. ROCERB.M E Region 1. Philadelphia, Bafeguards Branch. 79/05/08 4pp
- 7906200510 "Tech Spec Furnishing & Placing Nonshrink Portland Cement Oraut." by Oilbert Associates Inc # Metropolitan Edison Co 79/05/09 17pp
- 7904210005 Confirms results of NRC measurements of EPA milk cross-check samples based on 3 79 liters of milk received & corrected to 2.000-h on 790428 SMITH.Q.H Region 1. Philadelphia. Fuel Facility & Materials Bafety Branch 79/05/09 ip
- 7906220166 Forwards 790430 ltr to TH Pigford re TMI documents Lists
  TMI documents that have not been forwarded to President's
  Commission W/790430 ltr
  CDRNELLE K. Office of the Executive Director for Operations
  79/05/09 lp

- --7906220173 Notifies of delivery of matl requested on TMI Lists category breakdown of documents Complete listing of all documents will be available by 790601 Draft of ltr enci CORNELLE K Office of the Executive Director for Operations 79/04/30 App
- 7906220214 Forwards addl copies of PNOs re TMI incident COLLING.H E Assistant Director for Emergency Preparedness 79/05/07 ip
- 7906270153 Submits daily digest for 790507 ROSS.D F Division of Project Management 79/05/09 2pp
- 7906280160 Forwards B&W memo summarizing calculations restarting natural circulation in 9 steam generator Adequate head is available to drive B loop on 95% range WILSON.RF GPU Service Corp 79/05/09 19pp
- , 7906270023 Respands to TMI special operating procedure 2-77-073 which recommended respirator program Offers guidelines for determining "work area" MURRI.E L. Metropolitan Edison Co. 79/05/09 1p
  - 7906290383 Provides summary of activities while assigned to TMI-2 site RUHLMAN,W A Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/09 ip
  - 79061303Bl Provides possible method & time required to reduce hydrogen concentration inside containment from 1 8% to 1 0% or less, per H Denton request SCHIERLING.H Accident Analysis Branch 79/05/10 2pp
  - 7906200076 Forwards B Hanauer 790331-0428 logs & notebooks for TMI Info partially withheld home telephone numbers (ref FOIA Exemption 6) HANAUER, S H Assistant Director for Plant Systems 79/05/10
  - 7906210001 Summarizes Radiation Mgt Corp contract to perform whole body counts on each NRC employee leaving TMI site definitively, after tour of duty BDRES, Region 1, Philadelphia, Office of the Director 79/05/10 7pp
  - 7906220178 Submits recommendations re small break transients & accidents natural circulation onsite power distribution, determination of core status research & engineered safety feature equipment status # ACRS Advisory Committee on Reactor Safeguards 79/05/10 4pp
  - 7706260240 Notifies of operations w/Region 1 news ctr while vacationing Forwards procedure for independent measurements on radwaste liquid discharges ABRAHMIK Region 1, Philadelphia, Office of the Director 79/05/10 Spp
  - 7906260372 Submits topics for discussion at 790510 meeting w/util mgt Propounds questions re health physics organization, new plant stack treatment sys & compactor use OREOER. Region 1, Philadelphia, Office of the Director 79/05/10 2pp
  - 7906270188 Discusses deferring administration of stams at eight operating power reactors COLLING.P F Operator Licensing Branch 79/05/10 1p
  - 7906290255 Recommends near-term sampling frequencies Samples are only means to assure criticality control dissolved gas concentration measurement & chemistry status
    WILSON:R F GPU Service Corp 79/05/10 2pp
  - 7906290274 Discusses long-term RCB pressure control Current plan is to take primary sys down to 300 lb pressure for long-term natural circulation Discusses other options
    WILSON.R F OPU Service Corp 79/05/10 3pe
  - 7906270421 Provides summary of activities while assigned to TMI-2 site HOLTNER.E Region 1. Philadelphia, Office of the Director 79703710 ip
  - 7706210136 Discusses efficiency testing of charcoal filtration sys at TMI-2 Sys used for reduction of radioadine effluents should be tested every 720-h of operation COLLINS.J T Effluent Treatment Systems Branch 79/05/11 ip
  - 7906210202 Forwards corrected Xe-133 & I-131 release graphs for inclusion w/790508 graphs PORTER,S W Metropolitan Edison Co 79/05/11 3pp

- 7906210205 Discusses sewage & environ air sample min detectable limits for I-131 & particulates PORTER,S W Metropolitan Edison Co 79/05/11 1p
- 7906210221 Provides summary of activities while at THI-2, for 790413-28 Critical of licensee's inability to provide accurate time estimates ROTH, J. Office of inspection & Enforcement 79/05/11 2pp
- 7906220332 Forwards list of health physics staff, as of 790512 SMITH, 0 H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906250325 Forwards Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively, safety evaluation & notice of issuance & availability SCHMENGER, A Operating Reactors Branch 1 (Pre 790625) 79/05/11 2DD
- --7906250326 Amends 3B & 43 to Licenses DPR-24 & DPR-27, respectively, requiring actuation of safety injection, revising opening logic for pressurizer power operated relief valves & modifying power supplies SCHMENCER.A Operating Reactors Branch I (Pre 790625) 79/05/11 14pp
- --7906250327 Safety evaluation supporting Amends 38 & 43 to Licenses DPR-24 & DPR-27, respectively SCHWENCER, A Decrating Reactors Branch i (Pre 790625) 79/05/11 3pg
- --7704250328 Notice of issuance & availability of Amends 38 & 43 to Licenses DPR-24 & DPR-27-respectively SCHWENCER. A Operating Reactors Branch 1 (Pre 790625) 79/03/11 2pp
- 7906260251 Notifies of formet for repts of analytical data for AMI-5 samples Forwards summany of radionuclides released in Busquehanna River 790328-0511
  PDRTER.S Porter-Dertz Consultants, Inc. 79/05/11 2pp
- 7906270108 Discusses concern re vessel fracture in older operating plants following small break LOCA
  KELLEY. 6 Reactor Systems Branch 79/05/11 19
- 7906270172 Discusses qualitative evaluation of failure potential of TMI-2 reactor vessel, made for week ending 790512 No indication of cracking or extension SERPAN.C Z Metallurgy & Materials Branch 79/05/11 1p
- 7906280127 Forwards "Preliminary Annotated Sequence of Events, Accident of 790328, Prepared by Pata Mgt Reduction Group "
  ZODIACO, V P OPU Service Corp 79/05/11 2pp
- 7906280218 Forwards TMI-2 charcoal filtration sys data for use in evaluating charcoal efficency data

  Constructed T Effluent Treatment Systems Branch 79/05/11 7pp

- 790621014B Discusses actions required re TMI liquid discharges & reviews in-plant instructions record keeping & weekly sampling of tanks & sumps being discharged STOHR, J P Region 1. Philadelphia, Office of the Director 79/03/14 Sap
- 7906210152 Discusses discovery of radioactive math at TMI landfill Area is off limits & will be surveyed Lists actions required to resolve situation STOPR, JP Region 1. Philadelphia: Office of the Director 79/05/14 2pp
- 7906210236 Assigns staff for IE Resident Ofc at TMI-2 Discusses schedule for assignments by other IE regions GRICR, B H Region 1. Philadelphia, Office of the Director 79/05/14 4pp
- 7906260310 Responds to 790510 query Part 30 licenses apply to possession & use rather than implementation or manipulation of waste sys HILLIAMS.R L GPU Service Corp 79/05/14 1p
- 7906270154 Submits daily digest for 790507 ROSS,D F Division of Project Management 79/05/14 3pp
- 7906290032 Requests end to dumping of water from plant into Susquehanna River Physical & mental well-being of populace is in jeopardy WOHLSEN A B Lancaster, PA 79/05/14 lp
- 790629038? Provides requested summary of activities while assigned to TKI-2 site MONTOCHERY, D M Region 2. Atlenta, Fuel Facility & Materials Safetu Branch 79/05/14 ip
- 7406070130 Confirms 790515 telcon w/J Holman & M Deers THI training dept intends to resume licensed operator requalification program on 790521 https://doi.org/10.1007
- 79062003B5 Discusses procedures for handling radwasts shipments from facility Info partially withheld home telephone number (ref FOIA Exemption 6) STOHR.J P Region 1, Philadelphia, Office of the Director 79705/15 2pp
- 7906200477 Provides info re activities while at TMI-2 site,per BH Grier 790409 memo Critical of health physics function during early stages of incident HHITE,J R Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/05/15 3pp
- 79062(0158 Discusses insp of TMJ radioactive waste shipments Requests specific info for each shipment contents package type, transport company, destination & shipment coordinator STORR, JP Region 1, Philadelphia, Office of the Director 79/05/15 2pp
- 7906260286 Lists info needed for Wednesday meeting summary table of water releases, estimate of total curies released & increase in river water gross activity as result of TMI-2 event VOLLMER, R H Assistant Director for Systems Engineering 79/05/15 2pp
  - D6270170 Discusses encl BtW 780809 ltr indicating that 8&W advised swhers several months ago of need to observe both Pressurfer level & RCS pressure to ensure RCS is filled ATT80N.R J Division of Project Management 77405/15 Opp
  - 36290170 Forwards revisions to schedule for Westinghouse & C-E repts to scope of work, current licensing considerations, findings & recommendations HADANI.A C Reactor Systems Branch 79/03/15 4pp
  - M6290326 Discusses request for TMI-related actions by Ofc of Nuclear legulatory Research Forwards form to be completed \$2 returned \$4.790517.

    Administrative and Resource Control Staff. 19/05/15 1p
  - 16290386 Provides summary of activities white assigned to TMI-2 sita imments on licenses & NRC operations 'EERY'N W Region 2, Atlanta, Fuel Facility & Materials Bafety Panch 79/05/15 2pp
  - 6290401 Provides summary of activities while assigned to TMI-2 afteroments on licensee & NRC operations ILLSAP, M.J. Region 2. Atlanta. Fuel Facility & Materials Safety ranch 79/05/15 2pp

- 7906200022 Discusses 790401 telcons re potential for hydrogen esplosions in environ of high humidity Info partially withheld home telephone number (ref FOIA Exemption 6) SCHIERLING.H Accident Analysis Branch 79705/16 1p
- 79062002B0 Notification of 790518 meeting w/NRL & BNL in Bethesda: MD to discuss further work related to shield tank neutron damage SNAIDER.R P Systematic Evaluation Programs Branch (Pre 790625) 79/05/16 2pp
- 7906280227 Discusses hydrologic criteria for proposed interim solid waste storage area COLLINS, J T Effluent Treatment Systems Branch 79/05/16 1p
- 7906270379 Provides summary of activities while assigned to TMI-2 site Comments re licensee & IE/NRC operations IAVADOBSKI,R W Region 2, Atlanta, Fuel Facility & Materials Safety Branch 77/05/16 2pp
- 7906290406 Provides summary of activities while assigned to THI-2 site Comments on NRC operations

  JAPE.F Region 2, Atlanta, Office of the Director 79/05/16

  Zpp
- 7906130500 Forwards THI activities inventory forms re security items BRADY, R J Division of Security 79/04/17 7pp
- 7908210160 Discusses failure of health physics personnel to monitor use of special operating procedure 7-93 reactor bldg sump level measurement Area activity levels elevated MCGAUCHY, R W Region 1. Philadelphia. Office of the Director 79/05/17 10
- 7906220150 Discusses conducting operation in accordance w/licensee memos & directives rather than special procedures
  MCGAUGHY,R W Office of Inspection & Enforcement 79/05/17 3pp
- 770ARRO18R Summary of 790511 & 15 meeting W/NRC & General Public Utils to discuss design criteria layout & plot plan COSTOMIRIS, G H Gilbert Associates, Inc 79/05/17 bogers, r
- 7906220304 Discusses shift operation of NRC mobile lab Forwards lab schedule & list of personnel qualified to operate lab KOTTAN.J J Region I, Philadelphia, Office of the Director 79/05/17 3pp
- 7906260318 Discusses resolved issues re alternate decay heat removal sys during 790516-17 site visit Total sys analyzed by Hestinghouse Punetration study being prepared LIPINSKI.R Division of Systems Safety 79/05/17 2pp
- 7906270063 Forwards 790514 inspector findings re changes to plant procedures resulting from NRC 790507 order Procedures of order & operator understanding deemed adequate MCSELEY,N.C. Office of Inspection & Enforcement 79/05/17 is
- --790627006B Confirms procedural changes resulting from NRC 790507 order & operator understanding of changes JAPE,F Region 2, Atlanta, Office of the Director 79/05/14 to
- 7906270187 Notification of 790521 meeting W/Exxon to discuss transient & small break analysis in C-E & Hestinghouse plants containing Exxon fuel Distribution list enci MANE,W F Standardization Branch 79/05/17 2pp
- 7906270190 Requests receipt of all TMI-related documents generated by Ofc of Nuclear Regulatory Research All TMI documents will be forwarded to FOIA ofc SCROODING.R M Administrative and Resource Control Staff 79/05/17.
- 7906280149 Recommends heating coils not be installed in filter tracks serving auxiliary & feed bldgs MCCONNELL.JF GPU Service Corp 79/05/17 3pp
- 7906280238 Suggests experiments to measure radioactive levels of contaminated water Results of experiments will facilitate selection of processes to clean up water BROOKSBANK.R E GPU Service Corp 79/05/17 ip
- 7906010213 Forwards "B&W 177 Fuel Assembly Dwners' Group Asymmetric LOCA Loads Evaluation Program, Phase 2" & "B&W 177 Dwners' Oroup . Rept for Asymmetric LOCA Loads Evaluation, Phase 2 " MERBEIN.J O. Metropolitan Edison Co. 79/05/18 p
- --7906010218 "B&W 177 Fuel Assembly Owners Group Asymmetric LOCA Loads Evaluations Program: Phase 2." dtd 790410 a Metropolitan Edison Co 79/04/10 9pp

- --7906010229 "BLW 177-Fuel Assembly Dwners Group Assumptions, Methodology & Acceptance Criteria Rept for Asymmetric LOCA Loads Evaluation, Phase 2 " # Metropolitan Edison Co BAW-1538 79/04/30 37pp
- 7906200499 Discusses shift operation of NRC mobile lab Forwards RW McGaughy 790518 draft memo to reactor operations inspectors assigned to THI control room watch KOTTANJ J Region i. Philadelphia. Office of the Director 79/05/18 6pp
- 7906210239 Discusses insp of mine safety equipment prior to return B Weiss requests insp for contamination MCGAUGHYR W Region i, Philadelphia, Office of the Director 79/05/18 10
- 7906220132 Forwards util position re spent resin solidification for shipping & burial in anticipation of new NRC requirement. Three process vessels of EPICOR 2 will be designed MCGOEY.R General Public Utilities 79/05/18 ip
- 7906260079 Authorizes use of INEL personnel & equipment for TMI source term measurement project Forwards amended project brief, specifying no increase in funding ARSENAULT,F J Division of Safeguards, Fuel Cycle & Environmental Research 79/05/18 7pp
- 7906270063 Requests addi info re TM1 safety-related equuipment performance & exposure data in support of angoing qualification testing evaluation research program LEVINE,S Office of Nuclear Regulatory Research 79/05/18 2pg
- 7906270103 Submits daily digest for 790517 ROSS,DF Division of Project Management 79/05/18 4pp
- 7906270142 Discusses results of preliminary review of data on BMR pressure relief valve failure rate
  TEDEBCO,R L. Assistant Director for Reactor Safety 79/05/18
- 7906280190 Recommends changes in plant operating conditions in order to reach further primary pressure level for long-term operation ELAM.B D GPU Service Corp 79/03/18 3pg
- 7906280154 Requests returning combustion turbine generators to normal economic dispatch Precautionary measures not needed due to installation of two emergency disest generators
  ARNOLD,R C OPU Service Corp 79/05/18 1g
- 7906280236 Notifies of new criteria for design of process vessels for EPICOR 2 Bolidification vessels will be mfg in anticipation of potential NRC requirement MCGGEY.R GPU Bervice Corp 79/05/18 ip
- 7906290410 Provides summary of activities while assigned to TMI-2 site GLEKN, J E Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/05/18 ip
- 7906220097 Discusses DOT safety insp of vehicles transporting TMI radioactive waste KINNEMAN, J Region 1, Philadelphia, Office of the Director 79/03/19 1p
- 7906220103 Concurs w/790518 ltr suggesting relaxation of extra precautionary measures for area transmission sys VOLLMER.R H Division of Operating Reactors 79/05/19 1p
- 7906270040 Responds to 790518 ltr re extra precautionary measures for area transmission sys re TMI Concurs w/relaxation of measures
  VOLLMER.R H Assistant Director for Systems Engineering 79/05/19
- ---7906270043 Requests concurrance w/relaxation of extra precautionar, measures taken to assure reliable power supply to TMI W/ encl 790503 RW Werts memo ARNOLD,R C OPU Service Corp 79/05/18 2pp
- 7906280132 Recommends addl changes to current RCS pressure reduction ELAM, B D GPU Bervice Corp 79/05/19 1p
- 7906290118 Notifies of agreement to loan govt automobiles to DOT inspectors
  KINNEMAN, J D Region 1, Philadelphia, Office of the Director 79/05/19 lp

- 7906120009 Forwards requested info re NMSS participation in TMI incident
  CUNNINGHAMAR E Division of Fuel Cycle & Material Safety
  79/05/21 12ao
- 7906130388 Forwards personal record of TMI~related activities for 790328-0401, in response to H Denton 790424 memo MAZETIS, 0 R Reactor Systems Branch 79/05/21 10pp
- 7406210002 Forwards instructions for transcribing TMI interviews & miscellaneous info for investigation procedures OIBSQN.A, MARTIN.B Region i, Philadelphia, Office of the Director 79/05/21 ilpp
- 790427015& Submits daily digest for 790521 RDSS.D F Division of Project Management 79/05/21 3pp
- 7706290376 Provides requested summary of activities while assigned to TMI-2 site Comments on licensee & NRC operations ENGELKEN,R H Region 5. San Francisco. Office of the Director 77/05/21 2pp
- 7906210164 Forwards min environ survey team routine schedule Routine surveys will be made only on day shift,beginning 790526 STOKR.J F Region 1, Philadelphia, Office of the Director 79705/22 2pp
- 7906210169 Discusses off-hour environ surveys w/reduced manpower Environ survey teams available during off-hour shifts on callout basis only STOHRJ P Region 1. Philadelphia, Office of the Director 79/05/22 Opp
- 7906210176 Requests six beeper/pagers needed to implement reduced manpower phase & ensure full coverage STOHR, J P Region 1. Phyladelphia, Office of the Director 79/03/22 (p
- 7906220205 Forwards latest readings on equipment hatch & containment dome Requests evaluation of data COLLINS, J T Effluent Treatment Systems Branch 79/05/22 4pp
- 7906260090 Forwards update of preliminary annotated sequence of events of 790328 incident
  MOSELEY, N C Region 1. Philadelphia, Office of the Director
  79/05/22 40pp
- 7906270071 Discussed encl IE memo re surveillance test procedures for auxiliary or emergency feedwater test & actions resulting from TMI incident ROSS.D F Division of Project Management 79/05/22 2pp
- --7906270072 Discusses isolation of auxiliary or emergency feedwater during test Requests confirmation by 790530 re test procedures of PHRs w/redundant auxiliary or emergency feedwater sys MOBELEY.N C Division of Reactor Operations Inspections 79/03/18 | p
- ---7905270075 Discusses tentative ACRS schedules & interests thru June 1979 full committee meeting CROCKRYL P Division of Project Management 79/05/21 3pp
- 7906200399 Summarizes suit by City of Lancaster,PA seeking injunction against const of water decontamination facility & dumping info partially withheld litigation options (ref FOIA Exemption 5) EILPERIN, 8 F Office of the General Counsel 79/05/23 5pp
- 7906210181 Describes continuing manpower needs for TMI Environ Group Environ survey coordinator, environ surveyor & survey assistant required STORR, J P. Region 1, Philadelphia, Office of the Director 79/05/23 2pp
- '906220062 Notifies of form for repts of analytical data for HPR & ANI-5 samples. Activities of radionuclides identified on different filters will be reported PORTER,S Porter-Certz Consultants, Inc 79/03/23 3pp
- 7906220085 Recommends purchase of automatic TLD sys for environ & parsonnel dosimetry at TMI GRIER. B H Region 1. Philadelphia, Office of the Director. 79/05/23 4pp
- 7906220195 Forwards items for discussion during ASME radwaste course COLLINS.J T. Effluent Treatment Systems Branch, 79/03/23 2pj

- 7906260324 Discusses containment in-leakage rate Average pressure docay is OBZ per day KERRICAN.J Office of Nuclear Reactor Regulation 79/09/23 2pp
- 7906270139 Forwards completed TMI activities inventory for both completed & ongoing Ofc of Nuclear Regulatory Reseach-related TMI actions SCROGGINS, R M Administrative and Resource Control Staff 79/05/23 68pp
- 7906280155 Forwards Revision 2 of procedure 2-63.solid plant operations Revision reflects current plant operation BOUCHER.P GPU Service Corp 79/05/23 14pp
- 7906280157 Forwards summary of 790516 meeting w/NRC & govt officials in Hershey,PA re discharge of contaminated water into Susquehanna River ESTEVES;R M GPU Service Corp 79/05/23 lp
- 7906280158 Forwards liquid release info 790523-30 MCGOEY, R J OPU Service Corp 79/05/23 2pp
- 7906040231 Notifies of discharge of 7,400 gallons of water on 790514 ½ 7,100 gallons of water on 790515 Water released to influent of mechanical draft cooling tower discharge bypassing waste treatment sys

  TROFFER, G J Metropolitan Edison Co 79/05/24 2pp
- 7906060187 List of officials to contact re TMI Info partially withheld home telaphone numbers (ref FOIA Exemption 6) \* Commission 79/05/24 ip
- 7906210192 Summary of 790921 meeting w/PA Bureau of Water Guality Agenda & TMI radiological environ monitoring program organizational chart encl PORTER.8 W Hetropolitan Edison Co 79/05/24 3pp
- 7906210196 Summary of 790521 meeting w/EPA to discuss TMI environ monitoring data as requested by President's Commission PORTER.8 W Hetropolitan Edison Co 79/05/24 ip
- 7906220092 Forwards WE Wallace itr re chemical explosive hazard at TMI Info partially withheld address and telephone numbers (ref FOLA Exemption 6) JONES,C L. Pennsylvania: State of 79/05/24 3pp
- 7906060203 Forwards names to be added to 790413 list for radiation work permit training Info partially withheld Social Security numbers (ref FOIA Examption 6)
  SMITH.0 H Office of Inspection & Enforcement 79/05/25 19
- 7906120002 Forwards recommendations for possible changes to nuclear power plants in light of TMI incident KNIGHTON.0 W Division of Operating Reactors 79/05/25 7pp
- 7906200410 Discusses whole body count of exposed individual Skin dose provided for beta & gamma radiation Info partially withheld name & social security number (ref FOIA Exemption 6) SLOBODIEN M J Region 1, Philadelphia, Office of the Director 79/05/25 ip
- 7906210033 Provides info re activities while at TMI-2, for 790407-20 Many tasks could be perfoned by less qualified or experienced personnel EVERETT, R J Region 4, Dallas, Office of the Director 79/05/25 ip
- 7706210172 Forwards projected TMI liquid release info for 770523-30 COLLING, J F Effluent Treatment Systems Branch. 79/05/25 2pp
- 7906210241 Discusses manning of IE Resident Ofc at TMI-2 during name outline haure
  KEIMIO,R R Region 1, Philadelphia, Office of the Director 79/05/25 4pp
- 7906220287 Informs 790524 telcons re Norton Landfill Best souce of info is D Sly of NRC Environ studies by Brown Univ students vary greatly from NRC data STORR.J.P Region 1. Philadelphia. Office of the Director 79/05/28 2pp
- 7906270015 Submits daily digest for 790525 Forwards order re TMI records.
  ROSS,D F Division of Project Management 79/05/25, 2pp
- --7906270017 Orders preservation of all potential sources of data related to THI incident,
  CHILK, 8 J Docketing & Services Branch 79/05/22 3pp

- 17:0270393 Provides summary of activities while assigned to THI-2 sits Comments on licenses & NRC operations FRIEDHAN, L Region 1. Philadelphia, Office of the Director 79:05:725 2pp
- NNS290416 Provides summary of activities while assigned to THI-2 site performed environ surveys SIEANNS, CF Region 1. Philadelphia, Office of the Director 79/05/28 ip
- 77)&070161 Forwards NRC 790525 statement re use of EPICORE-IT sys at THI Directs util not operate sys w/contaminated water stream COLLMER, R H Assistant Director for Bystems Engineering 79/05/26
- lp .
- --7905070165 Directs NRC to prepare environ assessment re proposals to decontaminate & dispose of contamminated waste water Pending review.licensee should not operate EPICORE-II Sys CMILK.6 J Office of the Socretary of the Commission 79/08/17
- 7706270134 Provides guidance re priority in notifying individuals in case of significant gaseous or liquid release Info partially withheld home telephone numbers (ref FOIA Exemption 6) STORR, J P Office of Inspection & Enforcement 79/03/26 App
- 7508070197 Recommends monitoring of TMI-2 equipment to measure effects of abnormal environ Info would be invaluable in equipment qualification effort CHIRAMAL. M Plant Systems Branch 79/05/29 1p
- 1706210115 Forwards ropts on oxygen & hydrogen production & recombination re flammability & detonation limits in tentalment MELHER.C M. Assistant Director for Advanced Reactor Safety Research 79/05/27 ip
- -- 1706210121 Responds to NRC info request re flammability & detonation limits for hydrogen & oxygen steam mixtures at elevated temps & pressures RID.L N Assistant Director for Advanced Reactor Safety Research LARKING, J T Experimental Gas-Cooled Reactor Safety Research Branch 79/05/25 3pp
- ~-7906210125 Responds to NRC info request re potential for oxygen accumulation in reactor vessel during TMT-2 accident RIB.L N Assistant Director for Advanced Reactor Bafety Research 79/05/25 2pp
- --7906210137 "Evaluation of Radiolysis Associated W/TMI-2 Incident "
  CONINE: J C Knolls Atomic Power Laboratory KROMMENKOEK, D J.
  LOGAN, E Dak Ridge National Laboratory 79/05/31 10pp.
- 7905270387 Discusses ACRS TMI Subcommittee 790531-0601 meeting agenda 7e "Preliminary Discussion on Implications of TMI-2 for BWR" Forwards vugraphs to be used in presentation HELTEMES.C. J. Standardization Branch 79/03/29. 19pp
- 7908220078 Discusses radiation & contamination survey of Dragar respirators & associated equipment No excessive direct radiation or transferable contamination found SLOBBDIEN.M J. Region i, Philadelphia, Office of the Director 79/05/30 ip
- 7906260270 Forwards procedure for adjusting reactor bldg sump water pressure gauge to suppl procedure-2-93 Column of water must not exist in instrumentation line during zero adjustment. HOORE, J. P. GPU Service Corp. 79/05/30. 3pp
- 7906270110 Forwards 790522 memo & Apr 1979 monthly rept on TMI studies to nonradiological aquatic & water quality data for Busquehachna River HICKEY: CR Environmental Specialists Branch 79/05/30 ipp
- --7906270112 Forwards Apr 1979 monthly progress rept of TMI aquatic study.
  NARDACCI, O A Ichthyological Associates, Inc. 79/04/30 1p
- --7906270113 Monthly rept of TMI aquatic study for Apr 1979
  RARDACCI.O A Ichthyological Associates.Inc 79/04/30 22pp
- 7904180704 "Population Dose & Health Impact of Accident at TMI Nuclear Station:Preliminary Estimates Prepared by Ad Hod Interagency Dose Assessment Group," for 790328-0407.

  NELSON, C Environmental Protection Agency. NELBON, M Health, Education & Welfare, Dept of ROBENSTEIN, M, HEW, Dept of, Food & Drug Administration. NUREO/CR-0558 79/05/31. 103pp Available at NTIS

- 7906200431 Submits outline of radiological investigation rept GIBBON.A Region 1, Philadelphia. Office of the Director 79/05/31 ip
- 7906220162 Submits list of topics that Accident Analysis Branch recommends for inclusion in "lessons learned" activity HOUSTON-R W Accident Analysis Branch 77/05/31 3pp
- 7906220299 Discusses replacement of Metropolitan Edison dosinetrist at TMI SLOBODIEN, M J Region 1, Philadelphia, Office of the Director 79/05/31 1p
- 7906260127 Summary of 790530 briefing in Washington.DC re TMI-2 incident response program & status of improvements at facility CHILK.S J Office of the Secretary of the Commission 79/05/31
- ---7906260413 Summary of 790405 meeting w/ACRS in Washington, DC re scope & timing of ACRS annual rept on NRC safety research program CHILK, S J Office of the Secretary of the Commission 79/04/05
- 7906290457 "I-131 Removal Efficiency Determination of Adsorbent Samples" SCOTTIE: C D . KOVACH, J L Nuclear Consulting Services, Inc 79/05/31 App.
- 7906070126 Requests meeting to identify engineering evaluations of TMI incident
  MATTSON.R J Division of Systems Safety 79/06/01 2pp
- 7906210187 Authorizes waiver of hands-on search for members of Congressional Subcommittee on Natural Resources & Environ during 790601 plant tour
  VOLLMER.R H Assistant Director for Systems Engineering 79/06/01
- 7906220073 Agendas for technical working group & planning meetings re THI-2.for 790428-0601 \* Office of Nuclear Reactor Regulation 79/06/01 400pp
- 7906220157 Makes recommendations for reestablishing natural circulation at facility in evant of loss of natural circulation Gives results of calculations performed HQLAHANN G H Analysis Branch 79/06/01 5pp
- 7906220203 Forwards invoice from Radiation Mgt Corp for environ dosimetry & whole body counting for 790331-0430 Requests review HILLIARD.C L Division of Accounting 79/06/01 2pp
- 7906260086 Requests complete copies of TMI data collected to date by util Data Reduction & Mgt Group CORNELLE K Office of the Executive Director for Operations 79/06/01 1p
- 7906290244 Comments on proposed THI rediation protection plan Licensee should provide organization chart to reject change of command & commitment to ALARA program MURPHY.T D Division of Site Safety & Environmental Analysis

7

- 7906130405 Confirms security arrangements for East-West Towers due to round-the-clock manning of NRC operations ctr in support of activities at THI THOMPSON.D Office of I & E Elecutive Officer for Operations Support 79/06/06 2pp
- 7906130446 Provides interim guidance for TMI investigators
  THGMPSON.D Office of Inspection & Enforcement 79/06/06 3pp
- 7906260496 Discusses lessons learned from THI-2 incident re releases of lodine & hydrogen oride from containment Elements more easily released than previously thought READ, J B Accident Analysis Branch 79/06/07 Bpp
- 7906260495 Forwards "Supplementary Startup Rept " HERBEIN J G Metropolitan Edison Co 79/06/11 19
- --7906260458 "Supplementary Startup Rept" \* Metropolitan Edison Co 79/06/15 10pp
- 7906190452 Forwards update of commitments resulting from TMI incident, made by B&H un behalf of operating plant customers TAYLOR.J H Babcock & Hilcox Co 79706/13 6pp
- 7906200623 Contract "Conduct of Special Inquiry Into THI Incident," awarded to Rogovín,Stern & Huge BICKHIT,L Division of Contracts FIN 8-1360 79/06/13 40pp
- 7906260507 Forwards Sandia Lab 790508 ltr & enci re contingency vent-filter for TMI-2 reactor DISALVO.R Probabilistic Analysis Branch 79/06/13 ip
- --7908260510 Submits addl info to 790413 presentation re contingency vent-filter for TMI-2 reactor BENJAMIN:A S Sandia Laboratories 79/05/08 27pp
- 7906270003 Lists goals of TMI-2 investigation discussed 790413; establish facts surrounding incident & evaluate performance of licensee as basis for corrective action DAVIG.J O Office of Inspection & Enforcement 79/04/20 Bpp
- --7906290004 Mod irrevising accounting & appropriation data to NRC-17-79-451 Contract number is hereafter changed to NRC-10-79-659 BICKWIT.L Division of Contracts B-1360 79/06/20 1p
- 7906280003 Forwards input to 790606 request for info re TMI-2 activities
  LARKINS.J Program Goordination Branch 79/06/15 is
- --7906280004 Advises of 790331 incoming calls at Incident Response Center BROWN.K M Division of Safeguards 79/06/15 ip
- ~~7906280005 Forwards input to 790606 request re TMI-2 activities
  MCGRATH.P E Probabilistic Analysis Branch 79/06/13 ip
- --7906280007 Submits 790401 record of action in determining requirements for emergency response action assuming core melt accident would occur BLOND.R M Probabilistic Analysis Branch 79/05/31 13pp
- --7906280009 Responds to 790515 request for add1 info re TMI activities Discusses decay heat & fission product inventory.core melt amalysis & containment venting conceptual design MCGRATH.P E Probabilistic Analysis Branch 79/05/21 3pp
- --7906280010 Responds to 790423 request re record of actions in THI incident Advises no involvement EDISON,O E Probabilistic Analysis Branch 79/04/30 ip
- --7906280012 Responds to 790413 memo from LV Gassick re recording actions taken on TMI incident Submits questions raised re sysoperations & backup/contingency evaluations BARANGHSKY,P W Probabilistic Analysis Branch 79/05/02 ip.
- --790&280014 Advises involvement w/TMI incident included meitdown analysis natural circulation/debris bed cooling analysis & containment vent-filtering assessment CUNNINGHAM.M Probabilistic Analysis Branch 79/03/02 2pp
- --7906280018 Responds to 790608 memo re TMI-2 activities Involved as research project manager & coordinator of info between NRC personnel & external groups
  REED,P R Environmental Effects Research Branch 79/06/13
  2pp

- --7906280019 Responds to 790608 mamo re TMI-2 activities Naval Research
  Lab analyzing characteristics of acctivated charcoal INEL
  staffs mobile lab
  SOLBERG, D Division of Safeguards 79/06/08 1p
- --7906280021 Advises E Berdeque: performed clerical dubies 790430-0507 MULCEN.R Division of Safeguards, Fuel Cycle & Environmental Research 79/06/14 1p
- --7906280022 Responds to 790614 memo re TMI-2 activities Submits description of cierical duties performed 790514-0521 ROBERTSON, D.D. Assistant Director for Operations & Evaluations 7906/14 lb
- 7906280035 Comments on Lessons Learned Task Force Item 13 protection of containment should not be inhibited by any "legal constraints" of DBA theology SPEIS.T Reactor Systems Branch 79/06/15 1p
- 7906270234 Farwards "Second Interim Rept on TMI-2 Accident " HERBEIN.J G Metropolitan Edison Co 79/06/18 lp
- --7906270235 "Second Interim Rept on TMI-2 Accident "
  \* Metropolitan Edison Co 79/06/15 98pp
- 7906280265 Summary of 790612 meeting w/EPRI.ECI & Ofc of Nuclear Reactor Regulation re actions now being taken by industry in response to TMI-2 incident TEDESCO.R L Assistant Director for Reactor Safety 79/06/18 ip
- 7906210012 Discusses need to determine adequacy of portable radiation survey instruments as indicator of gamma exposure rates, due to ambient cloud of Ke-133 resulting from TM1
  ALLANJ M Region i. Philadelphia. Office of the Director 79/06/19 ip
- 7906220082 Discusses new personnel badging requirements for TMI Badge exchange will begin 790620 SLOBODIEN.M J Region 1. Philadelphia. Office of the Director 79706/19 ip
- 79062B0077 Notifies info requested by 790502 ltr re adequacy of station electric distribution sys voltage will be provided by 790801

  MERBEIN. J O Metropolitan Edison Co 79/06/25 ip
- G inspection reports. IE Bulletins & correspondence
- 7906:30478 Forwards insp plan. IP-1. "Insp Requirements to Review Licensee Actions Taken in Response to Nuclear Incident at THI "Plan to be implemented immediately in State of PA BRUNNER.E J Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/04/11 7pp
- 7706290154 Responds to IE Bulletin 79-05A.Forwards info re review of operating procedures
  MATTIMOE, J. J. Sacramento Municipal Utility District 77/04/16
- 7906200334 Forwards IE Insp Repts 50-289/79-08 & 50-320/79-07 on 790319-23 & 26 No noncompliance noted.
  BRUNNER, E. J. Region i, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- ~-7906200339 IE Insp Repts 50-289/79~08 & 50-320/79-07 on 790319-23 & 26 No noncompliance noted Major areas inspected previous insp findings selected licensee events & licensee followup to prompt RO HAVERKAMP.D R , KEIMIO.R R Region i, Philadeiphia, Reactor Operations Nuclear Support Branch, 79/04/19, 10pp
- 7906260041 Responds to IE Bulletin 79-06B Operating procedures have been reviewed to provide that automatic actions of engineered safety features will not be overridden a Combustion Engineering, Inc. 79/04/20 24pp.
- 7906290483 Responds to IE Bulletins 79-06 & 79-06A, Revision 1. Forwards info re TMI incident, Proposed design & Tech Spec changes will be submitted by 790514.

  CLAYTON, F.L. Alabama Fower Co. 79/04/24, 2ipp.
- 7906290303 Responds to IE Bulletin 79-08, Forwards results of investigation re operational arrors & sye miselignments identified during TMI incident.

  OILLELAND, J E Tennessee Valley Authority 79/04/24 14pp.

- 7906290341 Responds to IE Bulletin 79-08 Forwards results of review of BMR sys designs & operational procedures
  PILANT. J M Nebraska Public Power District 79/04/25 4pp
- 7906270098 Requests clarification of requirement for "Verification of Operability" from IE Bulletin 79-068
  HILLIAMS.F J Division of Project Management 79/04/27 1p
- 7906290493 Responds to IE Bulletin 79-08 Forwards info re review of TMI incident Existing line isolation not important to ECCS injection
- REED, C Commonwealth Edison Co 79/04/27 22pp
- 7706290125 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI incident CRANE.P A Pacific Osa & Electric Co 77/05/01 5pp
- 7906290132 Responds to IE Bulletin 79-058 Forwards info re procedures & methods for maintaining natural circulation MATTIMOE, J J Sacramento Municipal Utility District 79/05/02 4pp
- 7906260332 QC procedure QCP-M-012 for final acceptance insp 9 QPU Bervice Corp 79/05/04 20pp
- 7906120169 Forwards [E Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required GRIER.B H Region 1. Philadelphia, Office of the Director 79703707 2pp
- 7704270101 Urges more conservative 3-loop requirement by keeping only one reactor coolant pump in operation. IE Bulletin 79-068 HILLIAMS.F J Division of Project Management 79/05/07 is
- 7906270032 Requests review of encl C-E 790420 response to IE Bulletin 79-06B re TMI-related matters RDS9.D.F Division of Project Management 79/05/08 27pp
- 7906270140 Requests criteria for continued operation of charging pump per IE Bulletin 79-06B HILLIAMS.F J Division of Project Management 79/05/08 1p
- 7908270126 Recommends that NRC study potential use of nuclear instrumentation (source & intermediate) to determine existence of voids re IE Bulletin 79-064, Revision 1 HILLIAMB, FJ Division of Project Management 79/03/09 ip
- --7906270137 Requests establishing requirement for core thermocouples per IE Bulletin 79-06, HILLIAMS:FJ Division of Project Management 79/05/07 ip
- 7906270131 Requests info re consideration given to possible pressure spikes in ice condenser containment plants per IE Builetin 79-06A.Revision i HILLIAMS.F J Division of Project Menagement 79/05/09 ip
- 7906200507 Forwards "Operation Plan for IE Resident Ofc at TMI-2" ORIER.B H Region 1. Philadelphia, Office of the Director 79/05/11 Spp
- 7906260119 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H. Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906270034 Forwards IE Region IV evaluation of licensee response to IE Bulletin 79-05B VARQA:8 A. Light Water Reactors Branch 4 79/05/11 ip
- --790627003B Evaluates licensee 790504 response to IE Bulletin 79-03B re revision of procedures for natural circulation & angineered safety features actuation KABEEN.O.L. Region 4. Dallas. Reactor Operations Nuclear Support Branch 79/05/10. 2pp
- --7906270041 Forwards response to IE Bulletin 79-058 re revisions of procedures & training operation personnel on establishing & maintaining natural circulation TRIMBLE, D C Ankansas Power & Light Co. 79/05/04 ip
- 7906290146 Responds to IE Bulletin 79-05A Forwards info relevant to design of BWRs & events surrounding TMI incident BTEWART: W P Floride Power Corp. 79/05/12 18pp.
- 7906260232 Notifies of licensee procedures for radwaste shipments 870HR, J P Ragion 1, Philadelphia, Office of the Director 79/05/15 ip

- 7906290355 Discusses licensee response to IE Bulletin 79-06A.Revision 1 Recommends mpt consider assessing current licensee operator understanding of TMI incident WILLIAMS.F J Division of Project Management 79/05/15 ip
- 7906200381 Discusses procedure for coordinating DDT safety insp of vahicles transporting TMI radwaste Info partially withheld home telephone numbers (ref FOIA Exemption 4) STOHR, J.P. Region 1, Philadelphia, Office of the Director 79/05/16 2pp
- 7906270002 Forwards licensee response to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident"

  VARGALS A Light Water Reactors Branch 4 79/05/16 in
- --7906270005 Submits update to 790424 response to LE Bulletin 79-06A. Revision 1 re-tripping of pressurtier water level bistables & resetting of containment isolation GOODMIN.G Portland General Electric Co 79/05/04 2pp
- 7906260360 Notifies of IE procedures for handling Metropolitan Edison Co correspondence # Office of Inspection & Enforcement 79/05/17 2pp
- 7906270025 Forwards licensee responses to IE Bulletin 79-06A VARGA,S A Light Water Reactors Branch 4 79/05/17 1s
- --7906270029 Responds to LE Bulletin 79-06A.Revision i re revision of emergency procedures for coping w/transients b accidents WACHTER.L J Northern States Power Co 79/04/30 7pp
- 7906080087 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " GRIER.O H Region 1, Philadelphia, Office of the Director 79/05/18 1p
- 7906200505 Discusses duties of reactor operations inspectors assigned to THI control room watch Delineates requirements of operation plan MCGAUGHY, R & Region 1, Philadelphia, Office of the Director
- 7906260367 Forwards draft IE circular clarification of requirements for procurement processing & distribution of radiopharmaceuticals for human use

  \* Office of Inspection & Enforcement 79/05/18 2pp
- 7906270120 Requests into re manual trip on low presqurizer level.as stated in Item 4F of 1E Bulletin 79-058
  HILLIAMS.F J Division of Project Management 79/05/18 Spp
- 7706220141 Forwards modified "Echedule for Personnel Assignments, Regions II--[V" re IE Resident Ofc at TMI-2 ORIER.B H Region 1, Philadelphia. Office of the Director 77/05/27 5pp
- 7906260222 Reviews maint activities & equipment likely to have affected 790328 event FASAND, A N Region 1, Philadelphia, Office of the Director 79/03/31 Bpp
- 7906270011 Lists IE bulletins issued since TMI incident which have been withheld due to lack of available Util resources ORIER.B H Region 1. Philadelphia. Office of the Director 79706/08. 2pp
- R Periodic operating reports & related correspondence
- 7906120003 Discusses long-term environ radiation monitoring at THI & designates EPA as leed agency Forwards exposure estimates from DDE & Drookhaven Nati Labs, MATSON U President of US & Executive Offices. 79/04/13 18pp
- 7906290006 Forwards "THI Aquatic Study," monthly repts for Jan. Feb & March 1979, received in response to requests for nonradiological aquatic & water quality data HICKEY, C R Environmental Specialists Branch 79/05/03 ip.
- ---7906290007 Forwards "TMI Aquatic Study." monthly repts for Jan,Feb & Mar per NRC 790414 request Forwarding ltr from Ichthyological Associates dtd 790501 encl.
  MUDOE, J. E. Metropplitan Edison Co. 79704/16 2pp
- --7906290008 "TMI Aquatic Study," monthly rept for Jan 1979 by Ichthyological Associates Inc # Metropolitan Edison Co. 79/01/31 14pp

- --7906290010 "THI Aquatic Study," monthly rept for Feb 1979 by Ichthyological Associates,Inc + Metropolitan Edison Co 79/02/28 17pp
- --7906290011 "TMI Aquatic Study," monthly rept for Mar 1979 by Ichthyological Associates.inc NARDACCI.O A Metropolitan Edison Co 79/03/31 21pp
- 7906260473 Update of TMI-2 ralculations re 790423-26 damage to Zircaloy fuel rod cladding in core
  PICKLESIMER, M Division of Reactor Safety Research 79/05/04
- 7906200254 "TMI Dosimetry Project Rept for Data Collected 790331-0418 "
  \* HEW Dept of, Food & Drug Administration 79/05/07 28pp
- 7906260314 Forwards daily key word in context index from Data Reduction & Mgt Group MEISER, J.L. GPU Service Corp. 79/03/16 2pp
- 7906260343 Forwards graph depicting containment in-leakage rate 790402-0520 KERRIOAN.S Commission 79/05/23 2pp
- 7906220121 Forwards preliminary soils data \$\tau\$ soil boring logs HINTERHALTER, J Gilbert Associates, Inc 79/05/25 25pp
- 7906200429 "Status of TMI Offsite Emergency Radiological Environ Monitoring Program." 790503-30 CERTI.S M Porter-Gerti Consultants, Inc. 79/05/30 75pp
- S Reportable occurrences. LERs & related correspondence
- 7906220202 Submits summary of events 790328-790410 within Middletown Poloce Dept dealing w/incident at TMI MILLER, G M Middletown, PA 79/04/10 app
- 7906290026 Forwards noncompliance rept re pneumatic actuators & solenoid accessories which may not comform to specs Investigation under way to determine similar values KRAUSS:R W OH Bettis Corp 79/04/11 4pp
- 7905040359 Forwards PND-79-67AI.AJ & AK per NRC 790401 ltr transmitting IE Bulletin 79-05 ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/04/30 1p
- 7906220199 Unexecuted draft of notice of 790328 nuclear incident at TMT CHILK, B J Office of the Secretary of the Commission 79/05/02 10pp
- 7906060178 PNO-79-67AN(corrected) summary of info re nuclear incident as of 790514 Describes plant status & environ status PAULUS, R C , THOMPSON, D Office of Inspection & Enforcement 79/05/14 2pp
- 7906190531 Forwards "Interim Rept on TMI-2 Accident "
  HERBEIN, J O Metropolitan Edison Co 79/05/15 1p
- --7906190535 "Interim Rept on TMI-2 Accident " \* Metropolitan Edison Co 79/05/15 200pp
- 7906060101 PND-79-67AD summary of info re nuclear incident as of 770521. Describes plant status & environ status Highest incore temp reading was 301 F Leaks identified & are being corrected in Loop A PAULUS, R C . THOMPSON, D Office of Inspection & Enforcement 79/05/21 Zpp
- 7904060197 PND-79-67AP summary of info re nuclear incident as of 790522, Describes plant & environ status investigation under way to determine if death of cows was caused by radiation FLACK, E. D., CUNNINGHAM, L. J. HIGGINBOTHAM, L. Office of Inspection & Enforcement 79/05/22. 2pp.
- 7906030061 PNO-79-67AG summary of Info re nuclear incident as of 790329. Describes plant & environ status environ radiation levels consistent w/natural levals. PAULUSAR C . THOMPSON, D. Office of Inspection & Enforcement 79/05/29. 2pp
- 7906220133 PNO-79-67AR summary of info re nuclear incident as of 790604 Describes plant status & environ status. Average coolant tamp 157 F
  PAULUS, R.C. THOMPSON. D Office of Inspection & Enforcement 79/06/04. 2pp

- 7906270031 PNO-79-67AS summary of info re nuclear incident as of 790611 Describes plant & environ status Highest incore thermocouple reading is 280 F PAULUSIR C Office of Inspection & Enfarcement 79/06/11 2PP
- 7906270027 PND-79-67AT summary of info re nuclear incident as of 790618 Describes plant & environ status Highest incore thermocouple leading 273 F
  PAULUS.R C Office of Inspection & Enforcement 79/06/18 2pp
- 7906280043 Requests info re hydrogen explosion at TM1-2 MILSTEAD, W C Division of Systems Safety 79/04/18 ip
- 7906280045 Comments on constructive changes to regulatory requirements for nuclear power plants knowledge of reactor vessel water level & gas bubble dispersion need addressing WENZINGER E C Reactor Systems Standards Branch 79/04/18 tp
- T Hearing transcripts on non-antitrust matters
- 7906070012 Forwards transcript of 790405.06 & 09 closed meetings info partially withheld staff and scope of Commission sponsored investigation (ref FOIA Exemption 6) BICKKHIT, L. Office of the General Counsel 79/04/17 App
- 7906220161 Summary of 790417 meeting w/ACRS in Washington,DC re TMT Pp 335-466 \* ACRS - Advisory Committee on Reactor Safeguards 79/04/17 1330n
- 7706070027 Forwards draft cover sheet explaining legal & factual background of TM1 meeting transcripts [ufo partially withheld draft cover sheet (ref FOIA Exemption 5) BICKMIT.L Office of the General Counsel 79/04/18 ip
- 7906110114 Transcript of 790517 public meeting in Washington DC rebriefing on facts of TMI operational sequence Fp 1-108
  Interim operational sequence of events as of 790508 encl
  HENDRIE, J M , GILINSKY, V , KENNEDY, R T Commission 79/05/17
- 7906210014 Forwards site procedures for handling transcript files at YM BINION, T Office of Inspector & Auditor 79/05/24 Spp
- 7906120076 Transcript of ACRS Ad Hoc Bubcommittee on TMI-2 Accident implications 79031 meeting in Washington.DC Pp 1-350 CKRENT.D., CARBON.H W. ETHERINGTON.H ACRB Advisory Committee on Reactor Safeguards 79/05/31 35ipp
- 7906150224 Transcript of Ad Hoc Subcommittee on TMI-2 Accident Implications /90601 meeting in Washington.DC Pp 351-700 Supporting documentation encl DKRENT.D. CARBON.M W. ETHERINGTON.H ACRS Advisory Committee on Reactor Safeguards 79/06/01 400pp
- 7906130214 Transcripts of ACRS Bubcommittee on TMI-2 790606 meeting in Middletown.PA Pp 1-192 CARBON.M N : LAHROSKI:S : BENDER:M ACRS Advisory Committee on Reactor Safeguards 79/06/06 193pp
- 7906150234 Transcript of ACRS Subcommittee on TMI-2 790607 meating in Middletoum.PA Pp 193-405 CARBON.M W . LAHRUSKI.S . BENDER.M ACRS - Advisory Committee on Reactor Safeguards 79706/07 210pp
- 7906180373 Statement by WK Davis, vice-president of Natl Academy of Engineering, re TMI incident DAVIS, WK National Academy of Engineering 79/06/13 6pp
- U Congressional/Executive Correspondence
- 7904060196 Forwards Resolution of Inquiry by Representative J Weaver directing NRC to provide Congress w/complete info on TMI incident, Weaver's press release re-resolution encl KAMMERER, C Office of Congressional Affairs 79/04/02 3pp
- 7906260082 Forwards draft interim response to Congress re TMI incident KENNEKE.A Office of Policy Evaluations. 79/04/04 2pp
- 7906060144 Forwards TMI-related LERs & montly operating repts per 790405 telcon re Senator Hart 790403 ltr MIRAGLIA,F J Office of Nuclear Reactor Regulation 79/04/05 ip
- 7906060194 Forwards draft of JM Hendrie 790410 statement for Subcommittee on Nuclear Regulation of Senate Committee on Environ & Public Works Requests comments. W/o end KAMMERER,C Office of Congressional Affairs 79/04/06 1p

- 906[5023] Transcript of 7904[0 hearing before Senate Subcommittee on Nuclear Regulation re TMI incident Pp. 1-122 NENDRIE, J. M. Commission HART, G., MOYNIHAN, D. Senate, Environment & Public Works 79/04/10 124pp
- 90&070003 Lists congressmen to be notified in case of unexpected TMI events Info partially withheld hame telephone numbers (ref FOIA Exemption 6) KAMMERER, C Office of Congressional Affairs 79/04/11 2pp
- 906210260 Porwards issue brief 1879035 "Nuclear Power TMI Accident & its Investigation"
  DDNNELLY, W H Library of Congress 79/04/26 1p
- -7908210262 Issue bisef 1879035, "Nuclear Power IMI Accident & Its Investigation " DDNNELLY, W H , KRAMER, D S Library of Congress 79/04/19 30pp
- 905:30490 Forwards projected 1980 population distribution for 0-10 miles from TMI, in response to 790415 teleon request GUNNINOHAM. L J Division of Fuel Facility & Materials Safety 79/04/30 7pp.
- '706280062 Discusses congressional task force created to investigate TMI-2 incident Hearings will address TMI,US nuclear policy b waste storage Press release encl
  KAMMERER,C Office of Congressional Affairs 79/05/04 3pp
- '906120010 Transcript of Task Force on TMI Actident hearing before Committee on Interior & Insular Affairs on 790509 in Washington, DC Pp 1-90
  WEAVER, CARR, MAIKEY House of Rep., Interior & Insular Affairs 79/05/09 91pp
- --7906120012 Transcript of task force on TMI accident hearing before Committee on Interior & Insular Affairs on morning of 790511 in Washington DC Pp 1-216 MEAVER, CARR, MARKEY House of Rep , Interior & Insular Affairs 79/05/11 217pp
- --7405120013 Transcript of task force on TMI accident hearing before Committee on Interior & Insular Affairs on afternoon of 790311 in Washington, DC Pp 1-170 WEAVER, VCNTO, MARRIOTT House of Rep , Interior & Insular Affairs 79/05/11 191pp
- --7906120021 Transcript of bask force on TMI accident hearing before Committee on Interior & Insularr Affairs on 790515 in Washington DC Pp 1-145 WEAVER, CARR, MARKEY House of Rep., Interior & Insular Affairs 79705/19 147pp
- --7906120037 Transcript of ACRS Ad Hor Subcommittee on TMI-2 Accident Implications 790601 meeting in Washington DC Pp 351-700 QKRENT, D . CARBON, H H . ETHERINGTON, H . ACRS Advisory Committee on Reactor Safeguards 79/06/01 350pp
- 7906260465 Forwards list of upcoming Congressional hearings & calendar of number assigned to TMI hearing KAMMERER, C Office of Congressional Affairs 79/03/14 App
- 7906260470 Discusses agenda of Udall committee investigation/hearings into TMI incident & nuclear policy issues KAMMERER, C Office of Congressional Affairs 79/05/16 3pp
- 7906260301 Bummary of 790516 meeting w/NRC & govt officials in Hershey, PA to discuss discharge of contaminated water from plant into Susquehanna River WRICHT,J L. Pennsylvania, State of 79/05/17 4pp
- 790A210197 Responds to 790403 ltr re NRC actions following TMT-2 incident. Initial actions included review of possible generic problems. HENDRIE: J M Commission 79/05/18, 4pp
- ---7908210200 Forwards proposed response to G Hart 790518 ltr re state 5 local capabilities to cope w/civilian nuclear accident COLLING.H E Office of State Programs 79/04/05 9pp
- 7906230131 Bubmits summary of info re C Michelson Jan 1978 rept. "Decay Heat Removal During Very Bmall Break LOCA for B&W 205 Fuel Assembly PWR " Forwards related documents MATTSON.R. J. Division of Systems Safety 79/05/24 7pp
- --7906230135 Forwards C Michelson Jan 1978 summary of "Decay Heat Removal During Very Small Break LOCA for B&W 205-Fuel Assembly PWR" EISENHUT, D 9 Division of Operating Reactors, 79/04/17, ip

- --7906230148 Draft "Decay Heat Removal Problem Associated w/Raco.ery From Very Small Break LDCA for Combustion Engineering 5.1s 80 PHR " # 9abcock & Wilcox Co 77/05/31 37pp
- 7904080198 Notifies that transcripts of NRC discussion are not ready & will be sent when available KAMMERER.C Office of Congressional Affairs 77/05/25 ip
- 7906280138 Statement of RH Vollmer before House Subcommittee on Natural Resources & Environ VOLLMER, R H Assistant Director for Site Analysis 79/06/02
- 7906280140 Statement of RC Clusen before House Subcommittee on Natural Resources & Environ CLUSEN,R C Energy, Dept of 79/06/02 14pp
- 7906280141 Statement of EW Bretthauer before House Subcommittee on Science & Technology BRETTHAUER: E Environmental Protection Agency 77/06/02 10pp
- 7906270097 Forwards names of witnesses & panelists for Subcommittee on Natural Resources & Environ 790602 meeting \* House of Rep , Science & Technology 79/06/02 3pp
- 7906290194 Testimony before Subcommittee on Natural Resources & Environ of House Science & Technology Committee on 790662 W/supporting maps, charts & tables MujuGr.y E Netropolitan Edison Co 77/06/02 23pp
- 7906210175 Responds to enc1 790525 itr DDI is willing to cooperate w/NRC to evaluate impact of proposed discharge of treated radwaste wastewater from TMI on Chesapeate Bay wildlife ANDRUS, C D Interior, Dept of 79/06/15 2pp
- 7906220107 Responds to 790507 itr re liquio releases from TMI No water from within TMI-2 containment has been released Release of low level liquid wastes is permitted with the permitted of the percision & Enforcement 79/05/19 2pp
- DOCKET 50-321 EDWIN I HATCH NUCLEAR PLANT, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7906050274 Forwards proposed amends to fire protection Tech Specs covering add1 fire detection instrumentation t water suppression sys MHITMER.C F Georgia Power Co 79/05/29 13pp
- J Insurance & indemnity information
- 7906190307 Forwards Endorsements 40 & 41 to ANI Pulicy MP-78 DUCK.J R Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/96/12 Spp
- P Operating license stage documents & correspondence
- 7906040004 Forwards "Nonroutine Radiological Environ Operating Rept, Anomalous Measurement Rept " MANRY,M Georgia Power Co 79/03/28 ip
- --7906040010 "Nonroutine Radiological Environ Operating Rept. Anomalous Measurement Rept " Corrects errors contained in previously submitted rept \* Georgia Power Co 79/03/26 3pp
- 7906080246 Forwards addl info re trip setpoints, time delay & alternate power supply, requested at 790110 NRC meeting of NRC & util in Bathesda. MD.
  WHITMER.C F Georgia Power Co 79/06/04 Spp
- 7906080295 Bubmits requested info comparing plant design w/NRC-approved Browns Ferry design WHITHER.C F Georgia Power Co 79/06/04 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906070021 Forwards IE Bullstin 79-08. "Events Relevant to BHRs Identified During TMI Incident " Licenses action required O'RETLLY, J P Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7906050003 Ack receipt of IE Insp Repts 50-321/79-09 & 50-366/79-11 No proprietary info STAFFARR. W Georgia Power Co 79/04/19 ip

- 790514-0315 No proprietary info STAFFA,R H Georgia Power Co 79/04/25 lp
- Q Inspection reports, IE Bulletins & correspondence
- --7906140085 Forwards IE Insp Repts 50-321/79-10 & 50-366/79-12 on 790314-0316 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/04/03 2pp
- ---7906140093 IE Insp Repts 50-321/79-10 & 50-366/79-12 on 790314-16 No noncompliance noted Major areas inspected IE circulars & bulletins.LERs & followup of previous insp findings HIRKLEY,D G Region 2. Atlanta, Office of the Director DARICE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 Spp
- 7906140436 Responds to IF Bulletin 79-07 Discusses computer programs used in stess analysis of safety-related piping STAFFA,R W Georgia Power Co 79/04/25 2pp
- 7906130141 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required D'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/05/02 10
- 7906250455 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " D'REILLYJ P Region 2. Atlanta. Office of the Director 79/05/10 ip
- 7906:10065 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REIELY, J P Region 2, Atlanta, Office of the Director 79/05/11 in
- 790A200522 Ack receipt of 790410 & 0508 ltrs informing NRC of steps taken to correct violations noted in IE Insp Repts 50-321/79-08 & 50-366/79-10 LEWIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/05/15 ip
- --7906200527 Responds to NRC 790306 ltr re violations noted in IE lasp Repts 30-321/79-0B % 50-366/79-10 Corrective actions new policy re definition of operability has been established & test results will be reported STAFFA.R W Georgia Power Co 79/04/10 2pp
- --7906200932 Respond to NRC 790424 telcon re violations noted in [E Insp Repts 50-321/79-08 & 50-366/79-10 Corrective actions Tech Specs re inoperability reporting will be followed & test acceptance criteria will be followed STAFFA:R W Georgia Power Co 79/05/08 ip
- --7906200540 Forwards IE Insp Repts 30-321/79-08 & 50-366/79-10 on 761216-19,790101-03 & 0129-0209 & notice of violation D'REILLY.J P Region 2, Atlanta, Office of the Director 79/03/16 2pp

44 Notice of violation from insp on 790216-19,790101-03 & 209 | 1gion 2. Atlanta, Office of the Director 79/03/08 ip

nsp Repts 50-321/79-08 & 50-366/79-10 on 781216-19, 1129-0209 Noncompliance noted failure to rept in core isolation cooling inoperable & failure culation flow coastdown text results Region 2, Atlanta, Office of the Director Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/08 4pp

- 7904080268 Forwards Amend 1 to 780803 inservice insp program, in response to 790528 request WHITMER,C F Georgia Power Co 79/06/06 ip
- ---7906080269 Amené 1 to 780803 inservice insg program # Georgia Power Go 79/06/06 62pp
- R Periodic operating reports & related correspondence
- 7904070377 Forwards Nonroutine Radiological Environ Operating Rept. Anomalous Measurement Rept " MANRY, M Georgia Fouer Co 79/03/26 (p
- 7706130021 Forwards monthly operating rept for Hay 1979 MANRY: M Georgia Power Co 79/06/06 ip

- --7906130023 Monthly operating rept for May 1979 STANCIL.R Georgia Power Co 79/06/02 App
- S Reportable occurrences. LERs & related correspondence
- 7906040299 Forwards LER 79-030/03T-0 MANRY, M Georgia Power Co 79/05/24 1p
- ---7906040304 LER 79-030/03f-0 on 790508 possibility exists for unnecessary trip of plant svc water pumps during LDCA Logic schemes will be modified to distinguish botween loss of sys pressure & diesel test condition GREENE, T V Georgia Power Co. 79/05/24 1p
- 7906140358 RO 50-321/79-36 on 790923 during review of Class IE equipment in drywell. Bechtel noted sciencid on sample isolation valve did not have qualification document for accident conductors No safety harands MANRY. M Georgia Power Co 79/05/24 ip
- 7906060210 Foward LER 79-013/01X-1 MANRY,M Georgia Power Co 79/05/25 ip
- --7906060213 LER 79-013/01x-1 on 790131 scram received on intermediate range monitor Hi-Ki trip at notch 26 of rod 42-15 Gaused by notches being withdrawn past point required to achieve criticality Procedures revised GREENE,T V Georgia Power Co 79/05/25 2pp
- 7906060221 Fowards LER 79-033/011-0 MANRY,M Georgia Power Co 78/05/25 ip
- --7906060222 LER 79-033/01T-O on 790518 RHR return valves E11-F0198 & E11-F017B & RHR pump suction valves leaked during Encal leak rate testing Cause unknown Corrective maint will be performed to allow satisfactory leakage rate GREENE.T V Georgia Power Co 79/05/24 3pp
- 7906060215 Foward LER 79-032/01T-0 MANRY, M Georgia Power Co 79/05/30 1p
- --7906060218 LER 79-032/017-0 on 790516 sprinkler hanger mods indicated seismic design deficiency for cable spreading room sprinkler Caused by lack of detailed seismic analysis Analysis & mods have begun OREENE, T V Georgia Power Co 79/05/30 4pp
- 7906140542 Forwards LER 79-036/01T-0 MANRY,K Georgia Power Co 79/05/30 1p
- --7906140551 LER 79-036/01T-O on 790523 review of Class IE electrical equipment in drywell indicated that solenoid on reactor sample isolation valve B31-F019 was not documented as able to perform under accident condition New model ordered OREENE.T V Georgia Power Co 79/05/30 3pp
- 7906190324 Forwards LER 79-035/03L-0 MANRY,M Georgia Power Co 79/06/07 1p
- --7706190334 LER 79-035/03L-0 on 790521 diesel generator 1A found able to carry less than 50% of rated load Caused by improper alignment of synchronizer gear Gear realigned GREENE, T V Georgia Power Co 79/06/07 lp
- 7906190451 Farwards LER 79-032/01T-1 MANRY,M Georgia Power Co 79/06/07 1p
- --790619046i LER 79-032/01T-1 on 790516 mods indicated seismic design deficiency for cable spreading room sprinkler sys. Caused by failure to perform detailed seismic analysis on designs GREENE.T V Georgia Power Co 79/06/07 2pp
- 7906210165 LER 79-034 has been voided MANRY,M Georgia Power Co 79/06/12 ip
- 7906220179 LER 79-034 has been voided MANRY, M Georgia Power Co 79/06/12 (p
- 79Q6150330 LER 79-016 has been voided • Georgia Power Co 79/06/14 ip
- 7906290297 Forwards LER 79-037/01T-0 MANRY,M Georgia Power Co 79/06/18 1p

POLOGOGO Notification of 790516~17 meeting w/util in Wading River, HY for assessment of plant vital areas 5 to discuss security gregeram WILEGN-J N Light Water Reactors Branch 4 79/05/03 2pp

MO6190001 Responds to 790330 ltr requesting formal guidance on type of loose parts monitoring sys that would be acceptable to NRC forwards draft Reg Ouido 1 133
VARGA.8 A Light Water Reactors Branch 4 79/05/03 14pp

1906:1042: Regards to NRC recuest for analysis re dry storage under optimum moderator conditions Dry storage under such conditions is feasible & k-eff will be less than 0.75 for all values of moderator density NOVARRO, J.P. Long Island Lighting Go. 77/05/09 4pp

170000000000 Notifies that spray norries & spray norrie attachment welds may not have been hydrostatically tested by invoking Code Case 1614 to ASME Section III Change will be incorporated (nto appropriate design specs NOVARRO, J.P. Long Island Lighting Co. 79/05/23 tp

1906060290 Notifies of use of addit matts for component supports & alternate design requirements for bolted joints by invoking Code Case 1694-5 to ASME Baction III Change will be interportated into appropriate design specs

7705120218 Notifies that util has invoked Code Case Ni92 to ASHE Bection III permitting use of fleible metal hose in const of Ciass 1 & 3 piping Change to be incorporated into appropriate design specs & installation documentation NGVARRU. J P | Long Island Lighting Co | 77/05/29 | 1p

7906010201 Forwards /90515 rept, "Add1 Info on Justification of Mark II Lead Plant Safety Relief Valve Load Definition" by S&W, in response to NRC 770427 request MOVARRO, J.P. Long Island Lighting Co. 79/05/30 1p

--7906010203 "Addl Info on Justification of Mark II Lead Plant Safety Relief Valve Load Definition" • Stone & Webster, Inc. 79/05/15 14pp

## Q Adjudicatory correspondence

7903210426 Answers applicant 790205 request for summary disposition of certain contentions Asks that response time as to two admissible contentions, be held in aboyance, pending SER issuance Certificate of Syc and HOEFLING, R K Branch 4 79/02/02 5pp

7903210397 Forwards amend to NRC regulations for physical protection of nuclear power plants (100FR73).effective 790228 HOEFLING.R K Branch 4 79/03/07 6pp

7906040361 Responds to 790327 request Forwards documents on behalf of Buffolk County, NY. W/o encl HOEFLING, R K Branch 4 79/04/02 Zep

7906020223 Forwards IF Bulletin 79-02, "Pipe Support Base Plate Designs Using Contrate Expansion Anchor Bolts "
BORDENICK, D.M. Branch 4 79/04/26, 1p

--7706020226 Responds to 781205 ltr re design deficiencies in support base plates NRC still waiting for StW evaluation of both piping & electrical type supports info will be evaluated as part of continuing safety review

BORDENICK, B M Branch 4 79/01/15 ip

7906130140 Forwards into re provisions insuring safe plant design, spent fuel storage & disposal of radioactive waster in response to 790403 ltr VABSALLO, D.B. Assistant Director for Light Water Reactors 79/05/09 12pp

--7906130132 Opposes licensing of facility because of possibility of accident & lack of answers re storage & disposal of nuclear wastes.

MONTANA-DURN, B Affiliation Unknown 79/04/03 2pp

## H General correspondence

7906070365 Responds to 790403 request for CAO rept EMD-78-110 discussed in 790401 NY Times Rept may be obtained at CAO Washington OC NY emergency response plan has concurrence HOEFLING, R K Branch 3 79/04/13 1p

Q Inspection reports. IE Bulletins & correspondence

7906180394 Forwards IE Info Notice 79-10. "Nonconforming Pipe Support Struts " No written response necessary GRIER.8 H Region i. Philadelphia. Office of the Director 79/04/16 ip

7906110015 Forwards IE Bulletin 79-058. "Nuclear Incident at THI-Suppl " No written response required ORIER.8 H Region 1. Philadelphia, Office of the Director 79/04/23 1p

7906040169 Ack receipt of 790323 ltr informing NRC of steps taken to correct violation noted in IE losp Rept 50-322/79-02 CARLSON,R T Region L Philadelphia, Reactor Construction & Engineering Support Branch 79/04/27 ip

--7906040176 Responds to FIRC 790220 lt; re violation noted in IE [msp Rept 90-322/79-02 Corrective actions records of all welds previously heat treated have been reviewed & engineering evaluation initiated where rates have been exceeded HUFFORD, A W Long Island Lighting Co 79/03/23 2pp

--7908040182 Forwards IE insp Rept 50-322/79-02 on 790122-26 & notice of violation CARLSON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/02/20 2pp

---7906040186 Notice of violation from insp on 790122-26 a Region 1, Philadelphia: Reactor Construction & Engineering Support Branch 79/02/20 1p

--7906040188 IE Insp Rept 50-322/79-02 on 790122-26 Noncompliance noted failure to control post weld heat treatment per applicable ASME III code requirement.
TOTH.A D , DURM.J P Region 1, Philadelphia, Office of the Director MCGAUGHY.R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/02/15 13pp

7906130163 Forwards IR Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No Unitten response required ORIER.B H Region 1. Philadelphia. Office of the Director 79/05/02 ip

7906120166 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

7906260115 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assembles" GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/11 1p

E -

- --7906150420 "Qualification Type Test Rept Limitorque Valve Actuators for Class IE Svc Outside Primary Containment " HESS,T . DENKOHSKI,W . FORMICA.C Limitorque Corp 79/05/02
- --7906150422 "Rept of Seismic Test on SMC-04 Valve Control (Std) "
  \* Pacific Gas & Electric Co 79/03/30 72pp
- --7906190424 "Qualification Rept for Conductor Modules for AK Nuclear One Unit 2 " FEDERICK, H C Limitorque Corp IFS-409 79/03/09 37pp
- 7906190483 Submits addl info re environ qualification of Barton pressure & differential pressure transmitters CRANE,P & Factific Go 79/06/14 ip
- 7908200464 Forwards response to 790314 sequest for additinfo re main steam line break inside containment W/proprietary ½ nonproprietary versions of "Equipment Gualification" & applications for withholding proprietary info CRANE.P A Pacific Gas & Electric Co 79/06/14 ip
- --7906200472 Application for withholding proprietary info from public disclosure Forwards proprietaly & nonproprietary versions of Westinghouse rept. "Equipment Qualification" GRANE.P A Pacific Gas & Electric Co 79706/14 2pp
- ~~7906200480 Nonproprietary version of "Equipment Gualification" \* Hestinghouse Electric Corp 79/06/20 23pp
- 7906180321 Forwards changes to input palameters to correct logic error reported in Westinghouse App K ECCS model Change accounts for heating effect of zircaloy-water reaction CRANE,P A Pacific Gas & Electric Co 79/06/15 3pp
- G Adjudicatory correspondence
- 7906020063 Requests status of OL BROWN.J P Northern California Ecumenical Council 79/03/21 ip
- --7906020067 Requests alternate power sources & conservation measures in Chrin lieu of issuing CP BROWN. J P Northern California Ecumenical Council 79/02/16 fp
- 7906180253 Requests halt to nuclear plant const # Affiliation Unknown 79/04/02 ip
- --7906180237 Recommends postponement of OL issuance until earthquake safety factor is guaranteed BATES:T H . KAPILOFF:L . QAQH:M California, State of 79/04/05 300
- --7906180267 Forwards constituent ltr re facility const near geologic fault Requests any info dealing w/matter ANDREMS,M House of Rep 79/03/23 ip
- ---7906180274 Expresses concern re reactor const near active geologic fault LENABURG, 8 D Affiliation Unknown 79/03/18 ip
- --7906180284 Opposes nuclear facility const PETERS.M Affiliation Unknown 79/04/02 ip
- ---7905180293 Opposes const of facility near active geologic fault SILDER.R Affiliation Unknown 79/04/02 ip
- --7906180309 Requests facility const cease due to possible health hazards REYNOLDS, J. REYNOLDS, P. Affiliation Unknown 79/03/31 is
- ---7906180317 Requests facility const cease WEBSTER Affiliation Unknown 79/04/02 1a
- --7906180328 Requests facility const cease due to radiation hazards. KAMERER, D J Affiliation Unknown 79/04/03 to
- ---7906180333 Expresses concern over const of facility MCCARTHY.K J : CAROTHERS.J Affiliation Unknown 79/04/02 2pg
- 7905140018 Board notification semiscale experiment 8-A7-6 Unanticipated results re cladding temp require further study to determine safety significance Certificate of Byc encl Hearings Division 79/04/05 54pp

- 7906070327 Motion by joint intervenors Scenic Shoreline Preservation Conference, San Luís Obispo Mothers for Peace, S Silver, Ecology Action Club & JJ Forster for withholding of CP Cartificate of Svc enci FLEISCHAKER, D 8 Fleischaker, D 8 PHILLIPS, J R , KRISTOVICH, S Center for Law in the Public Interest 79/04/12 Spp
- 7906010059 Responds to 790331 ltr concerning unresolved questions about low level radiation & nuclear waste disposal Util will submit plans for increasing spent fuel pool storage capacity in near future VASSALLO, D B Assistant Director for Light Water Reactors 79/05/02 200
- 7906020118 Responds to ltr expressing opposition to plant operation because of proximity to active earthquake fault & problem of disposal of wastes Board is in process of preparing decision re plant licensing BOYD.R S Division of Project Management 79/05/04 2pp
- 7906010341 Request by joint intervenors that ASLB reopen evidentiary hearings to address Class 9 accidents 5 emergency planning in alternative, seeks directed certification on related questions Certificate of Svc encl FLEISCHAKER, D S Fleischaker, D S PHILLIPS, J R . KRISTOVICH, S Center for Law in the Public Interest 79/05/09 11pp
- 7906280013 Forwards attachments & orrata sheet to joint intervenors 790509 request to reopen or in alternative request for directed certification Certificate of Svc encl FLEISCHAKER, D S Fleischaker, D S 79/05/10 10pp
- --7905280015 Errata sheet to joint intervenors 790507 request to reopen or in alternative request for directed certification FLEISCHAKER, D. S. Fleischaker, D. S. 79/05/10 2pp
- 7906200238 Comments on Covernor EC Brown 790504 ltr to JM Hendrie Request for extraordinary action of singling out plant for suspension of licensing proceedings is unsubstantiated BONNER, J. F. Pacific Gas & Electric Co. 79/05/ii 2pp
- 7906220491 Responds to 790425 & 26 ltrs re opposition to facility const near Husgri fault No evidence generated in ASLB hearings for earthquakes at Hosgri greater than 7 5 DENTON, H R Office of Nuclear Reactor Regulation 79/05/14 2pp
- 7906260067 Defers ruling on reopening evidentiary hearings until NRC completes rept on effects of TMI on proceeding Other parties will be provided opportunity to respond to rept BOMERS, E.S. Atomic Gafety and Licensing Board Panel 79/06/05
- H General correspondence
- 7906060039 Requests that earthquake potential be considered before granting CP GREEVER, R Affiliation Unknown 79/03/17 3pp
- 7906010297 Discusses reasons for delays in facility const completion, in response to 790328 ltr of concern Verification of ability of plant to withstand possible earthquake is main cause of delay DENTON.H R Office of Nuclear Reactor Regulation 79/04/20 2pp
- ---7906010297 Requests info re delays in completion of const of facility Continued delays only preclude use of alternate energy sources to conserve oil NADEKAMPER.D Affiliation Unknown 74/03/28 ip
- 79D6040101 Objects TH Bates 790405 ltr supporting postponement of GL issuance Supports development of nuclear power CASTALDO, V F Affiliation Unknown 79/04/26 1p.
- --7906040111 Requests OL be denied due to proximity to earthquake zone KLINE, J., WATERHOUSE, H., WATERHOUSE, E. Affiliation Unknown 79/04/26 Spp
- 7906070401 Responds to 790328 ltr responential for delays in issuance of DL decision in order to satisfy antinuclear minority groups concerned resplant ability to withstand effect of earthquakes
  BOYD, R 8 Division of Project Management 79/04/27 2pp
- ---7906070403 Comments on granting of OL operation of plant should not be further postponed to satisfy anti-nuclear minority MILLER.P C Affiliation Unknown 79/03/28 1p
- 7906150252 Requests that CA Public Utils Commission withhold issuance of "certificate of necessity" for plant until Santa Barbara County can devise emergency evacuation plan MCDERMOTT, D. Affiliation Unknown 79/05/01 1p

- F05070308 Ack retript of 790323 ltr re S Lonaburg correspondence Forwards into giving brief history & status of licensing Stochas Wo encl KAPMERER. Office of Congressional Affairs 79/05/02 lp
- \*755140329 Discusses potential for delays in issuance of decision on QC.in order to satisfy antinuclear minority groups BOYD.R 8 Division of Project Management 79/05/04 2pp
- 1706180172 Responds to 790413 ltr re safety considerations involved in CL issuance VASSALLO,D B Assistant Director for Light Water Reactors 79/05/10
- Tablif0123 Responds to 790317 ltr re issuance of CP Forwards info re itructural design, inflation allowances for decommissioning tosts; waste storage, low level radiation effluents % transport of spent fuel EQYD.RS Division of Project Management 79/05/15 App
- J Insurance & indemnsty information
- 7904270241 Forwards Endorsements 59 % 60 to NELIA Policy NF-173 SEGER.R M Northeast Nuclear Energy Co (Northeast Utilities) 79/06/21 3pp
- I inspection reports. IE Bulletins & correspondence
- 7906120047 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Tombiation Support Problem " No action required ENDELMENT H Region 5, San Francisco, Office of the Director 79705/07 1p
- 7905180479 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/10 1p
- 7906080241 Forwards IF Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN, R H Region S. San Francisco, Office of the Director 79/05/18
- 790&130041 Forwards IE Bulletin 79-11, "Paulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENCELKENR H Region 5, San Francisco, Office of the Director 79/03/22 1p
- 7905180374 Forwards IE Bulletin 79-12, "Short Period Scram at DWR Facilities " No written response necessary ENGELKEN R H Region 5, San Francisco, Office of the Director 79/05/31 lp
- S Reportable occurrences. LERs & related correspondence
- 7903040359 Forwards PNO-79-67ALAJ & AK per NRC 790401 itr transmitting IE Bulletin 79-05 ENORLKENR-H Region 5, San Francisco, Office of the Director 79704/30 ip
- --7903040360 PNO-79-67AI summary of info re nuclear incident as of 790428, Describes plant & environ status \* Office of Inspectson & Enforcement 79/04/28 2pp
- 7994180219 Forwards PNO-79-67AN EMBELKEN, R H Region 5, Ban Francisco, Office of the Director. 1 p 79/05/14
- 7906180265 Forwards PND-79-67AO ENGELKEN.R H Region 5. San Francisco, Office of the Director, 79/05/21. 1p
- 7406180338 Forwards PNO-79-67AP
  ENGELKEN, R H Region 5, San Francisco, Office of the Director
  79/05/22 ip
- 7906180364 Forwards PNO-79-67AQ ENGELMENTR H Region 5, Ban Francisco, Office of the Director 79/05/30. 1p.
- 7904:30383 Responds to 790801 ltm Datails corrective actions for two items of noncompliance re-bolting of unistruct saddla brackets & non-Class I conduit crossing over Class I equipment GRANE:P A. Pacific Gas & Electric Co 79/06/04 3pg

- U Congressional/Executive Correspondence
- 7906080199 Forwards ltr from constituent containing Santa Barbara.CA Board of Bupervisors resolution that NRC defer final action re license application until adequate safety checks have been completed. LAGGMARSING R J House of Rep 79/04/24 2pp
- 7906290228 Responds to 790424 ltr forwarding U Schlesinger 790418 ltr re Banta Barbara-CA Board of Supervisors resolution urging NRC to defer final licensing action on faculity until safety can be assured GOSSICK,L V 79/05/25 Office of the Executive Director for Operations
- DOCKET 50-324 BRUNSHICK STEAM ELECTRIC PLANT, UNIT 2 P Operating license stage documents & correspondence
- 7904050147 Summary of 790424 meeting w/otil & GE in Bethesda.MD re resolution of questions on end-of-cycle recirculation pump trip feature Request for addl info encl HANNON J & Operating Reactors Branch 3 (Pre 790425) 79/04/30 4pa
- 7905070386 Forwards Amends 24 & 48 to Licenses DPR-71 & DPR-62. respectively, safety evaluation & notice of issuance & availability IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/05/02
- ~-7906070391 Amends 24 % 48 to Licenses BPR-71 & DPR-62, respectively, providing Tech Specs for protoctive instrumentation associated w/ATMS recirculation pump trip IPPDLITG.TA Operating Reactors Branch 3 (Pre 790625) 79/05/02 68pp
- --7906070400 Safety evaluation supporting Amends 24 \$ 48 to Licenses SPR-71 \$ SPR-62:respectively \* Operating Reactors Branch 3 (Pre 790625) 79/05/02 10pp
- --7906070404 Notice of issuance & availability of Amends 24 & 48 to Licenses DPR-71 & DPR-62:respectively IPPOLITO:A Operating Reactors Branch 3 (Pre 790625) 79/05/02 2pp
- 7906290201 Notification of 790921 meeting w/util in Bothesda.MD to discuss status of seismic reanalysis
  HANNON.J N Operating Reactors Branch 3 (Pre 790625) 77/05/17
- 7906120190 Responds to NRC 790312 ltr re implementation schedule for mods required as result of Mark I program Vent header deflector is only major mod required Schedule encl UTLEV, E E Carolina Power & Light Co 79/05/21
- 7906010240 Requests written confirmation re rayiaw of recirculation pump trip mod
  UTLEY.E E Garolina Power & Light Co 79/09/29 ip
- 7906080263 Requests revisions to radiological effluent Tech Specs Requests implementation of Tech Specs after 791201 UTLEY.E E Carolina Power & Light Co 79/05/31 67pp
- 7906120137 Forwards HG Kreider affidevit requesting that computer listings for ADLPIPE-2, large & small versions, be withheld from public disclosure (ref 10CFR2 790)
  UTLEY,E E Carolina Power & Light Co 79/05/31, ip
- 7906080319 Natifies that control & instrument terminations hylon insulating sleeve did not pass environ testing by Engineers & Contractors, Justification info for continued operation unnecessary

  UTLEY:E E Carolina Power & Light Co 79/08/29. In
- 7906080278 Discusses seismic analysis of safety-related piping Stress verification completed for all Categoy 1 & 2 lines inside containment Stress reanalysis of Category 3 & 4 lines to be completed by 790515
  FURR.8 J Carolina Power & Light Co 79/06/04 10pp

- 7906120393 Notifies of discovery that nylon insulating portions of compression-type termination lugs mfg by AMP. Inc had failed Investigation initiated & permanent solution will be implemented during next refueling outage

  UTLEY.E E Carolina Power & Light Co 79/06/06 2pp
- 7906200348 Discusses results of feedwater & control rod drive return line notice insp UTLEY,E E Carolina Power & Light Co 79/06/14 7pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906180013 Forwards IE Insp Repts 30-324/79-09 & 30-325/79-09 on 790226-0301 No noncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 2pp
- --7906180018 IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790226-0301 No noncompliance noted Major areas inspected periodic refueling tests & preparation for refueling JULIAN.C., GRAMAM.M.J. Region 2. Atlanta, Office of the Olrector MARTIN.R.D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 6pp
- 7906200534 Forwards IE Insp Repts 50-324/79-11 & 50-325/79-11 on 790313-16 No noncompliance noted LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/09 2pp
- --790620054i IE Insp Rept 50-324/79-11 & 50-325/79-11 on 790313-16 No noncompliance noted Major areas inspected refueling maint, fire protection mods, conformance w/Tech Spec aperating limits, neutron source removal & IE bulletins & circulars RILEY, B W Region 2, Atlanta, Office of the Director DANCE, H C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/06 4pp
- 7904070050 Forwards IE Insp Repts 50-324/79-12 & 50-325/79-12 on 790318-22 No noncompliance noted SUTHERLAND, J Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp
- --- 7906070058 IE Insp Repts 50-324/79-12 & 50-325/79-12 on 790318-22 No noncompliance noted Major areas inspected refueling/maint health physics program & radioactive waste mgt program GIBSUN.A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch TROUP.G L Region 2. Atlanta. Office of the Director 79/04/09 6pp
- 7906250361 Farwards IE Insp Repts 50-324/79-13 & 50-325/79-13 on 790327-30 No noncompliance noted LEWIS:R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 2pp
- ---7906250365 IE Insp Repts 50-324/79-13 & 50-325/79-13 on 790327-30 No noncompliance noted Major areas inspected fire protection & safe shutdown sys mods DANCERH C : 00275. J E : RILEY, B H Region 2: Atlanta, Reactor Operations Nuclear Support Branch 79/04/20 3pp
- 7906250367 Forwards IE Insp Repts 50-324/79-15 & 50-325/79-15 on 790402-05 No noncompliance noted LEMIB.R.C Region 2. Atlants. Reactor Operations Nuclear Support Branch 79/04/20 2pp
- ---7906250370 IE Insp Regts 50-324/79-15 & 50-325/79-15 on 790402-05 No noncompliance noted Major areas inspected complex Tech Spec surveillance tests & pipe support & restraint sys MARTIN:R D . BROOKS.E H Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/19 3pp
- 79060201B1 Responds to IE Bulletin 79-0B of events relevant to BWRs identified during TMI Investigative team has been established to review util's nuclear plant designs & operating procedures to ensure continued safety FURR.B.J Carolina Power & Light Co 79/04/23 17pp
- 7906130134 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required G'REILLY, J P. Region 2, Atlanta, Office of the Director 79/03-02. 1p
- 7906210096 Forwards affidevits for withholding info required in response to IE Bulletin 79-07.Requests that computer listings designated as Attachment 1 of 790424 ltr be withheld (ref 10CFR2 790).

  UTLEY.E E. Carolina Power & Light Co 79/05/04 Bpp

.

- 7906230440 Forwards IE lnfo Notice 79-12. "Attempted Damage to New Fuel Assemblies" O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 lp
- 7906110059 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required D'REILLY. J.P. Region 2, Atlanta, Office of the Director 72005(1)
- 790A080146 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-02 & 50-325/79-02 LEMIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/09/14 1p
- --7906080151 Responds to NRC 790221 ltr re violations noted in IE Insp Repts 30-324/79-02 & 50-325/79-02 Corrective actions review of safety-related sys will be made & QA manual revised FURR.B J Garolina Power & Light Co 79/04/20 3pp
- 7906140491 Responds to IE Bulletin 79-08 re implications of TM1 incident on BURs No Tech Bper changes required FURR.B J Carolina Power & Light Co 79/09/15 ip
- 7906250300 Notification of 790916 meeting w/utils in Bethesda.MD to discuss status of seismic reanalysis per 1E Bulletin 79-07 HANNON, J. Operating Reactors Branch 3 (Pre 790625) 79/09/19
- 7706270717 Responds to IE Bulletin 79-07 No OE type AK-2 circuit breakers used in safety-related sys UTLEY KE Carolina Power & Light Co 79/05/18 ip
- 7906230017 Responds to IE Bulletin 79-10 re operating requalification training programs W/Table 1 containing info requested in Items 1-5 UTLEY, E E Carolina Power & Light Co 79/05/24 3pp
- 7906040221 Forwards addl info in response to IE Bulletin 79-07 reseismmic pipe stress analysis as requested by NRC at 790821 meeting Wisupporting documentation UTLEY.E E Carolina Power & Light Co 79/05/29 23pp
- R Periodic operating reports & related correspondence
- 7906140444 Forwards monthly operating rept for May 1979 BANKB, H R Carolina Power & Light Co 79/06/11 1p
- --7906140449 Monthly operating rept for May 1979
  WILLISE Carolina Power & Light Co 79/06/04 18pp
- S Reportable occurrences, LERs & related correspondence
- 7904190340 Forwards LER 79-004/03L-0 FURR.B J Carolina Power & Light Co 79/02/27 ip
- ---7906150341 LER 79-006/03L-0 on 790131 while performing high drywell pressure functional check of core spray HPCI & LPCI A loop RHR logic failure alarm received Caused by blown fuse in P617 TOLLISON, A C Carolina Power & Light Co 79/02/27 1p
- 7906040153 Forwards 14-day radiological environ event rept on 790508-09 event reulted from valve laft open after tank transfer-causing release into reactor bldg through looss access cover Tank transfer procedure revised BANKS, H R Carolina Power & Light Co 79/05/22 App
- 7906140297 Confirms 790525 telcon w/EH Verdery re deficient mylon insulating sleave reported per IE Bulletin 79-01, "Environ Qualification of Class IE Equipment," LER to be submitted within 14 days ...
  TOLLISON:A C Ceroline Power & Light Ca 79/05/29 1p
- 7906140351 Confirms 790525 telcon w/MT Cottle re hanger supports in main steam safety relief & HPCI sys not meeting requirements of IE Bulletin 79-07 re seismic stress analysis LER to be submitted within 14 days
  TOLLISON
- 7906140391 Confirms 790325 telcon w/NRC re immediately reportable event per IE Bulletin 79-01 re Class IE equipment Inadequate nylon insulating sleeves may have been used LER will be submitted within 14 days

  TCLLISON,A C Carolina Power & Light Co. 79/05/29. 1p

- 7906080316 Submits 14-day radiological environ event rept suppl Shipment of radwaste loft site by sole-use vehicle on 790503.w/radiation levels up to 20 millirems/h incident to be reviewed BANKS, H R Carolina Pawer & Light Co 79/06/01 2pp
- 7904070279 Forwards LER 79-036/03L-0
  BANKB, H R Carolina Power & Light Co 79/06/04 ip
- --770&070202 LER 77-034/03L-0 on 790507 while performing visual insp of inaccessible snubbers, six snubber failed Caused by low fluid level All snubbers disassembled, inspected & rebuilt TOLLBON.A C Carolina Power & Light Co 79/06/04 ip
- 7906070283 Forwards LER 79-027/03L-0 BANKS, H R Carolina Power & Light Co 79/06/04 1p
- --7906070271 LER 79-027/03L-0 on 790307 while performing switch calibr. Itmit switches found out of tolerance Caused by incorrect Initial adjustment Switches roadjusted & checked YOLLISON.A C Carolina Power & Light Co 79/06/04 ip
- 7904080249 Forwards LER 79-024/03L-0 BANKS,H R Caroling Power & Light Co 79/04/05 1p
- --7906080250 LER 79-026/03L-0 on 790507 analyzer 02 was 1-CAC-ATH-1259;2 was reading upscale on 0-5T scale, when actual reading was 18 5% on 0-29% scale Caused by split rubber hose leading from air sample injet fitting Tube repaired TOLLIBON, A C Carolina Power & Light Co 79/06/04 1p
- 7906120422 Forwards LER 79-031/03L-0
  BANKS, H R Carolina Fower & Light Co 79/06/07 ip
- --7406120424 LER 79-031/03L-0 on 790910 while performing leak rate test, discovered four MBIVs exceeded leakage rate Caused by cracks in stellite Disks replaced Valves reassembled & tested satisfactorily TOLLISON, A C Cerolina Power & Light Co 79/06/07 ip
- 7986110228 Forwards LCR 79-028/03L-0 BANKB, It R Carolina Power & Light Co 79/06/08 ip
- --7906110232 LER 79-028/03L-0 on 770510 south torus hatch was open during reactor startup for physics testing following refueling outage Caused by operating procedure deficiency Procedures to be revised to require visual insp
  TOLLISON, A C Carolina Power & Light Co 79/06/08 2pp
- 7906120382 Forwards LER 79-034/03L-0 BANKS, H R Carolina Power & Light Co 79/06/08 ip
- --7906120388 LER 79-034/03L-0 on 790510 while performing PT 20 3, primary containment isolation valve local leak rate test containment isolation valves would not seat 5 hold pressure Caused by valve bushing wear, Valves distanted & bushings replaced TOLLISON, A C Garolina Power & Light Co. 79/06/08 ip
- 7906150177 Forwards LER 79-024/03L-0
  BANKS H R Carolina Fower 2 Light Co 79/06/08 ip
- --7906150183 LER 79-024/03L-O on 790510 drywell equipment drain recorder was driving downscale & integrator was driving backward Caused by air trapped in transmitter bellows & sensing lines Bellows & lines vented TOLLISON: A C Carolina Power & Light Co 79/06/08 19
- 7996180509 Forwards LER 79-033/03L-0 BANKB H R. Carolina Power & Light Co 79/06/13 lp
- --7904180514 LER 79-033/03L-0 on 790518 HPCI turbine tripped on mechanical overspeed at 3,500 rpm Caused by spring adjusting screw being approx five turns out of position Set screw for securing spring adjusting screw was approx six turns out. TOLLISON, A C Carolina Power & Light Co 79/04/13 2pp
- 7906220370 Forwards LER 79-035/03L-0 BANKG.H R Carolina Power & Light Co. 79/06/15 ip
- --7906220375 LER 79-035/03L-0 on 770521 during startup from refueling outage, discovered that mod to rod lock monitor was neither approved nor installed Mod approved & installed Procedures being written to prevent recurrence TOLLISON: A C. Carolina Power & Light Co 79/06/15 2pp
- 7906220406 Forwards LER 79-03B/03L-0 BANKB, H. R. Carolina Power & Light Cg 79/06/15 1p.

- --7906220409 LER 79-038/03L-0 on 790521 when diesel generator 3 speed was lowered to 60 hert; per second, engine "failed to start" alarm energized making generator inoperable Caused by upward drift in airpox tachometer switches Saitches recalibr TOLLISON.A C Carolina Power & Light Co 79/06/15 1p
- 7906220413 Forwards LER 79-037/03L-0 BANKS: H R Carolina Power & Light Co 79/06/15 1p
- --7908220420 LER 79-037/03L-O on 790519 control panel instrument 2-CAC-ATH-1263-2 gave downscale reading & 2-CAC-ATH-1239-2 was out of calibr Caused by being out of calibr Both instruments recalibr & returned to svc TOLLISON.A C Carolina Power & Light Co 79/06/15 1p
- 7906220398 Forwards LER 79-039/03L-0
  BANKS,H R Carolina Power % Light Co 79/06/18 ip
- --7906220400 LER 79-039/03L-0 on 790519 leak rate test on airlock not completed within 72-h Causud by administrative oversight Test completed satisfactorily TOLLIBON.A C Carolina Power & Light Co 79/06/18 ip
- 7906270167 Forwards LER 79-023/01T-0 FARR B J Carolina Power & Light Co 79/06/22 1p
- --7906270169 LER 79-023/017-0 on 790608 failure of any electrical components in bypass circultry could prevent isolation signal from closing containment isolation valves Wiring removed between override logic circuit & isolation valves TOLLISON, A C Carolina Power & Light Co 79/06/22 Zpp
- 7906270199 Forwards LER 79-043/03L-0 FURR.B J Carolina Power & Light Co 79/06/22 12
- --7906270201 LER 79-043/03L-O on 790525 drywell floor drain integrator 2016-FT-N013 discovered out of calibr Caused by warter in transmitter Transmitter drained.calibr & returned to svc TOLLIBON, A C Carolina Power & Light Co 79/06/22 1p
- 7906290356 Forwards LER 79-041/01T-0
  BANKS,H R Carolina Power & Light Co 79/06/26 1p
- --7906270362 LER 79-041/01T-O on 770612 during normal operation, reactor scrammed due to NSIV problem & after scram MSIV indications were de-energized Caused by power lead to do solenoid of 2821-F0220 terminating at ac solenoid Wiring corrected TOLLISON, A C Cerolina Power & Light Co 79/06/26 2pp
- DDCKET 50-325 BRUNSWICK STEAM ELECTRIC PLANT, UNIT 1
  P Operating license stage documents & correspondence

--;

7906070386 Forwards Amends 24 & 48 to Licenses DPR-71 & DPR-62, respectively, safety evaluation & notice of issuance & availability [PPOLITO.T A Operation Reactors Branch 3 (Pre 790625) 79/05/02 [3pp]

- --7906120164 Affidavit requesting computer listings for ACLPIPE-2.large & small versions, be withheld from public disclosure (ref 10CFR2 790)
  KREIDER, H G United Engineers & Constructors, Inc (subs of Raytheon Co ) 79/05/23 app
- 7906080315 Notifies that control & instrument terminations nylon insulating sleeve did not pass environ testing by Engineers & Contractors Justification info for continued operation unnecessary

  UTLEY.E E Carolina Power & Light Co 79/05/29 1p
- 7906080278 Discusses seismic analysis of safety-related piping Stress verification completed for all Categoy 1 & 2 lines inside containment Stress reanalysis of Category 3 & 4 lines to be completed by 790615 FURR: B J Carolina Power & Light Co 79/06/04 10pp
- 7906120393 Notifies of discovery that nylon insulating portions of compression-type termination lugs mfg by AMP, Inc had failed Investigation initiated & permanent solution will be implemented during next refueling outage

  UTLEY.E E Carolina Power & Light Co 79/06/06 2pp
- 7906200348 Discusses results of feedwater & control rod drive return line nozzle insp UTLEY.E E Carolina Power & Light Co 79/06/14 7pp
- G Inspection reports: IE Bulletins & correspondence
- 7906180013 Forwards IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790226-0301 No noncompliance noted LEMIS.R C Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/03/26 2pp
- --7906180018 IE Insp Repts 50-324/79-09 & 50-325/79-09 on 790226-0301 No noncompliance noted Major areas inspected periodic refueling tests & preparation for refueling JULIAN.C , GRAHAM.M J Region 2, Atlanta, Office of the Director MARTIN.R D Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 6pp
- 7906200534 Forwards IE Insp Repts 50-324/79-11 & 50-325/79-11 on 790313-16 No noncompliance noted LEHIS.R G Region 2. Atlanta. Reactor Operations Nuclear Support Branch 79/04/07 2pp
- ---7906200541 IE Insp Rept 50-324/79-11 & 50-325/79-11 on 790313-16 No nancompliance noted Major areas inspected refueling maint, fire protection mods.conformance u/Tech Spec operating limits, neutron source removal & IE bulletins & circulars RILEY, B W Region 2, Atlanta, Office of the Director DANCELH C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/06 4pp
- 7906070050 Forwards IE Insp Repts 50-324/79-12 & 50-325/79-12 on 790318-22 No noncompliance noted SUTHERLAND.J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/10 2pp

- 7906020181 Responds to IE Bulletin 79-08 re events relevant to BWRs identified during TMI Investigative feam has been established to review util's nuclear plant designs & operating procedures to ensure continued safety FURR.8 J Carolina Power & Light Co 79/04/23 17pp
- 7906130154 Forwards IE Circular 79-07, "Unorpected Speed Increase of Reactor Hotor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLYJ P Region 2, Atlanta, Office of the Director 79/05/02 ip
- 7906210076 Forwards affidavits for withholding info required in response to IE Bullstin 79-07 Requests that computer listings designated as Attachment 1 of 790424 ltr be withheld (ref 100fR2 790) UTLEY,E E Carolina Power & Light Co 79/05/04 Bpp
- 7906250440 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 in
- 7906110059 Forwards 1E Bulletin 79-10. "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/11 ip
- 7906080146 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-324/79-02 & 50-325/79-02 LEHIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/14 is
- --7906080151 Responds to NRC 790221 ltr re violations noted in IE Insp Regts 50-324/79-02 & 50-328/79-02 Corrective actions review of safety-related sys will be made & GA manual revised FURRB J Carolina Power & Light Co 79/04/20 3pp
- 7906140491 Responds to IE Bulletin 79-08 ro implications of TMI incident on DWRs No Tech Spec changes required FURR, B J Carolina Power & Light Co 79/05/15 1p
- 7906250300 Notification of 790516 meeting w/utils in Bethesda,MD to discuss status of seismic reanalysis per IE Bulletin 79-07 MANNON,U Operating Reactors Branch 3 (Pre 790623) 79/05/15
- 7906290719 Responds to IE Bulletin 79-09 No GE type AK-2 circuit breakers used in safety-related sys UTIEV, E E Carolina Power & Light Co 79/09/18 ip
- 7906230017 Responds to IE Bultetin 79-10 re operating requalification training programs H/Table 1 containing info requested in Items 1-5
  UTLEY, E E Carolina Power & Light Co 79/05/24 3pp
- 7906040221 Forwards add1 info in response to IE Bulletin 79-07 re seismmic sipe stress analysis, as requested by NRC at 790521 meeting H/supporting documentation UTLEY, E E Carolina Power & Light Co 79/05/29 23pp
- R Periodic operating reports & related correspondence
- 7906140444 Forwards monthly operating rept for May 1979 BANKS, H R Carolina Power & Light Co 79/06/11 1p
- --7906140449 Monthly operating rept for May 1979
  WILLIS.E Carolina Power & Light Co 79/06/04. 18pp
- 9 Reportable occurrences, LERs & related correspondence
- 7906040133 Forwards 14-day radiological environ event rept on 790508-09 event reulted from valve left open after tank transfer.causing release into reactor bldg through loose access cover Tank transfer procedure revised BANKS,H R Carolina Power & Light Co 79/05/22 App
- 7905050239 Forwards LER 79-024/03L-0.
  BANKS, H R Carolina Power & Light Co 79/05/29 1p
- --7906050262 LER 79-024/03L-0 on 790430 while performing chlorida intrusion monitor calibr & functional chack: 1-CDD-CURS-1 would not provide alarm function Caused by break in contact wiper assembly from mechanical wear TOLLISON: A C. Carolina Power & Light Co. 79/05/29 ip

- 7906140297 Confirms 790925 telcon w/EH Verdery re deficient nylon insulating sleeve reported per IE Bulletin 79-01, "Environ Qualification of Class IE Equipment " LER to be submitted within 14 days
  TOLLISON A C Carolina Power & Light Co 79/05/29 1p
- 790&140331 Confirms 790825 teleon w/WT Cottle re hanger supports in main steam safety relief & HPC1 sys not meeting requirements of IE Bulletin 79-07 re seismic stress analysis LER to be exhalited within 14 days
  TOLLISON
- 7906140391 Confirms 790525 telcon w/NRC re immediately reportable event per IE Bulletin 79-01 re Class IC equipment Inadequate nylon insulating sleeves may have been used LER will be submitted within 14 days
  TOLLIEGN.A C Carolina Power & Light Co 79/05/29 1p
- 79Q6050305 Forwards LER 79-028/03L-0
  BANKS,H R Carolina Power & Light Co 79/06/01 1p
- --7904050308 LER 79-028/OSL-0 on 790904 during reactor startup, operator had neither "full in" nor "full out" indications on rod 22-47 "Qut" indication now works & no problem found Rod can not presently be driven in to check "in" indication TOLLISON, A C Carolina Power & Light Co 79/06/01 ip
- 7904050328 Forwards LER 79-027/03L-0
  BANKB,H R Carolina Power & Light Co 79/04/01 ip
- --7706050332 LER 79-027/03L-0 un 770503 reactor core isolation cooling inboard steam isolation valve 1-EB1-F007 failed to open cause undetermined Valve was cleaned, stroked & returned to operation TOLLISON.A C Carolina Power & Light Co 79/06/01 ip
- 7904080314 Submits 14-day radiological environ event rept suppl Ehipment of radwaste left site by sole-use vehicle on 790503.w/radiation levels up to 20 millirems/h Incident to be reviewed BANKS.H R Carolina Power & Light Co 79/06/01 2pp
- 7906110176 Forwards LER 79-040/01T-0 BANKS.H R Carolina Power & Light Co 79/06/QB 1p
- --7906110188 LER 79-040/01T-0 on 790525 during reanalysis of safety-related piping sys.88 hanger supports did not have required seismic capacity Some 48 hangers supports have been strengthened to required capacity Further rept to follow TOLLISON,A C. Carolina Power & Light Co 79/06/08 2pp
- 7905110189 Forwards LER 79-034/03L-0 BANKS.H R Carolina Power & Light Co 79/06/08 lp
- --7906110192 LER 79-034/03L-0 on 790510 drywell equipment drain recorder was driving downscale & integrator was inoperative during performance of normal operator surveillance on control panel. Caused by motor drive amplifier transistor failure TOLLISON, A C Carolina Power & Light Co 79/06/08 ip
- 7906130167 Forwards LER 79-030/03L-0
  8ANKS:H R Carolina Power & Light Co 79/06/08 1p
- ~-7905:150:174 LER 79-030/03L-0 on 790508 while returning main steam line flow switch back to svc, switch indication pegged high; indicating nonexistant excessive steam flow Caused by plugged line Line reopened & instrument returned to svc TQLLISON, A C. Carolina Power & Light Co 79/06/08 2pp
- 7906130197 Forwards LER 79-031/03L-0 BANKS: H R Consumers Power Co 79/06/08, 1p.
- ~~7706150201 LER 79-031/03L-0 on 790512 while performing normal surveillance, oxygen level in drywell found greater than 4% Caused by GAC-ATH-1257 out of calibr instruments recalibr & returned to svc.
  TOLLISON, A C Carolina Power & Light Co 79/06/08 ip
- 7906150237 Forwards LER 79-041/01T-0 BANKS, H R Carolina Power & Light Co 79/06/08, ip
- ---7906150241 LER 79-041/017-0 on 790825, certain nylon insulation sleeve portions of compression type termination lugs did not meet environ qualification tests Each druwell termination will be checked for deterioration & safety assurance TOLLISON, A C Carolina Power & Light Co. 79/06/08 2pp
- 7706150245 Forwards LER 79-033/03L-0.
  BANKS, H R Carolina Fawer & Light Co. 79/04/08 1p.

- --7906150250 LER 79-033/03L-0 on 790513 unable to perform daily surveillance to verify that power ratio & peaking factor do not exceed specified values Caused by computer analog scanning sys Sys calibr & returned to svc
- 7906140312 Forwards LER 79-037/03L-0 BARKS.H ft Carolina Power & Light Co 79/06/12 1p
- --7906140314 LER 79-037/03L-0 on 790315 average power range monitor A
  upscale rod block alarm out of spec high Caused by
  instrument drift Instrument setpoint lowered
  TOLLIBON A C Carolina Power & Light Co 79/06/12 2pp
- 7906140527 Forwards LER 79-032/03L-0
  BANKS: EL R Garolina Power & Light Co 79/06/12 ip.
- --7906140533 LER 79-032/03L-0 on 790514 while performing Penetrant Test
  10 1 law reactor core isolation cooling component test. IE
  51-F048 steam supply did not work Caused by motor burning up
  for upskipum reason
  TOLLIGON, A C Carolina Power & Light Co 79/06/12 2pp
- 7906200366 Forwards LER 79-039/03L-0
  BANKB:# R Carolina Power & Light Co 79/06/15 ip
- --790620036/ LER 79-039/03L-0 on 790517 coolant sample line isolation valves would not close Caused by solanoids stuck in open position & control switches of sample station shorted Bolenoids were cleaned & returned to sec TOLL180N.A C Carolina Power & Light Co 79/06/15 2pp
- 7906220312 Forwards LFR 79-019/03L-0
  8ANKE. H R Carolina Power & Light Co 79/06/15 ip
- --7906220300 LER 79-019/03L-0 on 790520 operator noted recorder 1-CAC-TR-1258 for printing containment pressure was not working Caused by burned Gould part TF255-C-C & stuck contacts in K-3 relay Relay replaced TDCLLEON, A C Carolina Power & Light Co 79/06/15 1p
- 7906220316 Forwards LER 79-026/03L-1 BANKS, H R Carolina Power & Light Co 79/06/15 lp
- --7906민20대가 LFR 79-026/03L-1 on 790507 during normal operation oxygen analyzer indicated high oxygen concentration Caused by split hose from air sample inlet fitting Tubing repaired & replaced \* Carolina Power & Light Co 79/06/15 1p
- 7906220284 Forwards LER 79-014/03L-0
  BANKS: H R Carolina Power & Light Co 79/06/18 iP.
- --7906220274 LER 79-014/03L-0 on 790319 operator noted containment atmosphere dilution less than 4,350 Caused by frozen pressure control valve Regulator on pressure control valve adjusted TOLLISON.A C Carolina Power & Light Co 79/06/18 PP
- 7906280129 Forwards LER 79-027/03L-1
  BANKB, H R Carolina Power & Light Co 79/06/25 1p
- --7906280131 LER 79-027/03L-1 on 790303 reactor core isolation cooling imboard steam isolation valve 1-RS1-F007 would not open Cause not ascertained Breaker for F007 valva cycled several times locally & auxiliary contacts cleaned TOLLIGON. A C Cerolina Power & Light Co 79/06/25 1ρ
- 7906280084 Forwards LER 79-018/03X-1 BANKS, H R Carolina Power & Light Co 79/06/26 ip
- ~~7906280088 LER 79~018/03X-1 on 790414:main steam relief valve IB21~F013J opened at 520 pai during plant startup. Valve immediately reseated. Possible cause may be excessive pilot or second stage seat leakage TOLLIBON.A C Carolina Power & Light Co 79/06/26 2pp
- 7906280098 forwards LER 79-019/03K-1 BANKB, N R Caroline Power & Light Co 79/06/26 1p.
- --790AR80101 LER 79-019/03X-1 on 790320 during normal operation, recorder 1-CAC-TR-1288 was not working Caused by burnt K-3 relay & stuck contacts Relay replaced & recorder returned to operation TORLEBON-A.C Caroline Power & Light Co 79/06/26. 1p.

- --7906290333 LER 79-043/03L-0 on 790609 during normal reactor startup, control rad drive 18-23 had no indication at notch 30 Logic checked correctly Drywell instrumentation will be checked during neit outage
  TQLLISQN:A C Garolina Power & Light Co 79/06/27 IP
- 7906290366 Forwards LER 79-039/03L-0 BANKS.H R Caralina Power & Light Co 79/06/27 1p
- --7906290371 LER 79-039/03L-0 on 790613 during normal operation, 18 standby gas train de-anergized for approx 40 minutes Caused by hot spot breater for 18 reactor water cleanus pump causing feeder from E-6 to 18f to trip Breaker removed TOLLISON, A C Carelina Power & Light Co 79/06/27 2gp
- DOCKET 50-326 UNIV OF CALIFORNIA AT INVINE RES REACTOR

  J Insurance & Indemnity Information
- 7906260395 Forwards executed Amend 8 to Indemnity Agreement E-16, Amend 4 to Indemnity Agreement E-58, Amend 8 to Indemnity Agreement E-53 & Amend 13 to Indemnity Agreement E-15 DENESS.S J California, Univ of, Berkeley 79/06/21 5pp
- G Inspection reports, IE Bulletine & correspondence
- 790&0101&4 Act receipt of 79041& ltr informing NRC of steps taken to correct violations noted in IE insp NDRDEMAUG.L R Region 5. San Francisco. Safeguards Branch 79704/27 1p
- 7905180450 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" No written response necessary ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/10 ip
- 7906080234 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " ENGELERIR H Region 5. San Francisco, Office of the Director 79/05/18 ip
- DOCKET 50-327 SEQUOYAH NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7904100243 Forwards & discusses proposed agenda for 790402-04 site visit to trace representative protection sys channels Early stage of const prevented tracings during last visit LAGHER, DR Electric. Instrumentation & Control Systems Branch 79703/19 4pp
- 7904:30347 Suggests comparison of "insp" & "licensing review" facets of visit proposed in Lasher 790319 memo Requests brief analysis of agenda items re time spent on review suitability of work for inspector & expected resultant "insp rept"

  HANAUER.S H

  Assistant Director for Plant Systems 79/03/21, 1p
- iquests approval of flexible metal hose for use as ited piping by 790615 Forwards data demonstrating w/Reg Ouide 1 84 & ASME code applications in Case Code M-192

  1.E. Tennessee Valley Authority 79/05/21 300pp
  - tifies that responses to five gestechnical engineering ransmitted in 790322 Itr are included in Amend 61
  - E Tennessee Valley Authority 79/05/30 is
- '906260463 Forwards add1 info re seismic qualification data package in response to 790425 talcon request GILLELAND:U E Tennessee Valley Authority. 79/06/22 72pp
- Security, medical, emergency & fire protection plans
- 704080241 Forwards revisions to radiological emergency plan OILLELAND, J.E., Tennessee Valley Authority. 79/04/06. 200pp
- Insurance & indemnity information
- 04010278 Forwards executed Amends 12 & 3 to Indminity Agreements 8-52 b 8-82 respectively.

  PARRIGH 9. Tennessee Valley Authority. 79/03/27. 2pp

- 7906120274 Forwards MAELU Binder XB-66, including declarations & bond for payment of retrospective premiums DUCK, J.R. Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/06 App
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906220339 Forwards affidavit certifying that copies of Amend 61 to PSAR were mailed to intended individuals on 790613
  HILLS.L M Tennessee Valley Authority 79/06/18 2pp
- O Inspection reports. IE Bulletins & correspondence
- 7906180050 Forwards IE Insp Rept 50-327/79-18 un 790306-08 No noncompliance noted LEMIS, C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 2pp
- --7906150052 IE Insp Rept 50-327/79-18 on 790306-08 No noncompliance noted Major areas inspected fire protection & prevention procedures BRADFORD,W H , KELLOGG,P J Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/22 App
- 7906180720 Furwards IE Insp Repts 50-327/79-12 & 50-328/79-07 on 790205-07 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/26 2pp
- ---7906180731 IE Insp Repts 30-327/79-12 % 50-328/79-07 on 790205-07 No noncompliance noted Major areas inspected deficient areas noted in previous insp.including concrete cells in pumping station access roadway MCFARLAND,C R Region 2, Atlanta, Office of the Director HERDT.A R Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 6pp
- 7906010029 Forwards IE Insp Repts 30-32//79-17 & 50-328/79-10 on 790309-12 No noncompliance nated MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906010034 IE Insp Repts 50-327/79-17 & 50-328/79-10 on 790309-12 No noncompliance noted Major areas inspected test surveillance & progress of installation of safety-related major mechanical components in reactor bldgs.

  VALLISH,E J Region 2, Atlanta, Office of the Director BRYNNI, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 Spp
- 790607D156 Forwards IE Insp Repts 50-327/79-20 & 50-328/79-11 on 790326-29 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/10 2pp
- --7906070162 IE Insp Repts 50-327/79-20 & 50-328/79-11 on 790326-29 No noncompliance noted Major areas inspected inspector followup items & QA audits by TVA Const Div HERDT:A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch MAGFARLAND,C R. Region 2, Atlanta, Office of the Director 79/04/10 Spp
- 7906210299 Forwards IE Insp Rept 50-327/79-19 on 790313-16 No noncompliance noted LEWIB:R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/17 2pp
- --7706210304 IE Insp Rept 30-327/79-19 on 770313-16 No noncompliance noted Major areas inspected preoperational test witnessing, containment integrated leak rate test observation & independent verification of test data

  BONAT.T. WHITENER,H Region 2. Atlanta, Office of the Director DANGE.H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 77/04/12 12pp
- 7906040370 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-327/79-08 & 50-328/79-04 MWRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/25. 2pp
- --7906040375 Responds to NRC 790314 ltr re violations noted in IE Insp Repts 50-327/79-08 & 50-328/79-04. Corrective actions missing pipe caps replaced, & uncovered carbon steel ropes & stends covered witape GILLELAND, J & Tennessee Valley Authority, 79/04/05. 3pp
- --7906040377 Forwards IE Insp Repts 50-327/79-08 & 50-328/79-04 on 790130-0201 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch, 79/03/14, 3pp

- --7906040382 Notice of violation from insp on 790130-0201 \* Region 2, Atlanta, Offica of the Director 79/03/14 1p
- --7906040387 IE Insp Repts 50-327/79-08 & 50-328/79-04 on 790130-0201
  Nuncompliance noted failure to follow procedure for
  handling & protection of stainless attel piping
  VANDDORN, P K Region Z, Atlanta, Office of the Director
  CONLON, T E Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 79/03/09, 5pp
- 7706070384 Forwards IE Insp Rept 50-327/79-24 on 790411-13 No noncompliance noted MENNA, W B Region 2, Atlanta, Bafeguards Branch 79/04/25 2pp
- --7906070390 IE Insp Rept 50-327/79-24 on 790411-13 No noncompliance noted Major areas inspected security plan.security Organization, barriers, access controls, lock & key control, & detection aids Details withheld (ref 10CFR2 790)
  TOBIN, W. J. Region 2, Atlanta, Bafeguards Branch BESECKER, K. H. Region 2, Atlanta, Office of the Director 79/04/25 1p
- 7906270131 Requests info re consideration given to possible pressure spikes in ice condenser containment plants per IE Bulletin 79-06A. Revision 1
  WILLIAMS.F.J. Division of Project Management 79/05/09 1p
- 7906210078 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related sys Effort in progress to locate any AGME 8A-3121 Type 304 piping supplied by Youngstown Welding & Engineering Co OILLELAND, J E Tennesses Valley Authority 79/05/14 19
- 7906260267 Requests response to IE Bulletin 79-06A \$ 79-06A, Revision 1
  Also requests assessment & response to ACRE ltrs re
  recommendations resulting from TMI-2
  VARQA. B A Light Water Reactors Branch 4 79/06/01 2pp
- 7906280094 First interim deficiency rept incorrect Velan valve weights used in seismic piping analysis Final response to IE Bulletin 79-04 will be submitted before fuel load in Unit I
  OILLELAND, J E Tennesses Valley Authority 79/06/22 1p
- 3 Reportable occurrences, LERs & related correspondence
- 7906140442 Final deficiency rept bistable contacts in auxiliary room loops of pressuritor power relief valves failed in Unidersirable position Valve wiring corrected No other discrepancies found

  \*\* Tennessee Valley Authority 79/05/10 ip
- 7906140364 Submits second interim deficiency rept tensile anchor capacities lower than assumed in design allowables, initially reported on 790212 Stud anchor testing underway, complete anialysis to be submitted before Unit i fuel load OIELELAND, J E Tennessee Valley Authority 79/05/14 ip
- 1904080275 Forwards revised corrective action section to 790510 final deficiency rept re failure of control loop bistable on loss of gower OFLLELAND, J E Tennessee Valley Authority 79/05/31 1p
- -790 6080281 Revised 790510 final deficiency rept re control loop bistable failure on loss of power Revision specifies that wiring diagrams for bistable have been corrected & physical wiring will be corrected --Tenhessee Valley Authority 79/05/31 ip
- '906200342 Forwards interim rept re design basis accident movements of steel containent not properly accounted for in design Naxt rept will be made by 790109 OFLLELAND. JE Tennessee Valley Authority 79/06/11 4pp
- 906200438 Submits third interim deficiency rept re vibration in RHR piping initially reported 790208 Possible to avoid operational modes that result in unacceptable cavitation across valves Operating mode recommendations being developed OILLELAND, J. F. Tennessee Valley Authority 79/06/11 ip
- 906200382 Forwards finel deficiency rept re overstressed penetrations
  in containment shell
  GILLELAND, J E Tennessee Valley Authority 79/06/15 ip
- -7906200383 Finel deficiency reptroverstrassed penetrations in containment shell. Design drawings are being revised to move snubbers & secure them between piping & steel containment Mods will be performed prior to respective fuel load dates. Tennessee Valley Authority, 79/06/15. Ip

- 7906250269 Forwards final deficiency rept re-pipe restraint structural strand temp GILLELAND.J E Tennessee Valley Authority 79/06/1B 1p
- --7906250272 Final deficiency rept pipe restraint structural strand temp Pipe thermal insulation being redesigned to provide horizontal V-notch configuration in areas where strands are in close proximity to pipe

  \* Tennessee Vallay Authority 79/06/18 3pp
- 7906270224 Forwards revised final deficiency rept re-motor operated valve control circuit failures
  GILLELAND, J E Tennessee Valley Authority 79/06/20 19
- --7906270226 Revised final deficiency rept motor operated valve control circuit failure Relay failure could have triggered events deactivating part of one train of safety sys Relays will be subjected to burn-in period

  \* Tennessee Valley Authority 79/06/20 2pp
- 7906270274 Forwards first interim deficiency tept re flexible bellows penetrations of steel containment vessel misaligned during installation GILLELAND.J E Tennessee Valley Authority 77/06/25 1p
- --7906290316 First interim deficiency rept during hat functional preoperational testing, removal of bellows restraints revealed misalignment Caused by faulty installation sequence Bellows reinstalled # Tennessee Valley Authority 79/06/25 2pp
- DOCKET 50-328 SEQUOYAH NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7904100243 Forwards & discusses proposed agenda for 790402-04 site visit to trace representative protection sys channels Early stage of const prevented tracings during last visit LASHER.D R Electric, Instrumentation & Control Systems Branch 79/03/19 4pp
- 7904130347 Suggests comparison of "insp" & "licensing review" facets of visit proposed in Lasher 790319 memo Requesta brief analysis of agenda (tems rm time spent on review.switability of work for inspector & expected resultant "insp rept" HANAUER,S H Assistant Director for Plant Systems 79/03/21 lp
- 7906040204 Requests approval of flexible metal hose for use as safety-related piping by 790615 Forwards data demonstrating compliance w/Reg Guide t 84 / ASHE code applications addressed in Case Code N-192 GILLELAND. J E Tennessee Valley Authority 79/05/21 300pp
- 7906060293 Natifies that responses to five geotechnical engineering questions transmitted in 790322 ltr are included in Amend 61 of FBAR OILLELAND, J E Tennessee Valley Authority 79/05/30 1p
- 7906260463 Forwards addl info re seismic qualification data package in response to 790425 telcon request
  OILLELAND: J E Tenneseer

- 7906010029 Forwards IE Insp Repts 50-327/79-17 & 50-328/79-10 on 790309-12 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906010034 IE Insp Repts 50-327/79-17 & 50-328/79-10 on 790309-12 No noncompliance noted Major areas inspected test surveillance & progress of installation of safety-related major mechanical components in reactor bldgs VALLISH.E J Region 2, Atlanta, Office of the Director BRYANT.J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 3pp
- 7904070134 Forwards IE Insp Repts 50-327/79-20 & 50-328/79-11 on 790326-27 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 2pp
- --7906070162 IE Insp Repts 50-327/79-20 & 50-328/79-11 on 790326-29 No noncompliance noted Major areas inspected inspector followup items & 9A audits by TVA Const Day HERDITAR Region 2. Atlanta. Reactor Construction & Engineering Support Branch MACFARLAND.C R Region 2. Atlanta, Office of the Director 79/04/10 Bpp
- 7904040370 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations nated in IE Insp Repts 50-327/79-08 & 50-328/79-04 MURPHY.C E Regian 2. Atlanta. Reactor Construction & Engancering Support Branch 79/04/25 2pp
- --790&040375 Responds to NRC 790314 ltr re violations noted in 1E Insp Repts 50-327/79-08 & 50-328/79-04 Corrective actions missing pipe caps replaced. & uncovered carbon steel ropes & stands covered w/tape GILLELAND, J E Tennessee Valley Authority 79/04/05 3pp
- --7906040377 Forwards IE Insp Repts 50-327/79-08 & 50-328/79-04 on 790130-0201 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/14 3pp
- ~~7906040382 Notice of violation from insp on 790130-0201 \* Region 2. Atlanta. Office of the Director 79/03/14 1p
- --7906040387 IE Insp Repts 50-327/79-08 & 50-328/79-04 on 790130-0201
  Noncompliance noted failure to follow procedure for
  handling & protection of stainless steel piping
  VANDOURN.P K Region 2, Atlanta, Office of the Director
  CONLON.T E Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 79/03/09 3pp
- 7906270131 Requests info re consideration given to possible pressure spikes in ice condenser containment plants per IE Bulletin 79-064. Revision 1
  HILLIAMS.F.J. Division of Project Management 79/05/09 1p
- 7708210078 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related sys Effort in progress to locate any ASME 8A-3121 Type 304 piping supplied by Youngstown Welding & Engineering Co GILLELAND, JE Tennessee Valley Authority 79/05/14 ip
- 7706260267 Requests response to IE Bulletin 79-06A & 79-06A. Revision 1 Aiso requests assessment & response to ACRS 16rs re recommendations resulting from TMI-2 VARGA:8 A Light Water Reactors Branch 4 79/06/01 2pp
- 7906280094 First interim deficiency rept incorrect Velan valve weights used in seismic piping analysis Final response to IE Bullatin 79-04 will be submitted before fuel load in Unit i
  GILLELAND, J.E. Tennessee Valley Authority 79/06/22, ip
- S Reportable occurrences, LERs & related correspondence
- 7906140442 Final deficiency rept bistable contacts in auxiliary room loops of pressurizer power relief valves failed in understrable position. Valve wiring corrected No other discrepancies found

  \* Tennessee Valley Authority 79/05/10 ip
- 7906140364 Submits second interim deficiency rept tensile anchor capacities lower than assumed in design allowables. Initially reported on 790212 Stud anchor testing underway, complete analysis to be submitted before Unit I fuel load GILLELAND. J E Tennessee Valley Authority. 79/05/14. 19

- 7906080275 Forwards revised corrective action section to 790510 final deficiency rept re failure of control loop bistable on loss of power OILLELAND, J E Tennessee Valley Authority 79/05/31 lp
- The second secon
- --7906080281 Revised 790510 final deficiency rept re control loop bistable failure on loss of power Revision specifies that wiring diagrams for bistable have been corrected & physical wiring will be corrected \* Tennessee Valley Authority 79/05/31 ip
- 7906200342 Forwards interim rept re design basis accident movements of steel containent not properly accounted for in design Next rept will be made by 790109

  GILLELAND, J E Tennessee Valley Authority 79/06/11 4pp
- 790620043B Submits third interim deficiency rept re vibration in RHR piping initially reported 79020B Possible to avoid operational modes that result in unacceptable cavitation across valves Operating mode recommendations being developed OILLELAND. J F Tennessee Valley Authority 79/06/11 lp
- 7706200382 Forwards final deficiency rept re overstressed penetrations in containment shell OILLELAND, J E Tennessee Valley Authority 77/06/15 1p
- --79062003B3 Final deficiency rept overstressed penetrations in containment shell Design drawings are being revised to move snubbers & secure them between piping & steel containment Mods will be performed prior to respective fuel load dates \* Tennessee Vailey Authority 79/06/15 ip
- 7906230269 Forwards final deficiency rept re pipe restraint structural strand temp GILLELAMBIJE Tennessee Valley Authority 79/06/18 1p
- --7906250272 Final deficiency rept pipe restraint structural strand temp Pipe thermal insulation being redesigned to provide horizontal V-nutch configuration in areas where strands are in close proximity to pipe

  \* Tennessee Valley Authority 79/06/18 3pp
- 7906270224 Forwards revised final deficiency rept re motor operated valve control circuit failures
  GILLELAND, J E Tennessee Valley Authority 79/06/20 1p
- ~~7906270226 Revised final deficiency rept motor operated valve control circuit failure Relay failure could have triggered events deactivating part of one train of safety sys Relays will be subjected to burn-in period
  \* Tennessee Valley Authority 79/06/20 2pp
- 7906290274 Forwards first interim deficiency ropt re flexible bellows penetrations of steel containment vessel misaligned during instaliation
  CILLELAND.JE Tennessee Valley Authority 79/06/25 1p
- --7906290316 First interim deficiency rept during hot functional preoperational testing removal of beliows restraints revealed misalignment Caused by faulty installation sequence Bellows reinstalled \* Tennessee Valley Authority 79/06/25 2pp
- DOCKET 50-329 MIDLAND PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7904210346 Forwards second round questions ra FSAR review Major areas covered are environ qualification of safety-related equipment, response time testing & post-accident monitoring equipment requirements
  SATTERFIELD, R M Electric, Instrumentation & Control Systems
  Branch 79/03/20 13pp
- 7906140623 Cancels 790309 meeting w/util in Hethesda. MD re status of safety & environ review schedule
  HOOD.D S bight Water Reactors Branch 4 79/03/23 ip
- 7906010085 Notification of OL application Requests advice re add1 certifying action REGANN WH Environmental Projects Branch 2 79/05/01 4pp
- 7906070185 Forwards util positions re implementation of Reg Guides 1 1, 1 4,1 7,1 13,1 25,1 42,1 52,1 54 t 1 70, scheduled to be discussed in NRC 751219 meeting Reg Guide 1 4 encl BAUMAN,R C Consumers Power Co 78/11/07 3pp

\$290\$26 Summary of 790419-20 meeting w/util Bechtel & B&W in ethesds.MD re open items in review of FSAR COD.D Light Water Reactors Branch 4 79/05/15 30PP

\$210140 Requests two controlled copies of site emergency plan & epiementing procedures site maps showing location & grid tation numbers of onsite & affsite environ monitoring tations & maps used for offsite dose determination EPPLER, J G Region 3. Chicago, Office of the Director 79/05/17 ip

t070077 Requests review of possibility of requiring banks of ressuriser heaters to be classified as safety sys
ANAS.O Plant Systems Branch 79/05/29 2pp

±070263 Forwards Revision 1 to 790424 response to 100FR50 54 request e plant fill
MELLS H Consumers Power Co 79/05/31 22pp

\$150205 Describes statu of efforts by 8%H &" Bechtel to ungrade tater banks 5 % 6 of each pressurizer to Class IE QWELL.8 H Consumers Power Co 79/06/08 2pp

\$190203 Requests that sections/chapters of FSAR be evenly edistributed to comply w/Revision 21
ASTLEBURY, R. L. Bechtel Power Corp (subs. of Dechtel Corp.)
7/05/12 1p

i280161 Submits quarterly rept per ALAB-106 ½ Amend 1 to CP iscusses const work performed on site.QA qualifications of its supervisors & changes in personnel CMELL&B H Consumers Power Co 79/06/25 12pp

NGC Safety Evaluation Report (SER), suppls & correspondence

4160286 Forwards Plant Sys SER input Protection against dynamic ffects of piping rupture spent fuel storage, fuel handling ts.chemical & vol control sys, auxiliary & area ventilation is fire protection sys still unresolved ANAUER, S. H. Assistant Director for Plant Systems 79/03/20

## #4judicatory correspondence

t010272 Responds to 790409 order scheduling 790501 as date for rehearing conference & argument re applicant's motion or summary disposition Supports applicant's motion detificate of Syc encl
PTELF, DAVIS.R L Dow Chemical Co 79/04/25 Spp

#050030 Request by intervenors, other than Dow Chemical Co.to astheouse probability conference & briefing due to anflicting obligations Link.P. Affiliation Unknown 79/04/27 ip

#6550|60 Forwards motion by all intervenors other than Dow Chemical s.for rescheduling of prehearing conference If motion is 'enled.will appeal to ASLAB for emergency relief LYPN.P Checry, M M /Cherry, Flynn & Kanter 79/04/27 2pp

M140278 Mation by intervenors other than Dow Chemical Co for eacheduling of 790501 prehearing conference Requests later late & relocation of conference to Chicago, IL Certificate of low encl
LYMMLF Cherry, M M /Cherry, Flynn & Kanter 79/04/27 4pp

\*\*O6140286 Motion by intervenors other than flow Chemical Co for ASLAB assue order directing ASLB to reschedule & relocate 790501 prehearing conference. Certificate of Svc encl Cherry. M M / Cherry, Flynn & Kanter 79/04/24 4pp

4030394 Confirms events of 790430 & 790801 re request for astheduling of prehearing conference Bince ABLB conference lef begun not possible for ABLAS to act on request for learning relief.

AFLO.M.E Atomic Bafety and Licensing Appeal Panel 79/05/02

MO40426 Defers 790330 motion for summary disposition by util isheing further discovery, adopts five issues defining waters in controversy, requests NRC review & report on the reanners' contentions & orders preservation of evidence (ILLER, ME Atomic Safety and Licensing Board Panel 79/05/03

\*\*S180612 Requests second extension of time for filing rept of former issed in special proceeding in util hearing on possible iggelatory improvements for handling disciplinary matters \*\*CALE\_V B Volentine B Deale 79/05/04 ip

- 7906140460 Notice of appearance in remand proceeding on behalf of Dow Chemical Co Certificate of Syc and POTTER, W.C. Fischer, Franklin, Ford, Simon & Hogg 79/05/08 3pp
- 7906230016 Notifies of taking of depositions re 790503 order of J Hanes PF Orrefice DA Duran A Klomparens L Nute N Wessel J Temple R Renfrow J Falahee, J Bacon AH Aymond & D Rosso Certificate of Svc enci OLMSTEAD, W J Branch 4 79/05/10 4pp
- --7906230021 Requests add1 review of record by 790608 to identify all items within scope of 790503 order directing NRC to re-examine intervenor contentions, charges & allegations OLMSTEAD:N J Branch 3 79/05/10 2pp
- --7906230026 Requests add1 review of record by 790608 to identify all items within scope of 790303 order directing NRC to re-examine intervenor contentions, charges % allegations GLMSYEAD: H J Branch 4 79/03/10 2pp
- --7906230029 Requests add1 review of record to identify all items within scope of 790503 order directing NRC to re-examine intervenor contentions charges & allegations OLMSTEAD: U Branch 4 79/05/10 2pp.
- 7906210255 Orders extension of time until 790608 for NRC consideration of ALAB-541 CHILK.S J Office of the Secretary of the Commission 79/05/25 lp
- 7906290678 Opposes delay in OL review process DEMLOW, D J Michigan, State of 79/05/30 ip
- 7706270684 Requests meeting to resolve differences over const schedule >> completion date Opposes delay in licensing proceedings CALDWELL, B G Dow Chemical Co 77/05/30 ip
- I Financial information
- 7906010160 Ack receipt of 790328 itr re possible sale of shares in facility Action is recommended by ASLB & currently pending No formal application has been received to date BRADFORD, P A Commission 79/04/23 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7706050214 Forwards Amend 65 for application for CP & QL.consisting of Revision 21 to F5AR HQHELL,S H Consumers Power Co 77/05/31 2pp
- ~-7906030220 Amend 65 to application for CP & CL.consisting of Revision 21 to FBAR • Consumers Power Co 79/05/31 1000pp
- 7906:90448 Forwards Certificate of 8vc for Amand 65 to util application for CP & PL.consisting of Revision 21 to FBAR BACON, J L Consumers Power Co 79/06/13 2pp
- O Inspection reports, IE Bulletins & correspondence

7906040404 Fors 781201-28 No FIORELLI,0 Support Pra

- --7906040411 1b Insp Repts 50-327//0-23 9 50 50-7/0 and 51 incompliance noted Hajor areas inspected elevation mismatch in core flood systdiasel generator hldg.makeup feed pumps & reactor coolant pump motors COOK,R J. KNOP.R C. Region 3, Chicago. Office of the Director 79/03/22 Spp.
- 7906130123 Forwards IE Insp Repte 50-329/79-05 \$ 50-330/79-05 on 790405 No noncompliance noted FIORELLI, G Region 3. Chicago, Office of the Director 79/04/19 2pp
- --7906130127 IE Insp Repts 50-329/79-05 & 50-330/79-05 on 790405, No noncompliance noted Major areas inspected review of licenses corrective actions related to repts on undersized welds YIN; I T. Region 3. Chicago, Office of the Director 79/04/18 5as
- 7906250150 Forwards IE Insp Rept 50-329/79-08 & 50-330/79-08 on 790102-31 No noncompliance noted.
  FIORELLI, 0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/27. 2pp

- --7906250155 IE Insp Rept 50-329/79-08 & 50-330/79-08 on 790102-31 No noncompliance noted Hajor areas inspected site conditions & inadequate review of seismic & environ component qualification test data KNOP.R C . COOK.R J Region 3. Chicago, Office of the Director 79/04/25 App
- 7906120100 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07 in
- 7906190087 Forwards IE Info Notice 79~12. "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3. Chicago: Office of the Director 79/05/11
- 7906200021 Responds to IE Bulletin 79-03, "Lungitudinal Weld Defects in ASME 86-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Melding & Engineering Co " Spools may be in use Final rept to be submitted by 790718 HOHELLS H Consumers Power Co 79/05/14 1p
- 7906130093 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Bys " Licensee action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/22
- 7906250149 Requests page 2 of Insp Repts 50-329/79-09 & 50-330/79-09 be replaced w/encl FIORELI,O Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/05/23 is
- 7904200107 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creet Reactor " KEPPLER, J O Region 3, Chicago. Office of the Director 79/05/29 io
- S Reportable occurrences, LERs & related correspondence
- 7906190232 Notifies of receipt of 790430 interim rept re settlement of dissel generator foundations & bldg Will review matter upon receipt of final rept FIGRELLI.G Region 3. Chicago. Office of the Director 79/05/17
- 7906220176 Ack receipt of 790504 interim rept re component testing Will complete review upon receipt of final rept FIORELLI, G Region 3. Chicago, Office of the Director 79/05/18 is
- 7906230067 Ack receipt of util 790501 rept concerning reactor bldg spray piping supports Telcon repts of installed hangers at variance widesign drawings will necessitate further review FIORELLI, G. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/23 ip
- 7906220393 Forwards 790607 interim deficiency rept re discrepancies found in soldered components of J201 main control panel QA program mgt corrective action rept encl HOMELLIS H Consumers Power Co 79706/20 2pp
- ---7906220363 Interim deficiency rept on 790529 five loose wire terminations found on status display panel modules of main control panel Caused by insufficient mfg & insp procedures insp procedures being upgraded

  Bechtel Power Corp (subs of Bechtel Corp)
  - 904t3 interim deficiency rept re unacceptable in feedline pipe spools ers Power Co 79/04/20 4pp
- --7906220377 Interim Deficiency Rept 1 from 790226-0301 audit, nine pipe spools failed to meet ASME physical impact requirements Caused by failure to follow ASME Charpy impact procedures Next interim rept scheduled for 790715 ANDERBONJ M Bechtel Power Corp (subs of Bechtel Corp) 79/06/13 3pp.
- T. Hearing transcripts on non-antitrust matters
- 7904290522 Deposition of AH Aymand on 790530 in Jackson, HI Pp 1-86 AYMOND, A H Consumers Power Ca 79/05/30 86pp
- 7906290517 Deposition of JL Bacon on 790531 in Jackson,MI Pp 1-244 BACONJ,L Consumers Power Co 79/05/31 244pp

- 7906290933 Deposition of RC Youngdahl on 790611 in Washington DC Pp 1-147
  YOUNGDAHL, R C Consumers Power Co 79/06/11 147pp
- DOCKET 50-330 HIDLAND PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7904210346 Forwards second round questions re FSAR review Major areas covered are environ qualification of safety-related equipment response time testing & post-accident monitoring equipment requirements

  EATTERFIELD, R M Electric, Instrumentation & Control Systems

  Branch 79/03/20 13pp
- 7906140623 Cancels 790509 meeting w/util in Bothesda.MD re status of safety & environ review schedule HOOD.D S Light Water Reactors Branch 4 79/03/23 1p
- 7906010085 Notification of QL application Requests advice re addicertifying action REGAN.W H Environmental Projects Branch 2 79/05/01 4pp
- 7906070185 Forwards util positions re implementation of Reg Guides 1 1, 1 4, 1 7, 1 13, 1 25, 1 42, 1 32, 1 34 % 1 70, schoduled to be discussed in NRC 751219 meeting Reg Guide 1 4 encl BAUMAN,R C Consumers Power Co 78/11/07 3pp
- 7906290626 Summary of 790419-20 meeting w/util Bechtel & B&W in Bethesda,MD re open items in review of FSAR HOOD, D Light Water Reactors Branch 4 79/05/15 30PP
- 7906210140 Requests two controlled copies of site emergency plan & implementing procedures, site maps showing location & grid station numbers of onsite & offsite environ monitoring stations & maps used for offsite dose determination KEPPLER, J G Region 3. Chicago, Offsice of the Director 79/05/17
- 7906070077 Requests review of possibility of requiring banks of pressurizer heaters to be classified as safety sys. LAINAS.G Plant Systems Branch 79/05/29 2pp
- 7906070263 Forwards Revision 1 to 790424 response to 10CFR50 54 request re plant fill HOWELLE H Consumers Power Co 79/05/31 22pp
- 7906150285 Describes statu of efforts by BbW &" Bechtel to upgrade heater banks 5 % & of each pressurizer to Class IE HOWELL,S H Consumers Power Co 79/06/08 2pp
- 7906190235 Requests that sections/chapters of FBAR be evenly redistributed to comply w/Revision 21 CABTLEBURY, R. L. Bechtel Power Corp (subs of Bechtel Corp.) 79/06/12 1p
- 7906280161 Submits quarterly rept per ALAB-106 & Amend 1 to CP Discusses const work performed on site 0A qualifications of site supervisors & changes in personnel HOMELL 8 H Consumers Power Co 79/06/25 12pp
- E NRC Safety Evaluation Report (SER), supply & correspondence
- 7904160286 Forwards Plant Sys SER input Protection against dynamic affects of piping rupture spent fuel storage. Fuel handling sys.chemical & vol control sys. auxiliary & area ventilation sys fire protection sys still unresolved HANAUER. S H Assistant Director for Plant Systems 79/03/20 Sipp
- 9 Adjudicatory correspondence
- /906010272 Responds to 790409 order scheduling 790501 as date for prehearing conference & argument re applicant's motion for summary disposition Supports applicant's motion Certificate of Syc enci NUTE, L. F. DAVIS.R. L. Dow Chemical Co. 79/04/25 Spp
- 7905050030 Request by Intervenors other than Dow Chemical Co.to reschedule prehearing conference & briefing due to conflicting obligations
  FLYNN,P Affiliation Unknown 79/04/27 ip
- 7906050160 Forwards motion, by all intervenors other than Dow Chemical Co. for rescheduling of prehearing conference if motion is denied, will appeal to ABLAB for emergency relief FLYNN.P Cherry. M M /Cherry. Flynn & Kanter 79/04/27 2pp

- TF26140286 Hotion by intervenors other than Dow Chemical Co for ASLAB issee order directing ASLB to reschedule & relocate 790501 Prehearing conference Certificate of Svc encl t Cherry, M H /Cherry, Flynn & Kanter 79/04/24 4pp
- \*\*1350374 Confirms events of 790430 & 790501 re request for \*\*satteduling of prehearing conference Since ASLB conference 113 begun not possible for ASLAB to act on request for stergency relief C.FLO.H E Atomic Safety and Licensing Appeal Panel 79/05/02
- PSC40426 Defers 790330 motion for summary disposition by util larging further discovery, adopts five issues defining fatters in controversy, requests NRC review & report on "litereners' contentions & orders preservation of evidence "ILLER.H E Atomic Bafety and Licensing Board Panel 79/05/0 79/05/03
- This BOOL 2 Requests second extension of time for filing rept of former braid in special proceeding in util hearing on possible regulatory improvements for handling disciplinary matters ISALE, V 8 Valentine 8 Dealo 79/05/04 p
- Tible(Deco Notice of appearance in remand proceeding, on behalf of Dow Leverral Co Certificate of Svc encl Filtran C Fischer, Franklin, Ford, Simon & Hogg 79/05/08 3pp
- T15230916 Notifies of taking of depositions re 770503 order of J ha-es.PF Orrefice.DA Duran: A Klomparens L. Nute: M Wessel. J Teasle:R Renfrow. J Falahee. J Bacon: AH Aymond & D Rosso fertificate of Svc onci JMSTEAD: M J Branch 4 79/09/10 4pp
- --TPC&230021 Requests add1 review of record by 790608 to identify all items within scope of 790503 order directing NRC to re-eladine intervenor contentions, charges & allegations CLMSTEAD: W J Branch 3 79705710 2pp
- --770623-0026 Requests addit review of record by 790608 to identify all items within scope of 790503 order directing NRC to re-examine intervenor contentions:charges & allegations DLMSTEAD.W J Branch 4 79/05/10 2pp
- --776230027 Requests add1 review of record to identify all items within scope of 770503 order directing NRC to te-pramine intervenor contentions charges & allegations CLMSTEAD.W J Branch 4 79/05/10 2pp
- F54210255 Orders extension of time until 790608 for NMC presideration of ALAB-541 Office of the Secretary of the Commission 79/05/25
- ፕሪሬ<mark>ደዋዕ678 Opposes delay in OL review process</mark> ውይካኒውሐው J Michigan, State of 79/05/30
- FDA2TOSB4 Requests meeting to resolve differences over const schedule a coepietion date Opposes delay in licensing proceedings CALDMELLS G Dow Chemical Co 79/09/30 ip
- | Financial information
- 1955010160 Ack receipt of 790328 ltr re possible sale of shares in facility Action is recommended by ASLB & currently pending No fermal application has been received to date 25ADFORD.P A Commission 79/04/23 2pp
- g Utility Final Safety Analysis Report (FSAR) & amends
- 7506050214 Forwards Amend 65 for application for CP & OL. consisting of garlsion 21 to FBAR HOMELLIB H Consumers Power Ca 79/05/31. 2pp
- -- 7905050220 Amend 65 to application for CP & DL. consisting of Revision 22 to FBAR • Consumers Power Co, 79/05/31 1000pp.
- 7906190448 Forwards Certificate of Svc for Amend 65 to util application for CP & PL. consisting of Revision 21 to FBAR #ACOM: J L Consumers Power Co. 79/06/13. 2pp

## O Inspection reports: IE Bulletins & correspondence

- 7906040404 Forwards IE Insp Repts 50-329/78-23 & 50-330/79-23 on 781201-28 No noncompliance noted FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/03/26 2pp
- --7906040411 IE Insp Repts 50-329/78-23 & 50-330/78-23 on 781201-28 No voolutil it insp Repts 50-329/78-23 to 30-330/78-23 on 78:201 moncompliance noted Major areas inspected elevation mismatch in core flood sys.diesel generator bldg.makeup feed pumps & reactor coolant pump motors COOK.R J. KMOP.R C Region G. Chicago, Office of the Dir 79/03/22 Spp Region 3. Chicago, Office of the Director
- 7906130123 Forwards 1E Insp Repts 50-329/79-05 % 50-330/79-05 on 790405 No noncompliance noted FIDRELLI, 9 Region 3, Chicago, Office of the Director 79/04/19
- --7906130127 IE insp Repts 50-329/79-05 & 50-330/79-05 on 790405 No noncompliance noted Major areas inspected leview of licensee corrective actions related to repts on undersized welds YIN, I T Region 3. Chicago, Office of the Director 79/04/18
- 7906250150 Forwards IE Insp Rept 50-329/79-09 & 50-330/79-08 on 790102-31 No noncompliance noted
  FIORELLIO Region 3. Chicago, Reactor Construction & Engineering
  Support Branch 79/04/27 2pp
- --7906250189 (E Insp Rept 50-329/79-08 & 50-330/79-08 on 790102-3) No noncompliance noted Major areas inspected site conditions & inadequate review of seismic & environ component qualification test data KNOP.R C . CODK.R J Region 3. Chicago. Office of the Director 79/04/25 App
- 7905120100 Forwards [E. Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J. G. Region 3. Chicago. Office of the Director 79/05/07
- 7906190087 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11
- 7906200021 Responds to IE Bulletin 79-03. "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Melding & Engineering Co " Spools may be in use Final rept to be submitted by 790718
  HQHELL/8 H Consumers Power Co 79/05/14 ip
- 7904130093 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Bafety Sys " Licenses action required Region 3. Chicago, Office of the Director 79/05/22 KEPPLFR. J G

16220353 Forwards 790607 interim deficiency rept re discrepancies found in soldered components of J201 main control panel QA roogram mgt corrective action rept encl (OMELL, 8 H Consumers Power Co 79/06/20 2pp

'906220363 Interim deficiency rept on 790529 five loose wire terminations found on status display panel modules of main control panel Caused by insufficient mfg & insp procedures Insp procedures being upgraded ANDERSON, J M Bechtel Power Corp (subs of Bechtel Corp) 79/06/07 3pp

)4220371 Forwards 790613 interim deficiency rept re unacceptable impact values of main feedline pipe spools (OMELL, 8 H Consumers Power Co 79704/20 4pp

7906220377 Interim Deficiency Rept 1 from 790226-0301 audit nine pipe spools failed to meet ABME physical impact requirements Caused by failure to follow ASME Charpy impact procedures Nart interim rept scheduled for 790715 ANDERSON, J M Bechtel Power Corp (subs of Bechtel Corp ) 79706/13 3pp

Hearing transcripts on non-antitrust matters

06290522 Deposition of AH Aymond on 790530 in Jackson MI Pp 1-86 AYMOND: A H Consumers Power Co 79/05/30 86pp

7906290517 Deposition of JL Bacon on 790531 in Jackson, M1 Pp 1-244 BACON, J L Consumers Power Co 79/05/31 244pp

7906290533 Deposition of RC Youngdahl on 790611 in Washington,DC Pp 1-147 YDUNQDAHL,R C Consumers Power Co 79/06/11 147pp

DOCKET 50-331 DUANE ARNOLD ENERGY CENTER

F Security, medical, emergency & fire protection plans

7906150199 Forwards "Fire Hazards Analysis " LIU.L lowa Electric Light & Power Co 79/06/07 ip

--7906150204 "Fire Hazards Analysis" prepared by Bechtel \* Iowa Electric Light & Power Co 79/06/30 180pp

7905270150 Forwards modified physical security plan Plan withheld (ref 106782 790) ROOT.L.D Ipus Electric Light & Power Co 79/04/22 1p

J Insurance & indemnity information

'06150316 Forwards executed Amend 6 to Indemnity Agreement B-68 SECKMAN, P E I lowa Electric Light & Power Co 77/06/11 3pp

ndorsements 41 & 42 to NELIA Policy NF-214 & 5 to MAELU Policy MF-72 in: Newman. Reis, Axelrad & Toll 79/06/11 Spp

## documents & correspondence

- 7906210333 "Rept of Metallurgical Examination & Stress Evaluation of Rectroviation inlet Nozzie Safe-End Cracking," Rept IE-116 WEIBS,8. DEAN,R S. FOLEY,W J. Parameter, Inc. NRC-05-77-186 79703/16. 35pp
- --7906210339 "Finel Rept on Examination of Incomel Safe-End From Duane Arnold " PASUPATHI,V , SMITH,G P , FARMELO,D R Battelle Memorial Institute, Columbus Laboratories BCL-385-9 79/01/31 45pp
- 7906020171 Requests schedule for submittal of addl info re App G operating curves IPPOLITO, T A Operating Reactors Branch 3 (Pre 790625) 79/04/25 2pp
- 7906140539 Requests add1 info re util 7B1227 proposal to use actual control rod drive scram insertion times rather than times used in plant safety analyses.

  IPPOLITO, T A Derating Reactors Branch 3 (Pre 790625)

  79/05/01 3pp

- 7906200230 Requests two controlled copies of site emergency plans & implementing procedures, site maps showing location & grid station numbers of ensite & offsite environ manitoring stations & site maps used for offsite dose determination KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/17
- 7906010204 Forwards description of statistical analysis & compilation of data used in NEDO-24087-3 submittal H/scram time data. BHR/3 & 4 scram time data.duli core & partial core tests & means of fastest 3 of 4 scram times
- 7906120272 Forwards Revision 1 to Mark I project schedule which corrects 790517 submittal LIU.L Iowa Electric Light & Power Co 79/06/04 6pp
- O Inspection reports, IE Bulletins & correspondence
- 7906050033 Forwards IE Insp Rept 50-331/79-11 on 790227-28,0301,06-08 & 13-14 No noncompliance noted HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/04 2pp
- --7906050040 IE Insp Rept 50-331/79-11 on 790227-28.0301.06-08 & 13-14 No noncompliance noted Major areas inspected plant operations, startup testing.licensee action on previous insp findings & LER followup JACKIM,I N , WALKER,R D , KEY,W J Region 3. Chicago, Office of the Director 79/04/03 14pp
- 7906130130 Forwards IE Insp Rept 50-331/79-12 on 790112,18,0222 % 0326 No noncompliance noted FIORELLI,0 Ragion 3. Chicago. Office of the Director 79/04/19 20p
- --7706130133 IE Insp Rept 50-331/79-12 on 770112.18,0202 & 0326 No noncompliance noted Hajor areas inspected allegations relative to weld radiographs W/supporting documentation FOSTER, JE , WILLIAMB, C C , KEY, J Region 3, Chicago, Office of the Director 79/04/17 IEpp
- 7906020232 Responds to IE Bulletin 79-04 Forwards info re incorrect weights for swing check valves
  LIU.L lowa Electric Light & Power Co 79/05/01 3pp
- 7906120109 Forwards IE Info Notice 79-ii, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/07
- 7906110104 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906190094 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J G Region 3, Chicago. Office of the Director 79/05/11
- 7706260606 Responds to IE Bulletin 79-09 No GE AK-2 circuit breakers are in use or are planned to be used in safety-related sys LIU-L lowa Electric Light & Power Co 79/05/11 lp
- 7904080202 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7906230018 Forwards revision to page 2 of response to IE Bulletin 79-08 WALLACE, J A I lowa Electric Light & Power Co 79/05/21 2pp
- 7906130100 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/22
- 7706220432 Responds to Item ii of IE Bulletin 79-08 re TMI effect on BWRs Tech Spec changes are required based on presently available info WALLACE, J A lowa Electric Light & Power Co 79/05/22 ip
- 7906260036 Ack receipt of 790315 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-331/78-12.
  HEISHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/05/23 ip

- --7906260043 Responds to NRC 790706 ltr re violations noted in JE Insp Rept 50-331/78-12 Corrective actions safety-related parts have been segregated in their own area in warehouse TUTHILL. 8 J Inwa Electric Light & Power Co 79/03/13 tp
- 7904240049 Ack receipt of 790427 Itr informing NRC of steps taken to correct violations noted in 18 Insp Rept 50-331/79-09 KFPPIER. J G Region 3. Chicago, Office of the Director 79/05/23 2pp
- --7906260054 Responds to NRC ltr re violation noted in IE Insp Rept 90-331/79-09 Corrective actions quality dept reorganization has been completed to ensure GA program effectively axecuted 10/1/1/16\_8 J Iowa Electric Light & Power Co 79/04/27 3pp
- 7006200121 Figurards IC Info Notice 79-13, "Indication of Low Water Level in Oyeter Greek Reactor" KEPPLER, J 9 Region 3, Chicago: Office of the Director 79/09/29 If
- 7906270627 Ack receipt of 790426 its informing NRC of steps taken to correct violation noted in IC Insp Rept 50-331/78-33
  REPPLER, J & Region 3, Chicago, Office of the Director 79/05/29
- --7906270637 Responds to NRC 790323 ltr re violation noted in IE Insp Rept 50-331/70-33 Corrective actions maint dept directive describing welder qualification document control issued 701124 TUTMILL.8 J Iowa Electric Light & Power Co 79/04/26 3pp
- R Periodic operating reports & related correspondence
- 7906200248 Forwards monthly operating rept for May 1979 MAHMOND.E L. Iowa Electric Light & Power Co 79/06/14 is
- --7906200289 Monthly operating rept for May 1979
  VAN BICKEL, J Town Flectric Light & Power Co 79/06/14 7pp
- 6 Reportable occurrences: LERs & related correspondence
- /904250259 Forwards LER 79-012/03L-0 HAMMOND,E L. lowa Clectric Light & Power Co 79/06/21 ip
- ---7906250301 LER 79-012703L-0 on 790322 during surveillance testing small leak noted at threaded base of diesel lube oil high temp alarm Caused by switch which had vibrated loase in mounting socket allowing lubricant to escape Switch tightened VANDICKEL, J V I lower Electric Light & Power Co 79/05/21 1p

DOCKET 50-332 DARNHELL REPROCESSING PLANT

- 4 Inspection reports, IC Sulletins & correspondence
- /906280433 Forwards IE Info Notice /9~12, "Attempted Damage to New Fuel Assemblies "Q'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/10 ip

DOCKET 50-333 JAMES A FITZPATRICK NUCLEAR POWER PLANT

- H Comeral correspondence
- 7906130469 Responds to 790316 ltr to R Ryan which expressed concern for difficulty in trying to obtain info re facility shutdown ORIER, B.H. Region i, Philadelphia, Office of the Director 79/04/12, Rpp
- 7906290701 Responds to 790315 ith to JM Hendris, Facility was shut down by NRC 790313 order due to questions re ability of piping sys to withstand earthquakes Situation will be reviewed & plant returned to operation as soon as possible DENTON/H,R Office of Nuclear Reactor Regulation, 79/05/04, ip
- --7906270706 Expresses concerns re shutdown of facility Prolonged layoff of plant employees could have adverse effect on town of Oswego: NY FITZGIBBONB, J E Oswego, NY, 79/03/15 19
- 7906230047 Responds to 790313 ltr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOCA. Plant review is being expedited. 79/05/09 ip DENTON: H R. Office of Nuclear Reactor Regulation 79/05/09

- --7906230050 Expresses concern re shutdown of five reactors for seismic reasons Buggests action assures energy crisis & that plant overhauf more appropriate during refueling shutdown Benefics of huclear power outwich seismic risks SIMPSON.R & Affiliation Unknown 77/03/15 2;6
- 7906210418 Responds to 790319 ltr re NRC 750313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation wind threat to public health & safety
  DENTON: H R Office of Nuclear Reactor Regulation 77/05/16 2pp
- ~~7906210424 Comments on NRC capricious & cavalier acts Requests immediate reversal of unwise decision to shut down five plants Suggests more rational approach to improbable safety concerns in future MARCUS.O H Affiliation Unknown 79/03/19 2pp
- 7906270008 Responds to 790314 ltr re 790313 order stutting down five huclear power plants pending review of analysis techniques used in Seismic design of safety-related piping Maps of northeastern US earthquake iones encl
- 7906270020 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of anelysis techniques used in seismic design of safety-related piping Maps of northeestern US earthquake Iones encl
  DENTON. H R Office of Nuclear Reactor Regulation 77/05/17 3pp
- --7906270028 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual grobability of major seismic activity in this region HERRIMAN.C P Affiliation Unknown 79/03/31 2pp
- 7906270035 Responds to 790403 itr re 790313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Haps of northeastern US earthquake zones encil OENTONIK R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270042 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned FULLER, H R Affiliation Unknown 79/04/03 3pp
- 790o270053 Responds to 790321 ltr re 790313 orders shutting down five nuclear gower plants pending review of analysis techniques used in setsmic design of safety-related piping Maps of northeastern US earthquake jones entl
- --- 7906270056 Comments on 770313 orders shutting down five northeastern UB nuclear power plants Economic consequences for Maine, as well as power shortages, override slim prospect of marthquakes Plants should be reopened SULLIVAN.JF Affiliation Unknown 79/03/21 19
- 7906270060 Responds to 790327 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis tachiques used in seismic design of safety-related piping Maps of northeastern US marthquake rooms encl DENTON: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270066 Comments on 790313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its anti-nuclear attitudes GUIMBY,L Affiliation Unknown 79/03/27 lp
- 7906270067 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthqueke zones and DENYON, M R Office of Nuclear Reactor Regulation 79/05/17 3pp.
- --7906270073 Comments on 790313 orders shutting down five northeastern the nuclear power plants Plants should be reopened immediately.

  due to accommic prospects of plant closings
  GAUNDERS: J A Affiliation Unknown 79/03/23 ip
- 7906270076 Responds to 790322 itr to President re 790313 orders shutting down five nuclear power plants sending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US marthquate sones enti DENTON: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 79062700BO Responds to 79032B ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in reismic design of safety-related piping Haps of northeastern US earthquake zones enci DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp

- 7906270087 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending reaview of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake iones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --790627009: Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MCGONAGLE, H F Affiliation Unknown 79/03/15 1p
- 7906270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquate zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270099 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MARPLE.W W Affiliation Unknown ,79703/17 ip
- 7906270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic desingn of safety-related piping Haps of northeastern US earthquake sones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270117 Responds to 770322 ltr re 770313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 77/05/17 3pp
- 7906270124 Responds to 790324 Itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Haps of northeastern US earthquake zones encl
  DENTON:HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270132 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquaks tones enci
- --7906270133 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ili-conceived KOVLOVRIS:0 E Affiliation Unknown 79/03/17 ip
- 7906270143 Responds to 790313 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Haps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/03/17 App
- 7906270151 Responds to 790322 ltr re 790313 orders skutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake lones encl
  DENTON.HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270195 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-conceived considering current energy crisis RRETISCHMAR.H Affiliation Unknown 79/03/22 ip
- 7906270263 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safaty-related piping. Haps of northeastern US earthquake iones enci
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270264 Comments on 790313 orders shutting down five northeastern US nuclear power glants Decision was economically ill-conceived DEHEULLE,E H Affiliation Unknown 79/03/23, 4pg
- 7906270265 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake sones enci
  DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270266 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was overprotective act KATZENSTEIN,R E. Affiliation Unknown 79703/13. 2pp
- 7906270267 Responds to 790328 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquaks zones encl
  DENTON:H R. Office of Nuclear Reactor Regulation 79/05/17 3pp

- 7906210433 Responds to 790314 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation w/no threat to public health & safety DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 Spp
- --790621044! States that NRC overreacted in closing five nuclear plants Comments on impact of NRC action W/790315 forwarding ltr to JH Hendrie re shutdown of plants HENRY, T P Affiliation Unknown 79/03/14 2pp
- 7906130235 Requests that distribution list be updated by deleting LR Bennett as counsel & substituting VJ Cassan EARLY:P J Power Authority State of New York 79/06/12 1p
- J Insurance & indemnity information
- 7906070234 Forwards Endorsements 41-43 to NELIA Policy NF-208 & Endorsements 35 & 36 to MALEU Policy MF-77
  DEEQ,F H Power Authority State of New York 79/05/31 7pp
- P Operating license stage documents & correspondence
- 790∆010279 FDIA request for all records & communications re shutdown of five nuclear plants CASSAN V J Pawer Authority State of New York 79/03/16 2pp
- 7906130026 Delineates criterion to develop plant-specific info packages on site visits RUSSELL.W T Office of Nuclear Reactor Regulation 79/04/11 2pp
- 7906110032 Forwards attendance list of 790425-26 meeting at plant site re inservice testing program
  POLK.P J Operating Reactors Branch 3 (Pre 790625) 79/04/30
- 7906130227 Forwards listing of docketed info describing GA program EARLY,P J Power Authority State of New York 79/04/30 3pp
- 7906050109 Notification of 790504 meeting w/util.GE & 85W in Bethesda. MD to discuss schedule & plan of action for interim approval POLK.P J Operating Reactors Branch 3 (Pre 790425) 79/05/01
- 7906250091 Forwards memos discussing B McDermott concerns re shutdown of BW plants
  ROSB D F Division of Project Management 79/05/17. Ip
- --7906250101 Requests assessment of safety of continued operation of B&H reactor based on performance of relief & safety valves, performance of HPI pumps, reliability of auxiliary feedwater & core cooling in natural circulation ROSS.D Division of Project Management 79/05/08 2pp
- --7906250106 Discusses safety assessment of R&H plants in response to 790508 memo B&H plants should be shut down until reanalysis has been completed re core cooling in natural circulation, small break LOGA's ECCS

  MCDERHOTT.R J Guality Assurance Branch, 79/05/14 7pp
- --7904280112 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown HAASS,W P Guality Assurance Branch 79/05/15 2pp
- --7906230114 Discusses B HcDermott 790514 memo re safoty of B&W plants.
  Disagrees w/B HcDermott position favoring shutdown
  BKOVHOLT:D J Assistant Director for Guality Assurance &
  Gperations 79/05/15 2pp
- 7906250377 Forwards Amend 46 to License DPR-59,EIA & notice of issuance & availability IPPOLITO.T A. Operating Reactors Branch 3 (Pre 790625) 79705717 3pp
- --7906250380 Amend 46 to License DPR-59 approving deletion of limiting conditions of operation from ETS & mods to environ nonredicingical aquatic biological monitoring program IPPOLITO: TA Operating Reactors Branch 3 (Pre 790625) 79/05/17 23pp
- --79062503B4 ElA supporting Amend 46 to License DPR-59
  \* Operating Reactors Branch 3 (Pre 790625), 79/05/17 17pp

- 7904010273 Denies FDIA request for Oibbon 790314 & Thompson 790315 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shutdown plants Info withheld (ref FOIA Exemption 5)
  FELTON. J M Division of Rules and Records 79/05/21 4pp
- 7906190417 Requests authorization to restart plant, contingent upon piping strees re-evaluation & necessary mods of constraints in inacessible aleas Forwards rept on re-evaluation status of safety-related piping sys

  EARLY, P J Power Authority State of New York 79/06/08 8pp
- 7706200463 Informs that interpretive rept. "Nine Mile Point Aquatic Ecology Studies 1976." which includes matl for Fitzpatrick Unit 1 has been submitted under 770327 cover ltr from RR Schapider
  BLAKE, J W Power Authority Stato of New York 77/06/11 ip
- 7906200378 Corrects several editorial errors in Tech Spec Amend 46 CHILDS.V Power Authority State of New York 79/06/14 App
- 7906260423 Forwards add1 info re spent fuel storage expansion in response to NRC 790315 & 21 requests
  EARLY.P J Power Authority State of New York 79/06/22 19pp
- 7906280121 Forwards application for amend to License DPR-59 EARLY, P J Power Authority State of New York 79/06/26 2pp
- --7706280124 Application for amend to License DPR-54 to modify Tech Specs re emergency svc water pump test acceptance criteria Proposed changes & safety evaluation encl
  \* Power Authority State of New York 77/06/26 5pp
- Q Inspection reports. IE Bulletins & carrespondence
- 7904080095 Responds to IE Bulletin 79-04 re incorrect weights for swing check valves mfg by Velan Engineering Corp Results of investigation will be available w/completion of pipe stress analysis

  LEDNARD, J D Power Authority State of New York 79/04/16 ip
- 7906110027 Forwards IE Bulletin 79-098, "Nuclear Incident at TMI-Suppl " No written response required GRIER.8 H Region 1. Philadelphia, Office of the Director 79/04/23 1p.
- 7906290837 Forwards IE Insp Rept 50~333/79-05 on 790315 No noncompliance noted SMITH: 0 H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/04/24 2pp
- --7906290842 IE Insp Rept 50-333/79-05 on 790315 No noncompliance noted Major areas inspected results of effluent sample split Setween licensee & NRC during previous insp on 780927-29 KOTTON.J J Region 1, Philadelphia, Office of the Director BTOHR.J P Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 79/04/20 App
- 7906130168 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required ORIER, B H Region 1: Philadelphia, Office of the Director 79/05/02 1p
- 7706120185 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER,8 H Region 1, Philadelphia, Office of the Director 79/05/07. 2pp.
- 7906110143 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required ORIER, B H Region 1, Philadelphia, Office of the Director 79/03/11 ip
- 7906260136 Forwards lE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."

  ORIER, B K Region 1. Philadelphia. Office of the Director 79/03/11 ip
- 7904080098 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U." ORIER, B H Region 1, Philadelphia, Office of the Director 79/08/18, 1p
- 7906290743 Responds to IE Bulletin 79-09 re OE Type AK-2 circuit breakers. Four AK-2A-503 & fifteen AK-2A-25 breakers installed in 600 volt amergency power sys. Provides specific functions of breakers.

  LEONARD, J. D Power Authority State of New York 79/05/18 4pp.

- 7906290830 Responds to IE Bulletin 79-11 re faulty overcurrent trip device in circuit breakers for engineered safety sys Breakers not in use at facility LEONARDJJ D Power Authority State of New York 79/05/29 ip
- 7906260445 Forwards responses to questions re inservice insp program contained in NRC 790823 ltr EARLY,P J Power Authority State of New York 79/06/20 Spp
- 7905260335 Responds to IE Builetin 79-01A Plant staff has reviewed application of ASCO solenoid valves utilized within primary containment Replacement parts ordered to replace acetal plastic & Buma N mati containing parts

  LEGNARD. J D Power Authority State of New York 79/06/22 1p
- R Periodic operating reports & related correspondence
- 7906120365 Forwards monthly operating rept for May 1979
  LEDNARD, J D Power Authority State of New York 79/06/07 ip
- ~-7906120371 Monthly operating rept for May 1979
  ZUFELT, E Power Authority State of New York 79/04/30 9pp
- 7906130374 Submits weekly rept of status of SSW piping reanalysis effort as of 790525
  EARLY, P. J. Power Authority State of New York 79/06/07 2pp
- 5 Reportable occurrences, LERs & related correspondence
- 7906040223 RO 78-01 on 780105 inlet piping to safety relief valves was 6-inch double extra strong, causing inside diameter to be slightly smaller than throat diameter of valve Vendor evaluation rept due in Feb PASTERNAK, R J Power Authority State of New York 78/01/05 ip
- 7904040222 Forwards LFR 78-008/03L-0 LEQNARD, J D Power Authority State of New York 78/03/08 1p
- --7906040227 LER 78-008/03L-0 on 780210 during normal plant operation, snoke emanated from supply breaker for 13MOV131 reactor core overload Caused by electrical overload Damaged parts replaced POBUTKIEHICZ, B Power Authority State of New York 78/03/09 ip Available at NRC nrc
- 7904040305 Provides DE analysis & safety review results concerning potential RD 78-01 re nuclear boiler safety relief valve piping. Analysis concludes that piping does not comptomise safe operation of facility

  LEONARD, J D Power Authority State of New Yark 78/03/29 2pp.
- 7906040276 Forwards LER 78-059/03L LEONARD, J D Power Authority State of New York 78/08/30 in
- --7906040288 LER 78-089/03L-0 on 780805 primary containment pressure suppression pool level exceeded tech Spece limit by two inches Caused by operator failure to isolate SHR sys from teep-full subsys CHILDS,W V Power Authority State of New York 78/08/30 ip
- 7906040315 LER 78-048. number not used
  \* Power Authority State of New York 79/08/29 1p
- 7904080231 Forwards LER 79-024/03L-0
  LEONARD, J D Power Authority State of New York 79/06/05 1p
- --7906080235 LER 79-026/03L-0 on 790307 raduante bldg exhaust fan 69-FN-8A did not trip per Hi-Hi radiation signal Caused by misadjusted position switch associated w/discharge damper Switch linkage adjusted CHILDS: H V Power Authority State of New York 79/06/05. 2pp
- 7904150273 Forwards LER 79-027/03L-0 LEUNARD. J. D Power Authority Stats of New York 79/06/12 1p.
- --7906150278 LER 79-027/03L-0 on 790514 instrument 02-3-LIS-720 tripped minus 47 3 inches, instrument recalibr, then replaced Weekly testing will continue to assure good performance CHILDS: W V Power Authority State of New York 79/06/12 2pp
- 7906180363 Forwards LER 79-028/03L-0 LEONARD, J. D. Power Authority State of New York 79/06/13 1p

- --7906180567 LER 79-028/03L-O on 790517 during cold shutdown level instrument of carbon dioxide storage sys was out of calibr Caused by procedural error Instrument racalibr & satisfactorily tested CHILDS.H V Power Authority State of New York 79/03/17 2pp
- 906180474 Forwards LER 79-032/03L-0 LEONARD, J D Power Authority State of New York 79/06/15 1p
- -7906180482 LER 79-032/03L-0 on 790519 sequencing timer associated w/total flooding carbon dioxide sys not functioning properly Cause not stated Sequencing timer cams adjusted CHILDS.W V Power Authority State of New York 79/06/15 2pp
- '906180574 Forwards LER 79-030/03L-0 LECNARD, J D Fower Authority State of New York 79/06/15 1p
- -7906180580 LER 79-030/03L-0 on 790518 during cold shutdown, test point was discovered in error Caused by deviations in conduction of surveillance test procedures F-IBP-89 Procedure was immediately correted & surveillance complete CHILDS.H V Power Authority State of New York 79/06/15 2pp
- 906190271 Forwards LER 79-029/03L-0 LECNARD.J D Power Authority State of New York 79/06/15 1p
- -7906190275 LER 79-029/03L-0 on 790518 during snubber insp.14 snubbers required some work & six snubbers were determined to be potentially inoperable Snubbers removed & tested Two snubbers failed test & were declared inoperable CHILDS.H V Power Authority State of New York 79/06/15 2pp
- 906190410 Forwards LER 79-031/03L-0 LEDNARD.J D Power Authority State of New York 79/06/15 ip
- -7906190414 LER 79-031/03L-0 on 790519 fire door between north & south emergency switch gear rooms failed to close on automatic signal Door & closing mechanism Lubricated & adjusted CHILDS.W V Power Authority State of New York 79/06/15 2pp
- 906250274 Forwards LER 79-033/03L-0
  LEGNARD, J L Power Authority State of New York 79/06/20 ip
- -7906250277 LER 79-033/03L-0 on 790524 during review of plant sys. determined that reactor bldg cooling sys supply & return lines to drywell equipment drain sump did not have seismic stress analysis performed Uncertain if it is required CHILDS.W V Power Authority State of New York 79/06/20 2pp
- 90625026B Forwards LER 79-034/03L-0 LEONARD.J D Power Authority State of New York 79/06/21 1p
- -7906250270 LER 77-034/03L-0 on 790531 data sheets associated w/instrument surveillance procedures F-ISP-4 5 had not been revised as part of procedure revision which changed instruments calibr range Personnel reinstructed CHILDS.W V Power Authority State of New York 79/06/21 2pp
- 906250275 Forwards LER 79-035/03L-0 LEGNARD, J D Power Authority State of New York 79/06/21 1p
- -7906250276 LER 79-035/03L-0 on 790607 suction pressure switch 13P8-67A found to trip at 15 7 inches of mercury Pressure switch recallibute operations verified by completing surveillance procedure F-ISP-14-1 CHILDS,W V Power Authority State of New York 79/06/21 2pp

## OCKET 50-334 BEAVER VALLEY POWER STATION, UNIT 1

## Adjudicatory correspondence

906070330 Amend to PA Public Utils Commission 790402 patition to intervene & request for hearing Certificate of Svc encl LEVIN.J A Pennsylvania, State of 79/04/10 5pp

## General correspondence

- 706230047 Responds to 790313 itr re shutdown of five nuclear power plants because of seismic concerns Seismic design was not in accord w/accepted engineering practice Failed piping could cause LOGA Plant review is being expedited DENTON, HR Office of Nuclear Reactor Regulation 79/05/09 ip
- -7904230050 Expresses concern re shutdown of five reactors for seismic reasons Suggests action assures energy crisis & that plant overhaul more appropriate during refueling shutdown Benefits of muclear power outweigh seismic risks
  SIMPSON.R E Affiliation Unknown 79/03/15, 2pp

- 7906210418 Responds to 790319 itr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation w/no threat to public health & safety DENTON:HR Office of Nuclear Reactor Regulation 79/05/16 2pp
- --7906210424 Comments on NRC capricious & cavalier acts Requests immediate reversal of unwise decision to shut down five plants Suggests more rational approach to improbable safety concerns in future
  MARCUS.O H Affiliation Unknown 79/03/19 2pp
- 7906270008 Responds to 790314 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- /906270020 Responds to 790331 ltr re 790313 order shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-telated piping Maps of northeastern US earthquake iones encl
  DENTON.N R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270028 Comments on 790313 orders shutting down five northeastern US nuclear power plants Requests investigation into actual probability of major seismic activity in this region HERRIMAN.C P Affiliation Unknown 79/03/31 2pp
- 7906270035 Responds to 790403 ltr re 790313 orders shutting down five nuclear plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake tones onc!

  DENTON: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270042 Comments on 790313 orders shutting down five northeastern US nuclear power plants Actions poorly reasoned FULLER.W R Affiliation Unknown 79/04/03 Spp
- 7906270053 Responds to 790321 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismit design of safety-related piping Maps of northeastern US earthquake Jones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270096 Comments on 790313 orders shutting down five northeastern US nuclear power plants Economic consequences for Maine, as well as power shortages, override slim prospect of earthquakes Plants should be reopened
  SULLIVAN.J F Affiliation Unknown 79/03/21 tp
- 7906270060 Responds to 790327 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techiques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7706270066 Comments on 770313 orders shutting down five northeastern US nuclear power plants NRC should re-evaluate its anti-nuclear attitudes GUIMBY.L Affiliation Unknown 77/03/27 ip
- 7906270069 Responds to 790323 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US aerthquake zones encl
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270073 Comments on 790313 orders shutting down five northeastern US nuclear power plants Plants should be reopened immediately, due to economic prospects of plant closings GAUNDERG.J A Affiliation Unknown 79/03/23 ip
- 7906270076 Responds to 790322 ltr to President re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in saismic design of safety-related piping Maps of northeastern UB earthquake zones enci DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270080 Responds to 790328 itr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270087 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending reaview of analysis techniques used in selsmic desing of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/03/17 Spp

- --7906270091 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MCGONAGLE, W.F. Affiliation Unknown 79/03/15 1g
- 7906270095 Responds to 790317 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in sersmic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 Spp
- --7906270099 Commonts on 790313 orders shutting down five northeastern US nuclear power plants Decision was extremely ill-conceived MARPLE, WW Affiliation Unknown 79/03/17 ip
- 7906270109 Responds to 790314 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in selsmic desingn of safety-related piping Maps of northeastern US earthquake zones enci
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270119 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic desing of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, H R Uffice of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270124 Responds to 790324 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones enci
  DENTON, H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- 7906270132 Responds to 790317 ltm re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in setsmic design of sefety-related piping Maps of northeastern US can thouse zones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7706270135 Comments on 770313 orders shutting down five northeastern US nuclear power plants Decision was poorly timed & economically ili-conceived KOVLOVRIS.O E Affiliation Unknown 79/03/17 ip
- 790A270143 Responds to 790313 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake iones onci
  DENTON: If R Office of Nuclear Reactor Regulation 79/05/17 Spp
- 7906270151 Responds to 790322 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON.H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- ---7906270153 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was ill-conceived, considering current energy crisis KREYZBCHMAR, W Affiliation Unknown 79/03/22 1p
- 7906270263 Responds to 790323 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones enc1

  DENTON: H R Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270264 Comments on 740313 orders shulting down five northeastern US nuclear power plants Decision was economically ill-conceived.

  DEHEULLE,E H Affiliation Unknown 79/03/23 App
- 7906270265 Responds to 790315 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones encl
  DENTON, HR Office of Nuclear Reactor Regulation 79/05/17 3pp
- --7906270266 Comments on 790313 orders shutting down five northeastern US nuclear power plants Decision was overprotective act KATZENSTEIN:R L Affiliation Unknown 79/03/15 2pp
- 7906270267 Responds to 790325 ltr re 790313 orders shutting down five nuclear power plants pending review of analysis techniques used in seismic design of safety-related piping Maps of northeastern US earthquake zones and

- 7906210433 Responds to 790314 ltr re NRC 790313 orders to shut down five nuclear power plants NRC prefers to review situation in expedited & disciplined manner, to return plants to operation w/no threat to public health & safety DENTON, H R Office of Nuclear Reactor Regulation 79/05/21 5pp
- --7906210441 States that NRC overreacted in closing five nuclear plants Comments on impact of NRC action W/790315 forwarding ltr to JM Hendrie re shutdown of plants HENRY,TP Affiliation Unknown 79/03/14 2pp
- J Insurance & indemnity information
- 7906010253 Forwards executed Amend 5 to Indomnity Agreement 8-73 CHRISTNER:R S Duqueene Light Co 79/05/29 3pp
- P Operating license stage documents & correspondence
- 7906130026 Delineates criterion to develop plant-specific info packages on site visits
  RUSSELLU T Office of Nuclear Reactor Regulation 79/04/11 2pp
- 7906160060 Requests withdrawal of solid radioactive waste packaging GA program, submitted 790216 Approves operational GA program BUNN, C N Duquesne Light Co 79/05/07 19
- 7906260176 Summary of 790512 meeting w/util re auxiliary feedwater sys & related areas OLSHAN.L N Operating Reactors Branch 1 (Pre 790625) 79/05/15 5pp
- 7906250091 Forwards memos discussing 8 McDermott concerns re shutdown of B&W plants ROSS.D F Division of Project Management 79/05/17 1p
- --7906250101 Requests assessment of safety of continued operation of B&W reactor based on performance of relief & safety valves, performance of HPI pumps reliability of auxiliary feedwater & core cooling in matural circulation ROSS,D Division of Project Management 79/05/08 2pp
- --7908230106 Discusses safety assessment of BBW plants in response to 790508 memo BBW plants should be shut down until reanalysis has been completed re core cooling in natural circulation, small break LOCAs & ECCS
  MCDERMOTT.R J Guality Assurance Branch 79/05/14 7pp
- --7906250112 Discusses B McDermott 790514 memo re safety of 8%H plants Disagrees w/B McDermott position favoring shutdown HAASS.H P Guality Assurance Branch 79/05/15 2pp
- ---7906250114 Discusses B McDermott 790514 memo re safety of B&W plants Disagrees w/B McDermott position favoring shutdown. SKCVHDLT:D J Assistant Director for Guality Assurance & Operations 79/05/15 2pp
- 7906060069 Response to FOIA request for documents re discrepancy between results of original piping analysis for seismic stresses |Info partially denied documents w/NRC opinions tyresome/indictions(ref FOIA Exemption 5) FELTON:J M Division of Rules and Records 79/05/21 3pp.
- ---7906060109 Requests info re history of plant water hammer & pipe vibration problems OILINBKY,V Commission 77/03/19 1p
- --7906060118 Discusses plant water hammer & pipe vibration history, in response to Commissioner Gilinsky 790313 memo DENTON, H R Office of Nuclear Reactor Regulation 79/03/15 ip
- --7906060127 Discusses discovery of error in plant seismic design & subsequent NRC decision to shutdown five nuclear power plants GILINBKY, V Commission 79/03/19 Spp

- 906030282 Responds to MRC 790518 ltr Forwards amplified response spectra based on soil structure interaction Details result of analysis of small strain valves of plus or minus 50% DUNNIC N Duquesne Light Co 79/05/23 45pp
- 906290550 Notification of 790524 meeting w/util % 9%W to discuss response spectra to be used in facility pipestress reanalysis HIGGINTON, D Decrating Reactors Branch 1 (Pre 790625) 79/05/23 200
- 706290070 Discusses use of soil structure interaction for seismic pipe stress analysis being performed Methodology may be used provided seismic stresses calculated are increased by factor of 1 2 EISENRUT, D O Assistant Director for Systems Engineering 79/05/25 200
- 906150312 Discusses present status of piping sys reanalysis Reanalysis complete & two hydraulic snubbers installed No pipe is overstressed in event of safa shutdown earthquake Rept supporting 790706 request to be submitted by 790618 HOOLEVER.E J Duquesne Light Co 79/06/11 3pp
- 906200155 Forwards StW rept on "Soil-Structure Interaction in Development of Amplified Response Spectra," in response to NRC 790213 order to show cause WOOLEVER,E J Duquesne Light Co 79/06/11 ip
- -7906200158 "Soil-Structure Interaction in Development of Amplified Response Spectra " \* Stone & Hebster, Inc 79/06/11 203pp
- 7906210131 Forwards "Rept on Reanalysis of Safoty-Related Piping Sys" Requests mod of 790313 order for shutdown to permit operation until refueling Certificate of Svc encl DUNN,C N Duquesne Light Co 79706/19 3pp
- --7906210132 "Rept on Reanalysis of Safety-Related Piping Sys "
  \* Stone & Webster, Inc. 79/06/15 225pp
- 7906220351 Bubmits info requested by NRC on 790525 re design, fabrication history, preservice/inservice inspec & operating history of facility feedwater lines
  DUNN.C N Duquesne Light Co 79/06/20 4pp

# O Inspection reports. IE Bulletins & correspondence

- 7906260155 Forwards IE Insp Rept 50-334/79-03 on 790208-0327 No noncompliance noted CARLEON, T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/04/20 2pp
- 7906260165 IE Insp Rept 50-334/79-03 on 790208-0327 No noncompliance noted Major areas inspected soil-boring & testing program in area of station turbine bldg EBNETER, S D . VARELA, A A Region 1. Philadelphia. Office of the Director 79/04/20 Spp
- 7906110011 Forwards IE Bulistin 79-05B, "Nuclear Incident at TMI-Suppl " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/23 ip
- 7906:130:134 Forwards response to IE Bulletin 79~06A Procedural changes & training planned for completion prior to facility startup WOOLEVER.E J Duquesne Light Co 79/04/30 10pp
- 7904:60299 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Analysis of 26 valves for potential everstress is in progress MDDLEVER.E J Duquesne Light Co 79/04/30 ip,
- 7906070231 Ack receipt of 790405 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-334/79-04
  BRUNNER.E J Region i. Philadelphia. Reactor Operations Nuclear Support Branch 79/05/04 ip
- --7906070235 Responds to NRC 790314 ltr re violation noted in IE Ensp Rept 50-334/79-04 Corrective actions reviewed test data for missing documents & submitted info to Onsite Safety Committee DUNN,C N. Duquesne Light Co 79/04/05 2pp
- --7906070236 Forwards IE Insp Rapt 50-334/79-04 on 790212-16 & notice of violation BRUNNER,E J Region 1. Philadelphia, Reactor Operations Nuclear Support Branch. 79/03/14, 2pp

- --7906070239 Notice of violation from insp on 790212-16
  Region 1, Philadelphia, Office of the Director 79/03/14
- --7906070244 IE Insp Rept 50-344/79-04 on 790212-16 Noncompliance noted failure to maintain records of surveillance testing BECKMAN.D A Region i. Philadelphia. Office of the Director KEIMIO.R R Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/03/13 2Ipp
- 7906120158 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required GRIER,B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906110120 Forwards IE Builetin 79-10, "Requalification Training Program Statistics " Written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906260101 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director 79/09/11 1p
- 7906290790 Requests response date to IE Bulletins 78-12.78-12A to 78-12B be changed to 790702 DINN,C N Duquesne Light Co 79/05/11 1p
- 7906270194 Forwards response to Item 13 per Revision 1 of IE Bulletin 79-06A Unity Tech Spec & design change necessary is mod to pressurizer safety injection logic DUNNAC N Duquesne Light Co 79/05/17 2pp
- 7906080079 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" ORIER, BH Region 1, Philadelphia, Office of the Director 79/05/18 ip
- 7906290746 Responds to IE Bulistin /9-10, "Requalification Training Program Statistics " Forwards util requalification training program statistics program statistics DUNN, C N Duquesne Light Co 79/05/23 3pp
- 7906180601 Responds to IE Bulletin 79-01 Light switches have been replaced Safety-telated electrical equipment is qualified by ltr of compliance, test repts & analysis of equipment Tach Byocs available in Central Files only DUNN, C N Duquesne Light Co 79/06/14 2pp

## R Periodic operating reports >> related correspondence

- 7906010152 Forwards Jan 1979 Natl Pollution Discharge Elimination Sysmonthly rapts as submitted to PA Dapt of Environ Resources MOGRC, G W Duquesna Light Co 79/05/29 14pp
- 7906050275 Forwards pages 243 ½ 244 ½ revised table of contents to be added to "Annual Environ Rept 1978, Nonradiological, Vol 1," previously forwarded on 790326 Pages summarize use of herbicides

  DUNN, C N Duquesne Light Co 79/05/30 7pp
- 7906120325 Forwards monthly operating rept for May 1979 MODRE,G W Duquesna Light Co 79/06/08 ip
- --7906120328 Monthly operating rept for May 1979 TIMKO.D R Duquesne Light Co 79/06/06 4p;
- S Reportable occurrences, LERs & related correspondence
- 7906040245 Forwards LER 78-001/040 WERLING, J A Duquesne Light Co 78/01/16, 1p.
- --7906040247 LER-78-001/040 on 771025 reporting level in ETB for gross beta particles was reached or exceeded 771003-10 Caused by Chinese bomb fallout No corrective action appropriate WERLING, J A Duquesne Light Co 78/01/16 2pp
- 7906260397 RO on 790618 radiographs taken on 790615-16 & 18 of three steam generator nozzle-to-feedwater inlet piping welds showed cracking present in three inlet pipes Addl info & corrective action will be provided in followup rept.

  WERLING, J A Duquesne Light Co 79/06/19 2pp
- 7906290328 Forwards LERs 79-009/03L-0 \$ 79-013/03L-0. WERLING, J. A. Duquesne Light Co 79/06/21, 2pp

- --7906270333 LER 79-007/03L-0 on 790320 during surveillance test,diesel generator 1 output breaker failed to close upon actuation of control switch Cause of inoperable breaker unknown Operators reinstructed in test circuit & surveillance increased WERLING, J A Duquesne Light Co 79/06/21 1p
- --7906290339 LER 79-013/03L-0 on 790522 during surveillance of control room habitability syap pressure regulators for control room pressurization were found cycling Caused by improper calibr Controls tuned & procedure revised WERLING, J A Duquesne Light Co 79/06/21 1p

# DOCKET 90-335 ST LUCIE PLANT, UNIT 1

7904190419 Forwards Endorsements 25 & 26 to MAELU Policy MF-88 DUCK.J R Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/04/12 3pp

### M Antitrust correspondence

- 7906040418 Response of util in opposition to FL Cities' motion for antitrust hearing >> motion for consolidated hearings Certificate of 8vc encil BOUKNICHT. J A Lowenstein, Newman, Reis, Axelrad & Toll 79/04/13 3nn
- P Operating license stage documents & correspondence
- 7906050019 Responds to 780319 ltr requesting ref to specific GA program used to meet requirements of 10CFR71 51 Revision 2 to topical GA rept is in effect for Turkey Point & F5AR GA program is in affect for St Lucie

  UHRIG.R E Florida Power & Light Co 79/04/23 ip
- 7903250210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants
  THADANI,A C Reactor Systems Branch 79/05/02 43pp
- 7706120025 Notifies that reporse to IE Bulletin 79-04 re Velan swing check valves will be submitted by 790531
  UHRIG.R E Florida Fower & Light Co 79/05/02 1g
- 7903230087 Forwards summary of 790301 meeting w/C-E re natural circulation conditions in C-E operating reactors THADANI, A C Reactor Systems Branch 79/05/09 ip
- 7904050307 Forwards C-E proprietary rept "Control Element Assembly Guide Tube Eddy Current Testing " Forwards AE Sherer affidavit attesting to proprietary nature of rept UHRIGR E Florida Power & Light Co 79705/23 9pp
- 7904050315 Notifies of reduction in allowable peak linear heat rate in accordance \(\times 1761526 \fo 27 \) tolcon \(\times 17 \) Erickson Reduction necessitates change in Tech Specs Revised Figures encl UHRIG:R E Florida Power & Light Co 79/05/30 4pp
- 7906200418 Submits proposed change to requalification program procedure 0005720 re test scores on annual exams Requests response to implement change FINCHER, P. L. WETHY, C. M. Florida Power & Light Co. 79/08/31 1p
- 7906220309 Forwards requested info re feedwater line design & fabrication history
  UHRIG:R E Florida Power & Light Co 79/06/20, 4pp
- G Inspection reports. IE Bulletins & correspondence
- 7706130434 Responds to IE Bulletin 79-03. Status rept re Youngstown Welding & Engineering Co pipe will be sent no later than 790531 UHRIG:R E. Florida Power & Light Co 79/04/17 ip
- 7906050451 Ack receipt of IE Bulletine 79-06 \$ 79-06B Forwards responses to 79-06B & procedures identified for review URIG.R.E Florida Power & Light Co 79/04/24 7pp
- 7906250372 Forwards IC Insp Rept 50-335/79-09 on 790321-23 No noncompliance noted LEWISR G Region 2, Atlanta, Reactor Operations Nuclear Support Branch. 79/04/24 2pp
- ---7906250375 IE Insp Rept 50-335/79-09 on 790321-23 No noncompliance noted Major areas inspected steam generator cleaning program, noncountine swent rept program, plant procedures, IE bulletins & notices & open items.
  CANTRELLIF. B., WEBSTER, E. H. Region 2. Atlanta, Reactor Operations Nuclear Support Branch, 79/04/23 7pp

١

- 7906230002 Ack recaipt of 790501 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-335/79-06
  LEWIS.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/07 lp
- --7906230006 Responds to NRC 790404 ltr re violations nated in IE Insp Rept 50-335/79-06 Corrective actions safety evaluation conducted & procedure reviewed & determined satisfactory UHRIO,R E Florida Power & Light Ca 79/08/01 3pp
- --7906230006 Forwards IE Insp Rept 50-335/79-06 on 790212-16 & notice of Violation
  LEWIS.R C Region 2, Atlanta, Office of the Director 79/04/04
- --7906230010 Notice of violation from insp on 790212-16
  Region 2. Atlanta, Office of the Director 79/04/03 ip
- --7906230013 IE Insp Rept 50-335//9-06 on 790212-16 Noncompliance noted failure to complete written safety evaluation of mod to sys described in FSAR & failure to review & approve maint retest procedure

  WEBSTER,E H , CANTRELL,F S Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 7pp
- 7906180183 Ack receipt of 790418 itr informing NRC of stops taken to correct violations noted in IR Insp Rept 50-335/79-07
  KENNA,W B. Region 2, Atlanta, Safeguards Branch 79/05/09 lp
- --7906180195 Responds to NRC 790323 ltr re violations noted in IE Insp Rept 30-333/79-07 Corrective actions withheld (ref 10CFR2 790) URRIG:R E Florida Power & Light Ca 79/04/18 1p
- --7906180205 Forwards IE Insp Rept 50-335/79-07 on 790122-26 Notice of violation withheld (ref 100FR2 790)
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/23 2pp
- --7906180232 IE Insp Rept 30-335/79-07 on 790122-26 Noncompliance noted lax security Details withhold (ref 10CFR2 790) MCGUIRE, D R Region 2, Atlanta, Office of the Director BESECKER, K H . LONO, F J Region 2, Atlanta, Safeguards Branch 79/03/13 3ρp
- /906250452 Forwards IC info Notice 79-12, "Attempted Damage to New Fuel Assemblies " D'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7906:10063 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required d'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/03/11 1p
- 7906260293 Responds to IE Bulletin 79-09 re GE Model AK-2 circuit breaker Hork ander issued to perform checks described in 0E Svc Advice Ltr 175 & checks will be incorporated into switchgear maint procedure UHRIO:R E Florida Power & Light Co 79/05/22 tp

- 7906180554 Forwards LER 79-017/03L-0 SCHMIDT(A D Florids Power & Light Co 79/06/07 1p
- --7906180555 LER 79-017/03L-O on 790509 t8 charging pump casing block contained several internal cracks centered around pressure chambers Caused by suction cavitation resulting in vibration Pump block replaced SCHOPPMAN, M A Florida Power & Light Co 79/06/07 2pp
- "906180937 Forwards LER 79-018/03L-0 SCHMIDT,A D Florida Power & Light Co 79/06/07 1p
- --7906180558 LER 79-018/03L-0 on 790908 during routine diesel generator maint valves installed on engine crankcase oil drain line prior to performance of written safety evaluation Caused by failure to follow procedures gCHOPPMAN.M A Florida Power & Light Co 79/06/07 ip

## U Congressional/Executive Correspondence

7904260986 Provides add1 info re D Browning info request concerning FL nuclear power situation Discusses wastes produced by FL plants, efficients released. \$ consequences of possible accident GOSSICK.L V Office of the Executive Director for Operations 79/05/17 3pp

#### DOCKET 50-336 HILLSTONE NUCLEAR POWER STATION, UNIT 2

- I Financial information
- 7904200374 Forwards annual financial repts for owner-licensees O'CONNOR, L. A. Northeast Utilities 79/06/15 3pp
- --7906200375 Annual Financial Rept 1978 \* Western Massachusetts Electric Co 79/12/31 17pp
- --7906200376 Annual Financial Rept 1978 \* Hartford Electric Light Co 79/12/31 21pp
- ---7906200377 Annual Financial Rept 1978 \* Connecticut Light & Power Co 79/12/31 21pp
- J Insurance & indemnity information
- 770A190293 Forwards Endorsements 54 & 55 to MAELU Policy MF-52 CONNELL,T Northeast Nuclear Energy Co (Northeast Utilities) 79/06/12 3pp
- 7906280091 Forwards Endorsements 79 & 60 to ANI Policy NF-173 SEOER: R M Northeast Utilities 79/06/21 ip
- P Operating license stage documents & correspondence
- 7906250305 Forwards Mar 1979 "Thermal Plume Study "
  COUNSIL.W & Northeast Utilities 79/04/18 ip
- --7906250306 "Thermal Plume Study," Mar 1979 \* Northeast Utilities 79/03/31 350pp

7

- 7903230210 Summary of 790425 meeting w/C-E re natural circulation capability for C-E plants
  THADANI.A C Reactor Systems Branch 79/05/02 43pp
- 790\$230087 Forwards summary of 790501 meeting w/C-E re natural circulation conditions in C-E operating reactors THADANI,A C Reactor Systems Branch 79/05/09 1p
- 7906230082 Forwards questions & comments re inservice testing program & confirms 790523-24 meeting Requests formal response by 790625 REID.R W Operating Reactors Branch 4 (Fre 790625) 79/05/11
- 7906270257 Forwards Amend 52 to License DPR-65; safety evaluation & notice of issuance & availability REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/12
- --7906270258 Amend 52 to License DPR-65 authorizing Cycle 3 operation at 2,560 mm w/modified guide tubes for control element assemblies
  REID:R W Operating Reactors Branch 4 (Pre 790625) 79/05/12
  855pp

- --7906270259 Safety evaluation supporting Amend 32 to License DPR-65
  \* Operating Reactors Branch 4 (Pre 790625) 79/05/12 68pp
- ---7906270260 Notifies that mgt performance is adequate % responsive to NRC concerns No outstanding insplitems are related to safe operation of plant at stretch power level MLINGER.G R Division of Reactor Operations Inspections 79/02/09 lp
- --7906270261 Notice of issuance & availability of Amend 52 to License BPR-65 REID.R W Operating Reactors Branch 4 (Pre 790623) 79/09/12 3op
- 7906290033 Summary of 790511 meeting w/util & Bechtel re auxiliary feedwater sys & related areas
  CONNER.E C. Operating Reactors Branch 4 (Pre 790625) 79/05/21
- 7906050314 Proposes that min of two licensed reactor operators be stationed in main Control rooms at all times one of whom has direct responsibility for feedwater sys COUNSIL.W O Northeast Utilities 79/05/31 2pp
- 7706120339 Forwards addl info re C-E sleeved control element assembly guide tubes Data indicates that fuel assemblies remain acceptable for Cycle 3 operation COUNSIL-W G Northeast Utilities 77/06/06 7pp
- 7906210198 Forwards info in response to V Stello 790525 request redesign fabrication history & insp of feedwater lines Sysmests code requirements & can continue to operate safely COUNSIL.W G Northeast Nuclear Energy Co (Northeast Utilities) 79/06/18 27pp
- @ Inspection reports, IE Bulletins & correspondence
- 7906010043 Forwards IE Insp Repts 30-245/78-41 & 50-336/78-38 on 781106-1207 No noncompliance noted BRUNNER,E J Region i, Philadelphia, Office of the Director 79/03/21 2pp
- --7906010047 [E Insp Repts 50-245/78-41 & 50-336/78-38 on 791106-1207 No noncompliance noted Major areas inspected accessible portions of Unit 1 reactor, turbine & radusate filgs. Unit 2 auxiliary & turbine bidgs & radiation protection SHEDLOSKY.J T Region 1, Philadelphia, Office of the Director MCCABC.E C Region 1, Philadelphia, Reactor Operations Nuclear Support Brench 79/03/20 24pp
- 7906090173 Forwards IE Insp Rept 50-336/79-05 on 770306-09 No noncompliance noted BRUNNER, E. J. Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/10 Spp
- ---7906050183 IE Insp Rept 50-334/79-05 on 790306-09 No noncompliance noted Major areas inspected refueling preparations, containment integated leak rate test procedure & outage maint HIGGINS, J C. GRAHAM, P D Region 1, Philadelphia, Office of the Director CAPTHION, D L Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/05 9pp
- 7906040365 Responds to 790312 Itr rs IE Bulletin 79-03,ABME 8A-312 stainless steel pipe manufactured by Youngstown Helding & Engineering Co Forwards info on piping in use & program for volumetric examination
  COUNSIL.H Q Northeast Utilities 79/04/16 4pp
- 7706260546 Forwards IE Insp Repts 50-245/79-04 & 50-336/79-02 on 790210-0316 No noncompliance noted BRUNNER.E J. Region 1. Philadelphia. Reactor Operations Nuclear Support Branch 79/04/16 2pg
- ~~7906260551 IE Insp Repts 80~245/79~04 & 50~336/79~02 on 790210~0316 No noncompliance noted Major areas inspected accessible portions of Unit 1 reactor, turbine & radwaste bldgs.Unit 2 encl.auxiliary & turbine bldgs SMEDLOSKY.JT, RAYMOND.W J, MCCABE.E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/04/16
- 7906140528 Responds to IE Bulletin 79-01 re environ qualification of Class IE equipment Solenoid on safety-related valve in Unit 2 containment not qualified Bolenoid will be replaced before Cycle 3 operation CDUNSIL.H G Northeast Utilities 79/04/18 2pp
- 7906:10017 Forwards IE Bulistin 79-05B, "Nuclear Incident at TMI-Suppl " No written response required. ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 ip

- 7906020210 Responds to IE Bullatin 79-07 re seismic stress analyses of safety-related piping. COUNSTL.W O Northeast Utilities 79/04/24 9pp
- ...
- 7904080076 Responds to IE Bulletin 79-048." Operational Errors & Sys Misalignments Identified During TMI Incident "Emergency procedures have been revised to provide specific guidance, if voiding is indicated by check of reactor coolant sys flow COUNSIL, N O Northeast Utilities 79/04/24 Spp
- 790627009B Requests clarification of requirement for "Verification of Operability" from IE Bulletin 79-06B WILLIAMS,F J Division of Project Management 79/04/27 1p
- 7906070412 Responds to IE Bulletin 79-04, "Incorrect Weights for Swing Check Valves Mfg by Velan Engineering Corp " Lists subj valves used in Seismic Category I piping sys Investigation indicates no drawing discrepancies re valves COUNSIL.N C Northeast Utilities 79/04/30 2pp
- 7906120128 Responds to IE Bulletin 79-03 re longitudinal weld defects in ASME SA-312 stainless steel pips Welds found to be acceptable Response submitted per 790416 commitment GOUNSIL.W G Northeast Utilities 79/05/03 2pp
- 7906150200 Ack receipt of 790412 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-245/79-03 & 50-336/79-03
  SMITH.O H Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch 79/05/03 lp
- ---7906150205 Responds to NRC 790320 itr re violations noted in IE Insp Repts 50-245/79-03 % 50-336/79-03 Corrective actions 38-ft, 6-inch elevation immediately posted w/sign bearing radiation caution symbol COUNSIL,W O Northeast Nuclear Energy Co (Northeast Utilities) 79/04/12 2pp
- --7906150207 Forwards IE Insp Repts 50-245/77-03 & 50-336/77-03 on 770212-15 % notice of violation SMITH,0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 77/03/20 3pp
- --7906150210 Notice of violation from insp on 790212-15
  \* Region 1, Philadelphia, Fuel Facility & Materials Safety
  Branch 79/03/16 ip
- --7906150213 IE Insp Repts 50-245/79-03 b 50-336/79-03 on 790212-15
  Noncompliance noted failure to post radioactive matls
  storage area as required
  YUHAS: 0 P. CROCKER, W Region i. Philadelphia, Fuel Facility
  & Materials Safety Branch 79/03/16 6pp
- 7906120176 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER.B H Region 1. Philadelphia. Office of the Director 79/09/07 2pp
- 7906140524 Supplements 790507 response to IE Bulletin 79-07 Bafety-related piping meets satismic sys criteria CDUMBIL. W G Northeast Utilities 79/05/07 Ip
- 7906270137 Requests establishing requirement for core thermocouples per IE Bulletin 79-06 WILLIAMS:F J Division of Project Management 79/05/07 1p
- 7906290784 Responds to IE Bulletin 79-068 No Tech Spec changes required at present COUNSIL.W O Northeast Nuclear Energy Co (Northeast Utilities) 79/05/10 iP
- 7906110138 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics" Written response required.
  QRIER, B. H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906260124 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.B.H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906080091 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/16 ip

- 7906140277 Supplements response to IE Bulletin 79-07 Assessment revealed nitrogen addition sys & charging sys are in conformance w/high energy pipe break criteria specified in FSAR CDUNBIL.W G Northeast Nuclear Energy Co (Northeast Utilities) 79/06/08 2pp
- 7906180496 Responds to IE Bulletin 79-01, "Environ Qualification of Class IE Equipment " Second suppl to be submitted by 791031 COUNBIL.W O Northeast Utilities 79/06/12 17pp
- R Periodic operating reports & related correspondence
- 7906120345 Forwards monthly operating rept for Hay 1979 OPEKA, J. F. Northeast Utilities 79/06/08 ip
- --7906120347 Monthly operating rept for May 1979 SUDIGALA, 8 Northeast Utilities 79/06/07 5pp
- S Reportable occurrences. LERs & related correspondence
- 7906040321 Forwards LER 78-014/03L-0 FERLAND.E J Northeast Nuclear Energy Co (Northeast Utilities) 78/07/14 ip
- --7906040323 LER 78-014/03L-O on 780617 while performing monthly control element assembly surveillance testing assembly 2 dropped to zero steps from 178 steps No component failures causing control element assembly to drop CROCKETT. J. Northeast Nuclear Energy Co. (Northeast Utilities) 78/07/14 1p
- 7906040295 Forwards LER 78-023/03L-0 OPEKA, J F Northeast Utilities 78/10/13 lp
- ---7906040307 LER 78--023/03L-0 on 780912 during routine steady-state operation, spent fuel storage ventilation gaseous radiation monitor failed low Caused by shorted local alarm horn which blew power supply fuse Horn disconnected & fuse replaced CROCKER, J A Northeast Utilities 78/10/12 ip
- 7906120395 Forwards LER 79-012/01T-0 OPEKA.J F Northeast Utilities 79/06/05 ip
- --7906120401 LER 79-012/01T-0 on 790522 during rise to 30% power two of four linear power range channels found to be inoperable Open connections found between detector cables & field wiring Caused by connector pins pushed into connector STRATMAN.R A Northeast Utilities 79/06/05 2pp
- 7906180495 Forwards LER 78-019/03X-2 OPEKA:JF Northeast Utilities 79/06/14 1p.
- --7906180499 LER 78-019/03X-2 on 780803 while operating i3U diesel for surveillance, leaking injector pump observed Caused by elamental lead inclusions, resulting in stress risers at surface of valve cages
  STRATMAN,R A Northeast Utilities 79/06/14. 2pp
- 7906290260 Forwards LER-79-013/03L-0 OPEKA.J F Northeast Utilities 79/06/22 ip
- ---7906290269 LER 79-013/03L-0 on 790525 during check of control room chlorine detection sys, both detectors declared inoperable due to low drip rates in sensor Caused by clogged dispensers Dispensers cleaned, restoring operability BATES,R W Northeast Utilities 79/06/22 1p
- 7906290277 Forwards LER 77-056/03X-2 OPEKA, J F Northeast Utilities 79/06/26 1p
- --7706290270 LER 77-056/03X-2 on 771118 during routine operation, aerated waste evaporator concentrates tank was pressurfied w/air & ruptured Caused by application of 100 psi air to tank w/blockage in the in unvalved vent line. No repair planned \*\* Northeast Utilities 79/06/15 2pp.
- DOCKET 50-338 NORTH ANNA POWER STATION, UNIT 1
- F Security, medical, emergency & fire protection plans
- 7906150134 Requests investigation of two SER items.beliaved to be unjustified Sprinkler coverage on 259 5 elevation is unnecessary since area above base of pumps is solid concrete SRCHN.S C Virginia Electric & Power Co 79/06/ii 2pp

#### Q Adjudicatory correspondence

- 7903210437 Confirms 790300 meeting in Bethesda,MD u/parties to proceeding to discuss admissibility of Citizens' Energy Forum contentions
  OCLOBERO,S C Branch 2 79/03/02 1p
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO, J. F. Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
  CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7706010161 Forwards two stipulations of contentions elecuted & served at 770329 prehearing conference GOLDBERG.5 C Branch 2 77/04/04 1p
- 7906050053 Forwards util testimony & exhibits to be presented as evidence at public hearing during week of 790618 W/o encl CHRISTMAN, J N Hunton & Hilliams 79/04/27 4pp
- 7906200596 Objects to ASLB 790421 order Requests reinstatement of contention labeled "alternatives" & seeks severance from Citizens Energy Forum on emissions issue Certificate of Svc encl DOUGHERTY.S B Potomac Alliance 79/05/02 5pp
- 7906200592 Requests that ASLB reverse denial of contentions acceptable to util.NRC & intervenors Seeks admission of heavy load & leakage issues & contentions re EIS & need for present mod Certificate of Svc encl KROOT, I B Citizens Energy Forum 79/05/03 App
- 7906220125 Forwards addi portions of "NRC Staff Testimony re Pumphouse Settlement" SHAMSON,D T Branch 1 79/05/04 75pp
- 7906220219 Forwards response to 790407 & 10 interrogatories & document requests from intervenor 0 Arnold Objects to some questions & requests that are irrelevant to pumphouse settlement Certificate of Syc enc!

  CHRISTMAN.J N Hunton & Williams 79/05/04 5pp
- --790622020 Response to 790407 % 10 interrogatories & document requests from intervenor G Arnold re pumphouse settlement Supporting documentation encl Virginia Electric & Power Co 79/05/04 57pp
- 7906270278 Requests that ABLB postpone 790626 prehearing conference to 790724 Add1 time necessary for discovery & filing of motions Certificate of Suc encl KROOT.I B Citizens Energy Forum 79/05/18 3pp
- 7906200362 Evidentiary hearing re pumphouse settlement & turbine missile issues will commence on 790618 in Bethesda, MD Names of witnesses & counsel must be submitted by 790608 SKRUTSKI,R M Atomic Safety and Licensing Appeal Penel 79/05/21
- 7906210095 NRC motion for summary disposition re radon issure was in error:ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLO:H E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906210367 ASLAB will not take oral limited appearance statements at 790618 evidentiary hearing re pumphouse settlement & turbine missile issues ASLAB will accept written statements to be included in record.

  DUFLOWNE Atomic Safety and Licensing Appeal Panel 79/05/30 2pp

# J Insurance & indemnity information

- 7906120324 Endorsement 41 to NELIA Policy MF-57
  OERAS, T Hutual Atomic Energy Liability Underwriters 79/05/10
- 7906120331 Endorsement 42 to MAELU Policy MF-57
  OEROS.T Mutual Atomic Energy Liability Underwriters 79/05/10

- P Operating license stage documents & correspondence
- 7906070313 Forwards Amend 10 to License NPF-04.safety evaluation & notice of issuance & availability PARR.O D Light Water Reactors Branch 3 79/04/27 4pp
- --7906070319 Amend 10 to License NPF-04.incorporating changes to Tech Specs re structural integrity of reactor coolant pump section elbow splitter VASSALLO. D B Assistant Director for Light Water Reactors 79/04/27 15pp
- --7906070321 Safety evaluation supporting Amend 10 to License NPF-04 \* Light Water Reactors Branch 3 79/04/27 13pp
- ~~7906070325 Notice of issuance & availability of Amend 10 to License NPF-04 PARR.O D Light Water Reactors Branch 3 79/04/27 2pp
- 7906260623 "Results of Acceptance Fests of Outside Recirculating Spray Pump," final rept RAUCH, B Franklin Institute FIN 2-6567 7906260623 79/04/30 35pp
- 7906020242 Requests review of electrical power sys re conditions which could result in simultaneous or consequential loss of both required circuits to offsite network VASSALLO,D B Assistant Director for Light Water Reactors 79/05/02 9pp
- 7706020125 Forwards 770405 itr from J Allen of North Anna Environ Coalition requesting revocation of QLs Ltr is being treated as request for action per 10CFR2 706 Also forwards FR notice Ltr not encl DENTON: HR Office of Nuclear Reactor Regulation 79/05/04 1
- --7906020130 Notice of 790405 North Anna Environ Coalition request for NRC to revole OLs due to alleged nonconformance of estimated peak fuel cladding temps w/sids of 10CFR30 45(b) DENTON,H R Office of Nuclear Reactor Regulation 79/05/04 2pp
- 7906250317 Summary of 790508 meeting w/util to discuss auxiliary feedwater sys 5 Telated station areas
  GROTENHUISH Operating Reactors Branch 1 (Pre 790625)
  79/05/07 4pp
- 7906200520 Rejects util 790313 ltr requesting exemptions to Tech Specs requirements re demonstration of operability of each diesel generator once every 18 months PARR. O D Light Water Reactors Branch 2 79/05/14 3pp
- 7906180767 Grants 79030B request for withholding rept "Syc Water Reservoir & Spray Sys Performance Testing Evaluation" (ref 10CFR 2 790) PARR.Q D Light Water Reactors Branch 3 79/05/17 Spp
- 7906290841 Discusses radiological effluent tech specs for facility Requires submittal of solid waste process control program & Offsite Dose Calculation Manual by 790701 PARR.O D Light Water Reactors Branch 3 79/09/23 4pp
- 7906010237 Submits info re treatment & releaso of liquid wastes, in response to NRC 790323 ltr STALLINOS.C M Virginia Electric & Power Co 79/05/29 App
- 7906010268 Corrects designations re svc water pumphouse included in survey of expansion joints encl Oversized drawing encl BROWN, 8 C Virginia Electric & Power Co 79/05/29 6pp
- 7706050336 Advises that Units 3 & 4 should also be included on 7705i8 ltr BROWN,8 C Virginia Electric & Power Co 77/05/30 ip
- 790A030323 Discusses 770110 rept "GA Program Operations Phase." Requests exception from ANSI N45.2 4 \$ N45.2 8 paragraphs recall for control \$ equipment test Discusses proposed alternative

  BAUM, E. A. Virginia Electric & Power Co. 79/05/31 2pp.
- 7906290199 Forwards corrections for 790402 EIA re expansion of spent fuel pool REGAN,W H Environmental Projects Branch 2 79/06/01 4pp
- 7906210235 Schedule requested in NRC 790601 ltr re instrument qualification will be submitted by 790715 STALLINGS,C M Virginia Electric & Power Co. 79/06/19 ip

- 7906250261 Forwards info re PHR feedwater piping.in response to 790525 request Addl info to be sent by 790727 STALLINGS.C M Virginia Electric & Power Co 79/06/20 4pp
- G Inspection reports, IE Bulletins & correspondence
- 7906050376 Forwards IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790109-12 No noncompliance noted LEWIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/27 2pp
- --79060503B2 IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790109-12 No noncompliance noted Major areas inspected pre-operational containment integrated leak testing & testing pipe support & restraint sys testing
  JOHNSON.A H , BROKS,E H , MARTIN.R D Region 2, Atlanta,
  Reactor Operations Nuclear Support Branch 79/03/21 7pp
- 7906210419 Forwards IE Insp Repts 50-338/79-14 & 50-339/79-20 on 790326-27 No noncompliance noted SUTHERLAND. J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/16 2pp
- --7906210422 IE Insp Repts 50-338/79-14 & 50-339/79-20 on 790326-29 No noncompliance noted Major areas inspected scaled source leak tests followup on inspector identified items & installation & calibr of radiation monitoring sys JENKINS: 0 R Region 2. Atlanta. Office of the Director OIBSON.A F Region 2. Atlanta. Fuel Facility & Materials Safety Branch 79/04/16 4pp
- 7706200311 Forwards IE Insp Rept 50-338/79-10 & 50-339/79-15 on 790305-09 No noncompliance noted LENIS.R C Region 2. Atlanta, Office of the Director 79/04/19 2pp
- --7906200318 IE Insp Rept 50-338/79-10 & 50-339/79-15 on 790305-09 No noncompliance noted Major areas inspected operations review. IE bulletin & circular review & review of containment purge CANTRELLES & DYER, J A . WEBSTER.E H Region 2. Atlanta, Office of the Director 79/04/16 14pp
- 790625034; Forwards LE Insp Rept 50-338/79-17 on 790410-11 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 2pp
- --7906250345 IE Insp Rept 50-338/79-17 on 790410-11 No noncompliance noted Major areas inspected ultrasonic insp of reactor coolant pump elbow splitter plates CONLONIT E. CROWLEY: B R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/20 3pp
- 7706160070 Responds to IE Bulletin 77-07 re seismic analysis of safety-related piping Forwards 770419 ltr from Nuclear Svcs Corp & 770420 ltr from Teledyne Engineering Svcs SPENCER W C Virginia Electric & Power Co 77/04/24
- 7706010304 Forwards IE Insp Rept 50-338/79-13 on 770305-15 No noncompliance noted O'REILLY,J P Region 2. Atlanta, Office of the Director 77/04/23 2pp
- 7906180305 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-338/79-09 & 50-339/79-14 LEWIB.R C. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/05/02 Ip
- ---7906180312 Responds to NRC 790329 ltr re violations noted in IE Insp Repts 50-338/79-09 & 50-339/79-14 Corrective actions field changes completed & ADM 104 O cover sheet modified 57ALLINOS.C M Virginia Electric & Power Co 79/04/23 2pp
- ---7906180315 Forwards IE Insp Repts 50-338/77-09 & 50-339/79-14 on 790205-0302 & notice of violation LEWIS,R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/29 2pp
- --7906180321 Notice of violation from insp on 790203-0302 # Region 2: Atlanta, Office of the Director 79/03/22 ip

- --7906180355 IE Insp Repts 50-338/79-09 & 50-339/79-14 on 790205-0302
  Noncompliance noted failure to follow procedures for
  assuring completion of corrective action
  KIDD,M S Region 2, Atlanta, Office of the Director
  CANTRELL,F S Region 2, Atlanta, Reactor Operations Nuclear
  Support Branch 79/03/22 lipp
- 7906110068 Forwards IE Bulletin 79-10. "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/11 | 1p
- 7906180536 Responds to IE Bulletin 79-01 Forwards "Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Environ Qualification Requirements " BTALLINGS, C M Virginia Electric & Power Co 79/06/14 ip
- --7906180538 "Failure of Solenoid Operated Valves to Meet IE Bulletin 79-01 Environ Qualification Requirements "Environmentally unqualified valves have been or will be replaced Virginia Electric & Power Cd 79/06/14 2pp
- R Periodic operating reports & related correspondence
- 7706180491 Farwards monthly operating rept for May 1979 STALLINGS,C M Virginia Electric & Power Co 79/06/13 ip
- --7906180493 Monthly operating rept for May 1979
  MADISON, W. R. Virginia Electric & Power Co. 79/06/04 App
- S Reportable occurrences, LERs & related correspondence
- 7906140475 RO 79-057/01T-0 on 790424 potential overload exists, 4, 160 voit transfer bus & feeder breakers are not capable of continually carrying full load current Caused by improper sizing of transfer bus equipment

  \* Virginia Electric & Power Co 79/04/25 1p
- 7906050255 Forwards LER 79-073/01T-0 STALLINOS.C M Virginia Electric & Power Co 79/05/31 ip
- --7906050260 LER 79-073/01T-0 on 790517 incorrect valve weights used for stress calculations involving accumulator isolation motor operated valves Gause unknown Minor adjustment to spring hanger will restore compliance CARTHRIGHT.H R Virginia Electric & Power Co 79/05/31 2pp
- 7906030293 Forwards LERs 77-059/031-0, 79-060/031-0, % 79-063/031-0 STALLINGS,C M Virginia Electric & Power Co 79/05/31 1p
- --7906030295 LER 79-059/03L-O on 790501 fire protection hose stations in auxiliary bldg were inoperable for 10-h w/o backup sys of firewatch established Caused by isolation of auxiliary bldg for maint taking longer than initially estimated CARTWRIGHT.W R Virginia Electric & Power Co 79/05/31 ip
- --7906030298 LER 79-060/03L-0 on 790502 during routine startup operation, axial flux difference deviated greater than 57 from target Caused by power increasing too rapidly during startup operation CARTWRIGHT, W R Virginia Electric & Power Co 79/05/31 2pp

- --7906110160 LER 79-066/03L-0 on 790906 narrow range level transmitter LT-496 in L steam generator read erratically Channel inoperable Probable cause was drain lines off both high & low pressure sides of transmitter Lines capped CARTHRIGHT.W R Virginia Electric & Power Co 79/06/04 2pp
- --7906110162 LER 79-074/03L-0 on 790516 pressurizer level indicator L-1460 failed during performance of 1-PT-31 7 2 Cause unknown Hires reconnected & surveillance undertaten CARTWRIGHT,W R Virginia Electric & Power Co 79/06/04 2pp
- 790611019B Forwards LERs 79-068/3L-0.79-069/03L-0 & 79-071/03L-0 STALLINGS.C M Virginia Electric & Power Co 79/06/06 ip
- --7906110200 LER 79-068/03L-O on 79050B radiation monitoring channels RM-RMS-159 & RM-RMS 160 were declared inoperable due to failure of sample pumps 1-RM-RMS 159A & 159B Caused by solenoid valve coil shoring out Coil replaced CARTWRIGHT.N R Virginia Electric & Power Co 79/06/06 2pp
- --7906110202 LER 79-069/03L-0 on 790508 during load transient, axial flux difference deviated greater than 5% from target for four minutes Caused by rapid load reduction of 100 MH due to loss of drain pump A Control rods withdrawn CARTHRIGHT, H R Virginia Electric & Power Co 79/06/06 2pp
- --7906110204 LER 79-071/03L-0 on 790511 during periodic test at steady state operation low head safety injection pump 1A discharge valve failed to open within 40-s Cause unknown Valve manually opened reseated & returned to operation CARTHRIGHT.H R Virginia Electric & Power Co 79/06/06 2pp
- 7906110207 Forwards LER 79-070/03L-0 STALLINGS,C M Virginia Electric & Power Co 79/06/06 1p
- --7906110211 LER 79-070/O3L-0 on 790511 hose station AB-H-24 was isolated to perform maint on angle valve 1-FP-160 Caused by angle valve leak Angle valve replaced & hose station returned to operable status

  CARTWRIGHT.W R Virginia Electric & Power Co 79/06/07 1p
- 7906180543 Forwards LER 79-084/03L-0 STALLINGS: C M Virginia Electric & Power Co 79/06/13 tp
- --7906180544 LER 79-054/O3L-O on 790513 charging pump removed from svc to repair crack inlet piping Coused by bad weld at base of vent line Crack ground out & rewelded CARTHRIGHT.W R Virginia Electric & Power Co 79/06/12 2pp
- 7906200386 Forward's LER 79-077/03L-0 STALL[NGS:C M Virginia Electric & Power Co 79/06/18 1p
- --7906200389 LER 79-077/03L-0 on 790331 during power reduction, axial flux difference deviated greater than 5% from target Caused by rapid reduction necessitated by high bearing temp of feedwater pump C boration Corrected problem CARTHRIGHT.H R Virginia Electric & Power Co 79/06/18 2pp
- 7906290196 Forwards LERs 79-075/03L-0,79-081/03L-0 & 79-080/03L-0 BTALLINGS,C M Virginia Electric & Power Co 79/06/27 ip
- ---7906290205 LER 79-075/03L-0 on 790604 during steady state operation, axial flux difference deviated over 5% from target for two minutes; contrary to Tach Specs Caused by zenon oscillation initated by rod operability test Power reduced by 2% CARTWRIGHT:W R Virginia Electric & Power Co 79/06/27 2pp
- --7906290239 LER 79-081/03L-0 on 790608 individual red position indicators M-10 & D-10 placed in test status, contrary to Tech Specs Caused by repair work to remove previously installed jumper Calibr performed CARTHRIGHT, NR. Virginia Electric & Power Co 79/06/27 2pp
- --7906290215 LER 79-080/O3L-0 on 790608 during power escalation, exial flux difference deviated more than +5% from target for 16 minutes, contrary to Tech Specs Caused by withdrawal of control rods
  CARTWRIGHT, W R Virginia Electric & Power Co 79/06/27 2pp
- T Hearing transcripts on non-antitrust matters
- 7906290031 Transcript of 790618 meeting in Bethesda, MD Pp 1-200 ROBENTHAL, A S , BUCK, J H. , FARRAR, M G. Atomic Safety and Licensing Appeal Fanel 79/06/18 203pp,

- 7906290038 Transcript of 790619 meeting in Bethesda.MD Pp 201-458 ROSENTHAL.A S . BUCK.J H . FARRAR.M C Atomic Safety and Licensing Appeal Panel 79/06/19 259pp
- 7906270090 Transcript of 790620 hearing in Bethesda.MD Pp 459~623 ROSENTHAL.A S . BUCK.J H . FARRAR.M C Atomic Safety and Licensing Appeal Panel 79/06/20 182pp
- U Congressional/Executive Correspondence
- 7906050007 Forwards constituent's ltr re opening of plant BUTLER.M C House of Rep 79/04/19 2pp
- DOCKET 50-339 NORTH ANNA POWER STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7906070313 Forwards Amend 10 to License NPF-04, safety evaluation & notice of issuance & availability
  PARR.O D Light Water deactors Branch 3 79/04/27 4pp
- --7906070319 Amend 10 to License NPF-04, incorporating changes to Tech Specs re structural intagrity of reactor coolant pump section elbow splitter VASSALLO, D B Assistant Director for Light Water Reactors 79/04/27 19pp
- --7906070321 Safety evaluation supporting Amend 10 to License NPF-04

  \* Light Water Reactors Branch 3 79/04/27 13pp
- --7906070325 Notice of issuance & availability of Amend 10 to License NPF-04 PARR.O D Light Water Reactors Branch 3 79/04/27 2pp
- 7906260216 Discusses draft safety evaluation re exemptions to requirements of Apps G.H & J of 10CFR50 ROS6.D F Division of Project Management 79/05/02 12pp
- 7906060020 Porwards evaluation & request for add1 info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation " Requests response by 790518 PARR.O D Light Water Reactors Branch 3 79/05/03 5pp
- 7906180767 Grants 790308 request for withholding rept "Svc Water Reservoir & Spray Bys Performance Testing Evaluation" (ref 10CFR 2 790) PARR.O D Light Water Reactors Branch 3 79/03/17 Spp
- 7906290841 Discusses radiological effluent tech specs for facility Requires submittal of solid waste process control program & Offsite Dose Calculation Manual by 790701 PARR.O D Light Hater Reactors Branch 3 79/05/23 4pp
- 7904010237 Submits info re treatment & release of liquid wastes,in response to NRC 790323 ltr STALLINGS C M Virginia Electric & Power Co 79/05/27 4pp
- 790601026B Corrects designations re-svc water pumphouse included in survey of expansion joints encl Oversized drawing encl BROWN.S C Virginia Electric & Power Co 79/03/29 6pp
- 7906050251 Requests issuance of OL for facility, in spite of G-month moratorium imposed by NRC PROFFIT: # L Virginia Electric & Power Co 79/05/30 2pp
- 7706050336 Advises that Units 3 & 4 should also be included on 790518 Itr BROWN:8 C Virginia Electric & Power Co 79/05/30 1p
- 7906050323 Discusses 770110 rept "GA Program, Operations Phase "
  Requests exception from ANBI N45 2 4 & N45 2 8 paragraphs re
  calibr control & equipment test Discusses proposed
  alternative
  BAUM.E A Virginia Electric & Power Co 79/05/31 2pp
- 7906290199 Forwards corrections for 790402 EIA re expansion of spent fuel pool REGANN H Environmental Projects Branch 2 79/06/01 4pp
- 7906190338 Requests 790715 completion date for facility review conducted in response to TMT incident Util will submit rept discussing reccommended actions by 790701 PROFFITTM L. Virginia Electric & Power Co 79/06/14 2pp

- 7906250261 Forwards info re PHR feedwater piping in response to 790525 request Addl info to be sent by 790727
  BTALLINGS, C M Virginia Electric & Power Co 79/06/20 4pp
- 7906250280 Bubmits addi info re instrument qualification, in response to 790601 request Use of Barton transmitters is fully justified, based on presently & previously submitted data Use of sample lines from prinary sys components under review BROWN.5 C Virginia Electric & Power Co 79/06/22 2pp
- F Security, medical, emergency & fire protection plans
- 7906150134 Requests investigation of two BER items, believed to be unjustified Sprinkler coverage on 259 5 elevation is unnecessary since area above base of pumps is solid concrete

  BROWN. 8 C Virginia Electric & Power Co 79/06/11 2pp
- Q Adjudicatory correspondence
- 7903210437 Confirms 790308 meeting in Dethesda,MD w/parties to proceeding to discuss admissibility of Citizens' Energy Forum contentions GDLDBERG.B C Branch 2 79/03/02 ip
- 7906210047 Matian for extension until 790411 to prepare response to ALAB-509 SCINTGLJ.F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7904010141 Forwards two stipulations of contentions executed & served at 790329 prehearing conference OOLDBERG.6 C Branch 2 79/04/04 1p
- 7906090033 Forwards util testimony & exhibits to be presented as evidence at public hearing during week of 790618 W/o encl CHRISTMAN.J N Hunton & Williams 79/04/27 App
- 7706200596 Objects to ABLB 770421 order Requests reinstatement of contention labeled "alternatives" & seeks severance from Citizens Energy Forum on emissions issue Certificate of Bvc encl DOUGHERTY, 8 8 Potomac Alliance 79/05/02 5pp
- 7906200592 Requests that ASLO reverse denial of contentions acceptable to util NRC & intervenors Beeks admission of heavy load & leakage issues & contentions re EIG & need for present mod Certificate of Bvc encl KROOT, I B Citizens Energy Forum 79/05/03, 4pp
- 7906220123 Forwards add1 portions of "NRC Staff Testimony re Pumphouse Settlement " SMANBON,D T Branch 1 79/05/04 95pp
- 7906220219 Forwards response to 790407 & 10 interrogatories & document requests from intervenor 0 Arnold Objects to some questions & requests that are irrelevant to pumphouse settlement Certificate of Bvc end CHRISTMAN, J N Hunton & Williams 79/09/04 Spp
- --790622020 Response to 790407 % 10 interrogatories & document requests from intervenor G Arnold re pumphouse settlement Supporting documentation encl \* Virginia Electric & Power Co 79/05/04 57pp
- 7906270278 Requests that ASLB postpone 790626 prehearing conference to 790724 Add1 time necessary for discovery & filing of motions Certificate of Svc encl KROOT, I B Citizens Energy Forum 79/05/18 3pp
- 7906200562 Evidentiary hearing re pumphouse settlement & turbine missile issues will commence on 790618 in Bethesde, MD Names of witnesses & counsel must be submitted by 790609 GKRUTSKI.R M. Atomic Safety and Licensing Appeal Panel 79/05/21 in
- 7706210095 NRC motion for summary disposition re radon issure was in error; ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLO, H. E. Atomic Bafaty and Licensing Appeal Panel 79/05/25
  300.

- 7906210367 ASLAB will not take oral limited appearance statements at 790618 evidentiary hearing re pumphouse settlement & turbing missile issues ASLAB will accept written statements to be included in record DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/30
- J Insurance & indemnity information
- 7906120324 Endorsement 41 to NELIA Policy MF-57 GERAS.T Mutual Atomic Energy Liability Underwriters 79/05/10
- 7906120331 Endorsement 42 to MAELU Policy MF-57 GEROS.T Mutual Atomic Energy Liability Underwriters 79/05/10
- G Inspection reports, IE Bulletins & correspondence
- 7906090376 Forwards IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790109-12 No noncompliance nated LEWIG.R G Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/27 2pp
- --7906050382 IE Insp Repts 50-338/79-02 & 50-339/79-04 on 790109-12 No noncompliance noted Major areas inspected pre-operational containment integrated leak testing & testing pipe support & restraint sys testing JOHNSON.A H. BROKS.E H. MARTIN.R D. Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/21 7pp
- 790607010B Forwards [E Insp Rept 50-339/79-17 on 790306-08 No noncompliance noted MURPHY.C E Region 2. Atlanta, Safeguards Branch 79/03/28 20p
- --7906070114 IE Insp Rept 50-339/79-17 on 790306-08 No noncompliance noted Major areas inspected preservice insp of reactor vessel weids 5 steam generator C tube work observation, data review % evaluation CONLON.TE Region 2. Atlanta. Safeguards Branch ECONOMOS,N Region 2, Atlanta. Office of the Director 79/03/28 Spp
- 7906210419 Forwards IE Insp Repts 50-338/79-14 & 50-339/79-20 on 790326-29 No noncompliance noted SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/16 2pp
- --7906210422 IE Insp Repts 50-338/79-14 & 50-339/79-20 on 790326-29 No noncompliance noted Major areas inspector scaled source leak tests; followup on inspector identified (tems & installation) calibr of radiation monitoring sys JENKINS; 0 R Region 2. Atlanta, Office of the Director OIBSON A F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/04/16 4pp
- 7906200311 Forwards IE Insp Rept 50-338/79-10 % 50-339/79-15 on 790305-09 No noncompliance noted LEMIS/R C Region 2. Atlanta. Office of the Director 79/04/19 200
- --7906200318 IE Insp Rept 30-338/79-10 & 90-339/79-15 on 790305-09 No noncompliance noted Major areas inspected operations review, IE builetin & circular review & review of containment purge CANTRELL,F S . DYER, J A . WEBSTER.E H Region 2. Atlanta, Office of the Director 79/04/16 14pp
- 7906260524 Forwards IE Insp Repts 50-339/79-23,50-404/79-01 & 50-405/79-01 on 790410-12 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction Support Branch 79/04/25 2pp.
- --7906260327 IE Insp 50-339/79-23,50-40° ''' 790410-12 No noncompilance noted Ma 100FR90 55(6) items, blasting of °-21 notices MCFARLAND, C R , HERDT, A R Construction & Engineering Sup

100

- --7906180315 Forwards IE Insp Repts 50-338/79-09 & 50-339/79-14 on 790205-0302 & notice of violation LENIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/29 2pp
- --7906180321 Notice of violation from insp on 790205-0302
  \* Region 2. Atlanta, Office of the Director 79/03/22 1p
- --7906180355 IE Insp Repts 50-338/79-09 & 50-339/79-14 on 790205-0302
  Noncompliance noted failure to follow procedures for
  assuring completion of corrective action
  KIDD.M 8 Region 2, Atlanta, Office of the Director
  CANTRELL.F 5 Region 2, Atlanta, Reactor Operations Nuclear
  Support Branch 79/03/22 11pp
- 7906140487 Advises of response to IE Bulletin 79-03 re Youngstown weld defects.by 790611 BROWN:S C Virginia Electric & Power Co 79/09/10 lp
- 7906180536 Responds to IE Bulletin 79-01 Forwards "Failure of Solenoid Operated Valves to Meet IE Gulletin 79-01 Environ Qualification Requirements" STALLINGS.C M Virginia Electric & Power Co 79/06/14 lp
- --7906180538 "Failure of Solonoid Operated Valves to Heet IE Bulletin 79-01 Environ Qualification Requirements "Environmentally unqualified valves have been or will be replaced \* Virginia Electric & Power Co 79/06/14 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906250240 Notifies that six solenoid operated valves on containment isolation valves in sampling sys lacked environ qualification data All valves replaced prior to fuel loading BROWN,8 C Virginia Electric & Power Co 79/05/16 2pp
- 7906140421 Submits rept re potential overloads of electrical sys supplying offsite power for startup calculations. Review shows automatic shedding of certain non essential normal loads will provide adequate voltage profile BRQHN.S C Virginia Electric & Power Co 79/05/23 3pp
- 7906140432 Submits final rept on deficiency reported 790321 angle from braces located on exhaust ducting of diesel generator cooling fans Failure of angle from brace tack welds could have damaged fans Braces removed BROWN.
- 7906120178 Final deficiency rept re pipe stress analysis passing through main steam valve house Manufacturer of quench apray norzie gump will complete work to new specs & return pump to svc prior to fuel loading BRDWN.S C Virginia Electric & Power Co 79/06/06 200

- 790627003B Transcript of 790619 meeting in Bethesda,MD Pp 201-458 ROSENTHAL, A S . BUCK, J H . FARRAR, M C Atomic Safety and Licensing Appeal Panel 79/06/19 259pp
- 7906270090 Transcript of 790620 hearing in Bethesda, MD Pp 499-623 ROSENTHAL, A S . BUCK, J H . FARRAR, M C Atomic Safety and Licensing Appeal Panel 79/06/20 182pp
- U Congressional/Executive Correspondence
- 7906050007 Forwards constituent's ltr re opening of plant BUTLER.M C House of Rep 79/04/19 2pp
- DOCKET 50-341 ENRICO FERMI ATOMIC POWER PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7906010316 Notification of 790311 site visit w/util at Monros County.MI to tour facility
  KINYNER, L. Light Water Reactors Branch 1 79/04/30 2pp
- 7906050204 Lists generic Mark I owners group documents transmitted to NRC by GE, which are applicable to facility
  JENS.H H Detroit Edison Co 79/05/23 2pp
- 790619037B Forwards Certificate of Svc for Amend 23 to amended & substituted application for license HATERS.B R Detroit Edison Co 79/06/07 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906010052 Ack receipt of 790409 interim rept re terminal block deficiency FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 ip
- G Adjudicatory correspondence
- 7903200319 Forwards stipulation of contentions signed by all parties If acceptable, contentions should be adopted as issues by ASLB order, which would also begin formal discovery BLACK-R L. Branch 1 79703/05 1p
- --7903200326 Stipulation of contentions & agreement among parties
  Contentions refer to const problems & design of radiation
  monitoring sys
  HILLER, D Citizens for Energy & Employment BLACK, R L Branch
  1 VOIOT, H H Detroit Edison Co. 79/02/28 Spp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906010233 Forwards Amend 23 to FSAR Page withheld (ref 10CFR2 790) VOIQT.H H LeBoeuf, Lamb, Leiby & MacRae 79/05/31 3pp
- --7906010236 Amend 23 to FSAR Proprietary page withheld (ref 1907R2 790) Affidavit encl \* Detroit Edison Co 79/05/29 170pp
- O Inspection reports, IE Bulletins & correspondence
- 906140647 Forwards IE Insp Rept 90-341/79-07 on 790314-16 & notice of violation FIGRELLI, Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- ~7906140651 Notice of violation from insp on 790314-16 \* Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/04 1p
- -790614065B IE Insp Rept 50-341/79-07 on 790314-16 Noncompliance noted inadequate hanger insp corrective action DANIELEGN, D.H., YIN.I T Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/02 Spp
- 706130136 Forwards IE Insp Rept 50-341/79-08 on 790327-30 & notice of violation FIGRELLI, O Region 3, Chicago, Office of the Director 79/04/10 2pp
- -7906130139 Natice of violation from insp on 790327-30 \* Region G. Chicago, Office of the Director 79/04/05 ip

- --7906130143 IE Insp Rept 50-341/79-08 on 790327-30 Noncompliance noted failure to follow procedure for welding activities & records LEC,E W Region 3, Chicago, Office of the Director 79/04 Region 3. Chicago. Office of the Director 79/04/05 Яρр
- 7906140601 Forwards IE Insp Rept 50-341/79-10 on 790329-30 No nancompliance notes 3. Chicago, Reactor Construction & Engineering HINES.E Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/12 2pp Support Branch
- --7906140607 IE Insp Rept 50-341/79-10 on 790329-30 No noncompliance of noncompliance & related unresolved matters

  DANIELSON. D H , HILLIAMS. C Region 3. Chicago, Reactor
  Construction & Engineering Support Branch 79/04/09 Spp
- 7906260592 Forwards IE Insp Rept 50-341/79-09 on 790103-04 & notice of violation FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/19 2pp
- --7906260594 Notice of violation from insp on 790103-04 \* Region 3, Chicago, Office of the Director 79 79/04/19 200
- --7906260598 IE Insp Rept 30-341/79-09 on 790103-04 Noncompliance noted inadequate qualifications of personnel & maint of test records HARD, K D . MARSH, R J . DANIELSON, D H of the Director 79/04/16 13pp Region 3, Chicago, Office
- 7906:20106 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J O Region 3. Chicago. Office of the Director 79/05/07
- 7906040449 Ack receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-05 FIORELLIA Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/05/10 ip
- --7906040455 Responds to NRC 790327 ltr re violations noted in 1E Insp Rept 50-341/79-05 Corrective actions review of backfill repts was done to evaluate quantities & determine areas not adequately tested HINES, E Detroit Edison Co 79/04/26 3pp
- 790540454 Responds to IE Bulletin 79-09 re failure in GE Type AK-2 low voltage power circuit breaker Breaker not in use or planned for use HINES, E Detroit Edison Co 79/05/10 2pp
- 7906190092 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/11
- 7706280225 Forwards response to IE Bullstin 79~03 dtd 770312 ABME SA-312.Type 304 or other wolded pipe mfg by Youngetown Helding & Engineering Co not in use at facility HINES.E Detroit Edison Co 77/05/14 3pp
- 7906:30098 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee an circuit breakers for engineers between 99 accounts action required KEPPLER: J O Region 3, Chicago, Office of the Director 79/05/22
- 7906260097 Ack receipt of 790504 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-341/79-07 FIDRELLI, G Region 3. Chicago: Reactor Construction & Engineering Support Branch 79/05/23 in
- ---7906260108 Responds to NRC ltr re violations noted in IE Insp Rapt 50-341/79-07 Corrective actions Wisner & Becker procedures were modified HINES.E Detroit Edison Co 79/05/04. 5pp
- 7706200118 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29
- 7906290687 Ack receipt of 790511 ltr informing NRC of steps taken to correct violation noted in IE Insp Rapt 50-341/79-08 FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch. 79/05/30 ip

- -7906270674 Responds to NRC 770410 itr re violation noted in IE Insp. Rept 50-341/77-08 Corrective actions written reprimend will be issued to general foreman for unauthorized methods of implementing repairs Add training will be given HINES, E. Detroit Edison Co. 79/05/El. 3pp
- S Reportable occurrences, LERs & related correspondence
- 7906230076 Ack receipt of 790501 final rept re torus ring beam weld indications Review will be completed during future inap FIGRELLI.G Region 3, Chicago. Reactor Construction & Engineering Support Branch 79/05/23 ip
- 7906080263 Confirms 780419 teleon in which I/RC notified util that variation in insulation thickness on LE cable jacketing was determined "nohreportable"
  FAHRNER: W J Detroit Edison Co 79/05/25 1p
- 7906080264 Confirms 7Bil21 telcon in which NRC notified util that cracking of impeller vane of core spray pumps 8 & C was determined "nonreportable"
  FABRNER,W J Detroit Edison Co 79/05/25 ip
- DDCKET 50-344 TROJAN NUGLEAR PLANT, UNIT 1 E NRC Safety Evaluation Report (SER), supply & correspondence
- 7906260466 Forwards addl info re installation of isolation switches at local control stations for safe shutdown equipment b addl design details for inclusion in 790308 SER, in response to 790214 & 0418 requests

  GOODWIN, C Portland General Electric Co 79/06/18 48pp
- F Security, medical, emergency & fire protection plans
- 7906200303 Forwards request for add1 info re fire protection to complete safety evaluation SCHMENGER.A Operating Reactors Branch 1 (Pre 790625) 79/04/18
- O Adjudicatory correspondence
- 7906070360 First set of interrogatories submitted to N Bell & Consolidated Intervenors Affidavit & Certificate of Syc JOHNSON.R W Portland General Electric Co 79/03/05 13pp
- ---7906070362 First set of interrogatories submitted to E Rosolie & Coalition of Bafe Power Affidavit of Evc encl
  JOHNSON,R W Portland General Electric Co 79/03/05 10pp
- 7906180712 Motion for order compelling N Beil & Consolidated Intervenors to respond to encl 790305 interrogatories Certificate of Byc encl JOHNSON R W Portland General Electric Co AXELRAD.M . CARR.A V Lowenstein, Newman, Reis, Axelrad & Toll 79/03/23 4pp
- --7906180719 Licensee's first set of interrogatories to N Bell & Consolidated Intervenors Affidavits & Certificate of Syc JOHNSON, R W Portland General Clectric Co 79/03/05 14pp
- 7706040396 Confirms action taken during prohearing conference, Phase II, re-contentions of Coalition for Safe Power & Consolidated Intervenors Directs intervenors to give fuller responses to intervenores Adopts Phase II schedule
  MILLER, M.E. Atomic Bafety and Licensing Board Panel 77/04/12
- 7906040165 Answers by Consolidated Intervenors to second phase of first set of NRC interrogatories Certificate of Svc encl
  BELL.N Affiliation Unknown 79/04/14 Spp
- --7906040168 Answers by Consolidated Intervenors to licensee's first set of interrogatories BELL:N Affiliation Unknown 79/04/14 4pp
- 7906010076 Opposes 790410 petition of 8M Garrett pro se & for Coalition for Safe Power, seeking NRC review of ASLAB 790321 decision Certificate of Svc encl HASTINOS, W Portland General Electric Co 79/04/20 5pp
- 7706070218 Provides answers to intervenor's questions raised in 770331 prehearing conference. Certificate of Svc encl ERICKSON, L W Pacific Gas & Electric Go 77/04/20 10pp

- 7906080139 Responses to intervenor's questions raised at 790331 prehearing conference Certificate of Svc encl EIRCKSON,L W Portland General Electric Co 79/04/20 10pp
- J Insurance & indomnity information
- 79060B0297 Forwards executed Amend 4 to Indemnity Agreement B-78 ENEDECOR, E. Portland General Electric Co. 79/06/04 3pg
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906260001 Forwards logic diagrams (modified FSAR Figures 7 2-1) in response to NRC request for add1 info in support of license Amené 54 Diagrams show change in pressurizer safety injection logic Tech Spec change encl
  BROEHL, D J Portland General Electric Co 79/06/20 4pp
- P Operating license stage documents & correspondence
- 7906050416 Ack receipt of util 790206 ltr containing responses to questions re possible transit of crude oil unit trains across site Since proposed transportation has been abandoned future action has been dismissed SCHMENCER. A Operating Reactors Branch 1 (Pre 790625) 79/04/30 20m
- 7906260193 Bummary of 790512 meeting w/util re ausiliary feedwater sys t mods required in non-BtW plants in light of TMI-2 TRAMMELC.C Operating Reactors Branch ( Pre 790625) 79/05/18
- 7906030349 Responds to NRC 781128 ltr re containment purging during normal plant operation Provides addition on isolation valve closure & seismic Category I hydrogen vent sys GOODMIN, C Portland General Electric Co 79/05/31 3pp
- 7906110132 Forwards License Change Application 54 requesting amend of License NPF-1 Application evaluated as Class III Certificate of Svc encl BROEHL.D J Portland General Electric Co 79/06/06 2pp
- --7906110136 License Change Application 34 requesting change to License NPF-1 engineered safeguard features actuation logic in pressurizer
  - BROEHL, D. J. Portland General Electric Co. 79/06/06 9pp
- 7706190473 Ack receipt of NRC 790518 ltr re PGE-1020 Response schedula will be confirmed by 770615 JOHNSON-R W Portland General Electric Co 79/06/11 ip
- 7906220344 Responds to 790529 request for info on PWR feedwater lines Results of radiographic inspired yet complete Forwards isometric drawings refeedwater lines to steam generator, details of feedwater notiles sparger & supports GOODWIN.C Portland General Electric Co 79/06/18 75pp
- 7906270180 Discusses late receipt of NRC 790518 itr forwarding questions requesting additechnical plant info Proposes more formal arrangements re NRC distribution of plant-related correspondence FRANK, L. Oregon, State of 79/06/19 ip
  - add1 info re proposed control bldg design, in uest Further responses to be submitted wall along column N will be modified vation Certificate of Syc encl eneral Electric Co 79/06/22 42pp

## is & correspondence

"Lower Reactor Vessel Head quired "ice of the Director

- 7906270002 Forwards licensee response to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident " VAROA.S A Light Water Reactors Branch 4 79/05/16 1p
- --7906270005 Submits update to 790424 response to IE Bulletin 79-06A.
  Revision I re tripping of pressurizer water level bistables
  b resetting of containment isolation
  GOODMIN.C Portland General Electric Co 79/09/04 2pp
- 7906080242 Forwards 1E Circular 79-08, "Attempted Extortion Low Enriched U" ENQELKEN,R H Region 5, San Francisco, Office of the Director 79/05/18 10
- 7906130045 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/22 10
- 7906200054 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/29 ip
- 7906060281 Summarizes 790518 teicon w/CM Trammell in response to IE Bulletin 79-01.ltem 4 Location of valve MD 10010 is below post-LOCA containment water level Design activities initiated to relocate valve QODDWIN.C Portland General Electric Co 79/06/01 2pp
- R Periodic operating reports & related correspondence
- 7906150302 Forwards monthly operating rept for May 1979 WITHERS, B D Portland General Electric Co 79/06/05 ip
- --7906150307 Monthly operating rept for May 1979 BAIR.Q C Portland General Electric Co 79/06/05 4pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906040181 Notifies of potential deficiency in impeller locknut design for containment spray pumps Defect could cause locknut to loosen & lead to pump failure if impeller contacted pump casing GODDWIN.C Portland General Electric Co 79/04/14 ip
- 7906180221 Forwards PNO-79-67AN ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/05/14 ip
- 790618026B Forwards PNO-79-67AO ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/03/21 ip
- 7906180340 Forwards PNO-79-57AP ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/22 ip
- 7906040347 Forwards LER 79-007/03L-0
  WITHERS B D Fortland General Electric Co 79/05/25 1p
- --7906040350 LER 79-007/O3L-O on 790427, following reactor trip, feedwater isolation valve failed to close automatically Caused by sticking pilot valve in hydraulic operator sys Valve closed manually sys will be inspected PERRY, J. C Portland General Electric Co 79/05/25 2pp
- 7906180365 Forwards PNO-79-67AG ENCELKEN,R H Region 5, San Francisco, Office of the Director 79/05/30 1p
- 7906080292 Forwards LER 79-008/017-0 WITHERS, B D. Portland General Electric Co 79/05/31 1p
- --7906080294 LER 79-008/01T-O on 790521. during review of containment purge sys design. containment purge supply ducting was overpressivized Caused by faulty design which does not allow for effects of dynamic forces following LUCA.

  ORSER: W 8 Portland General Electric Co 79/05/31 2pp
- 7906140425 Forwards LER 79-009/03L-0
  WITHERS: B D Portland General Electric Co 79/06/04 ip

- --7906140434 LER 79-009/03L-0 on 790504 three transmitters found less conservative than Tech Spec limits Caused by normal instrument drift Transmitters recalibr within Tech Spec limits SCHMITT, R P Portland General Electric Co 79/06/04 3pp
- DOCKET 50-344 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 1

  F Security, medical, emergency & fire protection plans
- 7906200523 Discusses 790507-11 inspire implementation of parts of approved security plan Plans should be implemented in accordance w/encl ltr Ltr withheld (ref 10CFR2 790)
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/16
- 7904080303 Emergency Procedure 1202 24 steam supply sys rupture SIMON,L , MURRAY,T D Toleda Edison Co 79/04/02 17pp

#### O Adjudicatory correspondence

- 7906070149 Orders shutdown of plant until NRC determines that util has completed itemized changes in safety sys operating procedures & employee training CHICK.S J Office of the Secretary of the Commission 79/05/16
- 7906130296 Requests denial of 790424 demands by Toledo Coalition for Safe Energy re human & mechanical operational problems emergency plans & request for hearing Demands vague & inconsistent w/regulations CHURCHILL,B W Bhaw, Pittman, Potts, & Trowbridge 79/06/08 2pp

## J Insurance & indemnity information

## M Antitrust correspondence

- 7906220266 Notifies that certain documents were removed from ASLAB secretary's deek by unauthorized person Documents found in another ofc Investigation initiated DUFLO.M E Atomic Safety and Licensing Appeal Panel 78/10/02
- --7906220270 Forwards ABLAB memo issued in Davis-Besse & Perry proceeding re missing papers in ofc ROBENTHALA S Atomic Safety and Licensing Appeal Panel 78/10/03 in
- ---7906220277 Forwards 781107 rept, "Investigation of Unauthorized Removal of ASLAB Documents" Rept withheld (ref FOIA Exemptions 7A & 7E)
  CUMMINOB, J. Defice of Inspector & Auditor 78/11/10 ip
- --7706220285 Provides info re limited inquiry into loss or theft of A9LA8 sensitive documents Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7A & 7E) ATMELL,T L. Division of Security 78/10/05 2pp
- --7906220302 Provides summary of investigation into alleged removal of documents from ABLAB ofcs Info partly withhold due to enforcement proceedings (ref FDIA Exemptions 7A & 7E) ABBTON, O O Office of Inspector & Auditor 78/11/07 4pp
- --7906220320 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) ROBENTHAL, A S Atomic Safety and Licensing Appeal Panel 78/11/08 2pp
- --7906220336 Responds to 781107 mamp re investigation of document removal info partly withheld due to enforcement proceedings. (ref FOIA Exemption 7A) BURCH,C L Division of Security 78/12/04 2pp
- --7906220349 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A & 7E) Forwards Hashington Post 790128 0213 & 25 articles
  HURNEY, T F. Office of Inspector & Auditor 79/02/28 7pp
- --7906220364 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Examption 7E)
  CUMMINGG.J. J. Office of Inspector & Auditor 79/06/22 2pp

- O Advisory Committee on Reactor Safeguards reports & correspondence
- 7906230127 Submits requested change to Page 3/4 3-13 % associated safety evaluation, increasing certain safety margins ROE, L E Toledo Edison Co 77/10/27 3pp
- P Operating license stage documents & correspondence
- 7906260488 Requests status tept Forwards questions re design similarities to TMI
  AHEARDE.J F Commission 79/03/29 2pp
- 7906260519 Responds to 790329 request re plant status Unaware of any current problems of immediate health & safety significance Delays in power testing monitored by Region III Plans to evaluate control sys to improve regulatory performance DENTON.HR Office of Nuclear Reactor Regulation DAVIS, J & Office of Inspection & Enforcement 79/04/13 36pp
- --7906260523 Requests plant status rept Forwards questions AHEARNE, J F Commission 79/03/29 2pp
- 7906260474 Submits items of possible concern for inclusion in orders to BBW plant licensees Forwards 780330 PNO re reactor trip 3 subsequent blowdown at TMI-2 AHEARNE, J F Commission 79/04/27 ip
- 7904020036 Responds to 790321 request for info re QA program Util nuclear QA manual.revised 790108, is used for shipments of Type B quantities ROE.L E Toledo Edison Co 79/04/30 1p
- 7906160034 Notification of 790303 meeting w/util in Bethesda.MD to discuss facility upgrading to enhance ability to respond to feedwater transients Time changed to 9 30 AM VISSING, C Operating Reactors Branch 4 (Prs 790625) 79/05/02
- 7906160014 Notification of 790508 meeting w/util in Bethesda,MD to present design for control grade hard-wired reactor trips based on loss of feedwater & turbine trip conditions ZWETZIG,Q B Operating Reactors Branch 4 (Pre 790625) 79/05/08 to
- 7906280054 Requests solid radwaste process control program, not included in 790316 radiological effluent Tach Specs REID,R W Operating Reactors Branch 4 (Pre 790625) 79/05/15 2pp
- 7906200443 Requests site emorgency plan & implementing procedures, site maps showing location & grid numbers of onsite & offsite environ monitoring stations & site maps used for offsite dose determinations or evacuation KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/17 ip
- 7906270023 Summary of 790517 Affirmation Session 79-13 in Washington, DC Orders to shut down reactor for reasons of increased safety & reliability were approved CHILK.S J. Office of the Secretary of the Commission 79/05/17 ip
- 7906070300 Forwards modified operating procedures complying w/NRC 790809 order W/oversized encl in Central Files only ROE.L E Taledo Edison Ca 79/05/23 App
- 790&0&0280 Responds to 790508 request Submits post-mod test plans for auxiliary feedwater pump dynamic brake, interim anticipatory reactor trip sys & auxiliary feedwater flow indicators ROELL E Toledo Edison Co 79/05/26 4pp.
- 7906060255 Forwards revised procedure matrix reflecting updated procedures modified by NRC 790517 order ROE, L W Toledo Edison Co 79/05/29 4pp
- 7904040272 Bubmits response to 790304 request re diesel generator lockout ROE:LE Toledo Edison Co 79/05/30 2pp
- 7906210218 Forwards info re util actions complying w/NRC 790516 order ROE.L.E Toledo Edison Co 79/06/15 123pp
- 7906220298 Forwards "Analysis of Complete Loss of Feedwater Transient for Facility." in response to request for study of reliability of auxiliary feedwater sys W/o encl ROErL E Toledo Edison Co 79/06/15 ip

- 7906260431 Forwards responses to questions raised by NRC during 790608 site visit re procedural gaps.performance effect of flow on power operated relief valves, valve error correction & const cleanliness RDE, L E Toledo Edison Co 79/06/18 4pp
- 7906250342 Forwards oversized drawings of PWR feedwater lines in response to 790525 request for design info on cracking problem RDE.L. E. Taledo Edison Co. 79/06/19 4pp
- -7906250346 Oversized drawings of PWR feedwater lines \* Toledo Edison Co 79/06/19 21pp
- 7906270223 Submits requested info re analysis on capability of dry & isolated steam generator to start auxiliary feedwater pump 30 minutes after loss of all main auxiliary feedwater & test results for anticipatory reactor trip sys ROE.L E Toledo Edison Co 79/06/23 lipp
- G Inspection reports. IE Bulletins & correspondence
- 7906200482 Forwards IE insp Rept 50-346/79-04 on 790205-09 & notice of violation
  HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/03/28 2pp
- --7706200484 Natice of violation from insp on 770205-09
  \* Region 3, Chicago, Office of the Director 79/03/27 lp
- ---7906200486 IE Insp Rept 50-346/79-04 on 790205-09 Noncompliance noted failure to follow procedures CRESHELL, J B. CHOW. E T , STREETER. J F Region 3, Chicago, Office of the Director 79/03/27 15pp
- 7906290280 BtW site inspector daily rept on 790407 Plant status reactor Mode 5 cold shutdown for maint period has been extended one week to rework valves TAMBLING.T Region 3. Chicago. Office of the Director 79/04/07
- 7906290181 BtW site inspector daily rept on 790408 Plant status reactor in Mode 5 cold shutdown for main general valve maint & condenser leak tests.currently in progress TAMBLING.T, SMITH.J Region 3, Chicago, Office of the Director 79/04/08, 2pp
- 7906270044 B&W site inspector daily rept on 790409 Plant status reactor in Mode 5 cold shutdown maint outage Revision to procedures expected to be completed 790410 TAMBLING, T , SMITH, J Region 3, Chicago, Office of the Director 79/04/09 ip
- 7906290527 B&W site inspector daily rept on 790410 Plant status reactor in Mode 3 cold shutdown for maint outage Reviews of transients complete Condenser out of svc TAMBLING, T. SMITH, J. RIDEN, D. Region 3. Chicago, Office of the Director 79/04/10 2pp
- 7904290110 B&W site inspector daily rept on 790411 Plant status reactor in Mode 5 cold shutdown for maint outage Work complete on condenser & feedwater cleanup
  TAMBLING,T N , BAKER K R., SMITH.J D Region 3, Chicago, Office of the Niceston 79/04/11 2pp
  - r daily rept on 790413 Plant status reactor outage Administrative controls
  - (DEN, M D Region 3, Chicago, Office of 200
    - ily rept on 790414 Plant status reactor tage No major equipment out
      - cago, Office of the Director

1 900 40

- 7906290484 BbW site inspector daily rept on 790415 Plant status reactor in cold shutdown for maint outage BAKER, K.R., SMITH/J.D. Region G. Chicago, Office of the Director 79/04/15. 2pp
- 7906290973 B&W site inspector daily rept on 790412 Plant status reactor in cold shutdown for maint outage Change requested to containment isolation by licensee BAKER, K.R.; SMITH, J.D.; RIDEN, N.D. Region 3, Chicago, Office of the Director 79/04/12 4pp

- 7906290623 B&W site inspector daily rept on 790417 Plant status reactor in Mode 5 cold shutdown Surveillance testing & preventive maint in progress
  TAMBLING,T , REYES,L Region 3, Chicago, Office of the Director 79/04/17 2pp
- 7906010308 Responds to IE Bulletin 79-07 Forwards computer codes & analytical methods used to predict stresses in safety-related piping GRANT. J S Toledo Edison Co 79/04/24 3pp
- 7706230115 Forwards IE Insp Rept 50-346/79-06 on 770106.14 & 27
  KEPPLER, J G Region 9. Chicago, Office of the Director 77/04/25
- --7906230117 IE Insp Rept 50-346/79-06 on 790106.14 & 29 No noncompliance noted STREETER, J F , NORELIYS, C E , VOHLER, J E Region 3, Chicago, Office of the Director 79/04/20 26pp
- --7906230122 Forwards LER 78-061/01T-0 MURRAY.T D Toledo Edison Co 79/06/23 ip
- --7906230123 LER 78-061/01T-0 on 780612 voltage & time delay setpoints of essential bus undervoltage trip relays found incorrect Causad by defective relay Relay settings changed & time delay & voltage setpoints adjusted BEELER,T., KAROLY,D. Toledo Edison Co. 78/06/23 2pp
- --7906230125 Describes events re Jul 1976 plant operation & equipment failures during degraded grid voltage condition STOL7.J F Light Water Reactors Branch 1 76/10/19 Spp
- ---7906230128 Notifies that based on NRC insp efforts, util had modified license re protective circuitry to provide breaker coordination b isolation of onsite electrical sys KEPPLER. J C Region 3, Chicago, Office of the Director 77/10/31 ip
- 7906270462 B&W site inspector daily rept on 790420 Plant status in Mode 5 cold shutdown maint outage TAMBLING.T., REYES.L., DANIELS.T Region 3, Chicago, Office of the Director 79/04/20 2pp
- 790626057: Forwards IE Insp Rept 50-346/79-07 on 790409-12 & notice of violation HEISHMAN,R F Region 3, Chicago, Office of the Director 79/04/27 2pp
- ---7906260577 Notice of violation from insp on 790409-12

  \* Region 3. Chicago, Office of the Director 79/04/28 ip
- --7906260579 IE Insp Rept 50~346/79-07 on 790409-12 Noncompliance noted failure to review & approve applicable procedures recommended in Reg Ouide 1 33 App A re safety relief valve insp & repair RIDEN.M D . SPEBSARD.R L Region 3. Chicago. Office of the Director 79/04/25 4pp
- 7906010117 Ack receipt of 790326 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-03 DAVISA B Region G. Chicago. Fuel Facility & Materials Bafety Branch 79/04/30 ip
- --7906010122 Responds to NRC 790306 ltr re violations noted in IE Insp Rept 50-346/79-03 Corrective actions two entrances to incore tunnel locked GRANT.J 8 Toledo Edison Co 79/03/26 2pp.
- 7906260636 Forwards IE Insp Rept 30-346/79-08 on 790418 No noncampliance noted KEPPLER. J O Region 3. Chicago. Office of the Director 79/04/30 2pp
- --7906260639 IE Insp Rept 50-346/79-08 on 790418 No noncompliance noted Major areas inspected, administrative & operating regulatory performance of facility.

  TAMBLINMO,T N. SPESSARD,R L. Region 3, Chicago, Office of the Director HEISHMAN.R.F. Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/30, 3pp
- 7904020240 Responds to IE Bulletin 79-04. Describes investigation reweights used in pipe stress analysis of swing check valves Supporting documentation encl. QRANT, J S Toledo Edison Co 79/05/01. 12pp.

. .

- 7906260497 Forwards IE Insp Rept 50-346/79-09 on 790410-11 No noncompliance noted FIGRELLI.Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 2pp
- --7906260502 IE Insp Rept 30-346/79-09 on 790410-11 No noncompliance noted Major area inspected licensee action re IE Circular 78-08 JABLONSKI.F J , HAYES.D W Region 3, Chicaga, Reactor Construction & Engineering Support Branch 79/04/30 6pp
- 7906140249 Forwards responses to IE Bulletin 79-09B re TM1-2 incident GRANT, J S Toledo Edicon Co 79/05/04 5pp
- 7906:20125 Forwards IE Info Notice 79~11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3. Chicago. Office of the Director 79/05/07
- 790611010B Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region G. Chicago, Office of the Director 79/05/11 10
- 7906190102 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906060232 Responds to IE Bulletin 79-07 re use of GE Type AK-2 circuit breakers in safety-related sys Program established to ensure proper cycling, cleaning & lubrication of control rod drive control sys breakers
  GRANT, J S Toledo Edison Co 79/05/15 3pp
- 7904040291 Revises 790304 transmittal re change in response to IE Bulletin 79-03B. Item 4 Procedures will not be modified to provide manual reactor trip on low pressurizer level GRANT. J B Toledo Edison Co 79/05/15 2pp
- 7906190550 Ack receipt of 770418 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 30-346/79-04
  HEISHMAN,R I Region 3. Chicago. Reactor Operations Nuclear Support Branch 79/03/19 ip
- --7906190555 Responds to NRC 790328 ltr re violation noted in IE Insp Rept 50-346/79-04 Corrective actions demanding strict adherence to procedures, close review of procedures & mechanism for mod GRANT, J B Toledo Edison Co 79/04/18 2pp
- 7906230140 Bubmits followup to 790416 itr in response to IE Bulletin 79-03 Ultrasonic examination evaluation indicates acceptance stds of Section III of ABME Code, 1971 edition, are acceptable GRANT, J S Toledo Edison Co 79/05/16 ip
- 7904080203 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J O Region 3. Chicago, Office of the Director 79/03/18 ip
- 7906270120 Requests info re manual trip on low presurizer level as stated in Item 4F of IE Bulletin 79-058 WILLIAMS.F J Division of Project Management 79/05/18 3pp
- 7906230037 Forwards responses to Items 5 & 7 of IE Bulletin 79-058 re TMI-2 incident Submittal.in conjunction w/util 790504.15 & 18 Items.completes response to bulletin ORANT.J S Toledo Edison Co 79/05/21 4pp
- 7906130116 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/22
- 7906200137 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " KEPPLER, J O Region 3. Chicago, Office of the Director 79/03/29
- 7906250109 Ack receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-346/79-07 HEISHMAN.R F Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/05/27 ip

- --7906250119 Responds to NRC 790427 1tr re violations noted in 1E Insp Rept 50-346/79-07 Corrective actions use of safety relief valves insp M-46 has been discontinued New maint procedure will be written GRANT.J S Toledo Edison Co 79/05/17 2pp
- R Periodic operating reports & related correspondence
- 7906140394 Forwards monthly operating tept for May 1979 MURRAY.T D Toledo Edison Co 79/06/08 1p
- --7906140408 Monthly operating rept for May 1979 CABA,E C Toledo Edison Co 79/06/08 11pp
- 8 Reportable occurrences, LERs % related correspondence
- 7906290028 Summary of 790308 meeting w/util & Bechtel in Bethesda, MD re licensee design of hard wire control-grade reactor trip caused by loss of feedwater &/or turbine trip & other matters related to NRC shutdown order

  ZWETZIG & Derating Reactors Branch 4 (Pre 790625) 79/05/15
  4pp
- 7906080283 RO on 790518 68 hydraulic snubbers failed 18-month functional test verifying piston movement Analysis being conducted MURRAY.T D Toledo Edison Co 79/05/18 2pp
- 7904040237 Forwards LER 79-054/03L-0 MURRAY, T D Toledo Edison Co 79/05/27 1p
- --7906040239 LER 79-036/03L-0 on 790501 excessive leakage found through containment isolation valve NN236 Caused by either dirt on valve seating surface or slipped actuator linkage Valve cleaned & recalibr ROHRER.E Toledo Edison Co 79/05/27 2pp
- 7906030242 Forwards LER 79-058/03L-0 MURRAY, T D Toledo Edison Co 79/09/30 1p
- --7906050243 LER 79-058/03L-0 on 790903 IBM Sys 7 contact data logger failed, rendering fire 5 radiation remote monitoring inoperable Cause of failure unknown Computer reloaded & placed in operation BORYSIAK, M Toledo Edison Co 79/05/30 2pp
- 7906070202 Forwards LER 79-057/01T-0 MURRAY, T D Toledo Edison Co 79/06/01 1p
- --7906070208 LER 79~057/017-0 on 790518 hydraulic snubbers may not have fulfilled their functional requirements Cause under investigation.but possibly from improper installation of snubbers during const D'NEILL,JJ Toledo Edison Co 79/05/30 3pp
- 7906070269 Forwards LER 79-034/017-2 MURRAY, T D Toledo Edison Co 79/06/01 1p
- ---7906070272 LER 79-034/01T-2 on 790103 HPI pump 1-1 stopped, due to low recirculation flow indication Caused by inability of heat trace to maintain HPI pump recirculation line temp above freezing Thermostat setting increased BROWN,D H Toledo Edison Co 79/03/23 5pp
- 7906180546 Forwards LER 79-060/03L-0 MURRAY, T D Toledo Edison Co 79/06/13 ip
- ~~7906180547 LER 79~060/03L~O on 790519 fire barrier removed to allow removal of hydraulic snubber.but continuous fire watch was not established Caused by faulty procedure Mod made to hydraulic snubber testing procedure
  BROWN.R A Toledo Edison Co 79/06/13 3pp
- 7906180549 Forwards LER 79-059/03L-0 MURRAY, T D Toledo Edison Co 79/06/13 ip
- --7906180551 LER 79-059/03L-0 on 790517 unsealed hale discovered in fir barrier floor Caused by Uncompleted survey of work items, Gap sealed & training meeting held w/maint & const supervisors NAYLOR,R W. Toledo Edison Co 79/06/13 3ap
- 7906220383 Forwards LER 79-061/03L-0 MURRAY, T D Toledo Edison Co 79/06/14 1p

- --7906220387 LER 79-061/03L-0 on 790518 control room emergency damper HV5311A stuck in open position during surveillance testing Caused by humidity corroding brass bushings of shaft Damper repaired & humidiflers relocated RUDOLPH, J J Toledo Edison Co 79/06/14 3pp
- 7906220377 Forwards LER 79-062/03L-0 MURRAY, T D Toledo Edison Co 79/06/15 1p
- --7906220403 LER 79-062/03L-0 on 790521 automatic faeduater suction pressure switches found outside specified tolerance Caused by instrument drift & component failure Switches returned to normal tolerances on 790522 NELSON, J. HITCHENS, D. Toledo Edison Co. 79/06/15 4pp
- 7906250257 Forwards LER 79-063/03L-0 MURRAY, T D Toledo Edison Co 79/06/20 1p
- --7906250258 LER 79-063/03L-0 on 790523 containment pressurizer smoke detector DS 6635 did not alarm when tested Caused by broken wire in detector fixed base Hire repaired & detector successfully tested CHESKO.R C Toledo Edison Co 79/06/20 2pp
- 7906270175 Forwards LER 79-029/017-2 MURRAY, T D Toledo Edison Co 79/06/22 1p
- --7906270178 LER 79-029/01T-2 on 790306 borated water storage tank isolation valves DH7A & B were mistakenly closed Caused by personnel error Valves reopened & auxiliary operator disciplined BROWN. D H Toledo Edison Cu 79/03/16 Spp
- DOCKET 50-348 JOSEPH M FARLEY NUCLEAR PLANT. UNIT 1

  F Security, medical, emergency & fire protection plans
- 7706010100 Responds to 770312 ltr re delays in implementing requirements of 10CFR73 55 Region II should be notified when full compliance is achieved & compensatory measures are discontinued SCHMENCER. A Operating Reactors Branch 1 (Pre 770625) 79/04/30
- P Operating license stage documents & correspondence
- 7906230180 Discusses review of util 790301 revised ECCS analysis, which satisfies criteria of NRC 780427 order for mod of license Forwards safety evaluation of Zr-water correction to ECCS analysis SCHHENCER, A Departing Reactors Branch 1 (Pre 790625) 79/03/09
- ---7906250187 Safety evaluation supporting mod of Zr-water correction to ECCS analysis \* Operating Reactors Branch 1 (Fre 790625) 79/05/09 4pp
- 7906260179 Summary of 790508 meeting w/util in Bethesda,MD re auxiliary feedwater sys & related info
  REEVES,E A Operating Reactors Branch 1 (Pre 790625) 79/05/15

ion of 790606 meeting w/util to discuss App I ent Tech Specs proposed by 790416 ltr ating Reactors Branch 1 (Pre 790625) 79/05/23

> letion of two prerequisites for startup after onger term means of reactor tion have been installed ~ Co 79706/08 lp

> > edwater lines, in response to NRC wings encl W/o encl '9/06/15 140pp

- 7906220347 Forwards proposed Tech Spec changes re containment purge sys & single dropped rod protection Safeby evaluations encl CLAYTON.F L Alabama Power Co 79/06/20 18pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906140626 Forwards IE Insp Rept 50-348/79-11 on 790312-16 No noncompliance noted SUTHERLAND, U.T Region 2. Atlanta: Fuel Facility & Materials Safety Branch 79/03/29 2pp

- --7906140634 IE Insp Rept 50-348/79-i1 on 790312-i6 No noncompliance noted Major areas inspected temporary shielding on safety-related piping & separation of containment waste sys from noncontainment plant sys HOSEY.C H , GIBSON.A F Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 7pp
- 7906200350 Forwards IE Insp Rept 50-348/79-13 on 790327-30 No noncompliance noted LEWIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/12 2pp
- --7906200359 IE Insp Rept 50-348/79-i3 on 790327-30 No noncompliance noted Major areas inspected refueling activities VOOT-LOHELL.R J. MARTIN.R D Region 2, Atlanta, Office of the Director 79/04/12 App
- 7906140150 Forwards IE Insp Repts 30-348/79-15 % 50-364/79-05 on 790402-07 No noncompitance noted LEWIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/17 2pp
- --7906140157 IE Insp Repts 50-348/79-15 & 50-364/79-05 on 790402-07 No noncompliance noted Major areas inspected preoperational test procedures & test procedure for mod & refueling HAGNER, A O. MARTIN.R D. Region 2. Atlanta. Office of the Director 79/04/16 4pp
- 7906290483 Responds to IE Bulletins 79-06 & 79-06A, Revision 1 Forwards info re THI incident Proposed design & Tech Spec changes will be submitted by 790514 CLAYTON, F.L. Alabama Power Co. 79/04/24 21pp
- 7906220244 Act receipt of 790427 ltr informing NRC of steps taken to correct violations moted in IE Insp Repts 50-340/79-14 & 50-364/79-06 HURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/07 ip
- --7906220247 Responds to NRC 790411 ltr re violations noted in IE Insp Repts 90-340/79-14 & 50-364/49-06 Corrective actions new in-house procedure implemented to control electrical prints & instruction of all fixed supervision CLAYTON.F.L. Alabama Power Co 79/04/27 2pp
- --7906220248 Forwards IE Insp Repts 90-340/79-14 & 90-364/79-06 on 790327-29 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906220249 Notice of violation from insp on 790327-29
  \* Region 2, Atlanta, Office of the Director 79/04/12 ip
- --7906220250 IE Insp Repts 50-340/79-14 & 50-364/79-06 on 790327-29
  Noncompliance noted failure to control superseded drawings
  HUNT,M D Region 2, Atlanta, Office of the Director HERDT,A R
  Region 2, Atlanta, Reactor Construction & Engineering Bupport
  Branch 79/04/12 4pp
- 7906190215 Ack receipt of 790423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-348/79-09 KENNA,# B Region 2, Atlanta, Safeguards Branch 79/05/09 lp
- --7906190218 Forwards IE Insp Rept 50-348/79-09 on 790312-16 Notice of violation withheld (ref 10CFR2 790) KENNA, W B Region 2. Atlanta, Safeguards Branch 79/03/29 2pp
- --7906190223 IE Insp Rept 50-348/79-09 on 790312-16 Noncompliance noted infraction re protected area control protected area isolation rone & vital area control Details withheld (ref 10CFR2 790)
  FUCKKO, J M Region 2. Atlanta, Office of the Director TOBIN, W J Region 2. Atlanta, Safeguards Branch 79/03/29 ip
- 7906230437 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  O'REILLFUJ P Region 2, Atlanta, Office of the Director 79/05/10 ip
- 7906110058 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 is
- 7906290761 Responds to LE Bullatin 79-09 OE Tupe AK-2 circuit breakers are used in safety-related features at Units 1 & 2 CLAYTON.F L Alabama Power Co 79/09/18 2pp

- 7904290723 Forwards info in response to IE Bulletin 79-10 re requalification training program CLAYTON,F L Alabama Power Co 79/05/22 3pp
- R Periodic operating reports & related correspondence
- 7906190258 Forwards monthly operating rept for May 1979 CLAYTON.F L. Alabama Power Co. 79/06/12 ip
- -7906190260 Monthly operating rept for May 1979 HAIRSTON, W C Alabama Power Co 79/06/01
- S Reportable occurrences, LERs & related correspondence
- 7906010280 FOIA request for documents re abnormal occurences at plants, info re Westinghouse proposed nuclear fuel assembly plant in Prattyille, AL & info re transportation of nuclear waste & GAKES,D L Affiliation Unknown 79/04/23 2pp
- 7906050285 Forwards nonroutine environ operating rept providing 10-day written notification of 790515 occurence CLAYTON.F.L. Alabama Power Co. 79/05/25 1p
- --7906050287 Nonroutine environ operating rept discussing 790330-0514 drainage of i.860 gallons contaminated water onto Unit 2 floor drain sys Caused by inadequate design change control Drains were piugged \* Alabama Power Co 79/09/25 3pp
- /906040279 Forwards LER 79-021/01T-2 CLAYYUN.F L. Alabama Power Co 79/05/29 1p
- --7906040283 LER 79-021/01T-2 on 790412 initial results of test program revealed statistical sampling would not provide probability of greater than 95% anchor boit reliability Bolt testing program expanded to include 100% testing HAIRSTON.W G Alabama Power Co 79/05/29 4pp
- 7906010277 Responds to 790423 FOIA request Forwards computer printout of abnormal occurrences at plants until May 1979, paper on "Transportation of Nuclear Fuel & Waste." & list of package designs for which util is registered FELTON, J M Division of Rules and Records 79/05/30 57pp
- 7906190239 Forwards LER 79-019/03L-1 CLAYTON,F t. Alabama Power Co 79/06/08 1p
- ~~7906190242 LER 79-019/OSL-1 on 790420 fluoride & chloride concentrations in RCS in violation of Tech Spec limits Cause not determined RCS integriby not impaired & acceptable for continued operation
  HAIRSTON,W Q Alabama Power Co 79/06/OS 1p
- 7906250289 Forwards LER 79-017/01T-2 CLAYTON, F L Alabama Power Co 79/06/18 1p
- 7906250250 Forwards LER 79-021/01T-3 CLAYTON: F L Alabama Power Co 79/04/19 1p
- -7906250252 LER 79-021/01T-3 on 790412 statistical sampling of Seismic Coestrate I anchor belts would not provide probability greater than 95% reliability Caused under investigation Testing extended to 100% verification of anchors on pipe HAIRSTON:W C Alabama Power Co 79/06/19 4pp.
- 7906260333 Forwards 790615 ltr to EPA re item of noncompliance Analysis of turbine bldg sump effluent showed 9 13 pH Caused by error in sampling & analysis Steps have been taken to ensure violation does not recur

  CLAYTON, F. L. Affabama Power Co. 79/06/19 2pp
- DOCKET 50-352 LIMERICK GENERATING STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7906280033 Discusses effect of TMI-2 incident on proposed const of nuclear facilities
  DENTON, H. R. Office of Nuclear Reactor Regulation 79/05/11 Spp

- G Adjudicatory correspondence
- 7906140479 Requests NRC position on nuclear plant const in Limerick REYNIER, R H Reunier, Crocker, Allebach & Reber, P C 79/04/13 2pp
- 790608085 Opposes const of facilities in close proximity to populated areas Plants should be built at least 50 miles from densely populated areas OCODSTEIN.S J Affiliative Unknown 79/04/27 ip
- H General correspondence
- 7906070379 Ack receipt of 790413 ltr commenting on financial responsibility of nuclear facility numbers of TMI-2 incident SNYDER, O. L. Region 1. Philadelphia, Office of the Director 79/04/20 ip
- ~-7906070380 Requests financial responsibility for TMI-2 incident be placed on Ketropolitan Edison & stockholders ZEITLIN:H Affiliation Unknown 79/04/13 2pp
- 7906130089 Acks receipt of 790416 ltr commenting on inadequate supply of water SNYDER, G L Region 1. Philadelphia. Office of the Director 79/04/20
- ---7906130099 Comments on plant licensing & inadequate water supply BALDASSARI, J A Affiliation Unknown 79/04/16 2pp
- 7906180595 Ack receipt of 790413 ltr Board of Supervisors will be placed on distribution list for repts ve results of TMI investigation No current plans to cease const of nuclear power plants facility will be formally reviewed DENTON, HR Office of Nuclear Reactor Regulation 79/05/14 79/05/14 3pp
- ---7906(80602 Expresses concern of Board of Supervisors of Limerick Township.PA re continued const of facility, in light of TMI accident Requests NRC to investigate safety of facility RCYNIER.R H Pottstown PA 79/04/13 2pp
- G Inspection reports. IE Bullstins & correspondence
- 7906180405 Forwards IE Info Notice 79-10, "Honcomforming Pipe Support Struts " No written response necessary QRIER.B H Region 1, Philadelphia, Office of the Director 79/04/16 ip
- 7906050193 Ack receipt of 790302 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-332/78-08
  - CARLBON, RT Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/23 ip
- --7904050197 Responds to NRC 790131 ltr re violations noted in IE Insp Repts 50-352/78-12 & 50-353/78-08 Corrective actions required insp performed & documented open insp plans reviewed & field staff reinstructed BOYER.V 8 Philadelphia Electric Co 79/03/02 2pp
- --7906050201 Forwards IE Insp Repts S0-352/78-12 & 30-353/78-08 on 781226-27 & 790102 & notice of violation CARLSON,R T Region i. Philadelphia, Reactor Construction & Engineering Support Branch 79/01/31 2pp
- -7906030206 Natice of violation from insp on 781224-27 & 790102 \* Region 1. Philadelphia, Office of the Director 79/01/30
- --790A050212 IE Insp Repts 50-352/78-12 & 30-353/78-08 on 781226-129 & 790102 Noncompliance noted failure to perform insp for piping installation activities MATVIA, J. MCBREARTY, R. Region 1. Philadelphia. Office of the Director MCGAUOHY, R. Region i. Philadelphia. Reactor Construction & Engineering Support Branch 79/01/30 13pp
- 7906110031 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl" No written response required ORIER,B H Region I, Philadelphia, Office of the Director 79/04/23 ip.
- 7906130172 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/03/02 ip

- 7906020206 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co " Some pipes present, but not installed BDYER, V 8 Philadelphia Electric Co 79/05/07 ip
- 7906120189 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER,BH Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- S Reportable occurrences. LERs & related correspondence
- 7906020208 Ack receipt of 790420 ltr forwarding limitorque locinut installation deficiency CARLSUN.R T Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/05/02 lp
- --7906020211 Forwards Significant Deficienty Rept 8 re limitorque locknut installation deficienty SOYERY S Philadelphia Electric Co 79/04/20 io
- --7906020213 Significant Deficiency Rept 8 limitorque locknut installation deficiency \* Philadelphia Electric Co 79/04/30 4pp
- DOCKET 50-353 LIMERICK GENERATING STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7906280033 Discusses affect of TM1-2 incident on proposed const of nuclear facilities
  DENTON-H R Office of Nuclear Reactor Regulation 79/05/11 3pp
- Q Adjudicatory correspondence
- 7906140479 Requests NRC position on nuclear plant const in Limerick Tounship.PA REYNIER.R H Reynier.Crocker.Allebach & Reber,P C 79/04/13 2pp
- 790&0B00B5 Opposes const of facilities in close proximity to populated areas Plants should be built at least 50 miles from densely populated areas GODDSTEINS J Affiliation Unknown 79/04/27 1p
- H General correspondence
- 7906070379 Ack receipt of 790413 itr commenting on financial responsibility of nuclear facility owners re TKI-2 incident SNYDER.O L Region i. Philadelphia. Office of the Director 79/04/20 ip
- --7906070380 Requests financial responsibility for TMI-2 incident be placed on Metropolitan Edison & stockholders
  ZEITLIN, H Affiliation Unknown 79/04/13 2pp
- 7906130089 Acks receipt of 790416 itr commenting on inadequate supply of water SNYDER.0 L Region 1. Philadelphia. Office of the Director 79/04/20 1p
- ---7906130095 Comments on plant licensing & inadequate water supply BALDASBARI.J A Affiliation Unknown 79/04/16 2pp

- --7906050197 Responds to HRC 790131 ltr re violations noted in IE Insp Repts 50-392/78-12 & 50-353/78-0B Corrective actions required insp performed & documented.open insp plans reviewed & field staff reinstructed BOYER.V S Philadelphia Electric Co 79/03/02 2pp
- --7906050201 Forwards IE Insp Repts 50-352/78-12 & 50-353/78-08 on 781226-29 & 790102 & notice of vialation CARLSON:R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/01/31 2pp
- --7906050206 Notice of violation from insp on 781226-29 \$ 790102 \* Region i, Philadelphia, Office of the Director 79/01/30
- --7906050212 IE Insp Repts 50-352/78-12 & 50-353/78-08 on 781226-129 & 790102 Noncompliance noted failure to perform insp for piping installation activities MATTIA.J. MCGREARTY.R Region 1. Philadelphia. Office of the Director MCGAUGHY.R Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/01/30 13pp
- 7906110031 Forwards IE Bulletin 79-058, "Nuclear Incident at THI-Suppl " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/23 p
- 7906130172 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Hotor Generator Set Resulted in Reactor Power Increase " No written response required GRIER. B H Region 1. Philadelphia. Office of the Director 79/05/02 ip
- 7906020206 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Pipe Spools Mfg by Youngstown Welding & Engineering Co " Some pipes present but not installed BOYER ∨ S Philadelphia Electric Co 79/05/07 1p
- 7906120189 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER.B H Region i, Philadelphia. Office of the Director 79/05/07 2pp
- S Reportable occurrences. LERs & related correspondence
- 790602020B Ack receipt of 790420 ltr forwarding limitorque locknut installation deficiency CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 79705702 lp
- --7906020211 Forwards Significant Deficiency Rept 8 re limitorque locknut installation deficiency BDYER/V S Philadelphia Electric Co 79/04/20 ip
- ---7906020213 Significant Deficiency Rept 8 limitorque locknut installation deficiency \* Philadelphia Electric Co 79/04/30 4pp
- DOCKET 50-354 HOPE CREEK NUCLEAR STATION, UNIT 1
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO.JF Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY,E Hearings Division 79/03/26 34pp
- 7906180696 Motion for reconsideration of ALAB-540 & seygrence from consolidation established by ALAB-540 Admits issues not raised by any party & departs from "lead case" procedure previously adopted Certificate of Svc encl CONNER.T B Conner. Moore & Corber 79/05/02 13PP
- 7906210075 NRC motion for summary disposition re radon issue was in errorsALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Cartificate of Sycenci
  DUFLO.M E Atomic Bafety and Licensing Appeal Panel 79/05/25

- 7906230107 Request by utils that ASLAB grant summary disposition of all issues in consolidated radon proceeding Decision sought as matter of law since no genuine issue as to matl facts
  SILBERG, J A Shaw, Pittman. Potts, & Trowbridge 79/05/25 4pp
- --7906230110 Statement of matl facts re radon proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies i-7,9-18,20-24 & 26 Affidavit of MI Goldman & supporting documentation encl SILBERT. J E Shaw, Pittman, Potts, & Trowbridge 79/03/25 36pp
- -7906230112 Supplements 790525 affidavit of M1 Goldman % utils 790409 memo re radon emissions & de minimus approach Discusses Alleged Deficiencies 2.9.16 & 21 Seeks motion for summary disposition Certificate of Svc enci SILBERG.J A Shaw. Pittman. Potts. & Trowbridge 79/05/25 19pp
- G Inspection reports. IE Bulletins & correspondence
- 7906010036 Forwards IE Insp Repts 50-354/79-02 & 50-355/79-02 on 790227-0301 No noncompliance noted CARLSQN.R T Region i. Philadelphia. Office of the Director 79/03/21 2pp
- --7706010039 IE Insp Repts 50-354/79-02 & 50-355/79-02 on 790227-0301 No //Jobiousy le imp Repts 30-394/74-02 b 30-395/74-02 d 79022/-03t noncompliance noted Major areas inspected (60 program for pipe hangers b supports & subcontractors program for fabrication b installation of containment liner MARROHLL, FASAND, A Region 1, Philadelphia, Office of the Director MCGAUGHY, R Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/19 10pp
- 7904180413 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/14 1p
- 7906110037 Forwards IE Bulletin 79-050. "Nuclear Incident at TMI-Suppl " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/29 ip
- 7906130174 Forwards IE Circular 79-07. "Unexpected Spead Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 79/05/02 1p
- 7906120194 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER.B H Region 1, Philadelphia, Office of the Director 79/08/07 2pp
- 7906260151 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" ORIER.B H Region 1, Philadelphia, Office of the Director 79/03/11 ip
- 7906060261 Requests 30-day extension.until 790706.to complete evaluation of items mentioned in NRC Bulletins 78-12.78-12A. & 78-12B re atypical weld matl in reactor pressure vessel MARTIN.T J Public Service Electric & Gas Co of New Jersey 79/05/29 lp
- DOCKET 50-355 HOPE CREEK NUCLEAR STATION, UNIT 2
- O Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to Hearings Division 79/04/02 2pp
- ---7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906180696 Motion for reconsideration of ALAB-540 & severence from consolidation established by ALAB-540 Admits issues not raised by any party & departs from "lead case" procedure previously adopted Certificate of Svc encl CONNER: T B Conner, Moore & Corber 77/05/02 15PP
- 7906210095 NRC motion for summary disposition re radon issue was in error:ALAB-540 consolidated only 5 of 16 cases, Denies NRC motion as to parties in other proceedings Certificate of Svc DUFLO, H E Atomic Safety and Licensing Appeal Panel 79/05/25

- 7906230107 Request by utils that ASLAB grant summary disposition of a issues in consolidated radon proceeding Decision sought as matter of law since no genuine issue as to mat! facts
  SILBERO, J A Shaw, Pittman, Potts, & Trowbridge 79/05/25 4pp
- ---7906230i10 Statement of matl facts re radon proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies 1-7,9-18,20-24 & 26 Affidavit of MI Goldman & supporting documentation encl SILBERT. J E Shaw, Pittman, Potts, & Trowbridge 79/05/25 36;
- -7906230112 Supplements 790525 affidavit of MI Coldman & utils 79040 memo re radon emissions & de minimus approach Discusses Alisged Deficiencies 2.9,16 & 21 Seeks motion for summary disposition Certificate of Svc encl SILBERO, J A Shaw. Pittman, Potts. & Trowbridge 79/09/25 19;
- O Inspection reports, IE Bulletins & correspondence
- 7906010036 Ferwards IE Insp Repts 50-354/79-02 & 50-355/79-02 on 790227-0301 No noncompliance noted CARLSON.R T Region 1. Philadelphia, Office of the Director 79/03/21 2pp
- --7906010039 IE Insp Repts 30-354/79-02 & 50-355/79-02 on 790227-0301 noncompliance noted Major areas inspected GC program for pipe hangers & supports & subcontractors program for fabrication & installation of containment liner NARROW,L . FASAND.A N Region i, Philadelphia, Office of the Director MCGAUGHY,R W Region i, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/19 10pp
- 7906180413 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts" No written response necessary GRIER,B H Region 1, Philadelphia, Office of the Director 79/04/16 ip
- 7906110037 Forwards IE Bulletin 79-05B, "Nuclear Incident at IMI-Bupp!" No written response required ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 lp
- 7906130174 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required GRIER, B H Region 1. Philadelphia. Office of the Director 79/05/02 ip
- 7906120194 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER.B H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 7906260151 Forwards IE Info Notice 79-12. "Attempted Damage to New Ft Assemblies " GRIER.8 H Region 1. Philadelphia. Office of the Director 79/05/11 ip
- 7906060261 Requests 30-day extension until 790706, to complete evaluation of items mentioned in NRC Bulletins 78-12, 78-124, 78-128 re atypical weld matl in reactor pressure vessel MARTINIT J Public Service Electric & Gas Co of New Jersay. MARTIN, T J 79/05/29. 1p
- DOCKET 50-356 UNIV OF ILLINOIS LOPRA RESEARCH REACTOR
- G Inspection reports, IE Bulletins & correspondence
- 7906190062 Forwards IE Info Notice 79-12, "Attempted Damage to New Fi Assemblies " KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/2
- 7906080181 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " KEPPLER, J Q Region 3, Chicago, Office of the Director. 79/05/
- DOCKET 50-358 WILLIAM H ZIMMER NUCLEAR STATION: UNIT 1 A Application/construction stage documents & correspondence
- 790670381 Forwards assembly drawings for vertical fitting of 12-incl radius & unsupported fitting of formed sections BANTA,F L Burndy Husky 79/09/21 7pp
- 7906250081 Forwards request for add1 info re radiological assessment complete review of OL application .
  8TOLZ.J F Light Hater Reactors Branch 1. 79/05/18 4pp

1

## O Adjudicatory correspondence

- 7906010119 Second set of interrogatories submitted to applicant Certificate of Suc encl RIOBERO.S Miami Valley Power Project 79/03/19 App
- 7906080193 Util request that ASLB grant summary disposition of encl statement of mati facts WETTERHAHN,M J Conner, Moore & Corber 79/04/06 ip
- ---770&080197 Statement of matl facts as to which there is no genuine issue to be heard
  \* Cincinnati Gas & Electric Co 79/04/10 18pp
- 7906180693 Interrogatories for intervenor Miami Valley Power Project Certificate of Svc enci BARTH,C A Branch 3 79/04/20 10pp
- 7906080206 Statement of mati facts as to which there is no genuine issue to be heard M/affidavits & qualifications of RP Wiwi, HR Kelley, AH HilliKK Chittara, WH Zimmer, JM Emery & PL Anderson Certificate of Svc encl & Cincinnati Gas & Electric Co 79/04/23 40pp
- --7906080210 Util supplemental memo in support of summary disposition re intervenor Miami Vailey Power Project Contentions 11.12 & 13 HETTERHAHN: HJ Conner, Moore & Corber 79/04/23 20pp
- 7906050089 Advises that copy of applicants' objections to intervenor Miami Valley Power Project second set of interrogatories & motion for protective order was mailed on 790406 WETTERHANN, M J Conner, Moore & Corber 79/04/24 ip
- 7906080030 Supports intervenor Miami Valley Power Project objection to util Interrogatory 7 of third set of interrogatories Certificate of Svc encl BARTH.C A Branch 3 79/04/25 4pp
- 7906140627 Requests to make limited appearance statement at licensing preheating conference.

  ECKART-L E Affiliation Unknown 79/04/25 ip
- 7906050131 Corrects 790420 itr re timeliness of util abjections to intervenor Miami Valley Power Project second set of interrogatories & request for protective order Requests ruling an Contention 14 of NRC interragatory KOSIK:L S Kosik: L S 79/04/26 1p
- 7906140657 Requests to make limited appearance statement at licensing prehearing conference
  FOSTER, J O Affiliation Uninoum 79/04/26 ip
- 7906220066 Mation by intervenor Miami Valley Power Project to amend petition to intervene Seeks addition of Contention 17 re evidence of safety problems Cortificate of Svc enci KOSIKL S Kosik, L S 79/04/30 Spp
- --7906220070 Amend by intervenor Miami Valley Power Project to petition to intervene Proposed Contention 17 re fire insulation matl used in cable trays for protection asserts insulation is inadequate & tests are improperly performed KOSIK, LS Kosik, L 6 79/04/30 3pp
- 7906020111 Requests opportunity to present oral statement at 790522 pre-conference hearing in Moscow.OH HEYER, C J Affiliation Unknown 79/05/01 ip,
- 7906120033 Intervenor,D Fankhauser response in opposition to applicant summary motion Affidavit & Certificate of Svc enc. Holiver, J D 79/08/01 7pp
- 7906020112 Requests opportunity to present oral statement at 790522 pre-licensing hearings in Moscow. OH MEYER: R H Affiliation Unknown. 79/05/02 ip.
- 7906050043 Requests permission to make oral statement at preliminary hearing on 790522 OILMAN.M.S Affiliation Unknown 79/05/02 ip
- ---7906050203 Requests limited appearance at ASLB 790523 hearing in CincinnationH HAITS, B. L. Affiliation Unknown 79/05/01, ip.

- 7906180743 Responds to applicant motion for summary disposition of Fankhauser Contentions 1,2,4 % 6 re offsite monitoring & emergency planning Requests board to defer matter until further review by NRC Certificate of Svc encl REIS,E J Branch 3 79/05/02 3pp
- 7906280031 Opposes applicant 790406 motion for summary judgment re intervenor D Fankhauser contention Disputes applicant assertions re water monitoring Affidavit & Gertificate of Svc encl LUEBIERS.T A , HEILE.W P Cincinhati, OH 79/05/02 9pp
- 7906250227 Notification that 790426 request should be transmitted through formal filings in administrative proceeding BARTH,C A Branch 3 79/05/03 ip
- 7906010137 Applicants' response in opposition to 780417 motions by intervenors Hiami Valley Power Project & Fankhauser to delay OL hearing & suspend activities Certificate of Sveencl CONNER.T B Conner, Moore & Corber 79/05/07 13pp
- 7906010137 Response by intervenor Fankhauser in opposition to applicants' motion for summary disposition Affidavit & Certificate of Svc encl WOLIVER-J Wolliver, J D 79/05/07 7pp
- 7906190568 Opposes Miami Valley Power Project 790430 motion to admit new contention re fire protection barriers on electric cable trays Contention is irrelevant Motion does not conform to 10CFR2 714(a)(1) Certificate of Suc encl BARTH, C A Branch 3 79/05/07 9pp
- 7906210248 Opposes in part intervenors D Fandhauser & Miami Valley
  Power Project 790417 motions to postpone hearings until TMI
  analyses are completed Consideration of Contentions 2-5 &
  7-9 should be deferred Certificate of Svc
  REIS.E J Branch 3 /9/05/07 8pp
- 7904020202 Requests opportunity to present oral statements at 790522 pre-conference hearing in Moscow.H MAYER.V A . SAUER.M . FITCHTER.J H Affiliation Unknown 79/05/08 508
- 7906010297 Notifies that evidentiary hearing will commence on 790619 in Cincinnati.OH area,per ASLB 790404 & 790511 orders
  BECHIORFER,C Atomic Safety and Licensing Board Panel 79/03/11
- 7906040155 Denies 770416,17 % 0501 motions filed by intervenors Miami Valley Power Project, D Fankhauser & City of Cincinnati to postpone evidentiary hearing, re Contentions 1,6,11,12,14-16 Gentificate of Svc ancl BECHHOEFER.C Atomic Safety and Licensing Board Panel 79/05/11 600
- 7906230339 Individual requests to make limited appearance statements at prelicensing hearing conference ERBE.M , ERBE.E K Affiliation Unknown 79/05/14 12pp
- 7906250410 Forwards applicant 790514 objections to intervenor Miami Valley Power Project third set of interrogatories & motion for protective order Responses to interrogatories not objectionable WETTERHAHN, M J. Conner, Moore & Corber 79/05/14 1p
- --7906230411 Objection by util to intervenor Miami Valley Power Project 790420 third set of interrogatories Seeks protective order re-objectionable discovery & proprietary info Certificate of Syc enci WETTERHAHN, M J Conner, Moore & Corber 79/05/14 App
- 7906250415 Forwards page 5 of applicant opposition to intervenor Miemi Valley Power Project motion to amend petition to intervene. Page was omitted from original filing CONNER, T B Conner, Moore & Corber 79/09/14 2pp
- 7906280258 Applicant responses to intervenor Miami Valley Power Project third set of interrogatories Affidavit & Certificate of Bvc enc!
  BORGMANN.E A Cincinnati Gas & Electric Co. 79/05/14 70pp
- 7906060040 Petition seeking suspension of hearing on GL application until envestigation of TMI is completed & released to public \* Affiliation Unknown. 79/05/16 Spp.
- 7906250158 Requests to make limited appearance at licensing prehearing, BUZIAN.R C Affiliation Unknown 79/05/18. 1p.

- 7906290520 Motion to amend petition to intervene & admit addl contentions re insufficiency of radiological air monitoring program proposed by applicant Affidavit & Certificate of Svc encl LUEBBERG, T A , HEILE, W P Cincinnati, OH 79/09/18 9pp
- 7906210063 Five requests to make limited appearance statements at licensing prehearing conference FLAHERTY, J. DIERIG.V., SCHADLER, T.E. Affiliation Unknown 79/05/22 Spp
- 7906020034 Ltrs from eight citizens requesting to be present or be represented at 790522 ½ 23 pre-hearing conferences
  MILLER.W R , CURRY, J A , HOWISON, C Affiliation Unknown 79/05/23
- 7906260021 Applicant opposes Miami Valley Power Project motion to allow participation of non-attys in hearing Should be denied as matter of policy & per NRC Rules of Practice Notice of appearance, documentation & Certificate of Syc encl CONNER, T B , RADER, R M Conner, Moore & Corber 79/05/30 2ipp
- 7706290575 Forwards testimony re Contention 6 testimony & prof qualifications of EA Borgmann R Rooney 790405 affidavit will be introduced into evidence re Contention 6 WETTERHAMN M J Conner. Moore & Corber 79/06/01 Opp
- 7906280103 Applicant response to City of Cincinnati motion to amend patition to intervene New contentions broaden issues & should not be admitted Cartificate of Byc encl CONNER.H J Conner. Hoore & Corber 79/06/04 Bpp
- 7906270250 Evidentiary hearing on 790619 will be held at US District Court Bldg.Cincinnati.OH Limited appearance statements will be taken on morning of 790619 & evening of 790620 BECHHOEFER.C Atomic Bafety and Licensing Board Panel 79/06/05
- J Insurance & indemnity information
- 7706190446 Forwards executed Amend 2 to Indemnity Agreement 8-85 BORGMANN, E A Cincinnati Gas & Electric Co 79/06/14 2pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906120174 Forwards response to second round questions submitted in NRC 790202 & 16 ltrs Response consists of Amend 93 to license application, in form of FSAR Revision 58 BOROMANN, E A Cincinnati Oas & Electric Co 79/06/08 2pp
- --7906120181 Revision 58 to FSAR, contained in Amend 93 to license application
  \* Cincinneti Gas & Electric Co 79/06/08 170pp
- 7906190405 Forwards Certificate of 8vc for Amend 93 to license application, in form of Revision 58 to FSAR BORGMANN.E A Cincinnati Gas & Electric Co 79/06/14 2pp
- G Inspection reports, IE Bullatins & correspondence
- 7906260192 Forwards IE Insp Rept 50-358/79-11 on 790418-19 No noncompliance noted FIORELLI,0 Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/01 2pp
- --7906260197 IE Insp Rept 50-358/79-11 on 790418-19 No noncompliance noted Major areas inspected safety-related hangers, restraints & snubbers YiN. I T., DANIELSON, D. H. Region 3, Chicago, Office of the Director 79/04/30 Spp
- 7906120093 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J Q Region 3, Chicago, Office of the Director 79/05/07
- 7906140520 Responds to IE Bulletin 79-09 re failure of GE Type AK-2 circuit breakers in safety-related sys. Breakers not utilized BOROMANN, E A Cincinnati Gas & Electric Co 79/05/09 1p
- 7906190084 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Awaemblies"
  KEPPLER, J. O Region 3, Chicago, Office of the Director. 79/05/11
- 7906260617 Responds to IE Bulletin 79-03 No ASME BA-312 Type 304 or other welded pipe mfg by Youngstown Welding & Engineering Co are in use BORGMANN.E A Cincinnati Qas & Electric Co 79/05/15 1p

- 7906130088 Forwards IE Bulletin 79-11, "Faulty Overcurrent Frip Devid in Circuit Breakers for Engineered Safety Sys " Licensee on required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/
- 7706200099 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Dyster Creek Reactor " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/
- 8 Reportable occurrences, LERs & related correspondence
- 7906190229 Forwards corrective actions to be implemented at plant Const on suppression gool mod adding safety release valve quencher discharge devices will cease until all conditions are fulfilled KEPPLER, J O Region 3. Chicago. Office of the Director 79/05/
- T Hearing transcripts on non-antitrust matters
- 7906060217 Transcript of 790521 meeting in Cincinnati.OH Pp 121-214 BECHHOEFER.C . HODPER.F F , BRIGHT.G O Atomic Bafety and Licensi Board Panel 79/05/21 93pp
- 7906060193 Transcript of 790522 prehearing conference in Moscow, DH Pp 215-532 BECHHOEFER.C , HOOPER.F F , BRIGHT.Q O Atomic Safety and Licensis Board Panel 79/05/22 146pp
- 7904040211 Transcript of 790523 prehearing conference in Cincinnation Pp 341-532 BECHHOEFER.C , HOOPER.F F , BRIGHT.G O Atomic Safety and Licensis Board Panel 79/05/23 185pp
- U Congressional/Executive Correspondence
- 7906250166 Responds to 790521 ltr which forwarded Heitkamp family 790412 ltr re inadequate welding 5 insp of components Heitkamp ltr forwarded to IE YORE, J R Atomic Safety and Licensing Board Panel 79/05/30 ip
- --7906250175 Forwards Heitkamp family 790412 ltr re allegations of inadequate welding & insp of components ORADIBON.O House of Rep. 79/05/21 3pp
- 7906280237 Forwards tables of environ radiological monitoring data around plant Data has been accumulated for three years
  Applicant program monitors routine releases IE is considering placing monitoring network at nuclear stations
  KAMMERER, C Office of Congressional Affairs 79/05/30 3pp
- OGCKET 50-340 BATTELLE MEMORIAL INST CRITICAL FACILITY

  Q Inspection reports, IE Bulletins & correspondence
- 7906180432 Forwards IE Info Notice 79-12, "Attempted Damage to New F Assemblies" No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Direc' 79/05/10 ip
- 79060B0213 Forwards IE Circular 79-08, "Attempted Er Enriched U " ENGELKEN,R H Region 5, 79/05/18 Ip

- 7906250078 Summary of 790320 neeting w/applicants re unresolved safety issues resulting from NRC review of OL application ROOD. Light Water Reactors Branch 2 79/05/17 5pp
- 7906250314 Summary of 790307-08 meeting u/utils in Bethesda.HD to discuss seismic/structural audit open items Attendance list threeting agenda encl ROOD,H Light Water Reactors Branch 2 79/05/22 App
- 7906120286 Forwards nonproprietary & proprietary version of "Response to NRC Question 221 19" re effects of fuel design mod on critical heat flux Proprietary version withheld (ref 10CFR2 790)

  NAYNES, J 0 Southern California Edison Co 79/05/29 600
- --7906120270 Nonproprietary version of "Response to NRC Guestion 221 19 "
  re effects of fuel design mod on critical heat flux
  \* Southern California Edison Co 79/04/25 14pp
- 790622028B Forwards data from 1978 Unit i radiological environ monitoring rept which includes radiological preoperational monitoring program for Units 2 % 3 Data supplies omissions from 1978 rept
  DRAKE.J H Southern California Edison Co 79/06/06 36pp
- 7906150386 Forwards requested archeological site location maps Some sites shown have potential for nomination to Natl Register of Historic Places Requests withholding of maps to protect sites Oversized drawings Available in Central Files only BASKIN.K P Southern California Edison Co 77/06/12 2pp
- F Security, medical, emergency & fire protection plans
- 7906040356 Notification of 790427 meeting w/util in Dethesda. HD to discuss fire protection requirements ROOD, H Light Water Reactors Branch 2 79/04/19 3pp
- O Adjudicatory correspondence
- 7903210409 Forwards application for SNM license submitted in Jul 1978 CHANDLER.L J Branch 1 79/03/06 ip
- --7903210415 Forwards application for SNM license DRAKE, J H Southern California Edison Co 78/07/18 4pp
- --7903210421 Application for SNM license for storage only of unirradiated reactor fuel > associated redicactive mat1
  \* Southern California Edison Co 79/02/i8 28pp
- 7906180679 Responds to 790220 ltr to Commissioner Gilinsky opposing OL issuance Recipient is party to ongoing licensing proceedings; further correspondence should be directed to atty for filing CHANDLER.L.J Branch 1 79/05/02 2pp
- --7906180691 Opposes OL issuance, due to danger of earthquake hear site Forwards San Diego Tribune article "Target San Onofre, One Man's Nuclear Battle," CARSTENS, A S Affiliation Unknown 79/02/20 7pp
- 7906200361 Requests schedule for hearing; wishes to testify FEARS, K Affiliation Unknown 79/03/17 1p
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 7706250321 Forwards Amend is to FSAR, "Final Rept on Hydraulic Model Studies of Containment Emergency Sump Recirculation Intakes " & "Rept of Evaluation of Max Earthquake Offshore Zone of Deformation " DRAKE, J H Southern California Edison Co 79/06/18 ip
- --7906250324 Amend 15 to FSAR \* Southern California Edison Co 79/06/18 400pp
- --7906250330 "Final Rept on Hydraulic Model Studies of Containment Emergency Sump Recirculation Intakes " \* Southern California Edison Co 79/01/31 100pp
- --7906250338 "Rept of Evaluation of Max Earthquake & Site Ground Motion Parameters Associated W/Offshore Zone of Daformation " \* Southern California Edison Co 79/06/30 275ap
- @ Inspection reports, IE Bulletins & correspondence
- 7906140210 Forwards IE Insp Repts 50-361/79-09 & 50-362/79-09 on 790129-0202 & 06-09 No moncompliance noted SPENCER, Q S Region 5, San Francisco, Reactor Construction & Engineering Support Branch. 79/04/11 2pp

- --7906140215 IE Insp Repts 50-361/79-09 % 50-362/79-09 on 790129-0202 % O6-09 No noncompliance noted Major areas inspected installation & welding of reactor coolant pressure boundary piping & other safety-related piping NARBUT.PP Region 5. Gan Francisco. Reactor Construction & Engineering Support Branch MAYNES,R C Region 5. Gan Francisco. Office of the Director 79/04/11 App
- 7906210342 Forwards IE Insp Repts 50-361/79-10 % 50-362/79-10 on 790301-31 No moncompliance noted SPENCER.0 S Region 5. San Francisco. Reactor Construction & Engineering Support Branch 79/04/20 2pp
- --7904210347 IE Insp Repts 50-361/79-10 to 50-362/79-10 on 790301-31 No noncompliance noted Major areas inspected safety-related electric component receiving storage to installation, piping storage, fit-up to grinding operation ELIN. J 0. PATE.R J Region 5. San Francisco, Office of the Director HAVNES,R C Region 5. San Francisco, Reactor Construction to Engineering Support Branch 79/04/20 7pp
- 7906120051 Forwards [E Info Notice 79-il, "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/07 io
- 7906180481 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/10 tp
- 7906080243 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/18 ip
- 7906:3005: Forwards IE Bulletin 79-1:, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN,R H Region 5, San Francisco. Office of the Director 79/05/22 ip
- 7906200056 Forwards IE Info Notice 77-13, "Indication of Low Water Lovel in Oyster Creek Reactor " ENORLKEN.R H Region 5. San Francisco. Office of the Director 79/05/29 1p
- S Reportable occurrences. LERs & related correspondence
- 7906180225 Forwards PNO-79-67AN ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/14 1p
- 7906180273 Forwards PNO-79-67AO ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/21 tp
- 7906180341 Forwards PNO-79-67AP ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/08/22 1p
- 7706180368 Forwards PND-79-67AQ ENCELMEN,R H Region 5, San Francisco, Office of the Director 79/05/30 1p
- 7906130236 Notifies that final rept to 790222 interim rept re Taylor Forga pipe defects will be delayed until 790622 NUNB, D E Southern California Edison Co 79/06/04 ip
- 7706270239 Forwards final deficiency rept re surface defects in Taylor Forge carbon steel pipe MOORE.J B Southern California Edison Co 79/06/22 1p
- --7906270246 Final deficiency rept Taylor Forge pipe defects
  Describes investigation of surface fissures in pipe All
  linear indications identified were removed by surface
  conditioning &/or weld repair
  \* Southern California Edison Co 79/06/22 Spp
- 7906290404 Forwards final deficiency rept re design deficiencies in containment polar crane support girder bracket connections MODRE, J B Southern California Edison Co 79/06/22 1p
- --7906290411 Final deficiency rept design deficiencies in containment polar crane support girder/bracket connections Structural members to be added to reduce tension load requirement on boits to acceptable level

  \* Southern California Edison Co 79/06/22 7pp

- DOCKET 50-362 SAN ONOFRE NUCLEAR STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7906210301 Discusses 790403 field trip to observe regional % site geology CARDONG, T , 808EL.P Geosciences Branch 79/03/03 Spp
- 7906250206 Summary of 790214 meeting w/utils in Bethesda.MD re unresolved safety concerns RODO.H Light Water Reactors Branch 2 79/03/16 21pp
- 7906230059 Forwards summary of 790403-05 geological site visit RODD, H Light Water Reactors Branch 2 79/05/17 3pp
- --7906250072 Comments on geologic & seismic review of repts on facility Suggests further study to determine true origin of landslide features in Horno Canyon area No careful study of fractures & shear joints under facility has been performed DAVIS.JF California. State of 79/01/16 3pp
- 7906250078 Summary of 790320 meeting w/applicants re unresolved safety issues resulting from NRC review of OL application ROQD,H Light Water Reactors Branch 2 79/05/17 Spp
- 7906250314 Summary of 790307-08 meeting w/utils in Bethesda.MD to discuss seismic/structural audit open items Attendance list to meeting agenda encl RODD.H Light Water Reactors Branch 2 79/05/22 6pp
- 7706120286 Forwards nonproprietary & proprietary version of "Response to NRC Question 22: 17" re effects of fuel design mod on critical heat flux Proprietary version withheld (ref 10CFR2 770)

  HAYNES, J O Southern California Edison Co 77/05/27 épo
- --7906120290 Nonproprietary version of "Response to NRC Question 221 19" re effects of fuel design mod on critical heat flux \* Southern California Edison Co 79/04/25 14pp
- 7906220288 Forwards data from 1978 Unit 1 radiological environ monitoring rept which includes radiological preoperational monitoring program for Units 2 & 3 Data supplies omissions from 1978 rept

  DRAKE, J. H. Southern California Edison Co. 79/06/06. 36pp
- 7906150386 Forwards requested archeological site location maps Some sites shown have potential for nomination to Natl Register of Historic Places Requests withholding of maps to protect sites Oversited drawings available in Central Files only BASKIN.K P Southern California Edison Co 79/06/12 2pp
- F Security, medical, emergency & fire protection plans
- 7906040336 Notification of 790427 meeting w/util in Bethesda, MD to discuss fire protection requirements ROQD, H Light Water Reactors Branch 2 79/04/19 3pp
- O Adjudicatory correspondence
- 7903210409 Forwards application for SNM license submitted in Jul 1978 CHANDLER, L J Branch 1 79/03/06 ip
- --7903210415 Forwards application for SNM license
  DRAKE, J H Bouthern California Edison Co 78/07/18 4pp
- --7903210421 Application for SNM license for etorage only of unirradiated reactor fuel & associated redicactive matl
  \* Southern California Edison Co 79/02/18 28pp
- 7906180677 Responds to 790220 ltr to Commissioner Gilinsky opposing QL issuance. Recipient is party to ongoing licensing proceedings; further correspondence should be directed to atty for filing CHANDLER, L. J Branch i 79/05/02 2pp.
- --7906180691 Opposes OL issuence, due to danger of earthquake near site Forwards San Diego Tribune article "Target San Onofre, One Man's Nuclear Battle," CARSTENS: A B Affiliation Unknown 79/02/20 7pp
- 7906200361 Requests schedule for hearing; wishes to testify, FEARS, K. Affiliation Unknown 79/05/17 lp.

- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906250321 Forwards Amend 15 to FSAR. "Final Rept on Hydraulic Model Studies of Containment Emergency Sump Recirculation Intakes " > "Rept of Evaluation of Max Earthquake Offshore Zone of Deformation" DRAKE.J H Southern California Edison Co 79/04/18 1p
- ---7906250324 Amend 15 to FSAR
  \* Southern California Edison Co 79/06/18 400pp
- --7706250330 "Final Rept on Hydraulic Model Studies of Containment Emergency Sump Recirculation Intakes " \* Southern California Edison Co 77/01/31 100pp
- --7906250338 "Rept of Evaluation of Max Earthquake & Site Ground Motion Parameters Associated W/Offshore Zone of Deformation " \* Southern California Edison Co 79/06/30 275pp
- Q Inspection reports, IE Bulletins & correspondence
- 7906140210 Forwards IE Insp Repts 50-361/79-09 % 50-362/79-09 on 790129-0202 % 06-09 No noncompliance noted SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- ---7906140215 IE Insp Repts 50-361/79-09 & 50-362/79-09 on 790129-0202 & O6-09 No noncompliance noted Major areas inspected installation & welding of reactor coolant pressure boundary piping & other safety-related piping NARBUT, P Region 5, San Francisco, Reactor Construction & Engineering Support Branch HAYNES, R C Region 5, San Francisco, Office of the Director 79/04/11 6pp
- 7706210342 Forwards IE Insp Repts 50-361/79-10 t 50-362/79-10 on 770301-31 No noncompliance noted SPENCER.0 S Region 5, San Francisco, Reactor Construction to Engineering Support Branch 77/04/20 2pp
- --7904210347 IE Insp Repts 50-361/79-10 & 50-362/79-10 on 790301-31 No nancompliance noted Major areas inspected safety-related electric component receiving, storage & installation, piping storage, fit-up & granding operation ELIN, J O. PATE, R J. Region 5, San Francisco, Office of the Director HAYLES, R C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/20 7pp
- 7706120051 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ENGELKEN.R H Region 5, Ban Francisco, Office of the Director 79/03/07 1p
- 7906:8048: Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary.

  ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/10 ip
- 7906080243 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched V " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/03/18 lp
- 7906:130051 Forwards IE Builetin 79-ii. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKENIR H Region 5. San Francisco, Office of the Director 79/05/22 1a
- 7906200056 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/29 is
- 8 Reportable occurrences, LERs & related correspondence
- 7906180225 Forwards PNO-79-67AN ENGELKEN, RH Region 5, San Francisco, Office of the Director, 79/05/14 ip
- 7906180273 Forwards PNU-79-67AO
  ENGELKEN,R H Region 5, San Francisco, Office of the Director.
  79/05/21 ip
- 7906180341 Forwards PNO-79-67AP ENGELKEN,R H. Region 5: San Francisco, Office of the Director. 79/05/22 ip

l<sub>e</sub>q.

- 7906180368 Forwards PNO-79-67AQ ENGELKEN:R H Region 5. San Francisco. Office of the Director 79/05/30 1p
- 7906130236 Notifies that final rept to 790222 interim rept re Taylor Forge pips defects will be delayed until 770622 NUNN,D E Southern California Edison Co 77/06/04 lp
- 7906270239 Forwards final deficiency rept re surface defects in Taylor Forge carbon steel pipe
  MODRE, J R Southern California Edison Co 79/06/22 1p
- --7906270246 Final deficiency rept Taylor Forge pipe defects
  Describes investigation of surface fissures in pipe All
  linear indications identified were removed by surface
  conditioning 5/or weld repair
  \* Southern California Edison Co 79/06/22 Bpp
- 7906290404 Forwards final deficiency rept re design deficiencies in containment polar crane support girder bracket connections MOORE, J B Southern California Edison Co 79/06/22 1p
- --7906290411 Final deficiency rept design deficiencies in containment polar crane support girder/bracket connections Structural members to be added to reduce tension load requirement on bolts to acceptable level
   Southern California Edison Co 79/06/22 7pp
- ODCKET 50-363 FORKED RIVER NUCLEAR STATION, UNIT 1

  @ Inspection reports, IE Bullstins & correspondence
- 7906180389 Forwards IE Info Notice 79-10. "Noncomforming Pipe Support Struts" No written response necessary GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/16 1p
- 7906040401 Ack receipt of 790315 itr informing NRC of steps taken to correct violations noted in IE lnsp Rept 50-363/78-15
  CARLEON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Brench 79/04/17 ip
- --7904040407 Responds to NRC 781214 ltr re violations noted in IE Insp Rept 50-363/78-15 Corrective actions theodolite was serviced & two tachometers sent for recalibr FINFROCK. I R Jersey Central Power & Light Co 79/03/15 1p
- 7906110013 Forwards IE Bulletin 79-038. "Huclear Incident at THI-Suppi " No written response required ORIER.8 H Region 1. Philadelphia. Office of the Director 79/04/23 ip
- 7906070394 Responds to IE Bulletin 79-09 No GE Type AK-2 circuit breakers purchased to date FINFRGCK, I R Jersey Central Power & Light Co 79/05/01 tp
- 7906070395 Responds to IE Bulletin 79-04 Swing check valves not installed in facility
  FINFROCK.I R Jersey Central Power & Light Co 79/05/01 1p
- 7906180179 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-363/79-02 CARLBON,R T Region L. Philadelphia, Reactor Construction & Engineering Support Branch 79/03/03 ip
- ---7906190185 Responds to NRC 790312 Itr re violations noted in IE Insp Rept 50-363/79-02 Corrective actions initiation of program for daily monitoring of equipment pressurized w/inert gas FINFROCK.IR Jersey Central Power & Light Co 79/04/20 2pp
- ---7906150190 Forwards IE Insp Rept 50-363/79-02 on 790212-15 & notite of violation CARLBON:R T Region 1: Philadelphia: Reactor Construction & Engineering Support Branch 79/03/12 2pp
- --7906130192 Notice of violation from insp on 790212-19
  \* Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/03/09 1p
- --7906150195 IE Insp Rept 50-363/79-02 on 790212-15 Noncompliance noted failure to monitor pressure of inert gas blanket as required NARDOWL : CERNE, A C : MCGAUGHY, R W Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/09 10pp.

- 7706120163 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER.D H Region 1, Philadelphia. Office of the Director 79/05/07 200
- 7906280112 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  GRIER, B H Region 1, Philadelphia. Office of the Director 79/05/11 Ip
- DOCKET 50-364 JOSEPH M FARLEY NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7906190464 Forwards info re PWR feedwater lines in response to NRC 790525 request Four oversized drawings encl (4/o encl CLAYTON: F L Alabama Power Co 79/06/15 140pp
- G Inspection reports, IE Bulletins & correspondence
- 7906220248 Forwards IE Insp Repts 50-340/79-14 & 50-364/79-06 on 790327-29 & notice of violation MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- 7906140150 Forwards IE Insp Repts 50-348/79-15 & 50-364/79-05 on 790402-07 No noncompliance noted LEMIS,R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/17 2pp
- --7906140197 IE insp Repts 30-348/79-15 % 30-364/79-05 on 790402-07 No noncompliance noted Major areas inspected preoperational test procedures & test procedure for mod & refueling HAGNER, A G. HARTIN.R D. Region 2, Atlanta, Office of the Director 79/04/14 4pp
- 7904290483 Responds to IE Bulletins 79-06 % 79-06A. Revision 1 Forwards info re TMI incident Proposed design & Tech Spec changes will be submitted by 790514 CLAYTON,F C. Alabama Power Co 79/04/24 21pp
- 7905220244 Act receipt of 790427 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-340/79-14 % 50-364/79-06 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/07 ip
- --7906220247 Responds to NRC 790411 ltr re violations noted in IE Insp Repts 50-340/79-14 & 50-364/79-06 Corrective actions new in-house procedure implemented to control electrical prints & instruction of all field supervision CLAYTON.F L Alabama Power Co 79/04/27 2pp
- --7906220249 Notice of violation from insp on 790327~29

  \* Region 2, Atlanta, Office of the Director 79/04/12 ip
- --7906220250 IE Insp Repts 50-340/79-14 ½ 50-364/79-06 on 79032/-29 Noncompliance noted failure to control superseded drawings HUNT,M D Region 2. Atlanta, Office of the Director HERDT, A R Region 2. Atlanta, Reactol Construction & Engineering Support Branch 79/04/12 4pp
- 7906250437 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7906290761 Responds to IE Bulletin 79-09 GE Type AK-2 circuit breakers are used in safety-related features at Units 1 & 2 CLAYTON,F L Alabama Power Co 79/05/18 2pp
- 8 Reportable occurrences, LERs & related correspondence
- 7906010280 FOIA request for documents re abnormal occurences at plants, info re Westinghouse proposed nuclear fuel assembly plant in Prattville, AL & info re transportation of nuclear waste & fuel through AL QAKES, D.L. Affiliation Unknown, 79/04/23 2pp
- 7906010277 Responds to 790423 FOIA request Forwards computer printout of abnormal occurrences at plants until May 1979, paper on "Transportation of Nuclear Fuel & Waste," & list of package designs for which util is registered FELTON, J M Division of Rules and Records 79/05/30 57pp

- 7906260333 Forwards 790615 ltr to EPA re item of noncompliance Analysis of turbine bldg sump effluent showed 9 13 pH Caused by error in sampling 5 analysis Steps have been taken to ensure violation does not recur CLAYTON.F L Alabama Power Co 79/06/19 2pp
- DOCKET 50-366 EDWIN I MATCH NUCLEAR PLANT, UNIT 2

  F Security, medical, emergency & fire protection plans
- 7906050274 Forwards proposed amends to fire protection Tech Specs covering addl fire detection instrumentation & water suppression sys WHITMER:C F Georgia Power Co 79/03/29 13pp
- J Insurance & indemnity information
- 7906190307 Forwards Endorsements 40 & 41 to ANI Policy MF-78 DUCK,J R Marsh & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/12 3pp
- P Operating license stage documents & correspondence
- 7906110155 Proposes amend to Tech Specs Amend would substitute use of core max fraction of limiting power density for max total peaking factor in determination of average power range monitor scram & rod block trip settings
  WHITMER.C F Georgia Power Co 79/06/05 lipp
- G Inspection reports, IE Bulletins & correspondence
- 7906070021 Forwards IE Bulletin 79-08. "Events Relevant to BWRs Identified During TMI Incident " Licensee action required D'REILLY, J P Region 2. Atlanta. Office of the Director 79/04/14 2pp
- 7906050003 Ack receipt of IE lnsp Repts 50-321/79-09 % 50-366/79-11 No proprietary info STAFFAR W Georgia Power Co 79/04/19 ip
- 7906030074 Ack receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-366/79-09 LEWIB.R C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/25. Ip
- --7906050085 Responds to NRC 770323 ltr re violations noted in 1E Insp Rept 50-366/79-09 Corrective actions startup test procedures being changed to use correct core max peaking factor value STAFFA:R W Georgia Power Co 77/04/16 1p
- --7906050194 Forwards 1E Insp Rept 50-366/79-09 on 790220-23 & notice of violation LEMIS.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/03/23 2pp
- --7906050091 Notice of violation from insp on 79020-23
  \* Region 2. Atlanta. Office of the Director 79/03/23 ip
- --7906050100 IE Insp Rept 50-366/79-09 Noncompliance noted failure to effect proper corrective action in disseminating corrected value for core max peaking factor VOOT-LOUGELLR, MARTIN,R D Region 2, Atlanta, Office of the Director 79/03/23 5pp
- 790605010B Ack receipt of IE Insp Rept 50-366/79-13 on /90314-0316 No proprietary info STAFFA:R W Coorgia Power Co 79/04/25 1p
- ---7906050113 Forwards lE Insp Rept 50-366/79-13 on 790314-0316 No noncompliance noted. MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906050117 IE Insp Rept 50-366/79-13 on 790314-16 No noncompliance noted Major areas inspected concrete expansion affithor installation MODENOS,L Region 2, Atlanta, Défice of the Director BRYANT,J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 3pp
- 7906140081 Ack receipt of IE Insp Repts 50-321/79-10 & 50-366/79-12 on 790314-0316 No proprietary info, STAFFA.R.W Georgia Power Co 79/04/25 ip
- --7906140085 Forwards IE Insp Repts 80-321/79-10 & 50-366/79-12 on 790314-0316 No noncompliance noted LEMIE.R C Region 2, Atlanta, Reactor Operations Nuclear Bupport Branch 79/04/03 2pp

- --7906140093 IE Insp Rapts 50-321/79-10 & 50-366/79-12 on 790314-16 No noncompliance noted Major areas inspected IE circulars & bulletins.LERs & followup of previous insp findings HINKLEY,D 0 Region 2. Atlanta, Office of the Director DANCE,H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/03 5pp
- 7906(40436 Responds to IE Bulletin 79-07 Discusses computer programs used in stess analysis of safety-related piping BTAFFA:R H Georgia Power Co 79/04/25 2pp
- 7906:30141 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/02 io
- 7906250455 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fue Assemblies " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 ip
- 7906:10065 Forwards IE Builstin 79-10, "Requalification Fraining Program Statistics" Written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/11 10
- 7906200522 Ack receipt of 790410 & 0508 ltrs informing NRC of steps taken to correct violations noted in 1E lnsp Repts 50-321/79-08 & 50-366/79-10 LENIG.R C Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/05/15 1p
- --7906200527 Responds to NRC 790306 itr re violations nated in 1E Insp Repts 50-321/79-08 & 50-366/79-10 Corrective actions new policy re definition of operability has been established & test results will be reported STAFFA,R W Georgia Power Co 79/04/10 2pp
- --7906200532 Respond to NRC 790424 telcon to violations noted in IE In Repts 50-321/79-08 & 50-366/79-10 Corrective actions Tack Specs re inoperability reporting will be followed & test acceptance criteria will be followed STAFFA,R W Georgie Power Co 79/05/08 Ip
- --7906200540 Forwards IE Insp Repts 50-321/79-08 & 50-366/79-10 on 781216-19,790101-03 & 0129-0209 & notice of violation O'REILLY, J P Region 2, Atlanta, Office of the Director 79/03/16 2pp
- --7906200544 Notice of violation from insp on 790216-17.770101-03 & 0127-0209

  \* Region 2. Atlanta, Office of the Director 77/03/08 ip
- --7906200352 IE Insp Repts 50-321/79-08 \$ 50-366/79-10 on 781216-19, 790101-03 \$ 0129-0209 Noncompliance noted failure to rept HPGI & reactor core isolation cooling inoperable \$F\$ failure to rept recirculation flow coastdown test results ROBERS,R F Region 2. Atlanta. Diffice of the Director DANCE,H C Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/03/08 4pp
- R Periodic operating reports & related correspondence
- 7906120426 Forwards monthly operating rept for May 1979 MANRY, M Georgia Power Co 79/06/06 1p
- --7906120429 Monthly operating rept for May 1977 STANCIL:R Georgia Power Co 79/06/02 6pp
- S Reportable occurrences. LERs & related correspondence
- 7906150296 Forwards LER 79-009/03L-0 MANRY, M Georgia Power Co 79/01/24 1p
- --7906150304 LER 79-009/03L-0 on 790111 low switch & high switch of 2E51-N018 operated contrary to Tech Specs Caused by switch setpoint drift Corrected by performance of HNP-2-5202 procedure NIX.R.T. Georgia Power Co. 79/01/24 1p
- 7906060224 Forwards LER 79-034/01T-0 MANRY, M Georgia Power Co 79/05/21 1p
- --7906060227 LER 79-034/01T-0 on 790514 instruments in remate shutdown panel H21-P173 & heating.ventilation & air conditioning panels H11-P654 & H11-P657 did not meet seismic requirements Caused by installation error Proper instruents GREENE, T V Georgia Power Co 79/05/21 Zpp

1

1 1

100

1.164

, |

7706060233 Forwards LER 79-035/03L-0 MANRY, M Georgia Power Co 79/05/24 1p

--7906060239 LER 79-035/03L-0 on 790515 procedure HPN-2-3195, weekly breaker alignment checks, was performed one day late Caused by late issuance of assignment sheets Surveillance engineer made aware of importance of prompt sheet issuance GREENE.T V Georgia Power Co 79/05/24 ip

7906140414 RO 90-366/79-39 on 790524 listed valves did not meet individual valve leak rate criteria.per ASME Section XI MANRY.M Georgia Power Co 79/09/24 1p

7906140355 RO 50-366/79-40 on 790525 insp of piping for feedwater flow transmitters revealed sensing lines piped up incorrectly Piping arrangement will be changed prior to startup MANRY,M Georgia Power Co 79/05/25 ip

7906140467 RO 50-366/79-36 on 790923 during review of Class [E equipment, reactor sample isolation valve 2821-AOV-F019 did not have complete radiation qualification test rept document Redundant valve available to compensate MANRY, M Georgia Power Co 79/05/25 1p

7906060243 Forwards LER 79-036/01T-0 MANRY, M Georgia Power Co 79/05/30 1p

--7906060249 LER 79-036/01T-0 on 790516 sprinkler hanger mods indicated seismic design deficiency for cable spreading room designs Proper analysis & mods have begun GREEN.T V Georgia Power Co 79/05/30 4pp

7906140341 Forwards LER 79-038/01T-0 MANRY:M Georgia Power Co 79/03/30 1p

--7706140346 LER 79-03B/01T-0 on 790523 proper seismic documentation for RMS was absent Caused by failure to document change Review of other changes revealed no problems GREENE.T V Georgia Power Co 79/05/30 1p

7906140501 Forwards LER 79-041/01T-0 MANRY, M Georgia Power Co 79/05/30 1p

--7906140509 LER 79-041/01T-O on 790523 during maint outage, review indicated solenoid on reactor sample isolation valve did not have complete qualification testing Caused by design error Solenoid will be replaced GREENE

7706140517 Forwards LER 79-039/01T-0 MANRY.M Georgia Power Co 79/05/30 1p

---7906140532 LER-039/01T-0 on 790523 during shutdown.one feedwater check valve & three RHR gump suction valves deemed to have excessive leak rates Caused by change to ASME criteria AAME criteria reviewed & found too strigent GREENE.T V Georgia Power Co 79/05/30 3pp

7906140526 Ferwards LER 79-040/017-0 MANRY, M Opengia Power Co 79/05/31 1p

--7906140531 LER 79-040/01T-0 on 790523 during repair outage, two feedwater flow elements found piped to wrong low pressure taps Caused by personnel error during const Flow elements were repiped to correct taps OREENE:T V Georgia Power Co 79/05/31 3pp

7906140419 Farwards LER 79-037/03L-0 MANRY, M Georgia Power Co 79/06/01 Ip

--7906140424 LER 79-037/03L-0 on 790517 during cold shutdown, technicians inadvertently set isolation trip setpoint of alarm units 2031-K603AkB for leakage flow of 134 gallons/minute Caused by incorrect procedure Procedure revised NIX.R T Georgia Power Co 79/06/01 1p

7906140255 LER 50-366/044-0 has been voided MANRY, M Georgia Power Co. 79/06/04 ip

7906140447 Forwards LER 79-023/03L-1 MANRY, M Georgia Power Co 79/06/04 1p

7906i30270 LER 79-023/03L-1 on 790214 while performing startup test procedure HNP-2-10925 (MSIV closurs), discovered 2821-F028A outboard MSIV closed in 2-s Caused by failure of seal cartfidge bushing & seal assembly Parts repaired OREENEIT V Georgia Power Co 79/06/04 ip

7906200444 RO 50-366/1979-45, Revision O, on 790603 following reactor scram, 2L41-C001 HPC1 pump failed to start Caused by HPC1 stop valve remaining closed MANRY, M Georgia Power Co 79/06/04 ip

7906190361 Forwards LER 79-032/03T-0 MANRY, M Georgia Power Co 79/06/07 1p

---7906190366 LER 79-032/03T-0 on 790308 during review of emergency load shed logic schemes.possibility for unnecessary trip of plant svc water pump during LOCA arose Logic schemes to be modified GREENE,T V Georgia Power Co 79/06/07 Ip

7906190436 RO 50-366/79-45, Revision 1.on 790607 during reactor power ascension, power level fell below 1.000 counts, causing HPCI to initiate Caused by leaking HPCI pump mechanical seal Vessel level maintained by restoring condensate sys MANRY, M Georgia Power Co 79/06/07 3pp

7906190485 Ferwards LER 79-029/03L+1 MANRY,N Georgia Power Co 79/06/08 1p

--7906190492 LER 79-027/03L-1 on 790315 while shut down for repairs, main steam safety relief valve discharge line vacuum breaker valves found to be partially opened, hinge pins bent % springs distorted Caused by valves being slammed open NIX.R T Georgia Power Co 79/06/07 2pp

7906190385 Forwards LER 79-046/01T-0 MANRY, M Georgia Power Co 79/06/11 ip

--7906190390 LER 79-046/01T-0 on 790603 following stram, reactor core isolation cooling sys tilpped Caused by ruptured turbine exhaust diaphragm NiX:R T Georgia Powor Co 79/06/11 3pp

7906190496 Forwards LER 79-043/03L-0 MANRY,M Georgia Power Co 79/06/11 1p

--7906190502 LER 79-043/03L-0 on 790527 while performing normal surveillance procedure HNP-2-3011 on pressure switches 2B21-NO20A & B.switches tripped at 1,066 & 1,067 psig Caused by setpoint drift NIX.R T Georgia Power Co 79/06/11 ip

7906190309 Forwards LER 79-045/01T-0 MANRY:M Georgia Sower Co 79/06/11 ip

--7906190514 LER 79-045/01T-O on 790603 following reactor scram, HPCI sys received initiation signal but failed to start when turbine stop valve did not open Caused by smal water line leaking water to bracket drain cavity Line repaired NIX,R T Georgia Power Co 79/06/11 3pp

7906210167 LER 79-042 is voided MANRY, M Georgia Power Co 79/06/11 1p

7906150264 LER 79-027 has been voided \* Georgia Power Co 79/06/14 lp

7906150331 LER 79-012 has been voided \* Georgia Power Co 79/06/14 1p

7906150333 LER 79-018 has been voided \* Georgia Power Co 79/06/14 ip

DOCKET 50-367 BAILLY GENERATING STATION

G Inspection reports, IE Bulletins & correspondence

7906120118 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/07 to

7906060063 Responds to IE Bulletin 79-03 No ABME SA-312 Type 304 welded pipe used SHOR8.E M Northern Indiana Public Service Co 79/05/09 ip

7906190096 Forwards IE Info Notice 79~12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3. Chicago. Office of the Director 79/05/11

- 7906230040 Responds to IE Bulletin 79-04 Swing check valves have not been purchased or solicited from Velan Engineering Corp SHORB,E M. Northern Indiana Public Service Co. 79/05/21 ip
- 7906130104 Forwards IE Bulletin 79-ti. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Gafety Sys " Licensee action required KEPPLER, J O Region 3. Chicago. Office of the Director 79/05/22
- 790620012B Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906050306 Forwards plant well charts, well level readings, water meter readings, pond level readings, pneumatic pressure transducer measurements. Flint Lake pump station rainfall readings BOHN.R.J. Northern Indiana Public Service Co. 79/05/25 33pp
- 7906:10179 Forwards 7905:6-23 well charts.790523 Bailly wells w/o recorders.790523 pond levels.790523 pneumatic pressure transducers & 790523 water meter readings
  BDHN.R J Northern Indiana Public Service Co 79/06/06 32pp
- 7906190439 Forwards well charts for 790523-30, wells w/o recorders, pneumatic pressure transducars water meter readings for 790530 t pond levels for 790530 BDHN,R J Northern Indiana Public Service Co 79/06/08 32pp
- 7906260425 Forwards info well charts for 790530-0606.Bailly wells w/o recorders for 790606, pand levels, pneumatic pressure transducers, water mater readings & USGS wells for 790606 BOHN,R J Northern Indiana Public Service Co 79/06/15 32pp
- 7906270108 Forwards well charts for 790606-13, Bailly wells w/o recorders for 790613, pond levels for 790613, pneumatic pressure tranducers for 790613 & water moter readings for 790613 BOHN R J Northern Indiana Public Service Co 79/06/22 32pp
- U Congressional/Executive Correspondence
- 7906290245 Responds to 790413 ltr re installation of safety-related short pillings 2 evacuation plans for facility Discusses reviews leading to issuance of CP Forwards FES W/o encl OBSSICK, L V Office of the Executive Director for Operations 79/05/21 3pp
- --7906290261 Requests complete review of facility CP.including proposed use of short pilings Requests examination of evacuation plans & public hearing ro CP FITHIANLE J House of Rep 79/04/13 2pp
- DOCKET 50-368 ARKANBAS NUCLEAR ONE, UNIT 2
- F Becurity, medical, emergency & fire protection plans
- 7906270147 Responds to 790613 ltr re GA section of fire protection plan Util has met guidelines of "Nuclear Plant Fire Protection Function Responsibilities, Administrative Controls & GA "No changes planned TRIMBLE,D C Arkansas Power & Light Co 79/06/18 2pp
- G Adjudicatory correspondence
- 7906270088 Forwards proposed order confirming util commitment to shut down facility & modify operating procedures
  DENTON: H R Office of Nuclear Reactor Regulation 79/05/14 Spp
- 7906270097 Summary of 790509 meeting w/ulil to evaluate emergency feedwater sys in terms of TMI incident ENGLE/L B Light Water Reactors Branch 1 79/09/15 13pp
- 7906270093 Orders shutdown of plant pending upgrade, testing & analyses of emergency feedwater sys CHILK:8 J Office of the Secretary of the Commission 79/05/17
- P Operating license stage documents & correspondence
- 7906200316 Summary of 790509 meeting w/util in Bethesda, MD re emergency feedwater sys.List of attendees & request for addl info enci ENGLE: L Light Water, Reactors Branch 1 79/05/15 6pp

- 7906080306 Discusses mod of operating guidelines for small breaks HP: must remain in operation until LPIS is in operation & flowing in excess of 1.000 gallons/minute in each line & stable for 20 minutes TAYLOR, J H Babcock & Wilcox Co 79/05/30 2pp
- 7906190240 Forwards APL-TOP-1A.Revision 5. "GA Manual Operations." util Position 421 5B re grout matl testing 5 add1 info on Position 421 60 re physical properties of reinforcing steel TRIMBLE, D C Arkansas Power 5 Light Co 79/06/i1 4pp
- --7906190245 "QA Manual Operations." Revision 5 CAVANAVOH,W Arkansas Power & Light Co APL-TOP-1A 79/06/11 1200
- 7906200214 Forwards oversized drawings of contected feedwater lines to steam generator, including results of stress analysis tests & details of welding processes used in making notzle-tu-pipe, pipe-to-sparger & pipe welds: in response to 790525 request TRIMBLE.D C Arkansas Power & Light Co 79/06/18 19pp
- 7906270115 Rubmits addl info re gaseous effluent monitoring sys.in response to 790615 request Discusses location of effluent monitoring sys detectors range of scintillation detectors & max detectable release rate TRIMBLE.D C Arkansas Power & Light Co 79/06/22 11pp
- G Inspection reports. IC Bulletins & correspondence
- 7906150023 Forwards IE lnsp Repts 50-313/79-06 & 50-368/79-06 on 790212-0318 & notice of violation MADSEN.6 L. Region 4. Dallas, Reactor Operations Nuclear Suppo Branch 79/04/04 2pp
- --7906190045 Notice of violation from insp on 790212-0318

  \* Region 4, Dallas, Office of the Director 79/04/04 is
- --7706150055 IE Insp Repts 50-313/79-06 ½ 50-368/79-06 on 770212-0311
  Noncompliance noted inadequacy of control of non-Class IE
  test equipment
  HESTERMAN T F , JDHNSON, W D , SPANGLER, R G Region 4, Dallas,
  Office of the Director 79/04/03 18pp
- 7906050213 Requests addl 30 days to respond to IE Bulletin 79-03 re welding piping manufactured by Youngstown Welding & Engineering Records are currently being searched, response to be submitted by 790514 TRIMBLE.D C Arkanses Power & Light Co 79/04/12 ip
- 7906070374 Responds to IE Bulletin /9-04 ro use of Velan swing check valves Higher weights were used in soismic analysis; analyses are conservative TRIMBLE.D C Arkansas Power & Light Co 79/04/27 2pp
- 7906040149 Ack receipt of 790321 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-04 ½ 50-368/79-04 MADSEN.G L Region 4, Dallas, Reactor Operations Nuclear Suppo Branch 79/04/30 ip
- --7704040152 Responds to NRC 770228 itr re violations noted in IE In Repts 50-313/79-04 & 50-368/79-04 Corrective actions all effluent monitors to be calibr by 790401 TRIMBLE.D.C Arkansas Power & Light Co 79/03/21 2pp
- --790&040156 Forwards IE insp<sup>°</sup> Repts 50-313/79-04 & 50-368/79-04 on 790205-09 % notice of violation MADBEN.O L Region 4, Dallas, Reactor Operations Nuclear Support Branch 79/02/28 2pp
- --7906040160 Notice of violation from insp on 790205-09

  \* Region 4, Dallas, Office of the Director 79/02/29 ip
- --7906040162 IE Insp Repts 50-313/79-04 ½ 50-368/79-04 on 790205-09 Noncompliance noted failure to calibr effluent monitors MURRAY, B Region 4, Dallas, Office of the Director BROWN, G Region 4, Dallas, Fuel Facility & Materials Safety Branch, 79/02/25 6pp
- 7906040209 Responds to IE Bulletin 79-03 Some ASME SA-312 Type 304 longitudinal welded pipe afg by Youngstown Welding & Engineering Co installed in safety-related sys Examination program being developed TRIMBLE: D C Arkansas Power & Light Co 79/05/04 ip
- 7906120069 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required SEYFRIY.K V Region 4, Dallas, Office of the Director 79/05/01

- 7904110083 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 79/05/11 to
- 7906250016 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/11
- 7908250095 Ack receipt of 790826 ltr informing NRC of steps taken to correct violations nated in IE Insp Rept 50-368/79-06 MADSEN.O L. Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/22 ip
- --7906250105 Responds to NRC 790404 ltr re violations noted in IE Insp Rept 50-368/79-06 Corrective actions controls for connecting test equipment to safety-related equipment will be established TRIMLBE.D C Artansas Power & Light Co 79/04/26 2pp
- 7906260530 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-313/79-05 & 50-368/79-05 Requests addl info re steps taken to prevent recurrence of two items of noncompliance HADSEN, G L Region 4. Dallas, Reactor Operations Nuclear Support Branch 79/05/22 1p
- 7906260231 Forwards IE Insp Rept 50-368/79-11 on 790509-11 No noncompliance noted HINDS J A Region 3. Chicago, Safeguards Branch 79/05/24 2pp
- --7906260237 IE Insp Rept 50-368/79-11 on 790509-11 No noncompliance noted Major areas inspected shapping & receiving inventory & nuclear mati control Details withheld (ref 100FR2 790). FINLEY:A G . PATTERSON.J P . HIND.J A Region 3. Chicago, Safeguards Branch 79/05/21 ip
- 7906200039 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Oyster Creek Reactor" SEYFRIT.K V Region 4. Dallas. Office of the Director 79/05/29 ip
- 7906210229 Responds to IE Bulletin 79-11 No Westinghouse DB-75 or DB-50 circuit breakers are used in safety-related Class IE circuits
  TRIMBLE.D C Arkensas Power & Light Co 79/06/14 ip
- R Periodic operating reports & related correspondence
- 7906190268 Forwards monthly operating rept for Hay 1979
  TRIMBLE, D.C. Arkansas Power & Light Co. 79/06/15 ip
- --7906190273 Manthly operating rept for May 1979 EHIVELY,C N Arkansas Power & Light Co 79/06/14 Spp
- S Reportable occurrences, LERS & related correspondence
- 7906180142 Forwards PNO-79-67AM MADSEN,O L Region 4. Dailas. Reactor Operations Nuclear Support Branch 79/05/09 1p
- 7906180192 Forwards PNO-79-67AN
  MADBEN, Q L Region 4, Dallas, Reactor Operations Nuclear Support
  Branch. 79/05/16 1p
  - s PNO-79-67AO > AP Region 4. Dallas, Reactor Operations Nuclear Support

79-036/03L-0 & 79-037/03L-0 Co 79/06/12 1p

- --7706180587 LER 79-037/03L-0 on 790514 during Mode 3, supply valves to steam generator would not respond to control room demand signal Caused by blown fuse & stuck relay Similar to LER 50-368/77-026 Repairs made & valves proven operable SHIVELY, C N Arkansas Power & Light Co 79/06/12 1p
- DOCKET 50-369 WILLIAM B MCGUIRE NUCLEAR STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 7905140539 Concurs w/applicant evaluation of Reg Guide 1 114.Revision line conformance to R3C matters Facility complies w/reg guide HOLMAN, J Derator Licensing Branch 79/05/14 ip
- 7906250322 Notification of 790608 meeting w/util in Bethesda.MD to review radiological effluent Tech Specs
  BIRKEL.R A Light Water Reactors Branch 2 79/05/25 3pp
- J Insurance & indemnity information
- 7906150280 Forwards executed Amend 2 to Indemnity Agreement B-83 PARKER.W O Duke Power Co 79/06/07 2pp
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS.F D Dute Power Co 79/06/08 Spp
- **G** Inspection reports, 1£ Bulletins & correspondence
- 7904040360 Ack receipt of TE Insp Repts 50-369/79-18 % 50-370/79-09 on 790313-15 No proprietary info PARKER.W O Dute Power Co 79/04/23 1p
- --7906040362 Forwards IE Insp Repts 50-369/79-18 & 50-370/79-09 on 790313-15 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/28 2pp
- --7906040366 IE Insp Repts 50-369/79-18 & 50-370/79-09 on 790313-15 No noncompliance noted Major areas inspected nondestructive testing const deficiency repts, warehouse storage, outside storage areas GA audits & JE bulletin responses HUNT.M D Region 2. Atlanta. Office of the Director HERDT.A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 App
- 7906160024 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/79-15 & 50-370/79-07 MURPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/25 ip
- --7906160033 Responds to NRC 790323 Itr re violations noted in IE Insp Repts 50-369/79-15 & 50-370/79-07 Corrective actions all const & const GA personnel instructed in manufacturer's manual use PARKER, H O Duke Power Co 79/04/18 2pp
- --7906160037 Forwards IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790228-0302 & notice of violation MURPHy.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/23 2pp
- --7906160041 Notice of violation from insp on 790228-0302 Region 2: Atlanta, Office of the Director 79/03/23 1p
- --7906160044 IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790228-0302 Noncompliance noted assembly of safety valves w/o documented instructions ANG-M.P. Region 2. Atlanta, Office of the Director BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/03/23 4pp
- 7906250443 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  O'REILLY,J P Region 2, Atlanta, Office of the Director 79/03/10 ip ,
- 7906010346 Ack receipt of IE Insp Repts 50-369/79-21 & 50-370/79-10 on 790328-30 No proprietary info PARKER, W O Duke Power Co 79/05/14 1p
- --7906010349 Forwards IE Insp Repts 30-369/79-21 & 50-370/79-10 on 790328-30 No noncompliance noted HURPHY,C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch 79704/18 2pp.

- --7906010350 IE Insp Repts 50-369/79-21 % 50-370/79-10 on 790328-30 No noncompliance noted Major areas inspected steam generator narrow range level instrumentation installation, records & storage of safety related cable WALTERS,D K Region 2. Atlanta. Office of the Director BRYANT,J C Region 2. Atlanta, Cactor Construction & Engineering Support Branch 79/04/17 Spp
- 7906020120 Act receipt of 790412 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/79-14 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/05/15 lp
- --7906020121 Responds to NRC 790412 ltr re violation noted in IE Insp Rept 50-369/79-14 Corrective actions all safety-related terminal blocks in containment are being replaced w/sealed splices PARKER.W D Duke Power Co 79/04/12 2pp
- --7906020124 Forwards IE Insp Rept 50-369/79-14 on 790221-23 & notice of violation HURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/21 2pp
- --7906020126 Notice of violation from insp on 790221-23 \* Region 2, Atlanta, Office of the Director 79/03/20 ip
- --790A020128 IE Insp Rept 50-369/79-14 on 790221-23 Noncompliance noted improper cable termination
  WALTERS,D K Region 2. Atlanta, Office of the Director BRYANT,J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/20 4pp
- 7906140181 Responds to IE Bullotin 79-03 ASME SA-312 welded pipe method of liquid penetration meets requirements PARKER,W Q Duke Power Co 79/05/15 2pp
- 7906250163 Ack receipt of 790402 & 0508 ltrs informing NRC of steps taken to correct violations noted in IE Insp Rept 50-369/79-11
  MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/23 ip
- --7906250170 Responds to NRC 790411 ltr re violation noted in IE Insp Rept 80-369/79-11 Corrective actions shutdown request issued & damaged cable replaced PARKER.H O Duke Power Co 79/05/00 1p
- 7906260284 Informs NRC that revised response to IE Bulletin 79-03 will be submitted by 790601 PARKER, W O Duke Pawer Co 79/05/23 Ip
- U Congressional/Executive Correspondence
- 7906260541 Responds to 790423 ltr re 8 Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FES W/o encl GOSSICKL V Office of the Executive Director for Operations 79/05/15 2pp
- ---7906260544 Requests info re radiological impact of nuclear power plant cooling on drinking, in ref to SL Austin inquiry LENT, N F House of Rep 79/04/23 2pp
- DOCKET 50-370 WILLIAM B MCQUIRE NUCLEAR STATION, UNIT 2

  A. Application/construction stage documents & correspondence
- 7906140557 Concurs w/applicant evaluation of Reg Guide 1 114.Revision 1.re conformance to RGC matters Facility complies w/reg guide HOLMAN.J J Operator Licensing Granch 79/05/14, 1p
- 7904250322 Notification of 790408 meeting w/util in Bethesda.MD to review radiological effluent Tech Specs
  BIRKEL.R A Light Water Reactors Branch 2 79/05/25 3pp
- → Insurance & indemnity information
- 7906150280 Forwards executed Amend 2 to Indemnity Agreement 8-83 PARKER, W O Duke Power Co 79/06/07 2pp
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDER8, F D Duke Power Co 79/06/08 5pp

- O Inspection reports: IE Bulletins & correspondence
- 7906040360 Ack receipt of IE Insp Repts 50-369/79-18 & 50-370/79-09 on 790313-15 No proprietary info PARKER,W O Duke Power Co 79/04/23 1p
- ---7706040362 Forwards IE Insp Repts 50-367/77-18 & 50-370/77-09 on 790313-15. No noncompliance noted HURPHY,C E Region 2: Atlanta, Reactor Construction & Engineering Support Branch. 77/03/28 2pp
- --7904040366 IE Insp Repts 50-369/79-18 & 50-370/79-09 on 790313-13 No noncompliance nated Major areas inspected nondestructive testing, const deficiency repts, warehouse storage, outside storage areas, GA audits & IE bulletin responses HUNT, M D Region 2. Atlanta, Office of the Director HERDT, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 4pp
- 7906160024 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-369/79-15 & 50-370/79-07 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineerin Support Branch 79/04/25 ip
- --7906160033 Responds to NRC 790323 ltr re violations noted in IE lasp Repts 50-369/79-15 & 50-370/79-07 Corrective actions all const & const GA personnel instructed in manufacturer's manual use PARKER, N O Duka Power Co 79/04/18 2pp
- --7906160037 Forwards IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790228-0302 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 2pp
- --7906160041 Notice of violation from insp on 790228-0302
  \* Region 2. Atlanta, Office of the Director 79/03/23 ip
- --7906160044 IE Insp Repts 50-369/79-15 & 50-370/79-07 on 790228-0302 Noncompliance noted assembly of safety valves w/o documented instructions ANO,W P Region 2, Atlanta, Office of the Director BRYANT,J ( Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 4pp
- 790614011& Ack receipt of 790503 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-370/79-08 MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineeris Support Branch 79/05/10 ip
- --7905140122 Responds to NRC 790409 ltr re violations noted in IE Ins Rept 50-370/79-08 Corrective actions welding inspector & welder instructed to follow proper sequence for filling out documentation PARKER, W.O. Duke Power Co. 79/05/03 4pp
- --7906140142 Forwards 1E Insp Rept 50-370/79-08 on 75
  violation
  MURPHY, G E Region 2, Atlanta, Reactor Constr.
  Findingsring Support Branch 79/04/09

- --7906010350 IE insp Repts 50-369/79-21 & 50-370/79-10 on 790328-30 No noncompliance noted Major areas inspected steam generator narrow range level instrumentation installation, records & storage of safety related cable HALTERS, D K Region 2, Atlanta, Office of the Director BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/17 Spp
- 7906140181 Responds to IE Bulletin 79-03 ASKE SA-312 welded pipe method of Ilquid penetration meets requirements PARKER, H O Dute Power Co 79/09/15 2pp
- 7906260284 Informs NRC that revised response to IE Bulletin 79-03 will be submitted by 790601 PARKER, N Q Duke Power Co 79/05/23 1p
- 8 Reportable occurrences. LERs & related correspondence
- 7705010244 Forwards Significant Deficiency Rept 370/79-03 PARKER.H O Duke Power Co 79/05/23 ip
- --7906010231 Significant Deficiency Rept 370/79-03 on 790523 end plate finger found in bottom of motor's oil pot Caused by inadequate control during insp process of specific motor # Duke Power Co 79/05/23 3pp
- U Congressional/Executive Correspondence
- 7906260541 Responds to 790423 ltr re S Austin inquiry about radiological impact of nuclear power plant cooling on drinking water Forwards applicable FEG W/o encl GDSSIGK,L V Office of the Executive Director for Operations 79/05/15 2pp
- --7906260544 Requests info re radiological impact of nuclear power plant cooling on drinking in ref to SL Austin inquiry LENT,N F House of Rep 79704723 2pp
- DOCKET 50-373 LABALLE COUNTY STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7904070409 Notification of 790524-25 meeting w/util to discuss open items in draft SER BOURNIA.A Light Water Reactors Branch 3 79/05/07 2pp
- 7906020138 Confirms 790521 meeting w/util in Olen Ellyn, IL to discuss insp findings re const activities.

  KEPPLER, J O Region 3: Chicago, Office of the Director 79/05/08
- F Security, medical, emergency & fire protection plans
- 7906040035 Forwards fire protection status rept covering portions of review for which Power Sys Branch has review responsibility KNOX.J. Power Systems Branch 79/05/02 5pp
- J Insurance & indemnity information
- 7906040187 Forwards executed Amends 21,11.9 & 1 to Indemnity Agreements 8-10.8-47.8-59 & 8-84.respectively POCLER B Commonwealth Edison Co 79/03/29 Spp
- P Operating license stage documents & correspondence
  - irms 790521 meeting w/util in Olen Ellyn, (L to discuss re constructivities Region G, Chicago, Office of the Director 79/05/08

plans &

/17

- --7906050238 IE Insp Repts 50-373/79-12 & 50-374/79-09 on 790314-0315 No noncompliance noted Major areas inspected work & procedures re mod to reactor recirculating sys noizle safe-ends & thermal sleeves & suppression pool mod work activities NEISLER, J H. PHILLIPS.H 5. KNOP, R C Region 3. Chicago, Office of the Director 79/05/06 Bpp
- 7906140586 Forwards IE Insp Rept 50-373/79-09 on 790221-23 No noncompliance noted , HEIEHMAN,R F Region J. Chicago, Reactor Operations Nuclear Support Branch 79/04/13 2pp
- --7906140596 IE Insp Rept 50-373/79-09 on 790221-23 No noncompliance noted Major areas inspected operating staff training & station operating procedures MALKER,R D. NRIGHT,O C. SPESSARD,R L. Region J. Chicago, Reactor Operations Nuclear Support Branch 79/04/12 5pp
- 79062605B1 Forwards IE Insp Rept 50-373/79-16 on 790417-18 No noncompliance hoted FIORELLI.O Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/04/30 Zpp
- --7906260383 IE Insp Rept 50-373/79-16 on 790417-18 No noncompliance noted Major area inspected mod of recirculation sys LEE,E W. DAIELBON.D H Region 3. Chicago: Office of the Director 79/04/27 4pp
- 7906070266 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/79-11 & 50-374/79-08 FIORELLI.G Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/05/01 ip
- --7906070273 Responds to NRC 790315 ltr re violations noted in IE Insp Repts 50-373/79-11 & 50-374/79-08 Corrective actions missellamenus debris cleaned out of cable pan & okonite nuclear grade splice tapes applied over cable jackets REED.C Commonwealth Edison Co 79/04/18 9pp
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07
- 7906180784 Responds to IE Bulletin 79-03 re longitudinal wold defects in ABME SA-312 type 304 satinless steel pipe spools Spools not in use or planned for use REED.C Commonwealth Edison Co 79/05/10 2pp
- 7906190078 Forwards IE info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER. J D Region 3, Chicago, Office of the Director 79/05/11
- 7904:30082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER. J G Region 3. Chicago, Office of the Director 79/05/22
- 790626023B Responds to IE Bulletin 79-04 Review indicates swing check valves mfg by Velan Engineering Corp are not installed nor will be installed in any Seisnic Category I piping sys REED.C Commonwealth Edison Co 79/03/24 ip
- 7906200080 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Dyster Creek Reactor" KEPPLER.J. O Region 3. Chicago, Office of the Director 79/05/29
- 8 Reportable occurrences, LERs & related correspondence
- 7906230074 Ack receipt of 790419 final rept re post-tensioning sys Requests 790309 Inryco rept, "Investigation of Buttonhead Defects."
  FIORELLI, O Region 3. Chicago, Reactor Construction & Engineering Support Branch 79703/23 ip
- 7906140385 Forwards deficiency rept re nonconformance of ventilation steel stack DELGEOROG.L O Commonwealth Edison Co 79/06/06 ip
- --7906140393 Deficiency rept nonconformance of ventilation steel stack Nondestructive examination revealed crack in stack Parmanent repair under study Final rept will be submitted by 791001

  \* Commonwealth Edison Co 79/06/06. 2pp.

7906250284 Forwards Innyco 790309 rept. "Investigation of Buttonhead Defects." in response to 790523 request W/o ancl DELOEORGE.L O Commonwealth Edison Co 79/06/18 ip

DOCKET 50-374 LASALLE COUNTY STATION, UNIT 2

A Application/construction stage documents & correspondence

7906070409 Notification of 790524-25 meeting w/util to discuss open items in draft SER BOURNIAA Light Water Reactors Branch 3 79/05/07 2pp

790602013B Confirms 790321 meeting w/util in Olan Ellyn, IL to discussinsp findings re const activities
KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/08

F Security, medical, emergency & fire protection plans

7906040035 Forwards fire protection status rept covering portions of review for which Power Systems Branch has review responsibility KNOX.V Power Systems Branch 77/05/02 5pp

J Insurance & indemnity information

7906040187 Forwards executed Amends 21.11.9 % 1 to Indemnity Agreements B-10.8-47.8-59 & R-84, respectively POOLE.R D Commonwealth Edison Co 79/05/29 App

P Operating license stage documents & correspondence

7904200239 Requests two controlled copies of site emergency plans be implementing procedures, site maps showing location begind station number of onsite & offsite environ monitoring stations besite maps used for dose determinations KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/17

G Inspection reports, IE Bulletins & correspondence

7906050234 Forwards IE Insp Repts 80-373/79-12 & 50-374/79-09 on 790314-0315 No noncompliance noted FIORELLI,0. Region 3. Chicago. Reactor Construction & Engineering Support Branch 79704/06 2pp

---7906050238 IE Insp Repts 50-373/79-12 \$ 50-374/79-09 on 790314-0315 No noncompliance noted Major areas inspected work \$ procedures re mod to reactor recirculating sqs notitle safe-ends \$ thermal steeves & suppression pool mod work activities NEISLER, J H , PHILLIPS, H S , KNOP, R C Region 3, Chicago, Office of the Director 77/03/06 Spp

7906070266 Ack receipt of 790418 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-373/79-11 5 50-374/79-08 FIDRELLI.0 Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/05/01 ip

---7906070273 Responds to NRC 790315 ltr re violations noted in IE Insp Repts 80-373/79-11 & 50-374/79-08 Corrective actions miscellaneous debris cleaned out of cable pan & dkonite nuclear grade splice tapes applied over cable jackets REED.C Communusaith Edison Co 79/04/18 9pp.

7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/07 Ip

7906180784 Responds to 1E Bulletin 79-03 re longitudinal weld defects in ARME 8A-312 type 304 satinless steel pipe spools Spools not in use or planned for use REED.C. Commonwealth Edison Co. 79/05/10. 2pp

7706190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies."

KEPPLER J G. Region G. Chicago, Office of the Director. 79/05/11

7904130082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys." Licensee action required KEPPLER.J.O Region G. Chicago, Office of the Director 79/05/22 7906260238 Responds to IE Bulletin 79-04 Review indicates swing check valves mfg by Velan Engineering Corp are not installed nor will be installed in any Seismic Category I piping sys REED.C Commonwealth Edison Co 79/05/24 ip

7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/29

8 Reportable occurrences. LERs & related correspondence

7906230074 Ack receipt of 790419 final rept re post-tensioning sys Requests 790309 Inryco rept. "Investigation of Buttonhead Defects "FIORELLI, G Region 3, Chicago, Reactor Construction & Engineerin Support Branch 79/09/23 ip

7906140385 Forwards deficiency rept re nonconformance of ventilation steel stack DELGEORGE:L O Commonwealth Edison Co 79/06/06 1p

--7906140393 Deficiency rept nonconformance of ventilation steel stack Nondestructive examination revealed crack in stack Permanent repair under study Final rept will be submitted by 791001

\* Commonwealth Edison Co 79/06/06 2pp

7908250284 Forwards Inryco 790309 rept, "Investigation of Buttonhead Defects," in response to 790523 request W/o enci DELGEORGE, L O Commonwealth Edison Co 79/06/18 1p

DOCKET 50-375 NUCLEAR EXAMINATION REACTOR

O Inspection reports, IE Bullstans & correspondence

7906180436 Forwards IE Info Notico 79-12, "Attempted Damage to New Fue Assemblies " No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/10 10

7906080224 Forwards IE Circular 79-08. "Attempted Extertion - Low Enriched U" ENGELKEN, R H Region S. San Francisco. Office of the Director 79/05/18 1p

DOCKET 50-382 WATERFORD GENERATING STATION, UNIT 3

A Application/construction stage documents & correspondence

7904180077 Concurs w/recommended schedule change of CL safety review Oral approval already received from Licensing Project Hanager HANAUER, S H Assistant Director for Plant S:

7906050145 Forwards attendance list -- 700000 application COTA P C

- 7906160066 Notice of appearance on behalf of util Certificate of Svc encl STEVENSON, W.M. Monroe & Lemann 79/04/17 3pp
- 7906070175 Response to LA Consumer's League contentions submitted 790406 Contentions 2.3.4 & 6 should be accepted & Contention 1 rejected Ruling re Contentions 5 & 7 should be deferred Certificate of Svc encl MCGURREN, N J Branch 1 79/04/25 10pp
- 7906260394 Joint statement to ASLB by petitioners Gyster Shell Alliance. Save Qur Metlands & NRC indicating agreement on contentions in proceeding Parties unable to reach agreement on Contentions B-14 & 22 TROMBRIDGE, GF Shaw, Pittman, Potts, & Trowbridge JONES, L Collespie & Jones MCGURREN, H J Branch 1 79/05/31 20pp
- ( Utility Final Safety Analysis Report (FSAR) & amends
- '906140262 Forwards Amend 4 to FSAR ASWELL,D L Louisiana Power & Light Co 79/06/07 1p
- ~7906140265 Amend 4 to FSAR
  # Louisiana Power & Light Co 79/06/07 150pp
- Inspection reports: IE Bulletins & carrespondence
- 06220223 Forwards IE Insp Rept 50-382/79-04 on 790320-23 & notice of violation SEIDLE, H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/04/11 2pp
- 7906220228 Notice of violation from insp on 790320-23
  \* Region 4. Dallas. Office of the Director 79/04/11 2pp
- 7906220241 IE Insp Rept 50-382/79-04 on 790320-23 Noncompliance noted failure to follow contract procedures re care 1 maint of safety-related components 2 failure to perform required housekeeping survaillance per procedures STEMART,R C . CROSSMAN,W A Region 4. Dallas, Office of the Director HALL,R E Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/11 App
- 'Oblicoo4 Forwards IE Bulletin 79-058, "Nuclear Incident at TMI-Suppl" No written response required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/21 to
- 705120070 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 79/05/07 ip
- 906250022 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/11
- 906120143 Ack receipt of 790427 itr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-382/79-03
  SEIDLE,W C Region 4. Ballas, Reactor Construction & Engineering Bupport Branch 79/05/14 ig
- -7906120145 Responds to NRC 770328 ltr re violations noted in IE Insp Rept 50-382/79-03 Corrective actions nonconformance rept disposition & procedure revision will be completed by 770530 ASWELL,D L Louisiana Power & Light Co 77/04/27 3pp
- 7906130071 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required SEYRIT,K V, Region 4. Dallas. Office of the Director 79/05/22
- S Reportable occurrences, LERs & related correspondence
- 7906180161 Forwards PNO-79-67AM
  SEIDLE:W C Region 4. Dallas. Reactor Construction & Engineering
  Support Branch 79/05/08 ip
- 7906180182 Forwards PNO-79-67AN
  SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/05/16 ig
- 7906180247 Forwards PNO-79-67AU
  SEIDLE, W C Region 4. Dallas, Reactor Construction & Engineering
  Support Branch, 79/05/22 1p

- 7906290528 Forwards Part 21 rept from Zurn Industries, Inc Review of rept finds only one facility affected & two vendors involved ALDERSON, C E. Region 2. Atlanta. Office of the Director 79/05/22 tp
- --7906290535 Confirms 790518 telcon re cooling towers supplied to util by Zurn Industries. Inc No further ation by Zurn Industries is required Obligation now fulfilled ALDERSON, C E Region 2, Atlanta, Office of the Director 79/05/22 ip
- --7906290545 Notifies of concern re capability of essential cooling water sys to function in manner adequately providing for all safety-related cooling requirements Supporting documentation encl
  SENGSTAKEN, D. J. Zurn Industries, Inc. 79/05/03 35pp
- 7906180326 Forwards PND-79-67AP
  SEIDLE.W C Region 4. Dallas, Reactor Construction & Engineering
  Support Branch 79/05/23 1p
- DOCKET 50-387 SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1

  A Application/construction stage documents & correspondence
- 7906200323 Summary of 790419 meeting w/util in Bethesda, MD re-security plans Forwards request for add1 info for second round question re-draft security plan evaluation rept Request withheld (ref 10GFR2 790) CLARK, R Reactor Safeguards Licensing Branch 79/05/09 3pp
- 7906130504 Approves request for withholding Kraftwerk Union Aktiengeseilschaft tests & rept from public disclosure (ref 10CFR2 790) PARR,O D Light Water Reactors Branch 3 79/05/11 3pp
- 7906150105 Forward: second round questions re containment design & testing Revision 1 to design assessment rept is currently under review PARR.O D Light Water Reactors Branch 3 79/05/15 11pp
- 7906230162 Forwards request for addi info re initial tests & operation PARR.O D Light Water Reactors Branch 3 79/05/18 16pp
- 7906250315 Bummary of 790323 meeting w/util, Kraftwork Union & BRI Intl to discuss condensation escillation test to be conducted in Germany MINER® Light Water Reactors Branch 3 79/05/21 14pp
- 7906120394 Submits schedule for responding to NRC 790515 request for add1 info for Question O21 CURTISN W Pennsylvania Power & Light Co 79/06/07 1p
- 7906120400 Submits schedule for responding to 790518 request for addl info for Question 423 CURTIS:N W Pennsylvania Power & Light Co 79/04/08 1p
- 7906180438 Forwards Affidavit of Svc for Amend 11 to facility UL application CURTIS:N W Pennsylvania Power & Light Co 79/06/12 2pp.
- 7906260380 Submits licensing schedule for facility Press releases enci CURTIS,N W Pennsylvania Power & Light Co 79/06/20 Bpp
- C Utility Environmental Report (ER), amends & correspondence
- 7906040208 Forwards Amend 12 to OL application, containing Revision 2 to environ rept
  CURTION W Pennsylvania Power & Light Co 79/06/01 4pp
- --7906040210 Amend 12 to OL application, dtd 780720, containing Revision 2 to environ rept

  \* Pennsylvania Power & Light Co 79/06/01 350pp
- F Security, medical, emergency & fire protection plans
- 7905290735 Requests addl (info re physical security plan for review of OL application Security info withheld (ref 10CFR2 770)
  PARR: 0 D Light Water Reactors Branch 3 79/05/25 2pp
- O Adjudicatory correspondence
- 7906140652 Requests to make limited appearance statement at licensing prohearing conference
  WELLIYER, O W Affiliation Unknown 79/04/18 ip

- 7906030037 Requests limited appearance at licensing hearings FORD.D Affiliation Unknown 79/03/06 1p
- --7906050041 Requests limited appearance statement BULFORD.C Affiliation Unknown 79/05/11 ip
- --7906050210 Requests limited appearance at preliminary hearing conference HUNTINGTON,M Affiliation Unknown 79/05/11 lp
- 7906190013 Forwards motion to restrain util from obtaining govt permits involving safety or environ matters prior to evidentiary hearings on OL Motion petitions Governor of PA to declare moratorium on issuance of permits

  LEMANOWICA, I Citizens Against Nuclear Dangers 79/05/12 1p
- ---7906190150 Requests motion to restrain util from obtaining govt permits involving safety or environ matters prior to evidentiary hearings on OL Petitions Covernor of PA to declare moratorium on issuance of permits

  LEMANOMICA, J. Citizens Against Nuclear Dangers 79/03/12 1p
- 7906190560 First round discovery requests & interrogatories submitted to Citizens Against Nuclear Dangers per ASLB 790306 special prehearing conference order, re Contentions 2, 4, 6, 9-11, 16 & 17 CUTCHIN, J M Branch 3 79/05/21 1100
- --7906190565 First round discovery requests & interrogatories, submitted to C Marsh per ASLB 790306 special prehearing conference order, re Contentions 4,6 % 9-14 CUTCHIN, J M Branch 3 79/05/21 11pp
- --7706170572 First round discovery requests & interrogatories submitted to Susquehanna Environ Associates per ASLB 770306 special prehearing order, re Contentions 1,3,4,6,7-11 & 15 CUTCHIN,J H Branch 3 77/05/21 13pp
- --7906190576 First round discovery requests & interrogatories re Contentions 1-7 & 18, submitted to Environ Caalition on Nuclear Power per ASLB 790306 order W/Certificate of Svc CUTCHIN, J H Branch 3 79/05/21 18pp
- 7906270185 Denies Citizens Against Nuclear Danger 790512 motion to restrain applicant from obtaining govt permits, including parmit from State of PA Relief sought is against NRC policy. NRC has no authority over Governor of PA BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/06/07
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906040193 Forwards Amend 11 to OL.consisting of Revision 9 to FSAR CURTIS,N W Pennsylvania Power & Light Co 79/06/01 ip
- --7906040196 Amend 11 to GL.consisting of Revision 9 to FBAR CURTIS.N W Pennsylvania Power & Light Co 79/06/01 150pp
- G Inspection reports, IE Bulletine & correspondence
- 7906140201 Forwards IE Insp Rept 50-387/79-08 on 790227-0302 No noncompliance noted BRUNNER,E J Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/30 2pp
- --7906140207 IE Insp Rept 50-387/79-08 on 790227-0302 No noncompliance noted Major areas inspected implementation of preoperational testing administrative controls & followup on corrective actions re IE bulletins & circulars RAYMOND, W J Rogion 1, Philadelphia, Office of the Director, MCCABE, E C Region 1, Philadelphia, Reactor Operations Nuclear Support Branch 79/03/29 16pp
- 7706140621 Forwards IE Insp Repts 50~387/77~05 & 50/388/77~04 on 790205~0302 No noncompliance noted CARLEON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/09 2pp.
- --7906140628 IE Insp Repts 50-387/79-05 & 50-388/79-04 on 790205-0302. No noncompliance noted Major areas inspected installation & walding of reactor coolant pressure boundary in Unit 1 & installation of safety-related pipe support sys in Unit 2 GALLO,R M Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/04/05 7pp
- 7706180407 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts," No written response necessary ORIER, B.H. Region 1, Philadelphia, Office of the Director 77/04/16 1p

- 7906260319 Forwards IE Insp Rept 30-387/79-09 on 790227-28 & 0301-02 No noncompliance noted CARLEON.R T Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 79/04/20 2pp
- --7906260323 IE Insp Rept 50-387/79-09 on 790227-28 & 0301-02 No noncompliance noted Major areas inspected activities associated w/mods to feedwater nozzles & storage of safety-related components TRIPP-L E , WALTON.0 A , JERNIGAN.E P Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/18 App
- 7906i10033 Forwards IE Bulletin 79-05B, "Nuclear Incident at IMI-Suppl " No written response required GRIER, B H Region I, Philadelphia, Office of the Director 79/04/23 | 1p
- 7906130173 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/02 ip
- 7906070179 Act receipt of 790430 ltr informing NRC of steps taken to correct violation noted in IE Insp Repts 50-387/79-04 & 50-3887/79-03 CARL-BON, R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 ip
- --7706070184 Responds to NRC 770302 ltr re violation noted in IE Insp Repts 50-387/79-04 & 50-388/79-03 Corrective actions nonconforming weld joint reworked SABOL:A R Pennsylvania Power & Light Co 77/04/30 3pp
- --7906070197 Forwards IE Insp Repts 50-387/79-04 & 50-388/79-03 on 790212-15 & notice of violation CARLSON, R T Region 1. Philadelphia. Office of the Director 79/03/02 2pp
- --7906070206 Notice of violation from insp on 790212-15 \* Region 1. Philadelphia. Office of the Director 79/03/02 ip
- --7906070213 IE Insp Repts 50-387/79-04 & 50-388/79-03 on 790212-15
  Noncompliance noted failure to meet ASME III code
  requirements for pipe weld joint alignment
  DURR, J P Region 1, Philadelphia, Office of the Director
  TRIPP, L Region 1, Philadelphia, Reactor Construction &
  Engineering Support Branch 79/03/01 App
- 7906120192 Forwards IE Info Notice 79-ii. "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 7906260143 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER,B H Region 1, Philadelphia, Office of the Director 79/09/11 ip
- S Reportable occurrences. LERs & related correspondence
- 7906130480 Ack receipt of 790419 itr evaluating coax cable deficiency CARLBON,R T Region 1, Philadelphia, Reactor Construction 5 Engineering Support Branch 79/05/03 ip
- 7906210034 Ack receipt of 790406 itr forwarding final rept reundersized welds on safety-related pipe hangers CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79708/14 ip
- ---7906210036 Final deficiency rept undersized welds on safety-related pipe hangers, discussed in 790202 & 790406 ltrs Shop fabrication of hangers spec lacked specific criteria for acceptance/rejection of welds

  CURTIS, N.W. Pennsylvania Power & Light Go. 79/04/06 45pp
- 7906040265 Final rept of abnormal wear of roller pins in crosshead assemblies of emergency standby diesel generators Roller pins supplied by Cooper Energy Svc CURTIEN W. Pennsylvania Power & Light Co 79/05/29. 2pp
- DOCKET 50-388 SUSQUEHANNA BTEAM ELECTRIC STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 7905200323 Summary of 790419 meeting w/util in Bathesda, MD re security plans, Forwards request for addl info for second round question re draft security plan evaluation rept Request withheld (ref 10CFR2 790) CLARK, R. A Reactor Bafeguards Licensing Branch 79/05/08 3pp

- 7906120504 Approves request for withholding Kraftwers Union Attiengesellschaft tests & rept from public disclosure (ref 10CFR2 790) PARR.O D Light Water Reactors Branch 3 79/05/11 3pp
- 7905130105 Forwards second round questions re containment design & testing Revision I to design assessment rept is currently under review PATRA, O D Light Hater Reactors Branch 3 79/05/15 lipp
- 7906230162 Forwards request for add1 info re initial tests & operation PARR.O D Light Water Reactors Branch 3 79/05/18 16pp
- 7906250315 Summary of 790323 meeting w/util.Kraftwork Union & SRI Inti to discuss condensation oscillation test to be conducted in Germany MINER.S Light Water Reactors Branch 3 79/05/21 14pp
- 7906120394 Submits schedule for responding to NRC 790515 request for addl info for Question 021 CURTIS.N H Pennsylvania Power & Light Co 79/06/07 lp
- 7906120400 Submits schedule for responding to 790518 request for addl info for Question 420 CURTIS.N W Pennsylvania Power & Light Co 79/06/08 ip
- 7906180438 Forwards Affidavit of Svc for Amend 11 to facility OL application CURTIS.N W Pennsylvania Power & Light Ca 77/06/12 2pp
- 7906260380 Submits licensing schedule for facility Press relaases ancl CURTIS.N W Pennsylvania Power & Light Co 79/06/20 Bpp
- C Utility Environmental Report (ER), amends & correspondence
- 7906040208 Forwards Amend 12 to GL application.containing Revision 2 to environ rept CURTIS.N W Pennsylvania Power & Light Co 79/06/01 4pp
- F Security, medical, emergency & fire protection plans
- 7906290755 Requests addl info re physical security plan for review of OL application Security info withheld (ref 10CFR2 790) PARR,O D Light Water Reactors Branch 3 79/05/25 2pp
- O Adjudicatory correspondence

į.

- 7906140652 Requests to make limited appearance statement at licensing prehearing conference with the statement of the statement at licensing problem of the statement of the sta
- 7906030037 Requests limited appearance at licensing hearings FORD,D Affiliation Unknown 79/05/06 lp
- --7906050041 Requests limited appearance statement BULFORD:C Affiliation Unknown 79/05/11 Ip
- --7906050210 Requests limited appearance at preliminary hearing conference
  HUNTINGTON-M Affiliation Unknown 79/05/11 1p
- 7906190013 Forwards motion to restrain util from obtaining govt permits involving safety or environ matters prior to evidentiary hearings on DL Motion petitions Governor of PA to declare moratorium on issuance of permits
- ---7905190150 Requests motion to restrain util from obtaining govt permits ving safety or environ matters prior to evidentiary ngs on DL Petitions Governor of PA to declare prium on issuance of permits WIGA-I Citizens Against Nuclear Dansers 70/02/12 ip
  - bmitted
- ---7906190365 First round discovery requests & interrogatories, submitted to C Harsh per ABLB 790306 special prehearing conference order, re Contentions 4,6 & 9-14 CUTCHIN, J H Branch 3 79/05/21 11pp

- --7906190572 First round discovery requests & interrogatories submitted to Susquehanna Environ Associates per ASLB 790306 special prehearing order:re Contentions 1.3.4.6,9-11 & 15 CUTCHIN.J M Branch 3 79/05/21 13pp
- --7906190576 First round discovery requests & interrogatories re Contentions i-9 & 18, submitted to Environ Coalition on Nuclear Power per ASLB 790306 order W/Certificate of Svc CUTCHIN.J M Branch 3 79/05/21 18pp
- 7906270185 Denies Citizens Against Nuclear Danger 790512 motion to restrain applicant from obtaining govt permits, including permit from State of PA Relief sought is against NRC policy; NRC has no authority over Governor of PA BECHHOEFER, C Atomic Safety and Licensing Board Panel 79/06/07
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906040193 Forwards Amend 11 to OL.consisting of Revision 9 to FSAR CURTIS.N W Pennsylvania Power & Light Co 79/06/01 1p
- --7906040196 Amend 11 to OL.consisting of Revision 9 to FSAR CURTIS.N W Pennsylvania Power & Light Co 79/06/01 150pp
- O Inspection reports. IE Bulletins & correspondence
- 7905140621 Forwards IE Insp Repts 50-387/79-05 % 30/388/79-04 on 790205-0302 No noncompliance noted CARLSUN R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/09 2pp
- --7906140628 IE Insp Repts 50-387/79-05 & 50-388/79-04 on 790205-0302 No noncompliance noted Major areas inspected installation & welding of reactor coolant pressure boundary in Unit 1 & installation of safety-related pipe support sys in Unit 2 GALLOR M Region 1. Philadelphia. Reactor Construction & Engineering Support Branch 79/04/05 7pp
- 7906180407 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary GRIER.8 H Region 1. Philadelphia. Office of the Director 79/04/16 1p
- 7906110033 Forwards IE Bulletin 79-05B, "Nuclear Incident at THI-Suppl" No written response required GRIER, BH Region 1. Philadelphia. Office of the Director 79/04/23 ip
- 7906130173 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/02 ip
- 7906070179 Ack receipt of 790430 ltr informing NRC of steps taken to correct violation noted in IE lnsp Repts 50-387/79-04 & 50-388/79-03 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 ip
- --7906070184 Responds to NRC 790302 ltr re violation noted in IE Insp Repts 50-387/79-04 & 50-388/79-03 Corrective actions nonconforming weld joint reworked SABOL, A.R. Pennsylvania Power & Light Co. 79/04/30 Spp
- --7906070197 Forwards IE Insp Repts 50-387/79-04 & 50-388/79-03 on 790212-15 & notice of violation CARLSON,R T Region 1, Philadelphia, Office of the Director, 79/03/02 2pp
- --7906070206 Notice of violation from insp on 790212-15
  4 Region I. Philadelphia. Office of the Director 79/03/02
- --7906070213 IE Insp Repts 50-3B7/79-04 & 50-3BB/79-03 on 790212-15
  Noncompliance noted failure to meet ASME III cade
  requirements for pips weld joint alignment
  DURR, J P Region I, Philadelphia, Office of the Director
  TRIPP, L Region I, Philadelphia, Reactor Construction &
  Engineering Support Branch 79/03/01 6pp
- 7906120192 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER, B H Region I, Philadelphia, Office of the Director 79/05/07 2pp
- 7906260145 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  ORIER, B. H. Region 1. Philadelphia, Office of the Director 79/05/11 1p

### S Reportable occurrences, LERs & related correspondence

- 7906/30480 Ack receipt of 790419 ltr evaluating coax cable deficiency CARLSON.R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/03 ip
- 7906210034 Ack receipt of 790406 ltr forwarding final rept re undersized welds on safety-related pipe hangers CARLSON.R T Region i, Philadelphia, Reactor Construction & Engineering Support Branch 79/03/14 ip
- --7906210036 Final deficiency rept undersized welds on safety-related pipe hangers, discussed in 790202 & 790406 ltrs Shop fabrication of hangers spec lacked specific criteria for acceptance/rejection of welds CURTIS.N W Pennsylvania Power & Light Co 79/04/06 43pp
- 7906040265 Final rept of abnormal wear of roller pins in crosshead assemblies of emergency standby diesel generators Roller pins supplied by Cooper Energy Svc CURTIS.N W Pennsylvania Power & Light Co 79/05/29 2pp

### DOCKET 50-389 ST LUCIE PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 7906180102 Notification of 790516 meeting w/util in Bethesda. MD to discuss failure of offsite power w/simultaneous onsite power failure & other ALAB-537 matters Meeting originally scheduled for 790508 BIRKEL, R A Light Water Reactors Branch 2 79/05/02 2pp
- 7906:180131 Notification of 790508 meeting w/util in Bethesda. MD to discuss failure of offsite power w/simultaneous onsite gower failure 5 other ALAB-537 matters
  BIRKEL.R A Light Water Reactors Branch 2 79/05/02 2pp

### G Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO.J F Hearings Division 79/04/02 2pp
- ---7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 5-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 790&050000 Homo & order terminating jurisdiction over ALAB-435 steam generator tube integrity Intervenors' motion for new contention is dismissed as moot stay motion is denied & parties are directed to file prepared testimony DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/04/05 23pp
- 7904040026 Denies util's motion to cancel hearings & intervenors' motion for discovery, re adequacy of emergency power sys BUFLO, M E Atomic Safety and Licensing Appeal Panel 79/05/03 6pp
- 7906020033 Motion for extension of time in which to anewer questions re applicant's electrical grid & emergency power sys Applicant does not object to request Motion granted by ASLAB on 790515 Certificate of Svc encl PATON.W D Branch 4 79/05/11 App
- 7906140184 Orders extension of time until 790604 to review partion of ALAB-537 re electrial grid stability & emergency power sys NRC has decided not to review other items decided in ALAB-537.
  CHILK, BJ Office of the Becretary of the Commission 79/05/17 in
- 7906210095 NRC motion for summary disposition re radon issue was in error: ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc ancl DUFLO: M E. Atomic Befety and Licensing Appeal Panel 79/05/25 Gpp

### J. Insurance & indemnity information

7906190419 Forwards Endorsements 25 & 26 to MAELU Policy MF-89 DUCK.J.R. Marsh & McLenon: M & M Nuclear Consultants: Inc. Div 79/06/12 3pp.

### @ Inspection reports. IE Bulletins & correspondence

- 7906210064 Forwards IE Insp Rept 50-389/79-06 on 790327-29 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineerin Support Branch 79/04/11 2pp
- --7906210068 IE Insp Rept 50-389/79-06 on 790327-29 No noncempliance noted Major areas inspected safety-related piping record, radiograph review & reactor bldg refusiing canal liner welding steel containment liner weld repairs ECONDMOS:N Region 2. Atlanta. Office of the Director CONLONIT E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/10 6pp
- 7906200362 Forwards IE Insp Rept 30-389/79-05 on 790327-29 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/12 2pp
- --7906200364 IE Insp Rept 50-389/79-03 on 790327-2? No noncompliance noted Major areas inspected containment steel structures; safety-related components & safety-related structures outside containment
  MODENOS, L. Region 2, Atlanta, Office of the Director BRYANT, J C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 4pp
- 7906250452 Forwards IE Info Notico 79-12, "Attempted Damage to New Fue Assemblies " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 ip
- 7906260288 Responds to IE Bulletin 79-04 re Votan swing check valves No such valves being supplied for unit UHRIG.R E Florida Power & Light Co 79/05/22 ip

## U Congressional/Executive Correspondence

7906260586 Provides add1 info re D Browning info request concerning FL nuclear power situation Discusses wastes produced by FL plants, effluents released, & consequences of possible accident ODSBICKLL V Office of the Executive Director for Operations 79/05/17 3pp

DOCKET 50-390 WATTS BAR NUCLEAR PLANT, UNIT 1

A Application/construction stage documents & correspondence

- 7904160279 Forwards second round questions for transmittal to applicant Outstanding items qualification of safety-related equipment, identification of safety sys & equipment & identification of NRC requirements re safety sys SATERFIELD:R Electric, Instrumentation & Control Systems Branch 79/03/21 13pp
- 7906060007 Notification of 790517-18 meeting w/TVA in Knoxville,TN to discuss buckling design criteria,using encl info requests as basis for discussion STAHLE,GR Light Water Reactors Branch 4 79/05/08. 5pp
- 7906280016 Submits requests for add1 (nfo on mat1 integrity & methnical engineering Requests responses by 790629 VARGA.8 A Light Water Reactors Branch 4 79705/16 19pp

7906040204 Request safet: compl addr: OILL!

- G. Inspection reports. IE Bulletins & correspondence
- 7906150457 Forwards IE Insp Repts 50-390/79-11 & 50-391/79-08 on 790305-08 No noncompliance noted SUTHERLAND.J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 2pp
- --7906150463 IE Insp Repts 50-390/79-11 & 50-391/79-07 on 790305-08 No noncompliance noted Major areas inspected radiological environ monitoring program MACARTHURIT C , PEERVIN W , HUFHAN, J W Region 2, Atlanta, Office of the Director 79/03/29 4pp
- 7906030063 Forwards IE Insp Repts 50-390/79-14 & 50-391/79-11 on 790320-0323 No noncompliance noted MURPH/C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 2pp
- --7906050075 IE Insp Repts 50-390/79-14 & 30-391/79-11 on 790320-0321 No noncompliance noted Major areas inspected reactor vessel internals quality records & safety-related pipe support, restraint sys & Unit 2 containment genetrations records VALLISH.6 J Region 2. Atlanta. Office of the Director BRYANT.J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/03 Spp
- 7906220084 Forwards IE Insp Repts 50-390/79-15 & 50-391/79-12 on 790320-23 No noncompliance noted HURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- ~-7906220093 IE Insp Repts 50-390/79-15 & 50-391/79-12 on 790320-23 No noncompliance noted Major areas inspected protection of installed instrumentation components & panels; fire suppression equipment \$\frac{1}{2}\$ installation & records re cables RUFF.A B Region 2. Atlanta. Office of the Director BYANTIJ C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/06 4pp
- 7906210286 Forwards IE Insp Repts 50-390/79-16 & 50-391/79-13 on 790327-30 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/12 2pp
- --7906210291 IE Insp Repts 50-390/79-16 & 50-391/79-13 on 790327-30 No noncompliance noted Major areas inspected license action on previous insp findings, preservice insp-review of procedures & preservice insp-observation of work & work activities GTRARD, E H. Region 2. Atlanta, Office of the Director COLON, Y E. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/12 4pp
- 7906210041 Ack receipt of 790411 ltr informing NRC of steps taken to currect violations noted in IE Insp Repts 50-390/79-09 & 50-391/79-07 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/09 2pp
- --7906210046 Responds to NRC 790320 itr re violations noted in IE Insp. Rept 50-390/79-09 & 50-391/79-07 Corrective actions insp. of upilds show only 1 75 inches exceed specs No further action will be taken.
  GILLELAND.JE Tennessee Valley Authority 79/04/11 3pp
- --7906210051 Forwards IE Insp Repts 50-390/79-09 & 50-391/79-07 on 790220-23 & notice of violation MURPHY.C E Region 2. Atlanta, Office of the Director 79/03/20 3pp
- --7906210054 Notice of violation from insp on 790220-23
  s Region 2. Atlanta, Office of the Director 79/03/19 ip
- --7906210057 IE Insp Repts 50-390/79-09 & 50-391/79-07 on 790220-23
  Noncompliance hoted weld reinforcement on chemical & vol
  rol sys tants exceeded spacs
  RD,E H. COMLON,T E Region 2. Atlanta, Office of the
  79/03/19 6pp

- --7906210108 Notice of violation from insp on 790206-09

   Region 2, Atlanta, Reactor Construction & Engineering Support
  Branch 79/03/13 ip
- ---7906210110 IE Insp Rept 50-390/79-07 on 790206-09 Noncompliance noted failure to follow procedure applicable to cable routing in raceway RUFF,A B . BRYANT, J C Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/13 4pp
- 7906200174 Ack receipt of 790427 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-12 & 50-391/79-07 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 2pp
- --7906200186 Responds to NRC 790404 lbr re violation noted in IF Imag Repts 50-390/79-12 % 50-391/79-09 Corrective actions record requiring approval signature signed Painted over corrections determined to be typograpical in nature GILLELAND, J.E. Tennessee Valley Authority 79/04/27 2pp
- --7906200193 Forwards IE Insp Repts 50-390/79-12 & 50-391//9-09 on 790312-15 & notice of violation MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/04 2pp
- --7906200196 Notice of violation from insp on 790312-15 \* Region 2. Atlanta. Office of the Director 79/04/04 lp
- --7906200204 IE Insp Repts 50-390/79-12 & 50-391//9-09 on 790312-15
  Noncompliance noted insufficient records used to furnish
  evidence of activities affecting quality Record corrections
  painted over instead of line drawn through & corrected
  VAN DOORN,P K Region 2, Atlanta, Office of the Director
  CONLON.T E Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 79/04/04 5pp
- 7906210098 Responds to IE Bulistin /9-03 Investigation shows no piping in use or planned for use in safety-related sys Effort in progress to locate any ABME 8A-3121 Type 304 piping supplied by Youngstown Welding & Engineering Go
- 79060802B4 Submits revised response to QA records deficiently noted in 790404 insp Repts 50-390/79-12 & 50-391/79-09 GILLELAND, J E Tennessee Valley Authority 79/06/01 2pp
- 7906280094 First interim deficiency rept incorrect Velan valva weighte used in seismic piping analysis Final response to IC Bulletin 79-04 will be submitted before fuel load in Unit 1
  OILLELAND, J E Tennessee Valley Authority 79/06/22 ip
- 7906290392 Submits response to deviation & infractions cited in IC Insp Repts 50-390/79-20 & 50-391/79-16 GILLELAND. J E Tennessee Valley Authority 79/06/23 7pp
- S Reportable occurrences, LERs & related correspondence
- 7706140381 Forwards final deficiency rept re installation of seismit pipe hanger anchors GILLELAND, J E Tennessee Valley Authority 79/05/13 3pp
- --7906140387 Final deficiency rept improper installation of seismic pipe hanger anchor Gaused by lack of concern by some installers Anchor bolts inspected & addl instruction provided
  Tennessee Valley Authority 79/05/15 2pp
- 7906080277 Submits fifth interim deficiency rept re possible unconservative pressurizer relief & safety line blowdown analysis Rept to be submitted by 790748, after Westinghouse review of nozzle loads
  GILLELAND, J E Tennessee Valley Authority 79/05/20 ip
- 7706140404 Forwards final deficiency rept rs potential excessive water hammer forces in main feedwater sys GILLELAND, J E Tennessee Valley Authority 77/05/21 1p
- ---7906140410 Final deficiency rept Westinghouse informed util of potential excessive water hammer forces in main feedwater sys Analysis revealed check valves adequate to perform under accident conditions

  \* Tennessee Valley Authority 79/05/21 2pp
- 6140452 Submits second interim rept potential interior structural teal containment vessel movement envelops Util analysis of solit condition is not yet complete Next rept will be ubmitted by 790917
  ILLELAND, J E Tennesses Valley Authority 79/03/24 1p.

- 7906140378 Submits fifth interim deficiency rept possible unconservative pressurizer reliaf & safety line blowdown analysis, initially reported on 780505 Next rept to be sent 790718, after vendor completes review of nozzle loads GILLELAND, J E Tennessee Valley Authority 79/05/29 ip
- 7904080307 Revised 770510 final deficiency rept.re control loop bistable failure on loss of power Revision specifies that wiring diagram for bistables have been corrected & physical wiring will be corrected \* Tennessee Vailey Authority 79/05/31 1P
- 7906130330 Forwards interim deficiency rept for piles supporting essential raw cooling water pipe slab not being driven to drawing requirements investigation under way/corrective action to be determined OILLELAND, J E Tennessee Valley Authority 79/06/04 1p
- --7906130337 First interim deficiency rept piles supporting essential raw cooling water pipe slab not driven to design requirement CDB 79-3
  - \* Tennessee Valley Authority 79/06/04 [P
- 7906200433 Submits second interim deficiency rept re power operated relief valves initially reported 790407 Valve extended structure to be modified to increase natural frequency of valve GILLELAND, J E Tennesses Valley Authority 79/06/13 1p
- 7906220271 Forwards first interim rept re Doficiency 4 (orifice flanges) GILLELAND.J E Tennessee Valley Authority 79/06/15 ip
- ---7906220275 First interim deficiency rept orifice flanges do not meet specs Full investigation is being conducted to determine cause of orifice flanges hydro failure & possible consequences

  \* Tennessee Valley Authority 79/06/17 2pp
- 7906220384 Forwards final deficiency rept re pipes embedded in structural concrete as reported on 790112 % discussed in 790208 interim rept OILLELAND, J E Tennessee Valley Authority 79/06/15 tp
- --7906220387 Final deficiency rept pipes embedded in structural concrete
  Util failed to comply w/ACI 318-63 requirements General
  civil design criteria for affected structures evaluated &
  revised to ensure compliance
  \* Tennessee Vallay Authority 79/06/15 3pp
- 7906270218 Forwards final deficiency rept re auxiliary feedwater pump essential raw cooling water valves GILLELAND, J K Tennassee Valley Authority 79/06/20 ip
- --7906270220 Final deficiency rept auxiliary feedwater pump esential raw cooling water valves which might not open fast enough to prevent pump damage due to pumps running dry Supply valve operators to be replaced by faster acting operators \* Tennessee Vailay Authority 79/06/20 ip
- 7906270224 Forwards revised final deficiency rept re motor operated valve control circuit failures
  GILLELAND, J E Tennessee Vailey Authority 79/06/20 19
- --7906270226 Revised final deficiency rept motor operated valve control circuit failure Relay failure could have triggered events deactivating part of one train of safety sys Relays will be subjected to burn-in period

  \* Tennessee Valley Authority 79/06/20 2pp

## DOCKET 50-391 WATTS BAR NUGLEAR PLANT, UNIT 2

## A Application/construction stage documents & correspondence

- 7904160279 Forwards second round questions for transmittal to applicant. Outstanding items, qualification of safety-related equipment, identification of safety sys & equipment & identification of NRC requirements re safety sys SATTERFIELD, R Electric, Instrumentation & Control Systems Branch 79/03/21 13pp
- 7906060007 Notification of 790517-18 meeting w/TVA in Knoxville,TN to discuss buckling design criteria,using encl info requests as basis for discussion
  STAMLE,C R Light Water Reactors Branch 4 79/05/08 Spp
- 7906280016 Submits requests for add1 info on mat1 integrity & mechnical engineering. Requests responses by 790629, VARGA:8.A Light Water Reactors Branch 4 79/05/16 19pp

- 7706040204 Requests approval of flexible metal hose for use as safety-related piping by 770615 Forwards data demonstrating compliance w/Reg Guide 1 84 & ASME Code applications addressed in Case Code N-192 GILLELAND.J E Tennessee Valley Authority 77/05/21 300pp.
- 7906010282 Confirms schedule Forunds agenda for 790614-(5 meeting in Knoxville,TN to discuss containment buckling criteria GILLELAND,J E Tennessee Valley Authority 79/05/29 2pp
- 7906010196 Forwards Amend 39 to FSAR GILLELAND, J E Tennessee Valley Authority 79/05/29 1p
- --7906010198 Amend 39 to FSAR Includes responses to NRC second round questions, revised FSAR figures & miscellaneous FSAR text revisions \* Tennessee Valley Authority 79705/29 250pp
- 7906070191 Forwards Certificate of Svc.averring that Amend 39 to FSAR was served on 790604 MILLS.L M Tennessee Valley Authority 79/06/05 2pp
- ⊕ Inspection reports. IE Bulletins & correspondence
- 7906150457 Forwards IE Insp Repts 50-390/79-11 & 50-391/79-08 on 790305-08 No noncompliance noted SUTHERLAND. J T Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 2pp
- --7906150463 IE Insp Repts 50-390/79-11 % 50-391/79-07 on 790305-08 No noncompliance noted Major areas inspected radiological environ monitoring program MACARTHUR, T C , PEERY, W W , HUFHAM, J W Region 2, Atlanta, Office of the Director 79/03/29 4pp
- 7706090063 Forwards IE insp Repts 50-390/79-14 & 50-391/79-11 on 790320-0323 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Brench 79/04/03 2pp
- --7906050075 IE Insp Repts 50-390/79-14 & 30-391/79-11 on 790320-0321 No noncompliance noted Major areas inspected reactor vessel internals quality records & safety-related pipe support; restraint sys & Unit 2 containment penetrations records VALLISH:E J Region 2. Atlanta, Office of the Director BRYANT, J C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 5pp
- 7906220084 Forwards IE Insp Repts 50-390/79-15 \$ 50-391/79-12 on 790320-23 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906220093 IE Insp Repts 50-390/79-15 & 50-391/79-12 on 790320-23 No noncompliance noted Major areas inspected protection of installed instrumentation components & panels; fire suppression equipment & installation & records re cables RUFF, A B Region 2. Atlanta, Office of the Director BRYANTJ C Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/06 App
- 7906210286 Forwards IE Insp Repts 50-390/79-16 & 30-391/79-13 on 790327-30 No noncompliance noted MURPHY.C.E Region 2. Atlanta, Reactor Construction & Engin Support Branch 79/04/12 200

- -7906210034 Notice of violation from insp on 790220-23
   Region 2. Atlanta. Office of the Director 79/03/19 ip
- --7906210037 IE Insp Repts 50-390/79-09 & 50-391/79-07 on 790220-23
  Mancompliance noted weld reinforcement on chemical & vol
  control sys tants exceeded specs
  GIRARD.E H. COMLON I E Region 2. Atlanta, Office of the
  Director 79/03/19 App

- --7906190533 Responds to NRC 790309 lfr re violation noted in IE Insp Rept 50-391/79-04 Corrective actions core barrel assembly GILLELAND. J E Tennessee Valley Authority 79/04/30 3pp
- 7906200174 Ack receipt of 790427 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-390/79-12 & 50-391/79-09 MURPHY.C E Region 2. Atlanta Reactor Construction & Engineering Support Branch 79/05/14 2pp
- --7906200186 Responds to NRC 790404 ltr re violation noted in IE Insp Repts 50-390/79-12 & 50-391/79-09 Corrective actions record requiring approval signature signed Painted over corrections determined to be typographical in nature GILLELAND. J E Tennessee Valley Authority 79/04/27 2pp
- --7906200193 Forwards IE Insp Repts 50-390/79-12 & 50-391/79-09 on 790312-15 & notice of violation MURPHY,C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- --7906200196 Notice of violation from insp on 790312-15
  \* Region 2: Atlanta, Office of the Director 79 79/04/04 in
- --7906200204 IE Insp Repts 30-390/79-12 & 50-391/79-09 on 790312-15
  Noncompliance noted insufficient records used to furnish
  evidence of activities affecting quality Record corrections
  painted over/instead of line drawn through & corrected
  VAN DODRN.P K Region 2. Atlanta. Office of the Director
  CONLON.T E Region 2. Atlanta. Reactor Construction &
  Engineering Support Branch 79/04/04 Spp
- 7906210098 Responds to LE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related sys Effort in progress to locate any ABME SA-312 Type 304 piping supplied by Youngstown Melding & Engineering Co GILLELAND. J E Tennessee Valley Authority 79/03/14 1p
- 7906080284 Submits revised response to OA records deficiency noted in 790404 Insp Repts 50-390/79-12 & 50-391/79-09 GILLELAND, J E Tennassee Valley Authority 79/06/01 2pp
- 7908280094 First interim deficiency rept incorrect Velan valve weights used in seismic piping analysis Final response to IE Bulletin 79-04 will be submitted before fuel load in GILLELAND, J E Tennessee Valley Authority 79/06/22 1p
- 7906290392 Submits response to deviation & infractions cited in IE Insp Repts 50-390/79-20 & 50-391/79-16 GILLELAND, J & Tennessee Valley Authority 79/06/25 7pp
- S Reportable occurrences, LERs & related correspondence
- 7906140381 Forwards final deficiency rept re installation of seismic pipe hanger anchors GILLELAND, J E Tennessee Valley Authority 79/09/15 3pp
- --7906140387 Final deficiency rept improper installation of seismic pipe hanger anchor Caused by lack of concern by some installers Anchor boits inspected & addl instruction Tennessee Valley Authority 79/05/15 2pp
- 79Q6080277 Submits fifth interim deficiency rapt re possible unconservative pressurizer relief & eafety line blowdown analysis Rept to be submitted by 770716, after Westinghouse review of nozzla loads
  OILLELAND, J E Tennessee Valley Authority 79/05/20 1p
- 7906140404 Forwards final deficiency rept re putential excessive water hammer forces in main feedwater sys
  OILLELAND, J E Tennessee Valley Authority 79/05/21 1p

- -7906140410 Final deficiency rept Westinghouse informed util of potential excessive water hammor forces in main feedwater sys Analysis revealed check valves adequate to perform under accident conditions

  \* Tennessee Valley Authority 79/05/21 2pp
- 7706140432 Submits second interim rept potential interior structural steel containment vessel movement envelope Util analysis of as-built condition its not yet complete Next rept will be submitted by 790917
  OILLELAND, J E Tennessee Valley Authority 79/05/24 1p
- 7906140378 Submits fifth interim deficiency rapt possible unconservative pressurizer relief & safety line blowdown analysis, initially reported on 780505 Next rept to be sent 790718, after vendor completes review of nozzle loads GILLELAND, J E Tennessee Valley Authority 79/09/29 ip
- 7906080307 Revised 790510 final deficiency reptire control loop bistable failure on loss of power Revision specifies that wiring diagram for histables have been corrected & physical wiring will be corrected Tennessee Valley Authority 79/05/31 12
- 7905i30930 Forwards interim deficiency rept for piles supporting essential raw cooling water pipe slab not being driven to drawing requirements investigation under wayscorrective action to be determined OILLELAND, J E Tennessee Valley Authority 79/06/04 ip
- --7906130337 First intorim deficiency rept piles supporting essential raw cooling water pipe slab not driven to design requirement CDB 79-3

Tennessee Valley Authority 79/06/04

- 7906200433 Bubmits second interim deficiency rept re power aperated relief valves initially reported 790407 Valve extended structure to be modified to increase natural frequency of QILLELAND, J E Tennesses Valley Authority 79/06/13 ip
- 7906220271 Forwards first interim rept re Deficioncy 4 (orifice flanges) OilLELAND, J E Tennessee Valley Authority 79/06/18 ip
- --7906220275 First interim deficiency rept orifice flanges do not meet specs Full investigation is being conducted to determine cause of orifice flanges hydro failure & possible consequences \* Tennessee Valley Authority 79/06/17 2pg
- 79062203B4 Forwards final deficiency rept re pipes embedded in structural concrete.as reported on 790112 & discussed in 79020B interim rept GILLELAND, J E Tennessee Valley Authority 79/06/15 ip.
- --7906220387 Final deficiency rept pipes embedded in structural congrete Util failed to comply w/ACI 318-63 requirements General civil design criteria for affected structures evaluated & revised to ensure compliance « Tennessee Valley Authority 79/04/15 3pp
- 7906270218 Forwards final deficiency rept re auxiliary feedwater pump essential raw cooling water valves OILLELAND, J.K. Tennesses Valley Authority 79/06/20 1p
- --7906270220 Final deficiency rept auxiliary feedwater pump esential raw cooling water valves which might not open fast enough to prevent pump damage due to pumps running dry Bupply valve operators to be replaced by faster acting operators at the property of the propert
- 7906270224 Forwards revised final deficiency rept re motor operated valve control circuit failures
  GILLELAND.J.E Tennessee Valley Authority 79/06/20 ip
- ~~7906270226 Revised final deficiency rept re motor operated valve control circuit failure Relay failure could have triggered events deactivating much of one train of safety sys Control circuit fuses to meet Code & solid state relays screened a Tennessee Valley Authority 79/06/20 2pp.
- DOCKET 50-394 CALIFORNIA STATE POLYTECH COLLEGE RES REACTOR G Inspection reports: IE Builetins & correspondence
- 7904250445 Forwards IE Insp Rept 50-394/79-02 on 790412-13 No noncompliance noted

  CREMBUJ L Region 5. San Francisco: Reactor Operations Nuclear
  Support Branch 79/05/04 2pp

- --7906250449 [E Insp Rept 50-394/79-02 on 790412-13 No noncompliance noted Major areas inspected organization & administration surveillance procedures reactor operations & . dicommissioning
  JOHNSON,O W , FAULKENBERRY, B Region 5, Ban Francisco, Reactor
  Operations Nuclear Support Branch 79/05/04 ip
- 7906180467 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel
- Assemblies "No written response necessary ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/10
- 7906080227 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/18
- DOCKET 50-395 VIRGIL C SUMMER NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7906200295 Requests certification that discharges will comply w/applicable sections of Federal Water Pollution Control Act amend of 1972 BALLARD, R. I. Environmental Projects Granch 1 79/05/03 1p
- 7906120126 Natification of 790605 meeting w/util in Bethesda.MD to discuss induced seismicity at plant site BAER.R L Light Water Reactors Branch 2 79/05/11 App
- 7906020228 Requeste review & consideration of suggested changes in Natl Pollution Discharge Elimination Sys monitoring program NRC comments & recommendations on aquatic biological & water quality monitoring programs encl BALLARD, R L Environmental Projects Branch 1 79/05/15 Opp
- J Insurance & indemnity information
- 7904080270 Forwards executed Amend 1 to Indomnity Agreement B-86 NICHOLS, T C South Carolina Electric & Gas Co 79/05/30 2p
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906050276 Forwards Amend 14 to FSAR Affidavit of Svc encl CREWS.E H South Carolina Electric & Gas Co 79/06/04 2pp
- --7706050279 Amond 14 to FSAR \* South Carolina Electric & Gas Co 77/06/04 500pp
- M Antitrust correspondence
- 7904010158 Util seeks 2-week extension until 790419, for filing of response to scheduling order submitted by NRC on 790328 Certificate of Svc encl CUNNER, T B Conner, Moore & Corber 79/04/02 4pp
- 790407033B BC Public Syc Authority reply to Central Electric Power Cooperative 790319 reply brief re motions to dismiss latter's amended petition % no latter's 790322 ltr Certificate of Syc encl MORRIBON.H P , LEEPER.C S Cahill, Gordon & Reindel 79/04/19
- 7906050156 Forwards page 2 of encl to 790105 ltr from CH Fischer of SC Electric & Gas to PT Allen of Central Electrical Power Cooperative Ltr was appended to former's rasponse to latter's reply brief RADER:R M Conner, Moore & Corber 79/05/08 2pp
- G. Inspection reports, 1E Bulletins & correspondence
- 7904200585 Notifies Westinghouse will submit necessary matl for response to IE Bulletins 78-12 & 78-12A, re atypical welds, before 790528 deadline CREWS, E H South Carolina Electric & Gas Co 79/04/30 ip
- 7906250458 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P 79/05/10 1p Region 2, Atlanta, Office of the Director
- 7906250460 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/05/10 10

- 7906140173 Responds to 1E Builetin 79-03 re ASME SA-312 Type 304 welded pipe Pipes not in use or planned for use CREWB.E H South Carolina Electric & Gas Co 79/05/11 ip
- 7906190152 Ack receipt of IE Insp Repts 50-395/79-11.50-395/79-12 & 50-395/79-13 No preprietary info Insp Rept 50-395/79-13
- JOHNSON, M.C. South Carolina Electric & Gas Co. 79/05/15 1p
- --7906190162 Forwards IE Insp Rept 50-395/79-13 on 790409-12 No noncompliance noted MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 2pp
- -7906190168 IE Insp Rept 5D-395/79-13 on 790409-12 No noncompliance Notified it inspired 50-345/74-13 on 790409-12 No noncompliance noted Major areas inspected electrical cable instablation & records, electrical components instablation & records, licensee identified items & inspector followup RUFF, A Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/24 App
- 7906220071 Ack receipt of IE Insp Repts 50-395/79-11, 50-395/79-12 & 50-395/79-13 No proprietary info Insp rept 50-395/79-11 JOHNSON, M C South Carolina Electric % Gas Co 79/05/15 1p
- --7906220074 Farwards IE Insp Rept 50-395/79-11 on 790403-06 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 2pp
- --7906220081 IE Imsp Rept 50-395/79-11 on 790403-06 No noncompliance noted Major areas inspected prestressing tendons electrical penetrations through containment wall & emergency diesel generators
  SMAN,W B , BRYANT, J C Region 2, Atlanta, Reactor Construction
  & Engineering Support Branch 79/04/23 App
- 7906220086 Ack receipt of IE Insp Repts 50-375/79-11.50-375/79-12 & 50-375/79-13 No proprietary info Insp Rept 50-395/79-12 unci JOHNSON, H C South Carolina Electric & Gas Co 79/05/15 1p
- --7906220091 Forwards IE Insp Rept 50-395/79-12 on 790416-19 No noncompliance noted HURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 2pp
- --7906220101 IE Insp Rept 50-395/79-12 on 790416-19. No noncompliance NOAZOLOL LE INSP REPE 50-392/79-12 on 790416-19, No noncompli-noted Major areas [naspected licenses action on previous insp findings.IE bulletins & circulars.iOCFR50 55(e) items & const activities BURDETIE, TE , HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/27 5pp
- 7906290568 Ack receipt of 790525 ltr informing NRC of steps taken to correct violations noted in IE Insp. Rept 50-395/79-10
  MMRPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/31
- --7906290580 Responds to NRC 790504 ltr re violations noted in IE Insp Rept 50-975/79-10 Corrective actions clarification of work guidelines for piping welding JOHNSON,M C South Carolina Electric & Qas Co 79/05/25 Spp
- S Reportable occurrences. LERs & related correspondence
- 7906220300 Provides info re rated loadings for upset conditions on pipe supports & incorrect terminations on 7 ky motors.

  JOHNSON, M. C. Bouth Carolina Electric & Gas Co. 79/06/18 3pp
- DOCKET 50-374 UNIV OF VIRGINIA CAVALIER REACTOR G Inspection reports. IE Bulletins & correspondence
- 7906250424 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J. P Region 2, Atlanta, Office of the Director 79/05/10
- DOCKET 50-397 WPP88 NUCLEAR PROJECT, UNIT 2
- A Application/construction stage documents & correspondence
- 7906270271 Forwards Analysis Branch first round questions re GL application Requests response by 790720. VAROA:B A Light Water Reactors Branch 4 79/05/17 3pp

- F Security, medical, emergency & fire protection plans
- 7906120356 Forwards responses to NRC 790405 questionnaire re physical security plan Responses withheld (ref locFR2 790) RENBERGER, D.L. Washington Public Power Supply System 79/06/11
- P Operating license stage documents & correspondence
- 7906190469 Requests 790710 meeting w/NRC to discuss geology-related matters
  RENBERGER, D.L. Washington Public Power Supply System 79/06/13
- 7906150063 Notice of violation from insp on 790201-02 & 14-15 \* Region 5, San Francisco. Reactor Construction & Engineering Support Branch 79/03/21 App
- --7906150079 IE Insp Repts 50-397/79-03,50-460/79-04 & 50-513/79-04 on 790201-02 & 14-15 Noncomptiance noted failure to respond effectively to audit finding & failure to (mplement effective inspec program BISHOP, T W Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 7pp
- 7906;50085 Responds to NRC 790321 ltr re violations noted in IE Insp. Repts 50-3977/79-03, 50-460/79-04 & 50-513/79-04 Corrective actions audit conducted Feb 1977 Deficient hanger RD-405 will be removed & replaced properly RENBERGER.D L. Washington Public Power Supply System 79/04/20 3pp
- --7906150090 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-397/79-03, 50-460/79-04 5 50-513/79-04 ENGELKEN, R H Region 5, Ean Francisco, Reactor Construction & Engineering Support Branch 79/05/03 1p
- --7904150058 Forwards IE Insp Repts 50-397/79-03.50-460/79-04 \$
  50-513/79-04 on 790201-02 & 14-15 & notice of violation
  SPENCER.O 8 Region 5, San Francisco, Reactor Construction &
  Engineering Support Branch 79/03/21 2pp
- --7906190063 Notice of violation from insp on 790201-02 & 14-15
  \* Region 5. San Francisco. Reactor Construction & Engineering
  Support Branch 79/03/21 2pg
- --7905150079 IE insp Repts 50-397/79-03.50-450/79-04 & 50-513/79-04 on 790201-02 & 14-15 Noncompliance noted failure to respond effectively to audit finding & failure to implement effective insp program

  BISHOP.T W . SHACKLETON.O C . HAYNES,R C Region 5, San Francisco . Reactor Construction & Engineering Support Branch 79/03/21 7pp
- 7906130135 Forwards IE Carcular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required ENCELKEN.R H Region 5. San Francisco, Office of the Director 79/05/02 1p
- 7906120057 Forwards 1E Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGLIKEN R H Region 5, San Francisco, Office of the Director 79/03/07 1p
- 7906180498 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN,R H Region 5, Sen Francisco, Office of the Director. IO Ip

- S Reportable occurrences, LERs & related correspondence
- 7906180231 Forwards PND-79-67AN ENGELKEN,R H Region 5, San Francisco: Office of the Director 79/05/14 ip
- 7906180280 Forwards PND-79-67AO ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/21 1p
- 7906180351 Forwards PND-79-67AP
  ENGELKEN, R H Region 5. San Francisco. Office of the Director
  79/05/22 1p
- 7906180371 Forwards PND-79-67AQ ENGELKEN,R H Region 5, San Franc<sup>®</sup>isco, Office of the Director 79/05/30 ip
- 7906080301 Forwards deficiency rept re possible failure of partian of page whip restraint structure in main steam tunnel RENBERGER, D.L. Washington Public Power Supply System 79/05/3t ip
- --790A080305 Deficiency rept defective steel plate used in supporting structure for pipe whip restraints in main steam tunnel Cracking attributed to overheating SA-337 Class II steel Defective A-337 math rejected # Washington Public Power Supply System 79/05/31 1p
- 7906080312 Forwards deficiency rept on 780413 re defective solder connections on electrical penetrations X100, A.B.C & D
  RENBERGER, D.L. Washington Public Power Supply System 79/05/31
- --7906080313 Deficiency rept on 780413 defective solder connections on electrical penetrations X100.A.B.C & D Reported on 790504 Repair & GC procedures provided by Westinghouse \* Mashington Public Power Supply System 79705/31 ip

1

- DOCKET 50-400 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 1

  A Application/construction stage documents & correspondence
- 7906140565 Concurs w/corrective action re backfill against Category l structures & core const for dams & dike Agrees to resume earthwork if IE accepts field moisture control procedures JACKBON, R E Geosciences Branch 79705708 2pp
- 7906020207 informs that spismic Category I fill placement criteria & test criteria was found acceptable Requests IE determine whether applicant plans to replace matl w/fill which meets specs If not addl info is needed VABSALLO.D B Division of Project Management 79/05/09 2pp
- 7906200615 Confirms concurrence w/schedule for resumption of fill placement in dams & dikes in const site areas which presently contain no fill O'REILLY.J P Region 2. Atlanta. Office of the Director 79/05/10 1p
- 7906180781 Accepts revised placement & test criteria in HR Denton 790504 ltr to MA McDuffie Forwards request for info re design criteria for fill & backfill supporting pipes & conduits PARR, O D Light Water Reactors Branch 3 79/05/17 4PP
- 7906120428 Forwards geologic rept on fault F3 shift layer at Station 11+52 at main dam Feature is not fault or capable fault, as defined per 10CFR100.App A Oversized diagrams enc] MCDUFFIE.H A Carolina Power & Light Co. 79706/06 11pp

- 7906010192 Summarizes NRC guidelines for preparation of environ reptacts discussed at 790508 meeting MCDUFFIE.M A Carolina Power & Light Co 79/05/29 2pp
- C Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-507 SCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases

  CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906070177 Submits corrections to transcript of 790227-0308 proceedings Certificate of Svc encl.
  BARTH, C A Branch 3 79/04/16 7pp
- 7906070255 Denies motion by intervenors Conservation Council of NC & Wake Environ.Inc to remand & reopen hearings re necessity of facility Future motions re CPs must be consistent w//10CFR2 206
  CHILK:S J Office of the Secretary of the Commission 79/05/02
- 7906010142 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law SMITH, I W Atomic Safety and Licensing Board Panel 79/05/08 ip
- 7906210095 NRC motion for summary disposition re-radon issue was in error/ALAB-540 consolidated only 5 of 16 cases Danies NRC motion as to parties in other proceedings Certificate of Bvc encl DUFLD:ME Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906220473 Reopens evidentiary hearing due to changes in mgt which are materially relevant to remanded issue Directs util to submit affidavit detailing changes SMITH, I W Branch i 79/05/25 2pp
- G Inspection reports, IF Bulletins & correspondence
- 7906250440 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 | Ip
- 770.6270787 Responds to IE Builstin 79-03 re ASME SA-312 Type 304 pipe mfg by Youngstown Welding & Engineering Co Pipe not in use or planned for use MCDUFFIE.H A Carolina Power & Light Co 79/05/17 1p
- S Reportable occurrences, LERs & related correspondence
- 7906130270 RD on 790604 welds in 15 containment liner sleeves were not stress relieved Caused by misunderstanding of intent of code requirement Units returned to vendor for stress relieving GEORGE, H H Chemetron Corp , Tube Turns Div 79/06/07 2pp
- T Hearing transcripts on non-antitrust matters
- 7903140067 Transcript of 790302 hearing in Raleigh, NC. Pp 2,897-2,979
  Panel 3 testimony encl
  BMITH, I W., LEEDS, J. V., BRIGHT, G.O. Atomic Safety and Licensing
  Board Panel 79/03/02 200pp
- 7903140039 Transcript of 790306 hearing in Raleigh.NC Pp 2,980-3,223 SMITH, I W. LEEDS, J. V. BRIGHT.O U. Atomic Safety and Licensing Board Panel 79/03/06 243pp
- 7903140116 Transcript of 790307 hearing in Raleigh,NC Pp 3,224-3,506, in two vols Exhibits & testimeny enc i SMITH, I H . LEEDS, J V . BRIGHT, 0, 0 Atomic Safety and Licensing Board Panel 79703/07. 400pp
- DOCKET 50-401 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7906140565 Concurs w/corrective action re backfill against Catagory i structures & core const for dams & dike Agrees to resume earthwork if IE accepts field moisture control procedures JACKSON:R E, Ososciences Branch 79/05/08 2pp

- 7906020207 Informs that seismic Category 1 fill placement criteria & test criteria was found acceptable Requests IE determine whether applicant plans to replace matl w/fill which meets specs If not, add I info is needed VASSALLO, D B Division of Project Management 79/05/09 2pp
- 7906200615 Confirms concurrence w/schedule for resumption of fill placement in dams & dikes in const site areas which presently contain no fill O'REILLY, J.P. Region 2. Atlanta. Office of the Director 79/05/10 lp
- 7906/180781 Accepts revised placement & test criteria in HR Denton 790504 ltr to MA McDuffie Forwards request for info re design criteria for fill & backfill supporting pipes & conduits PARR.O D Light Water Reactors Branch 3 79/05/17 4pp
- 7906120428 Forwards geologic rept on fault F3 shift layer at Station 11+52 at main dam Feature is not fault or capable fault, as defined per 10CFR100, App A Oversized diagrams encl MCDUFFIE.M A Carolina Power & Light Co 79/06/06 lipp
- 7906150319 Notifies that portions of main & auxiliary damcove trenches are ready for inspiper App A to 10CFR100 MCDUFFIE,M A Carolina Power & Light Co 79/06/11 2pp
- 7906140285 Responds to 790517 request for info re 30-inch svc water lines & adjacent electrical conduit between emergency svc water-colling tower make—up intake structure & Tank Bldg 1 Info re seismic Category 1 piping to be submitted MCDUFFIE, MA Carolina Power & Light Co 79/06/12 125pp
- 7906190249 Confirms exposure of site fault in west auxiliary dam foundation Schedules mapping documentation during routine mapping sequence MCDUFFIE,M A Carolina Power & Light Co 79/06/15 ip
- C Utility Environmental Report (ER), amends & correspondence
- 7906010192 Bummarizes NRC guidelines for preparation of environ rept. as discussed at 790508 meeting MCDUFFIE.M A Carolina Power & Light Co 79/05/29 2pp
- G Adjudicatory correspondence
- 7906210047 Mation for extension until 790411 to prepare response to ALAB-509
  BCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of culemakin proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY:E Hearings Division 79/03/26 34pp
- 7906070177 Submits corrections to transcript of 790227-0308 proceedings Certificate of Svc encl. BARTH-C A Branch 3 79/04/16 7pp
- 7906070235 Denies motion by intervenors Conservation Council of NC & Hake Environ. Inc to remand & reopen hearings re necessity of facility Future motions re CPs must be consistent w/100FR2 206
  CHILK: 8 J Office of the Secretary of the Commission 79/05/02
- 7906010142 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law EMITH.I W Atomic Befety and Licensing Board Panel 79/05/08 ip
- 7906210095 NRC motion for summary disposition re radon issue was in error:ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings, Certificate of 8vc enci DUFLO:M E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906220473 Reopens evidentiary hearing due to changes in mgt which are materially relevant to remanded issue Directs util to submit affidavit detailing changes
  8MITM, I W Branch i 79/05/25 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906250440 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J.P. Region 2, Atlanta, Office of the Director 79/05/10 1p

- 7906290787 Responds to IE Bulletin 79-03 re ABMR SA-312 Type 304 pipe mfg by Youngstown Welding & Engineering Co Pipe not in use or planned for use MCDUFFIR: M A Carolina Power & Light Co 79/05/17 1p
- S Reportable occurrences. LERs & related correspondence
- 7906130290 RO on 790604 welds in 15 containment liner sleeves were not stress relieved Caused by misunderstanding of intent of code requirement Units returned to vendor for stress relieving GEORGE: HH Chemetron Corp., Tube Turns Div 79/06/07 2pp
- T Hearing transcripts on non-antitrust matters
- 790314006/ Transcript of 790302 hearing in Raleigh,NC Pp 2,897-2,979 Panel 3 testimony encl ShITH,I W . LEEDS.J V . BRIGHT,G O Atomic Safety and Licensing Board Panel 79/03/02 200pp
- 7903140059 Transcript of 790306 hearing in Raleigh.NC Pp 2,980-3,223 SHITH.I H , LEEDS.J V . BRIGHT.O O Atomic Safety and Licensing Board Panel 79/03/06 243pp
- 7903140116 Transcript of 790307 hearing in Raleigh.NC Pp 3.224-3.506, in two vals Ethibits & testimony oncl SMITH.I W. LEEDS.J V. BRIGHT.O O Atomic Safety and Licensing Board Panel 79/03/07 600pp
- DOCKET 50-402 SHEARDN MARRIS NUCLEAR POWER PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- 7906140365 Concurs w/corrective action re backfill against Category 1 structures & core const for dams & dike Agrees to resume earthwark if IE accepts field moisture control procedures JACKSON, R E Geosciences Branch 79/05/08 2pp
- 7906020207 Informs that seismic Category 1 fill placement criteria & test criteria was found acceptable Requests IE determine whether applicant plans to replace mati w/fill which mests specs if not.addi info is needed VASSALLO.D B Division of Project Management 79/05/09 2pp
- 7906200615 Confirms concurrence w/schedule for resumption of fill placement in dams & dikes in const site areas which presently contain no fill O'ABILLY.J P Region 2. Atlanta. Office of the Director 79/05/10 1p
- 7906180781 Accepts revised placement & test criteria in HR Danton 790504 ltr to MA McDuffle Forwards request for info re design criteria for fill & backfill supporting pipes & conduits PARRIO D Light Water Reactors Branch 3 79/05/17 4pp
- 7906120428 Forwards geologic rept on fault F3 shift layer at Station 11+52 at main dam Feature is not fault or capable fault, as defined per 100FR100.App A Oversized diagrams enc; MCDUFFIE,M A Carolina Power & Light Co 79/06/06 lipp
- 7906150319 Notifies that portions of main & auxiliary damcove trenches are ready for inspiper App A to 10CFR100 MCDUFFIE.M A Carolina Power & Light Co 79/06/11 2pp
- 17906140283 Responds to 790317 request for info re 30-inch svc water lines & adjacent electrical conduit between emergency svc water colling tower make-up intake structure & Tank Bldg 1 Info re seismic Category 1 piping to be submitted MCDUFFIE.M A Carolina Power & Light Co 79/06/12 125pp
- 7906150249 Confirms exposure of site fault in west auxiliary dam foundation Schedules mapping documentation during routine mapping sequence
  MCDUFFIE.M A Carolina Power & Light Co 79/06/15 1p
- C Utility Environmental Report (ER), amends & correspondence
- 7904010192 Bummarizes NRC guidelines for preparation of environ rept, as discussed at 790508 meeting
  MCDUFFIE.M A Carolina Power & Light Co 79/05/29 2pp
- G Adjudicatory correspondence
- 7706210047 Motion for extension until 790411 to prepare response to ALAB-509 8CINTO.J F Hearings Division 79/04/02 2pp

- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to devolop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY,E Hearings Division 79/03/26 34pp
- 7906070177 Submits corrections to transcript of 790227-0308 proceedings Certificate of Svc enc1
  BARTH.C A Branch 3 79704/16 7pp
- 7906070255 Denies motion by intervenors Conservation Council of NC & Wake Environ. Inc to remand & reopen hearings re necessity of facility Future motions re CPs must be consistent w/10CFR2 206
  CHILK.S J Office of the Secretary of the Commission 79/05/02
- 7904010142 Orants 10-day extension of time for NRC to file proposed findings of fact 1/2 conclusions of law SMITH.I W Atomic Safety and Licensing Board Panel 77/05/08 ip
- 7906210095 NRC motion for summary disposition re radon issue was in errorsALAB-340 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLD.M E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906220473 Reopens evidentiary hearing due to changes in mgt which are materially relevant to remanded issue Directs util to submit affidavit detailing changes SMITH.I W Branch i 79/05/25 2pp
- 0 Inspection reports, IE Bulletins & correspondence
- 7906250440 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  0'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7906290787 Responds to IE Bulletin 79-03 re ABME 8A-312 Type 304 pipe mfg by Youngstown Helding & Engineering Co Pipe not in use or planned for use MCDUFFIE.M A Carolina Power & Light Co 79/05/17 ip
- S Reportable occurrences, LERs & related correspondence
- 7906130270 RO on 790604 welds in 15 containment liner sleeves were not stress relieved Caused by Misunderstanding of intent of code requirement Units returned to vendor for stress relieving GEORGE, H H Chemotron Corp. Tube Turns Div 79/06/07 2pp
- T Hearing transcripts on non-antitrust matters
- 7903140067 Transcript of 790302 hearing in Raleigh, NC Pp 2:897-2,979 Panel 3 testimony encl SMITH, I W. LEEDS, J V. BRIGHT, C O Atomic Safety and Licensing Board Panel 79/03/02 200pp
- 7903140099 Transcript of 790306 hearing in Raieigh,NC Pp 2,980-3,223 SMITH,I W., LEEDS,J V., BRIGHT,G O. Atomic Safety and Licensing Board Panel 79/03/06 243pp
- 7903140116 Transcript of 790307 hearing in Raleigh.NC Pp 3,224-3,506, in two vols Exhibits & testimony enc; SMITH.I W. LEEDS.J V. BRIGHT.G O. Atomic Safety and Licensing Board Panel 79/03/07 600pp
- DOCKET 50-403 SHEARON HARRIS NUCLEAR POWER PLANT, UNIT 4
- A Application/construction stage documents & correspondence
- 7906140363 Concurs w/corrective action re backfill against Category i structures & core const for dams & dike Agrees to resume earthwork if IE accepts field moisture control procedures JACKBON.R E Geosciences Branch 79/05/08 2pp
- 7906020207 Informs that seismic Category i fill placement criteria & test criteria was found acceptable, Requests IE detarmine whether applicant plans to replace math w/fill which meets specs. If not addi info requested VASBALLO, D.B. Division of Project Management 79/05/09 2pp
- 7906200615 Confirms concurrence w/schedule for resumption of fill placement in dms & dikes in const site areas which presently contain no fill O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 ip

- 7906180781 Accepts revised placement & test criteria in HR Denton 790504 1tr to MA McDuffie Forwards request for info re design criteria for fill & backfill supporting pipes & conduits PARR, O D Light Water Reactors Branch 3 79/05/17 4pp
- 7906120428 Forwards geologic rept on fault F3 shift layer at Station 11+52 at Main Dam Feature is not fault or capable fault, as defined per 10CFR100, App A Dversized diagrams encl MCDUFFIE.M A Carolina Power & Light Co 79/06/06 1tpp
- 7906150319 Notifies that portions of main & auxiliary damcove trenches are ready for insp per App A to 10CFR100 MCDUFFIE.H A Carolina Power & Light Co 79/06/11 2pp
- 7906140285 Responds to 790517 request for info re 30-inch svc water lines & adjacent electrical conduit between emergency svc water.cooling tower make-up intake structure & Tank Bldg i Info re seismic Category i piping to be submitted MCDUFFIE.M A Carolina Power & Light Co 79/06/12 125pp
- 7906130249 Confirms exposure of site fault in west auxiliary dam foundation Schedules mapping documentation during routine mapping sequence MCDUFFIE.M A Carolina Power & Light Co 79/06/15 ip
- C Utility Environmental Report (ER), amends & correspondence
- 7906010192 Summarizes NRC guidelines for proparation of environ rept as discussed at 790508 meeting MCDUFFIE.M A Carolina Power & Light Co 79/05/29 2pp
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-507 GCINTO: J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY. E Hearings Division 79/03/26 34pp
- 7906070177 Bubmits corrections to transcript of 790227-0308 proceedings Certificate of Svc encl BARTH.C A Branch 3 79/04/16 7pp
- 7906070295 Denies motion by intervenors Conservation Council of NC & Make Environ Inc to remand 8 reopen hearings re necessity of facility Future motions re const permits must be consistent w/10CFR2 206
  CMILK.8 J Office of the Secretary of the Commission 79/05/02 5pp
- 7906010142 Grants 10-day extension of time for NRC to file proposed findings of fact & conclusions of law SMITH.I W Atomic Safety and Licensing Board Panel 79/05/08 1p
- 7906210095 NRC motion for summary disposition re radon (save was in error)ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Bvc encl DUFLO.M E. Atomic Sefety and Licensing Appeal Panel 79/05/25 3pp
- 7906220473 Reopens evidentiary hearing due to changes in mgt which are materially relevant to remanded issue.Directs util to submit affidavit detailing changes SMITH.I W Branch i 79/05/25 2pp
- G. Inspection reports, IE Bulletins & correspondence
- 7906250440 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 ip
- 7906290787 Responds to IE Bulletin 79-03 re ABME 8A-312 Type 304 pipe mfg by Youngstown Welding & Engineering Co Pipe not in use or planned for use MCDUFFIE.M A Carolina Power & Light Co. 79/05/17. 19
- 8 Reportable occurrences, LERs & related correspondence
- 7906130290 RO on 790604 welds in 15 containment liner sleeves were not stress relieved. Caused by misunderstanding of intent code requirement Units returned to vendor for etress relieving GEOROE, H. H. Chemetron Corp., Tube Turns Div. 79/06/07 2pp

- DOCKET 50-404 NORTH ANNA POWER STATION, UNIT 3
- A Application/construction stage documents > correspondence
- 7906060020 Forwards evaluation & request for addl info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation " Requests response by 790518 PARR.O D Light Water Reactors Branch 3 79/05/03 5pp
- 7906050280 Details positions re Reg Guide 1 11 Revision 0.% Reg Guide 1 120.Revision 1 Will comply w/Reg Guide 1 11 w/erception of containment pressure instrument lines Reg Guide 1 120 not applicable BROWN.8 C Virginia Electric & Power Co 79/05/30 2pp
- 7906050336 Advises that Units 3 & 4 should also be included on 790516 ltr BROWN,S C Virginia Electric & Power Co 79/09/30 1p
- 7906050323 Discusses 770110 rept "GA Program Operations Phase "
  Requests exception from ANSI N45 2 4 & N45 2 8 paragraphs re
  calibr control & equipment test Discusses proposed
  alternative
  BAUM E A Virginia Electric & Power Co 79/05/31 2pp
- G Adjudicatory correspondence
- 7906180785 FR notice of negative declaration supporting 790514 order extending completion of const dates No environ impact attributable to order other than statement considered in NASLP 740718 initial decision REGANLE H Environmental Projects Branch 2 79/04/18 2pp
- J Insurance & indemnity information
- 7906120324 Endorsement 41 to NELIA Policy MF-37
  GERAS,T Mutual Atomic Energy Liability Underwriters 79/05/10
  to
- 7906120331 Endorsoment 42 to MAELU Policy MF-57
  GERGS,T Mutual Atomic Energy Liability Underwriters 79/05/10
- G Inspection reports. IE Bulletins & correspondence
- 7906260524 Forwards IE Insp Repts 50-339/79-23,50-404/79-01 & S0-405/79-01 on 790410-12 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineeri Support Branch 79/04/25 Zpp
- ---7906260327 IE Insp 50-339/79-23,50-404/79-01 & 50-405/79-01 on 790410-12 No noncompliance noted Major areas inspected 100F80 55(e) items, blasting of foundations & posting Part 21 notices MCFARLAND.C R. HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/25 App
- 7906140487 Advises of response to IE Bulletin 79-03 re Youngstown weldefects, by 790611

  BROWN: S C Virginia Electric & Power Co 79/05/10 1p
- DUCKET 30-405 NORTH ANNA POWER STATION, UNIT 4
- A Application/construction stage documents  $\theta$  correspondence
- 7906060020 Forwards evaluation & request for add1 info re "Svc Water Reservoir & Spray Sys Performance Testing & Evaluation "Requests response by 790518 PARR.O D Light Water Reactors Branch G 79/05/OG, Spp
- 7906050280 Details positions re Reg Guide 1 11 Revision 0.8 Reg Guide 1 120.Revision I Will comply w/Reg Guide 1 11 w/erception of containment pressure instrument lines Rag Guide 1.120 not applicable BROWN 8 C. Virginia Electric & Power Co 79/05/30 2pp.
- 7906050336 Advises Units 3 & 4 should also be included on 790518 ltr. BROWN, S.C. Virginia Electric & Power Co 79/05/30, ip
- 7906050323 Discusses 770110 rept "QA Program, Operations Phase "Requests exception from ANSI N45,2 4 & N45 2,8 paragraphs recalibr control & equipment test Discusses proposed alternative.

  BAUM: E.A. Virginia Electric & Power Co. 79/05/31 2pp

### G Adjudicatory correspondence

7906180785 FR notice of negative declaration supporting 790514 order eitending completion of const dates No environ impact attributable to order other than statement considered in NASLP 740718 (nitial decision REGAN.W H Environmental Projects Branch 2 79/04/18 2pp

## J. Insurance & indecnity information

7906120324 Endorsement 41 to NELIA Policy MF-57 GERAS, T Mutual Atomic Energy Liability Underwriters 79/05/10

7906120331 Endorsement 42 to MAELU Policy MF-57
GEROS.T Mutual Atomic Energy Liability Underwriters 79/05/10

## Q Inspection reports. IE Builetins & correspondence

7906260524 Forwards IE Insp Repts 50-339/79-23.50-404/79-01 & 50-405/79-01 on 790410-12 No noncompliance noted HURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/25 2pp

--7906260327 IE Insp 50-339/79-23.50-404/79-01 & 50-405/79-01 on 790410-12 No noncompliance noted Major areas inspected 10CFR50 55(e) items.blasting of foundations & posting Part 21 notices HCFARLAND.C R. HERDT A Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/25 600

7906140487 Advises of response to IE Bulletin 79-03 re Youngstown weld defects by 790611 BROWN.S C Virginia Electric & Power Co 79/05/10 Ip

### DOCKET 50-406 TUSPEGEE INST RESEARCH REACTOR

O Inspection reports. IE Bulletins & correspondence

7908230425 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
O'REILLY, J P Region 2, Atlanta, Office of the Director 79705710 is

# DOCKET 50-407 UNIV OF UTAH RESEARCH REACTOR G Inspection reports, IE Bulletins & correspondence

7906250015 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/11 ip

## DOCKET 50-409 LA CROSSE BULLING WATER REACTOR

F Security, medical, emergency & fire protection plans

7906260022 "Fire Protection in Operating Nuclear Stations, Lacrosse Boiling Hater SER Review " HALL.R E . MACDOUGALL.R E Broothaven National Laboratory 7906260022 79/04/06 6pp

7906210368 Forwards Amend 15 to License DPR-45 & notice of issuance & availability Security plan evaluation rept withheld (ref 10CFR2 790)
ZIEMANN,D L Operating Reactors Branch 2 (Pre 790625) 79/05/16

## P Operating license stage documents & correspondence

7706060023 Forwards request for add1 infd re LACBWR Cycle 6.in order to continue review of 770226 request for Tech Spec changes
IEMANN.D L Operating Reactors Branch 2 (Pre 770625) 79/04/24

7906050231 Forwards draft evaluation of systematic evaluation program
Topic V-12 A, "Water Purity of BWR Coolant" Requests review
& response within 30 days
ZIEMANN D U Operating Reactors Branch 2 (Pre 790625) 79/04/30

7906130512 Summary of 790426 meeting w/util in Silver Spring.MD reresults of uitl Cycle 5 fuel examinations performed during current refueling outage Supporting documentation encl METMORE.J S Operating Reactors Granch 2 (Pre 790625) 79704730

7906190017 Forwards W Marcuson comments & results of NRC review of Dames & Moore rept. "Review of Liquefaction Potential.
La Crosse BWR (LACBUR). Near Genoa. Vernon County, WI " Planned program for further work is acceptable
ZIEMANN, D L Operating Reactors Branch 2 (Pre 790625) 79/01/30
3pp

7906120341 Forwards add) info re suitability of boron carbido poison matt proposed for high density fuel storage racks
LINDER, F Dairyland Power Cooperative 79/05/17 App

7906200235 Requests two controlled copies of site emergency plan & implementing procedures, site maps showing location & grid or station numbers of environ monitoring stations onsite & offsite & site maps used for offsite dose determination KEPPLER, J G Region 3, Chicago, Offsico of the Director 79/05/17 in

--7908270839 Amend 16 to License DPR-45 adding core power distribution limits for Allis-Chalmers Type I fuel assemblies & changing limits for offgas emission rates to account for cloanup of tramp activity

JECHANN, D L Operating Reactors Branch 2 (Pro 790825)

79/09/25 18pp

---7906290645 Safety evaluation supporting Amend 16 to License DPR-45
\* Operating Reactors Branch 2 (Pre 790625) 79/06/25 12pp

--7906290650 Notice of Issuance & availability of Amend 16 to License DPR-45 ZIEHANN,D L Operating Reactors Branch 2 (Pre 790623) 79/05/25 2pg

7906150217 Forwards addition for systematic evaluation program, in response to NRC 790418 request re HPCB discharge line info includes audit analysis piping sys for reactor plants, computer printout & several oversited diagrams LINDER, F Dairyland Power Cooperative 79/06/11 Spp

7906200380 Forwards requested info re gaseous effluent monitoring capabilities SHIMSHAK.R & Dairyland Power Cooperative 79/06/12 2pp

7906260212 Forwards revised enct to util 790517 itr w/addl info re suitability of boron carbide poison mat! proposed for reactor high density fuel storage racks. LINDER,F Dairyland Power Cooperative 79/06/21 6pp

## @ Inspection reports, IE Bulletins & correspondence

79060201B9 Responds to IE Bulletin 79-03 No Type 304 stainless steel piping mfg by Youngstun Welding & Engineering Co is in use or planned for use in safety-related sys at facility.

LINDER, F Dairyland Power Cooperative 79/04/20 2pp

'0625012B Forwards IE Insp Rept 50-409/79-08 on 79040B-11 No noncompliance noted REISHMAN,RF Region 3, Chicago, Reactor Operations Nuclear Support Branch. 79/04/25 2pp

790625013B IE Insp Rept 50-409/79-0B on 79040B-11 No noncompliance noted Major areas inspected preparation for refueling outage, prefuel & fuel handling activities & maint during rafueling outage LITTLE, M S . MENNING, J E , SWANSON, E R Region 3, Chicago, Office of the Director 79/04/22 Spp

- 7906260309 Forwards IE Insp Rept 50-409/79-06 on 790326-29 No noncompliance noted HEIGHMAN,R F Region 3, Chicago, Reactor Operations Nuclear Support Branch 79/04/25 2pp
- --7906260315 IE Insp Rept 50-409/79-06 on 790326-29 No noncompliance noted Major areas inspected handling, packaging & shipping of spent fuel assemblies & operations during refueling WARNIGK.R F. RIDGWAY, K B. Region 3, Chicago, Office of the Director 79/04/20 App
- 7906260587 Forwards IE Insp Rept 50-409/79-07 on 790409-11 No noncompliance noted FIGRELLIA Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/30 2pp
- --7906260589 IE Insp Rept 50-409/79-07 on 790409-11 No noncompliance noted Major areas inspected QA/QC program, peripheral shroud replacement ⊅ implementing procedures WARDK D . LIVERMORE, H + DANIELSON, D H Region 3. Chicago, Office of the Director 79/04/27 7pp
- 7906120104 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/07
- 7906020196 Act receipt of 790409 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 50-409/79-02
  HEISHMAN.R F Region 3. Chicago, Reactor Operations Nuclear Support Branch 79/05/08 ip
- --7906020198 Responds to NRC 790215 itr re violation noted in IE Insp Rept 50-409/79-02 Corrective actions cognizant personnel advised to review procedures for procurement actions LINDER:F W Dairyland Power Cooperative 79/04/09 2pp
- 7906110098 Forwards IE Bulletin 79-10, "Requalification Training Program Statistics " Written response required KEPPLER, J G Region 3, Chicago. Office of the Director 79/05/11 in
- 7906140168 Responds to IE Bulletin 79-09 re GE Type AK-2 circuit breakers Circuit breakers not in use or planned for use LINDER:F Dairyland Power Cooperative 79/05/11 ip
- 7906190090 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906080201 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U"
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/18
- 7906200569 Ack receipt of 790507 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-409/79-05
  HIND, J A Region 3, Chicago, Safeguards Branch 79/03/18 ip
- ---7906200573 Responds to NRC 790413 itr re violations noted in IE Insp Rept 50-409/79-05 Corrective actions withheld (ref 10CFR2 790). LINDER,F. Dairyland Power Cooperative 79/05/07 ip
- 7906:30097 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/22
- 7906200116 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Dyster Creek Reactor" KEPPLER.J.O Region 3. Chicago. Office of the Director 79/05/29
- R Periodic operating reports & related correspondence
- 7906120417 Forwards monthly operating rept for May 1979 LINDER, F Dairyland Power Cooperative 79/06/07 1p
- --7906120427 Monthly operating rept for May 1979
  PAFWORTH, L. G Dairyland Power Cooperative. 79/06/06 14pp
- B Reportable occurrences, LERs & related correspondence
- 7906140456 Forwards LER 79-008/03L-0 Drawing of containment ventilation exhaust damper leakage test encl LINDER:F Dairyland Power Cooperative 79/03/30 4pp

- 7706060265 Forwards LER 79-008/03L-0 LINDER,F Dairyland Power Cooperative 79/05/30 3pp
- --7906060269 LER 79-008/O3L-O on 790429 during periodic Type C leakage rate testing, containment isolation did not meet Tech Spec criteria Caused by damper disc shaft packing Replaced w/chevron type asbestos composition shaft packing SHIMSHAK, R E Dairyland Power Cooperative 79/05/28 ip
- 7906150310 Forwards LER 79-009/03L-0 LINDER.F Dairyland Power Cooperative 79/06/11 3pp
- --7906150318 LER 79-009/03L-0 on 790507 while reactor plant 125 volt do battery was removed for maint, control power key switch turned on Procedural change will be initiated requiring use of info tag on key switch PAPWORTH.L G Dairyland Power Cooperative 79/06/11 ip
- 7906270192 Forwards LER 79-010/03L-0 LINDER.F Dairyland Power Cooperative 79/06/20 3pp
- --7906270194 LER 79-010/D3L-0 on 790522 during reactor shutdown, gross alpha activity of primary coolant exceeded Tech Specs Gaused by irradiated fuel math in RCS Primary purification resins replaced % concentration reduced PAPHORTH.L G Dairyland Power Cooperative 79/06/20 4ρp
- DUCKET 50-410 NINE MILE POINT NUCLEAR STATION. UNIT 2
  H General correspondence
- 7906270701 Responds to 790315 ltr to JM Hendrie Facility was shut down by NRC 790313 order due to questions re ability of piping sys to withstand earthquakes Situation will be reviewed & plant returned to operation as soon as possible DENTON: HR Office of Nuclear Reactor Regulation 79/05/04 lp
- --7906290706 Expresses concerns re shutdown of racility Prolonged layof of plant employees could have adverse effect on town of Oswego.NY FITZOIBBONS,J E Oswego, NY 79/03/15 ip
- G Inspection reports, IE Bulletins & correspondence
- 7906180400 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary ORIER.B H Region 1, Philadelphia, "Office of the Director 79/04/16 ip
- 7906110021 Forwards IC Dulletin 79-03B, "Nuclear Incident at TMI-Suppl" No written response required GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906130167 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required GRIER, B H Region 1. Philadelphia, Office of the Director 79/05/02 lp
- 7906:20:82 Forwards IE Info Notice 79-11: "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER,B H Region 1: Philadelphia: Office of the Director 79/09/07 2pp
- 7906260131 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H Region 1, Philadelphia, Office of the Director, 79/05/11 1p
- 790627019B Responds to IE Bulletin 79-03 Downcomer piping for primary containment provided by Drave Corp Volumetric insp of downcomers have shown genesity indications
  RHODE.G K. Niagara Hohawk Power Corp 79/05/16 (p
- S Reportable occurrences, LERs & related correspondence
- 7906270166 Forwards interim deficiency rept. RHODE.Q.K Niagara Mohawk Power Corp. 79/06/19 1p.
- --7906270171 Interim deficiency rept review of ultrasonic testing recorrevealed that tests for containment liner were inadequate & certain ultrasonic testing techniques may not have been done by personnel \* Niagara Mohawk Power Corp 79/04/27 2pp

## DOCKET 50-412 BEAVER VALLEY POWER STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 7904010279 FOIA request for all records & communications re shutdown of five nuclear plants CASSAN.V J Power Authority State of New York 79/03/16 2pp
- 7906010273 Denies FOIA request for Olbban 790314 & Thampson 790315 memos to Commissioner Bradford, which contain NRC opinions & recommendations re five shubdown plants Info withheld (ref FOIA Examption 5) FELTON, J M Division of Rules and Records 79/05/21 4pp
- 7906290827 Ack receipt of 790509 application for extension of expiration date on CPPR-105 Advises \$1,200 fee required DIGGS.R M License Fee Management Branch 79/05/23 1p
- 7904130340 Responds to 790523 ltr Forwards fee for review of CP extension request WOOLEVER.E J Duquesne Light Co 79/06/04 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 7706180383 Forwards IE (nfo Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary GRIER, B H Region 1, Philadelphia, Office of the Director 77704/16 1p
- 7906110012 Forwards 1E Bulletin 79-05B, "Nuclear Incident at TMI-Buppl" No wijtten response required GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906:20156 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ORIER, B H Region I. Philadelphia, Office of the Director 79/05/07 2pp
- 7906260104 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER. B H Region 1, Philadelphia, Office of the Director 79/05/11 Ip
- 7906270203 Responds to IE Bulletin 79-07 No computer codes identified by S&W which used any of methods described in Item 1 NUPIPE 03/01-03/10 computer code used in seismic stress analysis of safety-related piping MODLEVER
- S Reportable occurrences. LERs & related correspondence
- 7906040397 Ack receipt of 790425 ltr forwarding interim rept on "Stop Work Directive" for Bingham-Willamette Co CARLBON,R Y Region 1. Philadelphia, Reactor Construction & Engineering Support Branch 79/05/04 1p
- --7906040402 Interim rept on Significant Daficiency 79-01."Stop Work Directive" for Bingham-Willametta Co \* Duquesne Light Co 79/03/29 2pp
- 7906140403 Submits Interim Rept 2 of potential Reportable Deficiency 79-05 improper drawings supplied by GE All termination cabinet panels at site are being reviewed against as-shipped drawings Final rept to be submitted 790438 DALE, L.F. Mississippi Power & Light Co. 79/05/29 1p

directive for

re welding \$ NDT of quench pumps, recirculation spray pumps & auxiliary feedwater pumps \$ Duquesne Light Co 79/06/01 ip.

### POCKET 50-413 CATAWBA NUCLEAR STATION, UNIT 1

- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 34 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy NF-61 SANDERS: F D Duke Power Co 79/06/08 39g

- Q Enspection reports: IE Bulletins & correspondence
- 7906130439 Responds to IE Builetin 79-03 Site has received 310 ft of pipe mfg by Youngstown Welding & Engineering Co Pipe will receive field hydrostatic test
  DAIL.L C Duke Power Co 79/04/20 2pp
- 7904020154 Responds to IE Bulletin 79-04 Design of facility has been reviewed No Velan valves in use
  DAIL.L C Duke Power Co 79/04/24 Ip
- 7906250446 Forwards [E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7906180734 Ack receipt of 790507 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/15 ip
- --7906180741 Responds to NRC 790413 ltr re violations noted in If Insp Repts 50-413/79-05 % 50-414/79-05 Corrective actions mitrogen blanket placed on heat exchanger & personnel instructed re nonconforming item rept DAIL.L C Duke Power Co 79/05/07 ip
- --7906180752 Forwards IE Insp Repts 50-413/79-05 % 50-414//9-05 on 790313-16 % notice of violation MURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/13 2pp
- ---790618075B Notice of violation from insp on 790313-16
  \* Region 2. Atlanta, Office of the Director 79/04/13 ip
- --7906180764 IE Insp Repts 50-413/79-05 & 50-414/79-05 on 790313-16
  Noncompliance noted deficiency in welder qualification maint
  records & infraction re containment spray heat exchanger
  storage requirements
  MCPARANDLO R GOUGE, M J Region 2. Atlanta, Office of the
  Director HERDT, A R Region 2. Atlanta, Reactor Construction &
  Engineering Support Branch 79/04/13 7pp
- 7906290475 Forwards revised cover sheet for IE Insp Repts 80.41/1/79-07 & 30-414/79-07 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/05 2pp

## DOCKET 50-414 CATAMBA NUCLEAR STATION, UNIT 2

- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 53 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 BANDERS: F D Duke Power Ca 79/06/08 5pp.
- 9 Inspection reports, IE Bulletins & correspondence
- 7906:30439 Responds to IE Bulletin 79-03 Site has received 310 ft of gipe mfg by Youngstown Welding & Engineering Co Pipe will receive field hydrostatic test
  DAILL C Dute Power Co 79/04/20 2pp
- 7906020154 Responds to IE Bulletin 79-04 Design of facility has been reviewed No Velan valves in use DAIL.L C Duke Power Co 79/04/24 1p
- 7906230446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

  O'REILLY.J P Region 2, Atlanta, Office of the Director 79/05/10 10
- 7905180734 Ack receipt of 790507 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-413/79-05 & 50-414/79-05 MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/15 ip
- --7905180741 Responds to NRC 790413 ltr re violations noted in IE Insp. Repts S0-413/79-05 & 50-414/79-05. Corrective actions. nitrogen blanket placed on heat exchanger & personnel instructed re nonconforming item rept DAIL, L C Duke Power Co 79/05/07. 1p
- --7906180752 Forwards IE Insp Repts 30-413/79-05 & 50-414/79-05 on 790313-16 & notice of violation HURPHY.C E Repion 2. Atlanta, Reactor Construction & Engineering Support Branch, 79/04/13, 2pp.

- --7906180758 Notice of violation from Ensp on 790313-16
  \* Region 2, Atlanta, Office of the Director 79/04/13 to
- --7906180764 IE Insp Repts 50-413/79-05 & 50-414/79-05 on 790313-16
  Noncompliance noted deficiency in welder qualification maint
  records & infraction re containment spray heat exchanger
  storage requirements
  MCFARLAND.C R . GOUGE.M J Region 2, Atlanta, Office of the
  Director HERDT, A R Region 2, Atlanta, Reactor Construction &
  Engineering Support Branch 79/04/13 7pp
- 7906290475 Forwards revised cover sheet for IE Insp Repts 50-413/79-07 & 50-414/79-07 MURPHY,C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/06/05 2pp

### DOCKET 50-416 GRAND GULF NUCLEAR STATION, UNIT 1

### A Application/construction stage documents & correspondence

- 7706120327 Responds to 780811 ltr Discusses mods to reactor protection sys power supplies.per conceptual design submitted Bept 1978 by GE DALE.L F Mississippi Power & Light Co 79/05/27 ip
- 7906120355 Responds to 790627 itr Forwards Affidavit of Svc for distribution of Amend 30 DALE,L F Mississippi Power & Light Co 79/06/04 2pp
- 7906120233 Forwards "Summary of Environ Protection Program re Const of Grant Gulf Nuclear Station" for six months ending 790430 MCGAUGHY, J.P. Mississippi Pawer & Light Co. 79/06/06 ip
- --7906120256 "Bummary of Environ Protection Program re Const of Grand Guif Nuclear Station" for six months ending 790430 \* Mississippi Power & Light Co 79/06/06 3pp

### G Adjudicatory correspondence

7906220378 Requests denial of intervenor Municipal Energy Agency of MS 790529 petition to show cause Util & affiliate Middle South Energy.Inc have complied w/license conditions of CP CONNER.T B Conner, Moore & Corber 79/06/19 6pp

### M Antitrust correspondence

- 7904040201 Municipal Energy Agency of MS requests commencement of proceedings to require util to comply w/CP license conditions re interconnect agreement Related correspondence w/DDJ encl MCDIARMID.R C Spiegel & McDiarmid 79/05/29 150pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906070099 Forwards IE Insp Repts 50-416/79-03 & 50-417/79-03 on 790227-0301 No noncompliance noted BUTHERLAND.J F Region 2. Atlanta, Fuel Facility & Materials Safety Branch 79/03/29 2pp
- --7906070104 IE Insp Repts 50-416/79-03 & 50-417/79-03 on 790227-0301 No noncompliance noted Major areas inspected administrative & mgt control.groundwater hydrology.site erosion & runoff & review of monthly quarterly repts
  HUFHAH.J W Region 2, Atlanta, Fuel Facility & Materials Safety Branch CUNNINGHAM.A L Region 2, Atlanta, Office of the Director 79/03/28 App
- 7906140649 Forwards IE Insp Repts 50-416/79-04 \$ 50-417/79-04 on 790301-02 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 2pp
- --7906140654 IE Insp Repts 50-416/79-04 & 50-417/79-04 on 790301-02 No noncompliance noted Major areas inspected electrical control panel cable terminations, storage & laydown areas & GA program implementation RAUSCH, J K , HEROT, A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 4pp
- 7906210073 Forwards IE Insp Rept 50-416/79-06 & 50-417/79-06 on 790327-29. No noncompliance noted.
  MCRPHY C E Region 2. Atlanta, Reactor Operations Nuclear Support Branch 79/04/11 2pp.

- --7906210078 IE Insp Rept 50-416/79-06 & 50-417/79-06 on 790327-29 No noncompliance noted Major areas inspected GA program implementation, storage & laydown areas, turbine bldg roof, cable tray supports, concrete testing & snubber operation RAUSCH.JK Region 2. Atlanta. Office of the Director HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/11 Spp
- 7906050127 Ack receipt of IE Insp Repts 50-416/79-05 % 50-417/79-05 on 790306-09 No proprietary info MCGAUGHY, J P Mississippi Power & Light Co 79/04/23 1p
- --7906050133 Forwards IE Insp Repts 50-416/79-05 % 90-417/79-05 on 790306-09 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/03 2pp
- ---7906050140 IE Insp Repts 50-416/79-05 & 50-417/79-05 on 790306-09 No noncompliance hoted Major areas inspected electrical components & sys.electrical cables & terminations, instrumentation & fire protection of the protection OIBBONS, T.D., RUFF, A.B. Region 2. Atlanta, Office of the Director ARYANT, J.C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 Spp
- 7906130144 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase "No written response required O'REILLY.J P Region 2, Atlanta, Office of the Director 79/05/02 ip
- 7906010190 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in 1E Insp Repts 50-416/79-02 \$ 50-417/79-02 MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/07 ip
- --7906010195 Forwards IE Insp Repts 50-416/79-02 & 50-417/79-02 on 790212-15 % notice of violation MURPHY:C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/22 2pp
- --7905010202 Notice of violation from insp on 790212-15
  4 Region 2, Atlanta, Office of the Director 79703/15 ip
- ---7906010205 IE Insp Repts 50-416/79-02 \$ 50-417/79-02 on 790212-15
  Noncompliance noted failure to follow procedure for control
  of weld filler metal
  YANDORN.P K , CONLON.T F Region 2, Atlanta, Office of the
  Director 79/03/15 Spp
- 7906260563 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  D'REILLY, J P Region 2, Atlanta, Office of the Director 79/09/10, in
- 7906220462 Responds to IE Bulletins 78-12,12A & 12B re reactor pressure vessel welds No discrepancies noted COHN.W C General Electric Co 79/05/11 3pp
- 7906290773 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME 8A-312 Type 304 Stathless Steel Piping " No such piping purchased from Youngstown Welding & Engineering Co DALE, L F Mississippi Pawer & Light Co 79/05/16 ip
- 7906230023 Ack receipt of TE Insp Repts 50-416/79-06 & 50-417/79-06 on 790327-29 No proprietary info
  MCGAUGHY, J P Mississippi Power & Light Co 79/05/22 ip
- 7906220467 Responds to IE Bulletins 78-12, 12A & 128 re reactor pressure versel wolds No archive wold matts available for verification purposes DALEAL F Mississippi Power & Light Co 79/05/25 ip
- 8 Reportable occurrences. LERs & related correspondence
- 7906200468 Submits interim deficiency rept re 4-inch std long radius 90 degree slbows Caused by mfg error Matl having carbon content greater than specified was identified w/low carbon steel number. Will issue final rept by 790825

  DALE-L F Mississippi Power & Light Co 79/05/21 ip
- 7706140365 Requests delay until 770713 to determine reportability of possible deficiency re failure of switch assembly in 4.16 kV switchgear DALE.M F Mississippi Power & Light Co 77/05/29 1p

- 7906140403 Submits Interim Rept 2 of potential Reportable Deficiency 79-05 improper drawings supplied by GE All termination cabinet gamels at site are being reviewed against as-shipped drawings Final rept to be submitted 790431 DALE/L F Mississippi Power & Light Co 79/05/29 lp
- 7906140437 Submits Interim Rept 2 of potential Reportable Deficiency 79/04 inadequate crimping found in power generation control complex interconnecting cables Final rept will be submitted on 79:115

  DALE: LF Mississippi Power & Light Co 79/05/29 19
- 7906140429 Submits Interim Rept 2 for deficiency re failure by GE to establish 1/2 implement approved OA program for electrical work performed Upgraded OA manual approved Final capt by 790905

  DALE-L F Mississippi Power & Light Co 79/06/01 ip
- 7706270219 Interim deficiency rept failure of several solid state devices, part of low voltage power circuit breakers Will complete imap 5 submit final rept by 791031 DALE-L F Mississippi Power 5 Light Co 79/06/18 1p

DOCKET 50-417 GRAND GULF NUCLEAR STATION, UNIT 2

A Application/construction stage documents & correspondence

- 7906120355 Respands to 790627 ltr Forwards Affidavit of Svc for distribution of Amend 30 DALE.E F Mississippi Power & Light Co 79/06/04 2pp
- 7906120253 Forwards "Summary of Environ Protection Program re Const of Grant Gulf Nuclear Station" for six months ending 790430 MCGAUGHY, J.P. Mississippi Power & Light Co. 79/06/06. Ip
- --7906120256 "Summary of Environ Protection Program re Const of Grand Gulf Nuclear Station" for six months ending 790430 \* Mississippi Power & Light Co 79/06/06 3pp
- G Adjudicatory correspondence
- 790622037B Requests denial of intervenor Municipal Energy Agency of MS 79052P petition to show cause Util & affiliate Middle South Energy, Inc have compised w/license conductions of CP CONNER, T B Conner, Moore & Corber 79/06/19 App
- M Antitrust correspondence
- 7706040201 Municipal Energy Agency of MS requests commencement of proceedings to require util to comply w/2P license conditions re interconnect agreement Related correspondence w/DOJ enc!
  MCDLARMIDLR C Spiecel & McDlarmid 79/05/29 15000
- @ Inspection reports, IE Bulletins & correspondence
- 7904070099 Forwards IE Insp Repts 50-416/79-03 & 50-417/79-03 on 790227-0301 No noncompliance noted SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Bafety Branch 79/03/29 2pp
- ---7906070104 IE Insp Repts 5D-416/79-03 & 50-417/79-03 on 790227-0301 No noncompliance noted Major areas inspected administrative & mgt control, groundwater hydrology, site erosion & runoff & review of monthly quarterly repts
  HUFHAM, J W Region 2, Atlanta, Fuel Facility & Materials Safety
  Branch CUNNINGHAM, A L Region 2, Atlanta, Office of the Director 79/03/28 App
  - panel cable terminations, storage & laydown areas & GA program implementation RAUSCH.J K. HERDT, A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 4pp
- 7906210073 Forwards IE Insp Rept 50-416/79-06 & 50-417/79-06 on 790327-29 No noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Operations Nuclear Support Branch 79/04/11 2pp,

- ---7906210078 IE Insp Rept 50-416/79-06 & 50-417/79-06 on 790327-29 No noncompliance noted Major areas inspected GA program implementation, storage & laudoum areas, turbine bidg roof, cable tray supports, concrete testing & snubber operation RAUSCH, J K Region 2. Atlanta, Office of the Director HERDIAR Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/11 5pp
- /904030127 Ack receipt of IE lnsp Repts 50-414/79-05 & 50-417/79-05 on 790306-09 No proprietary info MCGAUGHY, J P Mississipp; Power & Light Co 79/04/23 Ip
- --7906050133 Forwards IE Insp Repts 50-416/79-05 % 50-417/79-05 on 790306-09 Mo noncompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 2pp
- --7906050140 IE Insp Repts 50-416/79-05 & 50-417/79-05 on 790306-09 No noncompliance noted Major areas inspected electrical components & sys. electrical cables & terminations, instrumentation & fire protection GIBBONS, T D , RUFF, A B Region 2, Atlanta, Office of the Director BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/03 5pp
- 7906130144 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/05/02 ip
- 7906010190 Ack receipt of 790423 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-416/79-02 & 50-417/79-02 MRRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/07 ip
- --7906010195 Forwards IE Insp Repts 50-416/79-02 % 50-417/79-02 an 790212-15 % notice of violation MURPHY.C E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 79/03/22 2pp
- --7906010202 Notice of violation from insp on 790212-15 \* Region 2, Atlanta, Office of the Director 79/03/15 1p
- --7906010205 IE Insp Repts 50-416/79-02 & 50-417/79-02 on 790212-15
  Noncompliance noted failure to follow procedure for control
  of weld riller metal
  VANDOGRN,P K. CONLON,T F Region 2. Atlanta, Office of the
  Director 79/03/15 Spp
- 7906260563 Forwards IE (nfo Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 1p
- 7906290773 Responds to IE Bulletin 79-03, "Longitudinal Weld Defects in ASME SA-312 Type 304 Stainless Steel Piping " No such piping purchased from Yaungstown Welding & Engineering Ca BALE, L F Hississippi Power & Light Co 79/05/16 ip
- 7906230023 Ack receipt of IE Insp Repts 50-416/79-06 & 50-417/79-06 on 790327-29 No proprietary info MCGAUGNY, J P Mississippi Power & Light Co 79/05/22 1p
- 7906220467 Responds to IE Bulletins 78-12.12A & 12B re reactor pressure vessel welds No archive weld matls available for verification purposes
  DALE.L F Hississippi Power & Light Co 79/05/25 1p
- S Reportable occurrences, LERs & related correspondence
- 7908200468 Submits interim deficiency rept re 4-inch std long radius 90 degree albows Caused by mfg error Matl having carbon content greater than specified was identified w/low carbon steel number Will issue final rept by 790825

  DALE, L F Mississippi Power & Light Co 79/05/21 1p
- 7906140365 Requests delay until 790713 to determine reportability of possible deficiency re failure of switch assembly in 4 16 kV switchgear DALE.H F firstissippi Power & Light Co. 79/05/29 1p
- 7906140437 Submits Interim Rept 2 of potential Reportable Deficiency 79/04 inadequate crimping found in power generation combrol complex interconnecting cables Final rept will be submitted on 791115

  DALE, L.F. Mississippi Power & Light Co. 79/05/29, 10

- 7906140429 Submits Interim Rept 2 for deficiency re failure by GE to establish & implement approved GA program for electrical work performed Upgraded GA manual approved Final rept by 790905
  DALEL F Mississippi Power & Light Co 79/06/01 1p
- 790A270219 Interim deficiency rept failure of several solid state devices, part of low voltage power circuit breakers Will complete insp & submit final rept by 791031 DALE.L.F. Mississippi Power & Light Co 79/06/18 Ip
- DOCKET 50-423 MILLSTONE NUCLEAR POWER STATION, UNIT 3

  A Application/construction stage documents & correspondence
- 7904180135 Natification of 790515 meeting w/util in Bethesda,MD to discuss newly-reported fault
  DROMERICK.K A Light Water Reactors Branch 3 79/05/07 2pp
- 7904290636 Summary of 790515 meeting w/util & S&W in Dethesda.HD re bedrock fault in foundation areas JACKSON.R E Geosciences Branch 79/05/25 7pp
- I Financial information
- 7906200374 Forwards annual financial repts for owner-licensees O'CONNOR, L A Northeast Utilities 79/06/15 3pp
- --7906200375 Annual Financial Rept 1978

  \* Western Massachusetts Electric Co 79/12/31 17pp
- --7906200376 Annual Financial Rept 1978 \* Hartford Electric Light Co. 79/12/31 21pp
- ---7906200377 Annual Financial Rept 1978 \* Connecticut Light & Power Co 79/12/31 21pp
- J Insurance & indemnity information
- 7906190293 Forwards Endorsements 54 & 55 to MAELU Policy MF-52 CONNELL.T Northeast Nuclear Energy Co (Northeast Utilities) 79/06/12 3pp
- 7906270241 Forwards Endorsements 59 % 60 to NELIA Policy NF-173 SEGER:R M Northeast Nuclear Energy Co (Northeast Utilities) 79/06/21 3pp
- 790428009i Forwards Endorsements 79 & 60 to ANI Policy NF-173 SEGER.R.M Northeast Utilities 79/06/21 ip
- Q Inspection reports. IE Bulletins & correspondence
- 7906180397 Forwards IE Info Notice 79-10. "Noncomforming Pipe Support Struts " No written response necessary GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/16 ip
- 7906i10019 Forwards IE Bullstin 79-058, "Nuclear Incident at TMI-Suppl "No written response required ORIER, B H Region 1, Philadelphia, Office of the Director 79/04/23 ip
- 7906120176 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER,B H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 7906260124 Forwards IF Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  ORIER, B H Region 1, Philadelphia, Office of the Director 79/05/11 1p
- 7906290724 Responds to IF Bulletin 79-03 No welded pipe supplied by Youngstown Welding & Engineering in use or planned for use. COUNBIL. W.O Northeast Utilities 79/05/15 2pp
- DOCKET 30-424 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7906130327 Notifies that final rept re embed assemblies, originally scheduled for submittal by 790601, will be delayed until 790801 EHRENBERGER, W Georgia Power Co 79/06/01 1p

- F Security, medical, emergency & fire protection plans
- 7906050297 Forwards fire hazaids analysis Includes re-evaluation of other fire protection sys.as requested in 780930 ltr EHRENSPERGER.W Georgia Power Co 79/09/24 ip
- --7906050300 Fire hazards analysis \* Georgia Power Co 79/06/01 779pp
- O Adjudicatory correspondence
- 7906260278 Ack receipt of Georgians Against Nuclear Energy petition requesting reconsideration of 790413 denial of earlier Georgians Against Nuclear Energy petition Forwards FR notice DENTON-H R Office of Nuclear Reactor Regulation 79/06/06 ip
- --7906260282 Notice of receipt % availability of 790501 petition from Georgians Against Nuclear Energy requesting reconsideration of denial of earlier Georgians Against Nuclear Energy petition
  DENTON.H R Office of Nuclear Reactor Regulation 79/04/06 1p
- 7906280097 Forwards Georgians Against Nuclear Energy 790501 petition for reconsideration of request for suspension of CP FR notice encl
  DENTON: H R Office of Nuclear Reactor Regulation 79/06/06 2pp
- H General correspondence
- 7906060284 Requests revision to distribution list for CPPR-108 & CPPR-109 EHRENSPERGER, W. Georgia Power Co. 79/05/30 2pp
- Q Inspection reports. IE Bulletins & correspondence
- 7906180077 Ack receipt of IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790306-08 No proprietary info STAFFA,R W Georgia Power Co 79/04/25 ip
- --7906180070 Forwards IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790306-08 No noncompliance noted NURPHY,C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7905180098 IE Than Repts 50-424/79-04 & 30-425/79-04 on 790306-08 No noncompliance noted Major areas inspected 10CFR30 55(s) items previous inap findings.water quality QC inspector training & steel fabrication shop mat control HUNT.M D Region 2. Atlanta. Office of the Director HERDT.A R Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/30 4pp
- 7906140230 Responds to IE Bullstin 79-03 Submits info re pipe spools used in fabrication of piping subassemblies STAFFA.R W Georgia Power Co 79/05/09 2pp
- 7906250455 Forwards 1E Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 | Ip
- DOCKET 50-425 ALVIN W VOOTLE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7906130327 Notifies that final rept re embed assemblies, originally scheduled for submittal by 790601. will be delayed until 790801 EHRENBPERGER.W Georgia Power Co 79/06/01. 1p
- F Security, medical, emergency & fire protection plans
- 7906050297 Forwards fire hazards analysis Includes re-evaluation of other fire protection systes requested in 780930 ltr EHRENSPERGER.W Georgia Power Co 79/05/24 ip
- ---7906050300 Fire hazards analysis \* Georgia Power Co 79/06/01 779pp

### G Adjudicatory correspondence

- 7906260270 Ack receipt of Georgians Against Nuclear Energy petition requesting reconsideration of 790413 denial of earlier Georgians Against Nuclear Energy petition Forwards FR notice DENTON, H.R. Office of Nuclear Reactor Regulation 79/06/06 19
- --7906260282 Notice of receipt & availability of 790501 petition from Georgiams Against Nuclear Energy requesting reconsideration of denial of earlier Georgians Against Nuclear Energy petition
  - DENTON, H R Office of Nuclear Reactor Regulation 79/06/06 1p
- 7906280097 Forwards Georgians Against Nuclear Energy 790501 petition for reconsideration of request for suspension of CP FR notice encl
  DENTON: it R Office of Nuclear Reactor Regulation 79/06/06 2pp
- H General correspondence
- 7906060284 Requests revision to distribution list for CPPR-108 & CPPR-109 EHRENSPERGER.W Georgia Power Co 79/05/30 2pp
- 3 Inspection reports. IE Bulletins & correspondence
- 7906180077 Ack receipt of IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790306-08 No proprietary info STAFFA,R W Georgia Power Co 79/04/25 ip
- --7906180090 Forwards IE Insp Repts 50-424/79-04 & 50-425/79-04 on 790306-08 No noncompliance nated MURPHY.C E Region 2: Atlanta: Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906180098 IE insp Repts 30-424/79-04 & 50-425/79-04 on 790306-08 No noncompliance noted Major areas inspected 100FRSO 55(e) items previous insp findings, water quality GC inspector training & steel fabrication shop mati control HUNT.M D Region 2, Atlanta, Office of the Director HERDT.A R Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/30 4pp
- 7906140230 Responds to IE Bulletin 79-03 Bubmits info re pipe spools used in fabrication of piping subassemblies STAFFA.R W Georgia Power Go 79/05/09 2pp
- 7906290455 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " D'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/10 ip
- DOCKEY 50-433 UC-SANTA BARBARA RESEARCH REACTOR

  F Security, medical, emergency & fire protection plans
- 7906200344 Forwards rept on alterations to reactor facility Physical security plan being revised to reflect rept Rept withheld (ref iOCFR2 790)
  RROEG,R J. California, Univ of, Santa Sarbara 79/06/15 ip
- J Insurance & indemnity information
- 7906260375 Forwards executed Amend 8 to Indemnity Agreement E-16, Amend 4 to Indemnity Agreement E-58/Amend 8 to Indemnity Agreement E-53 & Amend 13 to Indemnity Agreement E-15 DENESS, 8 J California, Univ of, Berkeley 79/06/21 5pp
- @ Inspection reports: IE Bulletins & correspondence
- 7906180459 Forwards IE Info Notice 79—12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN.R H, Region 5, San Francisco. Office of the Director 79/05/10. 1a
- 7906080237 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5. San Francisco. Office of the Director.

- DOCKET 50-434 SURRY POWER STATION, UNIT 3
  U Congressional/Executive Correspondence
- 7906110367 Act receipt of VA congressional delegation 790317 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific consideration for setsmic events HENDRIE, J M Commission 79/05/21 2pp
- --790611037B Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic eyents HENDRIE.J M Commission 79/05/21 2pp
- --7906110380 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses sito-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --79061103B2 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reamalyses Discusses site-specific considerations for seismic events HENDRIE, J H Commission 79/05/21 2pp
- --7906110385 Ack receipt of VA congressional delegation 790319 itr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for sensmic events HENDRIE, J H. Commission 79/05/21 2pp
- --7906i10387 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906110390 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J K Commission 79/09/21 2pp
- --790&i10394 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalysas Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110397 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selsmic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110400 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110408 Forwards draft of proposed responses to 790319 1tr from 10 VA congressional delegates re pipe stress analysis at facility
  DENTON:H R Office of Nuclear Reactor Regulation 79/05/01 3pp
- --7906110411 Requests expedited review of piping stress reanalyses, independent from review of other three plants shut down for seismic-related issues BUTLER.C.H. DANIEL.R.H. HARRIS.H.E. House of Rep. 77/03/17
- DOCKET 50-435 SURRY POWER STATION, UNIT 4
  U Congressional/Executive Correspondence
- 7906110367 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific consideration for selsmic events HENDRIE.J M Commission 79/05/21 2pp
- ---7906110378 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for selsmic events HENDRIE, J M Commission 79/05/21 2pp

- --7906110380 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reamalyses Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --79061103B2 Ack receipt of VA congressional delegation 790319 itr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- ---7906110389 Act receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/03/21 2pp
- --7906110387 Ack receipt of VA congressional delegation 790319 itr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906110390 Ack receipt of VA congressional delegation 790319 itr re shutdown of facilities Steps have been taken re review of pipe stress reamalyses Discusses site-specific considerations for seismic events HENDRIE.J M Commission 79/05/21 2pp
- --7906110394 Ack receipt of VA Congressional delegation 790319 ltr re shutdown of faculities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/05/21 2pp
- --7906110397 Ack receipt of VA congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic eyents HENDRIE, J M Commission 79/05/21 2pp
- --7905110400 Ack receipt of VA Congressional delegation 790319 ltr re shutdown of facilities Steps have been taken re review of pipe stress reanalyses Discusses site-specific considerations for seismic events HENDRIE, J M Commission 79/03/21 2pp
- --7906i10408 Forwards for approval, draft of proposed responses to 7903i9 ltr from 10 VA Congressional delegates re pipe stress analysis at facility DENTON.H R Office of Nuclear Reactor Regulation 79/05/01 Spp

### DOCKET STN-50-437 FLOATING NUCLEAR PLANT

- A Application/construction stage documents & correspondence
- 7812050284 Submits statement on actions re recommendations made by US Comptroller General in rept "Before Licensing Floating Nuc Pur Plants, Many Answers are Needed." Forwards NRC Staff responses, related correspondence & NUREO repts W/encl GOSBICKIL V Office of the Executive Director for Operations 78/11/24 23pp
- 7904050314 Forwards suppl to SER up to & including Amend 26 & fire protection evaluation rept, Revision C Fire protection program meets std of General Design Criterion 3 HANAUER, B H Assistant Director for Plant Systems 79/03/19 3pp
- 7906280063 Submits ACRS consustant 790416 rept on containment shell buckling criteria
  BAER.R L Light Water Reactors Branch 2 79/09/23 12pp
- 7906290199 Notification of 790608 meeting w/util in Bethesda.HD to discuss add! info re core-debris distribution.mechanisms for dispersion b related dose calculation HAUPT.C A Environmental Projects Branch 1 79/08/29 is
- 7906110171 Forwards Revision 1 to 790517 core ladle rept (OPS Rept 36A57) HAGA:P B Offshore Power Systems (subs of Westinghouse Electric Corp ) 79/06/06 ip
- ---7906110173 Revision 1 to 790317 core lagle rept (QPS Rept 36A39)

  \* Northern Indiana Public Service Co 36A39 79/06/06 35pp
- 7906:80446 Ack receipt of NRC 7905:17 rept of 790507-08 meeting. Rept 36A59 & PDR Amend 27 contain definitive criteria for reverine & estuarine sites HAGALP B obsolete code... 79/06/Q6 ip

- 790626000P Confirms results of 790613 meeting re NRC licensing review Lists remaining action items HAQA.P B obsolete code 79/06/20 3pp
- © Adjudicatory correspondence
- 7906040410 Motion to establish schedule for filling of partial proposed findings of fact & conclusions of law Proposed schedule & Certificate of Svc encl
  COMAN, B Z , DOUGHERY, T M , KENDRICK, J R Offshore Power Systems
  (subs of Westinghouse Electric Corp ) 79/04/04 3pp
- 7906080136 Responds to ASLB 790404 inquiry re submittal of proposed findings of fact % conclusions of law Atlantic County,NJ will submit findings State of NJ has not made final decision Certificate of SVC encl
  KENRICK,JR Eckert, Seamans, Cherin & Mellott 79/04/12 4pp
- 7906230178 Reviews relevance of St Lucie investigative rept transmitted 790411 Rept prepared per NRC 771108 order REIS.E J Branch 3 79/05/02 2pp
- 7706250259 Advises that NRC members involved in responding to board questions contained in 790329 ltr have completed TMF assignments written responses will be transmitted on or before 770521 SOMINKI, S.M. Branch 3 79/05/02 Ip
- 7906220180 Denies NRDC 790216 motion for summary disposition of licensee FES for may of floating nuclear plants No genuine issue as to any matl fact Grants cross-motions for summary disposition by applicant % NRC HOLFE, S J Acomic Safety and Licensing Appeal Panel 77/05/25 iino
- Q Inspection reports. [F Bulletins & correspondence
- 7906290809 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/04/16 1p
- 7906250386 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GREILLY, J P Region 2. Atlanta, Office of the Pirector 79/05/10 ip
- U Congressional/Executive Correspondence
- 7906260109 Responds to 790404 ltr which forwarded KT Bridges 790312 ltr re floating nuclear power plants Forwards EIS of floating power plants indicating no unacceptable impact on marine biota or man W/o encl ODSBICKL V Office of the Executive Director for Operations 79/05/14 3pp

DOCKET 50-438 BELLEFONTE NUCLEAR PLANT, UNIT 1

A Application/

- --7906140645 IE Insp Repts 50-438/79-04 & 50-439/79-04 on 790312-15 No noncompliance noted Major areas inspected const status of intain structures & canals & site audit program WRIGHT.R W , HERDIAR Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 6pp
- 7906250352 Forwards IE Insp Repts 50-438/79-06 & 50-439/79-06 on 790403-06 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Bupport Branch 79704/24 2pp
- --7906250355 IE Insp Rept 50-438/79-06 & 50-439/79-06 on 790403-06 No noncompliance moted Major areas inspected structural steel structures & supports & Unit 2 containment liner plate, including review of work observation & qualify records BRYANT, J C, VALLISH, E J Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 ip
- 7905210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned for use in safety-related sys Effort in progress to locate any ASME SA-312 Type 304 piping supplied by Youngstown Welding & Engineering Co OILLELAND, J E Tennessee Valley Authority 79/03/14 19
- 7906220169 Ack receipt of 790308 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/79-05 & 50-439/79-05 MVRPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/14 Ip
- --7906220185 Responds to NRC 790412 ltr re violations noted in IE Insp Repts 50-438/79-05 & 50-439/79-05 Corrective actions informed by Prairie Tank of certified tests rept & removal of personnel qualification records OILLELAND, J E Tennessee Valley Authority 79/05/08 2pp
- --7906220234 Forwards IE Insp Repts 50-438/79-05 % 50-439/79-05 on 790327-30 % notice of violation HURPHY,C E Region 2. Atlanta, Office of the Director 79704/12 2pp
- ---7906220239 Notice of violation from insp on 790327-30
  \* Region 2: Atlanta, Office of the Director 79/04/12 ip
- --7906220242 IE Insp Repts 50-438/79-05 & 50-439/79-05 on 790327-30 Noncompliance noted missing welding filler metal certificate & inspector qualification records VANDORN,P K Region 2. Atlanta, Reactor Operations Nuclear Support Branch CONLON,T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/12 7pp
- S Reportable occurrences. LERs & related correspondence
- 7906140420 Forwards deficiency rept re blown fuses in low voltage switchgear GILLELAND. J E Tennessee Valley Authority 79/05/25 1p
- --7906140423 First interim deficiency rept blown fuses in low voltage switchgear Cause unknown, Util informed Westinghouse & requested investigation of problem 
  \* Tennessee Valley Authority 79/05/25 ip
- 7906130221 Provides first interim rept re seismic response for primary branch lines which may not be conservative Expects to submit next rept by 790727 GILLELAND. J E Tennessee Valley Authority 79/06/07 2pp

- Q Inspection reports. IE Bulletins & correspondence
- 7906150034 Forwards IE Insp Repts 50-438/79-03 % 50-439/79-03 on 790220-23 No moncompliance moted MURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/27 2pp
- --7706150039 IE Insp Repts 50-438/79-03 % 50-439/79-03 on 770220-23 No noncompliance noted Major areas inspected quality records % observation of work on reactor coolant pressure boundary piping BLAKE, J J. KLEINSCROE, H P. CONLON, T E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/26 5pp
- 7706140641 Forwards 1E Insp Repts 50-43B/79-04 & 50-439/79-04 on 790312-15 No noncompliance noted MURPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/30 2pp
- --7906140645 IE Insp Repts 50-433/79-04 \$ 50-439/79-04 on 790312-15 No noncompliance noted Major areas inspected const status of intake structures & canals & site audit program WRIGHT,R W., HERDT,A.R. Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/23 6pp
- 7906250352 Forwards IE Insp Repts 50-438/79-06 % 50-439/79-06 on 790403-06 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/24 2pp
- --7906250355 IE Insp Rept 50-438/79-06 & 50-439/79-06 on 790403-06 No noncompliance noted Major areas inspected structural steel structures & supports & Unit 2 containment liner plate, including review of work observation & qualifty records BRYANT.J C, VALLISH.E J Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/23 ip
- 7906210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME 8A-312. Type 304 piping supplied by Youngstown Helding & Engineering OILLELAND, J E Tennessee Valley Authority 79/08/14 1p
- 7906220169 Ack receipt of 790508 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-438/79-05 \$ 50-439/79-05 HURPHY, C E Region 2, Atlanta, Reactor Construction \$ Engineering Support Branch 79/05/14 ip
- --7906220183 Responds to NRC 790412 itr re violations noted in IE Insp Repts 50-438/79-05 & 50-439/79-05 Corrective actions informed by Prairie Tank of certified tests rept & removal of personnel gualification records OILLELAND, J E Tennessee Valley Authority 79/05/08 2pp
- --7906220234 Forwards IE Insp Repts 50-438/79-05 & 50-439/79-05 on 790327-30 & notice of violation HURPHY.C E Region 2, Atlanta, Office of the Director 79/04/12 2pp
- --790622023B Notice of violation from insp on 790327-30
   Region 2. Atlanta. Office of the Director 79/04/12 ip
- --790&220242 IE Insp Repts 50-438/79-05 & 50-439/79-05 on 790327-30 Noncompliance noted missing wolding filler metal certificate & inspector qualification records vANDORN.P K Region 2. Atlanta, Reactor Operations Nuclear Support Branch CONLON,T E Region 2, Atlanta. Reactor Construction & Engineering Support Branch 79/04/12 7pp
- S Reportable occurrences, LERs & related correspondence
- 7906140420 Forwards deficiency rept re blown fuses in low voltage switchgear QILLELAND, J. E. Tennessee Valley Authority 79/05/25 ip
- --7906140423 First interim deficiency rept blown fuses in low voltage switchgear Cause unknown Util informed Westinghouse & raquested investigation of problem \* Tennessee Valley Authority 77/05/25 ip
- 7905130221 Provides first interim rapt re seismic response for primary branch lines which may not be conservative Expects to submit next rept by 790727.

  OILLELAND. J E Tennessee Valley Authority 79/06/07 2pp
- 7906280279 Forwards final interim deficiency rept re pipes embadded in structural concrete GILLELAND.JE Tennesses Valley Authority 79/06/15 ip

- --7706250281 Final interim deficiency rept pipes embedded in structural concrete Review confirmed that no conduit.pipe size or spacing violation impaired structural integrity

  \* Tennessee Valley Authority 79/06/15 Zpp
- 7906280113 Forwards final deficiency rept re failure of cadweld sister splice rebar to meet ASTM A613 strength requirements CILLELAND. J E Tennessee Valley Authority 79/06/22 2pp
- --7906280114 Final deficiency rept failure of cadweld sister splice rebar to meet ASTM A615 strength requirements Rebar in failed splices is not representative of rebar used in permament structure

  \* Tennessee Valley Authority 79/06/22 1p

### DOCKET 50-440 PERRY NUCLEAR POWER PLANT, UNIT 1

### M Antitrust correspondence

- 7906220266 Notifies that certain documents were removed from ASLAB secretary's desk by unauthorized person Ducuments found in another of Investigation initiated DUFLO, M E Atomic Bafety and Licensing Appeal Panel 78/10/02
- --7706220270 Forwards ASLAB memo issued in Davis-Besse & Perry proceeding re missing papers in ofc ROSENTHALLAS Atomic Safety and Licensing Appeal Panel 78/10/03 to
- --7906220277 Forwards 781107 rept, "Investigation of Unauthorized Removal of ASLAB Documents" Rept withheld (ref FOIA Exemptions 7A & 7E)
  CUMMINOS.J J Office of Inspector & Auditor 78/11/10 ip
- --790&220285 Provides info re limited inquiring in lass or theft of ASLAB sensitive documents Info partly withheld due to enforcement proceedings (ref FDIA Exemptions 7A & 7E) ATWELL.T L Division of Security 78/10/05 2pp
- --7906220302 Provides summary of investigation into alleged removal of documents from ABLAB ofcs Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 74 & 7E) ABSTON.O O Office of Inspector & Auditor 78/11/07 4pp
- --7906220320 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FDIA Exemption 7A) ROSENTHAL-A & Atomic Safety and Licensing Appeal Panel 78/11/08 2pp
- --7906220336 Responds to 781107 memo re investigation of document removal Info partly withheld due to enforcement proceedings (ref FDIA Exemption 7A) BURCH-C L Division of Security 78/12/04 2pp
- --7906220349 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A & 7E) Forwards Washington Post 790128,0213 & 25 articles
  HURNEY,T F Office of Inspector & Auditor 79/02/28 7pp
- --7906220364 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FDIA Exemption 7E)
  CUMMINGB.J J Office of Inspector & Auditor 79/06/22 2pp
- O Inspection reports, IE Bulletins & correspondence
- 7906010333 Forwards IE Insp Repts 50-440/79-02 & 50-441/79-02 on 790313-16 No noncompliance noted FIORELLIO Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- --7906010336 IE Insp Repts 50-440/79-02 & 50-441/79-02 on 790313-16 No noncompilance noted Major areas inspected audit observations; review of Ernst-Comstock QA implementing procedures & quality records relative to civil activities HAKKINB,F C, HAYES,D W Region 3. Chicago. Office of the Director 79/04/02 lipp
- 7906070048 Responds to IE Bulletin 79-03 No ABME 8A-312 Types 304 & 316 piping used BAVIDSON, D R Cleveland Electric Illuminating Co 79/05/02 ip
- 7904120097 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required.

  KEPPLER. J G. Ragion 3. Chicago. Office of the Director. 79/05/07

- 7906190086 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"

  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906130090 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/22 ip
- 7906200101 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/29
- 8 Reportable occurrences, LERs & related correspondence
- 7906080757 Summarites status of evaluation of significant deficiency re 85M Constructors. Inc QA program Work on intake structures continuing; final rept delayed until 79083i DAVIDSON.D R Cleveland Electric Illuminating Co 79/05/29 ip

### DOCKET 50-441 PERRY NUCLEAR POWER PLANT, UNIT 2

- M Antitrust correspondence
- 7906220266 Notifies that certain documents were removed from ASLAD secretary's desk by unauthorized person Documents found in another ofc Investigation initiated DUFLO. H E Atomic Safety and Licensing Appeal Panel 78/10/02
- --7906220270 Forwards ASLAB memo issued in Davis-Besse & Perry proceeding re missing papers in ofc ROSENTHAL.A S Atomic Safety and Licensing Appeal Panel 78/10/03 ip
- --7906220277 Forwards 781107 rept. "Investigation of Unauthorized Removal of ASLAB Documents " Rept withheld (ref FQIA Exemptions 7A & 7E)
  CUMMINGS, J U Office of Inspector & Auditor 78/11/10 1p
- --7906220285 Provides info re limited inquiring in loss or theft of ASLAD sensitive documents Info partly withheld due to enforcement proceedings (ref FOLA Exemptions 7A & 7E) ATWELL.T L Division of Security 78/10/05, 2pp
- ---7906220302 Provides summary of investigation into alleged removal of documents from ASLAB afcs Info partly withheld due to enforcement proceedings (ref FOIA Exemptions 7A & 7E) ABSTON.O 0 Office of inspector & Auditor 78/11/07 4pp
- --7906220320 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) ROSENTHALLA & Atomic Safety and Licensing Appeal Panel 79/11/08 2pp
- --7906220336 Responds to 781107 memo re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) BURCH, C L Division of Security 78/12/04 2pp
- --7906220349 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A & 7E) Forwards Washington Post 790128, 0213 & 25 articles
  HURNEY.T F Office of Inspector & Auditor 79/02/28 7pp
- --7906220364 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7E)

  GUMMINGS.J.J. Office of Inspector & Auditor 79/06/22 2pp.
- Q. Inspection reports. IE Bulletins & correspondence
- 7906010333 Forwards IE Insp Repts 50-440/79-02 & 50-441/79-02 on 790313-16 No noncompliance noted FIORELLI.O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- ---7906010336 IE Insp Repts 50-440/79-02 & 50-441/79-02 on 790313-14 No noncompliance noted Major areas inspected audit observations; review of Ernst-Comstock QA implementing procedures & quality records relative to civil activities HAWKINS,F C, HAYES.D W Region 3, Chicago, Office of the Director. 79/04/02 11pp

- 7906070048 Responds to IE Bulletin 79-03 No ASME SA-312 Types 304 & 316 piping used

  DAVIDSON, D.R. Cleveland Electric Illuminating Co. 79/05/02 ip
- 7906120097 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/07
- 7906190086 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11
- 7906130090 Forwards IE Bulletin 79-il. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLERIJ G Region 3. Chicago. Office of the Director 79/05/22
- 7906200101 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Oyster Creak Reactor" KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/29
- S Reportable occurrences, LERs & related correspondence
- 7906080257 Summarizes status of evaluation of significant deficiency re S&M Constructors.Inc GA program Work on intake structures continuingsfinal rept delayed until 790831 DAVIDSON.D R Cleveland Electric Illuminating Co 79/05/29 ip
- DOCKET 50-443 SEABROOK NUCLEAR STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7906080282 Responds to NRC 790524 request Forwards matt Bangor Hydro-Electric Co filed under Amend 39 of license application.dtd 780515 Requests expedited antitrust review. in order to complete processing of new Amend 40 RITSHER, J A Ropes & Gray 79/05/29 4gp
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to SCINTO, J F Hearings Division 79/04/02 2pp
- --790&210040 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases

  CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906050034 Lists reasons for nonparticipation in seismic design proceedings Relates TMI incident to SBE studies by Public SVC Co of NH Forwards comments re fcility, presented to Commissioner DL Ray, but not allowed as evidence HEINHOLD, E H Affiliation Unknown 79/04/30 (2pp
- 7906050136 Forwards Seacmast Anti-Pallution League 790502 request for order to show cause re suspension or revocation of CPs BACKUS,R A O'Neil, Backus, Spielman 79705702 1p
- ---7906050138 Request by Seacoast Anti-Pollution League for order to show cause re suspension or revocation of CPs Certificate of Syc encl

- 7906010276 Suspends further consideration of alternative site issue, due to appeals court finding that cooling towers were not required
  DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/03/14
- 7905210095 NRC motion for summary disposition re radon issue was in error; ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/09/25
- H General correspondence
- 7906070065 Ack receipt of 790325 ltr to J Deutch of DDE re use of velocity caps Discusses capability of velocity caps to uithstand northeasters & other damaging storms DEYOUNG, R C Division of Site Safety & Environmental Analysis 79/04/14 4pp
- I Financial information
- 770&0.60246 Forwards Suppl i to Amené 40 H/supporting documentation. including financial qualifications of several utils re partial transfer of ownership RETSHER.J A Ropes & Gray 79/06/05 ip
- --7906060253 Forwards info re Suppl 1 to Amend 40 % request for partial transfer of CPPR-135 % CPPR-136 Forwards "Annual Financial Rept 1978" for utils MERRILL.D N Public Service Co of New Hampshire 79/06/01 /pp
- ---7906060236 "Annual Financial Rept 1978 " Supplemental info enci \* Central Vermont Public Service Corp 78/12/31 200pp
- ---7906060257 "Annual Financial Rept 1978 " Supplemental info encl \* Green Mountain Power Corp 78/12/31 100pp
- ~~7906060263 "Annual Financial Rept 1978 " Supplemental info encl \* Bangor Hydro-Electric Co 78/12/31 110pp
- --7906060267 "Annual Financial Rept 1978 " Supplemental info enci \* Central Maine Power Co 78/12/31 175pp
- --7906060268 "Annual Financial Rept 1978" Supplemental info encl \* Taunton Municipal Lighting Plant 78/12/31 84pp
- 7906190317 Forwards annual financial repts for each facility part-owner RITEHER, J A Ropes & Gray 79/06/18 2pp
- -7906190323 "Annual Financial Rept 1978 Northeast Utilities 78/12/31 4
- --7906190328 "Annual Financial Rept 1978 " HUEHMER:H Hudson Light & Power Dapt 78/12/31 55pp
- --7906190340 "Annual Financial Rept 1978 "
  \* Eastern Utilities Associates 78/12/31 40pp
- --7906190343 "Annual Financial Rept 1978 " \* Fitchburg Gas & Electric Light Co 78/12/31 20pp
- ---7906190346 "Annual Financial Rept 1978 "

  \* Vermont Electric Cooperative, Inc 78/12/31 24pp.
- ---7906190351 "Annual Financial Rept 1978 "
  \* Massachusetts Municipal Wholesele Co 78/12/31 40pp
- --7906190367 "Annual Financial Rept 1978 "
  # United Illuminating 78/12/31, 28pp
- --7906190374 "Annual Financial Rept 1978 "
  \* New England Cas & Electric Assoc 78/12/31, 34pp
- --7906190375 "Annual Financial Rept 1978 "
  \* Maine Public Service Co. 78/12/31 24pp
  - 7046190379 "Annual Financial Rept 1977-78 "
    Vermont Electric Power Co., Inc. 78/12/31 13pp
    - )344 Forwards annual financial repts for Public Syc Co of NH, New and Power Co & United Illuminating IER, J A Ropes & Gray 79/06/22 220pp

- --7906250381 "Annual Financial Rept 1977" & SEC Form 10-K
  \* Public Service Co of New Hampshire 77/12/31 58pp
- --7906250382 "Annual Financial Rept 1978 "
  # Public Service Co of New Hampshire 78/12/31 21pp
- ---7906250385 "Annual Financial Rept 1977" & SEC Form 10-K
  \* New England Power Co 78/12/31 43pp
- --7906250389 "Annual Financial Rept 1978" & SEC Form 10-K \* New England Power Co 78/12/31 45pp
- --7906250392 "Annual Financial Rept 1977" & SEC Form 10-K \* United Illuminating 77/12/31 62pp
- --7906250394 "Annual Financial Rept 1978" & SEC Form 10-K \* United Illuminating 78/12/31 51pp

### M Antitrust correspondence

- 7906290816 Discusses impact of Amend 40 to CP Dangor Hydro Electric will no longer be de minimus applicant Public Svc Co of NH should submit answer to Guestion 7 of App L, 10CFR50, on behalf of Bangor Hydro Electric TOALSTON, A Antitrust & Indemnity Group 79/05/24 1p
- Q Inspection reports, IE Bulletins & carrespondence
- 7906140574 Forwards IE Insp Rept 50-449/79-04 & 50-444/79-04 on 790312-13 No nencompliance noted CARLSON.R T Region i. Philadelphia. Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906140582 IE Insp Rept 50-443/79-04 & 50-444/79-04 on 790312-19 No noncompliance noted Major areas inspected const work in progress & licensee action on provious insp & findings MCGAUGHY,R W . MCBREARTY,R A . FOLSOM,J A Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/10 4pp
- 7906180416 Forwards 1E Info Notice 79-10, "Noncomforming Pipe Support Struts" No written response necessary ORIER.B H Region 1, Philadelphia, Office of the Director 79/04/16 1p
- 7906:1004: Forwards IE Builetin 79-05B. "Nuclear Incident at TMI-Suppl "No written response required CRIER.B H Region 1. Philadelphia. Office of the Director 79/04/23 1p
- 7904010130 Ack receipt of 790316 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-443/79-02 & 50-444/79-02 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/26 Ip
- --7904010134 Responds to NRC 790316 itr re violations noted in IE Insp Repts 50-443/79-02 & 50-444/79-02 Corrective actions clarifies wording of two statements in insp repts HASELTINE, J D Public Service Co of New Hampshire 79/03/16 20p
- 7906120198 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIERS H Region 1. Philadelphia. Office of the Director 79/05/07 2pp
- 7906260156 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER.8 H Region 1, Philadelphia, Office of the Director 79/05/11, 1p
- /906290782 Responds to IE Bulletin 79-03 Pipes mfg by Youngstown Helding & Engineering Co are being used & will be uitrasonically tested in accordance w/Dravo Procedure ESM-UT-4
  SHEPARD.A M Public Service Co of New Hampshire 79/05/11 2pp
- 7906290667 Responds to IE Bulletin 79-07 Westinghouse does not employ elgebraic summation techniques for response spectrum modal analysis: nor do time history analysis techniques employ earthquake directional motions
  SHEPARD: A M Public Egrvice Co of New Hampshire 79/05/24, 3pp

- S Reportable occurrences, LERs & related correspondence
- 7811090147 Forwards subj facils refueling water storge tank design deficiency rept
  JOHNSON-W P Public Service Co of New Hampshire 78/10/27 ip
- DOCKET 30-444 SEABROOK NUCLEAR STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7906080282 Responds to NRC 790524 request forwards matl Bangor Hydro-Electric Co filed under Amend 39 of license application.dtd 780515 Requests expedited antitrust review, in order to complete processing of new Amend 40 RITEMER, J A Ropes & Gray 79/05/29 4pp
- G Adjudicatory correspondence
- 7906210047 Mation for extension until 790411 to prepare response to ALAB-509 SCINTO, J. F. Hearings Division 79704/02 2pp
- --7904210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 5-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7704050034 Lists reasons for honparticipation in seismic design proceedings Relates TMI incident to SSE studies by Public SVC Co of NH Forwards comments re fcility, presented to Commissioner DL Roy, but not allowed as evidence WEINHOLD, E H Affiliation Unknown 77/04/30 12pp
- 7906050136 Forwards Seacoast Anti-Pollution League 790502 request for order to show cause re suspension or revocation of CPs BACKUS.R A O'Neil. Backus. Spielman 79/05/02 lp
- --790605013B Request by Beacoast Anti-Pollution League for order to show cause re suspension or revocation of CPs Certificate of Svc encl
  BACKUS,R A O'Neil, Backus, Spielman 79/05/02 Lépp,
- 7904040042 Responds to 790322 petition No proceeding to revoke CP will be initiated DENTON: H R Office of Nuclear Reactor Regulation 79/05/09 1p
- --790&040054 Forwards Clamshell Alliance petition asking NRC to revoke CP Suggests response be in ltr format Ofc of Executive Legal Director will be available for assistance in preparing response MURRAY.JP Rulemaking & Enforcement Division 79/04/24 lp
- ---7906040058 Forwards Clamshell Alliance petition for appropriate action Petition asks NRC to revoke CP GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/03 2pp
- ---7906040069 Petition to revoke CP \* Clamshell Alliance 79/03/22 3pp
- 7906010276 Suspands further consideration of alternative site issue, due to appeals court finding that cooling towers were not required DUFLO, M E · Atomic Safety and Licensing Appeal Panel 79/05/14 Spe
- 7906210095 NRC motion for summary disposition re radon issue was in error;ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Cartificate of Svc enci
  DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/25
- H General correspondence
- 7906070065 Ack receipt of 790325 itr to J Doutch of DOE re use of velocity caps Discusses capability of velocity caps to withstand northeasters & other damaging storms DEYOUNG; RC Division of Site Safety & Environmental Analysis 79/04/14 4pp
- I Financial information
- 7906060246 Forwards Suppl 1 to Amend 40 W/supporting documentation. including financial qualifications of several utils re partial transfer of ownership RITSHER.J A Ropas & Gray 79/06/05 ip

- --7906060253 Forwards info re Suppl 1 to Amend 40 & request for partial transfer of CPPR-135 & CPPR-136 Forwards "Annual Financial Rept 1978" for utils MERKILL, D.N. Public Service Co. of New Hampshire 79/06/01 7pp
- --7904040254 "Annual Financial Rept 1978" Supplemental info and \* Central Vermont Public Service Corp 78/12/31 200pp
- --7906060259 "Annual Financial Rept 1978 " Supplemental info encl \* Green Mountain Power Corp 78/12/31 100pp
- --7906060263 "Annual Financial Rept 1978 " Supplemental info encl \* Bangor Hydro-Electric Co 78/12/31 110pp
- --7906060267 "Annual Financial Rept 1978 " Supplemental info encl \* Central Maine Power Co 78/12/31 175pp
- --7706060268 "Annual Financial Rept 1978 " Supplemental info enci \* Taunton Municipal Lighting Plant 78/12/31 84pp
- 7906190317 Forwards annual financial repts for each facility part-owner RITSHER, J A Ropes & Gray 79/06/18 2pg
- ---7906190323 "Annual Financial Rept 1978 "
  \* Northwast Utilities 78/12/31 48pg
- --7906190328 "Annual Financial Rept 1978 "
  HUEHMER, H Hudson Light & Power Dept 78/12/31 55pp
- --7906190340 "Annual Financial Rept 1978 "
  \* Eastern Utilities Associates 78/12/31 40pp
- --7906190343 "Annual Financial Rept 1978 "
  \* Fitchburg Gas & Electric Light Co 78/12/31 20pp
- ~~7906190346 "Annual Financial Rept 1978 " \* Vermont Electric Cooperative, Inc 78/12/31 24pp
- --7906190351 "Annual Financial Rept 1978"

  \* Massachusetts Municipal Wholesale Co 78/12/31 40pp
- --7906190367 "Annual Financial Rept 1978 " \* United Illuminating 78/12/31 28p
- ---7906190374 "Annual Financial Rept 1978 "
  \* New England Cas & Electric Assoc 78/12/31 36pp
- --7906190375 "Annual Financial Rept 1978 "
  # Maine Public Service Co 78/12/31 24pp
- --7906190379 "Annual Financial Rept 1977-78 " \* Vermont Electric Pawer Ca , Inc 78/12/31 13pp
- 7906250344 Forwards annual financial repts for Public Syc Co of NH.New England Power Co & United Illuminating RITSHER, J A Ropes & Gray 79/06/22 220pp
- --7906230381 "Annual Financial Rept 1977" & SEC Form 10-K

  \* Public Service Co. of New Hampshire 77/12/31 58pp
- --7906250382 "Annual Financial Rept 1978 "
  \* Public Service Co of New Hamoshire 78/12/31 21po

\_ \_ \_ \_ \_ \_

-----

--7906250385 "Annual Financial Rept 1977" & SEC Form 10-K \* New England Power Co 78/12/31 43oo

- Q Inspection reports. IE Bulletins & correspondence
- 7906140374 Forwards IE Insp Rept 30-443/79-04 & 50-444/79-04 on 790312-13 No noncompliance noted CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906140582 IE Insp Rept 50-443/79-04 & 50-444/79-04 on 790312-13 No noncompliance noted Major areas inspected const work in progress & licensee action on previous insp & findings MCGAUGHY.R W . MCBREARTY.R A . FOLSOM. J A Region I. Philadelphia. Reactor Construction & Engineering Support Branch 79/04/10 4pp
- 7906180416 Forwards IE Info Nutice 79-10, "Nancomforming Pipe Bupport Struts" No written response necessary CRIER. B H Region 1, Philadelphia, Office of the Director 79/04/16 1p
- 7906(1004) Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl " No written response required GRIER.B H Region i, Philadelphia, Office of the Director 79/04/23 ip
- /906010130 Ack receipt of 790316 ltr informing NRC of steps taken to correct violations noted in IE Inep Repts 50-443/79-02 t 50-444/79-02 CARLSON,R T Region 1, Philadelphia, Reactor Construction & Engineering Support Branch 79/04/26 ip
- --7906010134 Responds to NRC 790316 ltr re violations noted in [f loap Repts 50-443/79-02 t 50-444/79-02 Corrective actions clarifies wording of two statements in insprepts HASELTINE.J D Public Service Co of New Hampshire 79/03/16
- 7906120198 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insolation Support Problem" No action required GRIER.B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp
- 7906260156 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" GRIER.B.H Region 1, Philadelphia, Office of the Director 79/05/11 ip
- 7906290782 Responds to IE Bulietin 79-03 Pipes mfg by Youngstown Helding & Engineering Co are being used & will be ultrasonically tested in accordance w/Dravo Procedure ESH-UT-4 SHEPARD A M Public Service Co of New Hampshire 79/05/11 2pp
- 7906290667 Responds to IE Bulletin 77-07 Hestinghouse does not employ algebraic summation techniques for response spectrum modal analysis, nor do time history analysis techniques employ earthquake directional motions
  SHEPARD, A.M. Public Service Co. of New Hampshire 79/09/24 3pp
- DOCKET 50-445 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 1

  A Application/construction stage documents & correspondence
- 7906200604 Summary rept re Unit 2 pressure vessel misorientation Caused by combined factors, including inadequate communication of evolving design criteria to designers & breakdown in vendor drawing review hetusen Olbbs & Hill & Westinghouse OARY,R J Texas Utilities Generating Co 79/04/30 3pp
- 7906250319 Summary of 790327 meeting w/util in Betherda.MD to discuss repair of reactor vessel support pedestal for Unit 2
  BURNELL, S B Light Water Reactors Branch 2 79/05/15 4pp
- 7906250323 Summary of 790425 meeting w/util in Bethasda, MD re status of & applicant plans for control of exclusion area BURHELL, S. B Light Water Reactors Branch 2 79/05/18 4pp
- 7905230163 Forwards requests for addl info required to complete evaluation of application for OL BAER, R L Light Water Reactors Branch 2 79/05/22 20pp
- 706130003 Forwards 790511 update of FSAR info re natural gas & oil wells surrounding facility site FEIST.C.K Texas Utilities Services, Inc. 79/05/30 ip
- ,705130012 Updates FSAR info re natural gas & oil wells in vicinity of nuclear facility Oversized drawing encl.

  HILLER, W.C. H. J. Gruy & Associates, Inc. 79/05/11 10pp

- 7904220200 Requests amend to CPPR-126 & 127 to authorize withdrawal of groundwater during const for addl year Submits pumpage summary. TX govt well data & ltr re evaluation of planned treatment facility Amend fee & two oversized maps encl GARY.R J Texas Utilities Generating Co 79/06/15 32pp
- G Adjudicatory correspondence
- 7905110360 Confirms 790418 meeting in Arlington, TX to discuss contentions re facility Requests proposed contentions be forwarded before meeting CHANDLER, L. J. Branch i 79/04/06 ip
- 7906050236 Suppl to petition to intervene Adds contentions re const of plant Affidavits & Certificate of Svc encl FOUKE, R L , JACOBSON, N H Citizens for Fair Utility Regulation 79/05/07 25pp
- 7904070305 Suppl to 790228 petition to intervene & listing of contentions ELLIS, J Citizens Association for Sound Energy 79/05/07 58pp
- 7906260084 Suppl to amended petition of intervenors Association of Community Organizations for Reform Now.M & C Bishop & O & H Wood Lists & provides bases for safety & environ contentions Affidavit & Certificate of Svc enci GAY.O M West Texas Legal Services 79/05/07 36pp
- 7706070399 Denies 790406 motion by Association of Community
  Organizations for Reform Now & West TX Legal Sycs for
  continuance of prehearing conference & filing contentions
  BOWERS.E 6 Atomic Safety and Licensing Board Panel 79/05/09
- 7904250483 Memo by applicants re interest & contentions of petitioners
  No petitioner has shown requisite interest or valid
  contention necessary to support intervention in proceeding
  Certificate of 8vc encl
  REYNOLDS:N S Debevoise & Lieberman 79/05/17 10pp
- 7904240205 Recommends intervenor status be granted to all petitioners Intervenor contentions should be consolidated/drafts acceptable contention re adequacy of facility const Certificate of 8vc encl GHANDLER, L J Branch 1 79/05/17 5pp
- 7904240474 Memo by applicants re significance of ALAN-549 in proceeding Associational standing doctrine has been misapplied to organizations seaking standing through people who are not members. Certificate of Syc encl
  REYNGLDS.N S Debevoise & Lieberman 79/06/04 9pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906120235 Forwards Amend 6 to FBAR Affidavit encl GARY,R J Texas Utilities Generating Co 79/05/31. 3pp
- --7906120239 Amend 6 to FSAR \* Texas Utilities Generating Co 79/05/31 600pg
- 7906120273 Forwards Affidavit of Svc for Amend 6 to FSAR FEIST.C K Texas Utilities Services, Inc. 79/06/08 3pp
- M Antitrust correspondence
- 7906070311 Notice of appearance of MG Berger on behalf of DGJ Certificate of Svc encl BERGER,M G Justice,Dept of 79/03/19 4pp
- 7906070317 Answer of TX Util Co & subsidiaries to Central Power & Light's first set of interrogetories & request for production of documents Affidavit & Certificate of Svc encl HORSHAM, J I , SAMPELS, M D Horsham, Forsythe & Sampels 79/03/28 16pp
- 7904040030 TX Utils Qenerating Co discovery rept for Mar 1979 responded to interrogatories & document requests from NRC, City of Brounsville & Central Power & Light & submitted response to NRC motion to compel W/Certificate of Syc KNOTTS, J B Debsycise & Lieberman 79/04/05 5pp
- 7906020255 Supplemental answers by TX Utils Canerating Co & subsidiaries to first set of interrogatories & request for production of documents from DOJ Supporting documentation & Certificate of Svc encl WORSHAM, J. I , BAMPELS, M D Worsham, Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman. 79/04/11. 40pp

- 7906040417 Request by Houston Lighting & Power for extension.until 790430.for filing replies to motions for summary disposition Certificate of Svc encl BARNETT.E W Baker & Botts BOUKNIGHT, J A . FRANKLIN, W J Lowenstein, Newman, Reis, Axelrad & Toll 79/04/11 5pp
- 7906020129 Response by DOJ to various motions of Houston Lighting & Power, TX Utils Generating Co & City of Austin Supporting documentation & Cortificate of Syc encl HARRIS, J L . BERGER, M G . CLARK, R H Justice, Dept of 79/04/23 4200
- 7906040136 Forwards answer by Tex-La Electric Cooperative, Inc to TX Utils Generating Co motion to dismiss Central & South West Corp as party intervenor, or in alternative, for summary disposition Certificate of Svc oncl RITTS.F H Northcutt E1y 79/04/23 4pp
- --7906040150 Forwards answer by Tex-La Electric Cooperative. Inc to Tx Utils Generating Co motion to dismiss Central & South West Corp as party intervenor.or.in alternative.for summary disposition RITTS.F H Northcutt Ely 79/04/23 Ip
- --7906040154 Request by Tex-La Electric Cooperative for denial of motion by TX Utils Generating Co to dismiss Central & South West Corp as party intervenor.or.in alternative.for summory disposition
  RITTS.F H Northcutt Ely 79/04/23 5pp
- 7906040454 Denies 790405 motion filed by Public Utils Board of City of Brownsville.TX to compel further production of documents by Bouth TX Electric Cooperative >> Medina Cooperative MILLER,M E Atomic Safety and Licensing Board Panel 79/04/23 2pp
- 7906020009 Add1 responses by Houston Lighting & Power to DDJ first set of interrogatories & request for production of documents Certificate of Svz encl COPELAND: J G Baker & Botts 79/04/27 3ipp
- 7906190034 Forwards second supplemental answer of TX Utils Generating Co to DGJ first interrogatories & requests for production of documents forwarded per 790418 meeting SLICKER,F K Worsham Forsythe & Sampels 79/04/27 1p
- --7906190043 Becond supplemental answer by TX Utils Generating Co to DOJ first interrogatories & requests for production of documents Supporting documentation & Certificate of Svc encl WORSHAM, I . SAMPELS, IS D Worsham, Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman 79/04/27 24pp
- 7904020119 Response by Public Utils Board of City of Brownsville, TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Svc encl JABLON, R A Spiegel & McDiarmis 77/04/30 38pp
- 7904020149 Answer in apposition to Houston Lighting & Power motion to compel NRC production of privileged documents Certificate of Svc encl
  LESSY.R., BLUME.M Anti-Trust Division 79/04/30 10pp
- 7904020209 Response by Houston Lighting & Power to NRC 790419 motion for reconsideration of ABLB 790416 order Requests that ABLB affirms order re-creation of new documents not maintained in normal course of business Certificate of Svc encl BOUKNIGHT.J A , FRANKLIN.W J Lowenstein, Newman, Reis, Axelrad & Toll BARNETT.E W Baker & Botts 79/04/30 lipp
- 7906020250 Raply by TX Utils Generating Co to combined answer of Central Power & Light & Central & Bouthwest in opposition to former's 790403 motion to dismiss Central & Southwest as intervanor W/pertinent documentation & Certificate of Svc KNOTT6.JB Debovoise & Lieberman WORBHAM,JI, SAMPELS.MD Worsham. Forsythe & Sampels 79/04/30 18pp
- 7906190054 Discovery progress rept for Apr 1979 Responded to TX Utils Generating Co & Houston Lighting & Power interrogatories Met w/utils on 790418 Certificate of Svc encl HARRIS, J L . BERGER, M G . CLARK, R H Justice, Dept of 79/04/30 600
- 7906200299 Forwards Public Utiks Boards of City of Brownsville.TX response to Houston Lighting & Power Co first set of interrogatories & first request for production of documents Affidavit & Certificate of Svc enc!
  WHITE

- --7706200300 Public Utils Board of Brownsville response to Houston Lighting & Power Co first interrogatories & first request for production of documents JABLOW.R A Spiegel & McDiarmid 77/05/02 111pp
- 7906200576 TX Utils Generating Co answer to Central Power & Light 790420 motion to compel further responses to latter interrogatories Previously supplied answers are complete & faircaddi demands by Central Power are redundant MNOTTS. J B Debevoise & Lieberman SAMPELS,K D , WORSHAM, J I Worsham, Forsythe & Sampels 79/05/02 Opp
- 7906070034 Discovery status rept for Apr 1979 NRC filed answer in opposition to motion of Houston Lighting & Power Co to compal production of privileged documents
  LESBY.R P Anti-Trust Division 79/05/03 2pp
- 7904040122 TX Utils Generating Co discovery progress rept for Apr 1979 responded to interrogatories from DOJ,met w/DOJ & NRC & endeavored to coordinate remaining discovery w/City of Brownsville.TX Certificate of Svc enci
- 7904230151 South TY Electric Cooperative & Medina Electric Cooperative monthly discovery rept for Apr 1979 no new discovery requests institated or received during month
  JOHN.D F Akin. Gump. Hauer & Feld 79/05/04 4pp
- 7906190140 Response by Houston Lighting & Power to Central Power & Light 790420 motions to compel answers to interrogatories Provides info re preparation of previous answers Certificate of Syc ancl
  BARNETY, E W Baker & Botts 79/05/07 10pp
- 7906210405 Rules on discovery, in response to NRC 790419 motion for reconsideration of ASLB 790416 order Upholds order reprotection of settlement documents & excepting Houston Lighting & Power from producing certain documents MILLER, M E Atomic Safety and Licensing Board Panel 79/05/07 200.
- 7905040032 Second request for util supplemental production of nantschnikal documents
  BLUME,M B Anti-Trust Division 79/05/08 lp
- 7906020137 Answer by Public Utils Board of City of Brownsville.TX to 790425 & 790430 motions by Oulf States Util re compliance w/790226 subposma duces tecum from ASLB Supporting documentation & Centrificate of Svc encl MCDIARMID.R C . FOIRER.M R Spiegel & McDiarmid 79/05/10 90pp
- 7906020037 Answer in apposition to Gulf Blates Util 790425 motion for protective order & for order setting conditions for compliance w/790226 subposes for production of documents Certificate of Svc encl HARRIS.J L Justice, Dept of 79/05/11 15pp
- 7906020167 Notices of appearance by SB Cuphert & RH Clark on behalf of DDJ Certificate of Svc encl CYPHERT,S B , CLARK,R H Justice,Dept of 79/05/11 5pp
- 7908230426 Houston Lighting & Power Co petition for extension until 790529 to compel further responses from Public Utils Board of City of Brownsville-TX Addl time required to determine scope of planned motion Certificate of Svc encl FRANKLIN, W J . BOUKNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll BARNETT, E W Baker & Botts 79/05/11 Spp
- 7906190147 Answers first set of interrogatories & request for production of documents submitted by TX Utils Generating Co Supporting documentation & Certificate of Syc encl LESBY.R P., BLUME, M.B. Anti-Trust Division 79705/14 10pp
- 7706070312 Notice of 770601 conference in Bethesda. MD to discuss pending motions 3 responses re discovery & summary disposition
  MILLER. M E Atomic Safety and Licensing Board Panel 77/05/15 1pt
- 7906280105 Motion by Houston Lighting & Power to include Central Power & Light within ABLB 790409 protective order satting terms for production of confidential documents to Public Utils Board of City of Brownsville.TX.Certificate of Svc encl BARNETT, E.W. Baker & Botts BOUKNIGHT, J.A. Lowenstein, Newman, Reis, Axelrad & Toll. 79/05/15 9pp
- 7906070046 Motion by Gulf States Utils Co to file brief in reply to DDJ & City of Brownsville, TX enswers to previous util motion & supplemental motion for protective order Seeks to clarify third party status.

  WETTERMANN, M. J., RADER, R. M. Conner, Moore & Corber 79/Q5/16 7pp

- 7706070315 Grants Houston Lighting & Pawer Co 770511 motion for extension of time, until 770529, far filing motion to compel further production from City of Brownsville, Tx MILLER.M E Atomic Safety and Licensing Board Panel 79/05/16 ip
- 7906170124 Requests RM Rader & DM Clements be added to svc list RADER,R M Conner, Moore & Corber 79/05/16 1p
- 7905020076 All Houston Lighting & Power confidential documents, produced for Public Utils Board of City of Brownsville, TX & reviewed by Central Power & Lightishall be subjt to terms & conditions of 790409 protective order MILLER, M E Atomic Safety and Licensing Board Panel 79/09/18 )
- 7706:304:8 Orants Culf States Util 790506 motion requesting leave to file reply brief in response to DOJ & City of Brownsville,TX answers to util request for protective order MILLER.M E Atomic Safety and Licensing Board Panel 79/05/22 p
- 7906290596 TX Utils Generating Co discovery rept for May 1979 util provided supplementary responses to NRC interrugatories & requests for production of documents Cartificate of Svc ancl KNOTTS, J B Pebevoise & Lieberman 79/06/06 Spp
- @ Inspection reports. If Buildtins & correspondence
- 7906200474 Forwards IE Insp Repts 50-445/79-08 & 50-446/79-08 on 790326-29 No noncompliance noted SEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/17 2pp
- --7906200324 IE Insp Repts 50-445/79-08 & 50-446/79-08 on 790326-29 Na noncompliance noted Major areas inspected observation of work & review of GA documentation re concrete placement in containment bldg & safety injection sys check valves TAPIAL JI, TAYLOR, R G, HALL R E Region 4, Dallas, Office of the Director 79/04/17 Spp
- 7986110005 Forwards IE Builetin 79-058, "Nuclear Incident at THI-Suppl " No written response required GEYRRIT.K V Region 4, Dallas, Office of the Director 79/04/21
- 7906120077 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/07
- 7906250027 Forwards IE info Notice 79-12, "Attempted Damage to New Fusi Assemblies " 8EYFRIT.K V Region 4. Dalies. Office of the Director 79/05/11
- 790613007.3 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licenses action required SEYFRIT, K V Region 4. Dallas, Office of the Director 79/05/22
- 7906270589 Ack receipt of 790517 Itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-445/78-08 & SO-446/78-08 BEIDLE, W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/12 Ip
- --7906290603 Responds to NRC 1tr re violations noted in IE Insp Repts 50-445/78-08 % 50-446/78-08 Corrective actions implementation of use of supplemental water from Squaw Creek Reservoir GARY, R J Texas Utilities Generating Co 79/05/17 2pp
- S Reportable occurrences. LERs & related correspondence
- 7706200567 Notifies that evaluation of reactor vessel noizle weld metal defects is continuing NRC will be informed of conclusion when reached OARY,R J Texas Utilities Generating Co 77/04/16 ip
- 7906180163 Forwards PNO-79-67AM 8EIDLE: M C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/08 ip
- 7906180184 Forwards PNO-79-67AN
  8EIDLE: W C Region 4. Dallas. Reactor Construction & Engineering
  8upport Branch 79/05/16 ip.

- 7906180250 Forwards PNO-79-67AO BEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/22 ip
- 7906180331 Forwards PNO-79-67AP SEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/05/23 ip
- 7906120208 Informs of RO of apparent weld metal defects in shop weld between Unit I reactor pressure vessel hat leg nozzle C % safe-end Investigation continuing GARYR J Texas Utilities Generating Co 79/06/08 ip
- 7906190209 Notifies that 1981-83 2,300 MW installation pipe supports may not meet seismic requirements Condition may be reportable Investigation continuing GARY,R J Texas Utilities Ca 79/06/15 ip
- 7906220324 Reconfirms 790522 verbal rept to RG Taylor that pipe wall thickness requirements in project piping specs may not be adequately conservative to meet ABME code stress requirements investigation & evaluation continue OARY.R J Texas Utilities Generating Co 79/06/18 ip
- T Hearing transcripts on non-antitrust matters
- 7904070011 Transcript of 790522 prehearing conference in Glan Rose.TX Pp 1-133
  HOWERS,E S . COLE.R F . KORNPLITH, L. Atomic Safety and Licensing Board Panel 79/05/22 135pp
- 7906180736 Transcript of 790601 hearing in Bethesda.MD Pg 213-471 MILLER,M E . WOLFE.S J Atomic Safety and Licensing Board Panel 79706/01 260pp
- OGCKET 50-446 COMANCHE PEAK STEAM ELECTRIC STA , UNIT 2

  A Application/construction stage documents & correspondence
- 7906200604 Summary rapt re Unit 2 pressure vessel misorientation Caused by combined factors including inadequate communication of evolving design criteria to designers & breakdown in vendor drawing review between Oibbs & Hill & Westinghouse GARY.R J Texas Utilities Generating Co 79/04/30 App
- 7906250319 Bummary of 790327 meeting w/util in Bethesda.MD to discuss repair of reactor vessel support pedestal for Unit 2
  BURWELL.B B Light Water Reactors Branch 2 79/05/18 4pp
- 7904250323 Summary of 790425 meeting w/util in Bethasda,MD re status of & applicant plans for control of exclusion area BURWELL,8 B Light Water Reactors Branch 2 79/05/18 4pp
- 7906230163 Forwards requests for add1 info required to complete evaluation of application for QL BAER.R L Light Water Reactors Branch 2 79/09/22 20pp
- 7906130003 Forwards 790511 update of FSAR info re natural gas & oil wells surrounding facility site
  FEIST, C K Texas Utilities Services, Inc. 79/05/30 tp
- --7906130012 Updates FBAR info re natural gas & oil wells in vicinity of nuclear facility. Oversized drawing enci MILLER, W C H J Gruy & Associates, Inc 79/05/11 10pp
- 7906220200 Requests amend to CPPR-126 & 127 to authorize withdrawal of groundwater during const for addl year Gubmits pumpage summary. TX govt well data & ltr re evaluation of planned treatment facility Amend fee & two oversized maps encl GARY.R J Texas Utilities Operating Co 79/06/15. 32pp
- Q Adjudicatory correspondence
- 7905110360 Confirms 790418 meeting in Arlington, TX to discuss contentions re facility Requests proposed contentions be forwarded before meeting CHANDLER.L J Branch i 79/04/06 ip
- 7706050236 Suppl to petition to intervene Adds contentions re const of plant Affidavits & Certificate of Byc encl FOUKE.R L , JACOBSON,N H Citizens for Fair Utility Regulation 79705/07 25pp.
- 7906070305 Suppl to 790228 petition to intervene & listing of contentions.

  ELLIBIO Citizens Association for Sound Energy, 79/05/07 SBpp

- 7906260084 Suppl to amended petition of intervenors Association of Community Organizations for Reform Now.M & C Dishop & O & W Wood Lists & provides bases for safety & environ contentions Affidavit & Certificate of Svc encl OAY.O M West Texas Legal Services 79/05/07 36pp
- 7906070399 Denies 790406 motion by Association of Community Organizations for Reform Now & West TX Legal Svcs for continuance of prehearing conference & filing contentions BOWERS. E.S. Atomic Safety and Licensing Board Panel 79/05/09 3pp
- 7906250483 Memo by applicants re interest & contentions of petitionors
  No petitioner has shown requisite interest or valid
  contention necessary to support intervention in proceeding
  Certificate of Svc encl
  REYNOLDS:N S Debevoise & Lieberman 79/05/17 10pp
- 7906260205 Recommends intervenor status be granted to all petitioners Intervenor contentions should be consolidated, drafts acceptable contention re adequacy of facility const Certificate of Svc encl CHANDLER.L.J Branch 1 79/05/17 5pp
- 7906210117 Time for NRC to elect to review ALAB-535 & ALAB-539 is extended until 790604 CHILK.B J Office of the Secretary of the Commission 79/05/21 ip
- 7906260494 Memo by applicants re significance of ALAB-549 in proceeding Associational standing doctrine has been misapplied to organizations seeking standing through people who are not members Certificate of Svc encl
  REYNOLDS, N.S. Debevoise & Lieberman /9/06/04 9pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906120235 Forwards Amend 6 to FSAR Affidavit encl GARY, R J Texas Utilities Generating Co 79/05/31 3pp
- ---7906120237 Amend 6 to FSAR
  \* Texas Utilities Generating Co 79/05/31 600pp
- 7906120293 Forwards Affidavit of Svc for Amend 6 to FBAR FEIST.C K Texas Utilities Services, Inc. 79/06/08 3pp
- M Antitrust correspondence
- 7906070317 Answer of TX Util Co & subsidiaries to Central Power & Light's first set of interrogatories & request for production of documents Affidavit & Centificate of Svc encl MORSHAM.J J . SAMPELS.M D Worsham, Forsythe & Sampels. 79/03/28
- 7904040030 TX Utila Generating Co discovery rept for Mar 1979 responded to interrogatories & document requests from NRC, City of Brownsville & Central Power & Light & submitted response to NRC motion to compel W/Certificate of Svc KNOTTS.J B Debaydise & Lieberman 79/04/08 Spp
- 7904020255 Supplemental answers by TX Utils Generating Co >>
  subsidiaries to first set of interragatories & request for
  production of documents from DOJ Supporting documentation &
  Cartificate of Syz encl
  HORSHAM, I . SAMPELS.H D Worsham, Forsythe >> Sampels KNOTTS.J B
  Debevoise >> Lieberman 79/04/12 4Opp
- 7906040417 Request by Houston Lighting & Power for extension, until 790430, for filing replies to motions for summary disposition Certificate of Syc enci BARNETT.E.W Baker & Botts, BOUKNICHT, J A., FRANKLIN, W J Lawenstein, Newman, Reis, Akeirad & Toll, 79/04/11 Spp
- 7706020129 Response by DGJ to various motions of Houston Lighting & Power, TX Utils Generating Co & City of Austin Supporting documentation & Certificate of Syc encl HARRIE, J. L., BERGER, M. G., CLARK, R. H. Justice, Dept. 09, 79/04/23 6200
- 7906040136 Forwards answer by Tex-La Electric Cooperative, Inc to TX
  Utils Generating Co motion to dismiss Central & South West
  Corp as party intervenor, or, in alternative, for summary
  disposition Certificate of Svc encl
  RITTS.F H Northcutt Ely 79/04/23 App

•

- ---7906040150 Forwards answer by Ter-La Electric Cooperative, Inc to Tr Utils Generating Co motion to dismiss Central & South West Corp as party intervenor, or, in alternative, for summary disposition RITS.F H Northcutt Ely 79/04/23 tp
- --7906040154 Request by Ter-La Electric Cooperative for denial of motion by TX Utils Generating Co to dismiss Central & South West Corp as party intervenor, or, in alternative, for summary disposition RITTS,F H Northcutt Ely 79/04/23 Spp
- 7906040454 Denies 790405 motion filed by Public Utils Board of City of Brownsville.TX to compel further production of documents by South TX Electric Comperative MidLER:M E Atomic Safety and Licensing Board Panel 79/04/23 200
- 7906020009 Add1 responses by Houston Lighting & Power to DOJ first set of interrogatories & request for production of documents
  Certificate of Svc enc1
  CDPELAND.J G Baker & Botts 79/04/27 3(pp
- 7906190034 Forwards second supplemental answer of TX Utils Generating Co to DOJ first interrogatories & requests for production of documents.forwarded per 790418 meeting SLICKER.F K Worsham, Forsythe & Sampels 79/04/27 1p
- --7706190043 Second supplemental answer by TX Utils Generating Co to DOJ first interrogatories & requests for production of documents Supporting documentation & Certificate of Svc encl WORSHAM, I . SAMPELS.M D Horsham, Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman 79/04/27 24pp
- 7906020119 Response by Public Utils Board of City of Brownsville.TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Svc encl JABLON.R A Spisgel & McDiarmid 79/04/30 38pp
- 7906020165 Answer in opposition to Houston Lighting & Power motion to Compel NRC production of privileged documents Certificate of Svc encl LESSY.R , BLUME.M Anti-Trust Division 79/04/30 10pp
- 7906020209 Response by Houston Lighting & Power to NRC 790619 motion for reconsideration of ASLB 790416 order Requests that ASLB affirms order re creation of New documents not maintained in normal course of business Certificate of Svc encl BOUKNIGHT, J. A., FRANKLIN, H. J. Lowenstein, Nauman, Reis, Axelrad & Toll BARNETT, E.W. Baker & Botts 79/04/30 (ipp
- 7904020250 Reply by TX Utils Generating Co to combined answer of Central Power & Light & Central & Southwest in opposition to former's 790403 motion to dismiss Central & Southwest as intervenor Myertinent documentation & Certificate of Svc KNOTTS.J B Debevoise & Lieberman WORDHAM.J & SAMPELS,M D Worsham. Forsythe & Sampels 79704/30 18pp
- 7906190054 Discovery progress rept for Apr 1979 Responded to TX Utils Generating Co & Houston Lighting & Power interrogatories Met w/utils on 790418 Certificate of Syc encl HARRIS.J L . BERGER.M O . CLARK.R H Justice,Dept of 79/04/30 600
- 7906200299 Forwards Public Utils Boards of City of Brownsville,TX response to Houston Lighting & Power Co first set of interrogatories & first request for production of documents Affidavit & Certificate of Syc enc!
  WHITE.S G Spiegel & McDearmid 79/05/02 6pp
- --7906200500 Public Utils Board of Brownsville response to Houston Lighting & Power Co first interrogatories & first request for production of documents JABLON,R A Spiegel & McDiarmid 79/05/02 11:pp
- 7906200576 TX Utils Demerating Co answer to Central Power & Light 790420 motion to compet further responses to latter interrogatories Previously supplied answers are complete & fairzaédi demands by Central Power are refundant KNOTTS.J B Debevoise & Lieberman BAMPELS.H D. WORSHAM.J I Worsham. Forsythe & Sampels 79/05/02 6pp
- 7906070034 Discovery status rept for Apr 1979 NRC filed answer in opposition to motion of Houston Lighting & Power Co to combel production of privileged documents

- 7906040122 TX Utils Generating Co discovery progress rept for Apr 1979 responded to interrogatories from DDJ met w/DDJ & NRC & endeavored to coordinate remaining discovery w/City of Brownsville.TX Certificate of Svc encl
  KNUTTS, J B Debevoise & Lieberman 79/05/04 Spp
- 7906230151 South TX Electric Cooperative & Medina Electric Cooperative monthly discovery rept for Apr 1979 no new discovery rept for Apr 1979 no new discovery requests initiated or received during month
  JOHN, D F Akin, Gump, Hauer & Feld 79/05/04 4pp
- 7906190140 Response by Houston Lighting & Power to Central Power & Light 790420 motions to compel answers to interrogatories Provides info re preparation of previous answers Certificate of Svc encl
  BARNETT, E W Baker & Botts 79/05/07 1000
- 7906210405 Rules on discovery, in response to NRC 790419 motion for reconsideration of ASLB 790416 order Upholds order reprotection of settlement documents be excepting Houston Lighting b Power from producing certain documents HILLER.N E Atomic Safety and Licensing Board Panel 79/05/07
- 7706040032 Second request for util supplemental production of nontechnical documents
  BLUME, M B Anti-Trust Division 77/05/08 ip
- 7906020137 Answer by Public Utils Board of City of Brownsville,TX to 790425 & 790430 motions by Oulf States Util re compliance w/790226 subpoena duces terum from ASLB Supporting documentation & Certificate of Svc encl HCDIARMID,R C . POIRER,M R Spiegel & McDiarmid 79/05/10 90pp
- 7906020037 Answer in opposition to Gulf States Util 790425 motion for protective order 4 for order setting conditions for compliance w/790226 subpoens for production of documents Certificate of Svc encl HARRIS. J L Justice. Dept of 79/03/11 15pp
- 7905020167 Notices of appearance by SB Cyphert & RH Clark on Sehalf of DOJ Certificate of Svc encl CYPHERT.8 B , CLARK.R H Justice.Dept of 79/05/11 5pp
- 7905250426 Houston Lighting & Power Co petition for extension until 790529 to compel further responses from Public Utils Board of City of Brownsville.TX Addl time required to determine scope of planned motion Certificate of Bvc encl FRANKLIN.W J . BOUNNJOHT.J A Lowenstein.Newman, Reis, Axelrad & Tolk BARNETT.E W Baker & Botts 79/05/11 Spp
- 7906190147 Answers first set of interrogatories & request for production of documents submitted by TX Utils Generating Co Supporting documentation & Certificate of Svc enci LESSY,R P , BLUME,N B Anti-Trust Division 79/05/14 10pp
- 7906070312 Notice of 790601 conference in Bethesda, MD to discuss pending motions & responses re discovery & summary disposition MILLER, M E Atomic Safety and Licensing Board Panel 79/05/15 &p
- 7906280109 Mation by Houston Lighting & Power to include Contral Power & Light within ASLB 790409 protective order setting terms for production of confidential documents to Public Utils Board of City of Brownsyille, TX Certificate of Svc encl BARNETT, E W Bater & Botts BOUKNICHT, J A Lowerstein, Newman, Reis. Axelrad & Toll 79/05/15 9pp
- 7906070046 Motion by Quif States Utils Co to file brief in reply to DDJ & City of Brownsville, TX answers to provious util motion & supplemental motion for protective order Seeks to clarify third party status.

  WETTERHAHN, M J , RADER, R M Conner, Moore & Corber 79/05/16 7pp
- 7906070315 Orants Houston Lighting & Power Co 790511 motion for extension of time.until 790529 for filing motion to campel further production from City of Brownsville.Tx MILLER.M E Atomic Safety and Licensing Board Panel 79/05/16 ip.
- 7706190124 Requests RM Rader & DM Clements be added to svc list RADER.R M Conmer, Moore & Corber 79/05/16 ip
- 7906020096 All Houston Lighting & Power confidential documents, produced for Public Utils Board of City of Brownsville, TX & reviewed by Central Power & Light, shall be subjt to terms & reviewed by Central Power & Cight, shall be subjt to terms & content to protective order c Safety and Licensing Board Panel 79/05/18 ip

- 7906130418 Grants Gulf States Util 7905Q6 motion requesting leave to file reply brief in response to DDJ & City of Brownsville.TX answers to util request for protective order MILLER,M E Atomic Safety and Licensing Board Panel 79/05/22 1p
- 7906290596 TX Utils Generating Co discovery rept for May 1979 util provided supplementary responses to NRC interrogatories & requests for production of documents Certificate of Svc pncl KNOTTS, J B Debevoise & Lieberman 79/06/06 Spp
- a Inspection reports, IE Bulletins & correspondence
- 7906200474 Forwards IE Insp Repts 30-445/79-08 & 50-446/79-08 on 790326-29 No noncompliance noted SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/17 2pp
- ---7906200524 IE Insp Repts S0-445/79-08 & 30-446/79-08 on 790326-29 No noncompliance noted Major areas inspected observation of work & review of QA documentation re concrete placement in containment bldg & safety injection sys check valves TAPIA, J I TAYLOR, R Q HALL, R E Region 4, Dallas, Office of the Director 79/04/17 Spp
- 7706120079 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/07
- 7906290027 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/11 1a
- 7906130073 Forwards IE Bullstin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ECYFRIY.K V Region 4, Dallas, Office of the Director 79/05/22
- 7906290889 Act receipt of 790517 ltr informing NRC of steps taken to correct violations noted in IE Inap Repts 50-445/78-08 & 50-446/78-08 EFIDLER,W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/06/12 ip
- --7906290603 Responds to NRC ltr re violations noted in IE Insp Repts 50-445/78-08 5 50-446/78-08 Corrective actions implementation of use of supplemental water from Squaw Creek Reservoir OARY, J Texas Utilities Generating Co 79/05/17 2pg
- 8 Reportable occurrences, LERs & related correspondence
- 7906200367 Notifies that evaluation of reactor vessel nozzle weld metal defects is continuing NRC will be informed of conclusion when reached GARY, R.J. Texas Utilities Generating Co. 79/04/16 ip
- 7906180163 Forwards PNC-79-676M.

  SEIDLE.H C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/05/08 ip
- 7906180184 Forwards PNO-79-67AN
  SEIDLE,W C Region 4, Dallas, Reactor Construction & Engineering
  Bupport Branch 79/05/16, 1p.
- 7906180250 Forwards PND-79-67AU SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/22 ip
- 7904180331 Forwards PNO-79-67AP
  SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/23 ip
- 790&120208 Informs of RO of apparent weld metal defects in shop weld between Unit I reactor pressure vessel hot leg nozzle C & safe-end Investigation continuing OARY, R J Texas Utilities Generating Ca 79/06/08 1p
- 7706190209 Notifies that 1981-83 2,300 MW installation pipe supports may not meet seismic requirements Condition may be reportable investigation continuing GARY, R J Texas Utilities Co 79706/15 lp
- 7906220324 Reconfirms 790522 verbal rept to RG Taylor that pipe wall thickness requirements in project piping specs may not be adequately conservative to meet ABME code stress requirements investigation & evaluation continue GARY.R J. Texas Utilities Generating Co 79/06/18 1p.

- T Hearing transcripts on non-antitrust matters
- 7906070011 Transcript of 790522 prehearing conference in Glen Rose,TX Pp 1-133 BOWERS,E S . COLE,R F , KORNBLITH,L Atomic Safety and Licensing Board Panel 79/05/22 135pp
- 7906180736 Transcript of 790601 hearing in Bethesda.MD Pp 213-471 MILLER,M E , WOLFE,S J Atomic Safety and Licensing Board Panel 79/06/01 260pp
- DOCKET 50-452 GREENWOOD ENERGY CENTER, UNIT 2
- A Application/construction stage documents & correspondence
- 7906250177 Discusses reactivation of environ review of CP application Forwards proposed outline of "Need for the Plant" section of FES suppl BALLARD.R L Environmental Projects Branch 1 79/09/23 4pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 7906130284 Act receipt of 790523 memo Requests copy of preliminary DES & opportunity to review statement MIKULA.E J Michigan, State of 79/06/06 ip
- DOCKET 50-453 GREENWOOD ENERGY CENTER, UNIT 3
- A Application/construction stage documents & correspondence
- 7906250177 Discusses reactivation of environ review of CP application Forwards proposed outline of "Need for the Plant" section of FES suppl BALLARD, R L. Environmental Projects Branch 1 79/05/29 4pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 7906130284 Ack receipt of 790523 memo Requests copy of preliminary DES & opportunity to review statement MIKULA, E. J. Michigan, State of 79/06/06 1p
- DOCKET 50-454 BYRON STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7904030125 Supports part of motion requesting ASLB schedule prehearing conference Opposes contention in motion that sufficient time has been allowed for preparation Certificate of Svc encl JOHNSON.B League of Women Voters of Rockford IL 79/04/23 2pp
- 7904020138 Confirms 790521 meeting w/util in Glen Ellyn, IL to discuss insp findings re const activities
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/08
- 7906290136 Forwards specific requests for info Te review of DL application Covers areas of Teview performed by various NRC branches Auxiliary Bys.Power Bys.Hechanical Engineering, Btructural Engineering, QA & Effluent Treatment Bys VAROA: B A Light Water Reactors Branch 4 79/05/13 77pp
- O Adjudicatory correspondence
- 7906050445 Requests clarification of procedures necessary to be accepted as petitioner at prehearing conference
  JOHNSON, B League of Women Voters of Rockford, IL 79/04/04 2pp
- 7906250124 Responds in support of applicant 790418 motion requesting scheduling of special preheaving conference Conference should be scheduled at earliest convenient date Certificate of Svc encl
  KARMAN, M Branch 2 79/05/04 4pp
- @ Inspection reports, IE Bulletins & correspondence
- 7906050054 Forwards IE Insp Repts 50-454/79-05 & 50-455/79-05 on 790321-0323 No noncompliance noted FIURELLI,6 Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 79/04/06 2pp
- --7906030087 IE Insp Repts 30-434/79-05 \$ 50-455/79-05 on 790321-23 No noncompliance noted Major areas inspected, hangar installation & related hanger procedures & recorde & concrete anchor installation GALLAGHER, E. J. SUERMANN, J. F. HAYES, D. W. Region 3. Chicago, Office of the Director 79/05/05 7pp

- 7906250132 Forwards IE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11 & notice of violation FIORELLI, G Region 3, Chicago, Office of the Director 79/04/20
- --7906230136 Notice of violation from insp on 790404-11
  \* Region 3, Chicago: Office of the Director 79/04/18 ip
- --7906250141 IE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11 Nancompliance noted inadequate storage of piping penetrations KNOP, R C . GALLAGHER.E J . KONKLIN.JE Region 3. Chicago, Office of the Director 79/04/18 12pp
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07 1p
- 7906070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ASME 8A-312 Type 304 pipe spools REED.C Commonwealth Edison Co 79/09/08 2pp
- 7905190078 Forwards lE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
  10
- 7906130082 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 to
- 7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J.G. Region 3, Chicago, Office of the Director 79/05/29
- B Reportable occurrences, LERs & related correspondence
- 7906020134 Ack receipt of 790419 final rept re-post-tensioning buttonhead deficiencies FIORELLIO Region 3. Chicago. Reactor Construction & Engineering Support Branch 79/05/09 ip
- 7906250284 Forwards Inryco 790309 rept. "Investigation of Buttonhead Defects," in response to 790823 request W/o encl DELGEORGE.L O Commonwealth Edison Co 79/06/18 1p
- DUCKET 50-455 BYRON STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7906050125 Supports part of motion requesting ASLB schedule prehearing conference Opposes contention in motion that sufficient time has been allowed for preparation Certificate of Sec encl JOHNSON, B League of Women Voters of Rockford, IL 79/04/23 2pp
- 790602013B Confirms 790321 meeting w/util in Olen Ellyn,IL to discuss insp findings re const activities
  KEPPLER,J G. Region 3, Chicago, Office of the Director 79/05/08
- 7906290186 Forwards specific requests for info re review of OL application, Covers areas of review performed by various NRC branches Auxiliary Bys. Power Bys. Mechanical Engineering, Btructural Engineering, OA & Effluent Treatment Bys VARGA: S A Light Water Reactors Branch 4 79/05/15 77pp
- Adjudicatory correspondence
- 7906290124 Responds in support of applicant 790418 motion requesting scheduling of special preheating conference Conference should be acheduled at sarliest convenient date Certificate of Syc enci
  KARMAN, M Branch 2 79/05/04 4pp
- 3 Inspection reports: IE Bulletine & correspondence

1 - 1

7906050054 Forward: IE Insp Repts 50-454/79-05 & 50-455/79-05 on 790321-0323 No nencompliance noted.
FIORELLI, G Region G, Chicago, Reactor Construction & Engineering Support Branch 79/04/06 2pp

- ---7906050057 IE Insp Repts 50-454/79-05 & 50-455/79-05 on 790321-23 No noncompliance noted Major areas inspected hanger installation & related hanger procedures & records & concrete anchor installation GALLAGHER, E. J. SUERMANN; J.F. HAYES, D.H. Region 3; Chicago, Office of the Director 79/05/05 7pp
- 7904250132 Forwards IE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11 % notice of violation FIDRELLI, G Region 3, Chicago, Office of the Director 79/04/20
- ---7906250136 Notice of violation from insp on 790404-11
   Region 3. Chicago. Office of the Director 79/04/18 ip
- --7906250141 IE Insp Repts 50-454/79-06 & 50-455/79-06 on 790404-11 Noncompliance noted inadequate storage of piping penetrations KMOP.R C. GALLAGHER.E J. KONKLIN, J E Region G. Chicago, Office of the Director 79/04/18 12pp
- 7906120083 Forwards IE Info Notice 79-11. "Lower Reactor Vessol Head Insulation Support Problem " No action required KEPPLER. J G Region 3, Chicago. Office of the Director 79/05/07
- 7906070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ABME 5A-312 Type 304 pipe spools REED, C Commonwealth Edison Co 79/05/08 2pp
- 790619007B Forwards IE Info Notice 79~12, "Attempted Damage to New Fuel Assemblies"

  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11
- 7906:30082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breafers for Engineered Safety Sys " Licenses action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22 ip
- 7906200080 Forwards TE Info Notice 79-13. "Indication of Low Water Level in Dyster Creek Reactor" KEPPLER.J & Region 3. Chicago, Office of the Director 79/03/29
- S Reportable occurrences. LERs & related correspondence
- 7904020134 Ack receipt of 790419 final rept re post-tensioning buttonhead deficiencies FIGRELLI.Q Region 3, Chicago, Reactor Construction & Engineering Bupport Branch 79/05/09 lp
- 7906230284 Forwards Inryco rept. "Investigation of Buttonhead Defects" dtd 790309, in response to 790323 request W/o enci DELOEOROE, L O Commonwealth Edison Co 79/06/18 ip.
- DOCKET 50-486 BRAIDWOOD STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 770602013B Confirms 770521 meeting w/util in Olen Ellyn, IL to discuss insp findings re const activities
  KEPPLER, J O Region 3. Chicago, Office of the Director 77/05/08
- 7906270156 Forwards specific requests for info re review of OL application Covers areas of review performed by various NRC branches Auxiliary Sys.Power Sys.Mechanical Engineering. Structural Engineering. OA & Effluent Treatment Sys VARGA: S A Light Water Reactors Branch 4 79/05/15 77pp
- 7906200536 Responds to 790409 request for mode to fish aggs & larvae portion of aquatic monitoring programs Approves proposed modes

  BALLARD, R L Environmental Projects Branch 1 79/05/18 3pp
- O Adjudicatory correspondence
- 7906200629 Responds to applicant 790418 motion requesting scheduling of special prehearing conference at earliest possible date Certificate of Byc encl KARMAN-M Branch 2 79/05/04, 4pp.

### G Inspection reports, IE Bulletins ₺ correspondence

- 790&050222 Forwards IE Insp Repts 50-456/79-03 & 50-457/79-03 on 790313-0315 No noncompliance noted FIORELICO Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/06 2pp
- ---7906050228 IE Insp Repts 50-456/79-03 % 50-457/79-03 on 790313-0319 No noncompliance noted Major areas inspected status of electrical contractors & respective GA/GC programs Review of previously identified items of noncompliance JUNES, C E . KNOP, R C Region 3, Chicago, Office of the Director 79/04/04 4pp
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07
- 7906070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ASME 8A-312 Type 304 pipe spools REED, C Commanwealth Edison Co 79/05/08 2pp
- 7904190078 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
- 7906130082 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/22
- 790&220158 Forwards ASME response supporting util contention re welding of split backing rings in const Requests NRC re-examine apparent noncompliance & consider changing infraction to observation REED.C Gommonwealth Edison Co 79/05/23 App
- 7906200080 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/29

### DOCKET 50-457 BRAIDWOOD STATION, UNIT 2

- A Application/construction stage documents & correspondence
- 7906270156 Forwards specific requests for info re review of GL application Covers areas of review performed by various NRC branches Auxiliary Sys.Power Sys.Mechanical Engineering. Structural Engineering A & Effluent Treatment Sys VARGA:S A Light Water Reactors Granch 4 79/05/15 77pp
- 7906200356 Responds to 790409 request for mode to fish eggs & larvae portion of equatic monitoring programs Approves proposed mode BALLARD, R. L. Environmental Projects Branch 1 79/03/18 3pp
- G Adjudicatory correspondence
- 7706030445 Requests clarification of procedures necessary to be accepted as petitioner at prehearing conference JOHNSON: B League of Women Voters of Rockford: IL 77/04/06 2pp
- 7906200625 Responds to applicant 790418 motion requesting scheduling of special preheating conference at earliest possible date Certificate of Svc encl KARMAN.M Branch 2. 79/05/04 4pp
- P Operating license stage documents & correspondence
- 790402013B Confirms 790821 meeting w/util in Olen Ellyn, IL to discuss insp findings re const activities

  KEPPLER, J G Region 3, Chicago, Office of the Director ' 79/05/08.
- Q Inspection reports, IE Bulletins & correspondence
- 7904050222 Forwards IE Insp Repts 50-436/79-03 & 50-457/79-03 on 790313-0315. No noncompliance noted FIORELLI, 0. Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/06. 2pp

- --7906050228 IE Insp Repts 50-456/79-03 & 50-457/79-03 on 790313-0315 No noncompliance noted Major areas inspected status of electrical contractors & respective GA/GC programs Review of previously identified items of noncompliance JONES.C E . KNOP.R C Region 3. Chicago, Office of the Director 79/04/04 App
- 7906120083 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07 ip
- 7906070241 Responds to IE Bulletin 79-03 Requests 90-day extension to review present use of ASME SA-312 Type 304 pipe spools REED, C Commonwealth Edison Co 79/09/09 2pp
- 790619007B Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J C Region 3, Chicago, Office of the Director 79/05/11 ig
- 790613008⊋ Forwards IC Bulletin 79-11, "Faulty Overcurrent Trip Davice in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER.J G Region 3. Chicago. Office of the Director 79/05/22
- 7906220138 Forwards ASME response supporting util contention re-welding of split backing rings in const Requests NRC re-examine apparent noncompliance & consider changing infraction to observation REED. C. Commonwealth Edison Co. 79/05/23 4pp
- 7906200080 Forwards IC Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J O Region 3, Chicago, Office of the Director 79/05/29

### DUCKET 50-458 RIVER BEND STATION, UNIT 1

- A Application/construction stage documents & correspondence
- 7906130004 Requests that proprietary portion of Gould, Inc qualification rept suppl, "Accelerated Aging Procedure," be withdrawn & returned to util w/o placement in PDRs (ref 10CFR2 790) WEIGAND.J G Gulf States Utilities Co 79/06/01 1p
- G Inspection reports, IE Bulletins & correspondence
- 7904i10001 Forwards IE Bulletin 79-059, "Nuclear Incident at TMI-Suppl " No written response required SEYFRIT.K V Region 4. Dailas, Office of the Director 79/04/21
- 7906120065 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required BEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/07
- 7906250018 Forwards IE info Notice 79-12, "Attempted Damage to New Fuel Assemblies " SEYFRIT,K V Region 4, Dallas, Office of the Director 79/05/11
- 7906130065 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required SEYFRIT.K V Region 4. Dallas, Office of the Director 79/05/22
- 8 Reportable occurrences, LERs & related correspondence
- 7706220036 Updates rept re potential deficiency of cadwell slesves Evaluation continues; issue not resolved at present. Update to follow within 30 days.

  HUMPHREYS, L. L. Guif States Utilities Co 77/04/27 1p
- 7904180152 Forwards PND-79-47AM SEIDLE:N Begion 4: Dellas: Reactor Construction & Engineering Support Branch 79/05/08 ip
- 7906180174 Forwards PND-79-67AN SEIDLE.N.C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/16 1p

- 7906180241 Forwards PNO-79-67A0 SEIDLE.W C Region 4. Dallas: Reactor Construction & Engineering Support Branch 79/05/22 1p
- 7906180318 Forwards PNO-79-67AP SEIDLE,W C Region 4. Daltas, Reactor Construction & Engineering Support Branch 79/05/23 ip
- 7706120392 Notifies that deficiency rept re cadweld sleeves will be completed within 30 days WEIGAND.J G QUIF States Utilities Co 79/05/31 ip
- DUCKET 50-459 RIVER BEND STATION, UNIT 2
- A Application/construction stage documents & correspondence
- 7904:30004 Requests that proprietary portion of Gould Inc qualification rept suppl. "Accelerated Aging Procedure." be withdrawn & returned to util w/o placement in PDRs (ref 10CFR2 790). WEIGAND.J G Gulf States Utilities Co 79/06/01 ip
- G Inspection reports. IE Bulletins & correspondence
- 7905110001 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Suppl" No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director 79/04/21
- 7906120065 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYPRIT.K V Region 4, Daltas, Office of the Director 79/05/07
- 7906250019 Forwards IE info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  SEYFRIT.K V Region 4. Dallas, Office of the Director 79/05/11
- 7906130065 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Action required SEYFRIT.K V Region 4, Dailas, Office of the Director 79/05/22
- 8 Reportable occurrences, LERs & related correspondence
- 7906180152 Forwards PNO-79-67AM SEIDLE,W C Region 4. Dallss, Reactor Construction & Engineering Support Branch 79/05/08 1p
- 7906180874 Forwards PNO-79-67AN SEIDLE,W C Region 4. Dailas, Reactor Construction 5 Engineering Support Branch 79/05/16 ip
- 7906180241 Forwards PNB-79-67AD SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/22 ip
- 79061803(8 Forwards PNO-79-67AP SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/23 ip
- DOCKET 50-460 WPPSS NUCLEAR PROJECT, UNIT 1
- A. Application/construction stage documents & correspondence
- 7906060013 Approves pronoced data of Aug 1980 for submittal of FBAR &
  - -1 79/08/01

- Q Inspection reports, IE Bulletins & correspondence
- 7906220133 Forwards IE Insp Repts 50-460/79-05 & 50-513/79-05 on 790327-29 No noncompliance noted SPENCER.O S Region 5, San Francisco, Office of the Director 79/04/13 2pp
- --7906220137 IE Insp Repts 50-460/79-05 & 50-513/79-05 on 790327-29 No noncompliance noted Major areas inspected const activities, training programs & miscellaneous open items ALBERT, W O. HAYNES, R C. Region 5, San Francisco, Office of the Director 79/04/13 App
- 7906130085 Responds to NRC 790321 Itr re violations noted in IE Insp. Repts 50-397/79-03.50-460/79-04 & 50-513/79-04 Corrective actions audit conducted Feb 1977 Deficient hanger RD-405 will be removed & replaced properly
  RENDEROER, D. L. Washington Public Power Supply System 79/04/20
- --7906150090 Ack receipt of 790420 itr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-397/79-03, 50-460/79-04 & 50-513/79-04 ENOELKEN.R H Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/03 ip
- ---7706150098 Forwards IE Insp Repts 50-397/79-03,50-460/79-04 & 50-513/79-04 on 770201-02 & 14-15 & notice of violation SPENCER, O 8 Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 2pp
- --7906150063 Notice of violation from insp on 790201-02 & 14-15 \* Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 2pp
- --7906150079 IE Insp Repts 50-397/79-03.30-460/79-04 & 50-313/79-04 on 790201-02 & 14-15 Noncompliance noted failure to respond effectively to audit finding & failure to implement effective insp program BIEMOP.T W. SHACKLETON.O C. HAYNES,R C. Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 7pp
- 7906120087 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN,R H Region 5. San Francisco, Office of the Director 79/05/07 ip
- 7905:180488 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/10 in
- 7906080245 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN:R H Region 5, San Francisco, Office of the Director
- 7906:120054 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/22 1p
- 7906200061 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/29 10
- 8 Reportable occurrences, LERs & related correspondence
- 7906180231 Forwards PNO-79-67AN
  ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/14 1p
- 7906180280 Forwards PNO-79-67AO ENGELKEN,R H Region 5, San Francisco. Office of the Director 79/05/21 ip
  - 180331 Forwards PNO-79-67AP. BELKEN,R H Region 3, San Francisco, Office of the Director 705/22 1p
  - 180371 Forwards PNO-79-67AG DELKEN-R H Region 5, San Francisco, Office of the Director 705/30 lp

1

# DOCKETED ITEMS

### DOCKET 50-461 CLINTON POWER STATION, UNIT 1

- @ Inspection reports, IE Bulletins & correspondence
- 7906250118 Forwards IE Insp Rept 50-461/79-04 & on 790403-05 No noncompliance noted FIDRELLI,Q Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/25 3pp
- --7906250123 IE Insp Rept 50-461/79-04 on 790403-05 No noncompliance noted Major areas inspected procedures for removal & replacement of recirculation inlet safe ends (N2) on reactor pressure yessel
  DANIELSON,D H , ERB,C M Region 3, Chicago, Office of the Director 79/04/25 6pp
- 7906120111 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/07 10
- 7906140464 Advises that response to IE Bulletin 79-03, "Longitudinal Weld Defects in ABME SA-312 Type 304 Stainless Steel Pipe Spools," will be submitted by 791231 WULLER, G E Illinois Power Co 79/05/10 ip
- 7906190093 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/11
- 7906130103 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required REPPLER, J O Region 3, Chicago, Office of the Director 79/05/22 is
- 7906200125 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/29

# DOCKET 50-462 CLINTON POWER STATION, UNIT 2

# G Inspection reports, 1£ Bulletins & carrespondence

- 7906120111 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/07
- 7706140464 Advises that response to IE Bulletin 77-03, "Longitudinal Weld Defects in ASME 8A-312 Tupe 304 Stainless Steel Pipe Bpaols:" will be submitted by 791231 WULLER:0 E illinois Power Co 79/05/10 ip
- 7906190095 Forwards IC Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11
- 7906;30:103 Forwards IE Bulistin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Bafety Sys " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22
- 7906200125 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER,J G Ragion 3, Chicago, Office of the Director 79/05/29

# DOCKET 50-469 FULTON GENERATING STATION, UNIT 1

# O Adjudicatory correspondence

- 7906260351 Requests by Save Solanco Environ Conservation Fund that NRC order util to show cause why application should not be terminated SACER.L. Sager & Sager Associates 79/05/14 7pp
- --7906260355 Urges on behalf of Peach Bottom Township, PA that site be reviewed at time plant needs to be constructed MALONE, Q. G. Affiliation Unknown 79/05/05 2pp

- --7906260364 Responds to 780501 ltr re proposed meeting on behalf of Fulton Township,PA, requesting that NRC not grant early site review SIDEBOTTOM,W J Affiliation Unknown 78/05/12 ip
- --7906260369 Advises that Fulton Township.PA Planning Commission opposes const of electrical generating plant on proposed site Requests termination of util application WEAVER.JW Affiliation Unknown 78/05/31 1p
- --7906260375 Requests on behalf of Drumora Township PA supervisors, termination of early site review plan Opposes const of any type of electrical generating plant MORRIS.A D Affiliation Unknown 79/04/07 2pp

### G Adjudicatory correspondence

- ---7906260378 Opposes const of add1 nuclear facility in area HESS.R W Pennsylvania, State of 79/04/30 2pp
- ~~7906260388 Opposes application for early site review WIDOFF, M P Pennsylvania, State of 79/03/02 2pp
- --7906260391 Opposes application for early site review Requests termination of proceeding Certificate of Svc encl HALKER.R S House of Rep 78/07/09 4pp

# DOCKET 30-464 FULTON GENERATING STATION, UNIT 2

- G Adjudicatory correspondence
- 7906260351 Requests by Save Solanco Environ Conservation Fund that NRC order util to show cause why application should not be terminated SAGERAL Sager & Sayer Associates 79/05/14 7pp
- --7906260353 Urges on behalf of Peach Bottom Township,PA that site be reviewed at time plant needs to be constructed MALONE.0 0 Affiliation Unknown 79/03/05 2pp
- --7906260364 Responds to 780501 ltr re proposed meeting on behalf of Fulton Township.PA, requesting that NRC not grant early site review SIDEBOTTOM, W. J. Affiliation Unknown 78/05/12 [p
- --7906260369 Advises that Fulton Township, PA Planning Commission opposes const of electrical generating plant on proposed site Requests termination of util application WEAVER, J W Affiliation Unknown 78/05/31 ip
- --7906260375 Requests on behalf of Drumore Township, PA supervisors, termination of early site review plan Opposes const of any type of electrical generating plant MORRIS: A B Affilfation Unknown 79/04/07 2pp
- ---7906260378 Opposes const of add1 nuclear facility in area HESB.R W Pennsylvania. State of 79/04/30 2pp
- ---7906260388 Opposes application for early site review WIDDFF.H P Pennsylvania, State of 79/03/02 2pp
- --7706260371 Opposes application for early site review Requests termination of proceeding Certificate of Svc encl WALKER, R S House of Rep 78/07/05 4pp
- DOCKET 50-466 ALLENS CREEK NUCLEAR STATION, UNIT 1

  D NRC Draft/Final Environmental Statements, supple & correspondence
- 7906190408 Requests addl info re endangared or threatened species in area of proposed facility Forwards appropriate sections of FES & suppl W/o encl BALLARD, R L Environmental Projects Branch 1 79/04/26 ip.

# Q Adjudicatory correspondence

7906070307 Request by util that two 790312 motions be found untimely NRDC motion to file brief amicus curiae & joint motion for extension to file brief amicus curiae by NRDC & Inst for Public Representation Certificate of Svc encl NEWMAN, J.R., REIG.H F., CULP.R H. Lowenstein, Newman, Reis, Axelrad & Toll 79/03/16 Spp

- 7905010082 Request for convenient location for prehearing conference Certificate of Svc encl MCCORKLE,B . HIMDERSTEIN.C Affiliation Uninoum 79/03/24 2pp
- --7906010083 Motion for period of discovery extension until 790502 HCCDRKLE.B. HINDERSTEIN.C Affiliation Unknown 79/03/24 Spi
- HCCORKLE, 8. HINDERSTEIN, C. Affiliation Uninown 79/03/24 3p
- 7906080183 Mation by Houston Lighting & Power Co to file response to 790319 amicus curiae brief from NRDC & Inst for Public Representation REIS,4F F. NEKHAN, J.R. Lowenstein, Newman, Reis, Arelrad & Toll COPELAND, J.O. Baker & Botts 79/03/28 2pp
- --7906080190 Response by Houston Lighting & Power Co to NRDC & Inst for Public Representation brief amicus curiae in support of Natl Lawyers Guild Urges denial of appeal NEHMAN.J R. R. REIS.H.F. Lowenstein.Newman.Reis.Arelrad & Toll COPELAND.J G. Baker & Botts 79/03/28 10pp
- 7906040383 Motion to postpone, until investigation of TMI-2 is completed, all further action in hearing process, except for discovery Certificate of Svc encl SCOTT.J M Teras Public Interest Research Group 79/04/02 3pp
- --7906040390 Request for production of documents
  SCOTT.J M Texas Public Interest Research Group 79/04/02 1p
- --7906040394 Interrogatories submitted to State of TX SCOTT.J M Texas Public Interest Research Group 79/04/02 ip
- 7905110440 Request by Houston Lighting & Power for denial of TX PIRG untimely 790327 brief seeking admission of renumbered Contention 12 re fire in wiring Certificate of Svc enc! NEWMAN, J R. REIS, H F., CULP, R H Louenstein, Newman, Reis, Arelrad & Toli 79/04/03 7pp
- 7904050016 First set of interrogatories & first request for documents submitted to NRC Cartificate of Svc encl DOHERTY, J F Affiliation Unknown 79/04/09 4pp
- 7904050082 Forwards response to first round of interrogatories submitted by TX PIRO LOWERRE.R W Teras. State of 79/04/10 ip
- 7905040445 Denies motions filed by TX PIRG & J Doharty for postponment of action Denies applicant's motion to reconsider 790406 order Denies TX PIRG motion to adopt JR Shreffler contentions
  WOLFE,S J Atomic Safety and Licensing Board Panel 79/04/13 3pp
- 7906020107 Answers C Hinderstein's second set of interrogatories & requests for production of documents Affidavit & Certificate of Svc encl COPELAND.0 J Baker & Botts NEWMAN.JR, CULP,R M Lowenstein, Newman, Reis, Axelrad & Toli 79/04/17 9pp
- 7906050021 First request for admissions from Houston Lighting & Power Co Certificate of Svc encl DDHRRTY.J F Affiliation Unknown 79/04/17 2pp
- --7906050191 Request for documents from NRC. Certificate of Svc encl. DQHERTY, J F Affiliation Unknown 79/04/17 1p
- 7906050414 Expresses opposition to nuclear plant const YEAGER.F B Affiliation Unknown 79/04/17 ip
- 7906180766 Requests opportunity to make traited appearance at avidentiary hearing MODDARD,S W Affiltation Union 2014/23 [p

- 7906080052 Applicant's response in opposition to TX PIRO request for entry upon land Request fails to set forth & describe items & lands to be inspected w/reasonable particularity Certificate of Svc encl COPELAND. J G. THRASH. C.O. Baker & Botts NEWMAN. J R Lowenstein, Newman, Reis, Azelrad & Toll 79/04/30 Spp
- 7906140178 Applicant response to B & RS Framson 790413 contentions Petitioners' contentions should be denied due to untimely filing & lack of merit Certificats of Svc encl COPELAND, J & Baker & Botts 79/04/30 App
- 7906180723 Applicant response to JF Doherty first set of interrogatories & second set of requests for documents Affidavit & Certificate of Svc encl COPELAND, J & THRASH, C G , NEWMAN, J R Baker & Botts 79/04/30
- 7904190015 Applicant response to JF Doherty first request for documents re NEDD-20623.NEDD-10349.NEDD-20944 & GESSAR Certificate of Svc encl COPELAND, J G Baker & Botts 79/04/30 3pp
- 7906040068 Responds to Intervenor C Handerstein's first set of interrogatories & requests for production of documents, received by NRC on 790418 Supporting documentation & Certificate of Syz encl
  FROCELICH, R W Division of Site Safety & Environmental Analysis 79/05/01 | 15pp
- 7906040114 Responds to TX PIRG 790402 request for production of documents Certificate of Svc encl SOHINKI,S M Branch 3 79/05/01 10pp
- 7906030108 Grants petitioners Rentfro.Framson.Potthoff,Marrack & Doherty extension.until 790525.in which to file submissions Directs Doherty to clarify affiliation w/TX PIRO MOLFE,8 J Atomic Bafesy and Licensing Board Panel 79/05/01 ip
- 7906070326 Responds to intervenor JF Doherty 790417 request for production of documents Forwards Research Info Ltr 91other documents will be placed in PDR W/o encl Certificate of Svc encl SURFINKI,S M Branch 3 79/05/01 3pp
- 7906040444 Notifies that time for NRC review of ALAB-533 is extended until 790522, to correspond w/review of ALAB-539 CHILK, S.J. Office of the Secretary of the Commission 79/05/02 ip
- 7906180124 Applicant response to JF Doherty first request for admissions Denies officers have discussed permanent abandonment of site because of ASLAB 790404 decision Affidavit & Certificate of Svc encl COPELAND. J O Baker & Botts 79/05/02 App
- 7906040430 Denies TX PIRG motion for reconsideration & clarification of ALAB-535 re application of relief on notice republication issue DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/03/03 5pp
- 7906070248 Admits intervenor JF Doherty's renumbered Contention 9 re strength of steel containment shells HOLFE, S J Atomic Safety and Licensing Board Panel 79/05/03 200
- 7906190240 Protests location of plant in close proximity to populated area Requests full party status for CP proceedings & receipt of EIS GRIFFITH.R Affiliation Unknown 79/05/03 ip
- 7906230179 Forwards 790316 board notification re recent issue on nonsefety-Grade Equipment to mitigate transients SCHINKI, S M Branch 3 79/05/03 2pp
- --7906230177 Beard notification recent issue on nonsefety-grade equipment to mitigate transients
  TEDESCO,R L Assistant Director for Reactor Sefety 79/03/16
  3pp
- 7906150235 Requests full party status for CP proceedings & receipt of EIS SCOTT, L W , FULLER, C , MCFARLAND, D Affiliation Unknown 79/05/04
- 7906070119 Denies on basis of untimeliness E Baskir 790501 appeal of ASLB 790209 rejection of petition to intervene DU FLO, M E Atomic Safety and Licensing Appeal Panel 79/05/08

- 7906220458 Applicant motion for supplemental notice of intervention procedures Notice would provide apportunity for parties discouraged by 780531 & 0911 notices to file petitions Draft notice & Certificate of Svc encl REIS-H F. NEWHAM.J F. Lowenstein, Newman, Reis, Axelrad & Toll COPELAND.J G. Baker & Botts. 79/05/09 12pp
- 7906290822 Opposes plant const Requests EIS for facility & status as full party to CP proceedings BTADE,K L Affiliation Unknown 79/05/09 3pp
- 7904070109 Defers action on applicant 790509 motion for supplementary notice of intervention procedures in view of Commission 790502 order indicating NRC review of ALAB-535 & ALAB-539 MOLFE.S J Atomic Safety and Licensing Board Panel 79/05/11 ip
- 7906280262 Opposition by applicant to intervenor FH Potthoff undated motion for 15-day extension to tile submission, per ASLB 790411 order Potthoff has not shown good cause for extension; motion should be denied Certificate of Svc encl COPELAND. J G. THRASH. C G. Baker & Botts NEWMAN. J R. Lowenstein, Newman, Reis, Ascirad & Toll 79/05/14 App
- 7906280245 Houston Lighting & Power second set of interrogatories & request for production of documents, submitted to intervener TX PIRG Certificate of SVx encl COPECAND.J Q. THRABH.C Q. Baker & Botts NEWMAN.J R Lowenstein, Newman, Reis, Axelrad & Toll 79/05/18 16pp
- 7906130427 Grants Potthoff extension of time, until 790601, to file submission permitted by 790411 order WOLFE,S J. Atomic Safety and Licensing Board Panel 79/05/21 2pp
- 7906210249 Responds to applicant 790309 motion for supplementary notice of intervention procedures Approves of motion, but seeks two amends re restrictions in motion limition contentions & time given to potential interven
- 7904260024 Submits new contentions per ALAB-535 & 770412 order Questions ability of ECCS, soley dependent upon ASLB single source of power OTTHOFF,F H Affiliation Unknown 77/05/25 App
- 7906250431 Submits add1 contentions per 790521 order Conservation program.if initiated.will eliminate need for generating capacity Biomass sys environmentally preferable to facility POTTHOFF,F H. Affiliation Unknown 79706701 2pp

### H General correspondence

- 7906020116 Comments on radioactive emissions during normal operations, temporary oneste storage of spent fuel elements & other contaminated matis 2 possible tectonic motion & geologic faulting at proposed site
  BASKIR.E Affiliation Unknown 79/05/01 5pp
- G Inspection reports, IE Bulletins & correspondence
- 7906110005 Forwards 1E Bulletin 79-058, "Nuclear Incident at TMI-Suppl " No writton response required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/04/21

# DOCKET STN-50-470 CEBSAR SYSTEM 80

- A Application/construction stage documents & correspondence
- 7906070277 Requests extension to file add1 info re CESSAR-F pre-docketing amend SCHERER.A E Combustion Engineering, Inc 79/06/01 ip
- DOCKET 50-471 PILORIM NUCLEAR POWER STATION. UNIT 2

  D NRC Draft/Final Environmental Statements, suppls % correspondence
- 7906060003 Forwards final suppl to FEB re plant const (NUREG-0549)
  REGAN-W H Environmental Projects Branch 2 79/05/18 2pp
- --7906060005 Notice of availability of final suppl to FEB re unit const REGAN,W H Environmental Projects Branch 2 79/05/16. 2pp.
- 7904030184 Forwards DES re CP application (NUREQ-0527) & FR notice of availability, Also forwards Seabrook alternate site study (NUREQ-0501) & Pilgrim FEG.final suppl (NUREQ-0547), for use in review of DES BALLARD, R. L. Environmental Projects Branch 1 79/05/31 Spp.

- --7906050176 Final suppl to FES re plant const # Office of Nuclear Reactor Regulation NUREG-0549 79/05/31 133pp Available at NTIS 7 25
- G Adjudicatory correspondence
- 7903200314 Forwards EA Licitra affidavit indicating that NRC reconsideration of reactor safety per Lawis Committee recommendations will have no impact on this proceeding SMITH.B H Branch 2 79703/01 4pp
- 7906050011 Forwards draft suppl to FES re unit const W/o encl SMITH.8 H  $$\rm Branch~2~79/04/12~ip$
- 7906120008 Notices of appearance of FS Hright & SM Leonard on behalf of Commonwealth of MA & notices of withdrawal of appearance of C Cork & J Brant on behalf of Commonwealth of MA Certificate of Svc encl WRIGHT, FS Massechusetts, State of 79/04/12 8pp
- 7906010222 Clarifies Commonwealth of MA request for extension of time to comment on draft suppl to FES (NUREO-0530) BURT.L. Massachusetts. State of 79/04/13 2pp
- 7906020251 Notifies that deposition intervenor of util personnel who prepared draft rept "Siting Study, Boston Edison Co," will be on 790426 Deponents will bring documents reflecting changes in rept since 790731 Certificate of Syc entl
  BURT, L Hassachusetts, State of 79/04/20 5pp
- 7906010144 Response in support of Communication of MA second motion to suppl record on "need for power" issue Requests ASLB allow additestimony be filed by 790518 Bupporting documentation b Certificate of Six encl
  SMITH.B H Branch 2 79/04/25 15p
- 7906010264 Suspends indefinitely deposition of applicant's consultant scheduled for 790426 Certificate of Svc encl HRIGHT.F 8 Massachusetts, State of 79704/25 3pp
- 7906010265 Mution for consideration of emergency planning issue Parties should be given opportunity to discuss sufficiency of emergency plans prior to issuance of CP Certificate of Svc encl
  MRIGHT.F.S. BURT.I. Massachusetts. State of 79/04/27 14po
- 7906230113 Socks dismissal of intervenor Cleetons 790416 interrogatories re radon values in Table S-3 ASLB does not haver jurisdiction over interrogatories as presented Centificate of Syc and MULKEY, M E Branch 2 79/05/07 2pp
- --7906230114 Responde to 790322 request re status of rulemaking to develop value for radon in Table 8-3 NRC is presently preparing paper A proposed rule which will be sent by 790406 CRRISTENDURY: E Hearings Division 79/03/26 ip
- 7906040041 Grants Commonwealth of MA 790404 motion to reopen record re "need for power" issue Applicant shall submit most recent long-range energy & demand forecasts of util & New England Power Pool LUTON.E Atomic Safety and Licensing Board Panel 79/05/09 1p
- 7706290185 Testimony on behalf of State of MA re ability of util to finance share of facility Financial analysis, transcript of util Board of Directors meeting, additestimony & Certificate of Bvc encl
  LEVY.P F Arkansas, State of 77/05/09 110pp
- 7906290179 Forwards PF Levy 790509 testimony on behalf of State of MA MA MEYER, M B Massachusetts. State of 79/05/09. 1p
- 7906260027 Direct testimony on behalf of applicant re alternative sites. Elaborates on util siting study for long range generating capacity expansion GRIFFIN, W R Boston Edison Co FRABCING, P J United Engineers & Constructors, Inc (subs of Raytheon Co ) 79/05/11 12pp
- 790626003R Direct testimony on financial qualifications of intervenor State of MA Contention 5. Delineates RM Kelmon role in ficense application & general financial duties Elaborates on TJ May financial responsibilities
  KELMON,R M , MAY,T J Boston Edison Co 79/05/11 13pp

- 7905270165 Opposition by util to State of MA motion to admit emergency planning contentions No factual basis presented or good cause shown for admission of contentions LEWALD, G. H. Ropes & Cray. STOODLEY, D. G. Boston Edison Co. 79/05/14 13pc
- 7904220116 Boston Edison Co supplemental testimony re need for facility Testimony provided by BH Weiner, FA Legrow, DV Bourcier, AN Barstou, FC Turner, N Godley & D Hanna Supporting Gocumentation encl WEINER, B H , LEGROW, P A Boston Edison Co 79/05/21 59pp
- 7905260005 Notification of appearance on behalf of MA Governor Ofc of Energy Resources
  KENNY, P. J. Massachusetts. State of 79/05/24 ip
- 7906250434 Orders resumption of evidentiary hearing on 790611 at Hemorial Hall, Plymouth, HA LUTON, E Atomic Safety and Licensing Board Panel 79/06/04 ip
- 7906280104 Permits State of MA Ofc of Energy Resources to participate
  in proceeding re need for power issue as interested state
  agency
  LUTOM.E Atomic Safety and Licensing Goard Panel 79/06/07 2pp
- 7906280260 Notice of reconstitution of ASLB AC Goodhops replaces E Luton as chairman LAZO.R M Atomic Safety and Licensing Board Panel 79/06/07 ip
- T Hearing transcripts on non-antitrust matters
- 7905140117 Transcript of 790524 meeting in Plymouth, MA Pp 9097-9218 LUTON, E , COLE, R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 79/05/24 121pp
- 7905050193 Transcript of 790525 hearing in Plymouth MA Pp 9219-9407 LUTON, E., COLE, R. F., CALLIHAN, D. Atomic Safety and Licensing Board Panel 79/05/25 189pp
- 7906220147 Transcript of 790529 meeting an Plymouth.MA Pp 9.408-9.592 LUTON.E. COLE.R F. CALLIHAN.D Commission 79/05/29 186pp
- 7906180726 Transcript of 790530 hearing in Plymouth, MA Pp 9,593-9,798 LUTON, E . COLE, R F . CALLIHAN, D Atomic Safety and Licensing Board Panel 79/05/30 200pp
- 7905220109 Transcript of 790531 hearing in Plymouth MA Pp 9799-10,046 LUTON.E . COLE.R F . CALLIHAN.D Atomic Safety and Licensing Board Panel 79/05/31 294pp
- T Hearing transcripts on non-antitrust matters
- 7905180728 Transcript of 790601 hearing in Plymouth, MA
  Pp 10.047-10.201
  LUTON, E , COLE, R F , CALLIHAN, D Atomic Safety and Licensing Soard
  Panel 79/06/01 150pp
- 7906260548 Transcript of 790611 hearing in Plymouth, MA Pp 10,209-10.341 GOODHOPE.A C . COLE.R F , CALLIHAN, D Atomic Safety and Licensing Board Panel 79/06/11 132pp
- DOCKET STN-50-482 HOLF CREEK GENERATING STATION
- A Application/construction stage documents & correspondence
- 7906070212 Clarifies current status of resolution of concrete problems DAVIS, J G Office of Inspection & Enforcement 79/04/25 Opp
- ---7906070214 Opposes further bldg of nuclear plants in KS Concerned re faulty concrete SALAVA,J Wolf Creek Nuclear Opposition, Inc. 79/01/02 ip
- 7906180180 Responds to 781224 ltr re quality of coment being used at site Forwards current summary of facts related to concrete problems At present time no concrete is being placed in reactor containment bldg.pending resolution of problem DAVIS.J © Office of Inspaction & Enforcement 79/04/27 Spp
- --7906180185 Expresses concern re quality of cement being used BKILLMAN.M Momen's International League for Peace & Freedom 78/12/24 19
- 7906120263 Requests NRC concurrence re use of ASME Section III Code Case N-242, "Matls Certification "
  PETRICK.N A SNUPPS-Standardized Nuclear Unit Power Plant System, 79/06/01 19

- 7905110159 Submits additinfore base mat.in reponse to 790529 telcon between util.consultants.Bechtel & NRC KOESTER,G L. Kansas Gas & Electric Co 79/06/06 9pp
- 7906110267 Submits info re BSAP computer program & miscellaneous project-developed programs, in response to NRC request Requests classification of info as proprietary Encl withheld (ref 10CFR2 790)
  KDMES: J M Bechtel Pawer Corp (subs of Bechtel Corp ) 77/06/06
  3pp
- O Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO.J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/24 34pp
- 7904040171 Responds to 790130 itr to JM Hendrie Forwards summary of concrete problems at facility At present, several requests for revocation of CP are under consideration & will be addressed when investigations are done DAVIS, J O Office of Inspection & Enforcement 79/04/27 5pp
- --7906040179 Recommends CP be revoked due to concrete problems DEBELLO, M Affiliation Unknown 79/01/30 1p
- 7906050096 Supports nationwide halt to nuclear plant const Cites Wolf Creek controversy as example MATHIASMIER, R. L. Affiliation Unknown 79/04/27 ip
- 7906290834 Requests CP be revoked Forwards 1t; to newspaper UHITE.T Affiliation Unknown 77/05/03 ip
- 7906210095 NRC motion for summary disposition re radon issue was in error;ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLO;M E Atomic Safety and Licensing Appeal Panel 79/03/25
  3pp
- 7906260403 Requests timely notification of any OL proceedings within jurisdiction of MD Public Svc Commission.to facilitate state participation
  HEARNE, T Missouri, State of 79/06/19 ip
- H General correspondence
- 7906010307 Responds to 790324 hearing re possible sale of 17% interest to rural electric cooperatives Request for hearing is premature, ownership notice not yet received ENGELHARDT, TF Deputy Executive Legal Director 79/04/16 3pp
- --7906010307 Requests hearing re possible sale of 17% interest in facility to certain rural electric cooperatives BELL.J E Affiliation Unknown 79/03/24 1p
- G Inspection reports, 1E Bulletins & correspondence
- 7906200546 Ack receipt of IE Insp Rept 50-482/78-13 No proprietary info KRESTER, G L Kansas Gas & Electric Co 79/03/05 1p
- 7906210025 Forwards IE Insp Rept 30-482/79-05 on 790326-29 No noncompliance noted SEIDLE, W.C. Region 4, Dalles, Reactor Construction & Engineering Support Branch 79/04/16 2pp
- --7906210032 IE Insp Rept 30-482/79-03 on 790326-29 No noncompliance noted Hajor areas inspected const activities including review of records & work on safety-related concrete & stping ROSENBERG.A B , HALL, R E Region 4, Dallas, Reactor Construction & Engineering Support Branch OBERG.C R Region 4. Dallas, Office of the Director 79/04/16 Spp
- 7906110003 Forwards IE Bulletin 79-05B, "Nuclear Incident at THI-Suppl " No written response required SEYFRIT, K V Region 4, Dallas, Office of the Director 79/04/21

# DOCKETED ITEMS

- 7906210300 Natifies Bechtel does concur w/util initial assessment re unacceptable welds in piping preassembly Installation of assemblies suspended until differences are resolved KOESTER, G.L. Kansas Gas & Electric Co. 79/04/25 ip
- 7904050056 Ack receipt of 790426 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/78-13
  Requests add1 info re failure to complete user tests within time limits
  GEIDLE, W C Region 4. Dallas, Office of the Director 79/04/26
- --7906050064 Responds to NRC 790216 ltr re violations noted in IE Insp Rept 50-482/78-13 Corrective actions ACI Method 1 will be followed for new mix designs Compliance w/Items 2,3,4,5 & 6 has been achieved KQESTER.G L Kansas Gas & Electric Co 79/03/22 6pp
- 7906050073 Ack receipt of 790323 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/79-01 Requests addl info re testing of concrete for slump limits, training & corrective measures planned SEIDLE, W C Region 4, Dallas, Office of the Director 79/04/26
- --7706050070 Responds to NRC 770301 ltr re violations noted in IE Insp Rept 50-482/77-01 Corrective actions documentation of failure to test batches 7383 & 7387 has been sent to A/E KOESTER.G L Kansas Oas & Electric Co 77/03/23 2pp
- 7906120068 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT, K V Region 4. Dallas, Office of the Director 79/05/07
- 7706250021 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  SEYFRIT.K V Region 4. Dallas. Office of the Director 77/05/11
- 7704130027 Ack receipt of 770423 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 50-482/79-03 SEIDLE,N C Region 4. Dallas, Reactor Construction & Engineering Support Branch 77/03/14 ip
- ---7906130033 Responds to NRC 790314 ltr re violations noted in IE Insp Rept 50-482/79-03 Corrective actions intensive training grogram conducted for concrete crews & concrete control procedures revised KOESTER,O L. Kansas Oas & Eiertric Co 79/04/23 2pp
- 7706140165 Ack receipt of 790425 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 90-482/78-12
  BEIDLC, W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/03/14 ip
- --7906140172 Responds to NRC 790221 ltr re violation noted in IE insp Rept 50-482/78-12 Corrective actions weld procedural changes have been completed & surveillance insps will be completed by 790528 KUESTER, O L Kansas Gas & Electric Co 79/04/25 3pp
- 7906130069 Forwards IS Sulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/22
- 8 Reportable occurrences, LERs & related correspondence
- 7902120222 Final significant deficiency rept re spot resistance welding of electrical raceway support matl Discusses matl deficiency safety implications & besting program at job sites \* Kansas Gas & Electric Co 79/02/07 14pp
- 7906180160 Forwards PND-79-67AM SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/08 ip
- 7906180177 Forwards PNO-79-67AN
  BEIDLE,W C Region 4. Dailas, Reactor Construction & Engineering
  Support Branch 79/05/16 ip
- 7906180245 Forwards PND-79-67AD SEIDLE,W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/05/22 ip
- 7906180324 Forwards PNO-79-67AP SEIDLE,W C Region 4. Dellas, Reactor Construction & Engineening Support Branch 79/03/23 ip

### U Congressional/Executive Correspondence

- 7906030166 Act receipt of 790301 request Forwards summary of concrete problems at site No concrete being placed in reactor containment bldg.pending resolution of basemat strength questions
  OBSICK.L V Office of the Executive Director for Operations
  79/03/01 4pp
- --7906050172 Requests info re concrete in facility basemat HHITTAKER:R House of Rep. 79/03/01 ip
- 7706250459 Forwards SL Bates 770412 ltr to T Cagleton re substandard bldg matls & disposal of radioactive wastes EAGLETON, T F Senate 79/05/07 2pp

# DOCKET STN-50-403 CALLONAY PLANT, UNIT 1 A Application/construction stage documents & correspondence

- 7906150194 Forwards Dames & Moore (interim rept, "Detailed Excavation Mapping, Ultimate Heat Sink Excavations " Rept available in Central Files only BCHNELL, D F Union Electric Co 79/05/09 ip
- 7906120146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SNUPPS FSAR PETRICK, N A SNUPPS-Standardited Nuclear Unit Power Plant System 79705/30 lp
- 7906120263 Requests NRC concurrence re use of ASME Section III Code Case N-242: "Matls Certification " PETRICK,N A SNUPPS-Standardized Nuclear Unit Power Plant System 79/06/01 ip

# @ Adjudicatory correspondence

- 7906260403 Requests timely notification of any OL proceedings within jurisdiction of MO Public Svc Commission, to facilitate state participation HEARNE, T Missouri, State of 79/06/19 ip
- G Inspection reports, IE Bulletins & correspondence
- 7906140562 Forwards IE Insp Rept 50-483/79-03 on 790306-12 & notice of violation
  FIORELLI.0 Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/04/04 2pp
- --7906:40564 Notice of violation from insp on 790406-12

  \* Region 3. Chicago, Reactor Construction & Engineering Support
  Branch 79/04/04 lp
- --7906140570 IE Insp Rept 50-483/79-03 on 790306-12 Noncompliance noted failure to failow established procedures for training non-QA/QC personnel who perform safety-related work activities KNOP,R C : HANSON: W A : JABLONSKIF, J Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/04/02
- 7906010124 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IC Insp\_Rept 50-483/79-03

- 7905130118 Forwards 1E Bulletin 79-11, "Faulty Overcurrent Trip Davice in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPFLER, J G Region 3, Chicago, Office of the Director 79/05/22
- 7906200139 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/29

#### DOCKET STN-50-484 TYRONE ENERGY PARK, UNIT 1

- A Application/construction stage documents & correspondence
- 7906120146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SNUPPS FBAR PETRICK.N A SNUPPS-Standardized Nuclear Unit Power Plant System 79/05/30 Ip
- 7906120263 Requests NRC concurrence re use of ASME Section III Code Case N-242, "Matls Certification " PETRICK.N A SNUPPS-Standerdized Nuclear Unit Power Plant System 79/06/01 1p

#### Q Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 BCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
  CHRISTEMBURY.E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon issue was in error:ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Cartificate of Svc enc1 DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906230107 Request by utils that ASLAB grant summary disposition of all issues in consolidated Radon proceeding Decision sought as matter of law since no genuine issue as to matl facts
  SILBERG. J A Shaw, Pittman, Potts, & Trowbridge 79/05/25 4pp
- --7906230110 Statement of matl facts re Rn proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies 1-7.9-18.20-24 & 26 Affidavit of MI Goldman & supporting documentation encl SILBERT. J E Shaw. Pittman. Potts. & Trowbridge 79/05/25 36pp
- --7906230112 Supple 790525 affidavit of MI Goldman & utils 790409 memo re Rn emissions & 60 minimus approach Discusses Alleged Deficiencies 2:9.16 & 21 Beeks motion for summary disposition Certificate of Svc encl BILBERG.J A Shaw, Pittman, Potts, & Troubridge 79/05/25 19pp
- 7906260403 Requests timely notification of any OL proceedings within jurisdiction of MO Public Svc Commission, to facilitate state participation HEARNE.T Missouri, State of 79/06/19 ip

### I Financial information

- 7906220204 "Annual Financial Rept 1978 "
  \*\* Comperative Power Association 78/12/31 25pp
- Q Inspection reports, 1E Bulletins & correspondence
- 7906120119 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/07
- 7706190098 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" ' KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11 in
- 7906220001 Responds to 1E Bulletin 79-03 re use of fusion welded pipe spools mfg by Youngstown Welding & Engineering Co No such pipe spools have been shipped to facility DIENHART, A. V Northern States Power Co 79/05/11 2pp

- 7906130111 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Bys " Licenses action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/22
- 7906230020 Responds to IE Bulletin 79-04 re incorrect weights for Velan swing check valves incorrect valve weights not used No mad required
  DIENHARTIA V Northern States Power Co 79/05/22 2pp
- 7906230046 Responds to IE Bulletin 79-07 re seismic stress analysis of safety-related piping Lists computer codes used in analyses DIENHART.A V Northern Btates Power Co 79/05/23 2pp
- 7906200132 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Oyster Creek Reactor" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/29
- DOCKET STN-50-495 STERLING POWER PROJECT NUCLEAR, UNIT 1
- A Application/construction stage documents & correspondence
- 7904120144 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SNUPPS FSAR PETRICK.N A SNUPPS-Standardized Nuclear Unit Power Plant System 79/05/30 ip
- 7906120263 Requests NRC concurrence re use of ASME Section III Code Case N-242 "Matts Certification " PETRICK, N A SNUPPS-Standardized Nuclear Unit Power Plant Gysten 79706/01 ip
- 7906270160 Requests notification of date for meeting w/NRC to discuss computer models which reflect upper plenum injection of ECCS WHITE, L D Rochester Gas & Electric Corp 79/06/20 ip

### Q Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-309 SCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
  CHRISTENBURY. E Hearings Division 79/03/26 34pp
- 7706120019 Requests 2-day extention until 770411 in which to file Meas per NRC 770308 order BRENNER.L Branch 3 79/04/09 2pp
- 7906210075 NRC motion for summary disposition re radon issue was in arroraLAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl.
- encl DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/25 Spp
- 7906230107 Request by utils that ASLAB grant summary disposition of alt issues in consolidated Radon proceeding Decision sought as matter of law since no genuine issue as to mat! facts SILBERG, J A Bhaw, Pittman, Potts, & Trowbridge 79/05/25. 4sp
- --7906230110 Statement of math facts re Rn proceedings as to which there is no genuine issue to be heard Discusses Alleged Deficiencies 1-7,9-18,20-24 & 26 Affidavit of MI Coldman & supporting documentation encl SILBERT. J E Shaw, Pittman, Potts, & Trowbridge 79/05/25 CAPP
- --7906230112 Supple 790525 affidavit of MI Goldman & utile 790409 Affice ea Rn emissions & de minimus approach Discusses Alleged Deficiencies 2.9,16 & 21 Seeks motion for summary disposition Certificate of Svc encl SILBERO, J A Shew, Pittman, Potts, & Trowbridge 79/05/25 19sp
- 7906260403 Requests timely notification of any DL proceedings within jurisdiction of MO Public Svc Commission, to facilitate state participation HEARNE, T. Missouri, State of 79/06/19 1p

# Q Inspection reports, IE Bullatins & correspondence

- 7906180417 Forwards IE Info Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary ORIER,8 H Region 1, Philadelphia, Office of the Director 79/04/16 ip
- 7906110042 Forwards IE Bulletin 79-058. "Nuclear Incident at THI-Buppl " No written response required GRIER, B H Region 1, Philadelphia, Office of the Director 79/04/23 1p
- 7906120202 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H . Region 1, Philadelphia, Office of the Director 79/09/07 2pp
- 7906270195 Responds to IE Bulletin 79-03 To date there have been no pipe spools of any type fabricated for or shipped to facilities ARTHURLJE Rochester Gas & Electric Corp 79/05/10 3pp
- 7906260197 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" GRIER, BH Region 1, Philadelphia, Office of the Director 79/05/11 1p

#### DOCKET STN-50-486 CALLOWAY PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 7906120146 Confirms plan to discuss & resolve matters re fuel rod bowing effects in SNUPPS FSAR PETRICK, N A SNUPPS-Standardised Nuclear Unit Power Plant System 79/05/30 ip
- 7906120263 Requests NRC concurrence re use of ASME Section III Code Case N-242 "Matls Gertification " PETRICK, N A SNUPPS-Standardised Nuclear Unit Power Plant System 79/06/01 1p

## G Adjudicatory correspondence

- 7906260403 Requests timely notification of any OL proceedings within jurisdiction of MO Public Svc Commission to facilitate state participation
  HEARNE, T Missouri, State of 79/06/19 ip
- G Inspection reports, IE Bulletins & correspondence
- 7906120127 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J. Q. Region 3. Chicago, Office of the Director 79/05/07 15
- 7906190104 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J G Region 3, Chicago. Office of the Director 79/05/11
- 7906190228 Responds to IE Bulletin 77-03 re use of fusion welded stainless steal pipe mfg by Youngstown Shipment of 65 spools at Callaway:70 at Wolf Creek BRYAN,J K Union Electric Co 79/05/11 Spp
- 7906:30:18 Forwards IE Bulletin 79-ii, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Bafety Sys " Licensee action required KEPPLER.J Q. Region 3, Chicago. Office of the Director 79/05/22
- 7906200139 Forwards IE Info Notice 79-13. "Indication of Low Water Level in Oyster Creek Reactor " KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/29

# DOCKET STN-50-488 PERKINS NUCLEAR STATION, UNIT 1

# Q Adjudicatory correspondence

7906010126 Opposes intervenors 770305 motion to reopen record for addl hearing Requests initial decision be issued Certificate of Bvc encl MCOARRY, J. H. Duke Power Co. 79/03/21 5pp

- 7906050240 Forwards memo re problems experienced in connection w/pipe support base plate design Problems are applicable to facility BARTH, C A Branch 3 79/04/05 2pp
- 7906ii0009 Forwards addi info on accumulator delivery re PWRs, as identified during continuing studies of ECCS performance NRC does not believe this matter has any effect on proceeding issues
  BARTH, C A Branch 3 79/04/05 2pp
- --7906110017 Concludes accumulator delivery behavior can have important effect on ECCS performance Suggests V8 std problem participants provide pressure & flow comparisons for all past & future std problems, where applicable ROSS,D F Assistant Director for Reactor Safety 79/04/05
- 7704040451 Denies intervenors 770305 motion to reopen record for add1 hearings Revises wording of 781027 partial initial decision. Paragraph 39 BOWERS,E 8 Atomic Safety and Licensing Doard Panel 79/04/12
- 7906020113 Opposes intervenors 790405 mution to reopen record \$\times\$ stay or suspension of licensing activities Intervenors have not satisfied criteria for stay of proceedings Certificate of Svc enc1
  BARTHIC A Branch 3 79/04/19 8pp
- H Ceneral correspondence
- 7906140576 Ltrs of concern re use of nuclear power JOHNSON.F., WINGATE, S. Affiliation Unknown FAGGART, J R Affiliation Unknown 79/04/22 5pp
- J Insurance & indemnity information
- 7906130031 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERG:F D Duke Power Co 79/06/08 5pp
- O Inspection reports, IE Bulletins & correspondence
- 7706130443 Responds to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown methods meet ASME code stds
  DAILL C Duke Power Co 79/04/20 2pp
- 7906140428 Responds to IE Bulletin 79-04 Valan valvas not in use DAIL, L C Duke Power Co 79/04/24 1p
- 7906250446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY,J P Region 2, Atlanta, Office of the Director 79/05/10 ip
- DOCKET STN-50-489 PERKINS NUCLEAR STATION, UNIT 2
- G. Adjudicatory correspondence

- 7906040451 Denies intervenors 790305 motion to reopen record for addl hearings Revises wording of 781027 partial initial decision. Paragraph 39 BOWERS, E S Atomic Sefety and Licensing Board Pagel 79/04/12
- 7904020113 Opposes intervenors 790405 motion to reopen record & stay or suspension of licensing activities Intervenors have not satisfied criteria for stay of proceedings Certificate of encl Branch 3 79/04/19 800 BARTH.C A
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS, F D Duke Power Co 79/06/08 Spp
- @ Inspection reports, IE Bulletins & correspondence
- 7906130443 Responds to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown methods meet ASME code stds
  SAILL C Dute Power Co 79/04/20 2pp
- 7906140428 Responds to IE Bulletin 79-04 Velan valves not in use DAEL.L C Dute Power Co 79/04/24 ig
- 7904250446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10
- DOCKET STN-50-490 PERKINS NUCLEAR STATION, UNIT 3
- G Adjudicatory correspondence
- 77060:0126 Upposes intervenors 770305 motion to reagen record for add1 hearing Requests initial decision be issued Certificate of Svc encl MCGARRY.J M Duke Power Co 79/03/21 5pp
- 7906040374 Forwards memo which contains info potentially relevant to issue of sabotage of spent nuclear fuel BARTH.C A Branch 3 79/04/05 2pp
- 7906050240 Forwards memo re problems experienced in connection w/pipe support base plate design Problems are applicable to facility
  BARTH.C A Branch 3 79/04/05 2pp
- 7906110009 Forwards add1 info on accumulator delivery re PHRs, as identified during continuing studies of ECCS performance NRC does not believe this matter has any effect on roceeding issues ARTH.C A Branch 3 79/04/05 2pp
- --7906110017 Concludes accumulator delivery behavior can have important effect on ECCS performance Suggests US std problem participants provide pressure & flow comparisons for all past & future std problems where applicable ROSS,D F Assistant Director for Reactor Safety 79/04/05
- 7906040451 Denies intervenors 790305 motion to reopen record for additional hearings. Revises wording of 781027 partial initial decision, Paragraph 39
  8DMERB.E B Atomic Safety and Litensing Board Panel 79/04/12
- 790±020113 Opposes intervenors 790405 motion to reapen record & stay or suspension of licensing activities intervenors have not satisfied criteria for stay of proceedings Certificate of

- O Inspection reports. IE Bulletine & correspondence
- 7906130443 Responds to IE Bulletin 79-03 Bite has received 200 ft of pipe mfg by Youngstown Helding & Engineering Co Youngstown methods meet ASME code stds DAIL.L C Duke Power Co 79/04/20 2pp
- 7906140428 Responds to IE Builetin 79-04 Velan valves not in use DAIL.L C Duke Power Co 79/04/24 ip
- 7906250446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " O'REILLY. J P Region 2, Atlanta, Office of the Director 79/05/10
- DOCKET STN-\$0-491 CHEROKEE NUCLEAR STATION, UNIT 1
- O Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAD-509 BCINTO, J F Hearings Division 77/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of Tulemaking proceeding to develop value for radon in Table S-3 Rept 2 progressed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906130443 Responds to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown methods meet ASME code stds DAIL. L C Duke Power Co 79/04/20 2pp
- 7906210095 NRC motion for summary disposition re radon issue was in error: ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc DUFLO, M. E Atomic Safety and Licensing Appeal Panel 79/05/25
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 59 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDERS.F D Duke Power Co 79/06/08 5pp
- G Inspection reports, IE Bulletins & correspondence
- 7905070284 Forwards IE Insp Repts 50-491/79-06, 50-492/79-06 & 50-493/79-06 on 790313-16 Na noncompliance noted MURPHY, C E Region 2, Atlanta, Office of the Director 79/04/06
- --7906070302 IE Insp Repts 50~491/79~06.50~492/79~06. 50~493/79~06. on 790313~16. No noncompliance noted Major areas inspected GA program.const procedures.Part 21 implementation.containment plate welding 2 vendor surveillance
  RAUSCH-J K Region 2, Atlanta, Reactor Construction & Enginearing Support Branch HERDT, AR Region 2, Atlanta, Office of the Director 79/04/05. 4pp
- ~-7906070302 IE Insp Repts 50-491/79-06.50-492/79-06 % 50-493/79-06 64 79/03/03/03 to Inspire to 50-44/1/7-06, 50-44/2/7-06 & 50-44/2/7-0
- 790614042B Responds to IE Bulletin 79-04 Velan valves not in Use BAIL.L C Duke Power Co 79/04/24 ip
- 7906190114 Act receipt of IE Inep Repts 30-491/79-08.50-492/79-09 & 50-493/79-08 on 790417-19 No proprietary info DAIL-L C Duke Power Co 79/05/08 ip
- --7906190114 Forwards IE Insp Repts 50~491/79~08,50~492/79~08 & 50~492/79~08 on 790417~19 No noncompliance noted HURPHY, C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 2pp.
- --7906190120 IE Insp Repts 50-491/79-08, 50-492/79-08 & 50-493/79-08 on 790417-19 No noncompliance noted, Major areas inspected review of GA implementing procedures for safety-related structures & containment.

  VALLISH: E J Region 2, Atlanta, Office of the Director BRYANT. J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01. Spp

- 7906200027 Responds to NRC 790413 ltr re violations noted in IE Insp Rept 50-491/78-08,50-492/78-08,50-493/78-08 Corrective actions sieves used for soil & concrete aggregate tests will be put in regular calibr program DAILL C Duke Power Co 79/05/09 ip
- 7906250446 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- S Reportable occurrences, LERs > related correspondence
- 7906140334 Forwards Final Rept 79/01-5P5-491/492/493 re recall of page fittings
  DAIL.L C Duke Power Co 79/05/10 ip
- ~-7906140336 Final Rept 79/01-3PS-491/492/493 weld fittings w/lot number W6719 contained erroneously identified high carbon steel mati that could crack when being welded All matl returned to vendor on 790412
  \* Duke Power Co 79/05/11 lp

# DECKET STN-50-492 CHEROKEE NUCLEAR STATION, UNIT 2

### Q Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO.J F Hearings Division 79/04/02 200
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 5-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7906130443 Responds to IE Bulletin 79-03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstown methods meet ASME code stds
  DATLL C Duke Power Co 79/04/20 2pp
- 7906210095 NRC motion for summary disposition re radon issue was in error:ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl DUFLOIME Atomic Safety and Licensing Appeal Panel 79/05/25
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Policy NF-182 & Endorsements 40 & 41 to MAELU Policy MF-61 SANDER8.F D Duke Power Co 79/06/08 Spp
- O Inspection reports, IE Bulletins & correspondence
- 7906070284 Forwards IE Insp Repts 50-491/79-06.50-492/79-06 t 50-493/79-06 on 790313-16 No noncompliance noted MURPHY,C E Region 2, Atlanta, Office of the Director 79/04/06 2pp
- --7904070302 IE Insp Repta 50-491/79-06.50-492/79-06 & 50-493/79-06 on 790313-16 No noncompliance noted Major areas inspected GA program, const procedures, Part 21 implementation, containment plate welding & vendor surveillance RAUSCH.J K. Region 2. Atlanta, Reactor Construction & Engineering Support Branch HERDT, AR. Region 2. Atlanta, Office of the Director 79/04/05 4pp
- 7906140428 Responds to IE Bulletin 79-04 Velam valves not in use DAIL, L. C. Duke Power Co. 79/04/24 ip
- 7906190114 Ack receipt of IE Insp Repts 50-491/79-08,50-492/79-08 & 50-493/79-08 on 790417-19 No proprietary info DAIL.L C Duke Power Co 79/05/08 1p
- --7906190116 Forwards IE Insp Repts 50-491/79-08, 50-492/79-08 & 50-493/79-08 on 790417-19 No noncompliance noted MURPHy.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 2pp
- ---7906190120 IE Insp Repts 30-491/79-08, 50-492/79-08 & 50-493/79-08 on 790417-19 No noncompliance noted Major areas inspected review of 94 implementing procedures for safety-related structures & containment VALLISH, E. J. Region 2. Atlanta, Office of the Director BRYANT, J. C. Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 5pp

- 7906200027 Responds to NRC 790413 ltr re violations noted in IE Insp Rept 50-491/78-08.50-492/78-08.50-493/78-08 Corrective actions sieves used for soil & concrete aggregate tests will be put in regular calibr program DAIL.L C Dute Power Co 79/05/09 ip
- 7906250446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " D'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 to
- S Reportable occurrences, LERs & related correspondence
- 7906140334 Forwards Final Rept 79/01-5PS-491/492/493 re recall of pipe fittings
  DAIL.t. Duke Power Co 79/05/10 1p
- --7906140336 Final Rept 79/01-5P8-491/492/493 weld fittings w/lot number W6719 contained erroneously identified high carbon steel mat1 that could crack when being welded All mat1 returned to vendor on 790412

  \* Duke Power Co 79/05/11 1p

## DOCKET BTN-50-493 CHEROKEE NUCLEAR STATION, UNIT 3

- O Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-BO9 SCINTO.JF Hearings Division 79/04/02 2pp
- ---7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of rador releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906130443 Responds to FE Bulletin 79~03 Site has received 200 ft of pipe mfg by Youngstown Welding & Engineering Co Youngstwon methods meet ASME code stds DAIL.L C Duke Power Ca 79/04/20 2pp
- 7906210095 NRC motion for summary disposition re radon issue was in error.ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLO.H E Atomic Safety and Licensing Appeal Panel 79/05/25
- J Insurance & indemnity information
- 7906130331 Forwards Endorsements 54 & 55 to ANI Police NF-182 & Endorsements 40 & 41 to MAELU Police MF-61 SANDERS F D Duke Power Co 79/06/08 Spp
- O Inspection reports, IE Bulletins & correspondence
- 7706070284 Forwards IE Insp Repts 50-491/79-06.50-492/79-06 & 50-493/79-06 on 790313-16 No noncompliance noted MURPHY:C E Region 2. Atlanta, Office of the Director 79/04/06 2an
- --7906070302 IE insp Repts S0-491/79-06, 50-492/79-06 & 50-493/79-06 on 790313-16 No moncompliance noted Major areas inspected QA program, const procedures, Part 21 implementation; containment plate welding & vendor surveillance RAUSCH, JK Region 2, Atlanta, Reactor Construction & Engineering Support Branch HERDT, AR Region 2, Atlanta, Office of the Director 79/04/05 4pp
- 7706140428 Responds to IE Bulletin 79-04 Velan yelves not in use DAIL.L C Duke Power Co 79/04/24 ip.
- 7906190114 Ack receipt of IE Insp Repts 50-491/79-08,50-492/79-08 \$ 50-493/79-08 on 790417-19 No proprietary info DAIL, L C Duke Power Ca 79/05/08 ip
- --7906190116 Forwards 1E Insp Repts 50-491/79-08,50-492/79-08 & 50-493/79-08 en 790417-19. No noncompliance noted MURPHY.C.E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/05/01 2pp
- --7906190120 IE Insp Repts 50-491/79-08, 50-492/79-08 & 50-492/79-08 on 790417-19 No noncompliance noted Major areas inspected review of QA implementing procedures for safety-related structures & containment.

  VALLISH, E. J. Region 2, Atlanta, Office of the Director BRYANT, J C. Region 2, Atlanta, Reactor Construction & Engineering Support Branch. 79/05/01 Spp

- 7906200027 Responds to NRC 790413 ltr re violations noted in IE Insp Rept 50-491/78-08, 50-492/78-08, 50-493/78-08 Corrective actions sieves used for soil, 5 concrete aggregate tests will be put in regular calitor program DAIL.L C Bute Power Co 79/03/09 ip
- 7906250446 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1o
- S Reportable occurrences. LERs & related correspondence
- 7906140334 Forwards Final Rept 79/01-598-491/492/493 re recall of pipe fittings
  DAIL-L C Duke Power Co 79/05/10 ip
- --7906140336 Final Rept 79/01-5PS-491/492/493 weld fittings u/lot number W6719 contained erroneously identified high carbon steel matl that could crack when being welded All matl returned to vendor on 790412

  \* Duke Power Co 79/05/11 1p

#### DOCKET STN-50-495 SHESSAR-P1

- A Application/construction stage documents & correspondence
- 7906010169 Forwards Amend 2 to Preliminany Design Approval-4 & FR notice
  BOYDER 6 Division of Project Management 79/05/04 9pp
- --7906010169 Extends expiration date of Preliminary Design Approval-4 from 790505 to 790605
  BOYD, R 8 Division of Project Management 79/05/04 2pp
- --7906010171 Notifies of extension of expiration date of Preliminary Design Approval-4 from 790503 to 790605 HELTEMES, C J Standardization Branch 79/05/04 4pp

### DOCKET STN-50-498 SOUTH TEXAS PROJECT, UNIT 1

- A Application/construction stage documents & correspondence
- 7906110414 Forwards "Marviken Full-Scale Critical Flow Tests Interim ReptrResults from Test 7 " Rept to assist NRC in responding to request for justification of use of BATAN-V methods for prediction of flow through orifices W/o encl PARR-O D Light Water Reactors Branch 3 79/05/08 3pp
- 7906250075 Requests add1 into by 790716, for review of FSAR PARR.O D Light Water Reactors Branch 3 79/05/22 5pp
- 7906250190 Gummary of 790510 meeting w/util in Bethesda,MD re soil/ structure interaction analysis LICITRA:EA Light Water Reactors Branch 3 79/05/23 5pp

## @ Adjudicatory correspondence

7906050403 Notifies that LA Sinkin will replace C Ryan as group representative before Board in potition to intervene in DL request by util Certificate of Box encl
JANEK.S M Citizens Concerned About Nuclear Power, Inc 79/04/14

- 7906230096 Opposes applicant brief appealing ABLB prehearing conference order ruling on intervention petitions Untimely submittal of petition to intervene due to mitigating circumstances
  BUCHORN, P. Affiliation Unknown 79/04/30 13pp
- 7906040040 Grants Citizens Concerned About Nuclear Power until 790314 to respond to applicants' brief on appeal DUFLO:M E Atomic Safety and Licensing Appeal Panel 79/05/01 ip
- 7906200601 Motion to strike applicant 790417 appeal & 790416 brief Brief & appeal are not in compliance w/NRC rules of practice Notice of appearance & Certificate of Svc encl SINKIN,S A Citizens Concerned About Nuclear Power, Inc. 79/05/01
- 7906190032 Responds to applicant 790417 brief appealing 790403 prehearing conference order granting intervention petitions ASLB did not abuse its discretion nor err in finding standing Certificate of Syc encl MCGURREN.H Branch i ULMAN.M B Operations & Administrative Division 79/05/02 28pp
- 7906190132 Denies motion by Citizens Concerned About Nuclear Power to strike applicant appeal from order granting intervention Applicant papers satisfy criteria of 10CFR2 714a
  SKRUTGKI.R H Atomic Safety and Licensing Appeal Panel 79/05/07 2pp
- 7906130430 Supports ALAB-349 allowing Citizens Concerned About Nuclear Power, Inc to intervene as party opposing issuance of DL Defers Citizens for Equitable Utils petition to Board for Judgment in favor of admission

  EKRUTSKI, R M Atomic Safety and Licensing Appeal Panel 79/03/18
- 7906260055 Submits reformulated contentions re denial of GL Facility has not been built in compliance w/safety stds.no reasonable assurance exists re public health 5 safety & applicant has violated 10CFR50 of GC requirements

  BINKIN.t A Citizens Concerned About Nuclear Power, Inc. 79/05/29
  400
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 7906130314 Forwards Amend 6 to FBAR Certificate of Byc encl TURNER, E A Houston Lighting & Power Co 79/06/11 3pp
- --7906130315 Amend 6 to FSAR \* Houston Lighting & Power Co 79/06/11 200pp

# M Antitrust correspondence

- 7906070311 Notice of appearance of MG Berger on behalf of DOJ Certificate of Svc encl BEROER,M G Justice,Dept of 79/03/19 4pp
- 7906070317 Answer of TX Util Co & subsidiaries to Central Power & Light's first set of interrogatories & request for production of documents Affidavit & Certificate of Svc encl WORSHAM, J I , SAMPELS, M D Worsham, Forsythe & Bampels 79/03/28 1690
- 7906060030 TX Utils Cenerating Co discovery rept for Mar 1979 responded to interrogatories & document requests from NRC, City of Brownsville & Central Power & Light & submitted response to NRC mation to compel M/Centificate of Svc. KNGTTS, J B Debevoise & Lieberman 79/04/05 Spp
- 7906020255 Supplemental answers by TX Utils Generating Co & subsidiaries to first set of interrogatories & request for production of documents from DOJ Supporting documentation & Certificate of Svc encl.

  MDRSHAM.J I , SAMPELBIM.D Worsham, Forsythe & Sampels KNOTTE, J & Debeyoise & Lieberman 79/04/11 40pp
- 7906040417 Request by Houston Lighting & Power for extension, until 790430, for filing replies to motions for summary disposition Certificate of Sec encl BARNETT, E W Baker & Botts BOUKNIGHT, J A , FRANKLIN, W J Lowenstein Newman, Reis, Axelred & Toll 79/04/11 Spp
  - 020129 Response by DOJ to various motions of Houston Lighting & wer.TX Utils Generating Cq & City of Austin Supporting cumentation & Certificate of Svc encl
    RRIS.J L , BERGER, M O., CLARK, R H Justice, Dept of 79/04/23

- 7906040454 Denies 790405 motion filed by Public Utils Board of City of Brownsville.TX to compel further production of documents by South TX Electric Cooperative & Medina Cooperative MILLERIM E Atomic Safety and Licensing Board Panel 79/04/23
- 7906080141 Motion by Gulf States Utils Co for protective order re confidential info Requests production of documents per 790226 subpoens be conditioned on reimbursement of expenses Supporting documentation & Certificate of Svc encl HETTERHAHN.M J Conner, Moore & Corber 79/04/25 29pp
- 7906020009 Addl responses by Houston Lighting & Power to DOJ first set of interrogatories & request for production of documents

  Certificate of Svc encl Baker & Botts 79/04/27 31pp COPELAND, J G
- 7906190034 Forwards second supplemental answer of TX Utils Generating Co to DOJ first interrogatories & requests for production of documents forwarded per 790418 meeting SLICKER,F K Worsham Forsythe & Sampels 79/04/27 1p
- --7906190043 Second supplemental answer by TX Utils Generating Co to DOJ first interrogatories & requests for production of documents Supporting documentation & Certificate of Svc WORSHAM, I . SAMPELS. M D Horsham. Forsythe & Sampels KNOTTS, J B Debevoise & Lieberman 79/04/27 24pp
- 7906010243 Forwards reply of Houston Lighting & Power Co in support of motion for summary disposition Certificate of Svc encl WEISS.T F Bater & Botts 79/04/30 7pp
- --7906010260 Reply by Houston Lighting & Power Co in support of motion for summary judgment Urges that request for application of collateral estoppel against Central Power & Light be granted Certificate of Svc encl BARNETT,E W Baker & Botts BOUKNIGHT,J A Lowenstein, Newman, Reis, Azelrad & Toll 79/04/30 32pp
- 7906020119 Response by Public Utils Board of City of Brownsville,TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Svc encl JABLON,R A Spiegel & McDiarmid 79/04/30 3Bpp
- 7904020165 Answer in opposition to Houston Lighting & Power motion to compet NRC production of privileged documents Certificate of Syc encl LESSY.R . BLUME, M Anti-Trust Division 79/04/30 10pp
- 7906020209 Response by Houston Lighting & Power to NRC 790419 motion for reconsideration of ASLB 790416 order. Requests that ASLB affirms order recreation of new documents not maintained in normal course of business Certificate of Byc encl.

  BOUKNIGHT, J A : FRANKLIN.W J Lowenstein, Newman, Reis, Axelrad & Toll BARNETT, E W Baker & Botts 79/04/30 lipp
- 7906020250 Reply by TX Utils Generating Co to combined answer of Central Power & Light & Central & Southwest in opposition to former's 790403 motion to dismiss Central & Southwest as intervenor Wypertinent documentation & Certificate of Svc KNOTTS, J B Debevoice & Lisberman. WDRSHAM, J I . SAMPELB, M D Worsham, Forsythe & Sampels 79/04/30 18pp
- 7906040393 Supplemental motion by Guif States Util amending protective order & order for setting conditions for compliance w/subpoena Certificate of Svc enc. RADER:R M Conner, Moore & Corber 79/04/30 6pp
- 790&190034 Discovery progress rapt for Apr 1979 Responded to TX Utila Generating Co & Houston Lighting & Power Interrogatories Mat w/utils on 790418 Certificate of Svc enc! HARRIS, J. L., BERGER, M. O., CLARK, R. H. Justice, Dept of 79/04/30
- 7905200299 Forwards Public Utils Boards of City of Brownsville,TX response to Houston Lighting & Power Co first set of interrogatories & first request for production of documents Affidavit & Certificate of Svc enc!
  WHITE
- 7906200576 TX Utils Generating Co answer to Central Power & Light 700420 motion to compel further responses to latter finterrogatories. Previously supplied answers are complete & fair; add1 demands by Central Fower are redundant KNOTTS: J.B. Debevoise & Lieberman. BAMPELB: M D , WORSHAM, J. I. Worsham, Forsythe & Sampels. 79/03/02. 6pp

- 7906290762 Submits Apr 1979 discovery progress rept for City of San Antonio Certificate of Syc encl HILSON, W. R. Matthews, Nowlin, Macfarlane & Barrett 79/05/02 4pp
- 7904070034 Discovery status rept for Apr 1979 NRC filed answer in apposition to motion of Houston Lighting & Power Co to compel production of privileged documents

  LESSY,R P Anti-Trust Division 79/05/03 2pp
- 7904040122 TX Utils Generating Co discovery progress regt for Apr 1979 responded to interrogatories from DDJ.met w/DDJ & NRC \$ andeavored to coordinate remaining discovery w/City of Brownsville.TX Certificate of Svc encl
  KNOTTS.J B Debevoise & Lieberman 79/05/04 5pp
- 7906230151 South TX Electric Cooperative & Medina Electric Cooperative monthly discovery rept for Apr 1979 no new discovery requests initiated or received during month JOHN D F Akin. Gump. Hauer & Feld 79/05/04 4pp
- 7906190140 Response by Houston Lighting & Power to Central Power & Light 790420 motions to compel answers to interrogatories Provides info re preparation of previous answers Certificate of Svc encl of Syc enc.: BARNETT.E W. Baker & Botts 79/05/07 10pp
- 7908210405 Rules on discovery, in response to NRC 790419 motion for reconsideration of ASLB 790416 order Upholds order reprotection of settlement documents & excepting Houston Lighting & Power from producing certain documents MILLER, M E Atomic Safety and Licensing Board Panel 79/05/07
- 7904040032 Second request for util supplemental production of nontechnical documents
  BLUME,MB Ants-Trust Division 79/05/09 ip
- 7904020137 Answer by Public Utils Board of City of Brownsville.TX to 790425 & 790430 motions by Oulf States Util re compliance w/790226 subpoens duces tecum from ASLB Supporting documentation & Certificate of Svc ancl MCDIARMID.R C , POIRER.M R Spiegol & McDiarmid 79/05/10 90pp
- 7904020037 Answer in opposition to Gulf States Util 790425 motion for protective order & for order setting conditions for compliance u/790226 subposes for production of documents Certificate of Svc encl
  HARRIS, J. L. Justice, Dept of 79/05/11 19pp
- 7906020167 Notices of appearance by SB Cyphert & RH Clark on behalf of DDJ Certificate of Svc encl CYPHERT, S B , CLARK, R. H Justice, Dept of 79/05/11 5pp
- 7906250426 Houston Lighting & Power Co petition for extension until 790529 to compel further responses from Public Utils Board of City of Brownsville, TX Addl time required to determine scape of planned motion Certificate of Svc encl FRANKLIN, W J . BOUXNIGHT, J A Lowenstein, Newman, Reis, Axelrad & Toll BARNETT, E W Bater & Botts 79/05/11 Epp
- 7906190147 Answers first set of interrogatories & request for production of documents submitted by TX Utils Generating Co Supporting documentation & Certificate of Svc encl LESSY.R P , BLUME.M B Anti-Trust Division 79/05/14 10pp
- 7906070312 Notice of 790601 conference in Bethesda, MD to discuss pending motions & responses re discovery & summary disposition
  MILLER, M E Atomic Bafety and Licensing Doard Panel 79/05/15 ip
- 7706280109 Motion by Houston Lighting & Power to include Central Power & Light within ASLE 770407 protective order setting terms for production of confidential documents to Public Utils Board of City of Brownsville.TX Certificate of Svc encl BARNETT.E.M. Baker & Botts. BOUKNIGHT.J.A Lowenstein, Newman, Reis, Axelrad & Toli 77/05/15 9pp
- 7906070046 Motion by Gulf States Utils Co to file brisf in reply to DUJ & City of Brownsville, TK answers to previous util motion & supplemental motion for protective order Seeks to clarify third party status.

  METTERHANN
- 7906070315 Grants Houston Lighting & Power Co 790511 motion for extension of time.until 790529.for filing motion to compel further production from City of Brownsville.Tx MILLER,M E. Atomic Safety and Licensing Board Panel 79/05/16
- 7906190124 Requests RM Rader & DM Clements be added to svc list RADER, R H Conner. Moore & Corber. 79/05/16 1p.

- 7906020096 All Houston Lighting & Power confidential documents, produced for Public Utils Board of City of Brownsville.TX & reviewed by Gentral Power & Lightishall be subjt to terms & conditions of 790409 protective order MILLERIM E Atomic Safety and Licensing Board Panel 79/05/18 in
- 7906/30410 Grants Gulf States Util 790506 motion requesting leave to file reply brief in response to DDJ & City of Brownsville.TX answers to util request for protective order MILLER:H E Atomic Safety and Licensing Board Panel 79705/22 ip
- 7906280232 Gulf State Utils reply brief to DOJ & Public Utils Board of City of Brownsville.TX answers in response to util motion for protective order & order setting conditions for compliance w/subpoena Affidavit & Certificate of Svc encl HETTERHAHN.H J . RADER,R M Conner. Hoore & Corber 79/05/31
- 7906290596 TX Utils Generating Co discovery rept for May 1979 util provided supplementary responses to NRC interrogatories & requests for production of documents Certificate of Svc encl NNOTTS.J B Debeyoise & Lieberman 79/06/06 5pp
- G Inspection reports, IE Bulletins & correspondence
- 7906230044 Forwards IE Insp Repts: 50~498/79-04 & 30-499/79-04 on 790320-23 & notice of violation SEIDLE.W C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7905250047 Notice of violation from insp on 790320-23
  \* Region 4, Dallas, Office of the Director 79/04/11 2pp
- --7906250051 IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790320-23
  Nancompliance noted failurs to follow concrete placement
  procedures
  HUBACEK, H G Region 4, Dallas, Office of the Director
  HALL, R E Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/04/11 Spp
- 7906110002 Forwards 1E Dulletin 79-05B. "Nuclear Incident at TMI-Suppl " No written response required SEYFRIT.K V Region 4. Dallas. Office of the Director 79/04/21
- 7906210107 Second interim rept of reportable deficiency dimensional error in base slab of mechanical-electrical Unit 2 auxiliary bidg Describes progress on redesion of bidg Final rept will not be available by 790501

  TURNER, E A Houston Lighting & Power Co 79/04/24 2pg
- 7906210109 Confirms 790426 & 27 telcons re improper storage of reinforcing steel NRC understands that util has found no significant departures exist from reinforcing steel requirements of site quality const procedures SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/01
- 7906120067 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required SEYFRIT.K V Region 4. Dallas. Office of the Director 79/05/07 ip
  - \* temptod Damage to New Fuel the Director 79/05/11

- S Reportable occurrences. LERs & related correspondence
- 7906180156 Forwards PNO-79-67AM
  SEIDLE, W C Region 4, Dailas, Reactor Construction & Engineering
  Support Branch 79/05/08 ip
- 7906180176 Forwards PNO-79-67AN
  SEIDLE:W C Region 4. Dallas, Reactor Construction 3 Engineering
  Support Branch 79/05/16 ip
- 7906180243 Forwards PND-79-67AD
  SEIDLE:W C Region 4. Dallas, Reactor Construction & Engineering
  Support Branch 79/05/22 ip
- 7906180320 Forwards PNO-79-67AP
  SEIDLE: W C Region 4, Dallas, Reactor Construction & Engineering
  Support Branch 79/05/23 ip
- 7906120390 Forwards final deficiency rept re concrete voids behind liner plate in reactor bldg exterior wall TURNER, E.A. Houston Lighting & Power Co. 79/06/05 1p
- --7906120397 Final deficiency rept on 781020 15th lift concrete voids
  Caused by inadequate planning for large pour long pour time,
  longer than normal slick lines & concrete pump breakdowns
  Immediate & long-term corrective actions have been effected
  # Houston Lighting & Power Co 79/06/15 13pp
- 7906120430 Second interim rept of deficiency ie improper anchor bolt mattl Final rept will not submitted until 790815, due to complesity of identifying & testing suspect bolts
  TURNER, E A Houston Lighting & Power Co 79/06/05 2pp
- 7906130007 Forwards final deficiency rept re failure to properly consider application of certain postulated loads in interior structural steel beams Deficiency would not have resulted in significant safety hazard TURNER, EA Houston Lighting 1/2 Power Co 79/06/05 2pp
- --7906130008 Final deficiency rept on 781025 beam-to-column connections Caused by human error & inadequate procedural training Beams have been reanalyzed, errors corrected & calculations design verified

  # Houston Lighting & Power Co 79/06/05 8pp
- 7906220367 Interim deficiency rept on 790516 essential cooling water gantry crane not designed to withstand DBT Caused by breakdown in design change program Design & change procedure being corrected TURNER, E.A. Houston Lighting & Power Co. 79/06/15 App.
- T Hearing transcripts on non-antitrust matters
- 7706180736 Transcript of 770601 hearing in Bethesda,MD Pp 213-471 MILLER, M & . WOLFE, S J Atomic Safety and Licensing Board Panel 79/06/01 260pp
- U Congressional/Executive Correspondence
- 7906070043 Requests info on Westinghouse reactor design & possibility of facility mod in light of TMI incident PICKLE. J J House of Rep 79/04/25 2pp
- 7906270271 Responds to 790416 itr which forwarded J Lowry 790404 itr requesting info on safety of plant const & operation Forwards "Summany of Progress of South TX Plant," providing general info re facility CDSSICK,L V Office of the Executive Director for Operations 79/05/22 4pp
- --7906290285 Forwards J Lowry 790404 ltr requesting info on wafety of plant const & operation SCHWEIKER,R S Benate 79/04/16 2pp
  - T STN-50-499 SOUTH TEXAS PROJECT, UNIT 2
  - plication/construction stage documents & correspondence
  - 10414 Forwards "Marviken Full-Scale Critical Flow Tests Interim t:Results from Test 7 " Rept to assist NRC in responding request for justification of use of SATAN-V methods for diction of flow through on files N/o and R

Ī

50075 Requests add1 info by 790716.for review of FSAR R.O D Light Water Reactors Branch 3 79/05/22. 5pp

# DOCKETED ITEMS

- 7906250190 Summary of 790510 meeting w/util in Bethesda.MD re soil/ atructure interaction analysis LTCITRA.E A Light Water Reactors Branch 3 79/05/23 Spp
- G Adjudicatory correspondence
- 7706050403 Notifies that LA Sinkin will replace C Ryan as group representative before Board in petition to intervene in OL request by util Certificate of Svc anci JANEX,S M Citizens Concerned About Nuclear Power, Inc 79/04/14 5pp
- 7904070223 Motion for continuance so as to comply w/ASLB 790403 order re intervention Certificate of Syc encl BUCHORN,P Affiliation Unknown 79/04/22 5pp
- 7906070304 Applicants' supplemental memo re 790417 appeal of 790403 prehearing conference order Since Austin Citizens for Economical Energy have not filed info per order/790417 appeal should be treated as moot Certificate of Svc encl NEWMAN, J R , REIS, H F Lowenstein, Nowman, Reis, Azelrad & Toll THRASH, C G Baker & Botts 79/04/27 3pp
- 790A070169 Intervenor's motion for extension of time.until 790514, to respond to applicant's brief on appeal SINKIN, L. A. Citizens Concerned About Nuclear Power, Inc. 79/04/30 to
- 7906200231 Grants NRC 790420 motion for extension until 790529 for parties to file repts on contentions
  BECHHOEFER.C Atomic Safety and Licensing Board Panel 79/04/30
- 7906230096 Opposes applicant brief appealing ASLB prehearing conference order ruling on intervention petitions Untimely submittal of petition to intervene due to mitigating circumstances

  BUCHORN,P Affiliation Unknown 79/04/30 13pp
- 7906040040 Grants Citizens Concerned About Nuclear Power until 790514 to respond to applicants' brief on appeal DVFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/01 ip
- 7905200601 Motion to strike applicant 790417 appeal & 790416 brief Brief & appeal are not in compliance w/NRC rules of practice Notice of appearance & Certificate of Svc encl BINKIN.S A Citizens Concerned About Nuclear Power, Inc 79/05/01
- 7906190032 Responds to applicant 790417 brief appealing 790403 prehearing conference order granting intervention potitions ASLB did not abuse its discretion nor err in finding standing Certificate of Svc encl MCGURREN, H Branch 1 ULMAN, M A Operations & Administrative Division 79/05/02 20pp
- 7906190132 Denies motion by Citizens Concerned About Nuclear Power to strike applicant appeal from order granting intervention Applicant papers satisfy criteria of IOCFR2 714a SKRUTSKI,R M Atomic Safety and L(censing Appeal Panel 79/05/07 20p
- 7906130430 Supports ALAB-54? allowing Citizens Concerned About Nuclear Power, Inc to Intervone as party opposing issuance of OL Defers Citizens for Equitable Utils petition to Board for judgment in favor of admission SKRUTSKI.R M Atomic Safety and Licensing Appeal Panel 79/05/18
- 7904240055 Submits reformulated contentions re denial of OL Facility has not been built in compliance w/safety stds.no reasonable assurance exists re public health 5 safety & applicant has violated 100FR50 of GC requirements

  SINKIN.L A Citizens Concerned About Nuclear Power, Inc 79/05/29
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 7906130314 Forwards Amend 6 to FSAR Certificate of Svc encl TURNER.E A Houston Lighting & Power Co 79/06/11. 3pp
- --7906130315 Amend 6 to FBAR \* Houston Lighting & Power Go 79/06/11 200pp
- M Antitrust correspondence
- 7906070311 Notice of appearance of MG Berger on behalf of DQJ Certificate of Svc encl BERGER,M G Justice.Dept of 79/03/19 4pp

- 7906070317 Answer of TX Util Co & subsidiaries to Central Power & Light's first set of interrogatories & request for production of documents Affidavit & Certificate of Svc encl WOR8HAM. J 1 Worsham. Forsythe & Sampeis 79/03/28 16pp
- 7906060030 TX Utils Cenerating Co discovery rept for Mar 1979 responded to interrogatories & document requests from NRC. City of Brownsville & Central Power & Light & submitted response to NRC motion to conpel W/Certificate of Svc KNOTTS.J B Debevoise & Lieberman 79/04/05 5pp
- 7906020255 Supplemental answers by TX Utils Generating Co & subsidiaries to first sat of interrogatories & request for production of documents from DOJ Supporting documentation & Certificate of Svc enc!

  WDRSHAM.J I Worsham. Forsythe & Sampels 79/04/11 40pp
- 7906040417 Request by Houston Lighting & Power for extension,until 790430, to file replies to motions for summary disposition Certifiate of Syc enci BARNETT,E W Daker & Botts 79/04/11 Spp
- 7906020127 Response by DOJ to various motions of Houston Lighting & Power.TX Utils Generating Co & City of Austin Supporting documentation & Certificate of Svc encl
  HARRIS.J L Justice, Dept of 79/04/23 62pp
- 7906040454 Denies 790405 motion filed by Public Utils Board of City o Brownsville.TX to compel further production of documents by South TX Electric Cooperative & Medina Cooperative MILLER,M & Atomic Safety and Licensing Board Panel 79/04/23
- 7904080141 Mation by Gulf States Utils Co for protective order re confidential info Requests production of documents per 790226 subpoena be conditioned on reimbursoment of expenses Supporting documentation 2 Cortificate of Svc encl WETTERHAHN,M J Conner, Moore & Corber 79/04/25 29pp
- 7906020009 Add1 responses by Houston Lighting &Power to DOJ first set of interrogatories & request for production of documents Certificate of Svc oncl COPELAND. J G Baker & Botts 79/04/27 Sipp
- 7906190034 Forwards second supplemental answer of TY Utils Generating Co to DOJ first interrogatories & requests for production of documents, forwarded per 790418 meeting SLICKER, FK Worsham, Forsythe & Sampels 19/04/27 ip
- --7906190043 Second supplemental answer by TX Utils Generating Co to E first interlogatories & requests for production of documents Supporting documentation & Certificate of Svc encl WORSHAM, I Worsham, Forsythe & Sampels 79/04/27 24pp
- 7906010243 Forwards repty of Houston Lighting & Power Co in support of motion for summary disposition Certificate of Svc encl WEIGS.T F Baker & Botts 79/04/30 7pp
- --7906010260 Reply by Houston Lighting & Power Go in support of motion for summary Judgment Urges that request for application of collateral astoppel against Central Power & Light be granted Certificate of Svc ancl BARNETT.E W Bater & Botts BOUKNIGHT.J A Lowenstein Newman, Reis.Axelrad & Toll 79/04/30 32pp
- 7906020119 Response by Public Utils Board of City of Brownsville.TX to Central Power & Light Co first set of interrogatories & request for production of documents Certificate of Syc encl JADLON.R A Spiegel & McDiarmid 79/04/30 38pp
- 7906020165 Answer in opposition to Houston Lighting & Power motion to campel NRC production of privileged documents Certificate of Svc encl
  LESSY, R Anti-Trust Division 79/04/30 10pp
- 7906020209 Respanse by Houston Lighting & Power to NRC 790419 motion for reconsideration of ASLB 790416 order Requests that ASLB affirms order re-creation of new documents not maintained in normal course of business Certificate of Syc encl BOUKNIGHT, J A Lowenstein, Newman, Reis, Axe) rad & Toll 79/04/30 files
- 7904020250 Reply by TX Utils Generating Co to combined answer of Central Power & Light & Central & Southwest in opposition to Former's 790403 motion to dismiss Central & Southwest as Intervenor W/pertinent documentation & Certificate of Svc KNOTFS, J B Debevoise & Lieberman 79/04/30 18pp

- 7904040393 Supplemental motion by Gulf States Util amending protective order & order for setting conditions for compliance w/subpoena Certificate of Svc encl
  RADER,R M Conner, Moore & Corber 79/04/30 6pp
- 7906190054 Discovery progress rept for Apr 1979 Responded to TX Utils Generating Co & Houston Lighting & Power Interrogatories Het W/utils on 790418 Certificate of Svc encl HARRIS.J L Justice.Dept of 79/04/30 6pp
- /906200299 Forwards Public Utils Boards of City of Brownsvills,TX response to Houston Lighting & Power first set of interrogatories & first request for production of documents Affidavit & Certificate of Bvc encl
  WHITE.S G Spiegel & McDiarmid 79/05/02 & pp
- ---7906200500 Public Utils Board of Brownsville response to Houston Lighting & Power Co first interrogatories & first request for production of documents JABLON,R A Spiegel & McDiarmid 79/05/02 filpp
- 7906200576 TX Util Generating Co answer to Central Power & Light 790420 motion to compel further responses to latter's interrogatories Previously supplied answers are complete & fairiaddl demands by Central Power are redundant MNOTTS. J B Debevoise & Lieberman 79/05/02 6pp
- 7906290762 Submits Apr 1979 discovery progress rept for City of San Antonio Certificate of Svc encl BILSDN, B R Matthews, Nowlin, Macfarlane & Barrett 79/05/02 4pp
- 7906070034 Discovery status rept for Apr 1979 NRC filed answer in opposition to motion of Houston Lighting & Power Co to compel production of privileged documents
  LESBY, R P Anti-Trust Division 79/05/03 2pp
- 7904040122 TX Utils Generating Co discovery progress rept for Apr 1979 responded to interrogatories from DOJ.met w/DOJ & NRC & endeavored to coordinate remaining discovery w/City of Brownsville.TX Certificate of Syc enci
- 7906230151 South TX Electric Cooperative & Medina Electric Cooperative monthly discovery rept for Apr 1979 no new discovery requests initiated or received during month JOHN.D F Akin. Gump. Hauer & Feld 79/05/04 4pp
- 7906190140 Response by Houston Lighting & Power to Central Power & Light 790420 motions to compel answers to interrogatories Provides into re preparation of previous answers Certificate of Eve enc!

  BARNETT.E H Baker & Botts 77/05/07 10pp
- 7906210405 Rules on discovery, in response to NRC 790419 motion for reconsideration of ASCB 790416 order Upholds order reprotection of settlement documents & excepting Houston Lighting & Power from producing certain documents MILLER, M E Atomic Safety and Licensing Board Panel 79/05/07
- 7904040032 Second request for util supplemental production of nontechnical documents
  RLUME, M.B. Anti-Trust Division 79/05/08 ip
- 7906020137 Answer by Public Utile Board of City of Brownsville.Tx to 790425 & 790430 motions by Guif States Util re compliance w/790226 subports duces tecum from ASLB Supporting documentation & Certificate of Syc encl HCDIARHID.R C Spiegel & McDiarmid 79/05/10 90pp
- 7906020037 Answer in opposition to Gulf States Util 790425 motion for protective order & far order setting conditions for compliance w/790226 subposens for production of documents Certificate of Svc encl HARRIS.J L Justice, Dept of 79/05/11 19pp
- 7906020167 Notices of appearance by SB Cyphert & RH Clark on behalf of DOJ Certificate of Svc encl
  CYPHERIAS B Justica. Dept of 79/09/11 Spp
- 7906230426 Houston Lighting & Power Co petition for extension until 790529 to compel further responses from Public Utils Board of City of Brownsville.TX Add time required to determine scope of planned motion Certificats of Syc encl FRANKLIN.W J Lowenstein.Newman.Reis.Axelrad & Toll 79/05/11 Bpp
- 7906190147 Answers first set of interrogatories & request for production of documents submitted by TX Utils Generating Co Supporting documentation & Certificate of Svc enci. LESS,R.P. Anti-Trust Division 79/05/14 10pp

- 7906070312 Notice of 790601 conference in Bethesda. MD to discuss pending motions & responses re discovery & summary disposition MillER. M E Atomic Safety and Licensing Board Panel 79/09/15 [p
- 7906280105 Mation by Houston Lighting & Power to include Central Power & Light within ASLB 790407 protective order setting terms for production of confidential documents to Public Utils Board of City of Brownsville, TX Certificate of Svc encl BARNETT.E H Baker & Botts 79/05/15 9pp
- 7906070046 Motion by Gulf States Utils Co to file brief in reply to DOJ & City of Brownsville, TX answers to previous util motion & supplemental motion for protective order Seeks to clarify third party status
  WETTERHAHN, M J Conner, Moore & Corber 79/05/16 7pp
- 7906070315 Grants Houston Lighting & Power Co 790511 motion foror extension of time, until 790929, for filing motion to compel further production from City of Brownsville.Tx MILLER, M E Atomic Safety and Licensing Board Panel 79/05/16 ig.
- 7906190124 Requests RM Rader & DM Clements be added to svc list RADER,R M Conner, Moore & Corber 79/05/16 1p
- 7706020096 All Houston Lighting & Power confidential documents, produced for Public Utils Board of City of Brownsville,TX & reviewed by Central Power & Light-shall be subj to terms & conditions of 770409 protective order HILLER.M E Atomic Safety and Licensing Board Panel 79/05/10 lp
- 7906130418 Grants Gulf States Util Co 790506 motion requesting leave to file reply brief in response to DQJ & City of Brownsville.TX answers to util request for protective order MiLLER.M E Atomic Gafety and Licensing Board Panel 79/05/22 ip
- 7906280232 Oulf State Utils reply brief to DOJ & Public Utils Board of City of Brownsville.TX answers in response to util motion for protective order & order setting conditions for compliance w/subpoena Affidavit % Certificate of Svc encl WETTERHAHN,M J. RADER,R M Conner, Moore & Corber 79/05/31 37pp
- 7906290596 TX Utils Generating Co discovery rept for May 1979 util provided supplementary responses to NRC interrogatories & requests for production of focuments Certificate of Sycencl KNOTTB, J B Debevoise & Lieberman 79/06/06 5pp
- O Inspection reports. IE Bulletins & correspondence
- 7906250044 Forwards IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790320-23 & notice of violation SEIDLE.H C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/04/11 2pp
- --7906250047 Notice of violation from insp on 790320-23
  \* Region 4, Dallas, Office of the Director 79/04/11 2pp
- --7906250051 IE Insp Repts 50-498/79-04 & 50-499/79-04 on 790320-23 Noncompliance moted failure to follow concrete placement procedures HUBACEK.N O Region 4, Dallas, Office of the Director HALL.R E Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/04/11 Spp
- 7906110002 Forwards IE Builetin 79-03B, "Nuclear Incident at IMI-Suppl "No written response required SEYFRIT.K V Region 4. Dallas, Office of the Director, 79/04/Ri
- 7906210107 Becond interim rept of reportable deficiency dimensional error in base slab of mechanical-electrical Unit 2 auxiliary bldg Describes progress on redesign of bldg Final rept will not be available by 790501 TURNER.E A Houston Lighting & Power Co 79704/24 2pp
- 7906210109 Confirms 790426 & 27 telcons re improper storage of reinforcing steel NRC understands that util has found no significant departures exist from reinforcing steel requirements of site quality const procedures
  SEYFRIT.K V Region 4, Dallas, Office of the Director 79/05/01
  2pp
- 7906120067 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required, SEYFRIT, K V Region 4, Dallas, Office of the Director 79/05/07

- 7906250019 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies"
  8EYFRIT.K V Region 4. Dallas. Office of the Director 79/05/11
- 7906120138 Ack receipt of 790303 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-498/79-04 & 50-499/79-04 & SEIDLELW C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/16 ip
- --7906:120141 Responds to NRC 7904:11 ltr re violations noted in IE Insp Repts 50-498/79-04 & 50-499/79-04 Corrective actions concrete placement procedures training session held on 7904:1 TURNER, E.A. Houston Lighting & Power Co. 79/05/03 2pp
- 7906130067 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Gircuit Breakers for Engineered Safety Sys " Licensee action required SEYFRIT.K V Region 4, Dallas, Office of the Director 79/09/22
- 5 Reportable occurrences, LERs & related correspondence
- 7906180136 Forwards PNO-79-67AM SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/05/08 ip
- 7906180176 Forwards PNO-79-67AN
  SEIDLE,W C Region 4. Dallas, Reactor Construction & Engineering Support Branch 79/05/16 ip
- 7906180243 Forwards PNO-79-67AD SEIDLE.W C Region 4. Dallas. Reactor Construction & Engineering Support Branch 79/05/22 ip
- 7906180320 Forwards PNO-79-67AP SEIDLE.H C Region 4, Dallas, Reactor Construction & Engineering Support Branch 79/05/23 ip
- 7906120370 Forwards final deficiency rept re concrete voids behind liner plate in reactor bldg exterior wall TURNER,E A Houston Lighting & Power Co 79/06/05 ip
- ---7906120397 Final deficiency rept on 781020 15th lift concrete voids
  Caused by inadequate planning for large pour, long pour time,
  longer than normal slick lines & concrete pump breakdowns
  Immediate & long-term corrective actions have been effected
  \* Houston Lighting & Power Co 79/06/15 13pp
- 7906120430 Second interim rept of deficiency re improper anchor bolt matl Final rept will not submitted until 790815 due to complexity of identifying & testing suspect bolts TURNER.E A Houston Lighting & Power Co 79/06/05 2pp
- 7906:30007 Forwards final deficiency rept re failure to properly consider application of certain postulated loads in interior structural steel beams Deficiency would not have resulted in significant safety hazard TURNER.C A Houston Lighting & Power Co 79/06/05 2pp
- --7706130008 Final defictioncy rept on 781025 beam-to-column connections Caused by human error & inadequate procedural training Beams have been reanalyzed, errors corrected & calculations design verified

  \* Houston Lighting & Power Co 79/06/05 8pp
- 7906220367 Interim deficiency rept on 790516 essential cooling water gantry crane not designed to withstand DBT Caused by breakdown in design change program Design & change procedure being corrected TURNER.E A Houston Lighting & Power Co 79/06/15 App
- T. Hearing transcripts on non-antitrust matters
- 7906180736 Transcript of 790601 hearing in Bethesda,MD Pp 213-471 MILLER,M E , HOLFE,S J Atomic Safety and Licensing Board Panel 79706/01 260pp
- U. Congressional/Executive Correspondence
- 7904070043 Requests info on Westinghouse reactor design & possibility of facility mod in light of TMI incident PICKLE, J J House of Rep. 79/04/25 2pp

- 7906290271 Responds to 790416 Itr which forwarded J Lowry 790404 Itr requesting info on safety of plant const & operation Forwards "Summary of Progress of South TX Plant," providing general info re facility GUSSICK.L V Office of the Executive Director for Operations 79/05/22 4pp
- --7906290285 Forwards J Lowry 790404 ltr requesting info on safety of plant const & operation SCHMEIKER, R S Senate 79/04/16 2pp
- DOCKET 50-500 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 7904210501 Forwards revision to SER re design criteria & bases for protection against dynamic effects essociated w/postulated rupture of piping outside containment HANAUER.S H Plant Systems Branch 79/03/29 8pp
- F Security, medical, emergency & fire protection plans
- 7906080303 Emergency Procedure 1202 24 steam supply sys rupture SIMON, L , MURRAY, T D Toledo Edison Co 79/06/02 17pp
- 9 Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
  CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon issue was in error,ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl DUFLO,M E Atomic Safety and Licensing Appeal Panel 79/05/25
- J. Insurance & indomnity information
- 7906200336 Forwards Endorsements 22 & 23 to MAELU Policy MF-92 LLOYD,R D Marsh & McLenon, M & M Nuclear Consultants, Inc Div 79/06/15 3pp
- M Antitrust correspondence
- 7906220266 Notifies that certain documents were removed from ASLAB secretary's desk by unauthorized person Documents found in another ofc investigation initiated DUFLO.NE Atomic Safety and Licensing Appeal Panel 78/10/02

- --7906220336 Responds to 781107 memo re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) BURCH.C L Division of Security 78/12/04 2pp
- --7906220349 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (raf FOIA Exemption 7A & 7E) Forwards Washington Post 790128, 0213 & 25 articles
  HURNEY.T F Office of Inspector & Auditor 79/02/28 7pp
- ~-7906220364 Comments on Ofc of Inspector & Auditor rept re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7E)
  CUMMINOS.J J Office of Inspector & Auditor 79/06/22 2pp
- DOCKET 50-501 DAVIS-BESSE NUCLEAR POWER STATION, UNIT 3
- A Application/construction stage documents & correspondence
- 7904210501 Forwards revision to SER re design criteria & bases for protection against dynamic effects associated w/postulated rupture of piping outside containment HANAUER.S H Plant Systems Branch 79/03/29 Opp
- F Security, medical, emergency & fire protection plans
- 7906080303 Emergency Procedure 1202 24 steam supply sys rupture SIMON,L . MURRAY,T D Toledo Edison Co 79/06/02 17pp
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO, J F Hearings Division 79/04/02 2pp
- ---7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
- 7706210095 NRC motion for summary disposition re-radon issuer was in strongALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl DUFLO.M E Atomic Sarety and Licensing Appeal Panel 79/05/25 300
- J Insurance & indomnity information
- 7906200336 Forwards Endorsements 22 & 23 to MAELU Policy MF-92 LLQYD,R D March & McLenon, M & M Nuclear Consultants, Inc. Div 79/06/15 3pp
- M Antitrust correspondence
- 7906220266 Notifies that certain documents were removed from ASLAB secretary's desk by unauthorized person Documents found in another ofc Investigation initiated
  DUFLOOM E Atomic Safety and Licensing Appeal Panel 78/10/02
- --7906220270 Forwards ABLAB memo issued in Davis-Besse & Perry proceeding re missing papers in ofc ROSENTHALAS Atomic Safety and Licensing Appeal Panel 78/10/03 ip.

- --7906220320 Comments on Ofc of Inspector & Auditor rept re investigatics of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) ROBENTIALAS Atomic Safety and Licensing Appeal Panel 78/11/08 App
- --7906220336 Responds to 781107 mamo re investigation of document removal info partly withheld due to enforcement proceedings (ref FOIA Exemption 7A) BURCH.C L Division of Security 78/12/04 2pp
- --7906220349 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to anforcement proceedings (ref FOIA Exemption 74 & 7E) Forwards Washington Post 790128, 0213 & 25 articles
  HURNEY. T F Office of Inspector & Auditor 79/02/28 7pp
- --7906220364 Comments on Ofc of Inspector & Auditor rept re investigation of document removal Info partly withheld due to enforcement proceedings (ref FOIA Exemption 7E)
  CUMINOS.J.J. Office of Inspector & Auditor 79/06/22 2pp
- DOCKET STN-50-302 HAVEN NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7906080272 Submits addl info on const runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request
  BURSTEIN.S Hisconsin Electric Power Co 79/05/29 3pp
- 7906130265 Forwards mass & energy release rates & main steam line break rates Rates withheld (ref 10CFR2 790)
  FAY.C H Wisconsin Electric Power Co 79/06/04 9pp
- 7906120421 Forwards Paper 24, "Toward Universal Climatological Extreme Wind Distribution." by NC Thom Paper was requested in J Goll 790524 telcon re response to NRC Question 372 6(2 3 1) FAY.C W Wisconsin Electric Power Co 79/06/05 3ipp
- 7906280117 Forwards response to NRC 790314 & 790419 requests for addl info re alternative site studies FAY.C W Wisconsin Electric Power Co 79/06/20 105pp
- B Utility Preliminary Safety Analysis Report, amends
- 7906120147 Forwards Amend 18 to PSAR BURSTEIN: 6 Wisconsin Electric Power Co 79/05/31 3pp
- --7906120151 Amend 19 to PSAR # Wisconsin Electric Power Co 79/06/30 150pp
- 7906120193 Forwards Amend 23 to PSAR for insertion into site addendum BURSTEIN B Wisconsin Electric Power Co 79/05/31 1p
- --7906120200 Amend 23 to PBAR
  \* Wisconsin Electric Power Co 79/05/31 117pp
- 7906290579 Forwards FP Libertowicz 790625 Affidavit of Svc offirming distribution of PSAR Amend 18 % PSAR Site Addendum Amend 23 BURSTEIN,S Hisconsin Electric Power Co 79/06/12 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906020203 Forwards request for additinfo based on review of environ rept Amends 9-11 % site visits Questions re alternate sites were sent 790314

  BALLARD,R L Environmental Projects Branch 1 79/05/15 14pp
- 7906150216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Environ Rept " HIRSTEIN,S P Wisconsin Electric Power Co 79/05/29 25pp
  - 260409 Forwards complete environ rept, including Amends 10 & 11 Terrata & Amend 12 RSTEIN,8 Wisconsin Electric Power Co 79/06/18 2pp
  - .260411 Forwards complete environ rept, including Amends 10 % 11 'errata & Amend 12 RSTEIN,6 Wisconsin Electric Power Co 79/06/18 2pp
  - .260414 Forwards complete environ rept, including Amends 10 t 11 'errata t Amend 12 RSTEIN.8 Wisconsin Electric Power Co 79/06/18 2pp

#### G Adjudicatory correspondence

- 7906010311 Advises that ASLB ref to both Haven units in legal documents is appropriate, even though applicants are seeking for only one unit Certificate of Svc encl CHURCHILL:B W Shaw, Pittman, Potts, & Trombridge 79/04/13 4pp
- 7906030175 Dismisses intervenor 790330 request for verification & analysis of mathematical computations & computer codes of S&W LUTCN.E Atomic Safety and Licensing Board Panel 79/05/07 2pp

#### DOCKET STN-50-503 HAVEN NUCLEAR PLANT, UNIT 2

- A Application/construction stage documents & correspondence
- 7906080272 Submits add1 info on const runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request BURSTEIN.S Hisconsin Electric Power Co 79/05/29 App
- C Utility Environmental Report (ER), amends & correspondence
- 7906150216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Environ Rept " BURSTEIN.S P Wisconsin Electric Power Co 79/05/29 25pp
- 7906260407 Forwards complete environ rept, including Amends 10 & 11 w/errata & Amend 12
  BURSTEIN,S Wisconsin Electric Power Co 79/06/18 2pp
- 7906260411 Forwards complete environ rept.including Amends 10 % 11 W/errata & Amend 12 BURSTEIN.S Wisconsin Electric Power Co 79/06/18 2pp
- 7906260414 Forwards complete environ rept, including Amends 10 & 11 W/errata & Amend 12 BURSTEIN,8 Wisconsin Electric Power Co 79/06/18 2pp

### Q Adjudicatory correspondence

- 7706050175 Dismisses intervenor 770330 request for verification & analysis of mathematical computations & computer codes of 8tW LUTON, E Atomic Safety and Licensing Board Panel 77/05/07 2pp
- DOCKET STN-50-504 KOSHKONONG NUCLEAR PLANT, UNIT 1
- A Application/construction stage documents & correspondence
- 7904080272 Bubmits addl info on const runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request BURSTEINS Hisconsin Electric Power Co 79/05/27 App
- C Utility Environmental Report (ER), amends & correspondence
- 7906150216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 Environ Rept " BURSTEIN:8 P Wisconsin Electric Power Co 79705/29 25pp
- 7906260409 Forwards complete environ rept, including Amends 10 % 11 w/errata & Amend 12
  BURSTEIN, 8 Wisconsin Electric Power Co 79/06/18 2pp
- 7906260411 Forwards complete environ rept, including Amends 10 & 11 w/errate & Amend 12 BURSTEIN.8 Wisconsin Electric Power Co 79/06/18 2pp
- 7906260414 Forwards complete environ rept.including Amends 10 % (1 w/errata & Amend 12 BURSTEIN:S Wisconsin Electric Pawer Co 79/06/18 2pp
- DOCKET STN-50-505 KOSHKONONG NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7904080272 Bubmits add1 info on const runoff settling basins & industrial wastewater treatment facilities, in response to 790406 request, BURSTEIN, B Wisconsin Electric Power Co 79/05/29 App

- C Utility Environmental Report (ER), amends & correspondence
- 7906150216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 to Environ Rept " BURSTEIN:8 P Wisconsin Electric Power Co 79/05/29 25pp
- 7906260409 Forwards complete environ rept, including Amends 10 % 11 w/errata & Amend 12
  BURSTEIN.S Wisconsin Electric Pawer Co 79/06/18 2pp
- 7906260411 Forwards complet: environ rept.including Amends 10 & 11 w/errata & Amend 12 BURSTEIN,S Wisconsin Electric Power Co 79/06/18 2pp
- 7906260414 Forwards complete environ rept.including Amends 10 b 11 w/errata b Amend 12 BURSTEIN.S Historisin Electric Power Co 79/06/18 2pp
- DDCKET STM-50-506 KOSHKONONG NUCLEAR PLANT, UNIT 3

  A Application/construction stage documents & correspondence
- 77060BD272 Submits add1 info on const runoff settling basins % industrial wastewater treatment facilities, in response to 770405 request BURSTEIN.8 Wisconsin Electric Power Co 79/08/29 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906190216 Forwards June 1979 "Response to Dept of Natural Resources Specific Comments on Amends 11 & 12 to Environ Rept " BURSTEIN, 8 P Wisconsin Electric Power Co 79/05/29 25pp
- 7906260409 Forwards complete environ rept including Amends 10 & 11 w/errata & Amend 12 BURSTEIN.8 Wisconsin Electric Power Co 79/06/18 2pp
- 7706260411 Forwards complete environ rept.including Amends 10 & 11 w/errata & Amend 12 BURSTEIN, S Wisconsin Electric Power Co 77/06/18 2pp
- 7906260414 Forwards complete environ rept.including Amends 10 b 11 w/errata b Amend 12 BURSTEIN.8 Wisconsin Electric Power Co 79/06/18 2pp
- DOCKET STN-50-507 KOSHKONONO NUCLEAR PLANT, UNIT 4

  A Application/construction stage documents % correspondence
- 7704080272 Submits add1 info on const runoff settling basins & industrial wastewater treatment facilities in response to 770404 request BURSTEINS Wisconsin Electric Power Co 79/05/29 3pp
- C Utility Environmental Report (ER), amends & correspondence
- 7904i30Zi6 Forwards "Response to Dept of Natural Resources Specific Comments on Amends if \$\mu\$ 12 to Environ Rept." dtd June 1779
  BURSTEIN, 8 P Wisconsin Electric Power Co 79/05/27 25pp
- 7906260409 Forwards complete environ rept.including Amends 10 w/errata & Amend 12 BURSTEIN.8 Wisconsin Electric Power Co 79/06/19 2pp
- 7906260411 Forwards complete environ rept.including Amends 1 w/errata & Amend 12 BURSTEIN 8 Wisconsin Electric Power Co 79/06/18 2pp
- 7906260414 Forwards templete environ rept, including Amends 1 w/errata & Amend 12 BURSTEIN/S Wisconsin Electric Power Co 79/06/18 2pp
- DOCKET STN-50-508 WPPSB NUCLEAR PROJECT, UNIT 3
- A Application/construction stage documents & correspondence
- 7706270125 Forwards groundwater drainage analysis for 770331 contained in two oversized drawings RENBEROER,D L. Washington Public Power Supply System 75

- --7906270130 Fifth suppl to design parameters of groundwater drainage sys for 790331-0315,contained in two oversized drawings \* Washington Public Power Supply System 79/06/22 3pp
- O Inspection reports, IE Bulletins & correspondence
- 7906260520 Forwards IE Insp Repts 50-508/79-03 & 50-509/79-02 on 790312-15 No noncompliance noted SPENCER, G S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/04/20 2pp
- --7906260525 IE Insp Repts 50-508/79-03 & 50-509/79-02 on 790312-15 No noncompliance noted Major areas inspected changes in site QA organizations & structural concrete QA procedure review ALBERT, H G , HAYNES, R G Region 5, San Francisco. Reactor Construction & Engineering Support Branch HUTSON, T H Region 5, San Francisco. Office of the Director 79/04/18 lipp
- 7906:120057 Forwards IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/05/07 1p
- 7906180480 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" No written response necessary ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/10 ip
- 7906080245 Forwards IE Circular 79~08, "Attempted Extortion Low Enriched U " ENGELKEN,R.H Region 5, San Francisco, Office of the Director 79/05/18 ip
- 7906:30054 Forwards IE Bulletin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN, R H Region 5, San Francisco. Office of the Director 79/03/22 ip
- 7908200081 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Ogster Creek Reactor" ENGELKEN, R H 79/09/29 in Region 5, San Francisco, Office of the Director 79/09/29
- S Reportable occurrences, LERs & related correspondence
- 7906180231 Forwards PNO-79-67AN ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/14 1p
- 7906180280 Forwards PNO-79-67AO ENGELKEN/R H Region 5. San Francisco, Office of the Director 79/05/21 1p
- 7906180351 Forwards PND-79-67AP ENGELKEN:R H Region 5. San Francisco, Office of the Director 79/05/22 1p
- 7906180371 Forwards PNO-79-67AQ ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/30 1p
- DOCKET STN-90-509 WPPSS NUCLEAR PROJECT, UNIT 5

  A Application/construction stage documents & correspondence
- 7906270125 Forwards groundwater drainage analysis for 790331-0515, > oversized drawings. Washington Public Fower Supply System 79/06/22

- 7906120057 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/07 Ip
- 7906180488 Forwards IE Info Notice 79-12. "Attempted Damage to New Fue] Assemblies " No written response necessary ENGELKEN,R H Region 5. San Francisco. Office of the Director 79/05/10 10
- 7906080245 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/18 1p
- 7906130054 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/03/22 10
- 7906200061 Forwards lE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" ENGELKEN.R H Region 3. San Francisco, Office of the Director 79/05/27 ip
- 8 Reportable occurrences, LERs & related correspondence
- 7906180231 Forwards PND-79-67AN
  ENGELKEN,R H Region 5, San Francisco, Office of the Director
  79/05/14 1p
- 7906180280 Forwards PND-79-67AU ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/21 1p
- 7906180351 Forwards PND-79-67AP ENGELKEN:R H Region 5. San Francisco. Office of the Director. 79/05/22 1p
- 7906180371 Forwards PND-79-67AQ ENGELKEN,R H Region 3, San Francisco, Office of the Director 79/05/30 10
- DUCKET 50-510 BLUE HILLS STATION, UNIT 1
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 770612000& Forwards errata sheet to FEB for facility (NUREG-0449) 6LATER, M Environmental Projects Branch i 79/04/30 3pp
- 9 Adjudicatory correspondence
- 7906020132 Forwards info re occupational exposure in commercial nuclear reactors & adequacy of neutron dosimetry now used WOODHEAD.C P Branch 3 79/04/04 ip
- 7906080028 Forwards prof qualifications of applicant witness panel in upcoming early site review hearing HETTERHARN.M J Conner, Moore & Corber 79/04/17 12pp
- 7906140644 Requests to make limited appearance statement at licensing prehearing conference WRIGHT.B Affiliation Unknown 79/04/26 ip
- 7906140470 Requests appearance at site hearings near Jasper,TX during week of 790506
  SPREADBURY, N N Stephen F Austin State Univ 79/04/26 ip
- 7906140638 Requests to make limited appearance statement at licensing prehearing conference LEBLANC.L P. Affiliation Unknown 79/04/23 ip
- 80165 Forwards applicant Gulf States Utils 790607 proposed dings of fact & conclusions of law in form of partial tial decision TERMAHN. M J Conner, Moore & Corber 79/06/07 ip
  - 6280)69 Quif States Utils proposed findings of fact b conclusions f law in form of partial initial decision re issues of site uitability Certificate of Svc encl
    ETTERHANN,M J Conner, Moore & Corber 79/06/07 59pg

### H General correspondence

7906150246 Supports const of nuclear plant WILLIAMS,C H Affiliation Unknown 79/04/28 ip

### DOCKET 50-511 BLUE HILLS STATION, UNIT 2

- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 7706120006 Forwards errata sheet to FES for facility (NUREG-0449) BLATER:M Environmental Projects Branch 1 79/04/30 3pp

#### G Adjudicatory correspondence

- 7904020132 Forwards info re occupational exposure in commercial nuclear reactors & adequacy of neutron dosimetry now used HGODHEAD.C P Branch 3 79/04/04 1p
- 7905090028 Forwards prof qualifications of applicant witness panel in upcoming early site review bearing METTERHAHNIM J Conner, Moore & Corber 79/04/17 12pp
- 7906140644 Requests to make limited appearance statement at licensing prehearing conference WRIGHT-B Affiliation Unknown 79/04/26 ip
- 7906140470 Requests appearance at site hearings near Jasper.TX during week of 790806

  SPREADBURY.W N Stephen F Austin State Univ 79/04/26 1p
- 790614063B Requests to make limited appearance statement at licensing prehearing conference
  LEBLANG.L P Affiliation Unknown 79/04/23 ip
- 7906280165 Forwards applicant Oulf States Utils 790607 proposed findings of fact & conclusions of law in form of partial initial decision
  WETYERHAHN.M J Conner, Moore & Corber 79/06/07 1p
- --7906280169 Gulf States Utils proposed findings of fact & conclusions of law in form of partial initial decision re issues of site suitability Certificate of Svc encl
  HETTERHAIM: M J Conner, Moore & Corber 79/06/07 59pp

## H General correspondence

7906150246 Supports const of nuclear plant
WILLIAMS, C H Affiliation Unknown 79704/28 1p

### DOCKET 50-513 WPP89 NUCLEAR PROJECT, UNIT 4

- A Application/construction stage documents & correspondence
- 7906060013 Approves proposed date of Aug 1980 for submittal of FGAR & environ rept
  BDYD.R S Division of Project Hanagement 79/05/01 3pp

### O Adjudicatory correspondence

ł

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-309 BCINTO.JF Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health affects of radon releases CHRISTENBURY,E Hearings Division 79/03/26, 34pp
- 7906210095 NRC motion for summary disposition re radon issuer was in error; ALAB-340 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Sycenci DUFLO.M E Atomic Safety and Licensing Appeal Panel 79/05/25

## G Inspection reports, IE Bulletins & correspondence

7706220133 Forwards IE Insp Repts 50~460/79-05 & 50-513/79-05 on 790327-29 No noncompliance noted. SPENCER, O.S. Region 5: San Francisco, Office of the Director 79/04/13 2pp

- ~~7906220137 IE Insp Repts 50-460/79-03 & 50-513/79-03 on 790327-29 No noncompliance noted Major areas inspected const activities, training programs & miscellaneous open items ALBERT, H G , HAYNES, R C Region 5, San Francisco, Office of the Director 79/04/13 4pp
- 7906190089 Responds to NRC 790321 ltr re violations noted in IE Insp Repts 50-397/79-03, 50-460/79-04 & 50-513/79-04 Corrective actions audit conducted Feb 1977 Deficient hanger RD-405 will be removed & replaced properly RENBERGER, D L Washington Public Power Supply System 79/04/20
- --7906150090 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-397/79-03, 50-460/79-04 & 50-513/79-04 ENGELKEN, R H Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/05/03 ip
- --7906150058 Forwards IE Insp Repts 50-397/79-03,50-460/79-04 & 50-513/79-04 on 790201-02 & 14-15 & notice of violation SPENCER,0 S Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 2pp
- --7906150063 Notice of violation from insp on 790201-02 & 14-15 \* Region 5, San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 2pp
- --7906150077 IE Insp Repts 50-397/79-03.50-460/79-04 & 50-513/79-04 on 790201-02 & 14-15 Noncompliance noted failure to respond effectively to audit finding & failure to implement effective insp program
  BISHOP,T W . SHACKLETON.O C , HAYNES,R C Region 5. San Francisco, Reactor Construction & Engineering Support Branch 79/03/21 7pp
- 7906120057 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required ENGELMEN.R H Region 5, San Francisco, Office of the Director 79/05/07 ip
- 7906180488 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/10 10
- /90&080245 Forwards IE Circular /9-08, "Attempted Extortion Low Enriched U " ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/05/18 in
- 7906:30054 Forwards IE Buildtin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGLKEN, R It Region 5, San Francisco, Office of the Director 79/03/22 ip
- 7906200061 Forwards IE Info Notice 79-13. "Indication of Low Water Lovel in Oyster Creek Reactor" ENGELKEN, R H Region 5, San Francisco, Office of the Director
- 8 Reportable occurrences. LERs & related correspondence
- 7906180231 Forwards PNO-79-67AN ENGELKEN,R H Region 5, San Francisco, Office of the Director. 79/05/14 ip
- 7706180280 forwards PND-79-67AO ENGELKEN.R H Region S. San Francisco. Office of the Director 77/05/21 ip
- 7906180351 Forwards PND-79-67AP ENGELKEN,R H Region 5, Ban Francisco, Office of the Director 79/05/22 ip
- 7906180371 Forwards PNO-79-67AQ ENGELKEN,R H Region 5. Ban Francisco, Office of the Director 79/05/30 ip

### DOCKET 50-514 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 7906190473 Ack receipt of NRC 790518 lt; re POE-1020 Response schedule will be confirmed by 790615
  -JOHNSON,R W Portland General Electric Co 79/06/11 1p

7906220230 Forwards Jan 1979 "Housing & Community Facilities Requirements Update." Vol 2 LINDBLAD.W J Portland Gameral Electric Co 79/06/15 2pp

# @ Adjudicatory correspondence

7903210311 Forwards proposed NRC response by RL Gotchy & R Weller to 771215 memo re ASLB questions Unable to give filing date for NRC revised alternative sites analysis being prepared by AML BORDENICK, B M Branch 4 79/03/07 11p

# R Periodic operating reports & related correspondence

7906200481 Forwards "Seismic Network Annual Rept." Nov 1977-Oct 1978 LINDBLAD, W.J. Portland General Electric Co. 79/04/12 1p

--7706200489 'Seismic Network Annual Rept." Nov 1977-Oct 1978, by TERA Corp \* Portland General Electric Co 79/01/31 58pp

DGCKET 50-515 PEBBLE SPRINGS NUCLEAR PLANT, UNIT 2

A Application/construction stage documents & correspondence

7904190473 Ack receipt of NRC 790518 ltr re POE-1020 Response schedule will be confirmed by 790615

JCHNSCN-R W Portland General Electric Co 79/06/11 1p

7906220230 Forwards Jan 1979 "Housing & Community Facilities Requirements Update," Vol 2 LINDBLAD.W J Portland General Electric Co 79/06/15 2pp

#### O Adjudicatory correspondence

7903210311 Forwards proposed NRC response by RL Gotchy & R Weller to 771215 memo re ASLB questions Unable to give filing date for NRC revised alternative sites analysis being prepared by AML BORDENICK, B M Branch 4 79/03/07 11p

# R Pariodic operating reports & related correspondence

7904200481 Forwards "Seismic Network Annual Rept." Nov 1977-Oct 1978 LINDBLAD: W J Portland General Electric Co 79/04/12 1p

--7906200489 "Seismic Network Annual Rept," Nov 1977-Oct 1978, by TERA Corp \* Portland General Electric Co 79/01/31 58pp

DOCKET STN-50-516 JAMESPORT NUCLEAR STATION, UNIT 1

# @ Adjudicatory correspondence

790&040093 Hotion to file supplemental brief Cortificate of Syc enci LIKE: [ Suffolk County, NY 79/04/19 7pp

7906020223 Forwards LE Bulletin 79-02. "Pipe Support Base Plate Designs Using Concrete Espansion Anchor Bolts "
BORDENICK. 8 M Branch 4 79/04/26 ip

ponds to 781205 ltr re design deficiencies in support NRC still waiting for StM evaluation of both ctrical type supports Info will be evaluated ontinuing safety review M Branch 4 79/01/15 ip

upplemental

r reply to 11 AB &

ef or in

### Q Inspection reports, IE Bulletins & correspondence

7906180394 Forwards IE Info Notice 79-10. "Noncomforming Pipe Support Struts " No written response necessary GRIER.B H Region i, Philadelphia, Office of the Director 79/04/16 ip

7906:1100:15 Forwards IE Bulletin 79-05B. "Nuclear Incident at THI-Suppl " No written response required GRIER.B H Region 1. Philadelphia. Office of the Director 79/04/23 ip

7906120166 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required GRIER, B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

790626D115 Forwards IE Info Notice 79-12. "Attempted Damage to New Ewel Assemblies " GRIER.B H Region I. Philadelphia. Office of the Director 79/05/11 lp

7906290794 Responds to IE Bulletin 79-03 Station design reviewed & walded pipe is not used in Westinghouse NBSB
PLASKON, R E Long Island Lighting Co 79/05/11 ip

7906290808 Responds to IE Bulletin 79-07 No seismic stress analyses of safety-related piping have been performed Intends to use NUPIPE computer program for piping analysis PLASKON, R E Long Island Lighting Co 79/03/30 ip

DOCKET STN-50-517 JAMESPORT NUCLEAR STATION, UNIT 2

7906040093 Motion to file supplemental brief Certificate of Svc encl LIKE, I Suffolk County, NY 79/04/19 7pp

7906020223 Forwards IE Bulletin 79-02, "Pipe Support Base Plate Besigns Using Concrete Expansion Anchor Bolts " BORDENICK, B M Branch 4 79/04/26 1p

--7906020226 Responds to 781205 ltr re design deficiencies in support base plates NRC still waiting for 85W evaluation of both piping 5 electrical type supports Info will be evaluated as part of continuing safety review BURDENICK, B M Branch 4 79/01/15 ip

7906180669 Opposes Suffoll County 790419 mation to file supplemental brisf Arguments presented are outside scape of evidence or radundant of arguments already admitted into evidence Certificate of Svc encl REVELEY, H T Hunton & Hilliams 79/05/04 4pp

7906200588 Requests ASLAB grant extension until 790608 for reply to Suffolk County motion to file supplemental brief NRC will complete evaluation of math re TML & submit info to ASLAB & all parties Motion granted by ASLAB on 790518 BORDENICK.B M Branch 4 79/05/08 Spp

7906270269 Renews 790419 request to file supplemental brief gr.in alternative to reopen record Further relief will be sought after ASLB has received NRC response to 790419 order Certificate of Syc encl
LICK.I Suffelt County, NY 79/05/16 6pp

### G Inspection reports, IE Bulletins & correspondence

7906180394 Forwards IC Info Notice 79-10, "Noncomforming Pipe Support Struts " No written response necessary GRIER.B H Region 1, Philadelphia, Office of the Director 79/04/16 ip

790A110015 Forwards IE Bulletin 79-05B, "Nuclear Incident at TMI-Buppl " No written response required ORIER.B H Region I. Philadelphia. Office of the Director 79/04/23 |

7906120166 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ORIER B H Region 1, Philadelphia, Office of the Director 79/05/07 2pp

7906260115 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER BH Region 1, Philadelphia, Office of the Director 79/05/11 1p

- 7706290794 Responds to IE Bulletin 79-03 Station design reviewed & welded pipe is not used in Westinghouse NSSG PLASKON R E Long Island Lighting Co 79/05/11 1p
- 7906290808 Responds to IE Builetin 79-07 No seismic stress analyses of safety-related piping have been performed Intends to use NUPIPE computer program for piping analysis PLASKON.R E Long Island Lighting Co 79705/30 1p

#### DOCKET STN-50-518 HARYSVILLE NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 7906190173 Confirms JC Killian & CE Murphy 790513 telcon re discontinuance of production of cadwald splices & placement of concrete for Category I structures D'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/15 2pp
- 7906250264 Notification of 790617 meeting w/util to discuss leak testing temp & pressure stds for piping embedded in concrete
  PENEDICT.R A r ROOD, H Light Water Reactors Branch 2 79/05/21

### O Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 BCINTO,J F Hearings Division 79/04/02 2pp
- ~-7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radom in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radom releases CHRISTENBURY,E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon issue was in error:ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl DUFLO:ME Atomic Safety and Licensing Appeal Panel 79/05/25

# Q Inspection reports. IE Bulletins & correspondence

- 7906010322 Forwards IE Insp Repts 50 518/79-05, 50-319/79-05, 50-520/79-05 & 50-521/79-05 on 790220-23 No noncompliance noted MURPHY.C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --790&010328 IE Insp Repts 50-518/79-05,50-519/79-05,50-520/79-05 & 50-521/79-05 on 790220-23 No nancompliance noted Major areas inspected review of previous insp findings, spray ponds & containment concrete SWAN,W B Region 2, Atlanta, Office of the Director 79/04/02 & 6pp
- 7906130147 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required 6'REILLYJ P Region 2, Atlanta. Office of the Director 79/05/02 ip
- 7904210078 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312, Type 304 piping supplied by Youngstoom Welding & Engineering O

### S. Reportable occurrences. LERs & related correspondence

- 7906140411 Bubmits interim deficiency rept breakdown in GC gragram at industrial engineering works on reactor pressure vessel shield wall initial rept to M Gouge on 790417. Final rept to be transmitted 790702

  OILLELAND, J E Tennessee Valley Authority 79/05/17 3pp
- 7904:90431 Forwards deficiency rept re const of piping elbows w/unspecified mat!
  OILLELAND.J E Tennessee Valley Authority 79/05/25 1p
- --7906190442 Deficiency rept on 790525, piping elbows constructed from unspecified math. Elbows w/heat code M6719 were identified, tested & returned to manufacturer # Tennessee Valley Authority 79/05/25 3pp

- DDCKET STN-50-519 MARTSVILLE NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents > correspondence
- 7906190173 Confirms JC Killian & CE Murphy 790515 telcon re discontinuance of production of cadweld splices & placement of concrete for Category I structures D'REFLLY. J P Region 2. Atlanta. Office of the Director 79/05/15 2pp
- 7906250264 Notification of 790619 meeting w/util to discuss leak testing, temp & pressure stds for piping embodded in concrete
  BENEDICT, R A , ROQD, H Light Water Reactors Branch 2 79/05/21
  - PP Light Water

### G Adjudicatory correspondence

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-309 GCINIO, J. F. Hearings Division 79/04/02 2pp
- --/906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept 5 proposed rule will be sent to NRC by 790406 Rule does not address health offects of radon releases CHRISTENDURY. E Hearings Division 79/03/26 34pp
- 7906210075 NRC motion for summary disposition re radon issue was in error; ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Syc encl
  DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/08/25

#### A Inspection reports, IE Bulletins & correspondence

- 7904010322 Forwards IE Insp Repts 50-518/79-05.50-519/79-05. 30-520/79-05 & 50-321/79-05 on 790220-23 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7904010328 IE Insp Repts 50-518/79-05.50-519/79-03.50-520/79-05 & 50-521/79-05 on 790220-23 No noncompliance noted Major areas inspected review of previous insp findings.spray ponds & containment concrete SWAN.W B Region 2. Atlanta, Office of the Director 79/04/02 App
- 7906:30147 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/02
- 7904210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312. Typo 304 piping supplied by Youngstown Wolding & Engineering OILLELAND. JE Tennessee Valley Authority 79/05/14 ip
- S Reportable occurrences, LERs & related correspondence
- 7906190431 Forwards deficiency rept re const of piping elbows w/wnspecified matt OILLELAND, J E Tennessee Valley Authority 79/05/25 ip
- --7904190442 Deficiency rept on 790525 piping elbows constructed from Unspecified matl Elbows w/heat code W4717 were identified, tested & returned to manufacturer # Tennessee Valley Authority 79/05/25 3pp

## DOCKET STN-50-520 HARTSVILLE NUCLEAR PLANT, UNIT 3

- A Application/construction stage documents & correspondence
- 7906190173 Confirms JC Killian & CE Murphy 790515 telcon rediscontinuance of production of cadweld eplices & placement of concrete for Category I structures O'REILLY, JP Region 2. Atlanta. Office of the Director 79705/15
- 7906250264 Notification of 790619 meeting w/wtil to discuss leak testing temp & pressure stds for piping embedded in concrete.

  BENEDICT.R A , ROOD, H Light Water Reactors Branch 2 79/05/21

#### O Adjudicatory correspondence

- 7903210426 Ack receipt of 790222 ltr requesting leave to intervene Informs that 790209 ltr was treated as intervention petition Forwards notice of establishment of ASLB to rule on petition M/o encl
  OULDBERG, S C Branch 2 79/03/05 ip
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509 SCINTO.JF Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table S-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases
  CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon issue was in error; ALAB-540 consolidated only 5 of 15 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLD, M E Atomic Safety and Licensing Appeal Panel 79/08/25
- Q Inspection reports. IE Bulletins & correspondence
- 7904010322 Forwards IE Insp Repts 50-518/79-05.50-519/79-05.
  50-520/79-05 & 50-521/79-05 on 790220-23 No noncompliance noted MMRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906010328 IE Insp Repts 50-518/79-05.50-519/79-05.50-520/79-05 & 50-521/79-05 on 790220-23 No noncompliance noted Major areas inspected review of previous insp findings, spray ponds & containment concrete SWAN, & B Region 2, Atlanta, Office of the Director 79/04/02 & 6pp
- 7906130147 Forwards IE Carcular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLYJ P Region 2. Atlanta, Office of the Director 79/05/02, ip.
- 7906210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME 9A-012-Type 304 piping supplied by Youngstown Welding & Engineering OILLELAND. J E Tennessee Valley Authority 79/05/14 ip
- S Reportable occurrences. LERs & related correspondence
- 7906190431 Forwards deficiency rept re const of piping elbows w/unspecified matl
  OllLELAND, J E Tennessee Valley Authority 79/05/25 1p
- --7906190442 Deficiency rept on 790925 giping elbows constructed from unspecified math Elbows w/heat code M6719 were identified, tested & returned to manufacturer. \* Fennessee Valley Authority 79/05/28 3pp
- DOCKET STN-50-521 HARTSVILLE NUCLEAR PLANT, UNIT 4

/construction stage documents k correspondence

115 telcan re

rartar

- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO. J.F. Hearings Division 79/04/02 200
- --7906210060 Responds to 790322 request for info re status of ruledating proceeding to develop value for radon in Table 5-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health offects of radon releases CHRISTENBURY. E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon (saue was in erroriALAB-540 consolidated only 5 of 15 cases Denies NRC motion as to parties in other proceedings Certificate of Evc encl DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/05/25
- a Inspection reports, IE Builetins & correspondence
- 7906010322 Forwards IE lnsp Repts 50-518/79-05.50-519/79-05, 50-520/79-05 & 50-521/79-05 on 790220-23 No nemcompliance noted MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906010328 IE Insp Repts 50-518/79-05, 50-519/79-05, 50-520/79-05 & 50-521/79-05 on 790220-23 No noncompliance noted Major areas inspected review of previous insp findings, spray ponds & containment concrete SWAN.W B Region 2. Atlanta, Office of the Director 79/04/02 600
- 7906130147 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase " No written response required O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/02 10
- 7906210098 Responds to IE Builetin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312. Type 304 piping supplied by Youngstown Welding & Engineering OILLELAND. J E Tennessee Valley Authority 79/05/14 ip
- DOCKET STN-50-522 SKAOIT NUCLEAR POWER PROJECT, UNIT 1

  A Application/construction stage documents & correspondence
- 7906150229 Forwards May 1976 "Environ Analysis Rept Mt Baker-Gnogvalate Natl Forest " Rept available in Central Files only MCGUIRE, J. R. Agriculture, Dept of 76/06/06 ip
- 7905310385 "Rept of Geningic Investigations in 1978-79 "
  \* Puget Sound Power & Light Co 79/05/31 200pp
- 7906:50261 Forwards info re costs associated w/selection of alternate sites, as requested in NRC 790321 ltr Tabulation & summary explanation sheets encl MECCA.J E Puget Sound Power & Light Co 79/06/12 4pp
- O Adjudicatory correspondence
- 7906010014 Replaces 790115 list of principal issues, submitted per A9LAB 790209 order Certificate of Svc encl
  LEED,R M. GENDLER,M W. Skagitonians Concerned About Nuclear Plants 79703716 23pp
- 7906090115 Various ltrs objecting to proposed const of facility IVERBON.W . HIENER.R , SCHULTZ.S Affiliation Unknown 79/04/10
- 7906020227 Request by intervenors Skagitonians Concerned About Nuclear Plants for motion ordering review of NRC position re relevance of Class 9 accident issue Renews motion to consider Class 9 accidents Centificate of 8vc enci LEED.R N Leed. Roger M 79/04/27 5pp
- 7906220122 Forwards "1979 West Group Forecast "
  THOUSEN F T Perkins, Cole, Stone, Olsen & Williams 79/09/04

7

- 7906200602 Requests denial of 790427 motion by Skagitonians Concerned About Nuclear Power In NRC proceeding ASLB, not NRC, grants license on basis of record & Board member personal tise Certificate of Svc encl R.M.A. Lowenstein:Newman:Rois:Arelrad & Toll 79/05/08 App
- 7906280017 Requests denial of Skagitonians Concerned About Nuclear Plants 790427 motion re consideration of Class 9 accidents NRC policy provides that Class 9 accidents need not be considered in EIS Certificate of Svc encl
  THOMSEN,F T Perkins, Coie, Stone, Olsen & Williams 79/05/11
- 7906200466 Reviews NRC safety review efforts in response to 790405 ltr expressing concerns re proposed nuclear facility close to Canadian border & City of Vancouver DENIDN.HR Office of Nuclear Reactor Regulation 79/05/16 2pp
- DOCKET 8TN-50-523 SKAGIT NUCLEAR POWER PROJECT, UNIT 2 A Application/construction stage documents & correspondence
- 7906150229 Forwards May 1976 "Environ Analysis Rept Mt Daker-Snogvalmie Natl Forest " Rept available in Central Files only MCOURE, J R Agriculture, Dept of 76/06/06 ip
- 7905310385 "Rept of Geologic Investigations in 1978-77" \* Puget Sound Power & Light Co 79/05/31 200pp
- 7906150261 Forwards info re costs associated w/selection of alternate sites, as requested in NRC 790521 htr Tabulation & summary explanation sheets encl
  MECCA.J E Puget Sound Power & Light Co 79/06/12 4pp
- O Adjudicatory correspondence
- 7906010014 Replaces 790115 list of principal issues submitted per ASLAB 790208 order Certificate of Svc encl LEED.R M , GENDLER, M W Skagitonians Concerned About Nuclear Plants 79/03/16 23pp
- 7904050115 Various ltrs objecting to proposed const of facility IVERBON,W , HIENER,R , SCHULTZ,B Affiliation Unknown 79/0
- 7906020229 Request by intervenors Skagitonians Concerned About Nuclear Plants for motion ordering review of NRC position re relevance of Class 9 accident issue Renews motion to consider Class 9 accidents Certificate of Svc encl LEED, R. N., Leed. Roger M 79/04/27 Spp
- 7906220122 Forwards "1979 West Group Forecast " THOMSEN.F T Perkins, Coie, Stone, Olsen & Williams 79/0\$/04
- 7906250224 Forwards amended response to Interrogatory 5 previously submitted on 790214

  BLACK:R L., Branch 1 79/05/04 1p
- 7906200602 Requests denial of 790427 motion by Skagitonians Concerned About Nuclear Power. In NRC proceeding, ABLB, not NRC, grants license on basis of record & Board member personal expertise Certificate of Svc encl BAUSER, M.A. Lowenstein, Newman, Reis, Axelrad & Toll 79/05/08, Spp
- 7906280017 Requests denial of Bkagitonians Concerned About Nuclear Plants 790427 motion re consideration of Class 9 accidents NRC policy provides that Class 9 accidents need not be considered in EIB Certificate of Byc encl
- 7904200466 Reviews NRC safety review efforts, in response to 790405

  1th expressing concerns re proposed nuclear facility close
  to Canadian border & City of Vancouver

  DENTON, HR Office of Nuclear Reactor Regulation 79/05/16 2pp
- DOCKET STN-50-528 PALO VERDE NUCLEAR STATION, UNIT 1 A Application/construction stage documents & correspondence
- 7906200319 Summary of 790425-26 meeting w/util in Phoenix, AZ re status of const. LICITRA, E, Light Water Reactors Branch S. 79/05/14 6pp

- 7908080265 Forwards press release announcing 1-yr delay in Unft I commercial operation, which is still within CP latest completion date Will file FSAR & OL stage environ rept in Cot 1979 UCAN BRUNT, E. E. Arizona Public Service Co. 79/05/25 4pp
- G Adjudicatory correspondence
- 7906220334 Objects to proposed facility site PARKER, Q A Affiliation Unknown 79/06/07 ip
- G Inspection reports, IE Bulletins & correspondence
- 7906120043 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem " No action required ENGLIKEN-R H Region S. San Francisco, Office of the Director 79/05/07
- 7906180472 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN R H Region 5, San Francisco, Office of the Director
- 7906080240 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN R H Region 5, San Francisco, Office of the Director 79/05/18
- 7906130037 Forwards IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/22
- 7904200049 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" ENGELKEN, R H Region 5, Ban Francisco, Office of the Director
- 8 Reportable occurrences, LERs & related correspondence
- 7906180213 Forwards PND-79-67AN
  ENGELKEN, R H Region 5. San Francisco, Office of the Director
  79/05/16 ip
- 7906180261 Forwards PNO-79-67AO ENGELKEN, R H Region S. San Francisco. Office of the Director 79/05/21
- 7706180335 Forwards PND-77-67AP ENGELKEN,R.H Region 5, flan Francisco, Office of the Director 79/05/22. 1p
- 7906180361 Forwards PNO-79-67AQ ENGELKEN, R H. 79/05/30. 1p Region S. San Francisco, Office of the Director
- DOCKET STN-50-529 PALG VERDE NUCLEAR STATION, UNIT 2 A Application/construction stage documents & correspondence
- 7906200319 Summary of 790425-24 meeting w/util in Phoenix: AZ re status
- Light Water Reactors Branch 3 79/05/14, App.
- 7704060266 Forwards press release announcing 1-up delay in Unit 1 commercial operation, which is still within CP latest completion date Will file FBAR & DL stage environ rept in VAN BRUNT, E. E. Arizona Public Service Co 79/05/25 4ap.
- Q Adjudicatory correspondence
- 7906220334 Objects to proposed facility site. PARKER.O.A Affiliation Unknown. 79/06/07
- G Inspection reports, IE Bulletine & correspondence
- 7906120043 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem." No action required.
  ENGELKEN.R H Region 5: San Francisco. Office of the Director. 79/05/07

79/05/22

1 5

- 7906180472 Forwards IE Info Notice 79-12. "Attempted Damage to New Fue) Assemblies "No written response necessary ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/10 1p
  - 79/05/10 lp
- 7906080240 Forwards 1E Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN.R H Region 5. San Francisco, Office of the Director 79/03/18 ip
- 7906130037 Forwards 1E Bullatin 79-11, "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required ENGELKEN.R H Region 5, San Francisco. Office of the Director
- 7905200049 Forwards IE Info Notice 79-13, "Indication of Low Hater Level in Oyster Creek Reactor" ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/29 to
- S Reportable occurrences, LERs & related correspondence
- 7906180213 Forwards PND-79-67AN
  ENGELKEN, R H
  Region 5. San Francisco, Office of the Director
  79/05/16 ip
- 7906180261 Forwards PNO-79-67AO ENGELKEN.R H Region 5. San Francisco. Office of the Director 79/05/21 1p
- 7906180333 Forwards PNO-79-67AP ENGELKEN, R H Region 5. San Francisco. Office of the Director 79/05/22 1p
- 79051B0361 Forwards PNO-79-67AG ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/30 in
- DOCKET STM-50-530 PALO VERDE NUCLEAR STATION, UNIT 3

  A Application/construction stage documents % correspondence
- 7906200317 Summary of 790425-26 meeting w/util in Phoenix.AZ re status of const Light Water Reactors Branch 3 79/05/14 6pp
- 7904060266 Forwards piess release announcing 1-gr delay in Unit 1 commercial operation, which is still within CP latest completion date Will file FSAR & OL stage environ rept in Oct 1979
  VAN BRUNT, E E Arizona Public Service Co 79/05/25 4gp
- O Adjudicatory correspondence
- 7906220334 Objects to proposed facility site PARKER.O A Affiliation Unknown 79/06/07 ip
- a Inspection reports. IE Bulletins & correspondence
  - Forwards 1E Info Notice 79-11, "Lower Reactor Vessel Head on Support Problem " No action required ',R H Region 5, San Franciscor Office of the Director 19
    - 79-12. "Attempted Damage to New Fuel Decessary len Office of the Director

tion - Low

- 5 Reportable occurrences, LERs & related correspondence
- 7906180213 Forwards PND-79-67AN ENGELKEN, RH Region 5. San Francisco, Diffice of the Director 79/05/16 1p
- 7906180261 Forwards PNO-79-67AD
  ENGELMEN, R N Region 5, San Francisco, Office of the Director
  79/05/21 Ip
- 7906180335 Forwards PNO-79-67AP ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/22 lp
- 7906180361 Forwards PNO-79-67AQ ENGELKEN.R H Region 5, San Francisco, Office of the Director 79/05/30 1p
- DOCKET 50-837 CLINCH RIVER BREEDER REACTOR
- F Security, medical, emergency & fire protection plans
- 7906080288 Forwards responses to NRC request for add1 info re physical security plan Plan withheld (ref 10CFR2 790)
  COPELAND,R L Energy,Dept of 79/06/01 4pp
- DOCKET 50-538 MEMPHIS STATE UNIV RESEARCH REACTOR

  G Inspection reports, IE Bulletins A correspondence
- 7906250417 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " O'REJLLY, J.P. Region 2. Atlanta. Office of the Director 79/09/10 1p
- 7906080155 Ack receipt of 790417 ltr infarming NRC of steps taken to correct violations noted in IE Insp Rept 50-538/79-01
  KENNA,W B Region 2, Atlanta, Safeguards Branch 79/05/14 1p
- --7906080157 Forwards IE Insp Rept 50-538/79-01 on 790306-07 Notice of violation withheld (ref 10CFR2 790) KENNA: W B Region 2. Atlanta: Safeguards Branch /9/09/2J 200
- --7904080169 IE Insp Rept 50-538/79-01 on 790306-07 Noncompliance note; failure to conduct security program review Details withheld (ref 10CFR2 790) PERNY.C D Region 2, Atlanta, Office of the Director GILLESPIE.F P Region 2, Atlanta, Safeguards Branch 79/0J/≥3
- DOCKET STN-50-546 MARBLE HILL NUCLEAR STATION, UNIT 1
- C Utility Environmental Report (ER), amends & correspondence
- 7906280030 Environ rept for OL stage
  \* Public Service Co of Indiana. Inc 79/05/31 800pp
- **Q** Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-309
  SCINTO.J F Hearings Division 79/04/02 2pp
- ---7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY, E Hearings Division 79/03/26 34pp
  - '06040164 Util responds in support of de minimus theory per ALAB-509as modified by ALAB-512 & 790305 order Recomends termination of reservation of jurisdiction initiated in ALAB-480 & continued in ALAB-493 Certificate of Svc encl VOICHT.H H LeBoeuf, Lamb, Leiby & MacRae 79/04/09 16pp
  - ObjBO365 Ack receipt of 790405 board notification Items discussed are outside jurisdiction of boards & NRC Requests NRC stop distributions in this doctar vOlfor, H H LeBosuf, Lamb, Leiby & MacRae 79/04/23 2pp

# DOCKETED ITEMS

- 7906210075 NRC motion for summary disposition re radon issue was in error; ALAB-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Svc encl
  DUFLO, N E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906180497 Forwards CE Cutshall statement to be considered as part of Save the Valley motion to reopen safety hearing DATTILO TM Dattilo, TM 79/06/12 ip
- --7906180500 Transcript of CE Cutshall statement re honeycomb patches in cement at facility, supporting Save the Valley motion to reopen safety hearings CUTSHALL,C E Affiliation Unknown 79/05/08 22pp
- K Utility Final Bafety Analysis Report (FSAR) & amends
- 7906280025 Forwards Amend 22 to license application, consisting of FBAR & environ rept for OL stage COUCHLINJ Public Service Co of Indiana, Inc. 79/06/01 3pp
- --7906280027 FSAR for facility \* Public Service Co of Indiana, Inc 79/05/31 8000pp
- --7906280030 Environ rept for OL stage
  \* Public Service Co of Indiana, Inc 79/05/31 800pp
- O Inspection reports. IE Bulletins & correspondence
- 7706120123 Forwards IE Info Notice 77~11. "Lower Reactor Vessel Head Insulation Support Problem " No action required KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/07
- 7906190101 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies" KEPPLER.J G Region 3. Chicago, Office of the Director 79/05/11 10
- 7906190225 Notification of 790515 meeting w/NRC in Plainfield, IN to discuss insp findings
  FIGRELLIC Region 3, Chicago, Office of the Director 79/05/14
- 7906230119 Responds to IE Bulletin 79-07 requesting info re seismic stress safety piping analysis DYNAPIPE & PIPSYS computer programs are used for piping sys COUGHLINJ Public Service Co of Indiana, Inc. 79/09/15 3pp
- 7906130113 Forwards IE Builetin 79-11. "Faulty Overcurrent Trip Device in Circuit Breakers for Engineered Safety Sys " Licensee action required KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/22
- 7906200136 Forwards [E Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/29 ip
- 7906220175 Ack receipt of 790502 interim rept re containment sump recirculation piping sleave Will complete review upon receipt of final rept FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 ip
- 7706230145 Ack receipt of 790509 interim rept re damage to containment liner FIGRELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 Ip
- 7906290804 Ack receipt of 790316 interim rept re post-tensioning trumplates
  FIGRELLI: Q Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/05/29 ip
- 7906130248 Provides addl info re two potentially reportable incidents
  Discusses qualifications of welders utilizing Cherne
  Contracting Corp welding procedures for radiographic
  examination of welds & qualification repts
  COUGHLIN, J Public Bervice Co of Indiana, Inc. 79/06/08 2pp
- U Congressional/Executive Correspondence
- 7906270058 Forwards CE Greenwood 790426 ltr re emergency planning for localities near nuclear facilities. HUDDLESTON:W.D Senate 79/05/21 1p

- DOCKET STN-50-547 MARBLE HILL NUCLEAR STATION. UNIT 2

  C Utility Environmental Report (ER), amends & correspondence
- 7906280030 Environ rept for OL stage
  # Public Service Co of Indiana, Inc. 79/05/31 800pp
- G Adjudicatory correspondence
- 7904210047 Motion for extension until 790411 to prepare response to ALAB-507 SCINTO, J F Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulemakir proceeding to develop value for radon in Table S-3 Rept b proposed rule will be sent to NRC by 790406 Rule dues not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7906040[64 Util responds in support of de minimus theory per ALAR-509, as modified by ALAR-512 \$ 790305 order Recomends termination of reservation of jurisdiction initiated in ALAR-480 & continued in ALAR-493 Certificate of Svc encl VOIGHT.H H LeBoouf, Lamb, Leiby \$ MacRae 79/04/09 16pp
- 7906180565 Acv receipt of 790405 board notification Items discussed are outside jurisdiction of boards & NRC Requests NRC stop distributions in this docket VDIOT, H H LeBoeuf. Lamb. Leiby & MacRae 79/04/23 2pp
- 7906210095 NRC motion for summary disposition re radon issue was in error: ALAB-540 consolidated only 5 of 16 cases Denies NRC mation as to parties in other proceedings Certificate of Svc enci
  DUFLO, M E Atomic Safety and Licensing Appeal Panel 79/05/25
- 7906180497 Forwards CE Cutshall statement to be considered as part of Bave the Valley motion to reopen safety hearing DATTILO.T.M Dattilo.T.M 79706/12 ip
- --7906180500 Transcript of CE Cutshall statement re honeycomb patches i cement at facility, supporting Save the Valley motion to reopen safety hearings CUTSHALL, C E Affiliation Unknown 79/05/08 22pp
- K Utility Final Safety Analysis Report (FSAR) & amends
- 7906280025 Forwards Amend 22 to license application consisting of FSAR & environ rest for DL stage COUGHLIN, J Public Service Co of Indiana, Inc. 79/06/01 3pp 1
- --7906280027 FSAR for facility \* Public Service Co of Indiana, Inc 79/05/31 8000pp
- Q Inspection reports, IF Bulletins & correspondence
- 7906120123 Forwards IE Info Natice 79-11, "Lower Reactor Vessel Head Insulation Support Problem" No action required KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/07 to.
- 7906190101 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J O Region 3. Chicago. Office of the Director 79/05/11
- 7906190225 Notification of 790515 meeting w/NRC in Plainfield IN to discuss imsp findings FIORELLI,0 Region G, Chicago, Office of the Director 79/05/14
- 7906230119 Responds to IE Bulletin 79-07 requesting info re seismic stress safety piping analysis DYNAPIPE & PIPSYS computer programs are used for piping sys.

  COUCHLINJ Public Service Co of Indiana. Inc 79/08/15 3pp
- 7906130113 Forwards IE Bullatin 79-11, "Faulty Overcurrent Trip Device in Circust Breakers for Engineered Safety Bys." Licensee action required KEPPLER, J. G Region 3, Chicago, Office of the Director 79/05/22 in
- 7906200136 Forwards IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor " KEPPLER,J G Region 3, Chicago, Office of the Director 79/09/29

# S Reportable occurrences. LLRs & related correspondence

- 7906220175 Ack receipt of 790502 interim rept re containment sump recirculation piping sleeve Will complete review upon receipt of final rept FIORELLI, O Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/24 ip
- 7906250145 Ack receipt of 790909 interim rept to damage to containment liner FIORELLI, G Region 3. Chicago, Reactor Construction & Engineering Support Branch 79/05/24 ig
- 7906290804 Ack receipt of 790516 interim rept re post-tensioning trumplates
  FIORELLI, G Region 3, Chicago, Reactor Construction & Engineering Support Branch 79/05/29 ip
- 7906130248 Provides add1 info re two potentially reportable incidents
  Discusses qualifications of welders utilizing Cherne
  Contracting Corp welding procedures for radiographic
  ezamination of welds & qualification repts
  COUGHLIN, J Public Service Co of Indiana, Inc 79/06/08 2pp

### U Congressional/Executive Correspondence

7906270058 Forwards CE Greenwood 790426 ltr re emergency planning for localities near nuclear facilities
MUDDLESTON.W D Senate 79/05/21 1p

# DOCKET 50-549 GREENE COUNTY NUCLEAR POWER PLANT

#### G Adjudicatory correspondence

- 7903210406 Objects to interrogatories of Green County,NY, because Interrogatories 9(A),7(B) & 11(H) require compilation of data, add research & addl calculations. Certificate of Svc encl LENIS,B H Branch 2 79/03/05 200
- 7906040147 Grants various extensions in discovery schedules 900DHOPE, A C Atomic Safety and Licensing Board Panel COHEN, E D New York, State of 79/03/13 2pp
- 7906010070 Objects to util 790305 second document request Certificate of Byc encl LEMIS, 8 H Branch 2 79/03/14 13pp
- 7904010106 Forwards JA Nickolitch 790312 testimany re land use issues NICKOLITCH, J A Gementon Civic Association 79/03/14 ip
- --7906010111 Testifies on land use issues Supporting documentation encl NICKOLITCH.J A Comenton Civic Association 79/03/12 21pp
- 7906010066 Response by intervenor Greene County (NY) to NRC & NY State Public Svc Commission objections to interrogatories subnitted by county to NRC & state Commission witnesses BUTZEL, A K Butzel & Kass 77/03/19, 4pp
- 7906010290 Notice of cancellation of all scheduled hearings at request of util COLE.R F Atomic Gafety and Licensing Board Panel 79/04/19, ip

## DUCKET STN-50-553 PHIFFS BEND NUCLEAR PLANT, UNIT 1

# A Application/construction stage documents & correspondence

- 7706180733 Concurs w/enci util rept conclusion component cooling water trench fault is minor cross fault Based on evidence to date, trench fault is considered to be noncapable JACKSON, R E Geosciences Branch 77/05/14 2pp
- /906250264 Notification of 790619 meeting w/util to discuss leat testing temp & pressure stds for piping embedded in concrete BENEDIGT, R A Light Water Reactors Branch 2 79/05/21 App
- 7906220245 Forwards "Structural Geology of Sevier Formation Folds & Faults at Plant Site."
  OILLELAND. J. E Tennessee Valley Authority 79/06/19 ip.
- --7906220246 "Structural Geology of Savier Formation Folds & Faults at Plant Site " WEBB,F. Tennesses Valley Authority 79/05/16, 10pp.

- 7906260224 Forwards add1 drawings to encl to 790430 ltr re fault in area of cooling water pumping station Two oversized drawings encl OILLELAND, J E Tennessee Valley Authority 79/06/19 ip
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 790411 to prepare response to ALAB-509
  SCINTO, J.F. Hearings Division 79/04/02 2pp
- --7906210060 Responds to 790322 request for info re status of rulerall's proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406 Rule does not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7906210095 NRC motion for summary disposition re radon issue was in error/ALAD-540 consolidated only 5 of 16 cases Denies NRC motion as to parties in other proceedings Certificate of Bvc enci DUFLO.H E Atomic Safety and Licensing Appeal Panel 79/05/25

# @ Inspection reports. IE Bulletins & correspondence

- 7906130146 Forwards IE Circular 79-07. "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase." No written response required O'REILLY, J.P. Region 2. Atlanta, Office of the Director 79/05/02 in
- 7906010133 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 30-553/79-02 & 50-554/79-02 HVRPHY,C E Region 2. Atlanta, Reactor Construction & Engineerit Bupport Branch 79/05/04 1p
- --7906010135 Responds to NRC 790315 ltr re violations noted in II insp Repts 30-553/79-02 & 50-554/79-02 Corrective actions requested CF Braun & Co to amend concrets spec GILLELAND, J E Tennessee Valley Authority 79/04/09
- ---790601013B Forwards [E Insp Repts 90-553/79-02 & 90-554/79-02 on 790205-08 % notice of violation MURPHY, C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/03/15 9pp.
- --7906010141 Notice of violation from insp on 790205-08
  Region 2, Atlanta, Office of the Director 79/03/13
- --7906010143 IE Insp Repts 50-553/79-02 & 50-554/79-02 on 790205-08 Noncompliance noted replacement of 3-inch aggregate w/I 5-inch aggregate WRIGHT, R W. HERDT, A R. Region 2, Atlanta, Office of the Director 79/03/13 6pp
- 790621009B Responds to IE Bulletin 79-03 Investigation shows no fififul in use or planned in safety-related sys Effort in progress to locate any ASME BA-312. Type 304 piping supplied by Youngstown Helding & Engineering OILLELAND, J E Tennessee Velley Authority 79/05/14, 1p
- 7906020131 Ack receipt of 790308 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 80-853/79-03 4 50-854/79-03 HURPHY.C E Region 2: Atlanta, Reactor Construction & Engineering Bupport Branch. 79/05/16 2pp
- --7906020135 Responds to NRC 790413 itr re violations noted in IE Emap Rept 50-553/79-03 & 50-554/79-03 Corrective actions site procurament files have been revisued & site OA unit raview verified, Documentation revisue angoing, GILLELAND, J E Tennessee Valley Authority, 79/05/08 4pp
- --7706020139 Forwards IE Insp Rept 30-353/79-03 & 30-354/79-03 an 790326-29 & notice of violation MURPHY,C E Region 2. Atlanta, Office of the Director 79/04/13. 2pp
- --7906020140 Notice of violation from insp on 790326-29
  \*\* Region 2, Atlanta, Office of the Director 79/04/13 2\*\*\*
- --7906020144 IE Insp Rept 50-553/79-03 & 50-554/79-03 on 790326-29
  Noncompliance noted failure to follow procedures for safety-related ever contracts preventive maint implementation & in-process weight. High Michigan Contracts of the Director. 9 (41): 1... Heging 2, Atlanta, Office at the Director. 9 (41): 1...

- R Periodic operating reports & related correspondence
- 7906120337 Requests comments & recommendations re const effects monitoring program, semiannual & sediment-elutriate repts Requests response by 790613
  ZELLER, H D Environmental Protection Agency 79/06/04 ip
- S Reportable occurrences. LERs & related correspondence
- 7906140406 Submits interim deficiency rept tensile anchor capacities being lower than assumed in design allowables Initial rept made to M Gouge on 790507 Final rept expected by 790817 GILLELAND, J E Tennessee Valley Authority 79/05/24 2pp
- 7906190431 Forwards deficiency rept re const of piping elbows w/unspecified matl GillElAND. J E Tennessee Valley Authority 79/03/25 1p
- --7906190442 Deficiency rept on 790525 piping elbows constructed from unspecified matl Elbows w/heat code W6719 were identified, tested & returned to manufacturer \* Tennessee Valley Authority 79/05/25 3pp
- 7906190381 Forwards detailed description of fault discovered in Unit 2 turbine bldg area
  OILLELAND, J E Tonnessee Valley Authority 79/06/14 4pp
- DOCKET STN-50-554 PHIPPS BEND NUCLEAR PLANT, UNIT 2
- A Application/construction stage documents & correspondence
- 7906180733 Concurs w/encl util rept conclusion component cooling water trench fault is minor cross fault Based on evidence to date, trench fault is considered to be noncapable JACKBON-R E Geosciences Branch 79/05/14 2pp
- 7906250264 Notification of 790619 meeting w/util to discuss leak testing, temp & pressure atds for piping embedded in concrete BENEDICT, R A Light Water Reactors Branch 2 79/05/21 4pp
- 7906220245 Forwards "Structural Omology of Sevier Formation Folds & Faults at Plant Site."

  OILLELAND, J E Tennessee Valley Authority 79/06/19 1p
- ---7706220246 "Structural Geology of Sevier Formation Folds & Faults at Plant Site " WEBB.F Tennessee Valley Authority 79/05/16 10pp
- 7906260224 Forwards addit drawings to enc.) to 790430 ltm refault in area of cooling water pumping station Two oversized drawings enc.l
  OILLELAND, J.E. Tennessee Valley Authority 79/06/19. ip
- G Adjudicatory correspondence
- 7906210047 Motion for extension until 7904f1 to prepare response to ALAB-509 BCINTO, J F Hearings Division 79/04/02, 2pp
- --7906210060 Responds to 790322 request for info re status of rulemaking proceeding to develop value for radon in Table 8-3 Rept & proposed rule will be sent to NRC by 790406. Rule does not address health effects of radon releases CHRISTENBURY.E Hearings Division 79/03/26 34pp
- 7906210093 NRC motion for summary disposition re radon issue was in error/ALAB-540 consolidated only 5 of 16 cases, Denies NRC motion as to parties in other proceedings Certificate of Bvc enci. DUFLD:M E Atomic Bafety and Licensing Appeal Panel 79/05/25
- G. Inspection reports, IE Bulletins & correspondence
- 7906130146 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Motor Generator Set Resulted in Reactor Power Increase" No written response required 0'REILLY.J P. Region 2, Atlanta, Office of the Director. 79/05/02 Ip
- 7906010133 Ack receipt of 790409 ltr informing NRC of steps taken to correct violations noted in IE Insp Repts 50-553/79-02 b 30-554/79-02 hURPHY.C.E. Region 2. Atlanta. Reactor Construction & Engineering Support Branch. 79/05/04. ip.

- ---7906010135 Responds to NRC 790315 ltr re violations noted in IE Insp Repts 50-553/79-02 & 50-534/79-02 Corrective actions requested CF Braun & Co to amend concrete spec OILLELAND.J E Tannesses Valley Authority 79/04/09 3pp
- --7906010141 Notice of violation from (msp on 790205-08
  Region 2. Atlanta, Office of the Director 79/03/13 ip
- --7906010143 IE Insp Repts 50-553/79-02 & 50-554/79-02 on 790205-08 Noncompliance noted replacement of 3-inch aggregate w/1 5-inch aggregate WRIGHT.R H , HERDT.A R Region 2, Atlanta, Office of the Director 79/03/13 App
- 7906210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312. Type 304 piping supplied by Youngstown Helding & Engineering OILLELAND, J E Tennessee Valley Authority 79/05/14 1p
- 790&020131 Ack receipt of 790508 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 30-553/79-03 & 30-554/79-03 MURPHY.C E Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/03/16 2pp
- --7904020135 Responds to NRC 790413 ltr re violations noted in IE Insp Rept 50-553/79-03 % 50-554/79-03 Corrective actions site procurement files have been reviewed & site QA unit review verified Documentation review ongoing GILLELAND.JE Tennessee Valley Authority 79/05/08 App
- --7906020137 Forwards IE Insp Rept 50-553/79-03 & 50-554/79-03 on 790326-29 & notice of violation MURPHY.C E Region 2. Atlanta. Office of the Director 79/04/13 2pp
- --7906020140 Natice of violation from Insp on 790326-27
  \* Region 2, Atlanta, Office of the Director 79/04/13 2pp
- --7906020144 IE Insp Rept 50-553/79-03 & 50-554/79-03 on 790926-29 Noncompliance noted failure to follow procedures for safety-related svc contracts, preventive maint implementation & in-process welding WIGHT.R W. OBUOE.M J. HERDT.A R Region 2. Atlanta, Office of the Director 79/04/13 lipp
- R Periodic operating reports & related correspondence
- 7906120337 Requests comments & recommendations re const effects monitoring program semiannual & sediment-elutriate repts Requests response by 790613

  ZELLER, H D Environmental Protection Agency 79/06/04 1p
- 8 Reportable occurrences: LERs & related correspondence
- 7906140406 Submits interim deficiency rept tensile anchor capacities being lower than assumed in design allowables Initial rept made to M Gouge on 790507 Final rept expected by 790817 OllLELAND. J E Tennesses Valley Authority 79/05/24 2pp
- 7906190431 Forwards deficiency rept re const of piping elbows w/unspecified metl
  QILLELAND, J E Tennessee Valley Authority 79/05/25 ip.
- ---7906190442 Deficiency rept on 790325 piping elbows constructed from unspecified matl Elbows w/heat code 46717 were identified, tested & returned to manufacturer \* Tennessee Valley Authority 79/03/25 3pp
- 7906190381 Forwards detailed description of fault discovered in Unit 2 turbine bldg area GILLELAND.J E Tennessee Valley Authority 79/06/14, 4pp
- DOCKET STN-50-556 BLACK FOX STATION, UNIT 1
- A Application/construction stage documents & correspondence
- 7706200333 Describes technical advisory committee program to assess TMI-2 events & apply lessons learned Tasks included assuring containment isolation & identifying sys used in transfer of radioactive fluid.

  FATE: M E Public Bervice Co. of Oklahoma, 79/06/15 80pp

#### G Adjudicatory correspondence

- 7906010081 Advises of filing of util proposed findings of fact re load combination methodology for reasons discussed in 790326 finding of facts.conclusions of laws & proposed order Centificate of Svc encl GALLO.J Isham. Lincoln & Beale 79/03/28 App
- ~~790A010089 Util proposed findings of fact re load combination methodology GALLOJ Isham, Lincoln & Beale 79/03/28 14pp
- 7904040385 Grants 790403 motion for extention,until 790412, for intervenors to file proposed findings of fact & conclusions of law MOLFE.S J Atomic Bafety and Licensing Board Panel 79/04/11 lp
- 7906040389 Denies GE 790328 motion requesting return of Reed rept brelated subtass force repts
  SHON.F J. WOLFE,S J. Atomic Safety and Licensing Board Panel
  79/04/12 2pp
- 7906040412 Grants 790416 motion for extension, until 790426, requested by to file proposed findings of fact & conclusions of law as requested by NRC WOLFE.S J. Atomic Safety and Licensing Board Panel 79/04/17 lp
- 7906050068 Responds to JG Davis 790411 ltr Provides info re ultimate heat sink sys & interconnection of sys between reactors Certificate of Svc encl DALTON.A T Dalton, A T 79/04/17 3pp
- 7906040379 Forwards application & complaint as attachment to motion of State of OK for indefinite stay in issuance of initial decison ROGERS.C S Qklahoma, State of 79/04/20 App
- 7906020233 Notice of filing by util to proposed findings of fact 5 conclusions of law from NRC & intervenors Notice of appearance of ME Gibbs on behalf of util 5 Certificate of Svc entl OALLO, J. GIBBS, M.E. Isham, Lincoln & Reale 79/04/26 3pp
- --7906020234 Response by util to proposed fundings of fact & conclusions of law from NRC & joint intervenors Citizens Action for Safe Energy. I Younghein & L Burrell Limited to findings where clarification of record is required GIBBB.M E . GALLO.J Isham, Lincoln & Beale 79/04/26 37pp
- 7906080114 Util request that ASLB grant extension until 790901, to permit util to file answer to State of OK 790419 motion for indefinite stay in issuance of initial decision Certificate of Svc encil GALLO, J Public Service Co of Oklahama 79/04/30 4pp
- 7906040024 Grants util 790504 motion to file replies by 790518 to intervenors 750427 repense to State of OK 790427 motion for indefinite stay in issuance of initial decision WOLFE.8 J Atomic Safety and Licensing Board Panel 79/05/04 1p
- 7906200390 Requests ASLB grant extension until 790318 for util to file answer to intervenors 790419 motion for indefinite stay of initial decision Motion seeks addl relief-reply is warranted Cortificate of Svc encl GALLO
- 7906220130 Submits draft of proposed ECCS findings which reflect record as of close of Feb 1977 hearing Certificate of Svc encl DAVIS.L D Branch 4 79/05/09 Sipp
- 7906260490 Response by applicants to State of OK motion for indefinite stay in issuance of initial decision State lacks standing to file motion w/ASLB: legal requirements for obtaining stay have not been met W/zupporting ltr & Certificate of Svc QALLO.J. GIBBS.M E Isham. Lincoln & Beale 79/05/11 24pp
- 7906190022 Grants applicant 790521 motion to file reply by 790531 to NRC response to State of DK motion for indefinite stay on issuance of initial decision & to intervenor 790518 motion to reopen record WOLFE, B J Atomic Safety and Licensing Board Panel 79/05/22 ip
- 7906230171 Certifies NRC determination of returning Reed rept & subtask force repts to OE Two requests to review repts were untimely Recommends repts under protective order, be returned WOLFE-S J Atomic Safety and Licensing Board Panel 79/05/30. Spp

- --7906250184 Hotion by GE to quash ASLB 781018 subposed to produce Responser OE willing to submit rept for insp by ASLB to determine lack of relevance to proceeding Requests appearance to present oral argument in support of motion EDGAR.G L , GALLEN.K P Horgan, Lewis & Bockius 78/10/30 3pp
- --7906250205 Memo by GE supporting 781030 motion to quash ASLB 781018 subpoens to produce Read rept Requests discovery be denied Info neither relevant nor necessary to decision M/supporting documentation EDQAR.G E , GALLEN.K F Horgan, Lewis & Bockius 78/10/30 44pp

### H General correspondence

- 7906010163 Responds to 790417 ltr Discusses release of all portions of safety hearing transcripts
  ENGELMARDT.T F Office of the Executive Legal Director 79/05/09
  2pp
- --7906010166 Requests release of all portions of transcripts of safety hearings GARNETT.H Affilization Unknown 79/04/17 1p
- DOCKET STN-50-557 BLACK FOX STATION, UNIT 2

  A Application/construction stage documents & correspondence
- 7906200333 Describes Sechnical advisory committee program to assess TMI-2 events & apply lessons learned Tasks included assuring containment isolation & identifying sys used in transfer of radioactive fluid FATE.M E Public Service Co of Oklahama 79/06/15 BOpp
- G Adjudicatory correspondence
- 7906010081 Advises of filing of util proposed findings of fact re load combination methodology for reasons discussed in 790326 finding of facts, conclusions of laws & proposed order Certificate of Syc encl GALLO.J Isham, Lincoln & Beals 79/03/28 4pp
- --7906010089 Util proposed findings of fact re load combination methodology GALLO.J Isham, Lincoln & Beale 79/03/28 14pp
- 7904040385 Grants 790403 motion for extention until 790412 for intervenors to file proposed findings of fact & conclusions of law MOLFE S J Atomic Safety and Licensing Board Panel 79/04/11 10
- 7905040412 Grants 770416 motion for extension until 790426 requested by to file proposed findings of fact & conclusions of law as requested by NRC

  HOLFE 8 J Atomic Safety and Licensing Board Panel 79/04/17 ip
- 790605006B Responds to JO Davis 790411 ltr Provides info re ultimate heat sink sys & interconnection of sys between reactors Certificate of Svc encl DALTON: A T Dalton, A T 79/04/17 3pp
- 7906040379 Forwards application & complaint as attachment to motion of State of OX for indefinite stay in issuance of initial decision RDGER8.CS Oklahoma, State of 79/04/20 Spp
- 7706020253 Notice of filing by util to proposed findings of fact & conclusions of law from NRC & intervenors Notice of apptarance of ME Gibbs on behalf of util & Certificate of Bvc encl GALLO. J. GIBBS. M E Isham, Lincoln & Beale 77/04/26 3pp
- --7904020204 Response by util to proposed findings of fact & conclusions of law from NRC & joint intervenors Citizens Action for Safe Energy, I Younghein & L Burrell Limited to findings where clarification of record is required OIBBS,M & , GALLO,J Isham, Lincoln & Deale 79/04/24 37pp
- 7905080114 Util request that ASLB grant extension until 79050), to permit util to file answer to State of OK 790419 motion for indefinite stay in issuance of initial decision Certificate of 8vc encl GALLO, J Public Service Co of Oklahoma 79/04/30 4pp

- 7906040024 Grants util 790504 motion to file replies by 790518 to intervenors 790427 reponse to State of DK 790427 motion for indefinite stay in issuance of initial decision WDLFE.S J Atomic Safety and Licensing Board Panel 79/05/04 ip
  - IDLFE: 5 0 Atomic Safety and Dicensing board Panel 74703704 II
- 7906200590 Requests ASLB grant extension until 790518 for util to file answer to intervenors 790419 motion for indefinite stay of initial decision Motion seeks addit relief, reply is warranted Certificate of Svc encl
  GALLO, J Public Service Co of Okiahoma 79/05/04 5pp
- 7906220130 Submits draft of proposed ECCS findings which reflect record as of close of Feb 1979 hearing Certificate of Svc encl DAVIS,L D Branch 4 79/05/09 31pp
- 7906260490 Response by applicants to State of CK motion for indefinite stay in issuance of initial decision State lacks standing to file motion w/ASLB, legal requirements for obtaining stay have not been met W/supporting It & Certificate of Svc OALLO, J. GIBBS.M E Isham. Lincoln & Beale 79/05/11 24pp
- 7906190022 Grants applicant 790921 motion to file reply by 790931 to NRC response to State of OK motion for indefinite stay on issuance of initial decision & to intervenor 790918 motion to reopen record WOLFE.S J Atomic Safety and Licensing Board Panel 79/09/22 19
- 7906250171 Certifies NRC determination of returning Reed rept > subtask force repts to GE Two requests to review repts were untimely Recommends repts under protective order, be returned MOLFE, S J Atomic Safety and Licensing Board Panel 79/05/30 Spp
- --7906250184 Motion by GF to quash ASLB 781018 subpoens to produce Reed rept GE willing to submit rept for insp by ASLB to determine lack of relevance to proceeding Requests appearance to present oral argument in support of motion EDGAR, G L , GALLEN, K P Morgan, Lewis & Bockius 78/10/30 Spp
- --7906250205 Memo by GE supporting 781030 motion to quash ASLB 781018 subposes to produce Read rept Requests discovery be denied Info neither relevant nor necessary to decision W/supporting documentation EDGAR.Q L. GALLEN.K P Morgan. Lewis & Bockius 78/10/30 44pp

### H General correspondence

- 7906010163 Responds to 790417 ltr Discusses release of all portions of safety hearing transcripts
  ENGELHARDT, T F Office of the Executive Legal Director 79/05/08
  2pp
- ---7906010166 Requests release of all portions of transcripts of safety hearings OARNETT,H Affiliation Unknown 79/04/17 1p

### DOCKET STN-50-561 8-8AR-205

- A Application/construction stage documents & correspondence
- 7706270187 Discusses encl B&W responses to NRC request for info regeneric issues identified in answers to BSAR~241 first round questions TEDESCORL Assistant Director for Plant Systems 76/04/08 ip

### DOCKET STN-50-966 YELLOW CREEK NUCLEAR PLANT, UNIT 1

- A Application/construction stage documents & correspondence
- 7906010245 Notification of 790511 meeting w/util in Cornith.MS to observe & discuss site geology & soils ROOD.H Light Water Reactors Branch 2 79/05/07 2pp
- 7906250264 Notification of 790619 meeting w/util to discuss leak testing temp & pressure stds for piping embedded in concrete BENEDICT.R A Light Water Reactors Branch & 79/05/21 4pp
- 7906290657 Summary of 790511 site visit & meeting w/MS Geological Survey, AL Geological Survey, Army Corps of Engineers & TVA at Yallow Creek site to inspect & discuss foundation conditions & verify continuity of exposed geological strata LEFEVRE, H E. Geosciences Branch 79/05/24 App

- G Inspection reports. IE Bulletins & correspondence
- 7906010018 Forwards lE Insp Repts 90-366/79-05 % 50-367/79-05 on 790313-15 No noncompliance noted MCRPHY.C E Region 2. Atlanta. Reactor Construction & Engineering Support Branch 79/04/02 2pp
- --7906010023 IE insp Repts 50-566/79-05 % 50-567/79-05 on 790312-15 No nancompliance noted Major areas inspected const status, procedures, work performance & associated quality records for site preparation & structural concrete HARRIS, J R Region 2, Atlanta, Office of the Director BRYANT, J C Region 2, Atlanta, Reactor Construction & Engineering Support Branch 79/04/02 4pp
- 7906260241 Forwards IS Insp Repts 50-566/79-06 % 50-567/79-D6 on 790410-12 No noncompliance noted MURPHY, C E Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 2pp
- --7906260247 IE Insp Repts 50-566/79-06 % 50-567/79-06 on 790410-12 No noncompliance noted Major areas inspected const status, licensee action on provious insp findings, GA records, warehouse storage & preventive maint sys GOUGE, M J . HERDT. A R Region 2. Atlanta, Reactor Construction & Engineering Support Branch 79/04/26 7pp
- 7906210098 Responds to IE Bulletin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312. Type 304 piping supplied by Youngstown Welding & Engineering OILLELAND. J E Tennessee Valley Authority 79/05/14 ip
- 5 Reportable occursences. LERs & related correspondence
- 7906190431 Forwards deficiency rept le const of piping elbows w/unspecified mati OILLCLAND.JE Tennessee Valley Authority 79/05/25 1p
- --7906190442 Deficiency rept on 790525 piping elbows constructed from unspecified matl Eibows w/heat code W6719 were identified, tested & returned to manufacturer \* Tennessee Valley Authority 79/05/25 3pp
- DOCKET STN-50-567 YELLOW CREEK NUCLEAR PLANT, UNIT 2

  A Application/construction stage documents & correspondence
- 7906010245 Notification of 790511 meeting w/utit in Corrith.MS to observe b discuss site geology & soils RGDD.H Light Water Reactors Branch 2 79/05/07 2pg
- 7906230264 Notification of 790619 meeting w/util to discuss leak testing, temp & pressure stds for piping embedded in concrete BENEDICT, R A Light Water Reactors Branch 2 79/05/21 4pp
- 7906290657 Summary of 790511 site visit & meeting w/MS Geological Survey, AL Geological Survey, Army Corps of Engineers & TVA at Yellow Creek site to inspect & discuss foundation conditions & verify continuity of exposed geological strata LEFEVRE, H E

- 7906210098 Responds to IE Bullatin 79-03 Investigation shows no piping in use or planned in safety-related sys Effort in progress to locate any ASME SA-312.Type 304 piping supplied by Youngstown Welding & Engineering OILLELAND, J E Tennessee Valley Authority 79/05/14 1p
- S Reportable occurrences, LERs & related correspondence
- 7906190431 Forwards deficiency rept re const of piping elbows w/unspecified matl GILLELAND, J E Tennessee Valley Authority 79/05/25 ip
- --7906190442 Deficiency rept on 790825 paging elbows constructed from unspecified math Elbows w/heat code W6719 were identified, tastef & returned to manufacturer \* Tennessee Valley Authority 79/05/25 Jpp Tennessee Valley Authority
- DOCKET STN-50-568 NEP NUCLEAR, UNIT 1
- A Application/construction stage documents & correspondence
- 7906080239 Forwards "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978 " HARRINGTON, J New England Power Co 79/05/30 ip
- -- 7906080260 "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978 "
  HERSEY, R . WALSH, W P Rautheon Co 79/03/30 93pp
- 7906210383 Forwards preliminary case rept & fourth draft of "Historic, Architectural & Archeological Investigation of former Charlestown Naval Air Station & Vicinity " BALLARD,R L Environmental Projects Branch 1 79/05/31 10pp
- -7906210392 "Historic.Architectural & Archeological Investigation of Former Charlestown Naval Air Station & Vicinity," fourth Rhode Island: State of 75/02/28 63pp
- 7906120279 Forwards "Population Statistics & Commercial Catch Rate of American Lobster (Humarus Americanus) in Charlestown-Hatunuct;RI Region of Block Island Sound." HARRINGTON, J. New England Power Co 79/06/05 ip
- --7905120287 "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charlestown Matunuck,RI Region of Block Island Sound " MARCELLO: R A New England Power Co DAVIS.W, Yankee Atomic Electric Co YAEC-1175 79/04/30 SOpp
- 7906120402 Forwards "Currents & Residual Drift in Block Teland Sound During Period Feb-Dec 1977" HARRINGTON, J. New England Power Co. 79/06/06 1p
- --7906120408 "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977" SNOONS,J H New England Power Co JACOBSON,J P Yankee Atomic Electric Co YAEC-1149 79/03/30 173pp
- 7906120379 Forwards "Vefocity Cap Fish Entrapment Assessment, Phase II. Comparative Study " HARRINGTON, J New England Power Co 79/06/Q7 1p
- ---7905120383 "Velocity Cap Fish Entrapment Assessment, Phase II, Comparative Study " \* Yankee Atomic Electric Co 79/03/30 225pp
- 7906180525 Forwards revised pages to PSAR, indicating that ref to Westinghouse RESAR, Revision 3, includes Amends 1-6 Info will be included in Amend NI3 of PSAR DEVINCENTIS. J. New England Power Co 79/06/13 2pp
- 7906190288 Confirms telcon notification re suspension of efforts to obtain OLs & CPs until QSA decision on disposition of Chaplestown RI site. Forwards 790612 press release announcing curtailment of activity

  HARRINGTON, J New England Power Co 79/06/13. 1p
- D NRC Draft/Final Environmental Statements, suppls & correspondence
- 7706050154 Forwards DES re CP application (NUREG-0529) & FR notice of availability Also forwards Seabrook alternate site study (NUREG-0501) & Pilgrim FEB, final suppl (NUREG-0549), for use in review of DES Environmental Projects Branch 1, 79/05/31 3pp
- ---7904090158 Notice of availibility of DES.
  BALLARD,R.L Environmental Projects Branch 1 79/05/31 2pp

- --7906050162 DES re plant const \* Office of Muclear Reactor Regulation NUREG-0527 79/03/31 554pp
- --7906050176 Final suppl to FES re plant const \* Office of Nuclear Reactor Regulation NUREO-0549 79/03/31 133pp Available at NYIS 7 25
- 7906290216 Forwards DES for proposed facilities & notice of availability Requests comments
  BALLARD,R L Environmental Projects Branch 1 79/05/31 1p
- 7906120396 Offers no comment on DES COTHER: M L. Agriculture, Dept of 79/06/05 ip
- 7906210170 No comments on DES re plant const MCCARTHY. O R Transportation. Dept of 79/06/15 1p
- G Adjudicatory correspondence
- 7906260138 Forwards 790316 Board notification re recent issue on nonsafety-grade equipment to mitigate transients CUTCHIN.J M Branch 3 79/05/03 2pp
- --7906260166 Board notification recent nonsafety-grade equipment to mitigate transients Recommends addl reviews to ensure adequate thermal margins TEDESCO.R L Assistant Director for Reactor Bafety 79/03/16
- I Financial information
- 7906190010 Applies for order withholding financial info from public disclosure Forwards Revision 3 in response to 781016 ltr Supporting affidavit encl BTEVENS.J R New England Power Co 79/02/09 17pp
- 7906190003 Advises of public release of financial tables forecasts k schodules submitted w/790209 ltm to PDRs Thirty days have elapsed since NRC 790312 request for justification for ithholding data Light Water Reactors Branch 3 79/05/11 4pp
- DOCKET STN-50-569 NEP NUCLEAR, UNIT 2
- A Application/construction stage documents & correspondence
- 7906080289 Forwards "Distribution & Abundance of Lobster Larvae in Block Island Sound.1978 " HARRINGTON,J New England Power Co 79/05/30 ip
- -- 7906080260 "Distribution & Abundance of Lobster Larvae in Block Island Sound, 1978 HERSEY, R. WALSH, W.P. Raytheon Co. 79/05/30 93pp
- 7906210383 Forwards preliminary case rept & fourth draft of "Historic-Architectural & Archeological Investigation of former Charlestown Naval Air Station & Vicinity "
  BALLARD, R L Environmental Projects Branch 1 79/05/31 10pp
- --7906210392 "Historic.Architectural & Archeological Investigation of Former Charlestown Naval Air Station & Vicinity," fourth draft Rhode Island, State of 75/02/28 63pp
- 7906120279 Forwards "Population Statistics & Commercial Catch Rate of American Lobiter (Humarus Americanus) in Charlestown-Matunuck, RI Region of Block Island Sound " HARRINGTON, J New England Power Co 77/06/05 ip
- --7906120287 "Population Statistics & Commercial Catch Rate of American Lobster (Homarus Americanus) in Charlestown Matunuck,Ri Region of Block Island Bound " MARCELLO,R A New England Power Co DAVIS,W Yankee Atomic Electric Co YAEC-1175 79/04/30 50pp
- 7906120402 Forwards "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977 " HARRINGTON.J New England Power Co 79/06/06 1p
- --790612040B "Currents & Residual Drift in Block Island Sound During Period Feb-Dec 1977" SNOUNE,J H New England Power Co., JACOBSON,J P., Yankee Atomic Electric Co., YAEC-1149 79/03/30 175pp

# DOCKETED ITEMS

- 7906120379 Forwards "Velocity Cap Fish Entrapment Assessment, Phase II. Comparative Study " HARRINGTON, J New England Power Co 79/06/07 ip
- --7906120383 "Velocity Cap Fish Entrapment Assessment.Phase II. Comparative Study " \* Yankee Atomic Electric Co 79/03/30 225pp
- 7906180525 Forwards revised pages to PSAR, indicating that ref to Westinghouse RESAR.Revision 3.includes Amends 1-6 Info will be included in Amend NI3 of PSAR DEVINCENTIS.J New England Power Co 79/06/13 2pp
- 7706190288 Confirms telcon notification re suspension of efforts to obtain OLs 5 CPs until GSA decision on disposition of Charlestown.RI site Forwards 790612 press release announcing curtailment of activity
  HARRINGTON.J New England Power Co 79/06/13 ip
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 7906050154 Forwards DES to CP application (NUREC-0527) & FR notice of availability Also forwards Seabrook alternate site study (NUREC-0501) & Pilgrim FES, final suppl (NUREC-0547), for use in review of DES BALLARD, R L Environmental Projects Branch 1 79/05/31 3pp
- --7906050158 Notice of availability of DES BALLARD,R L Environmental Projects Branch 1 79/05/31 ≥pp
- --7906050162 DES re plant const \* Office of Nuclear Reactor Regulation NUREO-0527 79/05/31 554ab
- --7906050176 Final suppl to FES replant const \* Office of Nuclear Reactor Regulation NUREG-0549 79/05/31 133pp Available at NTIS 7 25
- 7908270216 Forwards DES for proposed facilities & notice of availability Requests comments BALLARD, L. Environmental Projects Branch 1. 79/05/31 1p
- 7706120376 Offers no comment on DES COTNER.M L. Agriculture, Dept of 79/06/05 ip
- 7706210170 No comments on DES re plant const MCCARTHY, G R Transportation, Dept of 79/06/15, 1p
- O Adjudicatory correspondence
- 7906260198 Forwards 790316 Board notification re recent issue on nonsafety-grade equipment to miligate transients CUTCHIN.J M Branch 3 79/05/03 2pp
- --7906260166 Board notification recent nonsafety-grade equipment to mitigate transients Recommends add1 reviews to ensure adequate thermal margins.

  TEDESCO,R L Assistant Director for Reactor Safety 79/03/16
- I Financial information
- 7706190010 Applies for order withholding financial info from public disclosure Forwards Revision 3 in response to 781016 ltr Supporting affidavit encl STEVENSJUR New England Power Co. 79/02/09 17pp
- 7906190003 Advises of public release of financial tables, forecasts % schedules submitted \( \omega / 790209 \) ltr to PDRs Thirty days have elapsed since NRC 790312 request for justification for withholding date
  PARR. O D Light Water Reactors Branch 3 79/05/11 4pp
- DOCKET STN-50-572 RESAR-414
- A Application/construction stage documents & correspondence
- 7905270007 Comments on REBAR-414 integrated protection sys. Applicants should provide reliability analysis of protective sys to assess whether sys will perform satisfactorily after installation
  LIPINSKI.W C Argonne National Laboratory 79/04/20. 2pp

- DOCKET STN-50-974 BAGNAC NUCLEAR POWER PROJECT
- A Application/construction stage documents & correspondence
- 7906250211 Concludes that IAEA investigations of proposed Philippine nuclear reactor application are sufficient NRC should be aware of previous comments re application suitability before decision is made on application merit
  DENTON, HR Office of Nuclear Reactor Regulation 79/01/22 3pp
- 7906290819 Responds to 790119 ltr re export requirements for reactor equipment intended for The Philippines Equipment not subj to NRC export licensing authority BHEAJR Office of International Programs 79/03/08 19
- --7906290832 Responds to 790202 memo re export of reactor equipment The Philippines Components are listed as balance of plant equipment BUNCH, D.F. Program Support Branch 79/02/27 in
- --7906290838 Forwards Westinghouse 790119 itr listing reactor equipm for export to The Philippines Equipment is not considered to be specifically designed or prepared for use in nuclear facility Requests comments QPLINGER. G G Assistant Director for Export/Import & International Safaguards 79/02/02 ip
- --7906290849 Forwards list in chronological shipping order of balanc plant components intended for shipment to The Philippines Inquires whether mati is subject to NRC export licensing action RODI.J P Westinghouse Electric Corp 79/01/19 3pp
- 7904250030 Requests that NRC consider neutron detector positioning device & safety injection sys accumulators for export RODLJ P. Westinghouse Electric Corp 79/05/02 2pp
- --7906250034 Ack receipt of 790427 ltr concerning export of reactor components to The Philippines Review of components has been initiated SHEALJR Office of International Programs 79/05/01 ip
- G Adjudicatory correspondence
- 7906220224 Opposes proposed shipment of Westinghouse reactor to The Philippines ATOR:D Affiliation Unknown 79/04/10 2pp
- 7906090383 Patition to intervene 2 request for hearing per 10CFR110 Ctr for Development Policy. JN Porlas & Philippine Movement for Environ Protection Supporting documentation encl ASHER, T.R., BODIN, M.B. Asher, T. R. PC 79/04/19 20pp
- 7906180138 Requests denial of joint intervenors 790419 petition to intervene No objection to consolidation of XBNM-1471 \$\forall XR-0120 apposes consolidation \( \omega / XCOM-0013 \) Certificate of Svc enci BECKER. J M Office of the Executive Legal Director 79/05/22
- 7906260072 Joint reply of petitioners to NRC & Westinghouse request for denial of intervenor status Petitioners have standing under all applicable tests Consolidation of licenses will aid proceedings Certificate of Syc encl ASHER, TR. BOGIN. M.B. Asher, TR. PC 79/06/04 13pp.

DOCF

B ---

- 7906110124 Forwards PSAR Amend 22 re QA, in response to NRC 790430 itr Affidavit enci MCWHORTER, R. J Ohio Edison Co 79/06/05 3pp
- --7906110128 Amend 22 to PSAR
  \* Ohio Edison Co 79/06/05 16pp,
- G Adjudicatory correspondence
- 7903210453 Supports applicant 790216 motion to dismiss E Stebbins & Coalition for Safe Electric Power as intervenors: ASLB 780420 & 790122 orders dismissed all contentions of these intervenors Certificate of Svc encl.
  BARTH.C A Branch 2 79/03/07 3pp
- 7906040376 Forwards memo re behavior of iodine during postulated str generator tube rupture accidents BARTH C A Branch 3 79/04/05 ip

- DOCKET STN-50-581 ERIE NUCLEAR PLANT, UNIT 2 B Utility Preliminary Safety Analysis Report, amends
- 7906110124 Forwards PSAR Amend 22 re QA, in response to NRC 790430 ltr Affidavit encl MCMHORTER,R J Ohio Edison Co 79/06/05 Jpg
- --7906110128 Amend 22 to PSAR
  \* Ohio Edison Co 79/06/05 16pp
- G Adjudicatory correspondence
- 7903210453 Supports applicant 790216 motion to dismiss E Stebbins & Coalition for Safe Electric Power as intervenors: ASLB 780420 & 790122 orders dismissed all contentions of these intervenors Certificate of Svc encl BARTH, C A Branch 2 79/03/07 3pp
- 7906040376 Forwards memo re behavior of iodine during postulated steam generator tube rupture accidents

  BARTH,C A Branch 3 79/04/05 ip
- DOCKET 50-588 REGODOLA NUCLEAR POWER STATION
- G Adjudicatory correspondence
- 7904040374 Forwards memo which contains info potentially relevant to issue of sabotage of spent nuclear fuel BARTH.C A Branch 3 79/04/05 2pp
- DOCKET 50-589 ASCO FESCA I NUCLEAR POWER STATION
- G Adjudicatory correspondence
- 7906040374 Forwards mamo which contains info potentially relevent to issue of sabotage of spent nuclear fuel BARTH, C A Branch 3 79/04/08 2pp
- DOCKET STN-50-592 PALO VERDE NUCLEAR STATION, UNIT 4
- A Application/construction stage documents & correspondence
- 7904230125 FR notice of ACRS 790405-07 meeting in Mashington DC HCYLE.J L ACRS - Advisory Committee on Reactor Safeguards 79/03/16 7pp
- 7905110359 Confirms 790429 meeting in Riverside, CA GOLDBERG, J. R. Anti-Trust Division 79/04/10 1p
- 7906070258 Comments on util environ data statement in response to NRC 790412 request No conflict w/own plans Requests info replans for use of reclaimed wastewater for cooling units ARNO,N Army, Dept of Corgs of Engineers 79/06/01 1p
- 7906130218 Confirms 790801 telcon extending comment review period for DEB until 790826

  JANKUS, B Environmental Protection Agency 79/06/08 ip
- C Utility Environmental Report (ER), amends & correspondence
- - 25 Suppl 2 to environ rept for CP stage re alternative santal water source evaluation and Public Rervice Co. 79/06/04 108pp
    - iron rept for CP stage & "Freliminary • Alternative Pipeline •lds" by Museum of Northern
- AZ Dept of Anthropology COTE, F M NUS Corp 79/04/08 ip
- -7905180486 Suppl 2 to environ rept for CP stage & preliminary Archaeological Assessment of Five Alternative Pipeline Routes & Four Alternative Wellfields" by Museum of Northern AZ Dept of Anthropology \* Arizona Public Bervice Co 79/05/31 99pp

- D NRC Draft/Final Environmental Statements, supply & correspondence
- 7906120270 Confirms 790608 telcon granting extension until 790626 to comment on DES MASTBAUM.0 Environmental Defense Fund 79/06/08 Ip
- 790620033B Submits joint applicant-consultant comments on DES VAN BRUNT,E E Arizona Public Service Co 79/06/11 30pp
- 7906260462 Forwards comments on DES suggests expansion of radioactiv waste disposal section to indicate alternatives Section on environ impact of postulated accidents should be deleted It is outdated CUSTARD. C Health, Education & Helfare, Dept of 79/06/21 3pp
- Q Adjudicatory correspondence
- 790.604042B Requests funding as intervenor in proceeding Cost & available time for preparation make NRC funding necessary BARD-L Affiliation Unknown 79/03/27 2pp
- 7906050062 Responds to 790326 ltr requesting notification of hearing date & time No hearing date set at present time SOHINKIS M Branch 3 79704/05 1p
- 7904010301 Forwards Rules of Practice(10CFR2) \$ 781208 supplemental FR notice of hearing W/o encl SCHINKI,S M Branch 3 79/04/10 2pp
- 7904070347 Confirms 790424 meeting in Los Angles, CA GQLDBERG, J R Anti-Trust Division 79/04/17 ip
- 7706020030 Joint applicants' response to Palo Verde Nuclear Interven amended petition for co-intervention Petitioners are not entitled to intervene as matter of right or matter of discretion Certificate of Svc enc! BISCHOFF, C A, GEHR. A C Snell & Wilmer 79/04/26 13pp
- 7704020243 Petition to intervene Notice of appearrance of D Mastbaum DB Roe on behalf of intervenor Affidavit of WA Butter & Certificate of Svc encl MASTBAUM, D , ROE, D B Environmental Defense Fund 79/05/03 2ip
- 7706200291 Requests opportunity to testify at hearing on CP JOHNSTON, A Bisbee Anti-Nuclear Group 79/05/07 1p
- 7904040057 Denies Palo Verde Nuclear Intervenors 790306 amended petition to co-intervene Petitioners failed to justify untimely filing of original petition
  LAZO:RM Atomic Safety and Licensing Board Panel 79/05/10 7p
- 790a080221 Forwards 790511 petition to intervene by Morongo Band of Mission Indians Draws attention to request for special consideration re svc requirements GUESENDERRY.S V California Indian Legal Services 79/05/14 3pp
- ---7906080225 Petition to intervene by Morongo Band of Mission Indian Proposed transmission lines will adversely affect Indians' use of reservation lands Notice of appearance & Certificate of Svc enci QUESEMBERRY. B V California Indian Legal Services 79/05/11 ilpp
- 7906270233 State of CA & CA Public Utils Commission motion for extension until 790701 for latter to file formal comments ro DES DES not received until 790507. Commission needs addl time for evaluation Certificate of Svc encl MACKENZIE.V V California, State of 79/05/16 7pp
- 7904230042 Responds to 790327 ltr requesting NRC funding for participation in proceeding Request has been denied Funding policy currently under consideration MENDRIE, J M Commission 79/05/17 ip
- 7906180803 Orders inadmissibility of L Bard 790301 first amended contention challenging Section 3 8 2 of 10CFR71.App B.ra spent fuel containers Second 2 third amended contentions retransportation of radioactive maths should remain open LAZO,R M Atomic Safety and Licensing Board Panel 79/05/18 4;
- 7904200178 Opposes facility const Unneeded extra generating capacity waste problem remains unsolved VOSS:M A. Affiliation Unknown 79/05/30 2pp
- 7906290815 Motion to file reply to NRC & joint applicants response to Environ Defense Fund petition to intervent Responses contain factual inaccuracies: citation of inapposite cases & inaccurate analyses Certificate of Svc encl 4ASTBAUM.D , ROE, D B Environmental Defense Fund 79/06/01 4p;

# H General correspondence

7906150323 Comments on DES suggests recapture of waste by using cogeneration Solar energy is more appropriete technology Expresses concern re high level wastes Urges end to nuclear power \* Affiliation Unknown 79/06/11 4pp

# [ Financial information

7905200326 Notification of 790523 meeting w/util in Bethesda.HD to discuss submittal of nonproprietary financial info to complete review LICITRALE A Light Water Reactors Branch 3 79/05/14 2pp

# DUCKET STN-50-593 PALO VERDE NUCLEAR STATION, UNIT 8

A Application/construction stage documents > correspondence

7904230125 FR notice of ACRS 790405-07 meeting in Washington, DC HOYLE, J t. ACRS - Advisory Committee on Reactor Safeguards 79/03/14 7pp

7905110359 Confirms 790425 meeting in Riverside.CA GOLDBERG.J R Anti-Trust Division 79/04/10

7904070298 Comments on util environ data statement.In response to NRC 790412 request No conflict w/own plans Requests info re plans for use of reclaimed wastewater for cooling units ARNO.N Army, Dept of, Corps of Engineers 79700/01 1p

7906130218 Confirms 790601 telcon extending comment review period for DES until 790626 JANKUS, B Environmental Protection Agency 79/06/08 1p

C Utility Environmental Report (ER), amends & correspondence

7906050302 Forwards Suppl 2 to environ rept for CP stage VAN BRUNT, E E Arizona Public Service Co 79/06/04 3pp

--7906050325 Suppl 2 to environ rept for CP stage re alternative supplemental water source evaluation

\* Arizona Public Service Co 79/06/04 108pp

7906180493 Forwards Suppl 2 to environ rept for CP stage & "Preliminary Archaeological Assessment of Five Alternative Pipeline Routes & Four Alternative Wellfields" by Museum of Northern AZ Dept of Anthropology COTE, F M NUS Corp 77/06/08 tp

--7906180486 Suppl 2 to environ rept for CP stage & preliminary Archaeological Assessment of Five Alternative Pipeline Routes & Four Alternative Wellfields" by Museum of Northern AZ Dept of Anthropology \* Arizona Public Service Co 79/05/31 99pp

7906260459 Forwards Affidavit of Bvc for Suppl 2 to environ rept VAN BRUNT,E E Arizona Public Service Co 79/06/18 23pp

# D NRC Draft/Final Environmental Statements, suppls & correspondence

7906120270 Confirms 790608 telcon granting extension until 790626 to Comment on DES

MASTBAUM, D Environmental Defense Fund 77/06/08 1p

7904200338 Submits joint applicant-consultant comments on DES VAN BRUNTLE E Arizona Public Service Co 79/06/11 30pp

7706260462 Forwards comments on DES suggests expansion of radioactive waste disposal section to indicate alternatives Section on environ impact of postulated accidents should be delated It is outdated Health, Education & Welfare, Dept of 79/06/21 3pp CUSTARD, C

#### C Adjudicatory correspondence

7904040428 Requests funding as intervenor in proceeding Cost & available time for preparation make NRC funding necessary BARD.L. Affiliation Unknown 79/03/27 2pp

7906050062 Responds to 790326 1tr requesting notification of hearing date \$ time No hearing date set at present time BCHINKI.8 M. Branch 3 79/04/05. 1p

7906010301 Forwards Rules of Practice(10CFR2) \$ 781208 supplemental FR notice of hearing W/o encl SOHINKI.5 M Branch 3 79/04/10 2pp

7906070347 Confirms 790424 meeting in tas Angles, CA OCLDBERG, J R Anti-Trust Division 79/04/17 ip

7906020030 Joint applicants' response to Palo Verde Nuclear Intervenors amended petition for co-intervention Petitioners are not entitled to intervene as matter of right or matter of discretion Certificate of Svc encl
BISCHOFF,C A , GEHR.A C Snell & Wilmer 79/04/26 i3pp

7706020243 Petition to interveno Notice of appearrance of D Mastbaum & DB Roe on behalf of intervenor Affidavit of WA Butter & Certificate of Svc encl MASTBAUM.D., ROE.D B Environmental Defense Fund 79/09/03 2ipp

7906200291 Requests opportunity to testify at hearing on CP JOHNSTON, A Bisbee Anti-Nuclear Group 79/05/07 ip

7906040057 Denies Pain Verde Nuclear Intervenors 790306 amended petition to co-intervene Petitioners failed to justify untimely filing of original petition LAZO,R M Atomic Safety and Licensing Board Panel 79/05/10 7pp

7906080221 Forwards 790511 petition to intervene by Morango Band of Mission Indians Draws attention to request for special consideration re-svc requirements GUESENBERRY, 6 V California Indian Legal Services 79/05/14 3pp

--7906080225 Petition to intervene by Morango Band of Mission Indians Proposed transmission lines will adversely affect Indians' use of reservation lands Notice of appearance & Certificate of Svc enci GVESENBERRY, S V Colifornia Indian Legal Services 79/05/11 Lipp

7906270253 State of CA & CA Public Utils Commission motion for extension until 790701 for latter to file formal comments re DES DES not received until 790507 Commission needs addl time for evaluation Certificate of Svc encl MACKENZIE.V V California, State of 79/05/16 7pp

7906230042 Responds to 790327 ltr requesting NRC funding for participation in proceeding Request has been denied Funding policy currently under consideration HENDRIE.J M Commission 79/05/17 ip

7906180803 Orders inadmissibility of L Bard 79030t first amended contention challenging Section 3 8 2 of 10CFR71.App B.re spent fuel containers Second >> third amended contentions re transportation of radioactive matls should remain open LAZO.R M Atomic Safety and Licensing Board Panel 79/05/18 4pp

7906200178 Opposes facility const Unneeded extra generating capacity waste problem remains unsolved. VOSS, N A Affiliation Unknown 79/05/30 2pp

7906290815 Motion to file reply to NRC & joint applicants response to Environ Defense Fund petition to intervene Responses contain factual inaccurates, citation of inapposite cases & inaccurate analyses Certificate of Svc encl MASTBAUM,D , ROE,D B Environmental Defense Fund 79/06/01 App

# H General correspondence

7906190323 Comments on DEB suggests recapture of waste by using cogeneration Solar energy is more appropriete technology Expresses concern re high level wastes Urges end to nuclear Affiliation Unknown 79/06/11 4pp

#### I Financial information

7906200326 Natification of 790523 meeting w/util in Bethesda. MD to discuss submittal of nonproprietary financial info to complete review LICITRALE A Light Water Reactors Branch 3 79/05/14 2pp

DOCKET STN-50-596 NEW HAVEN, UNIT I

A Application/construction stage documents & correspondence

7906010241 Summary of 790424 meeting w/util.800 & LASL in Bethesda.MD re reactor safeguards requirements
CAPRA.R A Light Water Reactors Branch 3 79/05/02 5pp

- 7906290851 Requests addl info for review of FSAR re max probable flood water level-protection of structures against lightning & QA section PARR.O D Leght Water Reactors Branch 3 79/05/10 18pp
- 7906150320 Summarizes helicopter costs for 790507-10 site visit RAY, M J New York State Electric & Gas Corp 79/05/22 5pp
- 7906290853 Forwards info requested as result of 790507-09 site visit & 790312 ltr Request concerns water availabilty for cooling on Mohawk River
  REGAN.W H Environmental Projects Branch 2 79/05/25 9pp
- 7906120247 Responds to NRC 790427 ltr requesting affshore seismic reflection profiles Forwards drawings of Profiles 2 1.4 1.6 1.8.10.10 1.12 2.14.16 1.18 1.20 1.22 1.301.302 & 303 Transmittal will be included in next PSAR amend M/o encl KINTIGH.A E New York State Electric & Gas Corp 79/06/05 1p
- 7906220342 Requests that environ review not be delayed due to special geological aspects of site Also requests to continue use of R Capra as contact point w/NRC KIMTIGH.A E New York State Electric & Gas Corp 79/06/15 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906260227 Forwards Amend 3 to facility environ rept Amend contains responses to NRC 790423 & 790529 ltre
  KINTIGH, A E New York State Electric & Qas Corp 79/06/21 3pp
- --7906260233 Amend 3 to facility environ rept a New York State Electric & Qas Corp 79/06/21 270pp
- D NRC Draft/Final Environmental Statements, supply & correspondence
- 7906010274 Forwards agreement between NRC & NY Depts of Public Svc & Environ Conservation calling for preparation of designated sections of DES & FES by NY State Public Svc Commission SELLS.D E Environmental Projects Branch 2 79/04/17 2pp
- --790601028t Agreement by NY State Depts of Public Svc & Environ Conservation to provide NRC w/ technical support of NY Dept of Public Svc staff in preparation of designated sections of DES & FES GDSSICK.L V Office of the Evecutive Director for Operations & New York: State of 79/04/06 Bpp
- F Security, medical, emergency & fare protection plans
- 7906120433 Forwards amended physical security plan Plan withheld (ref 10CFR2 790) KINTIGH, A E New York State Electric & Gas Corp 79/06/08 2pp
- G Adjudicatory correspondence
- 7906050413 Forwards requested into re environ impact of nuclear plant const INDYKE.C.M New York, State of 79/04/13 33pp
- 7906180810 Forwards proposed protocol for joint hearing before NRC & NY State Board on Electric Generation Siting & Environ re common issues in const applications of Long Island Lighting Co & NY State Electric & Oas Corp FLYNN, H , ENGEL, D A , LEWIS, S H New York, State of 79/04/27 2pp
- --7906190812 Proposed protocol for joint hearing before NRC & NY State Board on Electric Generation Siting & Environ re common issues in const applications of Long Island Lighting Co & NY State Elec & Gas Corp \* New York, State of 79/04/27 (3pp
- 7906200582 Public statement hearing will be on 790522 to hear residents living in vicinity of preferred site;special hearing conference will be on 790523 Second public statement hearing will be 790614 for alternate site residents
  HENNER, S. Atomic Safety and Licensing Board Panel MATIAS, T.R. New York, State of 79704730 2pp.
- 7906200617 Request by util for denial of 790313 patitions to intervene Filed by Town of Gardner & Ulsten County Environ Kgt Council, Petitions Lack standing & fail, to Justify discretionary intervention Certificate of Byc entl. GHUTTAR , ZEBRAK, I. L. Huber, Magill, Lawrence & Farrell. 79/05/04 App

- 7906260506 Forwards NY Dept of Public Svc response to Ecology Action c Oswego interlocutory appeal of denial of motion for dismissal of application GREY.R New York: State of 79/05/07 ip
- --7906260511 NY Dept of Public Svc response to Ecology Action of Osweg interlocatory appeal of denial of motion for dismissal of application Recommends denial of appeal OREV, R New York, State of 79/05/07 2pp
- 7906090069 Forwards 790112 application to intervene Lists contentions opposing proposed facility Seeks confirmation of interior status Hinutes of 790108 meeting adopting resolution to intervene encl GRAY.R C Herico. NY 79/05/09 3pp
- ---7906050076 Advises of 790108 resolution to intervene in proceeding L is to be considered as petition to intervene GRAYAR C Mexico, NY 79701/12 ip
- --7908050079 Ack receipt of recent communication, which has been forwar to Ofc of Executive Legal Director

  \* Docketing & Services Branch 79/01/17 1p
- 7906040427 Requests intervenor status as party-of-interest w/o contentions JONES R P Oswego, NY 79/05/10 2pp
- 7906270272 Bubmits specific contentions ra environ & radiolugical concerns Assessment of impact on farmland is inadequate re estimation of value & use of land & adverse impact of dustinoise. Hitter & traffic on area agriculture
  WEBER.N X Oswego County Farm Bureau 79/05/10 Bpp
- 79061900B3 Requests location of hearing be changed from convention ctr.Empire State Plara.Albany.NY to auditorium of Columbia-Greene Community College,Hudson,Change would facilitate accessibility LANE.C D New York, State of 79/05/11 lp
- 7906270111 Submits 40 contentions as suppl to petition to intervene re need for addl power, consideration of alternatives, site selection process, impact on existing health facilities, financial capacity & effect on high voltage transmissions WEBER.8 , DALY.H Ecology Action of Oswego 79/05/11 9pp
- T Hearing transcripts on non-antitrust matters
- 7706290060 Transcript of 770320 prehearing conference before NY State Public Svc Dept & NY State Board on Electric Generation Siting & Environ Pp 1-1377 MATIAS: T R , SCHWARTZ: S A New York, State of 77/03/20 138pp
- 7906290054 Transcript of 790322 prehearing conference before NY State
  Public Svc Dept & NY State Board on Electric Generation
  Siting & Environ Pp. 138-207
  MATIAS:T R . SCHWARTZ, S A New York: State of 79/03/22 &5pp
- 7906290069 Transcript of 790522 joint hearing before NRC & NY state govt in Oswego.NY re public statements Pp 204-417.

  HENNER'S , JORDAN'H H , PARIS, O, Atomic Bafety and Licensing Doard Panel 79/05/22 214pp
- 7906290077 Transcript of 790523 joint hearing before NRC & NY state govt in Oswego, NY, Pp. 418-626 WENNER, S. JORDAN, W. PARIS, O. Atomic Sefety and Licensing Board Panel 79/05/23 209pp
- DOCKET STN-50-597 NEW HAVEN, UNIT 2
- A Application/construction stage documents & correspondence
- 7906010241 Summary of 790424 meeting w/util, StW & LASL in Bethesda. HD re reactor safeguards requirements CAPRAIR A Light Water Reactors Branch 3 79/05/02 5pp
- 7906299851 Requests add1 info for review of FBAR re max probable flood water level, protection of structures against lightning & QA section PARR.O D Light Water Reactors Branch 3 79/05/18 18pp
- 7906:150320 Summarizes helicopter costs for 790807-10 site visit RAY.M J New York State Electric & Gas Corp 79/05/22 5pp
- 7906290833 Forwards info requested as result of 790807-09 sits visit & 790312 ltr Request concerns water availability for cooling on Mohawk River REGAN-W H Environmental Projects Branch 2 79/05/25, 9pp

- 7906120247 Responds to NRC 790427 ltr requesting offshore seismic reflection profiles Forwards drawings of Profiles 2 i.4 i. 6 i.6 i0.10 i.12 2.14.i6 i.18 i.20 i.22 i.301.302 & 303 Transmittal will be included in next PSAR amend W/o encl KINTIOH.A E New York State Electric & Oas Corp 79/06/03 ip
- 7906220342 Requests that environ review not be delayed due to special geological aspects of site Also requests to continue use of R Capra as contact point w/NRC
  KINTIGH A E New York State Electric & Qas Corp 79/06/15 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906260229 Forwards Amend 3 to facility environ rapt Amend contains responses to NRC 790423 & 790529 ltms.
  KINTIGH A E New York State Electric & Gas Corp 79/06/21 3pp
- --7906260233 Amend 3 to facility environ rept
  \* New York State Electric & Gas Corp 79/06/21 270pp
- D NRC Draft/Final Environmental Statements, supple & correspondence
- 7904010274 Forwards agreement between NRC & NY Depts of Public Syc & Environ Conservation calling for preparation of designated sections of DES & FEB by NY State Public Syc Commission SELLG, D E Environmental Projects Branch 2 79704/17 2pp
- --7906010281 Agreement by NY State Depts of Public Bvc & Environ Conservation to provide NRC w/ technical support of NY Dept of Public Bvc staff in preparation of designated sections of DES & FEB GUSSICK.L V Office of the Executive Director for Operations • New York, State of 79/04/06 Bpp
- F Security, medical, emergency & fire protection plans
- 7906120433 Forwards amended physical security plan Plan withheld (ref 10CFR2 770) KINTIONIA E New York State Electric & Qas Corp 79/06/08 2pp
- O Adjudicatory correspondence
- 7906050413 Forwards requested into re environ impact of nuclear plant const Const INDYKE, C. M. New York, State of 79/04/13 33pp
- 7704190810 Forwards proposed protocol for joint hearing before NRC & NY State Board on Electric Generation Siting & Environ recommon issues in const applications of Long Island Lighting Co & NY State Electric & Gas Corp FLYNN, M . ENGEL, D A . LEWIS, S H New York, State of 79/04/27
- --7906180812 Proposed protocol for joint hearing before NRC & NY State
  Board on Electric Generation Siting & Environ re common
  Issues in const applications of Long Island Lighting Co &
  NY State Elect & Gas Corp
  \* New York, State of 79/04/27 ISpp.
- 7906200582 Public statement hearing will be on 770522 to hear residents living in vicinity of preferred site:special hearing conference will be on 790523 Second public statement hearing will be 790614 for alternate site residents
  WENNER.S Atomic Safety and Licensing Board Panel. MATIAS.T R. New York. State of 79/04/30 2pp
- 7906200619 Request by util for denial of 790313 petitions to intervene Filed by Town of Oardner & Ulster County Environ Mgt Council Petitions lack standing & fail to justify discretionary intervention Certificate of Svc enci SHUTT, R , ZEBRAK, I L Huber, Magill, Lawrence & Farrell 79/05/04.
- 7906260506 Forwards NY Dept of Public Svc response to Ecology Action of Oswego interlocutory appeal of denial of motion for dismissal of application GREY, R New York, State of 79/05/07 ip
- --7906260511 NY Dept of Public Bvc response to Ecology Action of Oswego interlocutory appeal of denial of motion for dismissal of application Recommends denial of appeal GREY.R New York, State of 79/05/07 2pp
- 7904050069 Forwards 790112 application to intervene Lists contentions opposing proposed facility Seeks confirmation of interior status Minutes of 790108 meeting adopting resolution to intervene encl.

  ORAY, R. C. Mexico, NY 79/05/09. 3pp

- --7906050076 Advises of 790108 resolution to intervene in proceeding Ltr is to be considered as petition to intervene GRAY.R C Mexico, NY 79/01/12 ip
- --7906050079 Ack receipt of recent communication, which has been forwarded to Ofc of Erecutive Legal Director

  \* Docketing & Services Branch 79/01/17 ip
- 7906040427 Requests intervenor status as party-of-interest w/o contentions
  JDNESS P Oswego, NY 79/05/10 2pp
- 7906270272 Submits specific contentions re environ & radiological concerns Assessment of impact on farmland is inadequate re estimation of value & use of land & adverse impact of dust, noise, litter & traffic on area agriculture WEBER.N K Oswego County Farm Bureau 79/05/10 Bpp
- 7906190085 Requests location of hearing be changed from convention ctr.Fmpire State Plaza,Albany.NY to auditorium of Columbia-Greene Community College.Hudson Change would facilitate accessibility
  LANE.C D New York. State of 79/05/11 1p
- 7906270111 Submits 40 contentions as suppl to patition to intervene re need for addi power, consideration of alternatives, site selection process, impact on existing health facilities, financial capacity & affect on high voltage transmissions HEBER, 6, DALY, H Ecology Action of Oswego 79/05/11 Ppp
- T Hearing transcripts on non-antitrust matters
- 7906270060 Transcript of 790320 prehearing conference before NY State Public Svc Dept & NY State Board on Electric Generation Siting & Environ Pp 1-137a HATIAS,T R , SCHMARTZ,S A New York, State of 79/03/20 138pp.
- 7906290034 Transcript of 790322 prehearing conference before NY State Public Syc Dept 5 NY State Board on Electric Generation Siting & Environ Pp 138-207 MATIAS, T R . SCHMARTZ. S A New York, State of 79/03/22 65pp
- 7906270069 Transcript of 790522 joint hearing before NRC & NY state govt in Oswego NY re public statements.Pp 204-417 HENNER.S , JORDAN.Y H , PARIS.Q Atomic Safety and Licensing Board Panel. 79/05/22 214pp
- 7906290077 Transcript of 790523 joint hearing before NRC & NY state govt in Oswego, NY Pp 418-626 HENNER.S., JORDAN, W. PARIS, O Atomic Safety and Licensing Board Panel 79/05/23 209pc
- DUCKET 50-579 CARROLL FACILITY I
- A Application/construction stage documents & correspondence
- 7906070358 Notification of 790502 site visit for NRC & ANL to inspect prime & alternate sites
  BALLARD.R L Environmental Projects Branch 1 79/04/26 23pp
- 7906040070 Summary of 790424 orientation meeting w/plant dedicated review team in Bethesda. MD BIRKELR A Light Water Reactors Branch 2 79/04/27. opp
- 7906010238 Forwards data sources index map per NRC 790404 request Map will be included in response to Question 361.1 NAUOHTON,W F Commonwealth Edison Co 79/05/22 2pp
- 7906060294 Responds to request for comments on environ rept & site safety rept Neither rept received HARRISON.B.W Illinois, State of 79/05/23 ip
- 7906250303 Summary of 790509 meeting w/util in Bethesda. MD reimplamentation of Recommendation 3 of encl NRC study group rept.NOREG-0292. "Nuclear Power Plant Licensing Opportunities for Improvement"

  BIRKEL. R A Light Water Reactors Branch 2 79/05/24 14pp
- --7906230304 "Nuclear Power Plant Licensing: Opportunities for Improvement "
  DENTON, H R Office of Nuclear Reactor Regulation, 77/06/30
- 790.6080276 Forwards responses to 790.404 questions & revised portions of text referenced in responses Responses & revision of site suitability ER to be distributed by first week of June, 1979 W/a and I. NAUONTON, W.F. Commonwealth Edison Co. 79/05/25, 1p.

- 7906070270 Notifies that refs requested in 790404 ltr have been sent under separate cover to GL Montent at ANL NAUGHTON:W F Commonwealth Edison Co 79/05/30 ip
- 7906130225 Forwards "Thermal Happing of Blowdown Discharge" & "Cooling Water Intale & Blowdown Discharge Study," in response to NRC 790404 ltr NAVGHTON,W F Commonwealth Edison Co 79/06/06 lp
- --7906130227 "Thermal Mapping of Blowdown Discharge "
   Commonwealth Edison Co 79/05/31 1Opp
- --7906130230 "Cooling Water Intake & Blowdown Discharge Study "
  \* Commonwealth Edison Co 79/05/31 125pp
- 7906130380 Notifies that Miles Quadrangle topographical map, referred to in 790511 ltr.is no longer available Area in vicinity of proposed facility will be included in Green Island Quadrangle 7 5-minute map NAUGHTON, N F Commonwealth Edison Co 79/06/06 ip
- 7906220352 Submits add1 info re site suitability, in response to NRC 790404 request NAUGHTON, W F Commonwealth Edison Co 79/06/18 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906130322 Forwards addl info to site suitability/environ rept Suggested area may contain archaeological sites KENNEY.D lllinois, State of 79/06/08 2pp
- 7906220380 Discusses transmittal of info re site suitability-environ rept. Questions 361 1d & 361 f-1) in response to NRC 790404 request NAUGHTON, W F Commonwealth Edison Co 79/06/19 2pp
- 7906260150 Forwards Suppl 1 to site suitability environ rept. Constituting amend to application for CP & early site review REED. C Commonwealth Edison Co 79/06/22 2pp
- --7906260159 Suppl ( to site suitability environ rept.constituting amend to application for CP & early site review \* Commonwealth Edison Co 79/06/22 400pp
- G Adjudicatory correspondence
- 7706290691 Requests limited appearance at hearing re plant const KERR.J Affiliation Unknown 77/05/22 lp
- --7906290697 Requests limited appearance at first public hearing re proposed plant MARICICH.R J Affiliation Unknown 79/05/22 ip
- 7906210387 Answer by applicant to 790504 FR notice to hearing for early site review Seeks inclusion of seismology, environ & safety findings, heat dissipation sys & site alternatives Notices of appearance & Certificate of Syc encl STCPTOE, P Isham, Lincoln & Beale 79/05/24 7pp
- 7906250420 Notifies of limited appearance.per 10CFR2 & 790501 hearing notice Reserves right to intervene if interests are adversely affected MILLER, J. OSENBAUGH, E. M., PETERSON, C. E. loua, State of 79/05/30 2pp
- 7904280079 Petition to intervene re CP application Seeks to present evidence re safety issues geology hydrology weather conditions aesthetics & other considerations Affidavit & Certificate of Svc encl COX.J N Jo Davies County Ad Hoc Committee on Nuclear Energy Information 79/06/01 5pp
- 7906290512 Petition to Intervene Catholic Worker of Dubuque, Dubuque Fellowship of Reconciliation. Environ Coordinating Organization & Carroll County Environ Coalition Join in patition Affidavita & Certificate of Svc encl SCHMAB.J C Towa Public Interest Research Group 79/06/01 18pp
- DOCKET 50-600 CARROLL FACILITY II

- A. Application/construction stage documents & correspondence
- 7906070358 Notification of 790502 site visit for NRC & ANL to inspect prime & alternate sites
  BALLARD.R L Environmental Projects Branch 1 79/04/26 25pp.

- 7906040070 Summary of 790424 orientation meeting u/plant dedicated roview team in Bethosda, MD BIRKEL,R A Light Water Reactors Branch 2 79/04/27 App
- 790601023B Forwards data sources index map per NRC 790404 request Map will be included in response to Guestion 361 t NAUGHTON, W.F. Commonwealth Edison Co. 79/05/22 2pp
- 770A0A0274 Responds to request for comments on environ rept & site safety rept Neither rept received HARRISON.S W Illinois. State of 79/05/23 ip
- 7906250303 Summary of 790309 meeting w/util (n Bethesda.MD reimplementation of Recommendation 3 of encl NRC study group rept.NUREG-0292, "Nuclear Power Plant Licensing Opportunities for Improvement "BIRKEL.R A Light Water Reactors Branch 2 79/05/24 14pp
- --7906250304 "Nuclear Power Plant Licensing Opportunities for Improvement " DENTON, HR Office of Nuclear Reactor Regulation 77/06/30 14pp
- 7906080276 Forwards responses to 790404 questions & revised portions of test referenced in responses Responses & revision of site suitability ER to be distributed by first week of June, 1979 W/o encl NAUGHTON, W F Commonwealth Edison Co 79/05/25 1p
- 7906070270 Notifies that refs requested in 790404 ltr have been sent under separate cover to GL Montent at ANL NAUGHTON, W F Commonwealth Edison Ca 79/05/30 ip
- 7906130225 Forwards "Thermal Mapping of Blowdown Discharge" & "Cooling Water Intake & Blowdown Discharge Study." in response to NRC 790404 ltr
  NAUGHTON, W.F. Commonwealth Edison Co. 79/06/06 ip
- --7906130227 "Thermal Mapping of Blowdown Discharge " \* Commonwealth Edison Co 79/05/31 10pp
- --7906(30230 "Cooling Water Intake & Blowdown Discharge Study " \* Commonwealth Edison Co 79/08/31 125pp
- 7906130380 Notifies that Miles Quadrangle topographical map, referred to in 790511 ltr-is no longer available Area in vicinity of proposed facility will be included in Green Island Quadrangle 7 5-minute map NAUGHTON, W F Commonwealth Edison Co 79/06/06 ip
- 7906220352 Submits addl info re site suitability.in response to NRC 790404 request NAUGHTON.W F Commonwealth Edison Co 79/06/18 2pp
- C Utility Environmental Report (ER), amends & correspondence
- 7906130322 Forwards addi info to site suitability/environ rept Suggested area may contain archaeological sites KENNEY.D Illinois. State of 79/06/08 2pg
- 7906220380 Discusses transmittal of info re site suitability-environ rept. Questions 361 ld & 361 1-1, in response to NRC 790404 request NAUGHTON, H F Commonwealth Edison Co 79/06/19 2pp
- 7906260150 Forwards Suppl 1 to site suitability environ rept. constituting amend to application for CP & early site review

  REED.C. Communwealth Edison Co 79/06/22 2pp
- --7906260159 Suppl 1 to site suitability environ rept, constituting amend to application for CP & early site review \* Commonwealth Edison Co 79/06/22 400pp
- G Adjudicatory correspondence
- 7906290691 Requests limited appearance at hearing we plant const KERR.J Affiliation Unknown 79/05/22 ip
- --7906290699 Requests limited appearance at first public hearing re proposed plant MARICICH.R J Affiliation Unknown 79/05/22 1p.

- 7906210387 Answer by applicant to 790804 FR notice re hearing for early site review Speks inclusion of seismology, environ & safety findings, heat dissipation sys & site alternatives Notices of appearance & Certificate of Syc encl
  STEPTOE,P Isham, Lincoln & Beale 79/05/24 7pp
- 7906250420 Notifies of limited appearance.per 10CFR2 % 790501 hearing notice Reserves right to intervene if interests are adversely affected MILLERT J. OSCNBAUGH.C M., PETERSON.C E. Iowa, State of 79/05/30 2pp
- 7706280079 Petition to intervene re CP application Seeks to present avidence re safety issues, geology, hydrology, weather conditions, assthetics & other considerations Affidavit & Certificate of Svc encl COX, J W Jo Davies County Ad Hoc Committee on Nuclear Energy Information 79/06/01 5pp
- 7906290512 Petition to intervene Catholic Worker of Dubuque, Dubuque Fellowship of Reconciliation, Environ Coordinating Organization & Carroll County Environ Coalition join in petition Affidavits & Certificate of Svc encl BCHWAB, J C lowa Public Interest Research Group 79/06/01 18pp

# DOMESTIC LICENSING OF SPECIAL NUCLEAR MATERIAL

# DOCKET 70-0008 BATTELLE COLUMBUS LABORATORIES

- 7906230170 Forwards supplemental info to "Financial Plan for Decommissioning of Battelle Columbus Labs Contaminated Facilities:" transmitted under 781122 cover ltr TOY.H L Battelle Memorial Institute, Columbus Laboratories 79/04/25 App
- 7905040380 Responds to 790123 ltr reporting changes to physical protection plan for West Jefferson Nuclear Science Area Mod changes are acceptable Encl withheld (ref 10CFR2 790) HCCORKLE, G W Physical Security Licensing Branch 79/04/27 1p
- 7906170025 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/11 to
- 7906080124 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18

## DOCKET 70-0025 ROCKWELL INTERNATIONAL CORP

- 7906180436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/09/10 1p
- 7906080226 Forwards IE Circular 79-08, "Attempted Extertion Low Enriched U" ENGELMEN,R H Region 5, San Francisco, Office of the Director 79/05/18 1e
- 7906230069 Ack receipt of 790510 ltr requesting temporary exception to certain requirements of 10CFR73 60(a)9(1) to permit removal of high enrichment of U fuel plates Soctions 2 & 9 of Amend MPP-1 to License SNM-1 are ammended BURNETT,R F Division of Safeguards 79/05/18 3pp

# DOCKET 70-0027 BARCOCK & WILCOX CO

- 7906220123 Amends License 8NM-42, Condition 18, re nonradiological gaseous effluent; in accordance w/780822 submittal & 10CFR70 CROW, W T Fuel Process & Fab Branch 79/04/04 1p
- 7906230168 Forwards revised pages to measurement control plan in response to comments contained in 790308 itr Pages withheld (ref 10CFR2 790) DAMERON.M G Babcock & Wilcox Co 79/04/20 Zpp
- 7906070044 Notifies of overpayment of amend fee,based on evaluation of manpower expenditure required for review of application.

  MILLER,W Q License Fee Management Branch 79/04/27 1p
- 7906250435 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies." O'REILLY,J P Region 2. Atlanta: Office of the Director 79/05/10 1p.

- 7906190570 Ack receipt of 790507 ltr informing NRC of steps taken to correct violation noted in IE Insp Rept 70-0027/79-03
  KENNA, H B Region 2. Atlanta. Safeguards Branch 79/05/11 ip
- ---7906190575 Responds to NRC 790410 ltr re violation noted in IE Insp Rept 70-0027/79-03 Corrective actions withheld (ref 10CFR2 790) WEING J F Babcock & Wilcox Co 79/05/07 ip
- --7906190587 Forwards IE Insp Rept 70-0027/77-03 Notice of violation withheld (ref 10CFR2 790)
  KENNA:W B Region 2. Atlanta, Office of the Director 79/04/10 2pp
- --7705190594 IE Insp Rept 70-0027/79-03 on 790224-28 Noncompliance noted lack of matl access area physical barrier Details withheld (ref 10CFR2 790) MODRE,D E Region 2, Atlanta, Sateguards Branch OILLESPIE,F P Region 2, Atlanta, Office of the Director
- 7906260512 Forwards IE Insp Rept 70-0027/79-09 on 790507-11 No noncompliance noted KENNA.W B Region 2. Atlanta. Safeguards Branch 79/05/22 1p
- --7906260314 IE insp Rept 79-0027/79-09 on 790507-11 No noncompliance noted Major areas inspected records 2 repts Details withheld (ref 100FR2 790) HODOER, J W , QTLLESPIE, F Region 2, Atlanta, Bafeguards Branch 79/05/16 1p

# DOCKET 70-0033 TEXAS INSTRUMENTS, INC

- 7906130126 Forwards updates to HEIR Project emergency plan, resulting from NRC review in Oct 1774 HOPPER, CM Texas Instruments, Inc. 79/04/03 12pp
- 7906140639 Forwards IE Insp Rept 70-0033/79-03 on 790305-8 No noncompliance noted SMITH,O H Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/04/09 2pp
- --7906140643 IE Insp Rept 70-0033/79-03 on 790305-08 No nencompliance noted Mayor areas inspected licensee action on previous insp findings, organization, operations, safety & procedure control KINNEY,W W. CRUCKCR.H W. Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 79/04/09 12pp
- 7906250310 Provides summary of determination & application of limits of errors for invantory differences & shipments as result of IE Insp Rept 79-06
  HDPPER C M Toxas instruments. Inc 79/04/20 4pp
- 790622012B Amends License SNM-23-Condition 11-re emergency planning in accordance w/78102B submittal & 100FR70 CROWN T Fuel Process & Fab Branch 79/04/23 fp
- --7904220134 Discusses review of 781025 emergency plan & 790202 & 0403 suppls Emergency plan mosts requirements of 10CFR50, App E & provides basis for acceptable state of emergency preparedness KETZLACH, N Fuel Process & Fab Branch 79/04/23 Spp
- 7906250308 Submits list of replacement pages to "Plan for Protection of Nuclear Facilities & Nuclear Matls "Pages withheld (ref 10CFR2 790) SHERNAN,F.L. Texas Instruments, Inc. 79/05/01 App
- 7906200097 Requests that GA plan for shipping packages for radioactive matts be withdrawn from application HFIR project is not user of general license for shipment of DDT spec containers SHERMAN F L. Texas Instruments, Inc. 79/05/08 1p
- 7906260053 Forwards IE Info Notice 79~12, "Attempted Damage to New Fuel Assemblies " ORIER.B H Region 1, Philadelphia. Office of the Director 79/05/11. 1p
- 7904260556 Ack receipt of 790502 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0033/79-04. MARTIN, W G Region 1. Philadelphia, Safeguards Branch 79/05/14
- --7904260561 Responds to NRC 770426 Itr re violations noted in IE Insp Rept 70-0033/79-04 Corrective ations plan for protection of facilities & matls has been properly changed CONROY, D., SHERMAN, F. Texas Instruments, Inc. 79/05/02 ip

- --7906260565 Forwards IE Insp Rept 70-0033/79-04 on 790305-09 MARTIN W O Region 1, Philadelphia, Bafeguards Branch 79/04/26 2pp
- --7906260568 IE Insp Rept 70-0033/79-04 on 790303-09 Infration noted noncompliance re physical barriers JONES,E W , MCKEOKN,L M , DEVLIN,J W Region 1, Philadelphia, Safeguards Branch 79/04/23 ip
- 7906260627 Summary of 790517 meeting w/TX Instruments, Inc in Silver Spring, MD re format & content of license renewal application of Attleboro, MA facility KETZLACH, N Fuel Process & Fab Branch 79/05/17 13pp
- 7906080049 Forwards IE Carcular 79-08, "Attempted Extention Low Enriched U " GRIER.B H Region I. Philadelphia. Office of the Director 79/03/18 1p
- DOCKET 70-0036 COMBUSTION ENGINEERING, INC
- 7906190036 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies" KEPPLER, J. G. Region 3. Chicago. Office of the Director 79/05/11
- 7906250005 Responds to 790216 ltr Revised measurement control plan reviewed & accepted Strengthening of matl control & accounting program required Assessment of MUF bias requested within two months
  PARTLON, J G Material Control Licensing Branch 79/05/16 5pp
- --7906250011 Amand MPP-3 to License SNM-33, superseding all previous safeguard amends Addresses conditions refectlity organization 5 operation, measurement procedure & control, inventory, records & repts 5 internal control PARTLON-J G Material Control Licensing Branch 79/05/16 7po
- 7906200538 Requests add1 ref matl (n order to enhance incident response ctr Add1 matls needed include sits emergency plan & implementing procedures & four sets of site maps showing environ manitoring stations

  KEPPLER, J G Region 3. Chicago. Office of the Director 79/05/17
- 7906080132 Forwards IE Circular 79-08, "Attempted Extertion Low Enriched U" KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18
- 7706270037 Requests info re prospect of flooding to further EIA CROW.W T Fuel Process & Fab Branch 79/05/22 ip
- DOCKET 70-0041 NORTH CAROLINA STATE UNIV
- 7906210351 Ack receipt of 790419 itr informing NRC of steps taken to correct violations noted in IE insp Repts 50-111/79-01 50-297/79-01 50-297/79-01 50-297/79-01 KENNA.W B. Region 2. Atlanta, Gafeguards Branch 79/05/03 ip
- --7906210354 Responds to NRC 790327 itr re violations noted in IE Insp. Repts 50-111/79-01.50-297/79-01 & 70-0041/79-01 Corrective actions/Form 742 prepared properly & copy for period Oct 1978 Mar 1979 forwarded to Region II ELLEMAN,T.S North Carolina State Univ 79/04/19 ip

- 7905140212 Forwards IE Insp Repts 70-0135/79-05 & 70-0364/79-08 on 790305-09 No noncompliance noted MARTININ G Region I. Philadelphia, Safeguards Branch 79/04/12
- --7906140218 IE Insp Repts 70-0135/79-05 & 70-0364/79-09 on 770305-09
  No moncompliance noted Major areas inspected physical
  security, health & safety & environ programs
  BISSETT,P Region 1, Philadelphia, Office of the Director
  JOYNER,J H Region 1, Philadelphia, Safeguards Branch
  79/03/28 6pp,
- 7906130043 Ack receipt of 790502 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0135/79-07 GRIER, B H Region 1. Philadelphia, Office of the Director 79/05/10 1p
- --7906130039 Responds to violations noted in IE Insp Rept 70-0139/79-07 Carrective actions shop talk re radiation cotamination work permits conducted Copy encl AUSTIN.M A Babcock & Wilcox Co 79/05/02 3pp
- ---7406130048 Forwards IE Insp Rept 70-0135/79-07 on 790313-14 \$ notice of violation SHITM.9 H Region 1, Philadelphia, Office of the Director 79/04/13 Spp
- --7906130052 Notice of violation from insp on 790313-16

  \* Region 1, Philadelphia, Office of the Director 79/04/12 to
- --7706130055 IE Ensp Rept 70-0135/79-07 on 790313-16 Noncompliance noted air sample not representative of breathing zone & failure to account for SNM CLEMONS.B E . CROCKER.H W Region 1, Philadelphia, Office of the Director 79/04/12 lopp
- 7906260034 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " QRIER, II # Region 1, Philadelphia, Office of the Director 79/05/11 1p

1

- 7906080039 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " QRIER, B H region 1, Philadelphia, Office of the Director 79/05/18 1g
- 7906220197 Requests payment of administrative fee for amend to Licentes SNM-145 & SNM-414 to delay physical inventory WEISS.D License Fee Management Branch 74/05/22 ip
- DOCKET 70-0143 NUCLEAR FUEL SERVICES, INC
- 7906250207 Forwards Revision 7 to 770415 matl control plan Revision withheld (ref 10CFR2,790) HENSLEY, K D Nuclear Fuel Services, Inc (subs of Getty Cil Co) 77/04/20 ip
- 7906230003 Notifies that License BNM-124 is amended to require NRC approval prior to introduction of SNM into process sys CUNNINONAM. R E Division of Fuel Cycle & Material Bafety 79/04/23 2pp
- 7906230183 Requests 30-day extension to comment on draft documents forwarded by R Burnett 790306 ltr Delay due to labor problems HICHEL.C J Nuclear Fuel Services, Inc. (subs. of Getty O(1 Co.) 79/04/25 ip
- 7906040172 Ack receipt of 790420 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0143/79-04 BUTHERLAND.J.T Region 2. Atlanta, Fuel Facility & Materials Bafety Branch 79/04/26 ip
- --7905040175 Responds to NRC 790330 ltr re-violations noted in 16 insp Rept 70-00143/79-04 Corrective actions chemical bldg employees have signed off on revised procedure MANBER, M C. Nuclear Fuel Services, Inc. (subs. of Getty Dil Ca.) 79/04/20 2pp
- --7906040177 Forwards IE Insp Rept 70-0143/79-04 on 790123-24 & notice of violation SUTHERLAND, J Region 2: Atlanta, Fuel Facility & Materials Safety Branch 79/03/30 2pp.
- --7906040180 Notice of violation from insp on 790123-26
  \* Region 2, Atlanta, Office of the Director 79/03/30 ip

- --7906040184 IE Insp Rept 70-0142/79-04 on 790123-24 Noncompliance noted failure of operators to sign chemical bldg 80P log CORYELL, G P, POTTER, J P Region 2, Atlanta, Office of the Director 79/03/30 5pp
- 7906250473 Forwards Revision 15 change pages to physical security plan Revision withheld (ref 10CFR2 790) MICHEL.C J Nuclear Fuel Gervices, Inc. (subs. of Getty Oil Co.) 79/04/26 2pp
- 7906150042 Forwards IE Insp Rept 70-0143/79-16 on 790416-18 No noncompilanmee noted KENNAV B Region 2, Atlanta, Safeguards Branch 79/04/27 1p
- --7906150047 IE Insp Rept 70-0143/79-16 on 790416-18 No noncompliance noted Major areas inspected nuclear fuel safeguards program & plans for coping w/strikes Details withheld (ref 10CFR2 790) MODRE,D E , LEE,T , TOBIN,W J Region 2, Atlanta, Safeguards Branch 79/04/27 ip
- 7906220441 Amends License SNM-124 by accepting Revision 15 to physical protection plans forwarded in license 790426 ltr Flan withheld (ref 10CFR2 790) MCCORKLEV. & Physical Security Licensing Branch 79/04/30
- 7706250309 Requests amend to License SNM-124 Amend withheld (refiOCFR2 790) HENSLEY, K D. Nuclear Fuel Services, Inc. (subs. of Getty Gil Co.) 77/04/30 2pp
- 7906010227 Accepts site security training plan submitted on 790216
  Amends License 8NM-124
  MCCORKLE, 0 W Physical Security Licensing Branch 79/05/03
- 7906040064 Responds to 790425 itr requesting 30-day extension of 790518 due date for submittel of revised Section 7 to fundamental nuclear mati control plan Extension granted PARTLOW, J O Katerial Control Licensing Branch 79/05/04 1
- 7906260625 Summary of 790509 meeting w/NFS in Silver Spring,MD re 790423 order & procedures to be followed before operations can resume DELANEY,J C Fuel Process & Fab Branch 79/05/09 2pp
- 7906250430 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 1p
- 7906050447 Ack receipt of 790501 ltr re suspension of stack fluoride monitoring program Request requires payment of \$150 administrative amend fee WEISS.D License Fee Management Branch 79/05/11 ip
- 7906270033 Notifies that lime for licensee to request hearing reintroduction of add1 6NM into process sys is extended to 790523 CROM-W T Fuel Process & Fab Branch 79/05/17 ip
- 7906290745 Notifies that License BNM-124 is amended Amend constitutes written approval to introduce SNM into process sys &/or commence operations using mgt personnel GROW-W T Fuel Process & Fab Branch 79/09/18 ip
- 7905290788 Notifies that request to delay scheduled annual audit of contract labs is justifiable Audit shall be conducted on or before 790731 PARTLON, J C Material Control Licensing Branch 79/09/22 1p
- 7906290741 Adds license condition to amend MPP-1 of License 8NM-124 Amend makes it permissible to book shipper values for low enriched plant II 790514 physical inventory PARTLOWIJ, 0 Material Control Licensing Branch 79/05/23 ip
- 7906260870 Responds to 790420 submission of ravised fundamental nucle mati control plan Revisions are acceptable Revises License Condition 2 1 of Amend MPP-1 to License SNM-124 PARTLOW, J O Material Control Licensing Branch 79/05/24 2pp
- 7906290840 Responds to 781229 itr Mod scheduled to be completed 60 da after Gil, Chemical & Atomic Workers Intl Union returns to work.
  MICHEL, C. J. Nuclear Fuel Services. Inc. (subs. of Gatty Gil Co.)
  79/05/30. ip

#### DOCKET 70-0192 PURDUE UNIV

- 7904080123 Ack receipt of 790417 ltr informing NRC of steps taken to correct violations noted in IE insp repts
  HIND, J A Region 3. Chicago. Safeguards Branch 79/05/08 1p
- --7906080130 Responds to NRC 790326 itr re violations noted in IE insprepts Corrective actions withheld (ref 100FR2 790) CLIKEMAN,F M Pordue Univ 79704/19 2pg
- 7906190045 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/11
  10
- 7906080178 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U "
  KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/18
  1p
- DOCKET 70-0364 PARKS TOWNSHIP SITE, BABCOCK & WILCOX CO
- 7906230166 Forwards revised Chapter 3 of License SNM-0414 Section II
  "Facilities Descriptions" Includes changes to continuous
  air monitoring & plant ventilation sys
  AUSTINIM A Babcock & Wilcox Co 79/04/30 116pp
- 7904250157 Notification that inventory processing operation will not be completed until 79030 due to math certification problems
  AUSTEN H A Babcock & Wilcor Co 79/03/13 1p
- 7906080217 Requests delay, until 790515, for implementing requirements of License Condition 4 7 to Licenses SNM-145 & SNM-414 AUSTIN, M Babcock & Wilcox Co , Nuclear Material Div 79/03/19
- 7904050199 Forwards IE Insp Rept 70-0364/79-07 on 790227-0301 No noncompliance noted MARTIN:W O Region 1. Philadelphia, Safeguards Branch 79/03/26 2pp
- --7906050205 IE Insp Rept 70-0364/79-07 on 790227-0301 No noncompliance noted Major areas inspected nuclear matt control & accounting in area of independent measurements of facility holdup GODY.A . BISSETT.P Region 1. Philadelphia, Office of the Director JOYNER, J H Region I. Philadelphia, Bafeguards Branch 79/03/26 4pp

- 790623017& Discusses safety evaluation for B&W 790301 license amend application requesting possession limit for enriched U for Parks Township, PA Pu storage vault BURKHARDT, W Fuel Reprocess & Recycle Branch 79/05/00 ip
- 7906210268 Ack receipt of 790425 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0364/79-05 GRIER.8 H Region 1. Philadelphia. Office of the Director 79/05/10 ip
- --7908210283 Responds to NRC 790404 itr re violations noted in IE Insp.
  Rept 70-0204/79-05 Corrective actions new mfg.
  Instructions specifically addressing 010ve Box 162 prepared
  & currently being routed for review & approval
  AUSTIN-M A Babcock & Hiltor Co., Nuclear Material Div 79/04/25
- --790621028B Forwards IE (nsp Rept 70-0364/79-05 on 790226-0302 & notice of violation SMITH G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79/04/04 2pp
- --7705210289 Notice of violation from insp on 790225-0302 SMITH G H Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79704/04 2pp
- ~~7906210295 IE insp Rept 70~0364/79~05 on 790226~0302 Noncompliance noted failure to have posted nuclear safety spec mod in Fab 9 area signab by authorized individual ROTH.J Region 1. Philadelphia. Office of the Director CRCKER, H W Region 1. Philadelphia. Fuel Facility & Materials Safety Branch 79704/04 15pp
- 7906050442 Ack receipt of 790501 ltr me Pu physical inventories Requests payment of \$150 administrative amend fee WEISS: D License Fee Management Branch 79/05/11 1p
- 7906260034 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " GRIER, B H: Region 1, Philadelphia, Office of the Director 79/03/11 1p
- 7906080039 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" GRIER: B H Region 1. Philadelphia. Office of the Director 79/05/18 ip
- 7906220197 Requests payment of administrative fee for amend to Licenses SMH-145 & SNM-414 to delay physical inventory WEISS, D License Fee Management Branch 79/05/22 ip

# DOCKET 70-0371 UNITED NUCLEAR CORP

- 7906140119 Forwards IE Insp Rept 70-0371/79-05 on 790226-0302 No noncompliance noted MARTIN.W G Region 1. Philadelphia. Safeguards Branch 79/03/28 1p
- --7906140124 IE Insp Rept 70-0371/79-05 on 790226-0302 No noncompliance noted Major areas inspected nuclear matl control % accounting & shipper-receiver differences Details withheld (ref 10CFR2 790)

  COHEN. I . RATTA.A D Region I. Philadelphia. Office of the Director JOYNER, J H Region 1, Philadelphia. Safeguards Branch 79/03/26 1p
- 7906200275 Forwards GA program
  KIRK.W F United Nuclear Corp 79/05/03 (p
- --7906200277 GA program for facility 18/03 9pp

ion from requirements samples evised to

ch 79/05/04 1g

- 7906010080 Responds to 790409 ltr Denies request to use bolt type seal on burial drums
  PARTLOM, B 0 Haterial Control Licensing Branch 79/05/07 lp
- 7906260038 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  on 1. Philadelphia, Office of the Director

- 7906260328 Ack receipt of IE Insp Rept 70-0371//9-01 on 790108-12 QANLEY, D & United Nuclear Corp 79/09/15 2pp
- --7906260331 Responds to NRC 790214 ltr 18 violations noted in If Insp Rept 70-0371/79-01 Corrective actions unattended to incorrectly parked storage carts were reparked in authorized locations OANLEY.D E United Nuclear Colp 79/03/09 Spp
- --7906260336 Clarifies elements of 790411 telcon re-posting of controller area GANLEY, D.E. United Nuclear Corp. 79/04/12 2pp
- --7906260340 Forwards IE Insp Rept 70-0371/79-01 on 790108-12 b colice of violation BMIYH.O H Region 1. Philadelphia. Fuol Facility & Materials Safety Branch 79/02/14 2pp
- --7906260342 Notice of violation from insp on 790108-12 \* Region i, Philadelphia, Fuel Facility & Materials Safety Branch 79/02/12 4pp
- --7908260347 IE Insp Rept 70-0371/79-01 on 790108-12 Noncompliance notal failure to identify 8 enforce proper protective clothing for ontry into potentially contaminated area ROTH-J. KINNEY.H. CROCKER.IW Rogion 1, Philadelphia, Fuel Facility 8 Materials Safety Branch /9/02/12 19pp
- 7906080050 Forwards IE Circular 79-08, "Attempted Extortion iow foriched U " GRIER: B H Region 1, Philadelphia: Office of the Director 79/03/18 19
- 7906290207 Discusses proposed agenda for 790606 meeting to discuss shipment & receipt & mgt control & accountability of BNM PARTLOW, J G Material Control Licensing Branch 79706/01 1p

# DOCKET 70-0510 U 8 COAST GUARD ACADEMY

7906130305 Discusses IE insp of Licenses 06-02695-01 & SNM-463 on 790221 No noncompliance noted Major areas inspected procedures & representative records & monautements reradiation safety HCCLINTOCK, R O Region 1. Philadelphia. Office of the Director 797/03/08 ip

# DOCKET 70-0597 CENTRAL MICHIGAN UNIV

790531000B IC Insp Findings & Licenses Ack dtd 790313 of Licenses 21-01432-02 & SNM-554 insp findings 19 iita),(b) Part 17 20, License 5 & procedures not posted in designated location TAYLOR, R Region 3, Chicago, Office of the Director 79/0 //LR

# DOCKET 70-0487 UNION CARBIDE CORP

- 7906270733 Recommends approval of Union Carbide Corp 781117 request to amend license by altering administrative procedures & redefining SMM limits DELANEY.J C. CROW.H T Radioisotopes Licensing Branch (Pre 790501) 79/03/26 2pp
- --7906290738 Discusses 771228,780003 & 1013 requests to amend license by increasing mass limits in not colls Amend should not be granted DELANEY. J. C. CROW. W. T. Radioisotopes Licensing Branch (Pre. 790501) 79/03/26 2pp

# DUCKET 70-0498 WALTZ MILL BITE, WESTENOHOUSE ELECTRIC CORP

- 7908010220 Amends Item BE of License SNM-770, to revise passassion limits
  GROW, N T Fuel Process & Fab Branch 79/03/29 3pp
- 7906230234 Forwards 1979 decommissioning program for retired Wastinghouse training reactor facilities DIPIAZZA:R P Westinghouse Electric Corp 79/04/27 Spp

### DOCKET 70-0708 EO & Q, INC

7906270004 Ack receipt of 790209 itr requesting that License SM:-682 not be renewed, License terminated CRUM N 7 Fuel Process & Fab Branch 79/05/07 ip

#### DOCKET 70-0734 GENERAL ATOMIC CO

- 7906290646 Forwards IE Insp Rept 70-0734/79-03 on 790305-09 No noncompliance noted BOOK.H E Region 5, San Francisco, Fuel Facility & Materials Safety Branch 79/04/27 2pp
- --7906290636 IE Insp Rept 70-0734/79-03 on 790305-09 No noncompliance noted Major areas inspected mod b changes to facilities & sys, internal review b audit safety tomnittee activities b required calibr CODLEY, W J. RIEDLINGER, B A. BOOK, W N. Region 5, San Francisco, Fuel Facility b Materials Safety Branch 79/04/27 1900
- 7906220444 Forwards mod to "Security Gward Training & Qualification Plan" submitted in 79020 ltr Plan withheld (ref 10CFR2 790)
  MCCORKLE, G W Physical Security Licensing Branch 79/04/30
- 7906040384 Responds to 790420 ltr re revision to measurement procedures for ventilation sys holdup b changes involving use of alternate measurement sys Changes are acceptable b license is revised to reflect changes
  PARTLOW, J G Material Control Licensing Branch 79/05/02 2pp
- 7706190016 Forwards IE Info Notice 77-12, "Attempted Damage to New Fuel Assemblies "
  ENGELKEN, R H Region 5, San Francisco, Office of the Director 77/05/10 to
- 7706080220 Forwards IF Circular 79-08. "Attempted Extortion Low Enriched U" ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/18 16
- 7906290632 Discusses IE Insp Rept 70-0734/79-05 on 790507-10 No noncompliance noted Major areas inspected activities related to physical protection against industrial sabotage & against theft of SNM NGRBERHAUG.L. R. Region 5, San Francisco, Safeguards Branch 79/05/24 2pp
- 7905290796 Forwards revision of Sections 1-8 of Amend MPP-1 to License 8NM-696 PARTLOW, J O Material Control Licensing Branch 79/05/29 4pp
- DUCKET 70-0754 VALLECITOS NUCLEAR CENTER, GENERAL ELECTRIC CO
- 7906010289 Forwards "Annual Financial Rept 1978 " CUNNINGHAM G E General Electric Co , Nuclear Energy Products Div 79/03/30 1p
- --7906010292 "Annual Financial Rept 1978 " JONES, R H General Flectric Co 78/12/31 46pp
- 7905210D52 Forwards Board notification item re C Johnson apidemiological study of cancer incidence near Rocky Flats plant CHANDLER, L J Branch 1 79/04/27 34pp
- 7906190020 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/05/10 1p
- 7906080222 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U " ENGELKEN,R H Region 5, San Francisco, Office of the Director 79/03/18, 1p
- 7906290641 Forwards IE Insp Rept 70-0754/79-05 on 790425-27.notice of violation & notice of deviation Rept & notices withheld (ref 10CFR2 790)
  NORDERHAUD, L. R. Region 5, San Francisco, Safeguards Branch 79/05/21 200

# DOCKET 70-0820 UNITED NUCLEAR CORP

7906230161 Forwards CE Bower 780519 ltr containing organization chart for fuel recovery operation w/780601 implementation date Due to delay in expansion program, implementation date delayed Updated chart encl
BOWERS: C E United Nuclear Corp 79/02/15 2pp

- --7906230164 Forwards modified organization chart for fuel recovery operation w/780601 implementation date BOWERS,C E United Nuclear Corp. 79/05/19 3pp
- 7906230159 Forwards updated Section 200 of License SNM-777 requested by RL Stevenson during 770227 telicon
  SCHULTZ.D M. United Nuclear Corp. 79/03/02 18pp
- 7906250046 Summary of 790321 meeting w/United Nuclear Corp in Silver Spring. MD re proposed 790201 emergency plan STEVENSON, R L Fuel Process & Fab Branch 79/04/06 2pp
- 7906210052 Forwards IE Insp Rept /0-0820/79-02 on 790122-26 No noncompliance noted MARTIN.W G Region 1. Philadelphia, Safeguards Branch 79/04/19
- --7906210055 IE Insp Rept 70-0820/79-02 on 790122-26 No noncompliance noted Major areas inspected implementation of security plans follower review of response to 781016 immediate action itr & insp repts

  MADDEN,W , ROGERS,M , DEVLIN,J Region i, Philadelphia, Office of the Director 79/03/29 ip
- 7906220155 Ack receipt of 790326 ltr w/revised pages & drawings for safety demonstration discribing Lagoon recovery process
  Technical changes do not affect safety or environ controls
  Apparent conflict w/intent of License Condition 26
  CROW. W T Fuel Process & Fab Branch 79/04/19 ip
- 7906260020 Requests 10-day extension for reporting physical inventory GREQG, R J United Nuclear Corp 79/04/24 ip
- 7906010183 Responds to 771117 % 780928 ltrs Accepts revvisions refundamental nuclear matt control plan Revises License Condition 2 l
  PARTICUM, J G Material Control Licensing Branch 79/04/30 2pp
- 7906140979 Act receipt of 790406 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0820/79-04 SMITH.O H Region i, Philadolphia, Fuel Facility & Matorials Safety Branch 79/08/03 ip
- --7906140587 Responds to NRC 790319 Itr re violation noted in IE Insp. Rept 70-0820/79-04 Corrective actions alarms immediately reset to proper sotpoint when criticality conditions discovered BOWERS.C E. United Nuclear Corp. 79/04/06 2pp
- --7906140392 Forwards IE Insp Rept 79-0820/79-04 on 790212-15 & notice of violation SMITH,0 H Region 1. Philadelphia, Fuel Facility & Materials Safety Branch 77/03/19 2ap
- --7906140598 Notice of violation from insp on 790212-15 \* Region 1, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/19 ip
- --790614060B IE Insp Rept 70-0820/79-04 on 790212-19 Noncompliance noted licenses failed to have alarm setpoints for three criticality monitors set between 5 & 20 milliroentigens/h CROCKER H W. KINNEY.H W. Region i. Philadelphia, Fuel Facility & Materials Bafety Branch 79/03/15 12pp
- 7906180621 Ack receipt of 790406 ltr informing NRC of ateps taken to correct violations noted in IF Inch Rents 30-19203/79-01 & 70-0820 71 SMITH. 0

--75

- 7906250033 Forwards IE Info hotics 79-12. "Attempted Damage to New Fuel
  - Assemblies '
    GRIER, B H Region I, Philadelphia, Office of the Director 79/05/11 | 1p
- 7906080046 Forwards IE Circular 79-08, "Attempted Estortion Low Enriched U " GRIER B H 77/05/18 1p Region 1. Philadelphia. Office of the Director
- 7906270207 Discusses proposed agenda for 790606 meeting to discuss shipment & receipt & mgt control & accountability of SMM PARTLOW J G Material Control Licensing Branch 79/06/01 i 79/06/01 1p
- DOCKET 70-0824 BASCOCK & WILCOX CO
- 7906250457 Amends License BMM-778, Condition 18, per 790420 application & 10CFR70, to read 6 mCi I-131 not to exceed 300 uCi in any one calendar week
  CROW W T Fuel Process & Fab Branch 79/04/20 ip
- 7906250313 Responds to NRC 790402 ltr Formards replacement pages for revisions to safeguards contingency plans Pages Withheld (ref 10CFR2 790) OLSEN.A F Babcock & Wilco: Co 79/05/08 2pp
- 7906200074 Requests registration as user of Hodel CNSI-1-13C OLSENIA F Babcock & Wilcox Co 79/05/09 1p
- 7906250436 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " Region 2. Atlanta, Office of the Director
- 7906190542 Act receipt of 790416 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-0824/79-03
  KENNA-W B Region 2. Atlanta. Safeguards Branch 79/05/14 ip 79/03/14 10
- --7906190544 Responds to NRC 790300 ltr re violations noted in IE Insp Rept 70-0824/79-03 Corrective action withheld (ref locFR2 790) ENCELDER.T C Babcack & Wilcot Co 79/04/16 ip
- --7906190547 Forwards IE Insp Rept 70-824/79-03 Notice of violation withheld (ref 10CFR2 790)
  KENNA, H B Region 2. Atlanta, Office of the Director 79/03/ Region 2. Atlanta, Office of the Director 79/03/30
- --7906190554 IE Insp Rept 70-0824/79-03 on 790313-15 Noncompliance noted review of measurement program not conducted by designated person & failure to properly document training program Details withheld (ref 100FR2 790) BATES.J W. MILKINS.T D. Region 2. Atlanta. Office of the Director GILLESPIE.F P. Region 2. Atlanta, Safeguards Branch 79/03/30 ip
- 7906010185 Forwards Indomnity Agreement 0-2.in response to 790916 itr OLSEN, A f Babcock & Hilcox Co 79/03/25 12pp
- DOCKET 70-0895 ARKANSAS, UNIV OF
- 7906040110 Responds to 790405 ltr re use of resident inspectors at nuclear plant sites Forwards rapt describing ravised insp program which should be implemented in 1979

  PAVIS.J Q Office of inspection & Enforcement 79/04/20 ip
- --7906040118 Supports concept of placing resident inspectors at commercial nuclear power plants Offers svc as inspectors at Black Fox Station or AK Power & Light plant in Russelville. WOLF.H Arkansas, Univ of 79/04/05 2pp
- MICKET 70-0925 CIMMARON FACILITY, KERR-MCGEE CORP
- 7906190029 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Accemblies KEPPLER, J O Region 3, Chicago, Office of the Director 79/05/11
- 7906080142 Forwards IE Circular 79-08, "Attempted Extertion Law Region S. Chicago: Office of the Director 79/05/18

- DOCKET 70-0959 NUCLEAR FUEL SERVICES, INC , (SUBS. OF GETTY CIL CO
- 7906260040 Forwards IE Info Notice 79-12, "Attempted Damage to Nr Assemblies "
  ORIER B H Region 1, Philadelphia, Office of the Director
  79/05/11 | 1p 79/05/11
- DOCKET 70-0984 PACIFIC NORTHWEST LAD
- 7906(80432 Forwards IE Info Notice 79-12, "Attempted Damage to Nr.
  Assemblies "No written response necessary
  ENGELKEN.R H Region 5, San Francisco, Office of the Director
- 7906080214 Forwards IE Circular 79-08, "Attempted Extortion Lou Enriched U " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/18
- DOCKET 70-1007 GENERAL ELECTRIC CO
- 7906190020 Forwards IE Info Notice 79-12. "Attempted Damage to Naw Assemblies " ENGELKEN, R H Region 5, San Francisco, Office of the Director 79/05/10
- 7906080222 Forwards IE Circular 79-08. "Attempted Extortion tow Enriched U " Region 5, Ban Francisco, Office of the Director 79/05/18
- DOCKET 70-1100 COMBUSTION ENGINEERING, INC.
- 7906220027 Amends License BNM-1067 to include decommissioning \$ financial plans in accordance w/790112 submittal & 10CPR70 CROM.W.T. Fuel Process & Fab Branch 79/04/23 1p
- --7906220030 Discusses review of 790112 license amend application à 790305 suppl Plan for future decontamination & financial arrangements provide satisfactory assurance of health bushes. Fuel Process & Fab Branch 79/04/27 3pp KETZLACHI N
- 7906260008 Requests amend of License BNM-1067 to Allow increase in a surichment of enriched U from 3 5% U-235 to 4 1% U-235 forwards necessary critical safety analyses of each step in fuel fabrication process

  LICHTENBERGER, H Combustion Engineering, Inc. 79/04/23 9059
- 7906260048 Forwards IE Info Notice 79-12, "Attempted Damage to Hew F Asymbiles ' ORICE, B H Region I, Philadelphia, Office of the Director 79/05/II Ip
- 7906250001 Responds to 790215 ltr Revised measurement control plan reviewed & accepted Strengthening of mati control & accounting program required Assessment of MVF bias requested within two months
  PARTIFICATION OF MEASUREMENT CONTROL LICENSIAN Description (1998) Material Control Licensing Branch 79/05/16 5);
- --7906250002 Amend MPP-4 to License ENM-1067, superseding previous safeguard amends Addresses conditions ne facility organization & operation, measurement procedure & control inventory, records & repts of internal control PARTLON, J & Material Control Licensing Branch. 79/03/16
- 7906080041 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched U" GRIER:B H Region 1, Philadelphia, Office of the Director 79/05/18, 1p
- DOCKET 70-1113 GENERAL ELECTRIC CO
- 7906250358 Submits latest revisions to Chapter 4 & App C of fundaments nuclear matt control plan Revisions withheld (ref JOCR2 790).

  KAPLANIA L General Electric Co., Nuclear Energy Products Day 79/04/17. 1p
- 7906230;55 Bubmits revisions to Chapter 4 of fundamental nucleer mitl control plan for Wilmington.NC fuel febrication plant Revisions withheld (ref 10cFR2 790), KAPLANA L. General Electric Co , Nuclear Energy Products Div 79/05/02 ip

- 7906040075 Requests that encl math control plan accounting program be improved in order to ensure compliance w/10CFR70 57 Revised measurement control plan reviewed & accepted Plan withheld (ref10CFR2 790)
  PARTLOW. J Q Material Control Licensing Branch 79/05/04 5pp
- 7908250312 Forwards addl info to Mod 2 to application Amend S-8 re physical inventory of U oxide pollets & SNM containers Info & mod withheld (ref 10CFR2 790) KAPLAN,A L General Electric Co .Nuclear Energy Products Div 79/03/04 2pp
- 7905250432 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  Q'REILLY, J P Region 2, Atlanta, Office of the Director 79/05/10 10
- 790626063B Submits corrected version of page 3 of safety evaluation for GE 790430 emergency plan STEVENSON,R C. Fuel Reprocess & Recycle Branch 79/05/14 2pp

# DOCKET 70-1143 WESTINGHOUSE ELECTRIC CORP

- 7906260044 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  GRIER.B H Region i, Philadelphia, Office of the Director 79/05/11 Ip
- 7906080055 Forwards IE Circular 79-08, "Attempted Extertion Low Enriched U " GRIER.B H Region i, Philadelphia, Office of the Director 79/03/18 Ip

#### DOCKET 70-1151 WESTINGHOUSE ELECTRIC CORP

- 7704050237 Responds to 770307 request to expand U recovery sys facility from scrap.by means of solvent extraction Control plan must be reviewed & approved prior to startup PARTLOH.J O Material Control Licensing Branch 77/04/04 ip
- 7906250360 Submits latest revision of 790406 measurement control plan for approval Revision withheld (ref 10CFR2 790) VOGEL.C E General Electric Co , Nuclear Energy Products Div 79704/06 ip
- 7906230167 Forwards revised "Application for Hithholding Proprietary Info from Public Disclosure," to be inserted with request for amend to License SNM-[107 Also forwards revised page 1944 of 790403 itr Revisions withheld (ref 10CFR2 790) DIPLAZZA.R P Hestinghouse Electric Corp 79/04/24 1p
- 7906040115 Revises Amend 80-4 to License BNM-1107 to require that licensee will adhere to fundamental nuclear matl control plan Request for additine to implement program may not be granted w/o proper justification License condition encl.
  PARTLOH, E G Haterial Control Licensing Branch 79/04/30 App
- 7906040044 Responds to 790502 teler & 790424 ltr re LEID model & requested time extension to use new model New License Condition 5 9 to Amend 80-4 allows licensee to calculate LEID within 60 days using revised model PARTLOH, J G Material Control Licensing Branch 79/05/04 ip
- 7906210070 Approves revision to License Condition 2 1 & addition of new Condition 2 2 2 to Amend 80-4 to License SNM-1107 Rejects request for 60-day extension to implement Section 4 & PARTLON-JO Material Control Licensing Branch 77/05/17 2pp
- 7706270030 Requests supporting info in order to conduct review of 790403 application for amend to License SNK-1107, authorizing operations w/SNM in plant expansion BTEVENBUN, R. L Fuel Process & Fab. Branch 79/05/22 3pp

# DUCKET 70-1193 CIMARRON FACILITY, KERR-MCGEE CORP

- 7706230182 Discusses license amend application for decontamination & dismantlement of obsolete solvent extraction equipment at Cimmeron, DK HAUGHNEY, C. J. Fuel Reprocess & Recycle Branch. 79/04/17 7pp
- 7906190029 Forwards IE Info Notice 79-12, "Attampted Damage to New Fuel Assemblies"
  KEPPLER, J. G. Region 3, Chicago, Office of the Director 79/05/11

7906080142 Forwards IE Circular 79-08, "Attempted Extortion - Low Enriched U " KEPPLER, J G Region 3, Chicago, Office of the Director 79/05/18

## DOCKET 70-1200 PRINCETON GAMMA-TECH

- 7906010123 Ack receipt of 770305 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1200/79-01 MCCLINTOCK R O Region 1, Philadelphia, Office of the Director 79/03/27
- --7906010129 Responds to NRC 790125 Itr re violations noted in IE Insp Rept 70-1200/79-01 Corrective actions new logbook in use, rooms have been posted & Pu/beryllium source use has been restricted LISTER, D.B. Princeton Gamma-Tech 79/03/05 2pp
- --7906010132 Discusses IE Insp Rept 79-1200/79-01 on 790109. Forwards notice of violation Noncompliance noted logbook unused rooms not posted mati used by unauthorized persons & stored in unathorized places

  MCCLINTOCK\_R U Region 1, Philadelphia, Office of the Director 79/01/25 2pp
- --7906010136 Notice of violation from insp on 790109 \* Region 1, Philadelphia, Office of the Director 79/01/25 2pp

#### DOCKET 70-1201 UF & CONVERSION FACILITY, BABCOCK & WILCOX CO

- 7906070318 Forwards IE Insp Rept 70-1201/79-10 on 790320-23 No noncompliance noted SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 2pp
- --7906070323 IE Insp Rept 70-1201/79-10 on 790320-23 No noncompliance noted Major areas inspected organisation, facility changes & mods.internal review & audits.safety committees & operation review KAHLE.J B. WOODRUFF, R. L. Region 2, Atlanta, Office of the Director POTTER.J P. Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/06 6pp
- 7906220113 Amends License 8NM-1168, Condition 12.re emergency plans in accordance w/790330 submittal & 10CFR70
  CROW, W T Fuel Process & Fab Branch 79/04/23 1p
- 7906250143 Reviews 780726 emergency plan & revisions for B&W KETZLAGH,N Fuel Process & Fab Branch 79/04/23 Spp
- 7906180164 Requests registration as user of BU-7 shipping container under License SNM-1168 All documentation required for container use has been obtained ZEFF.D.W Babcock & Wilcox Co 79/04/25. ip
- 7906260088 Forwards IE Insp Rept 70-1201/79-08 on 790319-23 No noncompliance noted SUTHERLAND, J T Region 2, Atlanta, Fuel Facility & Materials Safety Branch 79/04/26 2pp
- --7906260074 IE Insp Rept 70-1201/79-08 on 790319-23 No noncompliance noted Major areas inspected coordination w/offsite support agencies, emergency equipment, medical arrangements & fire prevention PERROTTI.D J. TROJANDHSKI.R. Region 2. Atlanta, Office of the Director HUFMAN.J W Region 2. Atlanta, Fuel Facility & Haterials Safety Branch 79/04/21 7pp.
- 7706260185 Forwards revised sections of Amend Request 78-4.
  Contamination action levels revised for further compliance w/approved license limits & proposed Reg Guide 8 24
  ZEFF,D W Babcock & Wilcox Co 77/04/30. 40pp
- 7906250429 Forwards IE Info Notice 79-12, "Attempted Damaga to New Fuel Assemblies " D'REILLY, J P Region 2, Atlanta, Office of the Director, 79/05/10 1p
- 7906200307 Forwards revised conditions re mail control & accounting program to be added to License SNM-1168 Revised conditions to Sections 3 0 & 4 0 of Amend MPP-2 should be implemented within 30 days PARTLOW, J O Material Control Licensing Branch 79/05/15 Spp

- 7906290818 Confirms 790509 telcan requests for addl info re revised 790430 application KETZLACH.N Fuel Process & Fab Branch 79/05/22 3pp
- 7906260572 Responds to 780906 & 790427 ltrs re changes to fundamental nuclear matl control plan Forwards request for addl info PARTLOW.J G Material Control Licensing Branch 79705/24 Jpp
- DUCKET 70-1220 GENERAL ELECTRIC CO
- 7906190033 Forwards 1E Info Notice 79-12, "Attempted Damage to New Fuel Assemblies Region 3. Chicago. Office of the Director 79/05/11 KEPPLER, J G
- 79060B0137 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U" KEPPLER, J G Region 3. Chicago, Office of the Director 79/0 Region 3. Chicago, Office of the Director 79/05/18
- DOCKET 70-1257 MIXED DXIDE FABRICATION PLANT, EXXON NUCLEAR CD , INC
- 7906010313 Forwards XN-NF-503 "Security Training & Qualification Plan for Exon Nuclear Mised Disce & Speciality Fuels Plant " Plan withheld (ref 100FR2 790) Exxon Nuclear Co , Inc (subs or Exxon Corp ) 79/02/20 NII SON R
- 7905180439 Forwards lE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies " No written response necessary ENGELKENIR H Region 5, San Francisco. Office of the Director 79/05/10 1 p
- 7906080218 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U " ENGELKEN, R H Region 5. San Francisco. Office of the Director 79/05/18
- 7906260576 Requests replacement of cover sheet for insp rept Changes rept number from 70-1257/79-01 to 70-1257/77-04 Also requests corresponding mod to 790316 ltr which forwarded Region 4. Dallas, Office of the Director 79/05/18 2pp
- DOCKET 70-1308 MORRIS OPERATIONS, GENERAL ELECTRIC CO
- 7906250226 Submits revision per 790227 application for renewal of License SN4-1255 General Electric Co 79/04/18 11pp
- 7906260213 Forwards IE Insp Rept 70-1308/79-03 on 790327 % 0402-05 No noncompliance noted DAVIS.A B Region 3, Chicago: Fuel Facility & Materials Safety Branch 79/04/23 2pp
- --7906260228 IE Insp Rept 70-1308/79-03 on 790327 t 0402-03 No noncompliance nubed Major areas inspected safety committees training surveillance testing foot storage t handling, airborne effluents t solid wastes PECK.C C , PISHCR.W L Region 3, Chicago, Fuel Facility PECK.C C , FISHCR.W L. Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/04/20 6pp
- 7906230158 Forwards table showing current inventory of fuel stored
- 7906040064 Responds to safeguards contingency plan.App A. submitted by 780918 ltr Format should be revised to reflect encl changes MCCORKLE, G W Physical Security Licensing Branch 79/05/04 fp
- 7906030126 Act receipt of 790424 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1308/79-02
  DAVIS.A B Region 3, Chicago, Fuel Facility & Materials Safety Branch 79/05/08 ip
- --7906050130 Responds to NRC itr re violations noted in IE insp Rept 70-1308/79-02 Corrective actions drums being moved to storage location in main bldg 3 stored away from combustible ZAHNAL L. General Electric Co 79/04/24 2pp
- 7906230038 Requests assistance in reviewing application for renewal of ROUSE,L C Fuel Process & Fab Branch 79/05/QB 2pp

- 7906250256 Forwards corrected attachment to 790424 ltr discussing fuel storage at existing Morris operation space DAMSDN.D M General Electric Co ,Nuclear Energy Products Div 79/03/08 2pp
- 7906190033 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies KEPPLER, J G Region 3. Chicago, Office of the Director 79/05/11 10
- 7906200575 Act receipt of 790501 ltr informing NRC of steps taken to correct violations noted in IE Imap Rept 70-1308/79-01 HINDS, J A Region 3. Chicago. Safeguards Branch 79/03/16 19
- -- 7904200584 Responds to MRC itr ie violations noted in IF Insp Rept 70-1308/79-01 Corrective actions withheld (ref 100FR2 790)

  ZAHNL C General Electric Go Nuclear Energy Products Div
  79/05/01 1p
- 7905200533 Requests addit reference matt in order to enhance incident response ctr Addl matts meeded include site emergency plan & implementing procedures & four sets of site maps showing environ monitoring stations Region 3, Chicago, Office of the Director 79/05/17 KEPPLER, J G
- 7906080137 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched V " KEPPLER, J G Region 3, Chicago, Office of the Director 79/0 Region 3, Chicago, Office of the Director 79/03/18
- 7906210395 Hotion to intervene as party & as interested state Requests hearing on license renewal & NRC preparation of EIS Notices of appearance, affidavits of support & Certificate of Svc encl SCOTT.W J . WOLFF.G W Illingis, State of 79/05/21 1500
- 7906210300 Petition to intervene Contentions allege applicant has not filed EIS no evacuation plans for area exist & major disaster is possible due to concentration of spent fuel in area Certificate of Svc encl ROREM, B L., STOREY, K., QUIGLEY, F. Affiliation Unknown 79/05/23
- 7906290622 Notification of appointment of AC Goodhope as ASCR chairran & LW Little & FJ Remick as ASCR members LAZO,R M Atomic Safety and Licensing Board Panel 79/04/05 2pp
- DUCKET 70-1309 MORRIS OPERATIONS, SOURCES & STANDARDS, GENERAL
- 7906190033 Forwards IE Info Notice /9-12, "Attempted Damage to New Fuel Assemblies " KEPPLER, J G Region 3. Chicago, Office of the Director 74/05/11 1 p
- 7706200533 Requests add1 reference mat1 in order to enhance incident response ctr Add1 mat1s needed include site emergency plan & implementing procedures & four sets of site maps showing environ monitoring stations KEPPLEN, J O Region 3. Chicago, Office of the Director 79/05/17
- 7906080137 Forwards IE Circular 79-08, "Attempted Extortion Low Enriched V " KEPPLER, J G Region 3, Chicago, Office of the Director 79/0 Region 3, Chicago, Office of the Director 79/05/19
- DOCKET 70-1319 U S NUCLEAR, INC
- 7906250428 Forwards IC Info Notice 79-12. "Attempted Damage to New Fuel Assemblies " O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10
- DOCKET 70-1351 ARMY, DEPT OF
- 7906140497 Ack receipt of 790411 lt; informing NRC of steps taken to correct violations noted in IE insp Rapts 30-9248/79-01, 40-8194/79-01 \$ 70-1351/79-01 MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director 79/05/08
- --7904140503 Responds to NRC 790330 ltr re violations noted in 1E Insp. Repts 30-5248/79-01, 40-8194/79-01 & 70-1351/79-01 Corrective actions installation of fence enclosing radiation area & storage of licensed math in locked cabinet BDWMAN.E L. Army.Dept of:Electronics Research & Development Command 79/04/11 ig

# **DOCKETED ITEMS**

- -~7906140506 Forwards notice of violation from IE Insp Repts 30-5248/79-01.40-8194/79-01 & 70-1351/79-01 on 790306 MCCLINTOCK, R D Region i, Philadelphia, Office of the Director
- ---7906:405:6 Notice of violation from insp on 790306 Honcompliance noted radiation levels outside calibr facility exceeded limits & licensed matl stored in unlocked cabinet MCCLINTOCK, R.O. Region 1. Philadelphia. Office of the Director

DOCKET 70-1359 IRT CORP

- 7906270024 Notifies of issuance of Amend 10 to License SNM-1405 axtending expiration data to 800430 per 790206 application CROW, W T Fuel Process & Fab Branch 79/05/03 2pp
- --7906270026 Discusses 790206 license amend application requesting extension of expiration date to 800430 Recommends approval CROM.W T Fuel Process & Fab Branch 79/05/03 2pp

DOCKET 70-1426 TRANSNUCLEAR, INC.

- 7905240706 Notifies that safeguards contingency plan for transportation & transfer points requires supplemental info & revision Encl annotated copy w/marginal notes withheld (ref 10CFR2 790) MCCORK/O W Physical Socurity Licensing Branch 79/04/13 3pp
- DOCKET 70-1432 RECYCLE FUELS PLANT, WESTINGHOUSE ELECTRIC CORP
- 7904250427 Forwards IE Info Notice 79-12. "Attempted Damage to New Fuel Assemblies "
  O'REILLY, J P Region 2. Atlanta, Office of the Director 79/05/10 to

DOCKET 70-1489 GOODYEAR AEROSPACE CORP

- 7906190027 Forwards IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies"
  KEPPLER, J Q Region 3, Chicago, Office of the Director 79/05/11
- 7904080140 Forwards IE Circular 79-08. "Attempted Extortion Low Enriched U "
  KEPPLER, J O Region 3. Chicago, Office of the Director 79/05/18

DOCKET 70-1510 NUCLEAR ASSURANCE CORP

- /906210296 Forwards check for addl \$240 to cover fees required for renewal of License SNM-1473 per 790502 request VIEBROCK, J M Nuclear Assurance Corp 79/05/10 1p
- ~-7706210302 Responds to 770423 ltr forwarding \$400 fee for renewal of License SNM-1473 Since application is subj to renewal fee of \$640, requests payment of add1 \$240 JACKSON.6 License Fee Management Branch 79/05/02 ip
- ~-7906210306 Applies for renewal of License BNM-1473 to permit delivery of SNM Suproduct matl & source matl to carrier for transport in Cask NAC-1 Forwards license renewal fee ROLLING. J D Nuclear Assurance Corp 79/04/23 3pp

DOCKET 70-1421 CONOVER & ASSOCIATES, INC

7906190433 Forwards Endorsements 34 % 35 to NELIA Policy NF-226 % Endorsements 29 % 30 to MAELU Policy MF-87 BARNETI, J E Conover & Associates, Inc. Insurance 79/06/14 Spp

DOCKET 70-1710 ST, MARY'S HOSP WA. CONNECTICUT

- 7906290145 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations noted in IE lnsp Rept 70-1710/79-01 on 790215 MCCLINTOCK,R O Region I, Philadelphia, Fuel Facility & Materials Safety Branch 79/03/02 ip
- --7906290162 Responds to NRC 790319 ltr re violations noted in IE Insp Rept 70-1710/79-01 on 790215 Corrective actions procedure established to ensure that mati not in storage will be under constant surveillance t leak tests performed MEAGHER, L V St Mary's Hosp WA. Connecticut 79/04/05 Spp

~~7906290171 Biscusses IF Insp Rept 70-1710/79-01 on 790215 MCCLINTOCK,R O Region 1, Philadelphia, Fuel Facility % Materials Safety Branch 79/03/19 2pp

DOCKET 70-1717 NORWALK HOSP

- 7906050184 Ack receipt of 790402 Itr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-1717/78-01 MCCLINTOCK.R O Region 1. Philadelphia. Fuel Facility & Material Safety Branch 79/05/02 ip
- --7706050188 Responds to NRC 770208 ltr re violations noted in IE [nsp Rept 70-17t7/78-01 Corrective actions audit of program has been performed & pacemaker protocol revised Protocol.encl BRADY.N A Norwalk Hosp 79/04/02 ip
- --7906050189 "Research Protocol for Clinical Investigation of Nuclear Pacemakers" \* Norwalk Hosp 79/03/05 18pp

DOCKET 70-1729 FUEL REC & STOR STA , ALLIED GENERAL NUCLEAR SERVICES

790618069/ Advises that NRC cannot require applicant or licensee to include parties to NRC proceedings in meetings or other contacts which are extraneous to ploceeding ENGELHARDT, T F Deputy Executive Legal Director 79/04/19 ip

DOCKET 70-1738 PACIFIC GAS & ELECTRIC CO

7906180137 Discusses [E Insp Rept 70-1738/79-01 on 790305-06 Details uithheld (ref 10CFR2 790)
NORDERHAUG, L R Region 5. San Francisco. Safeguards Branch 79/04/26 Zop

DOCKET 70-2000 MT SINAI HOSP HA

- 7904260009 Ack receipt of 790319 Itr informing NRC of steps taken to correct violation nated in IE Insp Rept 70-2000/79-01 on 790214 MCCLINTOCK, R D Region 1. Philadelphia. Office of the Birector 79/04/04 in
- --7906260010 Responds to NRC 790309 ltr re violation noted in IE Insp Rept 70-2000/79-01 on 790214 Corrective actions employees reinstructed in disposal of ladioactive wastes % hot lab waste basket labeled BRUNER.R., LIENINGER.V., LAZARUS.W. Mount Sinal CT/HA 79/03/19
- ---7904260011 Discusses IF Insp Rept 70-2000//9-01 on 790214 & forward notice of violation
  MCCLINTOCK,R O Region 1, Philadelphia, Office of the Director 79/03/19 200
- --7906260014 Notice of violation from insp on 790214 Noncompliance no failure to survey 5 record procedures for disposal of licensed waste matl 5 failure to clearly label licensed radioactive matl

  \*\* Region 1, Philadelphia. Office of the Director 79/03/19 to

- 7903210231 NRC interrogatories to Carolina Environ Study Group, per ASLB 790223 order KETCHEN.E G Branch 4 79/03/04 3pp
- --7903210234 Interrogatories to Carolina Action.per ASLB 790223 order KETCHEN.E O Branch 4 79/03/06 3pp
- ~-7903210237 Interrogatories to Davidson College Chapter of NC PIRG per ASLB 790223 order & ASLAB 790226 order Certificate of Svc enci KETCHEN,E G Branch 4 79/03/06 5pp
- 7904040141 Second set of interrogatories directed to intervenor Carolina Action Certificate of Svc encl HOEFLING.R K Branch 4 79/03/23 10pp
- --7904040143 Requests intervenor Carolina Action to produce documents identified in responses to NRC second set of interrogatories HOEFLING, R K Branch 4 79/03/23 1p
- 7906070170 Applicant's interrogatories to NADC.per ASLB 790223 order.

  \*\*b requests to provide documents Certificate of Svc enci
  \*\*MCQARRY.J M\*\* Duke Power Co\*\* 79/03/28 36pp
- 7906120016 Forwards verification of 790327 response to NRDC interrogatories to applicant W/o encl W/affidavit PORTER.W L. Duke Power Co 79/03/30 2pp
- 7906070333 Forwards answers to NRC interrogatories & motion to produce documents Certificate of Svc encl ROISMAN, A Z Natural Resources Defense Council 79/04/11 2pp
- --7906070341 Answers to NRC interrogatories Affidavits of AZ Roisman.TB Cochran & AR Tomplin enc! ROISMAN.A Z , COCHRAN.T B , TAMPLIN.A R Natural Resources Defense Council 79/04/11 12pp
- ---7906070343 Response to NRC motion to produce documents
  \* Natural Resources Defense Council 79/04/11 2pg
- 7906020212 Forwards applicant's motion to dismiss Safe Energy Alliance as party intervenor Includes page 2.omitted when motion was originally filed on 790402
  MCGARRY,M J Debevoise & Lieberman 79/04/12 ip
- ~-7906020219 Motion to dismiss Safe Energy Alliance as party intervenor includes page 2 omitted when motion was originally filed on 790402 Certificate of Svc encl MCOARRY, J M Debevoise & Lieberman 79/04/02 6pp
- 7906050399 Responds to 790308 request for production of documents Lists documents available for insp Draft agreement re info disclosure encl PDRTER.W E Duke Power Co 79/04/13 4pp
- 7906080121 Requests responses to 790316 interrogatories PORTOR:W L Duke Power Co 79/04/13 2pp
- 7906040037 Response to NRDC 790402 request for admissions Objects to Items 1.2 ½ 7 Admits Items 3.4.6 ½ 9 Denies Items 5.8 ½ 12 Neither admits nor denies Items 10 ½ 12 Affidavit ½ Certificate of Syc encil PORTER.W L. Duke Power Co 79/04/17 6pp
- 7906040078 Response to NRDC 790402 request for admissions by NRC 5 util Affidavit of BS Spitalny & Certificate of Svc encl SPITALNY.8 S Fuel Reprocess & Recycle Branch 79/04/17 10pp
- 7906150006 Requests to make limited appearance statement at licensing prehearing conference
  DYKES,V B Affiliation Unknown 79/04/21 2pp
- 7906020245 Forwards info requested on 790412 re NRDC Contention 3 Certificate of Syc enci PARKER, N D Duke Power Co 79/04/23 25pp
- 7906040065 Motion to compel applicant to respond to NRDC 790402 requests for admissions or file denial Certificate of Syc encl ROISMAN, A Z Natural Resources Defense Council, 79/04/25 6pp
- 7904070336 Motion for order to compel intervenor Davidson College Chapter of NC PIRO to respond to NRC second set of interrogatories, submitted 790323 Certificate of Svc ancl HDEFLING, RK Branck 4, 79/04/25 Spp

- --7906070336 Supports motion for order to compel intervenor Davidson Callege Chapter of NC PIRG to respond to NRC second set of interrogatories, submitted on 790323 Proposed form of order encl
  HOEFILING, R K. Branch 4 79/04/25 600
- --7906070369 Mation for order to compel intervenor Carolina Action to respond to NRC second set of interrogatories, submitted 790323 MOEFLING, R K Branch 4 79/04/25 2pp
- --7906070376 Supports motion for order to compel intervenor Carolina Action to respond to NRC second set of interrogatories submitted 790323 Proposed form of order encl HBEFLING:R K Branch 4 79/04/25 6pp
- 770602009B Motion by intervenor Carolina Environ Study Group to permit further perusal of info obtained through discovery Supporting documentation & Cartificate of Svc enci BLUM: S Blum & Shelley 77/04/27 Spp
- 7906020099 Requests extension of time through 790521, or ten days after applicant response to request for admissions, for filing of motions for summary disposition re Contentions 1-4 Certificate of Svc encl RDISMAN. A Z Natural Resources Defense Council 79/04/27 5pp
- 7906020109 Response to NRDC 790427 request for extension of time in which to file motion for summary disposition Does not oppose NRDC motion Howes for similar extension, Until 790521, on own behalf Certificate of Svc encl MCGARRY, J M Duke Power Co 79/05/01 5pp
- 7906220194 Motion for summary disposition re NRDC Contention 4 Urgss board to issue older for ALARA analysis to be completed % discovery to be allowed before completion of further proceedings Affidavit & Certificate of Svc oncl ROISMAN, A Z Natural Resources Defense Council 79/09/01 17pp
- 7906250082 Interrogetories submitted to NRC re weekly info rept for week ending 790413
  RDISMAN, A Z Natural Resources Defense Council 79/05/01 App
- --7906250087 Requests that board direct NRC to respond to 790501 interrogatories Certificate of Syc enc!
  RDIEMAN.A Z Natural Resources Defense Council 79/05/01 268
- 7906140441 Motion for extension of time until 790511 to file summary disposition to intervenor NRDC 790412 contentions-based on failure to respond to discovery Certificate of Svc encl
  KENTOREN. E G Branch 4 79/05/02 Spp
- 7906210126 Motion for protective order denying discovery sought by intervenor Carolina Environ Study Group Interrogatories are hypothetical & beyond scope of discovery Certificate of Bvc encl
  PORTER.W L Duke Power Co 79/05/03 4pp
- 7905250212 Requests status of amend to License SNM-1773 re receipt & storage of spent fuel LARK.R E South Carolina, State of 79/05/03 ip
- 7906250218 Forwards NUREG-0523, "Summary of Operating Experience w/Recirculating Steam Generators " W/o encl KETCHEN, E G Branch 4 79/05/03 2pp
- 7906130107 Grants extensions of time in which to file mations for summary disposition Util & NRDC have until 790521, NRC has until 790511.
  MILLER, M E Atomic Safety and Licensing Board Panel 77/05/04 19
- 7906210116 Forwards response to Interrogatory 120, submitted on 790416 by intervenor Carolina Environ Btudy Oroup HOEFLING, R K Branch 4, 79/05/07 1p
- --7906210120 Responds to intervenor Carolina Environ Btudy Group Interrogatory 120 Affidavit & Certificate of Svc encl SPITALNY, B S Fuel Reprocess & Recycle Branch HOEFLING, R K Branch 4 79/05/07 5pp
- 790A250057 Forwards supplemental response to Guestion 1 of NRC 790A23

  Itr Ataches pertinent output pages of probabilistic
  simulation production custing model used to determine change
  in production costs caused by operating at half capacity
  PARKER.M. O Duke Power Co 79/05/07, 17pp
- 7906280008 Answers to NRDC second set of interrogatories Supporting documentations affidavits & Certificate of Svc encl PORTER, W. L. Dute Power Co 79/05/07 34pp

7906260298 Opposes intervenor Carolina Environ Study Group 790427 motion for continuance Motion is insufficient as matter of law & does not rest on factors necessary for continuance Certificate of Svc enci KETCHEN, E O Branch 3 79/05/10 Spp

\*\*

- 790A010319 Forwards motions for summary disposition Intends to file supplemental affidavits attesting accuracy of affidavits which accompany motions Certificate of Svc encl HOEFLING.R K Branch 4 79705/11 4pp
- ~-7906010325 Motion for summary disposition of intervenor NRDC Contentions 1-5 Affidavits enci HQEFLING.R K , KETCHEN.E G Branch 4 79/05/11 100pp
- ~~7906010331 Statement of matl facts as to which there is no genuine (assue to be heard, submitted in support of NRC motion for summary disposition of NRDC Contentions 1-5 HDEFLING, R K Branch 4 79/05/11 20pp
- --7906010338 Motion for summary disposition of intervenors Carolina Environ Study Group & Carolina Action Contentions 1-3 Affidavit encl HOEFLING.R K . KETCHEN.E G Branch 4 79/05/11 97pp
- --7906010339 Statement of matl facts as to which there is no genuine issue to be heard, submitted in support of NRC motion for summary disposition of intervenors Carolina Environ Study Group & Carolina Action Contentions 1 & 3 HOEFLING, R K , KETCHEN, E Q Branch 4 79/05/11 10pp
- --7906010349 Statement of matl facts as to which there is no genuine issue to be heard, submitted in support of NRC motion summary disposition of intervenors Carolina Environ Study Grapy & Carolina Action Contention 2
  HOEFLING, R K , KETCHEN, E 0 Branch 4 79/05/11 7pp
- --7906010342 Motion for summery disposition of intervenor Carolina Action Contention 4 % contention of intervenor Davidson Chapter of NC PIRO Supporting affidavits encl HDEFLING:R K , KETCHEN:E O Branch 4 79/05/11 48pp
- 7906040159 Denies intervenor Carolina Environ Study Group 790427 motion for continuance MILLER.M E Atomic Safety and Licensing Board Panel 79/05/11 ip
- 770622003B Dismisses Carolina Action as intervening party & active participant due to failure to respond to applicant interrogatories
  MILLER.M E Atomic Bafety and Licensing Board Panel 77/05/23 1p
- 7906200597 Seeks dismissal of NRDC Contention 4 % granting of util 790521 motion for summary disposition Contention presents no issue of law or matl fact suitable for resolution Certificate of Svc encl MCGARRY. J M Duke Power Co 79/05/29 17pp

# DOCKET 70-2684 TRANSNUCLEAR, INC.

- 7906010037 Ack receipt of 790411 ltr informing NRC of steps taken to correct violations noted in IE insp of License 20-01412-03 on 790306 MCCLINTOCK.R O Region I. Philadelphia, Office of the Director 79/05/10 in
- --7905010063 Responds to NRC 790402 ltr re violations noted in IE insp of License 20-01412-03 on 790306 Corrective actions procedures for receipt of radioactive shipment altered & sign posted near access to radiation therapy room URAHMAVAR.8 M . GRUGAN.R A . OIFFORD.H C Baystate Medical Center MA/SP 79/04/11 10pp
- ---7906010065 Submits details of unified radiation safety program OIFFORD.H C Baystate Medical Center MA/SP 79/02/16 2pp
- --7906010075 Discusses IE insp of License 20-01412-03 on 790306 & Forwards notice of violation MCCLINTOCK.R D Region 1, Philadelphia, Office of the Director 79/04/02 2pp.
- ~~7904010077 Notice of violation from insp on 790306 Noncompliance noted failure to survey for contamination in mat1 before disposal.lack of surveillance for stored mat1 \$\psi\$ unposted radiation area 

  Region i. Philadelphia, Office of the Director 79/04/02 2pp

~~790&010077 Notice of violation from insp on 790306 Nancompliance noted failure to survey for comatamination in matl before disposal.lack of surveillance re stored matl & unposted radiation area

\* Region 1. Philadelphia. Office of the Director 79/04/02
2pp

#### DOCKET 70-2809 MARUBENI AMERICA CORP

7906140031 Forwards IE Insp Rept 70-2009/79-01 on 790409 Rept withheld (ref 10CFR2 790)
NORDERHAUG.L R Region 5: San Francisco: Safeguards Branch 79/04/23 2pp

#### DOCKET 70-2838 CINCINNATI GAS & ELECTRIC CO

7906250362 Forwards revised pages to license application for storage only of unirradiated reactor fuel & associated radioactive matl
FLYNN,J D Cincinnat: Gas & Electric Co 79/04/12 5pp

# DOCKET 70-2880 HERCY HOSP SP. MASSACHUSETTS

- 7906190221 Ack receipt of 790405 ltr informing NRC of steps taken to correct violations noted in IE Insp Rept 70-2880/79-01 on 790305
  MCCLINTOCK,R O Region i, Philadelphia, Fuel Facility & Materials Bafety Dranch 79/05/02 tp
- --7906190222 Responds to NRC lir re violations noted in IE Insp Rept 70-2880/79-01 on 790305 Corrective actions sealed calibr or ref sources shall be tested for leakage 2 nuclear medicine facility shall be surveyed weekly WILCIEK. J Mercy Hosp MA/SP 79/04/05 5pp
- ---7906190224 Discusses IE Insp Rept 70-2880/79-01 on 790305 Forwards notice of violation MCCLINTOCK,R O ' Region I. Philadelphia. Fuel Facility & Material's Safety Branch 79/03/23 2pp
- --7906190226 Notice of violation from insp on 770305 Noncompliance noted failure to make surveys necessary to determine that individuals handling I-131 were not overexposed & failure to leat test 160 uCi sealed Cs-137 ref source \* Region 1, Philadelphia, Office of the Director 79/03/23 2pp

## DOCKET 70-2094 LONG ISLAND LIGHTING CO

7906110421 Reponds to NRC request for analysis re dry storage under optimum moderator conditions Dry storage under such conditions is feasible & k-eff will be less than 0-95 for all values of moderator density

NDVARRO, J P Long Island Lighting Co 79/05/09 4pp

DOCKET 71-0018 NUCLEAR ASSURANCE CORP

7906210097 Forwards request for add1 info to complete review of GA program MACDONALD.C E Transportation Branch 79/05/30 7pp

DOCKET 71-0028 BORG-WARNER CORP

7906010069 Responds to 790402 request for addl info re GA program Forwards Procedure SP175-47 reflecting mods 800TH.J H Borg-Warner Corp 79/04/25 1p

~-7906D10072 GA program for facility ALBRIGHT, H C Borg-Warnet Corp 79/04/15 6pp

DUCKET 71-0034 BABCOCK & WILCOX CO

7906230171 Forwards Revision 1 of QA program for transportation & receipt of radioactive mat1 SULZER.R C Babcock & Wilcox Co 79/05/16 ip

--7906230174 Revision 1 to GA program for transportation & receipt of radioactive rat! # Babcock & Wilcox Co 79/05/16 4pp

DOCKET 71-0636 ITT GRINNELL CORP

7906050020 Forwards revises GA program for radioactive matl package Previously deleted Part 8 on audits encl KOHALSKI.J O obsolete code 79/05/02 1p

--7906050024 Revised GA program for radicactive mat1 package KGWALSKI,J G obsolete code 79/04/30 13pp

DOCKET 71-0037 NAVY, DEPT OF

790604900B Forwards GA program TOMPKINS:PS Navy,Dept of 79/04/[8 1s

--7906040011 GA program for receipt handling, storage & transfer of special forms of radioactive mat! ~ Navy,Dept of 79/04/18 12pp

DOCKET 71-0639 WALWORTH CO

7906200294 Forwards Revision 1 to QA program STEPHEN.W R Walworth Co (subs of 1U International Corp ) 79/05/10 ip

---7906200297 Revision 1 to GA program STEPHEN.U R Walworth Co (subs of IV international Corp ) 79/05/07 3pp

DOCKET 71-0047 CAPITOL INTERNATIONAL AWYS . INC

7906190476 Responds to 790413 ltr Forwards current organizational structure SPARKS,E Capitol International Airways, Inc. 79/04/17 1p

Forwards request for current organizational chart for use 79/04/13 4pp

--7908010101 Informs that activities conducted under applicable criteria of 10CFR50 App B will be executed w/regard to transportation packages by 790701 MACDONALD.C E Transportation Branch 79/05/02 1p

DOCKET 71-0059 GENERAL ELECTRIC CO

7906110274 Responds to NRC 790413 ltr requesting additinfo & clarification Radiation protection officer & radiation safety officer in organizational chart are same JOLLY, J. General Electric Co. 79705708... ip

BUCKET 71-0061 NAVY, DEPT OF

7906020201 Submits add1 info re QA program covering duties of radiation protection officer & director of Neapons Quality Engineering Ctr FERMAN, P. M. Navy, Dept. of 79/05/02 2pp

DOCKET 71-0068 YANKEE ATOMIC ELECTRIC CO

7905290058 Responds to 790413 request re GA program Suggests revision number of YODAP-I-A not be designated HEIDER, LH Yanker Atomic Electric Co 79/04/24 [p

DOCKET 71-0070 GENERAL HOTORS CORP

7706200251 Forwards @A program for License 12-13858-01 ABRAMS.C J Gamma Field Co 79/05/07 1p

---7906200256 0A program for License 12-13858-01 ABRAMS,C J Gamma Field Co 79/05/07 3pp

DOCKET 71-0072 BABCOCK & WILCOX CO

7906160019 Forwards GA program for License M8-002-01 PORTERA: C Babcock & Wilcox Go 79/05/04 2pp

--7906160021 QA program for License MS-002-01 \* Babcock & Wilcox Co 79/05/03 3pp

DOCKET 71-0074 NUCLEAR WELDING, INC

7906220455 Forwards requested GA program
HANES, T S Nuclear Welding, Inc 79/05/07 ip

--7906220459 QA program for industrial radiography license \* Nuclear Welding, Inc 79/05/07 11pp

DOJKET 71-0077 MIDSTATE TESTING LAB

7906200311 Responds to 790427 itr re 790403 application requesting approval of QA program Requests deletion of ref to "radiation control officer" KEILMAN.T J. Midstate Testing Laboratory, Inc. 79/05/09 lp

DOCKET 71-0085 NAVY, DEPT OF

7706250336 Notification that addl info re GA program will be provided no later than 770708 D'MALIA:R J Navy.Dept of 77/05/10 1p

DOCKET 71-0089 NAVY, DEPT OF

770627024B Responds to 770413 itr re GA program for USS Jasen radiographic facilities Program is contained in CINCPACFLIINST 4355 IA Provisions are made in code for annual insp of maint actions & annual audits HNSON,W N Navy.Dept of 77/05/25 ip

DOCKET 71-0090 COMBUSTION ENGINEERING CO . INC

7906010093 Forwards QA program approval for radioactive matl pactage MACDONALD, C E Transportation Branch 79/05/02 ip

--7406010095 Informs that acctivities conducted under applicable criteria of 10CFR71 App E will be executed w/regard to transportation packages by 790701
MACDOMALD.C E Transportation Branch 79/05/02 1p

## DOCKET 71-0096 PAN AMERICAN WORLD AIRWAYS

7906070039 Notifies that proposed QA program does not meet requirements of App I to 10CFR71 Forwards sample 790402 QA program for industrial radiography licensees to assist in application revision Requests revision by 790502 MACDONALD.C E Transportation Branch 79/04/27 3pp

#### DOCKET 71-0099 FOSTER WHEELER ENERGY CORP

7706020224 Forwards Foster Wheeler Energy Corp procedure, "Radiation Safety, AA Requirements for Radiography Source Shipments," Revision 1, dtd 790504
KOYACS,F B Foster Wheeler Corp 79/09/04 5pp

# DOCKET 71-0103 THIN CITY TESTING & ENGR LAR

7906020188 Forwards page 4 of GA program, per NRC 790413 request SCHULZE, H T Twin City Testing & Engineering Laboratory. Inc 50HULZE, H T 79/05/03 2pp

## DOCKET 71-0110 BUCKEYE STEEL CASTINGS

7906040125 Forwards GA program
KRANER, J F Buckeye International, Inc., Steel Castings Div
79/04/19 tp

--7706040132 GA program for industrial radiography KRANER: J F Buckeye international, Inc., Steel Castings Div 77/04/19 4pp

#### DOCKET 71-0115 BABCOCK & WILCOX CO

7905010187 Forwards request for addl info to complete review of QA Program MACDONALD.C E Fransportation Branch 79/05/00 13pp

# DOCKET 71-0119 INGERSOLL-RAND CO

7906230012 Forwards GA program w/requested change Radiation Bafety Officer Little changed to Radiation Protection Officer MORGANELLO.M M [ngersoll-Rand Co 79/05/11 1p

~~7906230015 GA program for industrial radiography licensees \* Ingersoll-Rand Co 76/06/26 3pp

#### DOCKET /1-0120 DANIEL INTERNATIONAL CORP.

7906200284 Forwards Revision 1 to QA program for License 39-01261-02 PLUMSTED, W C Daniel International (subs of Fluor Corp ) 79/05/09 1p

--7906200288 Revision 1 to 0A program for License 39-01261-02 \* Daniel International (subs of Fluor Corp.) 79/05/09 3pp

## DOCKET 71-0135 BABCOCK & WILCOX CO

790622043B Requests correspondence to PA operations sits be addressed to MA Austin instead of RA Williams AUSTIM, M.A. Babcock & Wilcox Co. 79/05/10 ip

# DOCKET 71-0137 METALS TESTING CO . INC

7906200066 Nutifies that proposed GA program does not meet requirements of App E to 10CFR71 Submits sample GA program as aid in revising application MACDONALD, C E Transportation Branch 79/05/18 3pp

DUCKET 71-0145 THAYER INSPECTION SERVICE, INC.

7906200346 Submits revised page of Part 71 GA program
THAYER: D W Thayer Inspection Service: Inc 79/05/09 2pp

#### DOCKET 71-0146 GLOBE X-RAY SERVICES, INC.

7906230157 Forwards copy of form to be used in compliance u/QA program BB Ozmun will be auditor OZMUNR V Clobe X-Ray Gervices, Inc. 79/05/09 2pp

# DOCKET 71-0150 PEABODY TESTING SERVICES

7906020185 Forwards add1 paragraph to GA program re audits.per NRC 790413 request
BANFIELD,E L Peabody Testing/X-Ray Engineering Co 79/05/03 2pp

## DOCKET 71-0154 GENERAL DYNAMICS

7906230019 Forwards QA program w/requested change Radiation Safety Officer title changed to Radiation Officer RQBERTS,V M General Dynamics Corp , Quincy Shipbuilding Div 79/05/09 ip

--7906230022 QA program License 20-11915-01 MESROBIAN,A L. General Dynamics Corp., Quincy Shipbuilding Div 79/05/09 3pp

## DOCKET 71-0157 FROCHLING & ROBERTSON, INC.

7906230011 Forwards revised Section VII of QA program for transportation packaging, allowing audit by Assistant Radiation Safety Coordinator, in reponse to request for add1 BRIODY, W W Freehling & Robertson, Inc. 79/09/10 2pp

#### DOCKET 71-0162 EBASCO SERVICES, INC

7906020170 Forwards addl copies of GA program for shipping packages for radioactive matl
JONAS,J W Ebasco Services, Inc (subs of Ensorch Corp.)
79/04/30 ip

--7906020175 QA program for License 29-07086-03 JUNAS, J W Ebasco Services, Inc (subs of Enserch Corp ) JONAS. J W Eb. 79/04/25 5pp

#### DOCKET 71-0169 FLORIDA POWER & LIGHT CO

7906050019 Responds to 780319 ltm requesting ref to specific GA program used to meet requirements of 10CFR71 51 Revision 2 to topical GA rept is in effect for Turkey Point & FSAR GA program is in effect for St Lucie UHRIG.R E Florida Power & Light Co 77/04/23 lp

## DOCKET 71-0174 SOUTHERN CALIFORNIA EDISON CO

7906010149 Forwards OA program approval for radioactive mat1 packa-MACDONALD.C E Transportation Branch 79/05/08 1p

---7906010154 Activities confucted under applicable criteria of App 10CFR to be executed w/regard to transportation packages by Transportation Branch 79/05/09 ip MACDONALD, C E

# DOCKET 71-0188 MAYNARD STEEL CASTING CO

7906200261 Forwards Revision 1 to GA program for License 48-07080-FAIST,C A Maynard Steel Casting Co 79/05/09 ip

--7906200263 Revision 1 to GA program for License 40-07090-01 \* Maynard Steel Casting Co 79/05/09 5pp

790626025B Requests add1 info re company organization % statement audit activities, to complete review of GA program MACDONALD, C E Transportation Branch 79/05/24 2pp

#### DOCKET 71-0190 TEXAS INSTRUMENTS, INC

- 790608089 Forwards request for addition to complete review of QA program
  MACDUNALD, C.E. Transportation Branch 79/04/27 13pp
- 7906200007 Requests that GA plan for shipping packages for radioactive matls be withdrawn from application HFIR project is not user of general license for shipment of DOT spec containers SHERMAN.F.L. Texas Instruments. Inc. 79/05/08 ip

#### DOCKET 71-0195 TOLEDO EDISON CO

- 770A020036 Responds to 790321 request for info re GA program Util nuclear GA manual, revised 770108, is used for shipments of Type B quantities ROE:L E Toledo Edison Co 79/04/30 ip
- 7906180682 Forwards GA program approval for radioactive matl package MACDONALD, C E Transportation Branch 79/05/17 1p
- --79061806B7 QA program approval for radioactive matl package 0195, Revision O HACDONALD, C E Transportation Branch 79/04/30 1p

# DOCKET 71-0202 PACIFIC GAS & ELECTRIC CD

- 7904050027 Forwards QA program approval for radioactive matl package MACDONALD.C E Transportation Branch 79/05/02 ip
- --7906050029 GA program approval for radioactive mat1 package 0202, Revision O MACDONALD, C E Transportation Branch 79/05/02 1p

## DOCKET 71-0207 CONNECTICUT YANKEE ATOMIC POWER CO

- 7904010145 Forwards QA program approval for radioactive mat! package MACDENALD,C E Transportation Branch 79/05/08 tp
- --7906010147 Informs that activities conducted under applicable criteria of 10CFR30 will be executed w/regard to transportation pkgs by 790801 MACDONALD, C E Transportation Branch 79/05/08 1p

### DOCKET 71-0208 NORTHEAST NUCLEAR ENERGY CO

- 7904210090 Forwards QA program approval for radioactive matl package MACBUNALD.C E Transportation Branch 79/05/30 1p
- --7906210092 OA program approval for radioactive mat1 package 0208, Revision O MACDUNALD.C E Transportation Branch 79/03/30 1p

# DOCKET 71-0213 INTERMOUNTAIN TESTING CO

- 7906190497 Advises that organization table has been changed to read Radiation Safety Officer instead of Radiation Protection Officer
  SCHELL, Y A Intermountain Testine Co 79/04/19 in
  - O GENERAL DYNAMICS CORP

### DOCKET 71-0225 NAVY, DEPT OF

- 7906050035 Requests mod of QA program submitted on 781220, re duties of radiation safety officer
  HENIFIN, E E Navy, Gept of, Naval Research Laboratory 79/04/26
  2pp
- 7906230044 Forwards Itrs sent to Navel organizations involved in radioactive matl packages Lists organizations which have submitted acceptable GA programs W/o encl MACDONALD.C E Transportation Branch 79/05/24 1p

# DOCKET 71-0229 WORD INDUSTRIES PIPE FABRICATING, INC.

7906230027 Submits addl info for OA program re radiation safety officer document control.handling.storage.shipping.insp ½ test ½ operating status.in response to NRC 79040½ request ROBBINS.R W Word Industries Pipe Fabricating. Inc 79/05/0/

# DOCKET 71-0230 BABCOCK & WILCOX CO

- 7906200514 Forwards revised QA program for shipping containers.Reviselta I MCCLANAMAN.H H Babcock & Wilcox Co 79/05/10 Ip
- --7906200515 GA program of shipping containers. Revision 1
  \* Babcock & Wilcox Co 79/05/10 34pp

# DOCKET 71-0233 D'HEILL TANK CO : INC

- 7906040148 Forwards GA manual for transportation packaging of radioactive mati ADAMS, K O'Neill Tank Co . Inc 79/04/20 ip
- ~-7906040151 Ga manual for transportation packaging of radioactive matl
  \* O'Noill Tank Co . Inc 79/04/20 2pp

# DUCKET 71-0240 POWER AUTHORITY OF STATE OF NEW YORK

- 7905150227 Forwards listing of docketed into describing GA program
  EARLY, P J Power Authority State of New York 79/04/30 3pp
- 7906200108 Forwards GA program approval for radioactive mati package MACDONALD.C E Transportation Branch 79/05/17 1p
- --7906200112 QA program approval for radioactive matl package 240. Revision O MACDONALD, C E Transportation Branch 79/05/17 (p

# DUCKET 71-0258 NUCLEAR ENGINEERING CO . INC

7906220211 Forwards acceptance criteria used to evaluate QA program Addl info is required to satisfy requirements of 10CFR71.App E MACDONALD.C E Fransportation Branch 79/05/16 [3pp

# DOCKET 71-0260 ASTROTECH, INC

7906200605 QA program for shipping packages of radiographic matls MYKYTA, L. Astrotech, Inc. 79/05/15 15pp

#### DOCKET 71-0275 DUQUESNE LIGHT

- 7906160060 Requests withdrawal of solid radioactive waste gackaging QA program, submitted 790216 Approves operational GA program DUNN,C N Duquesne Light Co 79/05/07 1p
- 7906180793 Forwards GA program approval for radioactive matl package MACDONALD, C. E. Transportation Branch. 79/05/17 1p
- ---7906180795 GA program approval for radioactive mat1 package 0275. Revision O MACDONALD.C E Transportation Branch. 79/05/07 ip

DOCKET 71-0279 UNIVERSAL TESTING, INC

7905050411 Notifies that proposed QA program does not meet requirements of App E to 10CfR71 Forwards sample QA program for industrial radiography licensees.dtd 770402.to assist in application revision Requests revision by 770502 HACDONALD.C E Transportation Branch, 79/04/27 3pp

DOCKET 71-0284 ULTRASONIC SPECIALISTS, INC

7904070207 Forwards GA program SOUTHERS.R L Ultrasonic Specialists: Inc 79/03/13 1p

--7904070209 GA program

\* Ultrasonic Specialists, Inc 79/03/13 4pp

DOCKET 71-0285 BELL GEOPHYBICS

7906140102 Forwards QA program for License 33-10126-01 BELL,J A Bell Geophysics 79/03/16 5pp

---7906140105 GA Program for License 33-10126-01 \* Bell Geophysics 79/03/16 4pp

DOCKET 71-0287 CARBON NON-DESTRUCTIVE TESTING

790407014B Forwards QA program for License 37-17285-01 MACVAUGH,R W Carson Nondestructive Testing 77/03/19 App

--7906070159 GA origram for License 37-17289-01 MCVAUGH,R W Carson Nondestructive Testing 79/03/19 3pp

DOCKET 71-0289 TERRADATA OCOPHYBICAL, INC.

7906140091 Forwards QA program for License 05-18317-01 MCBRIDE, Q E Terradata Geophysical, Inc 79/03/15 5pp

--7906140100 GA program for License 05-183(7-0)
MCBRIDE, G E Terradata Gaophysical, Inc. 79/03/16 3pp

DOCKET 71-0291 DJ INSPECTION SERVICES, INC

7906190427 Forwards GA program for License 2-2067 JOHNSON, H DJ Inspection Services. Inc 79/03/19 ip

--7906150430 QA program for License 2-2067 JOHNSON, M DJ Inspection Services, Inc. 79/03/19 4pp

DOCKET 71-0292 INDUSTRIAL GAMMA INSPECTION

7906140078 Forwards QA program for License 35-16760-01 SMITH-R Industrial Gamma Inspection 79/03/15 ip

---7906140080 GA program for License 35-16760-01, SMITH:R Industrial Gamma Inspection 79/03/15 Spp

DOCKET 71-0294 APPLIED ENGINEERING CO

7906150433 Forwards QA program for License 205 QUODWIN.J. Applied Engineering Co 79/03/23 ip

--7906150440 QA program for License 205 GOODWIN: J Metropolitan Edison Co 79/03/23 App

DOCKET 71-0295 ACUREX CORP

7906150446 Forwards QA program for License 2715-590L FENDRICK, J E Acurex, Alcore. 79/03/26 1p

--7906150449 GA program for License 2715-59GL FENDRICK, J E Acurex; Alcore 79/03/26 4pp

DOCKET 71-0298 STEEL TANK CONSTRUCTION CO

7906180193 Forwards GA program for License 8-2323, PADGETT.0 Steel Tank Construction Co 79/03/22 ip.

--7906180199 QA program for License 8-2323 CALLOHAY.C C Steel Tank Construction Co 79/03/22 5pg

DOCKET 71-0301 CTL ENGINEERING. INC

7904180584 Forwards GA program, Revision 1, for License 34-08331-01 CROWLEY, J & CTL Engineers, Inc. 79/03/19 1p

---7906180588 QA program.Revision 1.for License 34-08331-01 KVAMMEN.B., CROWLEY, J. L. CTL Engineers, Inc. 79/03/01 7p

DOCKET 71-0302 JOHNSON CONTROLS

7906010224 Forwards GA program
JONEB.K C Johnson Controls, Inc 79/03/23 1p

--7906010226 GA program for License 43~15119-01 JONES:K ( Johnson Controls: Inc 79/03/26 3pp

DOCKET 71-0303 MEMPHIS TESTING SERVICES, INC.

7906140068 Forwards GA program for License R-9635-C4 REID.R E Memphis Testing Services. Inc 79/03/28 19

---7906140073 GA program for License R-9635-C4
REID:R E Memphis Testing Services: Inc 79/03/28 App

DOCKET 71-0306 SNYDER DRILLING-WELL SERVICING CO

7906220493 Forwards QA program for License 12-13194-01 BNYER,H.L. Snyder Drilling-Wall Servicing 79/03/26 1p

--7906220474 GA program for License 12-13194-01 SNYDER.H L Snyder Drilling-Well Servicing 79/03/26 App

DOCKET 71-0308 ALASKA INDUSTRIAL X-RAY

7904040077 Forwards QA program for License 50-14084-01 MILLAR,P A Alaska Industrial X-Ray 79/03/18 !p

--7906040080 GA program for Elcense 50-16084-01 MILLAR,P A Aleska Industrial X-Ray 79/03/18 2pp

DOCKET 71-0310 BUCYRUS-ERIE CO

7906110425 Forwards GA program for License 48-06390-01 MERTZ.J M Bucyrus-Erie Co 79/04/04 1p

--7906110427 GA program for License 48-06390-01 MERTZ.J M Bucyrus-Erie Co 79/04/02 3pg

7906140659 Forwards request for addl info to complete review of GA

MACDONALD, C E Transportation Branch 79/05/08 2pp

DOCKET 71-0313 PRECISION INSPECTION: LTD

7706140044 Forwards QA program for License 8-203 SINK,J E Precision Inspection,Ltd 79/04/12, 1

--7906140048 GA program for License 8-203 SINK.JE Precision Inspection.Ltd 79/04/12 4pp

DOCKET 71-0314 SMITH-EMERY CD.

7906140053 Forwards QA program for License 2878-59. DUNHAM,M S Smith-Emery Co 79/04/09 1p.

--7906140057 GA program for License 2878-59 DUNHAM, M 8 Smith-Emery Co 79/04/09 App.

#### DOCKET 71-0315 RADIOGRAPHY INSPECTION, INC.

- 7904040099 Forwards GA program for License 29-10532-02 BALLARD, J L. Radiography Inspections 79/04/09 1
- -7906040104 GA program for License 27-10592-02 BALLARD:J L Radiography Inspections 79/04/09 4pp
- DOCKET 71-0316 MASON & HANGER-BILAS MASON CO . INC
- 7904050351 Forwards GA program HOLMBERG, R.L. Mason & Hanger Silas Mason Co., Inc. 79/04/16 19
- --7706050356 QA program for License 15-17192-01 \* Mason & Hanger Bilas Mason Co , Inc : 79/04/16 Ann

#### DOCKET 71-0318 MARATHON DIL CO

- 7906140006 Forwards GA program
  BARRE,C H Marathon Oil Co 79/04/16 1p
- --7906140008 GA program
  BARRE, C H Marathon Gil Co 79/04/16 4pp
- DOCKET 71-0319 GENERAL TESTING & INSPECTION CO
- 7904040074 Forwards GA program for License 34-09037-01 KRUEGEL, R & General Test & Inspection 79/04/17
- --7906040087 QA program for License 39-09037-01 \* General Test & Inspection 79/04/17 4
- DUCKET 71-0320 PITTSBURGH-DES MOINES GYEEL CO
- 7905160002 Forwards GA program for License 37-02607-02 HUGHE6,B J Pittsburg Des Moines Steel Co 79/04 79/04/18 1p
- --7906160003 GA program for License 37-02607-02 \* Pittsburg Des Moines Steel Co 79/04/18 4pp

#### DOCKET 71-0321 EXAM CO

- 790614003B Forwards GA program for License 35-1619;-01 MOBLEY, J D Exam Co 79/04/04 1p
- --7906140040 GA program for License 35-16191-01 \* Exam Co 79/04/04 3pp
- 7906220419 Requests registration as user of Models HN-100 Series 1 & 2, HN-1005, HN-200, HN-300, B3-1, Poly Panther, Half Super Tiger, Tiger, NFS-4, NLF-1/2, B6-33-180, LL-60-180, AP-101 & GH-142 REYNOLDS, L.E. Chem-Nuclear Sustems, Enc. 79/05/11 14
- DOCKET 71-0322 CONTROL COMPONENTS INTERNATIONAL
- 7906070164 Forwards GA program for License 3263-30.9tate of CA LAWRENCE, M Control Components, International (subs. of Babcock & Wilcox). 79/04/11. 1p
- --7906070171 QA program LAWRENCE:M Control Components, International (subs of Babcock & Wilcox) 79/04/11 3pp
- DOCKET 71-0324 ALLIED CHEMICAL
- 7906140063 Reaffirms position that GA program for U herafluorida cylinders complies w/NRC requirements Hilling to yewrite document if necessary & deliver revised program by 790702 NEWMAN.R T Allied Chemical Corp 79/04/27 ip.
- DOCKET 71-0325 CONSUMERS POWER CO
- 7906210412 Forwards request for addl info to complete review of GA Program MACDONALD, C E Transportation Branch 79/05/10 ip

- DOCKET 71-0326 INDUSTRIAL HEAT TREATING & METALLURGICAL CO . INC
- 7906010305 GA program for License 13-06147-04 EDWER,P K Industrial Heat Treating 79/04/23 2pp
- DOCKET 71-0327 PORTLAND GENERAL ELECTRIC CO
- 7706200167 Responds to 770503 request for info re QA program for radioactive shipments QA program submitted as Chapter 17 2 of 721218 FSAR & updated on 770202 as Amend 23 to FSAR UILLIAMS, J L Portland General Electric Ca 77/05/10 ip
- DOCKET 71-4824 MODEL HA-10, BABCOCK & WILCOX CO
- 790622043B Requests correspondence to PA operations sito be addressed to MA Austin instead of RA Williams
  AUSTIN:M A Babcock & Wilcox Co 79/05/10 ip
- DOCKET 71-4894 MODEL NPD-1-528, KERR-MCGEE NUCLEAR CORP
- 7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams AUSTIN.M A Babcock & Wilcox Co 79/05/10 10
- DOCKET 71-4949 MODEL UNC-1484, COMBUSTION ENGINEERING CO . INC
- 7706140015 Notifies that Certificate of Compliance 4949 for Model UNC-1484 expires 790531 Asks if renewal desired MACDONALD, C.E. Transportation Branch 79/04/12 lp
- 7706180153 Notifies of 770531 expiration of Certificate of Compliance 4949 for Model UNC-1484 Requests submission of consolidated application for renewal MACDONALD, C Transportation Branch 77/05/08 2pp
- 7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
  AUSTIN.M A Babcock & Wilcox Co 79/05/10 1p
- DOCKET 71-4986 MODEL RA-2: EXXON NUCLEAR CO . INC
- 7906230061 Notifies that Revision 4 to Certificate of Compliance 4786 was issued 790426 in response to 790105 application for amend After review of manpower expenditures required, \$1,128 will be refunded MILLER, W. O. License Fee Management Branch 79705/16 19
- DOCKET 71-5364 MODEL NPI-67-0442 NEUTRON PRODUCTS, INC.
- 7906180043 Forwards Revision 2 of Certificate of Compliance 3364 shipping package Model NPI-67-0442 MACDONALD, C E Transportation Branch 79/05/14 2pp
- --7906180052 Certificate of Compliance 5364, Revision 2, for radioa mat1 shipping package Model NPI-67-0442 MACDONALD, C E Transportation Branch 79/05/14 3pp
- DOCKET 71-8442 MODEL LA-36, BABCOCK & WILCOX CO
- 790622043B Requests correspondence to PA operations site be addre to MA Austin instead of RA Williams AUSTIN,M A Babcock & Wilcox Co 79/05/10 ip
- DOCKET 71-5450 MODEL RCC-1, -2, -3, WESTINGHOUSE ELECTRIC CORP
- 7904160014 Forwards revised drawings in support of application is revision of Certificate of Compliance 5450 to include RCC-4 shipping package W/a encl DIFIAZZA, R P Wastinghouse Electric Corp 79/05/04 2pp
- DOCKET 71-3595 MODEL L&M ORNL URANIUM SHIELDED CASK, ENERGY, DEPT
- 7906060034 Requests registration as user of Shipping Cask 5595.
  DIETZ.G R Isomedix, Inc (subs of Massfield Enterprises, Inc 79/04/17 ip

DOCKET 71-5768 MODEL 88-250-2, COMBUSTION ENGINEERING CO , INC

790622043E Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams AUSTIN.M A Babcock & Wilcox Co 79/09/10 ip

DOCKET 71-5790 MODEL A1-M3, ENGERY, DEPT OF

7906050014 Concludes Packages AL-M3 & AL-M6 mest current packaging criteria RDEDER, JR Energy, Dept of 79/04/10 ip

DOCKET 71-5791 MODEL A1-MA, ENERGY, DEPT OF

7906050014 Concludes Packages AL-M3 & AL-M6 meet current packaging criteria ROEDER.J R Energy.Dept of 79/04/10 ip

DOCKET 71-5805 MODEL ATCOR VNDB CASK, ATCOR, INC

7906290334 Forwards Ravision 8 of Certificate of Compliance 5805 for shipping package Model Vandenburgh MACDUNALD.C E Transportation Branch 79/06/05 2pp

--7905290734 Certificate of Compliance 9805 Revision 8, for radioactive matl shipping package Model Vandenburgh MACDONALD, C E Transportation Branch 79/06/05 3pp

DOCKET 71-5908 MODEL DOT-GM TYPE B. BABCOCK & WILCOX CO

7905220438 Requests correspondence to PA operations site be addressed to MA Austin Instead of RA Williams
AUSTIN, M A Babcock & Wilcor Co 79/05/10 1p

7906200072 Forwards Certificate of Compliance 5908,Revision 5.for Model DOT-6M Type B shipping package Supersodes Certificate of Compliance 5908,Revision 4 Constitutes authority to use package for shipment of radioactive matl MACDONALD.C E Transportation Branch 79/05/17 2pp

DOCKET 71-5926 MODEL 100, GENERAL ELECTRIC CO

7906070253 Forwards Revision 2 of Certificate of Compliance 3926 for shipping package Model GE-100 MACDONALD.C E Transportation Branch 79/05/08 2pp

--7906070260 Certificate of Compliance 5926,Revision 2,for radioactive matl shipping package Model CE-100
MACDONALD, C E Transportation Branch 79/05/08 3pp

DOCKET 71-5942 MODEL GE-700, GENERAL ELECTRIC CO

770&010327 Forwards request for add1 info to complete review of amend to Model GE-700 packaging Info should be submitted as revised pages to SAR Requests response schedule within 30 days
MACDUNALD.C E Transportation Branch 79/04/18 2pp

7906290163 Forwards revised BAR pages re criticality analysis accounting for reflection by lead & use of more correct U-23B cross-section set Revised structural analysis & oversized drawing of Model 700 GE shipping cask encl BUGGER.R M Missouri, Univ of 79/05/22 102pp

DOCKET 71-6058 HODEL 83-1, NUCLEAR ENGINEERING CO

79/06/40606 Supplements previous rept advising that certain shipping casks do not comply u/provisions of Certificate of Compliance 6038 Have placed all three casks in out-of-svc status until detailed insp is made BAER.T S Nuclear Engineering Co , Inc. (subs of Teledyne, Inc.). 79/05/07 2pp

7906200133 Notification that Cortificate of Compliance 605B for Model B3-1 expires 791231 Requests renewal of existing certificate of compliance if continued use is desired MACDONALD, G. E Transportation Branch 79/05/16 1p.

7906220100 Notifies that Certificate of Compliance 6058 for Model B3-1 expires 781231 Request for continuation as user of cortificate must be submitted NATALE.V Oak Ridge National Laboratory WILLIAMS, D H Arkansas Power & Light Co OLSEN.A F Babcock & Wiltox Co 79/05/16 2pp

DOCKET 71-6244 MODEL 6244. CHEM-NUCLEAR SYSTEMS.INC

7906180789 Requests renewal of Certificate of Compliance 6244.which expires on 790531 Forwards renewal fee REYNOLDS.L E Chem-Nuclear Systems, Inc 79/05/07 1p

7704200228 Requests registration as user of Model HN-100 Series 1 & 2, HN-100S,HN-200,HN-300,B3-1,Poly Panther,Half Super Tiger, Super Tiger, NFS-4, NLI-1/2, BS-33-180, LL-40-150, AP-100 & 101 & 0H-142 REYNOLDS,L E Chem-Nuclear Systems, Inc. 79/05/11 1p

DOCKET 71-62/2 MODEL POLY PANTHER, TELEDYNE ENERGY SYSTEMS

770622043B Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTINE A Bebcock & Wilcox Co 79/05/10 1p

DOCKET 71-6294 MODEL UNC-2901, COMBUSTION ENGINEERING, INC.

7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTINIA A Babcock & Vilcax Co 79/09/10 ip

DOCKET 71-6375 MODEL PB-1, CREM-NUCLEAR SYSTEMS, INC

7906190363 Notification that Certificate of Compliance 6375 for Model PB-1 shipping package will expire 790930 Requests submittal of consolidated application W/drawings, incorporating all previous submittals so that new certificate can be issued MACDONALD.C E. Fransportation Branch 79/05/16 ip

7906220191 Notifies Certificate of Compliance 6375 for Model PB-1 expires on 790930 Primary user should submit consolidated application for renewal MACDONALD, C E Transportation Branch 79/05/17 3pp

7906230009 Requests additinfo re changes made to Drawing 9123-6P8-0001. Revision E.in response to 790124 application for amend to Model PB-1 packaging MACDONALD, C C Transportation Branch 79/05/23 1p

DOCKET 71-6387 MODEL 60, BATTELLE MEMORIAL INSTITUTE

7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTIN, M A Babcock & Wilcox Co 79/09/10 1p

DOCKET 71-6574 HODEL HN-200, HITTMAN NUCLEAR & DEVELOPMENT CORP

7906130469 Notification of registration as user of Models HN-200, HN-100 Series 2 & HN-100 Series 1.in response to licensee 790108 request MACDUNALD, C E Transportation Branch 79/05/14 ip

DOCKET 71-4601 MODEL LL-50-100, CHEM-NUCLEAR SYSTEMS, INC.

7906200104 Requests Drawing 1042-D-0021, Revision D.in order to complete review of request for amend to Model LL-50-100 MACDONALD, C E Transportation Branch 79/05/17 19

DOCKET 71-6639 HODEL MH-IA, ARMY, DEPT OF

7706200100 Natifies that amend to Certificate of Compliance 6639.
Revision 4, Item 5 (b)(2)41() not required for proposed change to fuel basket design for shipment of TRIGA fuel assemblies
MACOGNALD, C Transportation Branch 79/05/17 ip

DOCKET 71-4679 MODEL 1/2 SUPER TIGER, NUCLEAR ENGINEERING CO

7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTIN: M A Babcock & Wilcox Co 79/05/10 ip

DOCKET 71-6698 MODEL NFS-4. NUCLEAR FUEL SERVICES. INC

7906050415 Submits historical info re NAC-1 spent fuel shipment cask usage ROLLING, J D Nuclear Assurance Corp 79/04/12 ip

7906160062 Responds to 790406 show cause order Euspension of license can be lifted for casks for which data has been acquired in in a timely fashion PARKER W O Dure Power Co 79/04/27 2pp

7706140552 Informs that 770400 ltr was sent on behalf of Duke Power Co MCGARRY, J M Debevoise & Lieberman 77/05/02 ip

DOCKET 71-6717 MODEL 6717 8

7906180168 Requests authorization as shipper under same terms & conditions listed in Certificate of Compliance 6717
KEENEY, H P Argonne National Laboratory - Argonne West 79/04/18

7906190559 Notification of registration as user of Model 6717-B in response to 790418 request MACDONALD.C E Transportation Branch 79/05/16 ip

DOCKET 71-9002 MODEL U-10-CL. BABCOCK & HILCOX CD

7906220438 Requests correspondence to PA operations site be addressed to MA Austin Instead of RA Williams
AUSTIN:M A Babcock & Wilcox Co 79/05/10 ip

DOCKET 71-9009 MODEL FL 10-1, GENERAL ELECTRIC CO

7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTIN.M A Babcock & Wilcox Co 79/05/10 ip

DOCKET 71-9010 MODEL NLI-1/2. NL INDUSTRIES, INC

7908050071 Submits info prior to first use of Model NLI-1 shipping container
DiP16226, R P Westinghouse Electric Corp 79/04/27 ip

7906290041 Forwards Revision 3 of Certificate of Compliance 9010 for shipping package Model NLI-1/2.

MACDONALD, C. E. Transportation Branch 79/03/25 2pp

--7906290033 Certificate of Compliance 9010, Revision 5, for radioactive matl shipping package Model NCI-1/2
MACDONALD, C E Transportation Branch 79/03/25 ip

DOCKET 71-9019 MODEL BU-7, GENERAL ELECTRIC CO

7906160001 Requests registration as user of GE Transportation Packages 9019 5 6458 GREGOR J United Nuclear Corp. 79/04/23 [p.

7406180164 Requests registration as user of BU-7 shipping container under License SMM-1168 All documentation required for container use has been obtained ZEFF, D W Babcock & Wilcox Co 79/04/25 lp

DOCKET 71-9022 MODEL CE-250-2, COMBUSTION ENGINEERING CO., INC

790622043B Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTIN:M A Babcock & Wilcox Co 79/05/10 1p

DOCKET 71-9033 MODEL 660 & 660E, TECHNICAL OPERATIONS, INC

7706190488 Forwards Certificate of Compliance 9033.Revision 2.for shipping package Models 660~b~660E List of package users registered under 10EFR71~12(b) or 49EFR173~393a encl MACDDNALD.C E Transportation Branch 79702/01~4pp

---7906190495 Certificate of Compliance 9033. Revision 2, for radioactive mat1 shipping package Hodels 660 % 660E MACDONALD.C E Transportation Branch 79/02/01 2pp

DOCKET 71-9044 MODEL 0E-1600, DENERAL ELECTRIC CD

7906190476 Notification of registration as user of Model GE-1600.in response to licenses 790326 request MACDONALD, C E Transportation Branch 79/05/14 1p

DOCKET 71-9045 MODEL BU-4, GENERAL ELECTRIC CO

7906220438 Requests correspondence to PA operations site be addressed to MA Austin instead of RA Williams
AUSTIN, M A Babcock & Wilcor Co 79/05/10 Ep

DOCKET 71-9070 MODEL N-55, ENERGY, DEPT OF

7906290831 Requests registration as user of Model CNSI 1-5 radioactive mati shipping cask
STRACCIA:F P Union Carbids Corp 79/05/16 ip

7906290735 Requests QA program be submitted prior to registration as package user or delivery of licensed matl to carrier for transport MAGDONALD, C E Transportation Branch 79/05/25 ip

DOCKET 71-9079 MODEL HN-100 SERIES 2. HITTMAN NUCLEAR & DEVELOPMENT

7906230031 Forwards Drawing C001-4-9119, Revision C. & Addendum 1 to BAR, Revision 1, for HN-100 Beries 2 Radwaste Shipping Cask Six oversized drawings encl TRFOTLIO, A O Hittman Nuclear & Development Corp (subs of Hittman Corp ) 79/09/09 2pp

--7706230043 "Addendum I to SAR for HN-100 Series 2 Radwaste Bhipping Gask Referencing 100FR71 Type A Packaging Regulations " ORIFFITH.J . TRIOILIO.O Hittman Nuclear & Development Corp (4ubs. of Hittman Corp ) 77/03/09 6pp

7906130469 Notification of registration as user of Models HN-200, HN-100 Series 2 & HN-100 Series 1, in response to licensee 790108 request MACDONALD, C E Transportation Branch 79/05/14 is

DOCKET 71-9080 MODEL HN-600, HITTMAN NUCLEAR & DEVELOPMENT CORP

7906200091 Requests registration as user of Model HN600. ARNDT.R W Picker Corp 79/05/10 1p

7906[50469 Notification of registration as user of Models HN-200-HN-100 Spries 2 & HN-100 Series 1.in response to licensee 79010B request MAGDDNALD, C E Trensportation Branch 79/05/14, Ip

# **DOCKETED ITEMS**

- 7906200127 Acks receipt f 790510 ltr re intended use of HN-600 under general license provisions of 10CFR71 12(b) Amend to this section requires approved QA program by 790101 Authorization terminated until QA program approved MACODNALD,CE Transportation Branch 79/05/17 1p
- DOCKET 71-9081 MODEL CNSI-1600, CHEM-NUCLEAR SYSTEMS, INC
- 7906040137 Requests registration as user of Madel CNSI-1600 DIETZ/0 R Isomedix. Inc (subs of Maesfield Enterprises, Inc ) 79/04/16 1p
- 7906200094 Requests registration as user of Model CNSI-1-13C OLSEN, A.F. Babcock & Wilcox Co. 79/05/09 1p
- DOCKET 71-9086 MODEL HN-100 SERIES 1, HITTMAN NUCLEAR & DEVELOPMENT
- 7906150469 Notification of registration as user of Models HN-200, HN-100 Series 2 & HN-100 Series 1 in reponse to licensee 790108 request MACDDONALD, C E Transportation Branch 79/05/14 lp
- DOCKET 71-9108 MODEL AL-33-90, ATCOR, INC.
- 7906180143 Requests registration as user of CNSI AL-33-90 radioactive matl shipping cask under License NPF-1 WITHERS, B D Portland General Electric Co 79/03/29 ip
- DOCKET 71-9117 MODEL RC-FBRTG-1000, ARMY, DEPT OF, EPG, FT BELVOIR
- 7906140017 Notifies of 790331 expiration of Certificate of Compliance 9117 for Model RC-FBRTG-1000 Requests submittal of Syncal Corp "Test Rept for One-W Radioisotope Thermo-Electric Generator" 5 renewal fee MACDONALD, C E Transportation Branch 79/04/12 1p
- DOCKET 71-9126 MODEL 20, 20A, 50, 50A, GAMMA INDUSTRIES
- 7906050379 Forwards Revision 1 of Certificate of Compliance 9126 for shipping package Models 20,204,50 & 504 Transportation Branch 79/04/04 ip

- --79060303B5 Certificate of Compliance 9126.Revision 1.for radioactive matl shipping package Models 20,20A,50 & 50A MASDQNALD,C E Transportation Branch 79/04/06 2pp
- --7906050390 Bafety evaluation supporting Certificate of Compliance 91 Revision 1 for radioactive mat1 shipping package Models 20,204,50 % 504 MACDUNALD.C E Transportation Branch 79/04/06 4pp
- DOCKET 71-9128 MODEL C-8, GAMMA INDUSTRIES
- 7906070014 Forwards Revision 1 of Certificate of Compliance 9128 for shipping package Model C-8 MACDONALD,C E Transportation Branch 79/04/06 1p
- --7906070017 Certificate of Compliance 9128.Revision 1, for radioactive matl shipping package Model C-8
  MACDONALD, C E Transportation Branch 79/04/06 2pp
- --7906070020 Safety evaluation supporting Certificate of Compliance 91 Revision Lifor radioactive matl shipping package Model C-8 MACDQNALD,C E Transportation Branch 79/04/06 4pp
- DOCKET 71-9132 MODEL T-3, NUCLEAR PACKAGING, INC.
- 7906280156 Responds to 790305 ltr re Revision 1 amend to BAR for T-3 Shipping Cask Forwards amended pages SIMCHUK, J D Nuclear Packaging, Inc. 79/05/18 169pp
- DOCKET 71-9506 MODEL M927684-2, ENERGY, DEPT DF
- 7906230007 Responds to 790427 ltr re Modal MS 27684-2 shipping package in Certificate of Compliance 9506 No plans for addl review of package RDEDER, J R Energy, Dept of 79/05/07 ip

		•	
	•		
7			
•		· ·	
√.			
		1.7	

# NONDOCKETED ITEMS

10CFR COMMISSION MEETING RECORDS	770607U098 Transcript of 790803 public meeting in Washington DC to discuss 8-3 rulemaking Pp 1-78 HENDRIE,J M , O[LINSKY,V , KENNEDY,R T Commission 79/05/03
7905240131 Expresses concern that concurrent jurisdiction between NRC & State of TX over U mill licensing may adversely affect Chevron U mill tailings subsidiary Urges adoption of Policy	76PP
Alternative 1 in SECY-79-88 TURNER, J G Chevron Oil Co (subs of Standard Oil Co of California) 79/04/16 2pp	7906070219 Ack receipt of 790416 ltr commenting on NRC interpretation & implementation of U Hill Tailings Radiation Control Act of 1978
	ENGELHARDY, T F Deputy Executive Legal Director 79/04/30 1p
7905240402 Expresses appreciation for 790320 ltr re U Mill Tailings Radiation Control Act of 1978 SHAPAR,H K. Office of the Executive Legal Director 79/04/17 lp	7906D70221 Comments on NRC interpretation of U Mill Tailings Radiation Control Act of 1978 State & NRC concurrent licensing jurisdiction is unnecessary
7905240422 Comments on 790202 memo re timing of certain requirements of U Mill Tailings Radiation Control Act of 1978 Act is subj to	TURNER, J G Chavron Industries. Inc , Chevron Resources Co Div 79704/16 2pp
interpretation & implementation resulting in 3-yr deferral of mill tailing licensing LYNCH,D A US Stael Corp 79/04/18 3pp	7906070292 Forwards NRC 790503 determination statement for withholding tape of Executive Branch briefing re intl safety matters W/o enci
7905250042 Ack receipt of 790322 ltr providing views on NRC interpretation & implementation of U Mill Tailings	CHILM, S J Office of the Secretary of the Commission 79/05/08 2pp
Radiation Control Act of 1978 SHAPAR, H K Office of the Executive Legal Director 79/04/17 ir	7906070279 Forwards NRC determination statement for withholding transcript of 790424 discussion of personnel matter
7905250068 Ack receipt of 790327 ltr providing views on NRC interpretation & implementation of U Mill Tailings Radistion Control Act of 1978	CHILK,S J Office of the Secretary of the Commission 79/03/08 2pp
SHAPAR, H K Office of the Executive Legal Director 79/04/19 ip	7906140101 Transcript of 790516 public meeting in Washington,DC re hearing on UCS petition for reconsideration Pp 1-47 Affirmation Session 79-13 encl
7905250071 Ack receipt of 790321 ltr providing views on NRC interpretation 5 implementation of U Mill Tailings Radiation Control Act of 1978 SHAPAR: H K Office of the Executive Legal Director 79/04/17 lp	HENDRIE, J H . GILINSKY, V . KENNEDY, R Commission 79/05/16 52pp
/905250075 Ack receipt of 790319 ltr providing views on NRC's	decammissioning to require plant operators to post bonds SCHULTZ.W B . ABBOTTS.J Public Interest Research Group 77/10/07 11pp
interpretation & implementation of U Mill Tailings Radiation Control Act of 1978 SHAPAR.H K Office of the Executive Legal Director 79/04/17 ip	7906140107 Transcript of 790508 public meeting in Washington DC re
7909250089 Ack receipt of 790921 ltr providing views on NRC's interpretation b implementation of U Hill Tailings	brieting on interagency radiological assistance program Pp 1-37 Presentation encl HENDRIE.J M , GILINEKY,V , KENNEDY,R T Commission 79/05/08 48pp
Radiation Control Act of 1978 SHAPAR.H K Office of the Executive Legal Director 79/04/17 ip	
7906020176 Transcript of 790501 public meeting in Washington.DC re resident inspector program Pp 1-38 HENDORIE.J M., GILLINSKY, V., KENNEDY, R. T. Commission. 79/05/01	7406140111 Transcript of 790508 public meeting in Washington.DC re ltrs to governors Pp i6 HENDRIE.J M , BRADFORD.P , AHEARNE.J Commission 79/05/08 7pp
ЗРРР	7906180369 Transcript of 790507 Affirmation Session 79-11 in Washington. DC Pp 1-6
7906020225 Transcript of 790511 public meeting & Affirmation Session 79-12 in Washington DC to discuss SECY-79-114 seeking to amend 10CFR19 & 20 to control radiation exposure to	HENDRIË, J.M., GILINSKY, V., KENNEDY, R. T. Commission 79/05/07 7pg
transient workers Pp 1-3 HENDRIE, J M., GILINSKY, V., KENNEDY, R.T. Commission 79/09/11 4pp	7906180384 Transcript of 790430 Affirmation Session 79-9 in Nashington, DC Pp 1-8 HENDRIE, J M . GILINGKY, V , KENNEDY, R T Commission 79/04/30 8pp
7906020227 SECY-79-114	
Seeks NRC approval to publish amends to 10CFR19 & 20 re radiation exposurs to transient workers Recommends approval Supporting documentation encl MINOGUE:R.B Office of Standards Development 79/01/12 65pp	7906180391 Transcript of 790312 public meeting in Washington,DC to discuss & vote on order in 8-3 rulemaking Pp 1-16 HENDRIE.J M . GILINSKY,V . BRADFORD,P Commission 79/09/11 16pp
790A020231 Value/impact assessment containing rept justification analysis of amend to regulations to control radiation doses to transient workers Recommends proposed action be taken * Uffice of Standards Development 79/01/12 31pp	7906180708 Transcript of 790511 public meeting to discuss NEPA regulations (SECY-79-305) Pp 1-9 HENDRIE.J M , GILINBAY.V , KENNEDY.R T Commission 79/05/11, 10pp
7905020234 Recommends paper re amend to 100FR19 & 20 provide analysis of "no further action" alternative including latest	7904180724 '.anscript of 790511 public meeting in Washington.DC re briefing on legislative matters (siting & licensing). Pp 1-33
assessment of impact & value SNYDER, B Office of Policy Evaluations 78/11/07, ip	HENDRIE, J M . GILINGKY, V . KENNEDY, R T Gommission 79/05/11 34pp

7904190044 Transcript of 790430 public meeting in Washington, DC to discuss 790329 Ofc of General Counsel memo on S-3 rulemaking HENORIE, J M., GILINSKY, V., KENNEDY, R. T., Commission 79/04/20 7pp

7906040017 Transcript of 790502 public meeting in Washington, DC to discuss 8-3 rulemaking Pp 1-78 HENDRIE: J M . GILINBKY, V , KENNEDY, R T Commission 79/05/02, 79pp

- 7906200305 Transcript of 790509 public meeting in Washington, DC re SECY-79-86 & U mill tailings Pp 1-52 HENDRIE, J H , OILINSKY, V , BRADFORD, P. A Commission 79/05/09 S20p
- 7906210079 Transcript of 790517 public meeting re SECY-79-B8 & U mill tailings Pp 1-26
  HENDRIE, J M . OILINSKY, V . KENNEDY, R T. Commission, 79/05/17
- 7906230136 Transcript of 790521 public meeting in Washington.DC relicensing schedules & related matters Pp 1-70 GLINSKY, V , KENNEDY, R T. , BRADFORD, P A Commission 79/05/21
- 7906260172 Summary of 790322 conference in Washington, DC re preservation of all records relating to TMI-2 incident CMILK, S. J. Office of the Secretary of the Commission 79/05/30
- --7906260410 Summary of 790417 meeting w/ACRS in Washington, DC re second interim rept on YMI-2 incident
  CHILK,S J Office of the Secretary of the Commission 79/04/19
- --7906260416 Summary of 790409 briefing in Hashington.DC re TKI-2 incident sequence of events & current assessment of safety of B&W reactors

  CHILK.S J Office of the Secretary of the Commission 79/04/05 ip
- --7906260420 Summary of 790329 meeting in Washington, DC re SECY-79-34A, "Regulation of Federal Radioactive Haste Activities" CHILK, S.J. Office of the Secretary of the Commission 79/04/05 to
- --7906260422 Summary of 790329 mesting in Washington, DC re SECY-79-154 & SECY-79-1544. "Rept to Congress deans for Improving State Participation in Stiting Activities" CHILK, S J Office of the Secretary of the Commission 79/04/02
- --7905260424 Summary of 790329 briefing in Washington, DC re THI-2 incident, current plant status & state & federal incident response CHILK.8 J Office of the Secretary of the Commission 79/03/29
- ---7905260427 Summary of 790323 meeting in Washington.DC re application by Edlow Intl Co for license to export SNM to India Subsequent vote approved license as meeting all relevant requirements CHILK.S J Office of the Secretary of the Commission 79/03/23
- --7906260430 Summary of 790322 Affirmation Session 79-7 in Washington DC re SECY-79-128-SECY-79-129 & SECY-79-148 NRC approved each notice of proposed rulemaking CHILK.S J Office of the Secretary of the Commission 79/03/23 29y
- --7904260434 Summary of 790322 meeting in Washington, DC re SECY-79-34A, "Regulation of Federal Radioactive Waste Activities "GHILK:8 J Office of the Secretary of the Commission 79/03/23

- 7906260162 Summary of 790529 conference in Washington, DC re State of MV v NRC decision Order approved, extending S-3 interim rule to 790730 CHILK: S J Office of the Secretary of the Commission 79/06/01
- /906260169 Summary of 790524 conference in Washington, DC re 1938 Soviet nuclear accident
  CHILK, S. J. Office of the Secretary of the Commission. 79/05/29
- 7906260174 Summary of 790522 discussion in Washington; DC, re NRC approval to preserve all TMI-2 records Addl order requested for records prior to 790282 re similar plant events CHILK:S J Office of the Secretary of the Commission 79/05/30
- 7904260178 Summary of 790522 discussion in Mashington, DC re NRC approval to preserve all TMI-2 records Addi order requested for records prior to 790328 re similar plant events CHILK:S J Office of the Secretary of the Commission 79/05/29 to
- 7906260184 Summary of 790522 discussion in Washington DC re SECY-79-278 & SECY-79-278A concerning physical protection of irradiated fuel shipments CHILK'S J Office of the Secretary of the Commission 79/03/25
- 7906260189 Summary of 790521 discussion in Washington, DC re formulation of Ofc of Nuclear Reactor Regulation interim organization to deal w/TMT-2 impacts
  CHILKS J Office of the Secretary of the Commission 79/05/24
- 7906260206 Bummary of 790517 meeting in Washington, DC re SECY-79-89 & 4 mili tailings Legislation to clarify metter will be requested by NRC CHILK-S. J Office of the Secretary of the Commission 79/05/23
- 7906260215 Summary of NRC 790517 briefing in Washington DC reinterim operational sequence of events of TMI-2 incident Order requested requiring involved parties to keep records CHILK/S J Office of the Secretary of the Commission 79/05/21 to
- 7906260219 Summary of 790317 hearing in Washington, DC re UCS grain patition for reconsideration CHILK: S J Office of the Secretary of the Commission 79/05/16 is
- 7906260223 Summary of 790511 meeting in Washington, DC re S-3 rule & statement of considerations No vote was completed Interimrule extended until 790530 CHILK-S J Office of the Secretary of the Commission. 79/05/11
- 7906260246 Summary of 790511 Affirmation Session 79-12 in Washington, CC re approval of SECY-79-114 Amended 10FR17 & 20 to control radiation exposure to transient workers CMILK-8 J Office of the Secretary of the Commission 79/03/14
- 7906260254 Summary of 790511 briefing in Washington: DC re siting to licensing Requested comments to be prepared by General Counsel on licensing sections of regulatory reform packages tubmitted to Congress CHILK: S J Office of the Secretary of the Commission 79/05/16 200.
- 7906260261 Summary of 790511 meeting in Washington DC re NEPA regulations Approved revision of proposed ltr to CEG recanditions for NRC compliance w/NEPA regulations.

  CHILK, 8 J Office of the Secretary of the Commission 79/05/14 ip
- 7906260266 Summary of 790510 briefing in Washington.DC re ongoing & planned NRC actions on TMI-2 incident CHILK.S J Office of the Secretary of the Commission. 79/03/14
- 7406260274 Summary of 790507 bristing in Washington DC re SECY-79-88 b NRC options on certain provisions of U Mill Tailings Radiation Control Act of 1978.
  CHILK-S J. Office of the Secretary of the Commission. 79/05/11

- 7905260279 Summary of 790508 discussion in Hashington.DC relitrs to governors Approved proposed litrs to governors of status wifixed nuclear facilities relemengency radiological planning CHILK.S J. Office of the Secretary of the Commission 79/05/15
- 7906260285 Summary of 790508 briefing in Washington,DC re objectives 8 organization of interagency radiological assistance program response to TMI-2 incident CHILK.8 J Office of the Secretary of the Commission 79/05/09
- 7906260303 Summary of 790503 meeting in Washington,DC re revisions to draft FR notice announcing promulgation of final fuel cycle S-3 rule CHILK.S J Office of the Secretary of the Commission 79/05/04
- 7706260313 Bummary of 770503 brisfing in Washington, DC re offsite radiological levels at TMI-2 Identification requested of potential contractors to perform monitoring CMILK.8 J Office of the Becrotary of the Commission 79/05/07
- 7706260316 Summary of 770502 discussion in Washington.DC rechanges to draft FR notice announcing promulgation of final fuel cycle S-3 rule CHILK.S J Office of the Secretary of the Commission 77/05/04
- 7906260335 Summary of 790502 briefing in Washington, DC re steam generator denting & replacement Special attention given to problem at Surry, but no action taken CHILK.S J Office of the Secretary of the Commission 79/05/09 ip
- 7905260345 Summary of 790501 briefing in Washington DC re resident inspector program Performance appraisal & projected FYBO cost analysis requested CHILK-8 J Office of the Secretary of the Commission 79/05/02
- 7906260330 Summary of 790430 meeting in Washington.DC re extension of interim fuel cycle rule NRC voted to extend rule through 790513 CHILK.S J Office of the Becretary of the Commission 79/05/01
- 7906260357 Summary of 790430 affirmation session in Washington, DC reappointment of JR Yore to part-time position on ASLB Grossman to full-time position on ASLB CHILM.S J Office of the Secretary of the Commission 79/05/02
- 7906260366 Bummary of 790426 continuing briefing in Washington, DC restate emergency proparedness activities for nuclear plant accidents
  CHILK'S J Office of the Becretary of the Commission 79/04/30
- 790526U371 Summary of 790426 briefing in Washington DC restatus of plants shut down 790313 to permit seismic reanalysis of piping sys CHILK/S J Office of the Secretary of the Commission, 79/04/30
- 790626U376 Summary of 790425 briefing by Study Group on Const in Maskington, DC re-funding of proposal for gathering of views of participants in ASLB cases
  CHILK, S. J. Office of the Secretary of the Commission, 79/05/07, 1p
- 7906260381 Summary of 790425 briefing by Ofc of State Programs in Washington, DC re current emergency preparedness programs. CHILK: S. J. Office of the Secretary of the Commission 79/04/30 1p
- 7906260396 Summary of 790425 briefing w/UCS.SMUD & Duke Power Co in Washington.DC restatus of operating B&W reactors CHLLK.5 J. Office of the Secretary of the Commission 79/04/27 in
- 7906260389 Summary of 790423 briefing in Washington, DC recurrent status of operating B&W reactors.

  CHILM.S J. Office of the Secretary of the Commission, 79/04/27
- 7906260393 Summary of 790420 briefing in Washington, DC re procedures for qualifying reactor operators CHILK.8 J. Office of the Secretary of the Commission, 79/04/30 2pp

- 790626U396 Summary of 790419 Affirmation Session 79-8 in Washington,DC re Kranish FOIA Appeal 79-A-3 (SECY-79-207) & appointment of HW Lewis to ACRS Kranish appeal denied CHILK,S J. Office of the Secretary of the Commission 74/04/20 206
- 7906250399 Summary of 790419 briefing in Hashington, DC re NRC activities involving gathering & analyzing data significant for operational safety CHILK:S J Office of the Secretary of the Commission 79/05/04 ip
- 7906260405 Summary of 790418 meeting in Washington, DC re updating requirements for physical protection sys for fuel cycle facilities
  CHILK, S J Office of the Secretary of the Commission 79/05/01

## ACRS ADVISORY COMMITTEE ON REACTOR SAFEQUARDS

- 7906040220 Notice of ACRS Subcommittee on Consideration of Class 9 Accidents 790404 meeting w/consultants & NRC in Washington, DC to discuss role of Class 9 accidents in licensing process HOYLE,J C ACRS - Advisory Committee on Reactor Safeguards 79/03/14 2pp
- 7904040189 Transcript of ACRS Subcommittee on Safeguards & Security 790823 meeting in Washington.BC Pp 1-47 BIESB.C P. MATHIS.W H. MARK.J C. ACRS Advisory Committee on Reactor Safeguards 79/05/23 148pp
- 7906150442 Gummarizes responses to IE Bulletin 79-06A, "Review of Operational Errors & Sys Misalignments Identified During TMI Incident "
  TAM.P ACRS Advisory Committee on Reactor Safeguards 79/05/07 10pp
- 7906180003 Summarizes responses to IE Bulletin 79-08. "Events Relevant to Boiling Mater Power Reactors Identified During TMI Incident"
  TAM: P ACRS Advisory Committee on Reactor Safeguards 79/05/09
- 7706220186 Summarizes responses to IE Hulletin 77-069 Operating manuals are being scrutinized Operational personnel are being trained Radioactive gases & liquids transfer lines are interlocked w/containment isolation &/or radiation signals.

  TAM.P Division of Site Safety & Environmental Analysis. 79/05/08 Sna
- 7906230056 Recommends consideration be given by NRC re establishment of quantitative safety goals for nuclear power reactors.

  CARBONIM H ACRB Advisory Committee on Reactor Safeguards
- 7906250474 Summary of 790104-05 meeting w/NRC in Washington.DC re NRC safety research program.evaluation of seismic design margins, subjoena by ASLB: request for review of LERs & testimony on waste mgt App enc!
  CARBON.M W. PLEBSET.M S. ETHERINGTON.H ACRS Advisory Committee on Reactor Safeguards 79/04/12 250pp.
- 7706260542 Transcript of 770602 ACRS subcommittee meeting in Washington DC re reliability & probabilistic assessment OKRENT, D. MARK.J C. KERN.H. ACRS Advisory Committee on Reactor Bafeguards 77/06/02 255pp
- 7906260569 Summary of 790307 meeting w/ACRE Subcommittee on Reactor Safety Research in Hashington.DC re preparation of 1979 Rept to Congress on NRC safety research OKREMT.D. ETHERINGTON.H. LAWROSKI.B ACRS Advisory Committee on Reactor Safeguards 79/04/05 11pp
- 7906260978 Summary of LER Subcommittee 790207 meeting in Washington, DC re ACRS raview of LERs for 1976-78 4 ACRS Advisory Committee on Reactor Safeguards. 79/02/07. Spp
- 7906260632 Comments on NRC licensing review of structural conditions in vicinity of plant Bits does not seem to have active faulting PHLBRICK.B S Affiliation Unknown 79/04/07, ip
- /906260637 Notifies of willingness to assist Reliability Subcommittee of LER Evaluation Program re ECCS valve failure rate analysis.

  REETHOF, 0 Pennsylvania State Univ 79/04/02. ip.

- 7906270003 Forwards comments on analysis of adequacy of reactor pressure vessel noticle safe replacements Concurs w/NRC decision permitting resumption of operators Cannot make determination on allegation of falsifying info BUSH.S H Battelle Memorial Institute, Pacific Northwest Laboratory 79/04/17 3pp
- 7905270242 Summary of 790411-12 Denver workshop re rewet phenomena CATTON. I ACRS Advisory Committee on Reactor Safeguards. 79/05/01 2pp
- 7904270243 Comments on recent ACRS meeting presentation lacked organization thoroughness & visual aids ALLEMANN,R T Battelle Memorial Institute, Pacific Northwest Laboratory 79704/09 2pp
- 7906270245 Forwards midgear review of Super Sys Code for LMFBRs Much of work is being done in duplicate Suggests more attention be given to natural convection phenomena in low Prandtl California, Univ of Los Angeles 79/03/23 2pp
- 7906280023 Summary of ACRS Subcommitte on WH Zimmer Nuclear Power Station. Unit I 790227 meeting w/util.QE, S&H, Conner, Moore & Corber & Ace Federal in Mashington, DC re util application
  - \* ACRS Advisory Committee on Reactor Safeguards 79/03/10 59pp.
- 790A290173 Summary of ACRS Subcommittee on Regulatory Activities 790i03 meeting in Washington DC re proposed reg guide, revisions to aristing reg guides & other matters pertinent to activities affecting licensing process

  ACRS Advisory Committee on Reactor Safeguards 79/02/09 20pg
- 7906290175 Summary of ACRS Subcommittee on ECCS 790116 meeting in Washington-DC re issues related to ECCS

  \* ACRS Advisory Committee on Reactor Safeguards 79/03/07 20pp
- 7906290647 Transcript of ACRS subcommittee meeting on reactor operations power level increase Pp 1-255 ETKERINGTON.H, MATHIS.H ACRS Advisory Committee on Reactor Safeguards 79/06/13 256pp
- 7906290655 Transcript of ACRS subcommittee 790612 meeting in Washington DC re reactor fuel Pp 254-404
  SHEMMON.P 9 . ETHERINOTON.H . MARK.J C, ACRS Advisory Committee on Reactor Safeguards 79/06/12 150pp
- 7906270663 Transcript of ACRB subcommittee 790611 meeting in Mashington: DC re reactor fuel Pp 1-253 SHEWMON.P G . ETHERINOTON.H . KARK.J C ACRB Advisory Committee on Reactor Bafeguards 79706/11 234pp
- 7905270759 Summary of 790306 meeting w/NRC.B&N & Bechtel in Washington, DC re review of proposed reg guides & revisions to existing reg guide4

  # ACRS - Advisory Committee on Reactor Safeguards 79/04/04 21pp
- 7906290763 Forwards memo on ACRS ECCS Subcommittee 790319-20 meeting in Los Angeles. CA WUT Y California Institute of Tachnology 79/04/23 5pp
- 7906290811 Minutes of ACRS 790309 meeting re committee 790417 recommendations, topics arising from TMI accident, procedures for handling OL & CP reviews, license for Bequoyah & addipostulated scenarios

  \*\* ACRS Advisory Committee on Reactor Sefeguards 79/05/10 1p
- 7906290843 Summary of 790328 visit to Shoreham site re methods of support for suppression pool vents, CATTON, I California, Univ of, Los Angeles 79/04/30 ip
- COMMISSION NRC COMMISSIONERS

i j

- 7904040065 Forwards rept on number of full-time permanent employees hired & promoted by NRC during first quarter FY79 Rept submitted per Energy Reorganization Act of 1974, Title II HENDRIE, J M Commission. 79/03/19 4pp.
- 7905290465 Comments on H R, 2 & H R, 65 (Bunset bills) HENDRIE, J M Commission 79/03/16 1p
- 7905300552 Informs of completion of NRC assessment of programs in support of congressionally-directed initiatives Requests approval of initiatives in encl FY79 budget HENDRIE, J. M. Commission 79/04/26, 15pp.

- 7906020041 Responds to 790129 ltr of concern re 790128 transportation accident near Monteagle, TN Requests NRC investigation Under existing regulations neither NRC nor DDT is responsible for prescribing specific routes M/supporting documentation HENDRIE, J M Commission 79/03/07 7pp
- --7906020083 Forwards revised memo of understanding between NAC & DOT for safety regulation in transportation of radioactive matls DIRCKS.H J Office of Nuclear Material Safety & Safeguards 79/03/02 13pp
- 7906050008 Heekly info rept for week ending 790504 REHM.T A Office of the Executive Director for Operations 79/05/09 25pp
- 7906070064 Comments on recent meeting re China Will forward comments on speech after careful study KENNEDY.R Y Commission 79/04/04 1p
- 7906070067 Confirms withdrawal from participation in Hamburg, Oarmany conference, due to time demands of TMI incident KENNEDY, R T Commission 79/04/23 ip
- 7908070070 Forwards RT Kannedy 790328 speech in Washington, DC W/o engl KENNEDY, R T Commission 79/05/15 ip
- 7906070074 Forwards RT Kennedy 790226 speech in Tucson AZ & 790320 speech in Hashington DC W/o enci KENNEDY R T Commission 79/05/15 ip
- 7906070078 Notifies of inability to attend & participate in seminar on energy & nat1 security
  KENNEDY.R T Commission 79/05/14 1p
- 7905070082 Forwards RT Kennedy 790514 memo re SECY-79-320, technology transfer to Brazil KENNEDY,R T Commission 79/05/16, 1p
- --7906070084 Comments on SECY-79-320 rs technology transfer to Bratil questions statutory & factual basis for NRC statement that transfer is not consistent w/administration policy re Hest German/Bratilian pilot enrichment plan KENNEDY, R T Commission 79/05/14, 2pp
- 7704070084 Ack receipt of photo of of: & test eite KENNEDY,R T Commission 79/03/28 ip
- 7906070088 Recommends 1980 conference be held at Doubletree Inn. 7060740000 necommends
  Scottsdale.AZ

  GENERALE.AZ

  GENERAL
- 7906070092 Ack receipt of "Strategic Options for Early 80's." by Van Cleave & Thompson KENNEDY,R ↑ Commission 79/04/02 1p
- 7906070093 Requests views on various questions re pending license applications covering exports destined for Taiwan KENNEDY, R. T. Commission 79/04/03 ip
- 7906070096 Ack receipt of monograph on natl security affairs, w/sections on Spanish bases, Iran & Congo KENNEOV, R T Commission, 79/04/04, ip
- 7906070097 Accepts invitation to attend 790427 seminar at Army/Navy KENNEDY, R. T Commission 79/04/04 1p.
- 7906070102 Ack receipt of update on successful sea trials of USB Indianapolis KENNEDY: R T Commission 79/04/09 ip.
- 7906070106 Regrets inability to meet w/J Hill during recent visit to KENNEDY.R T Commission 79/04/18, 1p
- 7904070107 Ack receipt of 790501 ltr which reviewed remarks of 790328 KENNEDY, R T Commission 79/05/11 1p
- ---7906070110 Comments on RT Kennedy's remerks of 790328 SKITH-0 State-Dept of 79/05/01 1p
- 7905070287 Commends decision to close several nuclear power plants WEISEL,H A Affiliation Unknown 79/03/06 ip

- 7906070289 Expresses congratulations for honor received for work on desegragation
  KENNEDY:R T. Commission 79/05/10 1p
- 7906070293 Notifies of inability to attend Adelphi Univ Conference on Energy & Environ KENNEDY:R T. Commission 79/04/24 ip
- 7906070294 Ack receipt of info re Natl Strategy Info Ctr work on SALT KENNEDY.R T. Commission 79/05/03 ip
- 7906070297 Commends action taken re closing of nuclear reactor KNOTT.M. Affiliation Unknown 79/05/10 ip
- 7906110300 Ack receipt of 790413 ltr re radiation exposure of nuclear plant workers Forwards SECY-78-415.1977 Annual Rept on Occupational Radiation Exposure & FR notice re stds for radiation protection HENDRIE.J M Commission 79/05/18 3pp
- --790511030? Forwards R Nader & 8 Holfe 790413 ltr re radiation exposure of nuclear plant workers. Requests updated info & NRC views on subj Concerped over careless attitude towards worker health due to lack of radiation—level std for plants WAMMN. H A House of Rep , Interstate & Foreign Commerce 79/04/13 5pp
- 500pp
- 7706110319 Forwards NRC response to GAO rept EMD-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight" HENDRIE: J M Commission 79/05/15 1p
- --7906i10323 Forwards NRC response to QAO rept EMD-79-16, "Reporting Unscheduled Evants at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight" HENDRIE, J. M Commission 79/05/15 ip
- --7905110332 Forwards NRC response to QAD rept EMD-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight "HENDRIE, J. M Commission 79/05/15 ip
- --7906110335 Forwards NRC response to GAO rept EMD-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight" HENDRIE: J H Commission 79/05/15 ip
- ---7906110336 Forwards NRC response to GAO rept EMD-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight "
  HEMDRIE, J M Commission 79703/13, ip
- --7906110338 Forwards NRC response to QAO rept EMD-79-16, "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight."
  HENDRIE, J. M. Commission 79/05/15, ip
- --7706110341 Forwards NRC response to GAO rept EMD-77-16. "Reporting Unscheduled Events at Commercial Nuclear Facilities Opportunities to Improve NRC Oversight" HENDRIE, J. M Commission. 77/05/15 ip
- 7906200283 Weekly info rept for week ending 790511. REHM.T.A Office of the Executive Director for Operations 79/05/16 GOpp
- 7906270107 Requests support for legislation re effective date provision of U Mill Tailings Radiation Control Act of 1978 Forwards draft statutory language which would eliminate duplication of licensing authority & section-by-section analysis HENDRIE: J M. Commission. 79/05/30 8PP
- 7906270116 Requests support for legislation re affective date provision of U Mill Tailing Radiation Control Act of 1978 Forwards draff statutory language eliminating duplication of licensing authority & section-by-section analysis W/o encl HENDRIE.J M Commission 79/05/30 ip
- 7906270123 Requests support for legislation re effective date provision of U Hill Tailing Radiation Control Act of 1978, Forwards draft statutory language which would eliminate duplication of licensing authority, W/o encl HENDRIE, J. M. Commission. 79/05/30, 1p,

- 7906270129 Requests support for legislation re effective date provisio, of U Mill Tailings Radiation Control Act of 1978 Forwards draft statutory language which would eliminate duplication of licensing authority W/o encl
  HENDRIE: J M Commission 79/05/30 ip
- 7906270133 Requests support for legislation re effective date provision of U Mill Tailings Radiation Control Act of 1978 Forwards draft statutory language which would eliminate duplication of licensing authority M/o and HENDRIE, J M Commission 79/05/30 1p
- 7906270144 Submits correction to 790507 testimony before Subcommittee on Energy, Nuclear Proliferation & Federal Svcs Firsthand insp repts were from regional inspectors, not resident inspector Intensity of inspectfort was equal HENDRIE, J M Commission 79/05/31 2pp
- 7906270150 Ack receipt of 790516 request for certain routine documents 1/2 reporting eves used internally by NRC C Kammerer is making arrangements for delivery of documents HENDRIE: J M Commission 79/05/31 1p
- --7906270157 Requests regular receipt of certain routine documents & reporting svcs used internally by NRC.so that Environ.
  Energy & Natural Resources Subcommittee can be kept abreast of NRC developments
  MOFFETT, T House of Rep., Oovernment Operations. 79/05/16 ip
- 7906270163 Ack receipt of 790316 ltr re transportation of waste matls Forwards description of NRC & DOT requirements for transportation of radioactive matls, NUREG-0170 & rept on transportation accidents from Jan 1979 to Feb 1979 HENDRIE, J M. Commission. 79/05/25 3p
- --770627016B Requests detailed rept outlining exact requirements of NRC in transportation of nuclear wastes & rept outlining locations & details of 22 accidents which have occurred GASER, J Senate 79/03/16. Sipp
- --7906270173 NUREG-0170 VI NUREG-0170.Vol 1. "FES on Transportation of Radioactive Matl by Air & Other Hodes " + Office of Standards Development 77/12/31 150pp.
- --7906270177 NUREO-0170 V2 NUREO-0170, Vol 2, "FES on Transportation of Radioactive Mat1 by Air & Other Modes" \* Office of Standards Development 77/12/31 225pp
- 7706280244 Responds to 770328 1tr re physical security & safeguard measures for handling shipments of highly enriched U Forwards proposed changes to 100FR70, 73 & 150 HENDRIE J. H Commission 79/05/25 29pp
- --7906280249 Requests addl & updated info re physical security & safeguard measures for handling shipments of highly enriched U.in light of deficiencies revealed in incident involving damaged seals on shipment to Romania.

  ZABLOCKI.C.J House of Rep : Foreign Affairs. 79/03/28 3pp
- 7906280251 Responds to questions in 780918 ltr re applicability or Price-Anderson Act to proposed waste isolation pilot plant under various conditions of operation Addresses only NRC authority under Price-Anderson Act HENDRIE. J. M. Commission. 79/05/25 9pp.
- ---7906280254 Requests NRC opinion on applicability of Price-Anderson Act to proposed waste isolation pilot plant under various operating conditions Facility to be built near Carlsbad, NM DINOELL, J D House of Rep. . Interstate & Foreign Commerce 78/09/18 ip
- 7906280237 Responds to 790329 ltr which forwarded JM Jones 790321 ltr. Comments on limited appearance statements at public hearing conducted by NRC in Salem County, NJ re licensing of nuclear waste storage facility HENDRIE, J M Commission 79/05/23 2pp.
- ---7906280261 Forwards JM Jones 790321 1tr commenting on manner in which public hearing was conducted by NRC in Salem County, NJ HUOHES W J House of Rep. 79/03/29 2pp.
- 7706280264 Responds to 770330 ltr re use of synthetic aperture radar in locating potential power plant sites. NRC has not used such techniques; but does use others such as infrared films taken from aircraft platforms & multispectral images
  HENDRIE; J M Commission 79/05/23 ip.

ħ,

- --7906280266 Requests info re use of synthetic agenture radar in locating potential sites for nuclear power plants DECONCINI, D. Senate 79/03/30 ip
- CONTRACT NRC CONTRACTS AND MODIFICATIONS
- 7906020169 Notification of contract execution.Mod 1, to "Add1 Logistica! Support for Stanislaus Nuclear Project, Unit 1, Antitrust Hearings "Contractor PGAE" HIGGINS, E. J. Division of Contracts NRC-10-78-604 79/05/09
- --7905020172 Mod 1, including transportation charges for items to be delivered under "Add1 Logistical Support for Stanislaus Nuclear Project, Unit 1, Antitrust Rearings "MATTIA, M J Division of Contracts BENTON, R P Pacific Gas & Electric Co NRC-10-78-604 79/04/11 ip
- 7906050001 Notification of contract execution.Mod 7.to "Analysis of Hypothetical Accidents Resulting in Core Meltdown " Contractor Battelle Columbus Labs NYNATT.H A. Resparch Contracts Branch FIN A-4067 NRC-04-076-293 78/12/02 ap
- ---7706050002 Mod 7.4dding funded period of performance to "Analysis of Hypothetical Accidents Resulting in Core Meltdown" HORTON,K V Research Contracts Branch FIN A-4067 NRC-04-076-293 79/04/17 2pp
- 790&070349 Notification of contract execution. Hod 2 to "PDR Micrographic Stolage & Retrieval Sys " Contractor ACCESS Corp MEDROW. L Administrative Contracts Branck NRC-17-79-449 79/04/20 1p
- 7906070352 Mod 2, extending term of contract & delaying original installation date by 30 days, to "PDR Micrographic Storage & Retrieval Sys"
   MATTIA.M J Administrative Contracts Branch NRC-17-79-449 79/04/09
- 7906130072 Notification of contract execution: "Bys Maint Programming,"
  Awarded to SBA, prime contractor & Rehab Group, Inc.
  \*\*subcontractor\*\*
  HAGAN, T F Administrative Contracts Branch NRC-10-79-375
  79/05/01, ip
- --7906130076 Contract "Sys Haint Programming," awarded to SBA,prime contractor & Rehab Group, Inc. subcontractor MATTIA, M J Administrative Contracts Branch NRC-10-79-375 79704/02 16pp
- 7906130078 Notification of contract execution "Transcription of TMI Tapes," awarded to Neal R Gross & Co.Inc WIGGINS,E J Administrative Contracts Branch NRC-10-79-400 79/09/17 1p
- ---7906i30084 Contract. "Transcription of TMI Tapes," awarded to Neal R Gross & Co.Inc. MATTIA:M J Administrative Contracts Branch NRC-10-79-400. 79/05/18 52pp
- 7906130086 Notification of contract execution Mod Bito "Operation & Maint of Technical Assignment & Control Bys (TACS) "
  Contractor Genasus Corp
  MEDROW, L.A. K Administrative Contracts Branch, NRC-07-77-110.
  79/03/15. 1p.
- --7906130091 Mod 8, increasing estimated hours & calling amount to "Operation & Haint of Technical Assessment & Control Sys (TACS)."

  HATTIA,M J Administrative Contracts Branch NRC-07-77-110 79/05/15 2pp
- 7906140186 Notification of contract execution: "Survey Instruments," awarded to Eberline Instrument Corp.
  MEDROW.L.A Administrative Contracts Branch FIN B-1215
  NRC-05-79-262. 79/04/06 ip
- --7906140208 Contract "Survey Instruments," awarded to Eberline Instrument Corp HATTIA:M.J Division of Contracts, FIN B-1215, NRC-08-79-262 79/04/06 355p
- 7906150123 Notification of contract execution. Mod 7 to "Consultant Byc in Connection W/Antitrust Hearing," Contractor:CH2M Hill: Inc.
  HENCZER. M. B Technical Assistance Contracts Branch. FIN 8-5002, 79/05/09. ip.

- --7906150125 Mod 7.closing out contract for "Consultant Syc in Connectic W/Antitrust Hearing" DOUGHERTY, D J Technical Assistance Contracts Branch FJN B-5002 AT(49-24)0080 79/05/08 Ip
- 7906190130 Notification of contract execution.Mod 1 to "Implementation & Operation of NRC Document Control Bys " Contractor TERA Advanced Bycs Corp MATTIA,M J Administrative Contracts Branch NRC-10-78-580 79/04/25 ip
- --790&150133 Mod 1.providing add1 equip & performance requirements & administrative changes to "Implementation & Operation of NRC Document Control Sys" HATTIA.M J Administrative Contracts Branch NRC-10-78-380 NRC-10-78-580 79/01/29 9pp
- 7906150152 Notification of contract execution "Technical Assistance in Development of Regulatory Framework for Nuclear Wasts Mgt." awarded to ANCA Ltd LEBD.C D Technical Assistance Contracts Branch NRC-02-77-201-45 79/05/08 [p
- --7906150155 Contract "Technical Assistance in Development of Regulatory Framework for Nuclear Waste Mgt," awarded to ANCA Ltd DOUGHERTY,D J Technical Assistance Contracts Branch NRC-02-77-201-45 79/05/08 15pp
- 7906150159 Notification of contract execution Mod 10 to "Document Distribution" Contractor Computer Data Sys. Inc HA0AN. T F Administrative Contracts Branch NRC-10-78-399 79/04/09 ip
- --7906150161 Mod (O,changing contractor name from Electronic Composition, Inc. to Computer Data Bys, Inc. to "Document Distribution" MATTIA,M J Administrative Contracts Branch NRC~10-70-399 79/04/09 tp
- 7906150163 Notification of contract execution.Mod 2 to "Electrostatic Copying Svc " Contractor Literature Research Co-HIGOINIS.E Administrative Contracts Branch NRC-10-78-361 79703701 ip
- --7906190169 Mod 2 increasing funding to "Electrostatic Copying 8vc " HATTIA M J Administrative Contracts Branch NRC-10-79-361 79/05/01 is
- 7906190171 Notification of contract execution "Expansion of Reliability Data Manual." awarded to IEEE HOLLETT.S A Research Contracts Branch FIN 8-6708 NRC-04-79-187 79709708 ip
- --7906150175 Contract "Expansion of Reliability Data Hanual," awarded to IEEE MORTON, K.V. Research Contracts Branch FIN 8-6708. NRC-04-79-187 79/03/28 6pp.
- 7706160027 Notification of contract execution. "Cataloging Support Byr." awarded to Informatics.Inc HAGAN, T F Administrative Contracts Branch NRC-10-79-362 NRC-10-79-362, 79/05/02 ip
- --7906160030 Contract "Cataloging Support Syc," awarded to Informatics: Inc MATTIA.M.J Division of Contracts, NRC-10-79-362 NRC-10-79-362 79/04/24 3pp
- 7906160032 Notification of contract execution, Mod 6, to "Tethnical Assistance/Bafaguards Suppl to OESMO," awarded to Lulejian & Associates; Inc.
  LEBD, C D Technical Assistance Contracts Branch FIN 8-1527
  AT(49-24)-0326, 79/03/22, ip.
- --7706160035 Mod 6.decreasing amount obligated to "Technical Assistants/ Safeguards Suppl to GEBMO"
  DUUGHERTY.D J. Division of Contracts FIN B-1527.
  ATC49-241-0326. 79/05/04 ip.
- 7906160038 Notification of contract execution. "Verification of Exentential Technique for Stability Calculations," awarded to Nuclear Associates Intl.
  MENCZER.H B Technical Assistance Contracts Branch. FIN 8-6905 NRC-03-79-150, 79/05/01 ip

- --7906160040 Contract "Varification of Exxon Tachnique for Stability Calculations," awarded to Nuclear Associates Intl DOUGHERTY, D. J Division of Contracts FIN 8-6805 NRC-03-79-150 79/05/01 6pp
- 7906180042 Notification of contract execution, Nod 3 to "Keypunching & Verification Svc " Contractor Intl Business Svc, Inc WIGGINS, E Administrative Contracts Branch NRC-10-77-071 NRC-10-77-071 77/05/02 ip
- 7906180049 Mod 3 extending period of performance to "Keypunching & Verification Svc "
  MATTIA.H J Division of Contracts NRC-10-77-071 79/04/26
- 7904180282 Notification of contract execution "Implementation of Executive Development Program." awarded to Project Associates.Inc PERLYAN.J. Purchasing Section NRC-10-79-368 79/05/07 ip
- --7906180288 Contract "Implementation of Executive Development Program,"
  awarded to Project Associates, Inc
  HARGETT, D. J. Division of Contracts NRC-10-79-368 79/05/09
- 7906180426 Forwards "Electrical & Instrumentation Technology & Codes Training program," Progress Rept 12 for Mar 1979 HALTON.R F Ebasco Services, Inc (subs of Enserch Corp) KRC-05-78-301 79706/12 1p
- --7706180433 "Electrical & Instrumentation Technology & Codes Training Program," Progress Rept 12 for Mar 1977 \* Ebasco Services, Inc (subs. of Enserch Corp.) NRC-05-78-301 79/06/12 3pp
- 7906180581 Notification of contract execution, Mod 1 to "Sys Maint Programming " Contractor Intl Business Sycs, Inc HAGAN, T F Administrative Contracts Branch NRC-10-79-372 79/04/24 1p
- ---7906180590 Mod 1,definitizing ceiling loaded rates to "Sys Maint Programming" • Division of Contracts NRC-10-79-972, NRC-10-79-372 79/04/20 3pp
- 7706180597 Notification of contract execution, Mod 1 to "Radioactive Matl Transportation " Contractor Univ of Denver HIGGINS, E Administrative Contracts Branch NRC-04-78-361 NRC-04-78-361
- --7906180606 Mod 1.extending period of performance to "Radioactive Matl Transportation" \* Division of Contracts NRC-06-78-361 NRC-06-78-361 79/04/13 2pp
- 7905180738 Notification of contract execution "Transfer of Multi-Channel Tapes to 30-Minute Cassettes." awarded to Dictephone Corp MATIJA, M J. Administrative Contracts Branch NRC-10-79-398 79/05/01. ip.
- --7906180744 Contract: "Transfer of Multi-Channel Tapes for 30-Minute Cassettes," awarded to Dictaphone Gorp MATTIA:M U Administrative Contracts Branch NRC-10-79-398, 79/09/01 10pp
- 7906:8075: Corrected notification of contract execution: "Transfer of Multi-Channel Tages to 30-Minute Cassettes," awarded to Dictaphone Corp.
  MATTIA: M J Administrative Contracts Branch. NRC-10-79-398 79/05/01. ip
- 7906190176 Notification of contract execution "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Wasts Mgt." awarded to Southwest Research Inst LEBO.G D. Technical Assistance Contracts Branch. NRC-02-77-201-46 NRC-02-77-201-4 79/05/17. 1p
- ---7906190181 Contract: "Basic Ordering Agreement to Develop Regulatory Framework for Nuclear Waste Mgt." awarded to Bouthwest Research Inst, BOUOHERTY, D. J Division of Contracts. NRC-02-77-201-46 79/05/17. 15pp.
- 7905230335 Notification of contract execution: "Implementation of ATMS Recommendations on Std Plant Designs," awarded to M Colay, PERLMAN.J., Purchasing Section, NRC-03-79-144, 79/05/17 ip

- --7906250336 Contract "Implementation of ATWS Recommendations on Std Plant Designs," awarded to M Golay HARGETT, D J Division of Contracts NRC-03-79-144 79/05/17. 5pp
- 7906230337 Notification of contract execution "Design of Integrated Financial Mgt Info Sys." awarded to Small Business Administration HAGAN.TF Administrative Contracts Branch NRC-09-79-349 790/05/17 to
- ---7906250340 Contract "Design of Integrated Financial Mgt Info Sqs." awarded to Samil Business Administration WATSON.C Division of Contracts NRC-09-79-349 79/05/17 1100
- 7906260123 Notification of contract elecution, Mod 1 to "Assessment of Mill Tallings Impoundment Diversion Ditches & Flood Protection "Contractor Water & Environ Consultants, Inc PERLMAN, J Purchasing Section NRC-02-79-021 79/05/17 1p
- --7906260130 Mad 1.extending period of performance to 790424, to
  "Assessment of Kill Tailings Impoundment Diversion Ditches &
  Flood Protection"
  HARGETT, D J Division of Contracts NRC-02-79-021, 79/09/02
- 7906260135 Notification of contract execution "Review of Slip Rate Versus Magnitude Study," awarded to D Blemmons PERLMAN,J Purchasing Section NRC-03-79-146 79/05/17 1p
- ---7906260140 Contract "Review of Slip Rate Versus Magnitude Study," awarded to D Siemmons.

  HARGETT, D J Division of Contracts NRC-03-79-146 79/05/17
- 7906270086 Notification of contract execution, Mod 4 to "PWR Vortex Technology " Contractor Univ of IA MENCZER, H B Technical Assistance Contracts Branch NRC-03-78-130 79/05/24 1p
- --7906270087 Mod 4 extending contract two months at no addl cost & changing reporting requirements to allow for incorporation of NRC comments into final rept to "PMP Vortex Technology "
  DOUGHERTY, D Division of Contracts NRC-03-78-130 79/05/24
- 7906270092 Notification of contract execution Mod 7 to "Bys/Project Maint Programming " Contractor Bmail Business Administration Subcontractor Rohab Group, Inc MCDRGM, L A Administrative Contracts Branch, NRC-10-77-183, 883-4-4-8(A)-77 79/05/14 1p.
- --7906270076 Mod 7,increasing ceiling price % amount obligated for performance of "Bys/Project Maint Programming " MATTIA.H J Division of Contracts NRC-10-77-153 BB3-4-4-8(A)-77 79/03/30 2pp.
- 7906270100 Notification of contract execution "Course on 'Preconditioning Interim Operating Mgt Recommendations (PCIOMR)/Process Computer Software fo BWR'," awarded to OE PERLMAN, J Purchasing Section NRC-05-79-260 79/03/21 1s

- 7904010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41, info on selsmic issues prepared for systematic evaluation program & insp repts for Beaver Valley Units WEISG.E R Sheldon. Harmon & Roisman 79/03/19. 2pp
- 7906010118 FOIA request by UCS for all documents re Task Action Plans A-40 & A-41.info on saismic issues prepared for systematic evaluation program & insp repts for Beaver Vailey units WEISB.E R Sheldon, Harmon & Roisman 79/03/19. 2pp
- 790601011B FOIA request by UCS for all documents re Task Action Plans A-40 & A-41.info on seismic issues prepared for systematic evaluation program 8 insp repts for Beaver Valley units WEISS.E R Sheldon. Harmon & Roisman. 79/03/19 2pp
- 7906010121 Responds to 790319 FDIA request re seismic issues SECY-77-361. "Systematic Evaluation of Operating Reactors, Phase I & II." is now available in PDR FELTON, J M Division of Rules and Records 79/05/17 [p
- 7906010125 SECY-77-361

  Reviews Phase I of systematic evaluation program to obtain approvel to proceed w/Phase II of plant-specific review Recommends NRC approve continuation of program plan CASE.E 0 Office of Nuclear Reactor Regulation 77/10/26 47pp
- 7906010127 Provides guidance on systematic svaluation program for operating reactors NRC approves objectives & general approach of program described in SECY-76-545 CHILKIS J Office of the Secretary of the Commission 77/01/27 2pp
- 7906010179 SECY-77-539
  Advises Commissioners of plans to convert provisional OLs to full-term licenses
  CASE/E O Office of Nuclear Reactor Regulation 77/10/14 5pp.
- 7905010246 Responds to FOIA request re equipment mentioned in 790502 ltr NRC has no records relevant to this request FELTON, J M Division of Rules and Records 79/05/11 1p
- 7906010249 FOIA request for info re equipment TM 5-6115-230-10 & HOL-GAR Mode) CE 600-A/C E/O DELILLO.J Affiliation Unknown 79/05/02 2pp
- 7906010295 Responds to 790507 FDIA request Provides final award amounts of Mt Sinai & George Washington Univ Contract NRC-01-78-018 FELTON.J M Division of Rules and Records 79/05/18 1p
- 7906010258 FOIA request for info re final award amounts of Mt Sinai & George Hashington Univ Contract NRC-01-78-018 & availability of final repts on these programs PARKERBON.L. Kinetic Research. Inc. 79/05/07 iP
- 7908010263 Responds to 790417 FOIA request for copy of winning proposal for Contract NRC-02-79-037 Info partially withheld identification of consultants & qualifications (ref FOIA Exemption 4)
  FELTON.J M Division of Rules and Records. 79/05/18 1p
- 7906010269 Responds to 781219 FOIA request re Edlow Intl export of SNK to India Four documents in PDR Info partially withheld: "Arms Control & Disarmament Agency Draft Disposition of Spent Tarapur Fuel/Storage Aboard US-O
- 7906010270 FOIA request for copy of winning technical proposal for Contract NRC-02-79-037. "Bludy of ALARA for Radiopharmaceutical Manufacturer "RAGANK.K Kinetic Research, Inc 79/04/17 ip.
- 7906050078 Responds to FOIA request for I Bloss 780407 presentation "Hazards to Persons Exposed to Ionizing Radiation (& to Their Children) from Dosages Currently Permitted by NRC."
  FELTON, J. M Division of Rules and Records. 79/05/23 2pp
- --7906050080 "Harards to Persons Exposed to Ionizing Radiation (& to Their Children) from Bosages Currently Permitted by NRC." revised for 780407 presentation to NRC. 8ROSS, D J. Roswell Park Memorial Inst. 79/04/07 34pp.

A Company of the Comp

- 7906050083 F01A request for I Bross (Roswell Hemorial Inst) Apr 1980 presentation of work published as "Tri-State Survey " LANGER, B Affiliation Unknown 79/04/27 ip.
- 7904040004 Responds to FOIA request for info on SL-1 accident & investigation Forwards S Hanauer 710910 memo to C Thornton. FELTON, J. M Division of Rules and Records 79/04/26 11p.

- --790604000B Comments on industrial reactor sabotage internal plant security should be strengthened HANAUER.S H Atomic Energy Commission (Pre 1975) 71/09/10 ip
- 790±040087 Responds to 730713 itr re review of rept BC-TDP-4 on seismic analysis of nuclear plant structures & equipment Submits chronological summary of basic seismic analysis requirements & structural design criteria HENDRIE. J H Atomic Energy Commission. Deputy Director for Technical Review (Pre-1975) 73/09/04 22pp
- --7906060087 Discusses justification for b implementation of recent regulatory positions on seismic analysis of Catagory i structures b components SHAD,L Atomic Energy Commission, Directorate of Licensing (Pre-1975) 79/05/07 5pp
- --7906060095 "Development of Criteria For Seismic Review of Selected Nuclear Power Plants " NEMMARK.N M . HALL.N J N M Newmark Consulting Engineering Services AT(49-24)-0116 77/09/30 58pp
- --7906060102 Proposes that NRC request opinions of ACRS on safety problems resulting from incorrect S&W pipe stress calculations OILINSKY, V Commission 79/03/13 1p
- --7904060105 Confirms 790313 conversation emphasizing desire to be tapt properly informed on matters of regulatory concern KENNEDY:R T Commission 79/03/13 1p
- --7906060112 Requests info re plant seismic-induced piping stress code compliance w/NRC safety requirements during QL issuance KENNEDY, R T Commission 79/03/14 1p
- --7906060117 Forwards vugraphs for PDR re NRC 790313 discussion of seismic design problems in certain plants COMBS,T & Public Document Branch 79/03/15 9pp
- ---7906060120 Forwards responses to 790314 memos from RT Kennedy & EJ Chilk re plant seismic-induced piping stress evaluation during OL application review W/RT Kennedy 790314 memo to LV Gossick

  DENTON, H R Office of Nuclear Reactor Regulation 79/03/15
- --7906060122 Requests info re NRC consideration of plant-specific piping sys in terms of past & present NRC safety requirements & NRC decision to apply recent findings on generic basis.

  KENNEDY.R T Commission 79/03/16 ip
- --7904060130 Ack receipt of 790313 mamo re understanding that each Commissioner is to be promptly advised of any matter of important regulatory concern.

  OOBSIGK.L.V Office of the Executive Director for Operations 79/03/20
- --7906060134 Expresses gratitude for 790320 briefing re seismic disaign Cites competence of three staffers. GILINSKY, V Commission 79/03/20 1p
- ---7906060136 Discusses 790321 conversations w/congressional staff1 repast events affected by S&W pipe stress calculations
  DENTON, H R Defice of Nuclear Reactor Regulation 79/03/21 1
- ---7906060145 Discusses 790320 congressional hearing re B&W calculations! error & subsequent shutdown of five nuclear plants GISBON, T Commission 79/03/20, 2pp
- 906060184 Forwards proposed statement setting forth NRC guidance re FOIA requests which concern TMI Info partially withheld statement (ref FOIA Exemption 5), BICKNIT,L Office of the General Counsel, 77/04/20, ip
- 7906060199 Summary of 790403 press conference held by G McGovern & UCS Forwards McGovern's statement & press release KAMMERER. C Office of Congressional Affairs 79/04/12. 5pp
- 7906070033 Provides INEL amployee radiation exposure history for 600607-780930, Info partially withheld:name, Social Security number & date of birth (ref FUIA Exemption 6) JONES, D. E. Energy, Dept of. 79/04/09 2pp.
- 7906070037 Forwards Fleischaker 790430 FOIA request for documents obtained through civil investigative demend re util proposal to construct Mendocino project.

  GOLDBERO, J. R Anti-Trust Division. 79/05/04. 1p.

- 7906070040 Provides INEL employee radiation exposure history for 760402-790331 Info partially withheld name Social Security number & date of birth (ref FOIA Exemption 6)

  JONES, D E Energy, Dept of 79/04/09 2pp
- 7706070066 Response to FDIA request for all documents re promulgation & possible future revisions of Reg Guide 1 3,Revision 2, & Reg Guide 1 4,Revision 2,both dtd Jun 1974
  FELTON, J M Division of Rules and Records 77/05/15 4pp
- --7906070075 Forwards proposed revision to Reg Guides 1 3 & 1 4 re procedure to use 150-rem thyroid & 20-rem whole body dose during CP review MINOGUE:R B Atomic Energy Commission (Pre 1975) 74/02/22 ip
- --79060700B0 Forwards comments on draft of proposed Reg Quide 1 3, Revision 2.2 Reg Quide 1 4.Revision 2,re assumptions used for evaluating potential radiological consequences of LOC. for BURS, W A Atomic Energy Commission (Pre 1975) 74/03/27 3pp
- --7906070100 Comments on proposed revision to Reg Ouide 1 3 recommends factor of 1 5 be used for short-term events such as accident analysis HINDS, J A General Electric Co 781-021-74 79/04/02 3pp
- --7905070105 Comments on proposed revisions to Reg Guides 1 4 & 1 21.to be considered at ACRS Reg Guide Subcommittee 740410 meeting no technical need exists for proposed revisions & no increased benefits will result

  Duke Power Co 79/04/04 Spp
- --7906070123 Forwards drafts of proposed Revision 2 to Reg Guide 1 3 & Revision 2 to Reg Quide 1 4, ROGERS,L Atomic Energy Commission (Pre 1973) 74/04/19 1p.
- --7906070130 Proposes issuance of eight new reg guides outlining positions developed by AEC on acceptable solutions to safety issues
  ARLOTTO. G A Atomic Energy Commission (Pre 1975) 74/05/01 2pp
- --7906070135 Discusses status of eight reg guide\* transmitted to R Mattson from G Arlotto in 740501 memo Reg Guide 1 3,Revision 2.8 Reg Guide 1 4.Revision 2,are being forwarded for further review JARVIB,S. Atomic Energy Commission (Pre 1975) 74/05/14 lp
- --7706070152 Discusses Revision 2 to Rsg Ouides 1 3 & 1,4 re use of 150-rem thyroid & 20-rem whole body dose during CP review Requests review schedule for proposed rsg guide revisions MINDOUE: R 8 Atomic Energy Commission (Pre 1975), 74/05/15 1
- --7906070138 Forwards Revision 2 to Reg Quides 1 3 & 1 4 re acceptable procedures for using 150-rem thyroid & 20-rem whole body dose during CP review FR notice & draft public announcement encl ROGERS, L. Atomic Energy Commission (Pre 1975), 74/06/18 1p
- --7906070163 Notice of issuance & availability of Reg Quide 1 3.Revision 2.& Reg Quide 1.4.Revision 2.re acceptable procedure for using 150-rem thyroid & 20-rem whole body dose during CP review H/draft public announcement ROGERS, L. Atomic Energy Commission (Pre 1975) 74/06/17 App
- --7906070167 Requests AEC re-evaluation of positions re Reg Guides 1 3, 1 5 \$ 1,25 & issuance of reg guides w/models & conditions consistent w/actual physical phenomena HINDS J. A General Electric Co , Nuclear Energy Products Div 74/07/29 2pp
- ~-7905070178 Comments on Reg Guide 1.3:Revision 2."Assumptions Used for Evaluating Potential Radiological Consequences of LOCA for BHRs." HAYNARD, C J Consumers Power Co, MAYN-75-74 74/09/03 ip
- --7906070188 Requests initiation of change actions to revise Reg Ouides 1 3 % 1 4 to more completely reflect recommended practices for LOCA radiological analyses Forwards draft guide indicating needed changes DENTON: H. R Office of Nuclear Reactor Regulation, 78/07/18
- 13pp.
  ---7906070193 Requests review of draft SECY-78-111A: "Accident Evaluation Practices in Siting & Licensing of Nuclear Power Plants -- Major Issues "
  GOLLER.K.R. Division of Siting: Health & Safeguards Standards
- --7906070329 Summarizes major issues & alternative approaches in current accident evaluation practices in siting & licensing of nuclear power plants

  HIMOGUE, R. Office of Standards Development, 78/09/21 101pp

- --- 7906070334 Requests delay in completion of draft SECY-78-111A until first draft of proposed revision to "General Policy Statement on Nuclear Power Reactor Site Evaluation," SECY-78-371, has been completed DEYOUNG, R C Division of Site Safety & Environmental Analysis 79/10/27 1p
- ---7906070340 "Assumptions Used for Evaluating Light Water Cooled Nuclear Power Plant Siting Distances for Purposes of 10CFR100 " \* Office of Standards Development 79/03/31 10pp
- --7906070348 "Assumptions Used for Evaluating Potential Radiological Consequences to Public from Design Basis Accidents in Light Water Cooled Nuclear Power Plants for Purposes of 10CFR90 & 91 "Value-Zimpact Btatement encl # Office of Standards Development 79/03/31 18pp
- 7904070071 FOIA request for all documents re promulgation & possible future revisions of Reg Ouids 1 3. Revision 2.& Reg Quids 1 4 Revision 2.both dtd Jun 1974 Requests waiver of all fees PERLMUTTER.C 8 Affiliation Unknown 79/03/28 3pp
- 7904070205 Responds to 790417 FOIA request for nonproprietary portion of Basic Ordering Agreement NRC-03-78-131.awarded to Oage-Babcock & Associates FELTON, J M Division of Rules and Records 79/05/11 ip
- 79Q6070216 Denial of FDIA request for TR Gibbon 790314 memo to Commissioner Bradford re oil requirements resulting from shutdown of five nuclear plants & Thompson 790315 memo to Bradford requesting info on TMI incident F
- 7906070222 FOIA request for all info & records re 790313 decision to shut fown five nuclear plants Requests waiver of any production fees associated w/request PLITCH.L H New England Regional Energy Project 79/03/23 1p
- 7906070229 Responds to 790503 FOLA request Forwards SAND-77-1371, "Spent Fuel Heatup Following Loss of Water During Storage." W/o encl FELTON.J M Division of Rules and Records 79/05/13 ip
- 7906070230 FOIA request for BAND-77-1371, "Spent Fuel Heatup Following Loss of Water Storage," dtd Sept 1978
  RYAN.C R Mothers & Others Mobilizing for Survival 79/05/03 1p
- 7906070232 Responds to FOIA request for licensing qualifications Tests, written answers & scores of reactor operators licensed for nuclear facilities are available at PDR FFLTON.J M Division of Rules and Records 79/05/23 2pp
- 7906070233 Requests licensing qualifications of all facilities' personnel, tests given & results for all plant operators EMSHGILLER.T R The Wall Street Journal 79/04/16 ip
- 7906070371 FOIA request for copy of Basic Ordering Agreement NRC-03-78-131. "Technical Assistance for Fire Protection Program Review & Evaluation." awarded to Gage-Habcock & Associates HEBB-M A Rolf Jensen & Associates, Inc. 79/04/17 1p
- 7906130336 Forwards 790402 memo re task group for generic implications of feedwater transients in B&W-designed reactors CASE.E O. Office of Nuclear Reactor Regulation 79/04/02 1p.
- 7906200470 "Effects of Weathering on Impregnated Charcoal Performance DEITZ.V R Navy,Dept of, Naval Research Laboratory 79/03/31. 78pp
- 7906210007 Technical data on SAIGP-100 radiolodine cartridge for total iddine (2,25-inches diameter by 1-inch deep).

  \* Science Applications, Inc. 79/05/06 Spp
- 7906210066 Notification of 790530 meeting in Bethesda,MD w/owners of all operating Westinghouse-designed plants to discuss solution of items in IE Bulletins 79-06A & 79-06A; Ravinion i
  O'REILLY,P D. Standardization Branch. 79/05/29, 3pp.
- 79062≥0136 NRC daily staff notes for 790517 GDSSICK.L.V. Office of the Executive Director for Operations. 79/05/18 ip
- 7906220186 Summarizes responses to IE Bulletin 79-068. Operating manualy are being scrutinized Operational personnel are being trained, Radioactive gases & liquids transfer lines are interlocked w/containment isolation &/or radiation signals. TAM:P Division of Site Bafety & Environmental Analysis 79/05/08 Bpp.

- 7906220259 Requests all into re unauthorized removal of ASLAB 781101 documents Trends Publishing, Inc. 79/04/24 ip
- 7906220263 Responds to 790424 request for info re unauthorized removal of ASLAB 781101 documents from ofc Forwards relevant documents FELTON, J M Division of Rules and Records 79/06/14 400
- 7906260200 Testimony before Subcommittee an Natural Resources & Environ of House Committee on Science & Technology 790602 meeting ARNOLD, R C OPU Service Corp 79706/02 App
- 7906260479 Forwards telegrams re-possible sabotage per FOIA request FLANDERS,D G Federal Bureau of Investigation 79/06/14 ip
- --7906260483 Advises sabotage not responsible for TMI incident per HR Danton statement. Human factor overrode automatic safety functions
  - \* Federal Bureau of Investigation 79/04/30 2pp
- --7906260489 Expresses concern of independent geological consultant re possible sabotage in 790328 THI incident \* Federal Bureau of Investigation 79/04/06 2pp
- --7906260498 Expresses concern of US Labor Party representative, P Octostein, re-possible sabotage in 790328 TMI incident \* Federal Bureau of Investigation 79/04/06 3pp
- -- 7906260303 Forwards E Weiss FOIA request & FBI telegrams re sabotage Requests copy of response
  FELTON.J M Division of Rules and Records 79/05/01 2pp
- 7906280550 FOIA request for copies of documents obtained by NRC from DBJ re PGME proposal to construct Mendocino project FLEISCHAKER, D S Center for Law in the Public Interest 79'04/30
- 7906260558 Responds to FUIA request for documents made available to NRC by DOJ re PG&E proposal to construct Mendocino project Forwards index to 148 microfilm rolls FELTON-J M Division of Rules and Records 79/06/12 ip
- --7906260359 Index to 148 microfilm rolls provided by CA Dept of Hater Resources Hatl involves PORE Jan-Har 1973 memos re proposal to construct Mendocino project. Encl available in Central California, State of 79/06/12 229pp
- 7906280222 Ack receipt of ltr re energy sources Forwards environ statement re nuclear power plant operation W/o encl VOLLMER.R H Assistant Director for Systems Engineering 79/05/it
- 7906270015 Forwards 790404 ltr from JC Villforth to LV Cossick, & 790401 memo & 790414 ltr from JA Califeno to JM Hendris ROBERTS, R. M. Health, Education & Helfare, Dept. of. 79/06/19 1p
- --7906290017 Forwards FOIA request received by NRC from AZ Roisman for documents re TMI incident originated by HEW Requests expedited review of documents FELTON.J.H Division of Rules and Records 79/06/12. 1p
- --7905290020 Expresses gratitude for 790403 itr describing plans for monitoring worker exposure to radiation Requests addl info re procedure for obtaining latest employee exposure data from Metropolitan Edison & opportunity to review sys. CALIFANO. J A. Health, Education & Helfare, Dept of, 79/04/14
- --7906290027 Discusses removal of Bureau of Radiological Health representative from command ctr covering TMI. Hill provide copies of Food & Drug Administration milk & food & water sampling results of previous day W/790401 meno. VILLFORTH. J C. HEW. Dept. of, UB Public Health Service. 79/04/04
- 7706270036 Forwards summary of etatus of B&W plants for 770419 w/IE site inspector daily repts of B&W reactors for 770409, DAVIS, J Q. Office of Inspection & Enforcement. 79/04/09. dpp.
- 7906290078 Forwards summary of 88W plant insp for 790411 w/IE site inspector daily rapts of 88W reactors for 790411. DAVIS, J Q Office of Imspection & Enforcement 79/04/12. 3pp.
- 7906290447 Forwards site inspector daily repts of Ball reactors for DAVIS, J. O Office of Inspettion & Enforcement, 79/04/26. ip.

- 7906290504 Forwards summary of B&W plant insp for 790410 w/IE site inspector 790410 daily repts
  DAVIS, J O Office of Inspection & Enforcement 79/04/10 2pp
- 7906290548 Forwards summary of 86W plant insp for 790412 w/fE site inspector 790412 daily repts
  DAVIS.J O Office of Inspection & Enforcement 79/04/12 3pp
- 7906290582 Forwards site inspector daily repts of B&W reactors for DAVIS, J C Office of Inspection & Enforcement 79/04/20 to.

#### CEN TEC 18 GENERIC TECHNICAL ISSUES

- 7703120401 Forwards Revision 2 of Task Action Plan A-27, reload applications Completion requires approx 0 07 man-yrs Completion projected for June 1979
  STELLO, V Division of Operating Reactors 79/02/16 3pp
- 7906020180 Concurs w/proposed revision to Task Action Plan A-17, \*89: Interaction in Nuclear Power Plants "
  EISENRUT.D G. Assistant Director for Systems Engineering 79/05/08
- 7904040392 Comments on revised Task Action Plan A-30, "Adequacy of Safety-Related Power Supplies suggests definition of areas of common concern among electric-related thermal analyses roorams STELLO, V. Division of Operating Reactors 79/04/13 2pp
- 7906180348 Determines that recent abnormal events involving potential failures of startup transformers necessitates expanding scope of Generic Issue B-23, "Degraded Orid Voltage "Describes proposed course of action VOLLLER, R Assistant Director for Systems Engineering QRIMES, 9 Assistant Director for Engineers & Projects (Pre 790625) 79/04/12
- 7906190118 Discusses add1 funding requirements identified during midgear review of BNL Mark I technical assistance contract Forwards program revision ltr requesting \$60,000 funding increase for BNL Contract A3108 M/a encl GRIMES.C. I Assistant Director for Plant Bystems 79/04/25 2;
- 7906290037 Notification of 790518 meeting w/BD Liaw/J Stronsmider in F Almeter in BethesdarMD to discuss technical assistance requirements for consequence analyses portion of Task Action Plans A-3.A-4 & A-5 Page 100 Strong Engineering Branch, 79/05/15, ip
- 7906250037 Notification of 790518 meeting w/BD Liaw, J Stronsmider 4 F Almeter in Bethesda. HD to discuse technical assistance requirements for consequence analyses portion of Task Action Plans A-3.A-4 & A-5 LAGRANGE, R Q Engineering Branch. 79/05/15 1p
- 7906230037 Notification of 790318 meeting w/BD Liaw.J Btronsmider k F Almeter in Bethesda.MD to discuss technical assistance requirements for consequence analyses portion of Task Action Plans A-3,A-4 & A-5 LAGRANGE.R.Q. Engineering Branch. 79/03/15. ip.
- 7906290192 Notification of 790530 meeting w/Mark I owners group in Bethesda, MD to discuss safety relief valve discharge load frequency & off-center quencher load definition for Mark I containment long-term program, GRIMES, C I Plant Systems Branch, 79/03/22 2pp
- 7906290192 Notification of 790530 geeting w/Mark I owners group in Bethesda: MD to discuss safety relief valve discharge load frequency & off-center quencher load definition for Mark I containment long-term program, GRIMES, C. I. Plant Systems Branch, 79/05/22 2pp.

#### ILE INSPECTION AND ENFORCEMENT

- 7902150334 Forwards IE Info Notice 79-03, "Limitorque Valve Obdref Lisit Switch Lubricant," for 790209 issuance Draft of transmittel Itr enc. No insp followup is necessary. MOSELEY.N C Division of Reactor Operations Inspections 79/02/64
- --7902150358 IE Info Notice 79-03. "Limitorque Valva Geared Limit Switch Lubricant." Notes excessive failure rates of referenced switches due to hardening & drying out of lubricant. Recommends Mobilgreese 28 as replacement.

  4 Office of Inspection & Enforcement. 79/02/09. 1p.

- 7902210141 Forwards IE Bulletin 79-01, "Environ Qualification of Class IE Equipment," w/draft transmittal letter for 790208 dispatching W/list of 11 systematic evaluation program plants for which no action is required MOSELEY,N C Office of Inspection & Enforcement 79/02/06 2pp
- 7905040199 Forwards IE Circular 79-06, "Failure to Use Syringe & Bottle Shields in Nuclear Medicine," & list of licensees # Region 5, San Francisco, Office of the Director 79/04/19 900.
- 7905110048 IE Bulletin 79-10, "Requalification Training Program Statistics " \* Office of Inspection & Enforcement 79/05/11 9pp
- 7708060153 IE Info Notice 79-10, "Nonconforming Pipe Bupport Struts " \* Office of Inspection & Enforcement 77/04/16 3pp
- 7904060159, IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem" \* Office of Inspection & Enforcement 79/05/07 2pp
- 7904060161 IE Info Notice 79-12, "Attempted Damage to New Fuel Assemblies "
  - \* Office of Inspection & Enforcement 79/05/10. 2pp
- 7906060164 IE Info Notice 79-13, "Indication of Low Water Level in Oyster Creek Reactor" \* Office of Inspection & Enforcement 79/05/29 (ipp
- 7906060165 IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circuit Breafers for Engineered Safety Bys " > Office of Inspection & Enforcement. 79/05/22 6pp
- 7906040168 IE Bulletin 79-12, "Short Period Screms at BWR Facilities " IE Circular 77-07 encl \* Office of Inspection & Enforcement. 79/05/31 Spp
- 7906060172 IE Circular 79-08, "Attempted Extortion Low Enriched U " Sanitized summary of GE Wilmington incident \* Office of Inspection & Enforcement 79/05/18 7pp
- 7906290214 IE Info Notice 79-14, "Bafety Classification of Electrical Cable Support Sys " ENGELKEN.R H Office of Inspection & Enforcement 79/06/11 3pp
- 7906290220 IF Info Notice 79-17. "Source Holder Assembly Damage from Misfit Between Assembly & Reactor Upper Orid Plate "O'REILLY, J P Office of Inspection & Enforcement 79/06/20 App
- 7906290232 IE Bulletin 79-02. Revision 1. "Pipe Bupport Base Platu Besigns Using Concrete Expansion Anchor Bolts " SEYFRIT. K V Office of Inspection & Enforcement 79/06/21 11pp
- 7706290237 IE Circular 79-07. "Occurrence of Split or Punctured Regulator Diaphragms in Gertain Self-Contained Breathing Apparatus " SEYFRIT.K V Office of Inspection & Enforcement 79/06/22. Opp

# NUREO NUREO REPORTS AND RELATED CORRESPONDENCE

- 7903210496 NUREO-0330
  Buff Book 2 Status Summary Rept.Advanced Reactor Safety
  Research, data as of 790131
  4 Office of Nuclear Reactor Regulation 79/02/27, BOpp
- 7903300582 Notifies that NRC has completed review of environ statutes as promised in 781219 itr Summary of NRC responsibilities under various environ statutes encl
  DENTON, H. R. Office of Nuclear Reactor Regulation. 79/03/16 10pp.
- ---7903300886 Requests participation in Task Force on Environ Statutes, to review compliance w/ existing regulations Request for info & cooperation enci. ANDRUS,C.D. Interior,Dept of 78/11/16 12pp
- 7405290349 Forwards NUREO-0555, "Environ SRP for Environ Review of CP Applications for Nuclear Power Plants,"
  DEYOUNO, R. C. Division of Site Sefety & Environmental Analysis 79/03/21. 1p.
- --7905290349 NUREQ-0555 NUREQ-0555; "Environ SRP for Environ Review of CP Applications for Nuclear Power Plants," + Office of Nuclear Reactor, Regulation, NUREQ-0555, 79/05/21, 800pp. Ayailable at NTIS.

- 7906010050 NURE0-0020 V3 N4 Orey Book Operating Units Status Rept.data as of 790331 \* Commission 79704730 130pp
- 7906010219 NUREG-0298
  White Book Fire Protection Action, Status Summary Rept, Revision 1
  \* Commission 79/03/02 26pp
- 7906010337 Research Info Ltr 53 results of initial series of three incore experiments on coolability limits of post-accident particulate LMFBR fuel debris in sodium pool Forwards NUREO/CR-0263 & NUREO/CR-0421 LEVINE:S Office of Nuclear Regulatory Research 79/09/10 7pp
- 7904010337 Research Info Ltr 53 results of initial series of three incore experiments on coolability limits of post-accident particulate LMFBR fuel debris in sodium pool, Forwards NUREO/CR-0263 & NUREO/CR-0421 LEVINE, S
- --7904010344 NUREC/CR-0243 "Debris Bed Studies & Experiments at Bandia Lebs " RIVARD.J B Sandia Laboratories FIN A-1181 SAND78-0299 78/07/31 59pp Available at NTIS
- ---7906010351 NUREG/CR-0421
  "Post-Accident Heat Removal Debris Bed Experiments D-2.&
  D-3 "
  RIVARD, J B Sandia Laboratories FIN A-1181 SAND78-1238
  78/11/30 60pp Available at NTIS
- 7906020094 NUREG-0482
  "Occupational Radiation Exposure at Light Hater Cooled Power Reactors:" annual rept for 1977.
  PECK,L J Office of Management and Program Analysis 79/05/31 92pp Available at NTIS
- 7906020097 NUREG/CR-0220

  "Manifestations of Nunlinearity in Fuel Ctr Thermocouple
  Steady State & Transient Data Implications for Data
  Analysis "
  LANNINO, D D BARNES, B O . WILLIFORD, R. E Battelle Memorial
  Institute, Pacific Northwest Laboratory FIN B-2043 PNL-2692
  79/01/31 122pp Available at NTIB
- 7904020102 NUREG/CR-0799
  "Experimental Investigation of Aerosol Behavior in
  Fost-LHFBR Accident Reactor Containment Atmosphere"
  HEGRZYN.J., SHAH,D T. New York, State Univ of, Buffalo. FIN
  B-5974 79/04/30 45pp Available at NTIS
- 7906020105 NUREG/CR-0426 V2
  "Radiation Dose to Const Workers at Operating Nuclear Power
  Plant Sites," Vol 2 .Apps A-F
  ENDRES.O.W., SHIPLER.D.B. Battelle Memorial Institute, Pacific
  Northwest Laboratory FIN 8-2073 PNL-2773 78/12/31 200pp
  Available at NTIS
- 7906020143 NUREG-0548
  "Belection & Training of ABLB Panel Members.Rept to Congress."
  " Commission 79/04/30 241pp, Available at NTIS
- 7906020148 NUREG/CR-0658
  "Mathematical Simulation of Sediment & Contaminant Transport
  in Surface Haters." annual rept.Oct 1977-Sept 1978
  ONISHI,Y. ARNOLD.E H., SERNE.R J. Battelle Memorial Institute,
  Pacific Northwest Laboratory FIN 8-2271-9 PNL-2902 RE 79/01/31.
  32pp Available at NTIS.
- 7906020195 NUREO/CR-0793
  "Buckling Criteria & Application of Criteria to Design of
  Steel Containment Bhell," final rept, Jan 1978-Har 1979.
  SEIDE:P, WEINGARTEN.V, MASRI.S. International Structural
  Engineers, Inc. NRC-03-77-131 79/03/31 105pp. Available at
  NTSA
- 7906020220 NUREG-75/087 13.1.2

  8RP.Revision 1 to Section 13.1.2, "Review of Safety Analysis Rept for Nuclear Power Plants."

  9 Office of Nuclear Reactor Regulation, 79/04/30, 5pp.
- 7906020244 NUREO/CR-0780
  "Analysis of Aerosol Particles Undergoing Gravitational Agglomeration," annual progress rept for Oct 1977-Bept 1978 LOYALKA-B, K. Missouri, Univ. of. FIN 8-8978, 79/04/30, 107pp, Available at NTIS

7906050048 Responds to request for NUREG-0465. "Transportation Security Personnel Training Manual." Vols 1-3 Rept may be purchased from NTIS

Safeguards Standards Branch 79/04/04 2pp

--7906050049 Requests NUREG-0465, "Transportation Security Personnel Training Manual," Vols 1-3 NELSON.H D Nuclear Vote 79/03/29 (p

7906050086 NUREG/CR-0786

"FRAP-S3 Computer Code for Steady State Analysis of Orlde
Fuel Rods," model assessment rept
COLEMAN.D R. LAATS.E T. SCOFIELD.N R. EG & G. Inc. FIN A-6046
TREE-1352 79/04/30 98pp Available at NTIS

7906050098 NUREG/CR-0001

PROJUGOS MANGEY CHRONOLI "Rod-Bundle Thermal-Hydraulic Analysis Using Boundary-Fitted Coordinate Sys" SHA, H T, THOMPSON, J F. Argonne National Laboratory FIN A-2045 ANL-78-1 79/01/31 45pp Available at NTI8

7906050110 NUREG/CR-0739

"Guarterly Technical Progress Report on Water Reactor Safety Programs Sponsored by NRC Div of Reactor Bafety Research." Jan-Mar 1979 YBARRONDO.L J EG & G, Inc FIN A-6041 TREE-1299 79/04/30 BOpp Available at NTIS Jan-Mar 1979

7906050134 NUREG/CR-0610
"Surface Heat Flux Perturbations in BDHT Fuel Pin
Simulators" OTT,L J. CHILDS,K W Dak Ridge National Laboratory ORNL/NUREG-54 77/04/30 121pp Available at NTIS FIN 8-0125

7906050141 NUREC/CR-0699
"Leak Rate Tests on PC-1 Pu Product Cans Bealed by Helding."
final rept, Sept 1978-Jan 1979
COLTENIJ D. PETITIJOHN, R R SRI International NRC-D0-78-076
79/05/31 28pp Available at NYIS

7904050200 NUREG/CR-0547
"LWR Safety Research Program, "quarterly progress rept,
Jul-Sept 1978 SACKS, R. G. . KYGER, J. A. Argonne National Laboratory FIN A-2014 ANL-78-107 79/01/31 51pp Available at NTIS

7704030216 Responds to WA Spratley 770413 Itr to JM Hendrie re safaty of nuclear power plants Forwards IE Bulietins 77-05 & 77-05A, NRC Annual Rept 1978, NUREG-0376 & NUREG-757/111 NUREG-75/087 will answer other question W/o encl DEYOUNG.R C Division of Site Gafety & Environmental Analysis 77/05/01 2pp

--7906050221 Requests into on safety programs for input or criticism of State of OH review of nuclear reactor safety Relevant info from state ofc enci SPRAYLEY.W A Ohio, State of. 79/04/13 6pp

7906050226 NUREG/CR-0644

\*\*Geofechnical Analysis of Soil Samples From Test Trench at #\*Geofechnical Analysis of Soil Samples From Test Trench at ### Hestern NY Nuclear Byc Ctr.West Valley.NY " FICKIES.R H . FAKUNDINY.R H New York, State of FIN B~6C NYSOS/77~2401 79/04/30 27pp Available at NTIS 4 50 FIN 9-4008

7906050273 NUREC-0380 V3 N3
"Program Summary Rept"
\* Office of Management and Program Analysis 79/05/18 101pp
Available at NTIS

7906050277 NUREG/CR-0716
mp Gas Cooled Reactor Safety Studies" quarterly

7906180713 NUREC/CR-0AB9
"Methods for Prediction of Strong Earthquake Ground Motion"
# Southern California, Univ of FIN 8-6677 79/05/31

7906180717 NUREG/CR-0683

Statistical Methods for Evaluating Sequential Matt Dalance Data "
MINCEK,M A , STEWART,K B , PIEPEL.O F Battelle Memorial (natitute, Pacific Northwest Laboratory FIN 8-20149 PNL-2720 79/04/30 170pp Available at NTIS

7906180722 NUREG-0525

"Safeguards Summary Event List (SSEL) "
DAVIDSON, J. Division of Safeguards 79/05/31 114pp Available

7906180732 NUREG-0246

\*Fuel Supply Investment Cost Coal & Nuclear "

\* United Engineers & Constructors, Inc. (subs. of Raytheon Cd |
NRC-04-76-351 COO-2477-10 79/04/30 350pp Available at NIIS

7904180742 NUREO/CR-0551
"LWR Pressure Vessel Irradiation Surveillance Dosimetry,"
quarterly progress rept.Jul-Sept 1978
GUTHRIE.G L , MCELROY.W N , LIPPINCOTT, E P Hanford Engineering
Development Laboratory FIN B-5988-7 HEDL-TME 78-8 78/12/31
230pp Available at NTIS

7906180749 NUREG/CR-0712

MGNIBO747 NOREGICK-UTZ "BHK Steady State Capability of MBAP-EM Sys " SHARP.D A Savannah River Ecology Laboratory FIN A-DPST-NUREO-78-1 79/04/30 75pp Available at NTIS

7906180757 NUREQ/CR-0823

"Buckle Spherical Harmonics Solutions of Neutron Transport Problems " BLQMGUISTR N , LENIS E E Northwestern Univ FIN A-4079 79/05/31 100pp A/ailable at NTIS

7906180762 NUREG/CR-0713

"BUR LOCA Analysis Capability of WRAP-EH Sys "
BUCKNER: M R. BECKMEYER: R R . GREGORY: M V . Savannah River Ecology
Laboratory FIN B-4126-8 DPST-NUREO-78-2 79/04/30 44ap
Available at NTIS

7906180765 NUREC-0358
"SER Related to Operation of FFTF. Buppl I"
# Office of Nuclear Reactor Regulation 448 79/05/31 150pp
Available at NTIS

7906180770 NUREO/CR-0/14
"User's Quide for BWR LOCA Analysis Capability of WRAP-EM BECKMEYER.R R , GREGORY,M V , REED.R L Savannah River Scology Laboratory FIN B-4126-8 DPST-NUREO 78-3 79/04/30 208ap

7906180774 NUREO/CR-0738

"Physical Protection of Nuclear Matl In-Transit," quarterly progress rept. Jan-Mar 1979
CHAPMAN.L D Sandia Laboratories FIN A-1060 SANG79-0651
79/04/30 13pp Aveilable at NTIS

7906180779 NUREG/CR-0825

FUGIBOTY NUREGICE-0825

"Critical Experiments Measurements & Analyses to Establish Crack Arrest Methodology for Nuclear Pressure Vessel Steels." fourth annual rept.Oct 1977-Oct 1978

HAHM, O T , GEHLEN, P C , HOAGLAND, R O Battelle Memorial Institute. Columbus Laboratories FIN A-4046

AVAIIABLE ADDRASTORIES FIN A-4046

AVAIIABLE AT NTIS

i

79061E0804 NUREC/CR-0796

7906210318 NUREO/CR-0678

"Analysis of Heat & Mass Transfer Processes of U Oxide
Bubble in Sodium for Fuel Aerosol Simulant Test (FAST)"
TOBIAS/M L Oak Ridge National Laboratory FIN 8-0121
ORNL/NUREG/TM-3 79/05/31 49pp Available at NTIS

7706210325 NUREG/CR-0824

"Octitical Experiments, Measurements & Analyses to Establish Crack Arrest Methodology for Nuclear Pressure Steels." quarterly rept for Oct - Dec 1978.
HANN, G T , GEHLEN, P C , MARSCHALL, C. N. Battells Menorial I Columbus Laboratories FIN A-4046 BM-2026 79/05/31 E Available at NTIS 6 00 Battelle Memorial Institute. -2026 79/05/31 86pp 7906210365 NUREO/CR-0335
"Advanced Reactor Safety Reseach," quarterly rept,Jan-Mar 1978
COATS,R L , POWELL,J E , WALKER,J V Sandia Laboratories FIN A-1016 SAND78-1421 79/01/31 194pp Available at NTIS

7905210376 NUREG/CP-0006

"Review Group Meeting on Two-Phase Flow Instrumentation,"
rept of 780313-14 meeting at Rensselaer Polytechnic Inst.
Troy.NY
HSU.YY Office of Nuclear Reactor Regulation 79/04/30 468pp
Available at NTIS

7906230111 Forwards errata NUREO/CR-0421, "Post-Accident Heat Removal Debris-Bed Experiments D-2 & D-3." (SAND78-1238) RIVARD, J B Sandia Laboratories 79/04/05 3pp

7906230132 Forwards add1 comments on NUREO-0396, to be added to notebook of comments forwarded 790405
COLLINS, H E Assistant Director for Emergency Preparedness
79/05/15 ip

--7906230133 Ack receipt of ltr requesting return of 790330 comments on NRC/EPA task force rept on emergency planning All comments received have been placed in PDR COLLINS.H E Assistant Director for Emergency Preparedness EPA 520/1-78-01 79/04/27 1p

--7908230134 Requests return of comments on NUREG-0396 so mods can be made in light of TMI developments WANNINGER, A Commonwealth Edison Co 79/04/02 ip

--7906230136 Comments on NUREO-0396 questions validity of technical data dealing w/doses.timing.probabilities & distances Info presented & conclusions reached place undus emphasis on unrealistic worst-case scenarios
BEOLETTO.JA Southern California Edison Co 79/04/18 3pp

--7906230138 Comments on NUREQ-0396 guidance predominantly general in nature & subj to diverse interpretation Need to develop consistent federal guidance on emergency planning & uniform federal policy for emergency plan review AXELRQD.D New York, State of 79/04/13 5pp

--770&230137 Comments on NUREO-0376 endorses concept of emergency planning tones Plans to update state & local plans to reflect NUREO-0376 concepts as soon as final adoption of rept MCCLELLAND, B J Washington, State of 79/03/02 ip

--7906230141 Comments on NUREG-0396 considers info provided of value in IL emergency planning program Supports need to separate siting criteria from emergency planning Prudent to re-evaluate analyses performed per WASH-1400 REIZEN,M S Michigan, State of 79/04/17 3pp

--7906230142 Comments on NUREO-0396 basis for planning recommendations is inapropriate Many NUREO-0396 recommendations are beyond scope of licensing considerations.
URRIO.R E. Florida Power & Light Co L-79-96 79/04/19. 2pp

---7906230144 Comments on NUREO-0396 agrees w/principles developed in document Guestions adequacy of 10-mile radius for emergency plenning zone YOUNG:0 Kentucky, State of 79/05/09 1p

--7906230146 Further comments on NUREG-0396 in light of TMI incident rept does not consider possibility or consequences of explosion similar to that threatening TMI Recommended planning distances for maltdown not adequate

JONES, O. L. Virginia, State of 79/04/30, 2pp

--7906230:47 Comments on NUREG-0396 TMI incident demonstrates need & importance of detailed hazard analysis of each fixed nuclear facility in FA Analysis should go beyond generalized linear definition of emergency planning zones HENDERSON, O.K. Pennsylvania, State of 79/05/10. ip.

---7906230150 Comments on NUREQ-0396.contains useful observations & infobut entirely inadequate in moving NRC toward achieving effective plans to protect public after severe accident BANGRUFT; M Public Citizen Litigation Group 79/03/10 ip

7906260483 NUREQ-0554
"Bingle-Failure-Proof Cranes for Nuclear Power Plants "
POREE,L. Division of Engineering Standards 79/03/31 14pp.

7906260574 "Nuclear Power Plant Fire Protection Fire Detection (Bubsus Sturdy Task 2) "
BERRY, D L Sandia Laboratories FIN A-1080 SAND78-1373
79/03/31 36pp.

7906260596 NUREC/CR-0686
"Advanced Two-Phase Flow Instrumentation Program, "quarterly progress rept for Jul-Sept 1978
IURNAGE,K Q . DAVIS,C E . THOMS.D Q Oak Ridge National Laboratory
FIN B-0401 79/05/31 66pp

7906260601 Research Info Ltr S4 forwards NUREO/CR-0465, "SETS User's Manual for Fault Tree Analyst." by Sandia Labs LEVINE.S Office of Nuclear Regulatory Research 79/05/15 2pp

--7906260608 NUREG/CR-0465
"BETS User's Manual for Fault Tree Analyst "
HORRELL.R B : STACK.D W Sandia Laboratories FIN A-1191
SAND77-2051 79/05/15 96pp Available at NTIS

7906260605 NUREC/CR-0751

"Physical Protection of Nuclear Facilities," quarterly progress rept for Jan-Mar 1979
CHAPMAN.L D Sandia Laboratories FEN A-1060 BAND79-0754
79/04/30 30pp

7906270173 NUREG-0170 VI NUREG-0170.Vol 1, "FEB on Transportation of Radioactive Matl by Air & Other Modes" • Office of Standards Development 77/12/31 150pp

--7906270177 NUREO-0170 V2 NUREO-0170, Vol 2, "FES on Transportation of Radioactive Matl by Air & Other Modes" \* Office of Standards Development 77/12/31 225pp

7906280011 NUREO/CR-0781
"Skyshine-II Procedure Calculation of Effects of Structure Dosign on Neutron, Primary Gamma-Ray & Secondary Gamma-Ray Dose Rates in Air"
LAMPLEY, C M Radiation Research Associates NRC-03-78-175 PRA-17901 79/05/31 155pp Available at NTIS

7906280020 NUREG/CR-0422 V8
"UMR Safety Research Program," quarterly rept.Apr-June 1778
BERMAN,M Sandia Laboratories FIN A-1019. SAND78-1901 79/01/31
112pp Available at NTIS

7706280066 NUREG/CR-0648
"Measurement of Phase Velocities in Mist Flows Using
Stagnation Probes"
FINCKE,JR. DEASON,VA Idaho National Engineering Laboratory FIN
A-6074 TREE-1350 79/03/31 41pp

7906290083 NUREG-0468
"Investigation & Analysis of Mass Mortality of Commercial
Lobsters (Homanus Americanus) in Seabrook Harbor, NH During
Oct of 1977 "
HICKEY, CR Division of Site Safety & Environmental Analysis
78/07/31 105pp Available at NTIS \$6.50

7906290167 NUREG-0540 VI N4
"Title List of Documents Made Publicly Available." for Apr
1979
\* Technical Information & Document Control 79/04/30 33App
Available at NTIS

/906290188 NUREG/CR-0692 V6

"Repts Distributed under NRC Reactor Safety Resparch
Foreign Technical Exchange Program " Vol VI. Jul-Dec 1978
GUCENER, D S Oak Ridge National Laboratory FIN 8-0126
ORNL/NUREG/NSIC 79/05/31 115pp Available at NTIS

7906290197 NUREG-0961
"Physical Protection of Shipments of Irradiated Reactor
Fuel, Interim Guidance "
KASUN, D.J. Office of Nuclear Material Safety & Safeguards
79/06/30 36pp Available at NTIS

7906290481 NUREC/CR-0629
"Field & Modeling Study of Windblown Particles From
U Mill Tailings Pile," interim rept.
SCHWENDIMAN.L., SEHMEL, & A., HORST, T. W. Battelle Memorial Institute
Pacific Northwest Laboratory, FIN B-2095-9, PNL-2890 79/04/30.
132pp Available at NTIS

7906290487 NUREO/CR-0753
"Guarterly Progress Rept on Blowdown Heat Transfer
Separate-Effects Program," Jan-Mar 1979
MHITE, J D., 80HANAN, R.E., CLARK, D L. Dak Ridge National Laboratory
FIN 8-0125 ORNL/NUREO/TM-3 79/05/31, 27pp. Available at NTIS

7906290494 NURED/CR-0691
"Bibliography of Repts on Research Sponspred by NRC Ofc of Nuclear Regulatory Research." Jul-Dec 1978
BUCHANAN, J R Oak Ridge National Leboratory FIN 8-0126
ORNL/NUREO/NSIC 79/05/91 130pp.

7906290498 NUREQ-0570 vosavova nonce-usyo "Toric Vapor Concentrations in Control Roca Following Postulated Accidental Release " WINO.J Division of Site Safety & Environmental Analysis 79/06/30 Japp Available at NTIS

7906290551 NUREQ/CR-0507 V3 "Stress Analysis of Cylindrical Pressure Vessels H/Closely Spaced Nozzles by Finite-Element Method; Vessels H/Three Nozzles Under Internal Pressure & External Loadings,"

WEED,R A Cak Ridge National Laboratory -18 79/05/31 58pp Available at NTIS ORNL/NUREO-18

7906290616 NUREG-0380 V3 N6
"Program Bummary Rept." Vol 3, Number 6
# Office of Hanagement and Program Analysis 79/06/15 70pp
Available at NTIS

7906290668 NUREQ/CR-0556 "Aerodynamic Considerations on Injection of Tornado-Generated Missiles From Ground Level into Tornado Flow HALL:R T Navy, Dept of. FIN B-1143. 79/06/30 97pp

7906290673 NUREO/CR-0710 Advanced Tuo-Phase Flow Instrumentation Program: " quarterly progress rept for Oct-Dec 1978
TURNADE, K G , DAVIB.C E , THOMAS, D G. Dak Ridge National Leboratory FIN B-0401
GRNL/NUREO/IM-3 79/05/31 33pp Available at NTIB

7906290792 Submits changes to be made in NUREG CR-0421, "Post-Accident Heat Removal Debr(s-Red Experiments D-2 & D-3," (SAND78-1238)
RIVARD J B Sandia Laboratories 79/04/05 3pp

#### CORRESPONDENCE WITH OTHER ORGANIZATIONS ORD

7903020022 Responds to 781107 request Forwards composite listing of anticipated requests for NRC safety reviews Supersedes both 780731 & 1026 lists BARBER, R N Energy. Dept of 79/01/09 9pp

7703200100 Responds to 781013 ltr re NRC coordination w/Interagency Horking Group on Medical Radiation re flagnostic r-ray guidance.NRC has no requirements for diagnostic r-rays; sees no specific application of new guidance QULLER.K.R Division of Biting, Health & Bafeguards Standards 78/10/30 1p.

--7903200101 Offers to help NRC u/program to minimize unproduction exposure of persons to diagnostic z-rays,per D Costle 780920 recommendations
MARTIN.J E Environmental Protection Agency 78/10/13 2pp

--7903200106 "Radiation Protection Guidance to Federal Agencies for Diagnostic X-Rays Approval of Recommendations" COSTLE.D M Environmental Protection Agency RICHMOND, J B. Health. Education & Welfarm. Dept of 78-2776 78/02/01 Spg

7903230294 Comments on EPA "Hazardous Waste Quidelines & Regulations: "regulations unclear in role that regulatory agencies play in implementation EPA must concur w/NRC requirements re U mill tailings W/FR notice OOSSICK.L V Office of the Executive Director for Operations 600 79/03/16

7905160435 Forwards outlines & schedules for ten ltrs proposed for HTOR-OT preapplication review program HTORFILL, K L Gas-Cooled Reactor Associates GCRA/NRC-0015 79/05/09 37pp

7905220068 Summary of 790402 meeting w/DDE re SHOCK-II subroutine & chronology of events involved w/problem NOONAN, V. S Engineering Branch 79/04/06 2pp.

7905250222 Responds to litrine C Johnson, Forwards NIH comments on C Johnson manuscriptine epidemiological evaluation of cancer incidence rates for 1967-71 in areas w/measured concentrations of Pu soil contemination near Rocky\*Flats PARSONT, M.A. Rediological Health Standards Branch. 79/04/2 79/04/30

7906010211 Provides guidancs & funding to BNL to support evaluation of Mark I containment suppression pool hydrodynamic loads, STELLO, V. Division of Operating Reactors 79/05/02 2pp

--- 7906010216 Std order for DOE work, "Mark I Containment Assessment," increasing funding. TRIPLETT, M.P. Office of Nuclear Reactor Regulation. FIN A-GIOB-9 779/03/02 6pp. 7906020145 Forwards IE Info Notice 79-11, "Lower Reactor Vessel Head Insulation Support Problem "
PAPPAS,H Region 3, Chicago, Office of the Director 79/03/08

-- 7906020147 IE Info Notice 79-11. "Lower Reactor Vessel Head Insulation Support Problem Region 3. Chicago, Office of the Director 79/05/07 2pp

7906050389 Requests opportunity for WPPSS & TX Utils Generating Co to participate in NRC 7905126 meeting re UCB petition for emergency & remedial action & petition for reconsideration REYNDLDB, N S Debovoise & Lieberman 79/05/07 ip

7905030391 Requests opportunity to participate in NRC 790316 meeting re UCS petition for emergency & remedial action & petition for reconsideration Duke Pawer Co 79/05/04 1p PORTER N L

7906080120 Forwards IE Circular 79-08. "Attempted Extortion - Lou Enriched V." which was sent to listed parties on 790518 PAPPAS.H Region 3. Chicago. Office of the Director 79/05/18

7905110429 Ack receipt of 790427 ltr re UCB petition for emergency to remedial action on adequacy of fire protection criteria Participation at NRC meeting not desmed necessary to further client interests Conner, Hoore & Corber 79/05/04 2pp CONNER. T B

7905120087 Ack receipt of UCS 790328 petition requesting NRC order for all operating reactors to perform seismic reanalysis within 120 days floquest will be handled per 10CFR2 206 FR notice DENTON: H R Office of Nuclear Reactor Regulation 79/05/10 is

--7906120090 Notice of UCS 780328 petition requesting NRC order for reanalysis of spismic capabilities of all operating reactors 80YD,R S Office of Nuclear Reactor Regulation 79/05/10 ip

--7906120095 Forwards UCS 79032B petition requesting seismic reanalysis of operating plants Petition will be treated per 10CFR2 204 Requests prompt response CHILK.6 J Office of the Secretary of the Commission 79/04/25

7906120222 Forwards IE Circular 79-07, "Unexpected Speed Increase of Reactor Recirculation Motor Generator Sat Resulted in Reactor Power Increase " Bubmits list of licensees to whom circular was sent on 790502 PAPPAS.H Region 3, Chicago, Office of the Director 79/05/03

7906120250 Notifies that IE Bulletin 79-11. "Faulty Overcurrent Trip Device in Circit Breakers for Engineered Safety Sys." has been forwarded to listed utils PAPPAB.H Region 3. Chicago. Office of the Director 79/08/24

7906140101 Transcript of 790516 public meeting in Washington.BC reharang on UCS petition for reconsideration Pp 1-47 Affirmation Session 79-13 anci.
HENDRIEJ, M., OILINSKY, V., KENNEDY, R. Commission 79/05/16 52pp

7906140474 Responds to 790427 ltr extending invitation to address NRC ra UCB petition for amergency & remedial action re fire protection Unable to attend Commands utils on fire protection efforts LOPATA: J R Carboline Co 77/05/04, 2gp,

7906200075 Forwards IE Info Notice 79-13; "Indication of Low Hater Level in Ogster Creek Reactor" KEPPLER.J G Region 3, Chicago, Office of the Director 79/05/29

7906260015 Forwards IE Info Notice 79-12, "Attempted Damage to New Fwel Assemblies " Lists recipient licensees PAPPAB.H Region G. Chicago, Office of the Director 79/05/14

### PROPOSED RULE

7903300537 Responds to 790226 request.Forwards description of recent NRC successes in improving mgt of regulatory process Specific examples enci.
MINDOUE, R. B. Office of Standards Development 79/03/06 5pp

- 7904170494 Responds to 790130 ltr re application of 10CFR30 59 to GE reload fuel If reload involves meither Tech Spec change nor unreviewed safety quastion, prior NRC approval is not Reactor Safety Branch 79/04/02 1p
- 7905280074 Summary of 790416 meeting w/AD Little. Inc in Sethesda MD re 10CFR21 notification of potential for incorrect ASLPIPE seismic stress analysis of safety-related piping application RUSSELL, W T Assistant Director for Systems Engineering 79/04/17
- 7906020008 Comments on proposed rules 10CFR19 & 20 requests public hearing to discuss dose limitations
  STRELOW, R Leva, Hawes, Symington, Martin & Oppenheimer 79/03/13
- 7906020008 Comments on proposed rules 10CFR19 & 20 requests public hearing to discuss dose limitations
  STRELCH,R Leva, Hawes, Symington, Martin & Opponheimer 79/03/13
- 7906020204 Comments on proposed rule 10CFR35 agrees w/safety committee concept & membership Chairmanship of committee should be assigned to mgt member TWITE, O M Vet Admin Hosp HN/MI 79/04/25 1p
- 7906090424 Comments on proposed rules 10CFR19 & 20 opposes rule change No conclusive evidence that current sys is not adequate Economic impact of change is substantial & adoption of rule would show NRC acceptance of linear hypothesis RICHARDSON,H D Affiliation Unknown 79/04/11 2pp
- 7906030424 Comments on proposed rules iOCFR19 & 20 opposes rule change No conclusive swidence that current sys is not adequate Economic impact of change is substantial & adoption of rule would show NRC acceptance of linear hypothesis RICHARDSON.H D Affiliation Unknown 79/04/11 2pp
- 7906070051 Comments on proposed rules 10CFR19 & 20 basic concept is sound Limits should not be placed on licensee EVRAETS.J C California, Univ of, Los Angeles 79/03/30 2pp
- 790A070051 Comments on proposed rules 10CFR19 & 20.basic concept is sound Limits should not be placed on licensee EVRAETS, J C California, Univ of, Los Angeles 79/03/30 2pp
- 7906D70060 Comments on proposed rules 10CFR19 & 20 opposes elimination because no data exists to indicate that dose of 12 rem/year is more risky than 5 rem/year WEGST.W F California Institute of Technology 79/04/02 2pp
- 7906070060 Comments on proposed rules 10CFR19 & 20 opposes elimination because no data exists to indicate that dose of 12 rem/year is more risky than 5 rem/year WEGST,W F California Institute of Technology 79/04/02 2pp
- 7905070388 Comments on proposed rules 10CFR17 & 20 opposes rule because of insufficient supporting scientific info b need to retain flexibility for emergencies TSCHAECHE, A N Affiliation Unknown 79/04/16 3pp
- 7906070388 Comments on proposed rules 10CFR19 & 20 apposes rule because of insufficient supporting scientific info & need to retain floxibility for emergencies TSCKAECHE.A N Affiliation Unknown 79/04/16 3pp
- 7906070414 Comments on proposed rule 10CFR35 approves rule because present safety committees have too many members.
   GY.R W Clinton Regional Hosp. 79/04/94 tp
- 7906070416 Comments on proposed rule 1QCFR19 \$ 20 opposes rule Reducing permissible accupational radiation exposures is overteaction Recent human studies inconclusive SULLIVAN.T J Consumers Power Co 79/04/23. 2pp
- 7706070416 Comments on proposed rule 10CFR19 \$\nu2000 20 apposes rule Reducing permissible accupational radiation exposures is overreaction. Recent human studies inconclusive SULLIVANAT J Consumers Power Co 77704/23 2pp
- 7906070417 Comments on proposed rules 100FR20 & 13 opposes rule Existing mechanism is satisfactory Addl certification requirements are unnecessary GRANT, J. B. Yoledo Edisen Co. 1-59, 79/04/18 1p
- 7906070417 Comments on proposed rules 10CFR20 & 13.opposes rule Existing mechanism is satisfactory Addi certification requirements are unnecessary, GRANT, J S. Toledo Edison Co. 1-59 79/04/18 ip

- 7906070418 Comments on proposed rule 10CFR35 supports rule because it will increase effectivness of rediation safety & make meaningful committees
  CULEERTIR 8 Hissouri Delta Community Hosp 79/04/26 ip
- 7906070419 Comments on proposed rule 10CFR35 supports rule because it permits flexibility & will simplify composition of Medical Isotope Committee DAY.J. Hosp of Philadelphia 77/04/23 (p
- 790607C420 Comments on proposed rule 10CFR35 supports rule because shift in committee emphasis is benefical & proposed membership is more representative GDEDE, M R lows Methodist Medical Center 79/04/27 ip
- 906080056 Comments on proposed rule 10CFR35 supports rule because Radiation Safety Committee would handle needs well CUNNINGHAM, M 5 Trinity Lutheran Hosp 79/04/27 ip
- 7906080061 Comments on proposed rule lOCFR35 apposes rule because simplified committee lacks sufficient medical expertise to evaluate use of isotopes
  HALTER:M 0 Campbell County Memorial Hosp 79/04/25 Ip
- 7906080081 Notifies that petition for separate public hearing on proposed rule to amend 10CFR19 & 20 has been forwarded to appropriate parties for consideration CHILK, S J Office of the Secretary of the Commission 79/05/07
- 7706080001 Notifies that petition for separate public hearing on proposed rule to amend 100ERIP & 20 has been forwarded to appropriate parties for consideration CHILK,8 J Office of the Secretary of the Commission 79/05/07
- 7906130075 Submits draft amends constituting general revision of Apps Q b H to 10CFR50 re fracture toughness requirements b reactor vessel survailiance program requirements. respectively ARLOTTO.G A Division of Engineering Standards 79/05/09 15pp
- --7706130077 "Domestic Licensing of Production & Utilitation Facilities Fracture Taughness Requirements for Nuclear Power Reactors," 10CFR50 CHILK.S J Commission 79/05/09 20pp.
- 7906130148 Comments on proposed rule lOCFR35 supports proposed amend authorizing simplified membership for Radiation Safety MIKOLOWSKY, D. J. Manchester Memorial Hosp. 79/04/26 [p.
- 7906130155 Comments on proposed rule 10CFR9 supports proposed amends re public records
  HENRY, J C | | Illinois Power Co | 79/04/24 | 1p
- 7906130173 Comments on proposed rules 10CFR19 & 20 supports proposed changes Requests uniform regulations in all states PRENDEROAST. H B LFE Corp 79/04/23 1p
- "906130175 Comments on proposed rules 10CFR19 & 20 supports proposed changes Requests uniform regulations in all states PRENDEROAST.W B LFE Corp 79/04/23 ip
- 7906130182 Comments on proposed rule 10CFR39 committee composition changes would result in excessively large membership

- 106130188 Comments on proposed rules 10CFR19 & 20 supports proposed rule
  PILLARD, C H International Brotherhood of Electrical Workers 79/04/23
- '06130191 Comments on proposed rules 10CFR19 & 20 supports provision requiring licensee to obtain previous total occupational exposure Requests reconsideration of allowable quarterly exposure RICCIO.T J International Brotherhood of Electrical Workers 79/04/27 ip
- Obligion Comments on proposed rules 10CFR19 & 20 supports provision requiring licenses to obtain previous total occupational exposure Requests reconsideration of allowable quarterly esposors RICCIG.T J International Brotherhood of Electrical Workers 79/04/27 1p
- '06130194 Comments on proposed rules (DCFR19 & 20 supports proposed changes Recommends delaying implementation until NRC hearing on adequacy of present occupational dose stds QCRE.J W Baltimore Gas & Electric Co 79/04/19 ip
- '06130194 Comments on proposed rules 10CFR19 & 20 supports proposed changes Recommends delaying implementation until NRC bearing on adequacy of present occupational dose stds OGRE.J W Baltimore Qas & Electric Co 79/04/19 1p
- '06130410 Comments on proposed rule 10CFR35 supports amend Medical facilities should have choice of Kedical Radioisotope Committee or Radiation Safety Committee TOW.D E Vet Admin Hosp WR.Massathusetts 79/04/26
- '06140012 Comments on proposed rule 100FR19 & 20 questions intent of second paragraph of Item 2.page 10.389.which implies that keeping of worker records for exposure is no longer mandatory Objects to 3-rem exposure per querter BERTELL.R Affiliation Unknown 79/03/30 2pp
- '06140928 Comments on proposed rules 10CFR19 & 20 quarterly dose limit should be 25% of annual limit BANCROFT,M H Public Citizen Litigation Group 79/04/24 3pp
- '06140525 Comments on proposed rules 10CFR19 & 20 quarterly dose limit should be 25% of annual limit BANCROFT,M H Public Citizen Litigation Group 79/04/24 3pp
- 04140929 Comments on proposed rules 10CFR19 & 20 apposes rule due to insufficient biomedical basis PARKER, H O Duke Power Co 79/04/12 3pp
- '06140529 Comments on proposed rules 10CFR19 & 20 appases rule due to insufficient biomedical basis PARKER.H O Duke Pawer Co 79/04/12 3pp
- '06140536 Comments on proposed rules 10CFR19 & 20 opposes rule due to insufficient supporting scientific info NILSON.R Exxon Nuclear Co , Inc (subs of Exxon Corp ) 79/04/17 5pp
- 06140536 Comments on proposed rules 10CFR19 & 20 apposes rule due to insufficient supporting scientific info NILEONNE Exxon Nuclear Ca . Inc (subs of Exxon Corp ). 79/04/17
- 06140553 Comments on proposed rules 10CFR02 & 50 state & federal agencies should coordinate site reviews to avoid duplication of effort & provide technical & legal input MARSH.L. New York: State of 79/03/29. 15pp
- 06140553 Comments on proposed rules iOCFRO2 & 50 state & federal agencies should coordinate site reviews to avoid duplication of affort & provide technical & legal input HARSH,L. New York, State of 79/05/29, 15pp
- 06:40972 Comments on proposed rules 100FR19 & 20 any change in accomplated dosm-averaging formula 5(N-18) should be clearly defined SINCLAIR W K National Council on Rediation Frotection & Heasurements 79/04/23 2pp.
- 04140572 Comments on proposed rules 100FR19 & 20 any change in accumulated dose-everaging formula 5(N-18) should be clearly defined.
  - :ional Council on Radiation Frotaction & '04/23 200 04/23

- 7906140577 Comments on proposed rules 10CFR19 & 20 opposes rule Public hearing should be held to discuss consequences of eliminating dose bank \* Isham. Lincoln & Beale 79/04/23 App
- 7906140577 Comments on proposed rules 10CFfi19 & 20 opposes rule Public hearing should be held to discuss consequences of eliminating dose bank \* Isham Lincoln & Beale 79/04/23 6pp
- 7906140581 Comments on proposed rule 100FR35 membership of Medical Isotope Committee is already simplified & logical HORNBERGER.K D St Marys Hosp MO/KA 79/04/19 ip
- 7906140588 Comments on proposed rule 10CFR39 hosps accredited by Joint Commission on Accreditation for Hosps already have radiation committees Such hosps should be exempt from rule ARNDT, T D Affiliation Unknown 79704726 ip
- 7906140389 Comments on proposed rules 10CFR19 & 20 recommends imposition of requirements of prompt notification whenever individual receives yearly dose over 3 rems Guarterly stds should not be retained HIYTL.R L Public Service Electric & Gas Co of New Jersey 79/04/23 2pp
- 7906140589 Comments on proposed rules 10CFR19 & 20 recommends imposition of requirements of prompt notification whenever individual receives yearly dose over 3 roms Guarterly stds should not be retained MITTL,R L. Public Service Electric & Gas Co. of New Jersey 79/04/23 2pp
- 7906140622 Comments on proposed rules 10CFR19 & 20 opposes rule Fieribility not allowed for situation where higher exposure is justified BASKIN-K P Southern California Edison Co 79/04/17 ip
- 7906140622 Comments on proposed rules 10CFR19 & 20 apposes rule Flexibility not allowed for situation where higher exposure is justified Southern California Edison Co 79/04/17
- 7906140631 Comments on proposed rules 10CFR19 & 20 quarterly dose stds should be eliminated because 5-rem annual rate presents no biological hazard Total man-rems would be higher by imposing quarterly dose stds GRANT, J & Toledo Edison Go 79/04/19 1p
- 7906:14063: Comments on proposed rules tOCFR: \$ 20 quarterly dose stds should be eliminated because 5-rem annual rate presents no biological hazard Total men-rums would be higher by imposing quarterly dose stds CRANT. J & Toledo Edison Co 79/04/19 ip
- 7906140661 Comments on proposed rules 10CFR19 & 20 proposed dose level for monitoring individuals aged 18 & over is unrealistic.

  Urges adoption of realistic values & waiver of 5-rem annual EVRAETS. J C Affiliation Unknown 79/04/17 2pg
- 7906140661 Comments on proposed rules 10CFR17 & 20 proposed dose lass! for monitoring individuals aged 18 & over is unrealistic. Urges adoption of realistic values & waiver of 5-rem annual limit

-

- EVRAETS. J C. Affiliation Unknown 79/04/17 2pp
- 7706160050 Comments on proposed rule 10CFR7 opposes rule Listed exemptions re records of financial institutions & wells should be deleted EVENSONAL J Affiliation Unknown 77/04/18 ip
- 7906160053 Comments on proposed rules 10CFR19 \$ 20 supports elimination of accomulated dose-averaging formula 5(N-18) Favors annual dose-limiting stds, w/retention of 3-ram quarterly limit VANBRUNT, E E Arizona Public Bervice Co ANPP-12785-JRM 79/04/20
- 7906160053 Comments on proposed rules 10CFR19 & 20 supports elimination of accumulated dose-averaging formula 5(N-18) Favore annual dose-limiting stds.w/retention of 3-rem quarterly limit VANBRUNT, E E Avizona Public Service Co ANPP-12983-JRN 79/04/20
- 7906160055 Comments on proposed rules 10CFR19 & 20 lifting limit of 1 25 rems per quarter would result in higher exposures to many individuals & chaos in administering radiation control program MOBLEY, M H Tennessae, State of 79/04/17 ip

- 7906160055 Comments on proposed rules 10CFR19 & 20 lifting limit of 1 25 rems per quarter would result in higher exposures to many individuals & chaos in administering radiation control program HOBLEY, M H. Tennessee, State of 79/04/17 10

- 7906160056 Comments on proposed rules 10CFR19 & 20 objects to unclear wording re determination of prior dose Questions revised radiation protection stds
  ANDERSON.C R American Airlines, Inc. 79/04/10 Spp
- 7906180029 Comments on proposed rule 10CFR50 urges stricter rules for all nuclear plants
  HCBRIDE, M S Affiliation Unknown 79/04/20 1p
- 7705180147 Comments on proposed rules 10CFR17 > 20 basic concept of proposal is good but approach is poor. Wording indicates overexposures are deliberate Opposes proposal PEEPLEG.W P Affiliation Unknown 77/04/11 3pp
- 7906180149 Comments on proposed rules 10CFR19 & 20 basic concept of proposal is good but approach is poor Mording indicates overexposures are deliberate Opposes proposal PEEPLES; W P Affiliation Unknown 79/04/11 3pp
- 77061B0337 Comments on proposed rules 10CFR19 & 20 favors mod of existing dose stds allowing up to 12-rem/yr whole body dose under certain conditions Requests adoption of 3-rem/yr std PAGEL, J W . ANGLIN.D R Vanderbilt Univ 79/04/27 2pp
- 7906180357 Comments on proposed rules iOCFR19 ½ 20 favors mod of existing dose stds allowing up to 12-rem/yr whole body dose under certain conditions Requests adoption of 5-rem/yr std PAGEL, J W , ANGLIN, D R Vanderbilt Univ 79/04/27 2pp
- 7906180358 Comments on proposed rules 10CFR19 & 20 proposed elimination of 5(N-18) rule is incompatible w/total man-rem ALARA objections Rule would establish no ecjentific basis for proposed dose limit changes SHERMOOD, G G General Electric Co , Nuclear Energy Products Div MFN-108-79 79/04/20 2pp
- 7906180358 Comments on proposed rules 10CFR19 & 20 proposed elimination of 5(N-18) rule is incompatible w/total man-rem ALARA objections Rule would establish no scientific basis for proposed dose limit changes SHERHOOD, G G General Electric Co , Nuclear Energy Products Div MFN-108-79 79/04/20 2pp
- 7906180360 Comments on proposed rules 1905R19 & 20 requests that 5(n-18) formula guidelines be retained WINTERS,C E Todd Shipyards 79/04/16 2pp
- 7906180360 Comments on proposed rules 10CFR19 & 20 requests that 5(n-18) formula guidelines be retained HINTERB, C. E. Todd Bhighards 79/04/16 2pp
- 7906180363 Comments on proposed rules 10CFR19 & 20 recommends that regulations include provisions allowing prescribed dose levels to be exceeded when qualified expert believes circumstances warrant such action OARFIELD,D & Beckman Instruments, Inc. 79/04/23 2pp
- 7906180363 Comments on proposed rules 10CFR19 & 20 recommends that regulations include provisions allowing prescribed dome regulations include provisions allowing prescribed dome levels to be exceeded when qualified expert believes circumstances warrant such action GARFIELD, D. K. Backman Instruments, Inc. 79/04/23 2pp
- 7906180788 Comments on proposed rules iOCFR19 & 20 opposes rule because long-term effects of radiation are unknown STURGES, B R Affiliation Unknown 79/04/20 3pp
- 7906:8078B Comments on proposed rules 10GFR19 & 20 opposes rule because long-term effects of radiation are unknown STURGES, B R Affiliation Unknown 79/04/20 3pp
- /906200219 Comments on proposed rules 10CFR19 & 20 supplements 790416 tumments Objects to elimination of S(N-18) formula. Proposed amends are not supported by scientific data that justify mod of current rules LEWIS.L. Health Physics Society 79/04/24 ip

- 7906200219 Comments on proposed rules 10CFR19 & 20 supplements 790416 comments Objects to elimination of S(N-18) formula Proposed amends are not supported by scientific data that justify mod of current rules LEWIS.L. Health Physics Society 79/04/24 Ep
- 7906200285 Comments on proposed rule 10CFR35 approves proposed amend Suggests clarification re-actual number of recommended committee members
  WILSON,R D Wilson,R D MD 79/04/26 1p
- 7706200J01 Responds to 770425 itr re deletion of long-standing 5(N-18) dose-averaging formula from 10CFR20 Proposed action is part of broader action to strengthen stds & implementation of ALARA concept MINOGUE, R B Office of Standards Development 77/05/22 3pp
- 7906200301 Responds to 790425 ltr re deletion of long-standing 5(N-18) dose-averaging formula from 10CFR20 Proposed action is part of broader action to strengthen stds & implementation of ALARA concept MINOGUE/R B Office of Standards Devolopment 79/05/22 3pp
- --7906200304 Requests explanation of nuclear workers radiation dose stds to list of regulations now in force SACCO.E Affiliation Unknown 79/04/25 ip
- --7906200304 Requests explanation of nuclear workers radiation dose stds & list of regulations now in force BACCO.E Affiliation Unknown 79/04/23 ip
- 7906200548 Comments on proposed rules 10CFR19 & 20 changes would remove flexibility & provide little or no corresponding banefit to BURSTEIN B Wisconsin Electric Power Co 79/04/24 2pp
- 7906200548 Comments on proposed rules 10CFR19 & 20 changes would remove flexibility & provide little or no corresponding benefit to workers
  BURSTEIN, 8 Wisconsin Electric Power Co 79/04/24 2pp
- 7906200350 Comments on proposed rules 10CFR19 & 20 finds significant inconsistency in proposed rule

  \* Atomic Industrial Forum 79/04/24 4pp
- 7906200550 Comments on proposed rules 10CFR19 5 20 finds significant inconsistency in proposed rule # Atomic Industrial Forum 79/04/24 App
- 7906200553 Comments on proposed rules 100FR19 & 20 cannot support changes in present form until issues of employment status after max allowed exposure are sufficiently addressed PDRTER.B J Louisiana. State of 79704/25 2pp
- 7904200553 Comments on proposed rules 10CFR19 & 20 cannot support changes in present form until issues of amployment status after max allowed exposure are sufficiently addressed PORTER.II J Louislana. State of 79/04/25 2pp
- 7906200603 Comments on proposed rules 10CFR19 & 20 proposal of requiations is premature
  CAMILL.W J Consolidated Edison Co of New York 79/04/23 4pp
- 7906200603 Comments on proposed rules 10CFR19 & 20 proposal of regulations is premature CAMILL.W J Com

- 79062:0043 Forwards Oulf Nuclear. Inc 790411 comments on proposed rules 100FR19 & 20 PAUL.R. House of Rep. 79/04/18 ip
- TOUCHT HOUSE OF HELP PROMITE PE
- 7906210358 Comments on proposed rules 10CFRIG & 20 since EPA is gresently reviewing & updating existing federal radiation protection guidance for accupational radiation expoures, progosed amends are inappropriate ANDERSON, T M Westinghouse Electric Corp NS-THA-1979 79/04/23 Sne
- 7906210358 Comments on proposed rules 10CFR10 & 20 since EPA is presently reviewing & updating existing federal radiation protection guidance for occupational radiation expoures, proposed amends are inappropriate ANDERSON.T M Westinghouse Electric Corp NS-THA-1979 79/04/23 3pp
- 7906210362 Requests inclusion of proposed rules 100FR19 & 20 to NRC occupational radiation dose stds COHEN.N Affiliation Unknown 79/04/23 ip
- 7906210362 Requests inclusion of proposed rules 10CFR19 & 20 to NRC occupational radiation dose stds COHEN.N Affiliation Uninown 79/04/23 ip
- 7906220043 Comments on proposed rules 10CFR19 & 20 requests value/impact analysis for rule change COUNSIL.H & Northeast Utilities 79/04/20 2pp
- 7906220043 Comments on proposed rules 10GFR19 & 20 requests value/impact analysis for rule change COUNSIL.W G Northeast Utilities 79/04/20 29p
- 7706220058 Comments on proposed rules 10CFR19 & 20 proposal is unwarranted, without sound basis & would be counterproductive to orderly mgt of nuclear gower plants
  LUNDVALL.A E Baltimore Cas & Electric Co 79/04/25 2pp
- 790622005B Comments on proposed rules 10CFR19 & 20 proposal is unwarranted without sound basis & would be counterproductive to orderly mgt of nuclear power plants
  LUNDVALL.A E Baltimore Gas & Electric Co 79/04/25 2pp
- 7906220063 Comments on proposed rules 10CFR19 & 20 elimination of 5(N-18) formula is admirable step in right direction Elimination of requirement for obtaining worker's total occupational radiation exposure history is unwarranted TUCKER.K Affiliation Unknown 79/04/22 ip
- 7906220063 Comments on proposed rules 100FR19 & 20 elimination of 5(N-18) formula is admirable step in right direction Elimination of requirement for obtaining worker's total occupational radiation exposure history is unwarranted TUCKER.K Affiliation Unknown 79/04/22 1p
- 7906220430 Comments on proposed rules 10CFR70 & 73, questions whether assurance criteria will be used to upgrade rule & whether Commissioners agree w/definitions
  VON ERRENFRIED. Affiliation Unknown 79/04/23 ip
- 7904220430 Comments on proposed rules 10CFR70 & 73 questions whether assurance criteria will be used to upgrade rule & whether Commissioners agree w/definitions VON EMREMPRIED. Affiliation Unknown 79/04/23 ip
- ---7906220437 Requests info concerning proposed rules 10CFR70 & 73 VON EHRENFRIED. Affiliation Unknown 79/04/22 ip
- ---7906220437 Requests info concerning proposed rules 10CFR70 & 73 VON EHRENFRIED. Affillation Unknown 79/04/22 ip
- ---7908220447 Requests verification that Safeguards Licensing Branch & IE , will recognize & sanction use of MAIT as design tool for safeguards upgrades.

  VON EHRENFRIED. Affiliation Unknown 79/04/26 Ip
- --7906220447 Requests verification that Safeguards Licensing Branch & IE will recognize & sanction use of MAIT as design tool for safeguards upgrades.
  VON EHRENFRIED. Affiliation Unknown 79/04/26 ip
- 7906260782 Ack receipt of 790418 itr which forwarded MP Peoples comments on proposed rules 100FR19 & 20. Discusses NRC policy for radiation & dose-limiting seds 008516 kt. V. Office of the Executive Director for Operations 79/09/17. 9pp

- 7906260882 Ack receipt of 790418 ltr which forwarded WP Peeples comments on proposed rules 10CFR19 & 20 Discusses NRC palicy re radiation & dose-limiting stds 00S816K.L V Office of the Executive Director for Operations 79
- 7906260626 Comments on proposed rules 10CFR19 & 20 imposition of 3-rems/yr may pose hardship for critical drafts w/high demand & short supply BRONSON,F Health Physics Society 79/03/16 4pp
- 7906260626 Comments on proposed rules 10CFR19 & 20 imposition of 5-rems/yr may pose hardship for critical drafts w/high denand & short supply BRONGON.F Health Physics Society 79/03/16 4pp
- 7906260629 Comments on proposed rules 10CFR19 & 20 arbitrary change would undermanne worker confidence in protection sys forwards 790402 remarks at AIF conference LEE, B Commonwealth Edison Co 79/04/06 20pp
- 7906260629 Comments on proposed rules 10CFR19 & 20 arbitrary change would underwine worker confidence in protection sys Forwards 790402 ismarks at AIF conference LEC.B Commonwealth Edison Co 79704705 20pp
- 7906270016 Comments on proposed rules 10CFR19 & 20 urges retention of 5(N-18) formula No need to whiminate formula has been shown. Flexibility in emergency situations is needed & ALARA program is more effective dose limit TSCHAECHE, AN People for Energy Progress 79/04/16 3pp
- 7906270016 Comments on proposed rules 10CFR19 \$ 20 urgss retention of 5(N-18) formula No need to eliminate formula has been shown.

  \*\*eleribility in emergency situations is needed & ALARA program is more effective dose limit
  TSCHAECHE, A N People for Energy Progress 79/04/16 3pp
- 7908270173 NURFC-0170 VI NURFC-0170, Vol 1. "FES on Transportation of Radioactive Matl by Air & Other Modes " # Office of Standards Development 77/12/31 150pp
- --7906270173 NUREC-0170 VI NUREC-0170.Vol 1. "FES on Transportation of Radioactive Matl by Air & Other Modes" \* Office of Standards Development 77/12/31 150pp
- --790627017/ NUREC-0170 V2 NUREC-0170 Vol 2. "FES on Transportation of Radioactive Mati by Air & Other Modes" \* Office of Standards Development 77/12/31 225pp
- ---7906270177 NUREC-0170 V2 NUREC-0170.Vol 2. "FES on Transportaton of Radioactive Matl by Air & Other Modes" \* Office of Standards Development 77/12/31 225pp

# PRM PETITION FOR RULEMAKING

- 7906050004 Requests copy of petition submitted to NRC re certification requirements for health physics personnel DELAPAZ.A Army.Dept of 79/04/13 ip.
- 7906080225 Comments on petition for rulemaking 10CFR-6 rules of practice & other pertinent regulations shoud be amended to prescribe time periods for completion of licensing review PRATT.C M Affiliation Unknown 79/04/05 7pp
- 7906:30:17: Comments on patition for rulemaking supports generic rulemaking to improve nuclear licensing Recommends case-by-case analysis for alternate energy source issue & alternative siting methodology issue
  O'SRIEN, J M Affiliation Unknown 79/04/23 ip
- 7906130196 Comments on petition for rulemaking iOCFR20-13; current regulations require licensees to be technically qualified Proposed changes should be denied DIPIAZZA: R P Westinghouse Electric Corp WRD-LS&S-743 79/04/30 3pp
- 7906130200 Comments on petition for rulemaking 10CFR20-13, requests denial of Section 20 60D, requiring certification of health physics personnel on five levels HOUN, J R Health Physics Society 79/04/27 Gpp
- 7906130204 Comments on petition for rulemaking 100FR20-13 Section 20 600 requiring formal certification for all espects of radiation protection, is of no benefit Section would handicap staffing SULLIVAN.T J. Consumers Power Co. 179/04/27. 2pp.

## NONDOCKETED ITEMS

- 7905130209 Comments on petition for rulemaking iOCFR20-13 Section 20 600 is unnecessary Competence of health physics staff is gained from education & experience BENT2.R Public Service Co of Oklahoma 79/04/24 ip
- 7904130216 Comments on petition for rulemaking 10CFR20-13 requests demial of Section 20 600 Nuclear power station health physics depts are operated by highly qualified personnel JENCKES.T A Pacific Oas & Electric Co 79/04/27 lp
- 7906130304 Comments on petition for rulemaking 10CFR20-13 Section 20 600 should apply only to nuclear reactor facilities WILLIAMS.P R Dow Corning Corp 79/04/23 2pp
- 7906130406 Comments on petition for rulemaking 10CFR71 requests 180-day extension to file description of QA program MCCARTHY.E L. Yuba Heat Transfer Corp. 79/06/04 1p
- 7906140104 Revision of 770705 petition for rulemaking re decommissioning to require plant operators to post bonds SCHULTZ.W B , ABBUTE, J Public Interest Research Group 77/10/07
- 7906140546 Comments on petition for rulemaking iOCFR20-13 upposes rulemaking Downplays importance of academic requirements for health physicists
  KATHREN.R L. Affiliation Unknown 79/04/17 4pp
- 7906140998 Comments on petition for rulemaking lOCFR20-13 apposes rulemaking Addl certification of health physicists is no guarantee of competence or immunity from bad practice MANN.J R Affiliation Unknown 79/04/20 3pp
- 7906140563 Communts on petition for rulemaking tOCFR20-13 opposes rulemaking Covt should not certify profs or specify min experience requirements WEGST.W F California Institute of Tachnology 79/04/18 2pp
- 7906140569 Comments on petition for rulemaking IOCFR20-13 opposes rulemaking Classifications for certification lack specificity Current sys is sufficient CURTIS.N W Pennsylvania Power & Light Co 79/04/17 2pp
- 7906i40573 Comments on patition for rulemaking 10CFR20-13 opposes rulemaking Existing American Board of Health Physics certification program practides need for govt program HOLEMAN.OR Vale Univ 79/04/19 2pp
- 7905190504 Requests 30-day extension to comment on petition for rulemaking 10CFR20-13 TERPILAKAM 8 Affiliation Unknown 79/04/20 ip
- 790620021B Comments on petition for rulemaking 10CFR71 questions necessity for users to develop GA program Beaks examption for low level radiation sources Requests extension of 780701 deadline for submission of GA program
  OAMBLE.O C Nuclear Energy Service, Inc 78/06/01 1.0
- 7906200223 Comments on petition for rulemaking 10CFR20-13 approves 20 600 which incures high stds for personnel in field of radiation protection Disapproves of portion denuing licansee power to override decisions of certified health physicists RUBY,L. California, Univ. of, Berkeley 79/04/19 2pp
- 7906200568 Comments on petition for rulemaking 10CFR20-13: amend will not contribute to current certification process Will only administratively burden NRC.
  RENZETTI,J L. Navy, Dept of 79/04/30 ip
- 7906200572 Comments on petition for rulemaking iOCFR20-13. supports petition Belisves certification of health physics personnel should be open to public scrutiny ROBINSON(G J. Affiliation Unknown 79/04/27 ip
- 7906200579 Comments on petition for rulemaking 100FR20-13 not in best interest of NRC to engage in certification of individual personnel MERCER, D D Montana, State of 79/04/26 2pp
- 7906200586 Comments on petition for rulemaking 10CFR20-13 should not by adopted Proposal to have NRC certify radiation protection personnel is unnecessary in view of existing license review procedures

  \* Army, Dept of. 79/04/26 2pp
- 7906200594 Comments on petition for rulemaking 10CFR20-13.petition implies NRC is not presently evaluating qualifications of health physicists or radiation safety officers which is not true.
  - true. \* Affiliation Unknown. 79/04/24, 2pp

- 7906200600 Comments on petition for rulemaking 10CFR20-13 proposed amends have previously been addressed by NRC in reg guide No need for new amends
  LANGER,R R Dow Chemical Co 79/04/25 2pp
- 7906200616 Comments on petition for rulemaking 10CFR2-7 strongly supports making proposal easier MANUS.R Affiliation Unknown 79/04/20 1p
- 7906210400 Fifteen public interest groups request NRC amend emergency procedures re-accidental release of radioactivity Proposed amends involve population evacuation, monitoring equipment & certification of procedural adequacy BANCROFT.M H Public Citizen Litigation Group POLLOCK, R Critica Mass Energy Project 79/03/09 19pp
- 790A220041 Comments on petition for rulemaking 10CFR20-i9 proposed action should be considered as only one of several possible responses to problem HILLIG.C A Philippines 77/04/10 3pp
- 7906220059 Requests petition for rulemaking 190FR20-13 which would require health physics personnel to be certified by NRC DELAPAZ.A Army, Dept of, White Bands Missile Range STEWS-TE-AN 79/04/13 1p
- 790622006: Comments on petition for rulemaking iOCFR20-13 petitioner has not demonstrated existence of pressure on health physics personnel to engage in bad practices PARKER.W O Dute Power Co 79/04/30 2pp
- 7906220149 Comments on petition for rulemaking 10CFR20-13 since healt; physicists are certified by American Board of Health Physics:amend would duplicate procedures. Does not approve of federal govt entering judgment of competence COURTNEY. J C Affiliation Unknown 79/04/19 1p
- 7904250129 Comments on petition for vulemaking 10CFR20-13 proposed certification program unnecessary in light of present measures for ensuring high level of health physics competence

  UHRIO.R E Florida Power & Light Co L-79-105 79/04/27 2pp
- PROJECTS PREDOCKET LICENSING
- 7906010009 Summary of 790418-19 moeting w/ANL in Argonno, IL re preparation of final QFIS on handling & storage of spent LHR fuel ROBERTS, J. P. Fuel Reprocess & Recycle Branch 79/05/02 1p
- 7906010242 Forwards FSAR Amend 35. "Changes to Section 13 3."
  HEDL-TI-75002-35
  SCHADE,A R Hanford Engineering Development Laboratory 79/04/18
- 7906010320 Furwards 780907 ltr stating specs for monitor wall, in response to request for info re mealing of Holf Park mine what & monitor well Aims forwards 790405 ltr re seepage reduction from impoundment, resulting from tailings removal MCGRATH.E J McOrath. E J 79/04/19 Spp
- 7906010335 Requests info re tailings impoundment Review will be completed upon raceipt of response SCARAND.R A Fuel Process & Fab Branck 79/03/06 4pp
- 7906020069 "Nonproliferation Alternative Bys Assessment Program Heavy Mater Reactor," preliminary safety & environ info document, Vol II, Revision 1 # Energy, Dept. of 79/04/30 85PP
- 7906020071 "Nonproliferation Alternative Sys Assessment Program High Tamp Gas Cooled Reactors," preliminary safety & environ info document. Vol 1V. Revision 1 # Energy, Dept of 79/04/30, 190pp
- 7906020073 "Nonproliferation Alternative Sys Assessment Program LWRs. preliminary safety & environ info document. Vol I. Revision I \* Energy. Dept of 79/04/30 200pp
- 7906020074 "Nonproliferation Alternative Sys Assessment Program LMFB preliminary safety & environ info document, Vol VI, Revision I Energy, Dept of 79/04/30 190pp
- 7906020077 "Numproliferation Alternative Sys Assessment Program Gas Cooled Fast Reactor," preliminary safety & environ info document Vol V.Revision 1 « Energy, Dept. of 79/04/30, 130pp

- 790A020080 "Preconceptual Study of Proliferation-Resistant Heterogeneous Oxide Fueled LHFBR Core," final rept.Vol 1 BACK,C N , CARELLI,M D , COFFIELD,R D Hestinghouse Electric Corp 78/11/70 2/5pp
- 7906020082 "Preconceptual Study of Proliferation-Resistant Heterogeneous Oxide Fueled LMFBR Core." final rept.Vol 2 \* Wastinghouse Electric Corp 78/11/30 385pp
- 7906020087 GEFR-0G392
  "Preconceptual Design Study of Proliferation-Resistant Homogeneous Quide Fueled LMFBR Cores"
  TALWAR B General Electric Co UC-79B 78/11/30 205pp
- 7906020091 ESG-80E-13244
  "Preconceptual Study of 1,000 MW Carbide-Fueled LMFBR
  Designs," summary rept
  VITTI.JA . FELTEN.L D . BRITTINGHAM.J C Rockuell International
  Corp UC-79E 78/09/30 170pp Available at NTIS
- 790602014: Transcript of 790517 meeting in Betnesda.MD Pp 2.663-2.769 MILLERIM E . WENNER.S Atomic Safety and Licensing Board Panel 79/05/17 106pp
- 7904020214 Forwards NUREG-0511, "Draft Generic EIS on U Hilling " 5 FR rotice Rept withheld (ref 10CFR2 790) SCARAND, R A Uranium Retovery Licensing Branch 79/04/23 2pp
- 7906040161 Requests util not be required to answer certain interrogatories from CA Dept of Water Resources Requests remaining interrogatories be deferred, pending response to util interrogatories Certificate of Svc encl
  DDYLE.M M , ARMSTRONG.H H McCutchen, Doyle, Brown & Emerson FURBUSH,H H Pacific Gas & Electric Co 79/04/23 16pp
- 7906040372 Responds to 790426 itr requesting EIS CP application never filedino EIS issued REGAN.W H Environmental Projects Branch 2 79/05/14 ip
- 7906050118 Advises that JR Goldberg will present ASLAB w/oral argument on Behalf of NRC re Southern CA Edison Co appeal from ASLB 790125 order GOLDBERG, JR Anti-Trust Division 79/05/04 1p
- 7906090410 Responds to alleged self-serving ltr of 790412 Assumes mischaracterizations are further attempt to influence case re notion to grant discovery before NRC MCDIARHID,R C Spiegel & McDiarmid 79/04/16 (p
- 7906060010 Defines issues that parties will be expected to address at 790522 oral argument DUFLO.NE Atomic Safety and Licensing Appeal Panel 79/05/04 2pp
- 7906060214 Transcript of 790515 meeting in Bethesda, MD Pp 2,235-2,435 MILLER: M E , LUTON, E , WENNER, S Atomic Safety and Licensing Board Panel 79/05/15 201pp
- 7906060219 Transcript of 790522 hearing in Bethesda: MD Pp 1-130 ROSENTHAL: A . FARRAR: M . SALZMAN: R Atomic Safety and Licensing Appeal Panel 79/05/22 133pp
- 7906070037 Forwards Fleischater 790430 FOIA request for documents obtained through civil investigative demand re util proposal to construct Mendacino project OOLDBERGLJ R Anti-Trust Division 79/05/04 ip
- 7906070322 Response by CA Dept of Hater Resources in apposition to PGBE motion for protective order re RH Gerdes deposition Certificate of Syc encil unoN.H C California, State of 79/04/13 16pp

- 7906180765 NUREG-0338
  "SER Related to Operation of FFTF, Suppl 1 "
  "Diffice of Nuclear Reactor Regulation 448 79/05/31 130pp
  Available at NTIS
- 7906190007 Notice that ASLAB for antitrust proceedings has three members RS Saliman, McFarrar & AS Rosenthal, Chairman SKRUTEKI, R M Atomic Safety and Licensing Appeal Panel 7590-0179/05/17 ip
- 7906200558 Progress rept re State of CA Dept of Water Resources 780925 request for computer-stored documents Forwards item-by-item description of documents & draft stipulation to protective order Certificate of Syc encl
  MEISS, R L , FURBUSHAM H Pacific Oas & Electric Co ARMBTRONG, N H
  McCutchen, Dogle, Frown & Emerson 79/04/30 74pp
- 7906210372 Seeks denial of util motion for protactive order re 790402 fourth set of interrogatories from CA Dopt of Mater Resources Util cannot justify request for extension, objections to questions are inconsistent & unsubstantial DEMMEDIAN, G. GRUSKIN, S.N., HORN, H.C. California, State of 79705708 1800
- 7906220479 Directs util to submit all info & matl promised in response to NRC motion to compel discovery, along w/addl info to which util & NRC agreed during informal discussions Requests response within 30 days
  MILLER, M E Atomic Safety and Licensing Board Panel 79/09/16 Ip
- 7906260505 Responds to NRC 790503 motion to compel discovery Util supplies addl info to Questions 2-B re load dropping ability, annual min loads, native load, capacity sales & purchases & energy bank Certificate of Svc encl WEISS, R Pacific Gas & Electric Co DUYLE, M M ARMSTRONO, W M McGutchen, Doyle, Brown & Emerson 79/05/11 14pp
- 7906260950 FOIA request for copies of documents obtained by NRC from DDJ re PGVE proposal to construct Mendacino project FLEISCHAKER, D. S. Center for Law in the Public Interest 79704/30 to
- 7906260555 Responds to FOIA request for documents made available to MRC by DDJ re POME proposal to construct Mendacino project Forwards index to 140 microfilm rolls FELTON.J M Division of Rules and Records. 79706/12 Ip
- --7906260557 Index to 148 microfilm rolls provided by CA Dept of Water Resources Matl involves PG&C Jan-Mar 1973 memos re proposal to construct Mendocino project Encl available in Central Files \* California, State of 79/06/12 229pp
- 7906290698 Requests preparation of proposal relisolation of new yellowcake calciner & new yellowcake barreling operation from rest of bidg & provision of addlemission control HAZLE.A J Colorado, State of 79/05/22 2pp
- 7906270803 Requests that NRC make all dispersion & deposition evaluations of radiological & chemical exposure to Lincoln Park area due to present offsita groundwater contamination caused by seepage from existing Cotter mill tailings ponds HAZLE: A J Colorado: State of 79/03/04 4pp
- PT21 NONCOMPLIANCE REPORTS AND RELATED CORRESPONDENCE
- 7905150650 Forwards itr re ADLPIPE program for computing piping response to various static & transient loads Requests info be considered as Part 21 rept DINOWELL, I W. Arthur D. Littie, Inc. 79/04/19 19
- --7905190697 Forwards memo confirming info furnished at 790416 meeting w/NRC re ADLPIPE program for computing piping response to various static & transient loads Five benchmark solutions will be verified Lists ADLPIPE licensees
  DINGWELL, I W Arthur D Little, Inc 79/04/19 29pp
- GARRY GUALITY ASSURANCE INSPECTIONS

В

ŀ

- 7906010105 Ack receipt of 790411 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990074779-01 POTAPOVS.U. Region 4. Dalles, Vendor Inspection Branch
  - 7906010108 Responds to NRC 790315 ltr re deviation noted in QA Program
    Insp Rept 99700074/79-01 Corrective actions.W-122 weld
    procedure has been revised to (ncorporate backing ring tack
    welding
    MENSON,J L Diamond Power Specialty Corp (subs of Babcock &
    Wilcox) 79/04/11 2pp.

- ---7905010110 Forwards GA Program Insp Rept 99900074/79-01 on 790227-0302 & notice of deviation POTAPOVS,U Region 4. Dallas, Vendor Inspection Branch 79/03/15 2pp
- --7906010112 Notice of deviation from insp on 790227-0302 POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 79/03/15 1p
- --7906010114 GA Program Insp Rept 99900074/79-01 on 790227-0302 Noncompliance noted tack welding procedures not developed & qualified ELLERSHAWL E , HUNNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/03/14 7pp
- 770&050159 Ack receipt of 770420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 9700306/79-01 POTAPOVA,U Region 4. Dallas, Vendor Inspection Branch 79/05/03 1p
- ~-7904050163 Responds to NRC 790407 ltr re deviation noted in GA Program Insp Rept 99900306/79-01 Corrective actions dead weight tester calibr source changed to obtain more timely svc BGNNER.E J Leslie Co 79/04/20 3pp
- --7906050169 Forwards QA Program Insp Rept 99900306/79-01 on 790312-16 & notice of deviation PCTAPOVS,U Region 4. Dallas, Vendor Inspection Branch 79704/09 2pp
- --7706050171 Notice of deviation from insp on 770312-16
  + Region 4, Dallas. Vendor Inspection Branch 77/04/06 ip
- --7906050177 GA Program Insp Rept 99900306/79-01 on 790312-16
  Roncompliance noted master test gage not calibr as
  prescribed % assembly instruction procedure not
  reviewed by GA manager.
  SUTTON.J W., WHITESELL.D W. Region 4, Dallas, Vendor Inspection
  Dranch 79/04/06 9pp
- 7906050165 Ack receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in QA Program Insp Rept 99900049/79-01 POTAPQV9,U Region 4, Dallas, Vendor Inspection Branch 79/05/03 1p
- --7906050170 Responds to NRC 790406 ltr re deviation noted in GA Program Insp Rept 99900049/79-01 Corrective actions nonconformance rept issued & recaiving insp personnel instructed to create noncomformance rept for all nonconforming conditions TONEATTI.V W Atwood & Morrill Co , Inc (subs of Foster Wheeler Corp ) 79/04/20 2pp
- --7906050174 Forwards GA Program Insp Rept 97900049/79-01 on 790321-23 & natice of deviation POTAPOVS,U Region 4. Dallas, Vendor Inspection Branch 79704/06 2pp
- --7906050179 Notice of deviation from insp on 770321-23
  \* Region 4, Dallas, Vendor Inspection Branch 79/04/09 2pp
- --79060301B2 GA Program Insp Rept 99900049/79-01 on 790321-23
  Noncompliance noted receiving inspector processed cover on
  Drawing C-24237, although cover had outside diameter of
  29 4373 Inches
  KELLEY, H D , WHITESELL, D E Region 4, Dallas, Vendor Inspection
  Branch 79704/05 Bpp
- 7906050186 Ack receipt of 790426 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900004/79-01 PDTAPUVB.U Region 4: Dallas, Vendor Inspection Branch 79/03/03 ip
- --7908050198 Responds to NRC 790328 ltr re deviations noted in QA Program Insp Rept 9990004/79-01. Corrective actions change notices not released unless all changes are clearly noted & new quality-related analytical chemistry procedures under review RICKARD.C.L. General Atomic Co (subs of Quif Oil Corp.) 79/04/26. 7pp
- --7906050198 Forwards QA Program Insp Rept 99900004/79-01 on 790226-0301 & notice of deviation. POTAPOVS.U. Region 4. Dallas, Vandor Inspection Branch. 79/03/26. 2pp.
- --7906050204 Notice of deviation from insp on 790226-0301.
  \* Region 4, Dallas, Vendor Inspection Branch 79/03/19 3pp.

- ~~7906050208 GA Program Insp Rept 99900004/79-01 on 790224-0301
  Noncompliance noted:certain design activities not properly
  implemented & analytical chemistry lab procedures not
  revisued as prescribed
  MCMEILL.W M , WHITESELL D E
  Inspection Branch 79/03/19 App
- 7906060044 Ack receipt of 790417 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900205/79-01 PDTAPOVS,U Region 4. Dallas. Vendor Inspection Branch 79/05/02 1p
- --7906060048 Responds to NRC 790330 ltr re deviation noted in GA Program Insp Rept 99900205/79-01 Corrective actions correct certifications received from supplier CARREAU,0 Process Equipment Co , Inc 79/04/17 1p
- --7906060052 Forwards GA Program Insp Rept 99900205/79-01 on 790312-13 D notice of deviation POTAPOVS.U Region 4, Dalias, Vendor Inspection Branch 79/03/30 2pp
- --7906060053 Notice of deviation from insp on 790312-13 \* Region 4, Dallas, Vendor Inspection Branch 79/03/28 ip
- --7906060059 GA Program Insp Rept 99900205/79-01 on 790312-13 Noncompliance noted certificate for developer had batch number different from batch number on developer cans ELLERSHAHLE E, HUNNICUTT, DM Region 4, Dailas, Vendor Inspection Branch 79/03/28 4pp
- 7906060070 Act receipt of 790308 & 0420 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900277/79-01.
  PDTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 79/04/30 ip
- ---7906060075 Responds to NRC 790330 1tr re deviation noted in GA Program Insp Rept 99900297/79-01 Corrective actions GC Inspected terminals & marked damaged ones requiring replacement Power operated screwdrivers banned from area LEATHERS,F H Foxboro Co 79/04/20 ip
- --7906060080 Ack receipt of 790308 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900297/79-01 Add1 info required specific description of steps necessary to correct defective terminals POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 79/03/30 ip
- --7906060086 Responds to NRC 790202 ltr re deviation noted in GA Program
  Insp Rept 79700277/77-01 Corrective actions audits will be
  conducted & customers will send test rept on wire & cable
  used on panel jobs
  DENZER.H O Foxboro Co 79/03/08 3pp
- ---7906060074 Forwards QA Program Insp Rept 99900277/79-DE on 790116-19 & notice of deviation BEYERIT.K V Region 4. Dallas. Office of the Director 79/02/02 2pp
- --7904060097 Notice of deviation from insp on 790116-19 SEYFRIT,K V Region 4, Dailas, Office of the Director 79/01/29 2pp
- --7906060101 GA Program Insp Rept 99900297/79-01 on 790166-19
  Noncompliance noted failure to take committed corrective action & damaged insulation of reinsulated terminals not consistent w/Criterion V of 10CFR50.App B FOSTER.W E , HUNNICUTT.D M Region 4. Dallas, Vandor Inspection Branch 79/01/29. App.
- 7706060104 Forwards QA Program Insp Rept 97900002/79-01 on 790312-14 A notice of deviation PDTAPOVB.U Region 4, Dallas? Vendor Inspection Branch 77903/30 2pp.
- ---7906060108 Notice of deviation from insp on 790312-16

  \* Region 4: Dallas, Vendor Inspection Branch 79/03/29 ip
- --7906060115 GA Program Insp Rept 99900002/79-01 on 790312-16.
  Noncompliance noted fuel rod travelers signed off before completion of hydrogen testing.
  MCNETILL, W. M. WHITESELL, D. E. Region 4. Dailas, Vendor Inspection Branch 79/03/29 7pp
- 7906070019 Ack receipt of 790423 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900356/79-01 POTAPOVB.U. Region 4, Dallas, Vendor Inspection Branch. 79/05/03, ip

- --7906070022 Responds to NRC 790320 ltr re deviation noted in QA Program Insp Rept 99900356/79-01 Corrective actions QC manual revised to include duties & authorities of all personnel performing quality-related activities DUNCAN.C F Burndy Husky 79/04/23 7pp
- ---7906070023 Forwards GA Program Insp Rept 99900356/79-01 on 790212-15 & notice of deviation POTAPOV8.U Region 4, Dallae, Vendor Inspection Branch 79/03/20 2pp
- --7906070025 Notice of deviation from insp on 790212-15
  \* Region 4. Dallas, Vendor Inspection Branch 79/03/07 ip
- --7906070026 QA Program Insp Rept 97900356/79-01 on 790212-15 Noncompilance noted failure to clearly delineate duties & responsibilities of personnel & failure to include mgt policy statement in QA program SUTTON.J W , WHITESELL, D E Region 4. Dallas, Vandor Inspection Branch 79/03/07 12pp
- 7906070020 Forwards QA Program Insp Rept 99900314/79-01 on 790226-0301 No noncompilance noted POTAPOUS.U Region 4. Dallas. Vendor Inspection Branch 79/03/26 2pp
- --7906070031 GA Program Insp Rept 99900314/79-01 on 790226-0301 No noncompliance noted Major areas inspected implementation of 10CFR50, App B criteria, other NRC requirements & applicable codes & stds CLLER:R E . HUNNICUFT, D M Region 4, Dallas, Vendor Inspection Branch 79/03/23 16pp
- 7906120022 Forwards GA Program Insp Rept 99900005/79-01 on 790402-06. No noncompliance noted PDTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 79/04/20 200
- --7906120028 GA Program Insp Rept 99900005/79-01 on 790402-06 No noncompliance noted Major areas inspected implementation of topical regit & other applicable codes & sids, moisture & hydrogen controls & pellet attributes MONEIL.W M. HHITESELL, D.E. Region 4, Dallas, Vendor Inspection Branch 79/04/19 9pp
- /906160004 Ack receipt of 790202 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990031/79-02 POTAPOVS.U Region 4, Dallas, Office of the Director 79/03/26
- --7906160005 Responds to NRC 790312 itr requesting add1 info re deviation noted in GA Program Insp Rept 99900031/79-GZ Corrective actions purchase orders will be forwarded to QA for approval HENSLER, D.A. βingham-Willamette Co /9/03/16 2pp
- --7906160006 Requests add1 info to complete rayiew of response to deviations from GA Program Insp Rept 99900031/79-02 POTAPDV8.U Region 4. Dailas. Office of the Director. 79/03/12 ip
- ~7906160007 Responds to NRC 781219 ltr re deviations noted in GA Program Insp Rept 99900031/79-02. Corrective actions beam welder recalibr & work order format being revised TMARP/W.E. Bingham-Hillamette Co. 79/02/02. 8pp
- -7906160008 Forwards GA Program Insp Rept 99900031/79-02 on 78:113-16 & f deviation

- ---7906180244 Responds to NRC 790227 ltr re deviations noted in QA Program
  Insp Rept 99900302/79-01 Corrective actions QA manual
  updated & personnel qualification records refiled
  GOLDBERO, H R Wastern Piping & Engineering Co . Inc 79/04/04
  300
- --7906180231 Forwards GA Program Insp Rept 99900302/79-01 on 790122-29 & notice of deviation POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 79702/27 2pp
- --7906180255 Notice of deviation from insp on 790122-29
  Region 4. Dalias. Office of the Director 79/02/26 2pp
- --7906180263 GA Program Insp Rept 99900302/79-01 on 790122-29
  Noncompliance noted failure to take committed corrective
  actions Helding procedures specs packages did not contain
  required qualification of personnel records
  SUTTON-J W. WHITEBELL.D E Region 4, Dallas, Vendor (napaction
  Branch 79/02/26 9pp
- 7906180654 Ack receipt of 790316 ltr informing NRC of steps taken to correct deviations noted in GA Program Insp Rept 99900340/79-01 PDTAPGV8.U Region 4, Dallas, Vendor Inspection Branch 79/03/26. ip
- ---7706180659 Responds to NRC 770213 ltr re deviations noted in GA Program Insp Rept 97900340/79-01 Corrective actions all assembly & research torque wrenches will be maintained in central location BARCLAY.J F Yarway Corp 79/03/16 ip
- --7906180663 Forwards GA Program Insp Rept 99900340/79-01 on 790123 & notice of deviation POTAPDVS.U Region 4. Dallas. Vendor Inspection Branch 79/02/13 2pp
- --7906180666 Notice of deviation from insp on 790123
  \* Region 4. Dallas. Vendor Inspection Branch 79/02/13 ip
- --7906/80670 GA Program Insp Rept 99900340/79-01 on 790123 Noncompliance noted assembly & research torque wrenches were found w/calbr due date of 78/108

  KELLEY,W D. HHITESCLL,D E Region 4, Dallas, Vendor Inspection Branch 79/02/12 App
- 7906190030 Ack receipt of 790423 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900305/79-01 POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 79/05/03 ip
- ---7906190035 Responds to NRC 790201 ltr re deviation noted in QA Program
  Insp Rept 99700505/79-01 Changes dates of commitment for
  corrective action agreed to at 790413 meeting
  YEMIER, B E Ebasco Services, Inc (subs of Enserch Corn '
  70/04/23 ip
- 7706190039 Act receipt of 790418 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900033/79-01 POTAPDVS.U Region 4, Dallas, Vandor Inspection Branch 79/03/03 Ip
- ---7906190046 Responds to NRC 790406 ltr re deviation noted in GA Program
  Insp Rept 99900053/79-01 Corrective actions: drawings in
  question have been revised to show correct dimensions Welds
  have been repaired
  KNIESER, GW Anchor/Darling Valve (subs of Anchor/Darling
  Industries, Inc.) 79/04/18 ip
- ---7906190052 Forwards GA Program Insp Rept 79900053/79-01 on 790221-23 & notice of deviation POTAPOVS,U Region 4: Dellas, Vendor Inspection Branch 79/04/06, 2pp
- -7904190047 Notice of deviation from insp on 790221-23 POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch. 79704/03 1p.
- --7906190074 OA Program Insp Rept 99900033/79-01 on 790221-23.

  Noncompliance noted failure to adhere to min size socket weld specified in ABME code & fillet well less than min size specified

  KELLEY.W.D. HITTEBELL.D.E. Region 4, Dallas, Vendor Inspection Branch. 79/04/03, 9pp.

## NONDOCKETED ITEMS

- 7905190080 Act receipt of 790420 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990401/78-04
  POTAPOVS, U Region 4. Dallas. Vendor Inspection Branch 79/05/03. 1p
- --77061900B1 Responds to NRC 790321 ltr re deviation noted in GA Program Insp Rept 99900401/78-04 Corrective actions revision to GA of design manual ETHERIDGE.M R Combustion Engineering, Inc. 79/04/20 App
- /906210058 Forwards GA Program Insp Rept 99900057/79-01 on 790312-15
  No noncompliance noted
  PDTAPDVS, U Region 4, Dallas, Office of the Director 79/04/02
- --7906210059 GA Program Insp Rept 99900037/79-01 on 790312-15 No noncompliance hoted Major areas inspected implementation of 10CFRSO App B criteria, other NRC requirements & applicable codes & stds & action on previous insp findings 0LLER.R E . HUNNICUTI.D M Region 4. Dallas, Office of the Director 79/03/30, 10pp
- 7906210061 Forwards QA Program Insp Rept 99900240/79-01 on 790306-08 No noncompliance noted POTAPOVB.U Region 4. Dallas. Office of the Director 79/04/03.
- ---7906210069 GA Program Insp Rept 99900240/79-01 on 790306-08 No noncompliance noted Major areas inspected implementation of 10CFRSO App B criteria & customer requirements, including insp of GA manual/program design control & contracts ACEE, J R Region 4, Dallas, Office of the Director 79/04/03 Spp.
- 7906210074 Act receipt of 790423 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9990036/79-01 POTAPOVE, U Region 4, Dallas. Office of the Director 79/05/09 10
- --7906210076 Responds to NRC 790319 ltr re deviation noted in GA Program
  Insp Rept 99900036/79-01 Corrective actions in-process
  rejection notice issued & disposed of & responsible foremon
  reinstructed re welding machine settings
  BATES: B J . MILLER, L C . STONE, W A Combustion Engineering, Inc
  79/04/23 2pp
- --7906210080 Forwards QA Program Insp Rept 99900036/79-01 on 790226-0302 & notice of deviation PDTAPDV8.U Region 4, Dallas. Office of the Director 79/03/19
- --7906210083 Notice of deviation from insp on 790226-0302.

  \* Region 4, Dallas, Office of the Director 79/03/16 ip
- --7906210086 GA Program Insp Rept 99900036/79-01 on 790226-0302.
  Noncompliance noted welder was not welding within specified amperage range
  HONTER,V H. HHITEBELL,D E. Region 4: Dailas, Office of the
  Director 79/03/16 Spp
- 7906210088 Ack receipt of 790430 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9900032/79-01 POTAPOVS.U Region 4, Dallas, Office of the Director 79/05/15.
- ---7906210091 Responds to NRC 790404 ltr re deviation noted in GA Program Insp Rept 9990052/79-01 Corrective actions.QA manual is being revised to assure adequacy of review of mods to design & technical requirements

  ORFENE,J J. Crosby Valve & Gage Co. GA-JG-4215 79/04/30. 2pp
- ~~7906210093 Forwards GA Program Insp Rept 99900052/79-01 on 790320-21 & motice of deviation POTAPOVS.U Region 4, Dailes, Office of the Director. 79/04/04.
- ---7906210097 Notice of deviation from insp on 790320-21 Region 4, Dallas, Office of the Director 79/04/03 ip.
- ---7906210099 GA Program Insp Rept 99900052/79-01 on 790320-21
  Noncompliance noted:deviations re design verification & audits.

  KELLEY: M. D., 'HHITEBELL, D. E. Region 4, Dallas. Office of the Director. 79/04/03. 10pp.

- 7906210297 Ack receipt of 790327 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900047/79-01 POTAPOVB.U Region 4. Dallas. Vendor Inspection Branch 79/04/05 1p
- --7906210307 Responds to NRC 790220 ltr re deviation nuted in GA Progra Insp Rept 99900047/79-01 Corrective actions revised electrode checkout log & 2-h limit established for exposing electrodes to ambient temp & humidity MILLER, T D Westinghouse Electric Corp 014-79-TDM 79/03/27 40p
- --7906210312 Forwards GA Program Insp Rept 99900047/79-01 on 790108-12 & notice of deviation POTAPOVB,U Region 4, Dalias, Vendor Inspection Branch 79/02/20 2pp
- --7906210316 Notice of deviation from insp on 790108-12 \* Region 4, Dallas, Office of the Director 79/02/15 2pp
- --7906210322 GA Program Insp Rept 99900047/79-01 on 790108-12 Noncompliance noted improper control of weld electrodes HUNTER:V M , KELLEY,W D , WHITESELL,D E Region 4, Dallas, Vendor Inspection Branch 79/02/15 12pp
- 7906210326 Ack receipt of 790312 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900030/79-01 PDTAPDUS,U Region 4, Dallas, Vendor Inspection Branch 79/03/26 ip.
- ~~7906210331 Responds to NRC 790222 ltr re deviation noted in QA Progr.
  Insp Rept 99900038/79-01 Corrective actions revision of
  maint control procedure & procedure specs for welding
  machines
  AMAND.M Ishikawajima Harima Heavy Industries Co ,Ltd.
  QAO-9L-016 79/03/12 3pp
- ---7906210335 Forwards GA Program Insp Rept 99900038/79-01 on 790108-12 % notice of deviation PUTAPOVB.U Region 4. Dallas. Vendor Inspection Branch 79/01/30 2pp
- --7406210338 Notice of deviation from insp on 740108-12 \* Region 4. Dallas. Office of the Director 74/01/26 ip.
- --7906210344 GA Program Insp Rept 9990003B/79-01 on 79010B-12 Noncompliance noted nonconsistent calibr procedures for welding control BARNES, I, HONNICUTT, D M Region 4, Dallas, Vendor Inspection Branch 79/01/24 11pp
- 7906210401 Forwards QA Program Insp Rept 99900098/79-01 on 790312-15. No noncompliance noted PDTAPQVB.U Region 4. Dallas, Vendor Inspection Branch 79/04/09 2pp
- --7906210406 GA Program Insp Rept 99900098/79-01 on 790312-15 No noncompliance noted Major areas inspected implementation of 10CFR30. App B criteria & applicable codes & stds. including inspectes & weld mati control HUNTER, V H Region 4. Dallas. Vendor Inspection Branch 79/04/06 6pp.
- 7906220210 Ack receipt of 790425 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900507/79-01.
  POTATOVB,U Region 4: Dallas, Vendor Inspection Branch 79/05/09. io
- --7906220213 Responds to NRC 790330 ltr re deviation noted in GA Progr Insp Rept 9990507/79-01 Corrective actions project instruction PI-88-1:Revision 4.will be revised & notification of scheduled revision will be issued by 790430. MCFARLAND:J E Bargent & Lundy: Inc 79/04/25 3pp
- ---7908220216 Forwards GA Program Insp Rept 99900507/79-01 on 790312-16 & notice of deviation. POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch. 79/03/30 2pp
- --790622021B Notice of deviation from insp on 790312-16
  \*\* Region 4, Dallas, Office of the Director 79/03/28. 1p
- --790622022 GA Program Insp Rept 99900507/79-01 on 790312-16
  Noncompliance noted project instruction covering project
  status repts did not mest requirements & some
  signatures on GA record submittal schedules not dtd.
  COSTELLO, J. R., BROWN, R. L. HALE, C. J. Region 4, Dallas, Vendor
  inspection Branch 79/03/30 idpp.

- 7906230025 Ack receipt of 790501 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900317/79-01 PDTAPOVS, U Region 4, Dailas, Vendor Inspection Branch 79/05/10 10
- --7906230028 Responds to NRC 790409 ltr re deviation noted in GA Program Insp Rept 99900317/79-01 Corrective actions master sheet has been reviewed & reminder forms issued for corrective action requests delayed past 30 days

  BENDER, B B Cooper Industries, Inc., Cooper Energy Services Div 79/05/01 5pp
- --7906230030 Forwards GA Program Insp Rept 99900317/79-01 on 790319-23 & notice of deviation SEYFRIT.X V Region 4. Dallas. Office of the Director 79704/09 2pp
- --7906230033 Notice of deviation from imap on 790319-23
  \* Region 4, Dallas, Office of the Director 79/04/09 4pp
- --7906230035 GA Program Insp Rept 99900317/79-01 on 790319-23
  Noncompliances noted failure to take preventive measures
  within committed time for deviation identified in Insp Rept
  99900317/78-01 re mfg process control
  FOSTER.W E . HUNNICUTT.D M Region 4, Dallas, Vendor Inspection
  Branch 79/04/05 12pp
- 7906230032 Forwards GA Program Insp Rept 99900503/79-01 on 790411 No noncompliance noted POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 79704/30 1p
- --7906230036 GA Program Insp Rept 9990503-79-01 on 790411 No noncompliance noted Major areas inspected implementation of Rept B&ROE COM-NP-1A.including initial mgt meeting ANDERSON.D G. POTAPOUS,U. HALE.C J. Region 4. Dallas. Vendor Inspection Branch 79/04/27 3pg
- 7906230048 Forwards QA Program Insp Rept 99900209/79-01 on 790314-15 No noncompilance noted POTAPDUS U Region 4. Dallas, Vendor Inspection Branch 79/04/03 2pp
- --7906230049 GA Program Insp Rept 99900209/79-01 on 790314-15 No noncompliance noted Major areas inspected followup on IOCFR21 rept re possible deficiencies of fabricated rigid rod struts.Bergen-Paterson Part 2.000 CLLERSHAN,L C., HUNNICUTI.D H. Region 4, Dallas, Vendor Inspection Branch 79/04/03 4pp
- 7906230051 Forwards QA Program Insp Rept 99900357/79-01 on 790305-07 No noncompliance noted PGTAPOUS,U Region 4, Dallas, Vendor Inspection Branch 79/04/04 2pp
- --7906230052 GA Program Insp rapt 99900357/79-01 on 790305-07 No noncompliance noted Hajor areas inspected implementation of 10CFR30 App B & applicable codes & stds & vendor corrective action re 10CFR21 rapt KELLEY, N D , WHITESELL, D E Region 4, Dallas, Vendor Inspection Branch 79/04/02 14pp
- 7906230055 Ack receipt of 790214,0411 & 12 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp. Rept 9900017/78-02.
  SEYFRIT.K V Region 4. Dellas, Office of the Director 79/05/10

- ---7906230066 Notice of deviation from insp on 781127-30
  \* Region 4, Dallas, Office of the Director 78/12/19 4cc
- --790623006B GA Program Insp Rept 97900017/78-02 on 781127-30 Noncompliance noted deviations re action on previous insp findings.design control.post-weld heat treatment & mfg process control BARNEB: I, RODERDS.H W., HUNNICUTT.D M. Region 4, Dallas, Vander Inspection Branch 78/12/13 17pp
- 7906230069 Forwards GA Program Insp Rept 99900114/79-01 on 790226-0303 & notice of deviation POTAPOVB,U Region 4, Dallas, Vendor Inspection Branch, 79/04/02 2pp
- --7906230071 Notice of deviation from insp on 790226-0303 \* Region 4. Dallas. Vendor Inspection Branch 79/04/02 Lp
- --7906230073 GA Program Insp Rept 99900114/79-01 on 790226-0303 Noncompliance noted calibr documentation for magnetic particle testing equipment not available SUTTON, W . WHITESELL, D E Ragion 4, Dallas, Vendor Inspection Branch 79/03/29 10pp
- 7906290200 Ack receipt of 790413 ltr informing NRC of steps taken to correct deviation noted in OA Program Inap Rept 99900334/79-01 POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 79/05/25 1p
- --7906290211 Responds to NRC 790426 ltr requesting add1 info on Item 0 Corrective actions engineering change notice log revised so headings & info required is functional DEANE,E O Transamerica Delaval, Inc 79/05/14 2pp
- --7706290217 Ack receipt of 790423 ltr informing NRC of stops taken to correct deviations noted in GA Program Insp Rept 97900334/79-01 Addl info requested re steps taken to correct \$ prevent recurrence of Item O POTAPOVS, U Region 4, Dallas, Vandor Inspection Branch 779/04/26 ip
- --7906290223 Responds to NRC 790320 ltr re deviation noted in GA Program Insp Rept 99900334/79-01 Corrective actions GA & GC manuals revised-microfilm storage investigated, internal audit schedule revised & engineering change notice log revised DEANE,E G Transamerica Delaval, Inc 79/04/13 4pp
- ---7908290225 Forwards QA Program Insp Rept 99900334/79-01 on 790305-09 & notice of deviation POTAPOVS,U Region 4, Dallas, Vendor Inspection Branch 79708/20 2pp
- --790£290229 Natice of deviation from insp on 790305-09
  \* Region 4, Dallas, Office of the Director 79/03/19 4pp
- --7906270236 QA Program Insp Rept 99900334/79-01 on 790305 O9 Noncompliance noted GA program & change control practices not consistent w/10CFR50 App B & applicable codes \$ stds. FOSTER.W E Region 4. Dallas. Diffice of the Director HUNNICUTT.D M Region 4. Dallas. Vendor Inspection Branch 79/03/19 12pp
- 7906290238 Ack receipt of 790412 & 0512 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99900355/79-01 POTAPOVB.U Region 4. Dellas, Vandor Inspection Branch 79/0422 4.
- --7906290243 Submits add1 info re QA Program Insp Rept 99900355/79-01.per NRC 790423 request Describes method of documentation used for training 2 indoctrination HRRATA.Y Hirata Valve Industry Ca , Ltd , Kawaski Div 79/05/12
- --7906290231 Ack receipt of 790412 ltr re steps taken to correct deviation noted in GA program insp rept. Add1 info required POTAPQUS.U Region 4. Dallas. Vendor Inspection Branch 79/04/23 ip
- --7906270264 Responds to NRC 770202 itr re deviation noted in QA Prograe
  Insp Rept 97900359/79-01. Corrective actions valves machined
  A revelédé, detalied welding procedures revisat & applicable
  welding records examined re interpass tamp per ABME code.
  HIRATA.Y Hirata Valva Industry Co . Ltd . Kawaski Div EH-336
  79/04/12 5pp
- --7906290268 Forwards QA Program Insp Rept 99700355/79-01 on 790112 4 16-18 & notice of deviation POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch. 79/02/02 2pp

- --7906290274 Notice of deviation from insp on 790112 % 16-18 \* Region 4. Dallas, Office of the Director 79/01/31 3pp
- --7906290282 GA Program Insp Rept 97900355/79-01 on 790112 & 16-18
  Noncompliance noted qualification of hardfacing welding
  procedure specs not consistent w/requirements
  BARNES, I, HUNNICUTT, D M Region 4, Dallas, Vendor Inspection
  Branch 79/01/31 11pp
- 7905270563 Ack receipt of ltr informing NRC of steps taken to correct deviations noted in QA Program Insp Rept 97900063/79-01
  POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch.
  79/05/15 lp
- --7906290572 Responds to NRC 790412 ltr re deviations noted in QA Program
  Insp Rept 99900063/79-01 Corrective actions welding
  procedure revised & pertinent addenda distributed to weld
  shop
  HARNEY, D B Dresser Industries, Inc. 79/05/10 2ap
- --7906290576 Forwards GA Program Insp Rept 99900063/79-01 on 790319-22 & notice of deviation POTAPOVS.U Region 4. Dallas, Vandor Inspection Branch 79/04/12 2pp
- --7906290583 Notice of deviation from insp on 790319-22
  \* Region 4, Dallas, Office of the Director 79/04/12 2pp
- --7906270591 GA Program Insp Rept 99900063/79-01 on 790319-22
  Noncomplisate noted mfg process control welding not
  consistent w/weld procedure spec 2 distribution of
  wald procedure addenda not consistent w/code criterion
  ROBERTS.H W. JOHNSON.J M., HUNNICUTT.D M. Region 4. Dallas.
  Vendor Inspection Branch 79/04/09 11pp
- 7906290614 Ack receipt of 790502 itr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 9790524/79-01 PCTAPOVS, U Region 4, Dallas, Vendor Inspection Branch 79/05/17 in
- --7906290620 Responds to NRC 790413 ltr re deviation noted in QA Program Insp Rept 99900524/79-01 Corrective actions revision of Procedure DC-2 to delete requirement of specifying issue dates of codes & stds for design descriptions DERIENZO,P P Gibbs & Hill, Inc (subs of Dravo Corp) 79/05/02 Spp
- --7906270621 Forwards GA Program Insp Rept 99900524/79-01 on 790326-30 tootice of deviation POTAPOVS.U Region 4, Dallas, Vendor Inspection Branch 79/04/13 2pp
- ~~7906240624 Notice of deviation from insp on 790326~30 \* Region 4. Dallas. Office of the Director 79/04/12 ip
- --7906290630 GA Program Insp Rept 97900524/79-01 on 790326-30
  Noncompliance noted design descriptions did not specify
  issue date of applicable codes & stds & design checklists
  not used on all design reviews
  BRCWN.R L. COSTELLO,J R. HALE,C J Region 4, Dallas, Vendor
  Inspection Branch 79/04/12 12pp
- 7906290651 Responds to NRC 790426 ltm re deviation noted in QA Program Insp Rept 9990025/79-01 Corrective actions copies of acknowledgments of 790208 instructions were signed by red room attendant & GC inspector MOERKE. R H Southwest Fabricating & Wolding Co (subs of IU International Corp ) 79/05/15 3pp
- 7706290633 Ack receipt of 770326 & 0515 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 97900028/79-01 Region 4, Dallas, Vendor Inspection Branch 79/08/22 1
- --7906290662 Ack receipt of 790326 ltr informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 79900025/79-01 Requests addi info re method of documenting stated instructions to provide auditable record POTAPOVS.U Region 4. Dallas. Vendor Inspection Branch 79/04/26 2pp
- --7906290671 Responds to NRC 770226 ltr re deviation noted in GA Program Insp Rept 97900025/79-01 Corrective actions: temp stratification within rod box has been corrected Mods have maintained air temp within 150 F to 300 F MOERKE, N H Southwest Fabricating & Welding Co (subs of IU International Corp.) 77/03/26 10pp

- --7906290682 Forwards GA Program Insp Rept 99900025/79-01 on 790129-0202 b notice of deviation POTAPOVS.U Region 4. Dallas, Vendor Inspection Branch 77/02/26 2pp
- --7906290690 Notice of deviation from insp on 790129-0202 POTAPOUS V Region 4. Dallas. Vendor Inspection Branch 79/02/21 3pp
- --7906290707 GA Program Insp Rept 99900025/79-01 on 790129-0202
  Noncompliance noted storage of coated electrodes not
  consistent w/Cr(terion YIII of 10CFR50 App 8 % temp
  requirements of Procedu: WMC-1, Revision O
  BANNEG, I., ROBERDS, H. W. HUNNICUTT, D. M. Region 4, Dallas,
  Vendor Inspection Branch 79/02/21 24pp
- 7906290676 Ack receipt of 790209 & 0425 ltrs informing NRC of steps taken to correct deviation noted in GA Program Insp Rept 99700066/78-03 POTAPOVS.U Region 4. Dallas. Vandor Inspection Branch 79/05/22 1p
- --7906290693 Forwards responses to 790402 request for add1 info re deviation noted in GA Program Insp Rept 99700066/78-03 WARREN.N C Bendix Corp 79/04/25 16pp
- --7905290695 Requests addl info to 790209 response re steps taken to correct deviation noted in GA Program Insp Rept 99900065/78-03 SEYFRIT,K V Region 4. Dallas, Office of the Director 79/04/02 2pp
- --7906290705 Responds to NRC 790104 ltr re deviation noted in GA Program
  Insp Rept 99900066/78-03 Corrective actions training &
  indoctrination program will be revised & procedure developed
  for handling & storage of items to prevent deterioration
  WARREN.M C Bendix Corp 79/02/09 5pp
- --7906290708 Forwards GA Program Insp Rept 99900066//B-03 on 781211-15 % notice of deviation SEYFRIT,K V Region 4, Dallas, Office of the Director 79/01/04 3pp
- --7906270711 Notice of violation from insp on 781211-15
  Region 4. Dallas, Office of the Director 79/01/04 3pp
- --7906290716 GA Program Insp Rept 99900066/78-03 on 78t211-15
  Nancompliance noted training procedure not revised as
  committed handling 5 storage not accomplished w/approved
  procedures 8 minutes of training meeting not maintained
  BARNEG.I., ROBERDS.H.W., HUNNICUTT.D.M. Region 4, Dailas,
  Vendor Inspection Branch 78/12/29 12pp

# REGGD REGULATORY GUIDES

- /704020215 Corrects 790416 ltr forwarding draft rag guide." Lightning Protection for fluctear Power Plants " STADER E Bechtel Power Corp (subs of Bechtel Corp) 77/04/19
- 7906020216 Comments on proposed Revision 2 to Reg Guide 1 B wording should be changed as follows, "included in one year of experience.should be training b experience sufficient to qualify individual"

  BASILE, J. A. Public Service Co. of Oklahoma 79/04/09 2pp
- 790602022 Value/impact statement for proposed Revision 3 to Reg Guide i 35. "Inservice Insp of Ungrouted Tendons in Pressurized Concrete Containments "

  \* Office of Standards Development 79/04/30 7gp
- 7906070340 "Assumptions Used for Evaluating Light Water Cooled Nuclear Pawer Plant Siting Distances for Purposes of 10CFR100 " \* Office of Standards Development 79703/31 10pp
- ---790407034B "Assumptions Used for Evaluating Potential Radiological Consequences to Public from Design Basis Accidents in Light Water Cooled Nuclear Power Plants for Purposes of 10GRSO \$ 51 " Value/Impact Statement encl # Office of Standards Development 79/03/31 iBpp
- 7906070069 Comments on progosed Reg Guide 1 144 disagrees u/proposed position requiring internal audits to be conducted annually Recommends scope of procurement actions not requiring external audits be extended to include source verification, VIOLETTE, J B Bechtel Power Corp (subs of Rechtel Corp.) 79/03/01 2pp

- 7906070079 Comments on proposed Reg Guide I 144 recommends endorsement of std w/regard to scheduling of internal audits Suggests C3 bi be extended to include acceptable alternative methods for use by customers, reather than auditing GORE, J W. Atomic Industrial Forum 79/04/05 2pp
- 7906070083 Comments on proposed Reg Guide 8 23 guide is sound % strengthens radiation control operations Concerned re recordkeeping & insufficient initiative given to institution or prof health physicist GREENFIELD, M A California, Univ of, Los Angeles 79/03/29 2pp
- 7906070091 Comments on proposed Reg Guide 1 144 recommends no specific required audit frequency Endorses mfg audit as alternative EDELMAN; M R Cleveland Electric Illuminating Co 79/03/26 2pp
- 790c070174 Comments on proposed Reg Guide 8 23 usage interval for determining monitoring requirements is unspecified & conflicts w/Reg Guide 10 8-39 Refs cited are out of date & should be updated BLAHD, W H , WETTERAU, L W Vet Admin Hosp LA, California 79/04/03 1p
- 7906:20:07 Forwards 7705:19 ltr discussing Reg Ovide 1 :20 requirements for cable penetrations
  WRIGHT, R. ACRS Advisory Committee on Reactor Safeguards
  79/03/02 ip
- --7906120112 Discusses 770518 ltr re evaluation of cabla penetrations Recent tests of fire barriers show thermafiber & special gypsum product to withstand J-h E-119 furnace fire ELIASEN.A N Sargent & Lundy. Inc 79/04/19 ip
- 7905130178 Proposed Reg Guide 1.35 1. "Determining Prestressing Forces for Insp of Prestressed Concrete Containments "

  \* Office of Standards Development 79/04/30 21pp
- --7905130180 Draft value/impact statement for proposed Reg Guide 1 35 i, , "Determining Prestressing Forces for Insp of Prestressed Concrete Containments" ## Uffice of Standards Development ## 79/04/30 | 5pp
- 7906140613 Comments on proposed Reg Guide 8 B disagraes that relationship between radiation dose & biological effects are well known only for high doses

  BHICK.C B Environmental Policy Institute 79/04/20 ip
- 7906140619 Comments on proposed Reg Guide 1,8, education and experience requirements for personnel are needlessly high PARKER, W O Duke Power Co 79/04/23 4pp
- 7906140618 Comments on proposed Rag Guide 8 23 objects to survey frequency schedule Cites radiation-producing equipment not addressed & contamination level tables not provided YUSKO.J.O Allegheny General Hosp 79/04/17 App
- 79G6140648 Comments on proposed Revision 2 to Reg Ouide 1 8 recommends
  Paragraphs 3s-3c under Part C be revised to recognize sys
  knowledge gained through test experience, as well as formal
  sys training
  DALE, L F Mississippi Power & Light Co AECM-79141 79/04/20 ip
- 7906140655 Comments on proposed Reg Guide 7 9 falls to specify requirements to ensure that occupational radiation exposures are ALARA BERICK, D Environmental Policy Institute 79/04/15 1p
- 7906150094 Comments on proposed Reg Quide 2 6 opposes guide ANS-15 std for emergency planning is adequate WHITTEMORE.W L. General Atomic Co (subs of Quif Dil Corp.) 79/04/20 3pp
- 7906130104 Comments on proposed Reg Ouide i 8 requirements not confistent w/extensive testing Suggests change in educational 3 experience criteria CAHN: A L. Bechtel Power Corp (subs of Bechtel Corp.) 79/04/19
- 7906130479 Comments on proposed Revision 4 to Reg Quide 8 8 experience W/radiation exposure to date does not warrant reduction of allowable radiation does to nuclear power plant personnel GOLLEY,R W Affiliation Unknown, 79/06/18, 2pp
- 7906160019 Comments on proposed Rag Guide I 144. "Auditing of GA Programs for Nuclear Power Plants." fails to recognize methods other than audits for GA programs Mandatory audit scheduling may be unsatisfactory MARTIN.O.L American Society of Guality Control 79/04/18 2pp.

- 7906160046 Comments on proposed Reg Quide 10 8, "Quide for Preparation of Applications for Medical Programs" objects to thin window survey meter 3 sensitivity requirement for area wipe tests MANTHE. H E St Anthony Hosp WI/MI 79/04/19 1p
- 7906160048 Comments on proposed Revision 2 to Reg Quide 1 8 "Personn Belection & Training " different & addl qualifications identified in Regulatory Position 3 add confusion & are not necessary HALL, B M Affiliation Unknown 79/04/19 2pp
- 7906180034 Comments on proposed Revision 2 to Reg Quide : 8 Section 5 should be revised to more accurately agree w/requirements of ANSI 3 1-1978 JOHNSON.W P Yankee Atomic Electric Co WYC 79-15 79/04/23 2
- 7906180062 Comments on proposed draft reg guide. "Lightning Protection for Nuclear Power Plants" authors have confused usage of lightning stroke w/lightning surge Distinction is crucial since difference in magnitude is extremely significant STADE, R E Bochtel Power Corp (subs of Bechtel Corp.) 79/04/16
- 7906180748 Draft Reg Quide 3 XXX, "Calculational Models for Est(esting Radiation Doses to Man From Airborne Radioactive Matls Resulting From U Milling Operations"

  \*\* Office of Standards Development 79/05/31 Spp.
- 7906169778 Comments on proposed Reg Quide 1 144 does not agree w/Regulatory Position C3a(2) internal audits Suggests reg guide be modified to state that audits should be scheduled at frequency commensurate w/status & importance of activity NILSON:R Exxon Nuclear Co . Inc (subs of Exxon Corp ) 79/04/17 200
- 7906200491 Comments on proposed Reg Guide 1 69 problems w/cross-ref of other reg guides UHR10.R E Florida Power & Light Co L-79-104 79/04/27 lp
- 7906200493 Comments on proposed Reg Guide 3 11 1 suggest aditorial correction in Paragraph C 2b(1) deleting word "particular " GEIOER, E L. Eberline Instrument Corp. E1916298 79/04/27 Lp
- 7906200496 Comments on proposed Reg Quide 1 128.Revision 1 for "hydrogen build-up" condition to occur, battery would have to be receiving an overcharge w/simultaneous failure of ventilation sys

  BOETTGER: J T Power Engineering Society 79/04/24 2pp
- 7906200498 Comments on proposed Reg Quide 1 8 Revision 2 EEI health physics task force believes qualifications for radiation protection manager are adequately addressed in existing reg guide JENCKES.T A Pacific Oas & Electric Co 79/04/27 ip
- 7906200502 Comments on proposed Reg Quide 1 7 does not agree w/resolution of comment on Position C.7
  JOHNSON,W P Yankee Atomic Electric Co WYC 79-13 79/04/25 2;;
- 7906200518 Comments on proposed reg guide 1 XXX draft guide sets forth Concrete Radiation Shielding for Nuclear Power Plant: "draft needs guidelines related to biological shielding design HAGA:PB obsolets code FNP-PAL-016, 79/04/26 1p
- 7906200528 Comments on proposed Reg Guide 2,6, recommends NRC withdraw reg guide 2 formally endorse existing std, ANSI/ANS i5 16-1978
  GARTER, R S Commerce, Dept of, National Bureau of Standards 79/09/01 ip
- 7906200535 Commants on proposed Reg Quide 1.8 Revision 2 requirement for 3-month indoctrination/training program for individuals who will be supervising preoperational tests is unduly restrictive COUNSIL.H 6 Northeast Utilities 79/04/23 2pp
- 7905200545 Comments on proposed reg guide 1, XXX. disagrees w/any interpretation of NRC regulations that would apply to occupational law doses.

  0'DDNNELL.E P. Ebasco Services, Inc. (subs. of Enserch Corp.)
  79/04/25 3pp
- 7906210023 Notifies that comment re Reg Guide 1 131, prepared by IEEE-383-1974 working graup, will be forwarded. GARBHICK, A Boston Insulated Wire & Cable Co. 77/10/24 1p
- --7906210038 Comments on proposed Reg Guide 1 31.Section C 3 each cable connector configuration should not be tested Requests rewording.

  HACA: P B Offshore Power Systems (subs. of Westinghouse Electric Corp.) 77/10/18 1p.

- --7906210040 Comments on Reg Guide 1 31.page 1 131-3.Paragraphs 9 & 11. propane would not produce quoted amount of heat BIMBER.R M Affiliation Unknown 77/08/28 1p
- 7906210416 Comments on proposed Reg Ouide 10 XXX suggests clarification of terms "mati" & "waste disposal" 79/04/23 4pp
- 7906220423 Comments on proposed reg guide 1 XXX NRC quality groups, ANS safety classes & ABME III classes are analogous & should be used to define valves BUCKLEY.C F American National Standards Institute 79/04/24 1p
- 7906220463 Comments on proposed reg guide 1 XXX specific concepts need clarification in particular, interpretation of ASME Code Section XI, definition of reg guide terms & implementation of reg guide CERECEDA.M Affiliation Unknown 79/04/19 ip
- 7906230106 Forwards Draft 1 to proposed Revision 2 of Rog Guide 1 94, preliminary value/impact statement & ANSI/ASME N49 2 5-1970, which relate to GA requirements for installation insp & testing of structural concrete, steels, soils & foundations ARLOTTO.O.A Division of Engineering Standards 79/05/16 7pp
- --7508230108 Preliminary value/impact statement on GA requirements for installation, insp % testing of structural concrete, structural steel, soils & foundations during const phase of nuclear power plants

  \* Division of Engineering Standards 79/05/11 App
- ---7905230109 ANSI/ASME N45 2 5
  ANSI/ASME N45 2 5-1978 "Supplementary QA Requirements for Installation Insp & Testing of Structural Concrete, Structural Steel Soils & Foundations During Const Phase of Nuclear Power Plants "

  \* American Society of Mechanical Engineers 79/05/16 26pp
- 7906290835 Proposed Revision 2 to Reg Guide 5 44. "Parimeter Intrusion Alarm Sys " # Office of Standards Development 79/05/31 25pp

### RES RESEARCH AND TECHNICAL ASSISTANCE REPORTS

- 7906010337 Research Info Ltr 53 results of initial series of three incore experiments on coolability limits of post-accident particulate LHFBR fuel debris in sodium pool Forwards NUREG/CR-0263 & NUREG/CR-0421 LEVINE.B Office of Nuclear Regulatory Research 79/05/10 7pp
- --770&010344 NUREO/CR-0243
  "Debris Bed Studies & Experiments at Bandia Labs "
  RIVARD, J B Sandia Laboratories FIN A-1181 SAND78-0299
  78/07/31 59pp Available at NTIS
- --7906010351 NUREO/CR-0421
  "Post-Accident Heat Removal Debris Bed Experiments D-2 & D-3"
  RIVARD.J B Sandia Laboratories FIN A-1181 SAND78-1238
  78/11/39 60pp Available at NTIS
- 7706020110 "Code Assessment & Applications Program, Improved RELAP4 Jet Pump Model." ROSS:E E. Idaho National Engineering Laboratory FIN A-6039 CANP-TR-046 79/04/30. 60pp
- 7906020114 "Water Reactor Research Directorate;" menthly rept for Mar 1979 BOSTWICK,# E Idaho National Engineering Laboratory 79/04/30 250pp
- 7906020115 "BEACON/MOD2A Computer Program for Subcompartment Analysis of Nuclear Reactor Containment User's Manual "HELLS,R A , BROADUS,C R , DDYLE,R J | Idaho National Engineering Leboratory, FIN A-6042 77/03/31, 330pp.
- 7906020153 "Code Development & Analysis Program, Fuel Vapor Pressures" MASCH-R.E EG & G, Inc FIN A-6046 CDAP-TR-053 79/04/30 Sipp
- 7906040413 "NRC-Related Haste Mgt Resources BNL Capabilities in Waste Mgt Science;" informal rept SCHMEITZER D 0 Brookheven National Laboratory FIN A-3016. 79704/30 12pp

- 7906050180 "Forecasting Electricity Demand by States in US on Admual Basis:" interim rept for Mar 1979 CHERN.W S Oat Ridge National Laboratory FIN 8-0190-8 79/04/03
- 7906050279 "PBF/LOFT Lead Rod Program Tests LLR-3.LLR-4 % LLR-5.Gulck Look Rept " VARACALLE.D J. GARNER.R W EG & O. Inc FIN A-6111. TFBP-TR-315 79/04/30 100pp
- 7906120136 Research Info Ltr 30 summarizes & comments on result of study published as NUREO/CR-0093, "Nuclear Safety Guide, TID-7016, Revision 2"

  LEVINE: 8 Office of Nuclear Reactor Regulation 79/04/06. 4pp
- 7906140127 "Structural Integrity of Water Reactor Pressure Boundary Components," monthly progress rept for Feb 1977 LDSS.F J Navy, Dept of, Naval Research Laboratory 6390-66M-FJL SA 79/03/16 Spp
- 7906180218 "Program for Standardized Analysis of Fuel Shipping Containers:" quarterly summary, Jan-Mar 1979 WHITESIDES:C E , WESTFALL,R M Oak Ridge National Laboratory FIN B-0172 ORNL/CSD/INF-79 79/04/20. 7pp
- 7906180230 "Environ Assessments of Fuel Cycle Facilities." progress rept.Mar 1979 ZITTEL.H E Oak Ridge National Laboratory FIN 8-0279 ORNLZED/E18-89 79/03/31 App
- 7906180729 Research Info Ltr 44 radiation doses to const workers at operating nuclear power plant sites. Submits results of completed research Forwards NUREG/CR-0426.Vol 2 LEVINE.8 Office of Nuclear Regulatory Research. 79/01/04 3pp
- 7906190049 "Review of Critical Experiments Performed for Fuel Cycle Guidance Safety," quarterly summary, Jan-Mar 1979 HHITE8IDES.G E. WESTFALL,R.M Oak Ridge National Leboratory FIN B-0409 ORNL/CSD/INF-79 79/04/20 11pp
- 7906200608 "PWR Steam Generator Tube Integrity Program." monthly progress rept for Apr 1979 CLARK.R A Battelle Hemorial Institute. Pacific Northwest Laboratory FIN B-2097 79/05/21 9pp
- 7906200620 "Application of Internal Friction Nondestructive Evaluation Technique for Detecting Incident Gracking of Bypass Lines & Pipes in BWR Piping Bys." Progress Rept 10 for 790402-27 "Daedalean Associates: Inc. NRC-04-78-242. 79/09/31 10pp
- 7906210011 "Threadfin Shad Impingement.Population Response," progress rept.Oct-Dec 1978 CDUTANT.C C. MCLEAN.R B. Oak Ridge National Laboratory FIN B-0406 79/06/05 6pp.
- 7906210013 "Fire Protection in Operating Nuclear Power Stations: Gwad-Cities Stations 1 & 2 BER Review " HALL:R E Drockhaven National Laboratory FIN A-3107 79/04/12.
- 7906210020 "Acoustic Emmission/Flow Relationships for Inservice Monitoring of Nuclear Pressure Vessels," monthly ltr rept. Apr 1779 HUTTON.P H , SCHWENK.E B , KURTZ.R, J Battelle Memorial Institute, Pacific Northwest Laboratory FIN 8-2488 79/05/11 3pg
- 7706210031 "Threadfin Shad Impingement, Population Response, " quarterly progress rept, Jan-Mar 1779 VAN WINKLE, W. Oak Ridge National Laboratory FIN 8-0406 79/06/05 47pp
- 7906220183 "Threadfin Shad Impingement, Effect of Cold Stress," progres rept. Jul-8ept 1978
  COUTANT, C C. MCLEAN, R B Oak Ridge National Laboratory FIN B-0406, 79/06/05 2pp
- 7906220215 "Her 1979 Monthly Highlights," OFc of Nuclear Regulatory Research Programs, DIV of Reactor Safety Research at ORNL MYNATT, R Oak Ridge National Laboratory ORNL/NUREO/TM-3 79/04/06 36pp.
- 7906230)24 "Geophysical Investigations of Anna.OH Earthquake Zone" quarterly progress rept.Aug 1978-Feb 1979 MAUK.F. J. HENRY.8 G. KEMBALL.J. Michigan, Univ. of. UNGM-NUREO-79-0. 79/03/31 16pp
- 7906230169 "Thermal Hydraulic LMFBR Safety Experiments," monthly highlight rept for Apr 1979
  JONES, C.C. Brockhayen National Laboratory FIN A-3024 79/04/30

- 7906230172 "Div of Reactor Safety Research-ORNL Programs," Apr 1979 monthly bighlight rept MYNATT.F R Oak Ridge National Laboratory 79/05/09 36pp
- 7906230173 "Lightwater Reactor Thermal Hydraulic Development Frogram." monthly highlight ltr for Apr 1979 JONES, O. C. Brookhaven National Laboratory FIN A-3045 79/04/30
- 7906250043 "Short Segmented Cask Code Development & Validation Program," monthly highlight ltr for Apr 1979 AGRAWAL, A K. CERBONE, R J. Brookhaven National Laboratory FIN A-3015-7 79/04/30 App
- 7906250053 "BWR Blowdown/Emergency Control Ctr Program," monthly progress rept for Apr 1979
  BURNETTE, O W General Electric Co , Nuclear Energy Products Div NRC-04-76-215
  79/03/09 29pp
- 706260013 "HTGR Safety Program," monthly highlight Jtr for Apr 1979 SCHWEITZER, D.G. Srookhaven National Laboratory FIN A-3016 79/05/10 Spp
- 906260017 "Advanced Reactor Safety Analysis Technical Assistance Reactor Projects:" monthly highlight rept for Apr 1979 BARI.R A Brookhaven National Laboratory FIN A-3000 79/03/15
- 306260031 "Thermal Fuels Behavior Program, Operational Transient Test Søries OPIRAN 1-2 Experiment Spec Document " EEMKEN.R S , GARNER.R W , MCCARDELL.R K Idaho National Engineering Laboratory FIN A-6041 79/04/30. 2pp
- 706260037 "Stress Corrossion Cracking of PNR Steam Generator Tubing." monthly highlight rept for Apr 1979 VAN ROOYEN.D Brookhaven National Laboratory 79/05/09 Spp
- 706260042 "Thermal Reactor Safety Code Development," monthly highlight Ltr rept for Apr 1979

  D[AMOND:D J . SHIER.W Brookhaven National Laboratory FIN

  A-3014-9 79/04/30 10pp
- 706260601 Research Info Ltr S4 forwards NUREO/CR-0465, "SETS User's Manual for Fault Tree Analyst." by Sandia Labs LEVINE.S Office of Nuclear Regulatory Research 79/05/15 2pp
- 706260413 "Biocide Products in Aquatic Environs," quarterly progress (Obsourd Telephone 1979

  ANDERSON, D. R. DEAN, R. M. GIBSON, C. I. Battelle Memorial Institute,
  Pacific Northwest Laboratory FIN 8-2096-9 79/05/31 56pp
- 906260616 Interim progress rept. "Chamical Effluents in Surface Waters From Nuclear Power Plants " HARRISON:F Lawrence Livermore Laboratory FIN A-0119 79/04/09
- 904240620 Interim progress rept. "Chemical Effluents in Surface Waters From Nuclear Power Plants" HARRISON.F Lawrence Livermore Laboratory FIN A-0119 79/01/31
- 902280001 Quarterly progress rept for Jan-Har 1979, "Bibliography of Study on Continental Rifts" BRAILE.L W Purdue Univ KELLER.O R Texas, Univ of LIDIAK.E ( Pittaburgh, Univ of NRC-04-76-323 79/04/12 71pp of LIDIAK, E Q
- -7906280002 "Bibliography of Study on Continental Rifts " # Purdue Univ 79/01/31 26pp
- 906290178 "LGCA Tast Beries Tast LGC-3 Experiment Predictions '
  YACKLE, T. R., KLINK, P. H., SPORE, T. W. EG & G., Inc. FIN A-6041
  79/04/30 165pp
- 906290204 "Code Development & Analysis Program FRAPCON-2 Uncertainty Analysis Option " PECK:S O EG & G. Inc FIN A-6050 CDAP-TR-055 79/04/30 40pp
- 906290250 "Summary & Assessment of Return to Nucleate Boiling Phonomena During Blowdown Tests Conducted at INEL " EATON.A M . TOLMAN,E.L EQ & Q. Inc FIN A-6278. LTR 20-99.79/04/30 Bipp.
- 706270265 "Inhalation Dosage Determination Resulting From Blowdown Suppression Tank Failure & From Release Directly to LOFT Containment Following L2-3 Blowdown" SCHOFIELD:R 8 E0 & O. Inc. FIN A-6048 79/01/16 14pp.

- 7908290278 "Best Estimate Prediction for LOFT Nuclear Experiment (2-) \*
  KEE.E J. GRUSH, W H EQ & Q. Inc FIN A-6048 79/04/30 98pp
- 7906290291 "Stress Analysis of Modified Rake Assemblies H/Positive Leck Devices for Cap Screws" FINICLE, D. P. EG & G. Inc. FIN A-6048 79/01/23 30pp
- 7906270311 "Refined Analysis of Effects on LOFT Containment Bldg Resulting from Main Steam & Feedwater Broaks " MOSBY, W R EO & G. Inc FIN A-6048 79/01/16 33pp
- 7906290505 "FRAPCON-1 Computer Code for Steady State Analysis of Cilia Idaho National Engineering
- 7906290542 "Postirradiation Metallurgical Tachniques to Estimate LOFT Peak Cladding Temps " OLSEN,C S Idaho National Engineering Laboratory FIN A-6048

#### REVIEW ORP NRC REBEARCH REVIEW GROUPS

- 7906120110 Forwards certified minutes of Risk Assessment Review Orac, 780605-09 meeting in Berkeley.CA AUSTIN.J M. Office of Policy Evaluations 79/03/13 13pp
- 7906210027 Notification of 790622-29 meeting w/Project Nutlear Sicherheit, Fuel Behavior Research Branch of NRC & JAERI in Idaho Falls, ID for info exchange on codes & cladding JOHNSON, W V Fuel Behavior Branch 79/05/15 Bpp
- 7906210035 Forwards draft summary rept from Sandia Labs re effect of age on fire retardant ejectrical cable FEIT.R Division of Reactor Safety Research 79/05/18 1p
- --7904210037 Draft summary rept. "Comparison of Polymer Flammabilities & Determination of Loss of Fire Retardant Additives W/Aging "CLOUGH.R L . SALAZAR.E A Sandia Laboratories 79/09/10 9pp
- 7906260234 Summary of 790123 meeting of LOFT Review Group in Ideho Falls, ID re-presentation of L-2 data, code comparisons, cladding thermocouple accuracy & effect on rewet & implementation of LOFT data BURTT.J D., PHOENIX, W.C., SAMUELB, T.K. Division of Reactor Safety Research 79/01/23 170pp
- 7906260628 Notification of 790613 meeting w/LQFT Review Group in 1845; Falls,ID to discuss L2-3 results MCPHCRSQN,Q D Division of Reactor Safety Research 79/04/19
- 7905280048 Summary of 781107 meeting of LOFT Review Group in Omithersburg, MD ra power range testing, experimental safety analysis long-range experimental plans & test prodictions HARRIS, P A , PHOENIX.W C , SAMUELS, T K Division of Reactor Safety Research. 78/11/07 136pp

# RULEMAKING

- 7906270012 Notifies that unofficial transcript of NRC 790603 meeting P ABLO rept in clearance rule proceeding is available in PDR Transcript is not part of formal or informal record of decision of matters discussed, per 100FR9 103, BICKHITLL Office of the General Counsel 79/06/07 1p
- POSITION PAPERS BEFORE THE COMMISSION SECY
- 7904010125 SECY-77-561 Reviews Phase I of systematic evaluation program to obtain approval to proceed w/Phase II of plant-specific review Recommends NRC approve continuation of program plan CASE.E 0 Office of Nuclear Reactor Regulation 77/10/86
- 7906010146 SECY-79-297 Enforms Commission of receipt of Transmuclear, Inc 790420 applacation for license to export highly enriched U to SHEA, J.R. Office of International Programs 79/04/26. 1p.

- 7906010179 SECY-77-539
  Advises Commissioners of plans to convert provisional OLs to full-term licenses
  CASE.E.O. Office of Nuclear Reactor Regulation 77/10/14 5pp
- 7906020017 Forwards proposed license for US Army Matls & Mechanics Research Ctr to export source matl to United Kingdom Requests review SHEA.J R Office of International Programs 79/04/04 Opp
- --770602002: Executive Branch position re US Army Matls & Mechanics Research Ctr application for license to export 250 kg depleted U alloy to United Kingdom License should be granted MOSENZO,L V State,Dept of, Bureau of Qceans & Internat! Environ & Scientific Affairs 79/01/03 2pp.
- --7906020023 Application by US Army Matle & Mechanics Research Ctr for license to export 250 kg depleted U alloy to United Kingdom MRIGHT.E S Army,Dept of, Matls & Mechanics Research Center 79/06/12 2pp
- --7906020027 License for Army Matls & Mechanics Research Ctr to export 250 kg depleted U to United Kingdom OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/04 2pp
- 7906020101 BECY-79-286
  Provides NRC review of Trensnuclear, Inc 790103 application for license to import low enriched U as U hexafluorido from France BHEALJ R Office of International Programs 79/04/23 3pp
- --7906020103 Application by Transnuclear. Inc for license to import 5.500 by U.enriched to max of 2 3% U-235, from France MATSON, V. Transnuclear, Inc 79/01/03 2pp
- --7906020106 License for Transnuclear, Inc to import max of 5,000 kg U, enriched to max of 2 3% U-235, from France OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/01/03 2pp
- 7905020227 GECY-79-114

  Beeks NRC approval to publish amends to 10CFR19 & 20 re
  radiation exposure to transient workers Recommends approval
  Supporting decumentation encl
  MINDGUE,R B. Office of Standards Development 79/01/12 65pp
- --7706020231 Value/impact assessment containing rept justification analysis of amend to regulations to control radiation doses to transient workers Recommends proposed action be taken a Office of Standards Development 779
- ---7706020234 Recommends paper re amend to iOCFR17 & 20 provide analysis of "no further action" alternative including latest assessment of impact & value SNYDER. B Office of Policy Evaluations 78/11/07 lp
- 7906040398 Responds to 790206 memo which raised question re RECY-78-623 on pipe cracking Ultrasonic insp did detect cracks in safe-ends Pipes that crack in svc should be replaced w/piping made of resistant mat!

  DENTON, H. R. Office of Nuclear Reactor Regulation 79/04/27 4pp
- --7906040403 Raises questions re SECY-78-623 on reactor pipe cracks BRADFORD.P A Commission 79/02/06. 1p
- 7906060067 SECY-79-1878
  Notifies that faccility attachment for License Application
  XSNM-1345 for Bruce Generating Station Unit 1 is concluded
  Info on Stations 2.3 % 4 still being collected
  SHEA.J R Office of International Programs. 79/05/02 1p
- 7904060071 SECY-79-233A
  Informs Commissioners of preliminary comments on proposed
  license for Ediow Inti to export low enriched U to India
  Recommendations deferred until Executive Branch briefing on
  partinent foreign policy developments
  SHEA, J.R. Office of International Programs 79/04/24 3pp
- 7906060076 SECY-79-307
  Notifies Commissioners of withdrawal of Inst for Resource
  Mgt application for license to export highly enriched U to
  Bolivia. M/790108 Itr of cancellation.
  SHEA, J R. Office of International Programs 79/05/01 is

- 7906060078 SECY-79-306
  Notifies Commissioners of withdrawal of Inst for Resource
  Mgt application for license to export research reactor to
  Bolivia W/790108 ltr of cancellation
  SHEA.J.R Office of International Programs 79/05/01 1p
- 7906070101 SECY-79-241
  Submits add1 info re several proposed export licenses
  Discusses 790316 meeting of Euratom Supply Agency Dalegation
  of Commission of European Communities & NRC Ofc of Intl
  Programs re urgent need for highly enriched U in Europe.
  SHEA.J R Office of International Programs 79/03/30 3pp
- 7906070101 SECY-79-241

  Submits add1 info re several proposed export licenses
  Discusses 790316 meeting of Euratom Supply Agency, Delegation
  of Commission of European Communities & NRC Ofc of Intl
  Programs re organt need for highly antiched U in Europe.
  SHEA, J. R. Office of International Programs 79/03/30 3pp
- /9C&O/O:O: ECCY-79-241
  Submits add1 info re several proposed export licen.es
  Discusses 79O316 meeting of Euratom Supply Agency.Delegation
  of Commission of European Communities & NRC Ofc of Intl
  Programs re urgent need for highly enriched U in Europe
  SHEA.J R Office of International Programs 79/03/30 Opp
- 7906070101 SECY-79-241

  Submits add info as several proposed export licenses.
  Discusses 790316 meeting of Euratom Supply Agency, Delegation of Commission of European Communities & NRC Ofc of Inti Programs re urgent need for highly enriched U in Europe SHEA.J R Office of International Programs 79/03/30 3pp
- 7704070101 SECY-79-241
  Submits add1 info re several proposed export licenses
  Discusses 770316 meeting of Euratom Supply Agency Delegation
  of Commission of European Communities & NNG Dec of Inti
  Programs re urgent need for highly enriched U in Europe
  SHEA.J.R Office of International Programs 79/03/30 3pp
- 7906070101 SECY-79-241

  Bubmits addi info re several proposed export licenses
  Discusses 790316 meeting of Euratom Supply Agency Delogation
  of Commission of European Communities & NRC Ofc of Intl
  Programs re urgent need for highly enriched U in Europe
  SHEA.J.R Office of International Programs 79/03/30 3pp
- 7904070101 SECY-79-241

  Bubmits add) info re several proposed export licenses.
  Discusses 790316 meeting of Euratem Supply Agency, Delegation
  of Commission of Eurapean Communities & NRC Dfc of Intl
  Programs re orgent need for highly enriched U in Europe
  BHEALJR Office of International Programs 79/03/30 Spp
- --7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedulo of reactor operators as well as conversion & fabrication planning of Nukem OUPPEL.H European Communities. Commission of 79/03/19. Spp
- 7906110313 SECY-78-415
  NRC 1977 Annual Rept on Occupational Radiation Exposure
  Provides info on exposure risks in NRC-licensed activities
  & measures for risk control. Supporting documentation encl
  MINGOUE:R B Office of Standards Development. 79/07/31, 500pp
- 7906110430 BECY-A-79-30
  Seeks Commissioner approval for appointment of JR Yore as part-time atty panel member
  LAZOR M Atomic Safety and Licensing Board Panel 79/04/03, 2pp
- 7906130184 SEGY-R-338

  Bubmits addl guidance on acope of applicant environ repts
  W/respect to accidents

  MCCODL.W B Atomic Energy Commission (Pre 1975) 71/11/15 1p
- ---7906130189 Discusses addl guidance re scope of applicant environ repts w/respect to accidents
  MUNTZIO.L.M Atomic Energy Commission (Pre 1975) 71/11/15.
  28pp
- 7906180050 SECY-79-308
  Informs Commissioners or Nisso-Iwai American Corp license application amend to change intermediate consignees.
  BHEA, J.R. Office of International Programs. 79/05/01 1p
- ---7906180060 Requests amend to Nissho-Iwai American Corp export license to change specified intermediate consignees in Japan TSUJI:N. Nissho-Iwai American Corp 79/04/20 1p

906180116 SECY-79-305
Informs Commissioners of actions required to implement final
CEG NEPA regulations. Recommends NRC comply w/regulations
subj to specified conditions Supporting documentation encl
SHAPAR.H K Office of the Executive Legal Director BICKHIT.L
Office of the General Counsel. 79/03/01 68pp

906180615 BECY-79-310
Reviews proposed amend to RMI Co license to export matl to
Canada Amend would extend expiration date for two yrs &
increase quantity of depleted U to 135,059 kg Amend should
be granted
BHEALJR Office of International Programs 79/04/30 4pp

-7906180619 License for RMI Co to export 99,250 lb U.contained in 100,000 lb depleted U, to Ganada License now referred to as XV-8342
GUHIN-M A Assistant Director for Export/Import & International Safeguards 76/12/10. 2pp

-7905180624 Amend 1, extending expiration date to 801001 b deleting Condition 1 from license for RMI Co to export source math to Canada License now referred to as XV-8342 OPLINOER. G 0 Assistant Director for Export/Import & International Safeguards 78/07/10 1p

-7906180638 Requests extension of export license expiration date to BD1001 Also requests increase of mati authorized for export to 135.057 kg depleted U BCHAEFFER, M R RMI Co., RMI Titanium 78/07/07 2pp

-790A180A51 Executive Branch position re RMI Co application for amend to export license increasing quantity of depleted U authorized for export to Canada Amend should be issued NOSEMZOL V State Dept of 79/03/14 ip

-770&180652 Amend 2 to RMI Co License XU-8342, increasing quantity of matl authorized for export to 135,057 kg depleted U & deleting Condition 7
OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/22 ip

906180739 SECY-79-280 Informs Commissioners of receipt of 790216 application from Edlow Intl Ca for license to export 13,125 kg U to Italy SHEA,J R Office of International Programs 79/04/19 1p

~7906180747 Application by Ediow Intl Co for license to export 13,125 kg U to Italy HARMOND W Ediow International Co 79/02/16 1p

7906180754 SECY-79-289
Informs Commissioners of Edlow Intl Co 790416 application for license to export 48.000 kg U-308 to Brazil.
SHEA, J R Office of International Programs. 79/04/23 1p

--7906180761 Application by Edlow Intl Co for license to export 48:000 kg U-309 to Brazil HARMON:b W Edlow International Co 79/04/16 ip

--7905180766 Advises that application to export 50 short tons of U-308 is to fulfill requirements of Brazilian Resources Legislation Lists US suppliers for application. HARMON, D W Ediow International Co 79/04/17 1p

7906180771 BECY-79-249A Informs Commissioners of GE 790413 license application amend requesting rescheduling of first thisment date to 790831 SHEAJ.R Office of International Programs 79/04/23 ip

--7906:80776 Requests application amend to reschedule first shipment date to 79083; Also asks that DDE itr requesting assurances be expedited to Embassy of Japan to meet new schedule requirements
WILSON.B D General Electric Co., Nuclear Energy Products Div. 79704/13 1p.

7906180802 SECY-79-282
Forwards Executive Branch position re Mitsubishi Intl Corpapitation for license to export 342 kg U-235 to Japan SHEA.J R Office of International Programs 79/04/19 ip

--7906180806 Executive Branch position re Kitsubishi Inti Corpapilication for license to export 342 kg U-235, enriched to 2.85. to Japan. License should be granted, MOSENZO, L.V. Brate, Deat. of, 79/04/16, 3pp.

7906200002 SECY-79-200A
Informs Commissioners of receipt of 740409 amend to
application by German Dominques to export U hexafluoride to
Spain.
SHEA, J. R. Office of International Programs, 79/04/24, ip.

7906210079 Transcript of 790517 public meeting re BECY-79-88 & U mill tailings Pp 1-26
HENDRIE.J M. GILINSKY, V. KENNEDY, R. T. Commission 79/05/17
2600

7906230086 BECY-79-280A
Forwards Executive Branch position re Ediaw Intl Co
application for license to export 593 kg U-235 to Italy
BHEALJ R Office of International Programs 79/05/02 ip

--7906230087 Executive Branch positions re Ediow Intl Co application license to export 593 kg enriched U-235 to Italy License should be granted Forwards ltr of assurance from Delegation of Commission of European Communities NOGENIU, L V. State.Dept of, Bureau of Oceans & Internat1 Environ & Scientific Affairs 79/04/24 3pp

7904230091 BECY-79-077A
Forwards Executive Brench position re QE application for license to export 331 kg enriched U-235 to Japan SHEA.J R Office of International Programs 79/05/11 1p

--7906230094 Executive Branch position re GE application for license export 331 kg enriched U-235 to Japan License should be issued Forwards 790427 ltr of assurance NOSENZO, L V State, Dept of 79/05/11 3pp

7904230103 SECY-78-120A
Summarizes responses of govt agencies to Administrative
Conference Recumendation 77-3 that agencies experiment
w/procedures for prompt disclosure of significant info
communicated erally during rulemaking proceedings
KELLEY.J L Office of the General Counsel 79704/12 5pp

7906230482 BECY-A-77-24
Requests approval of draft ltr to Solicitor General recommending DQJ seek Supreme Court ruling on DC Circuit Court 770325 decision on ex parte contacts in Home Box Ofc YFCC M/o encl
8TRAUSS.P L. Office of the General Counsel 77/04/29 6pp

7906290496 SECY-79-328
Informs Commissioners of receipt of GE application for license to export Tarapur reactor replacement parts & components to India SHEA,J R Office of International Programs 79/05/10 1p

--7908290311 Application by GE for license to export Tarapur reactor replacement parts & components to India \* General Electric Co 79/04/25 2pp

770627053: SECY-79-329
Informs Commissioners of receipt of Hitsui & Co application for license to export U.enriched to 3 78% in 102 kg U~235, to Japah
SHEALJ R Office of International Programs 77/05/11 1p

--7906290553 Forwards Mitsui & Co application for license to esport U. enriched to 3 95% in 10248 U-235.to Japan MGNDEN, T Mitsui & Co . Ltd 79/05/01 lp

790629097; Informs Commissioners of receipt of Ediow Intl Co license application to export 1,000 metric tons of U.contained in 1,180 metric tons U-308, to United Kingdom SHEA, J R Office of International Programs 79/05/1; 1p

---79062905B5 Forwards license application to export 1,000 metric tens U. contained in 1,180 metric tons of U-308, to United Kingdom License is extension of axpired License 88B-7982 EDLOW, U Ediow International Co 79/05/07 ip

7706270604 BECY-79-268A
Recommends approval of amend to Aerojet Ordnance &
Mfg Co license to export 45,043 kg U.contained in 45,360 kg
depleted U.to Canada
BHEAJ R. Office of International Programs 79/05/14 4pp

--7906270612 License for Aerojet Ordnence & Mfg Co to export 45:043 kg U.contained in 45:360 kg depleted U.to Canada OPLINGER:00 O Aesistant Director for Export/Import & International Safeguards. 78/08/16. 2pp

---7906290779 Amend 1 to license for Aerojet Ordnance & Hfg Co, intrfasion amount of math authorized for export to 100,000 kg depleted U contained in 100,704 kg depleted U alloy. OPLINGER,0.0 Assistant Director for Export/Import & International Safeguards. 79/03/14 1p

7906290714 SECY-79-014A
Informs Commissioners of Executive Branch response to pending license application for Nissho-Iwai American Corp to export 5,448 kg U-285 enriched to 45,4% to Japan Forwards applicant 790400 itr requesting amend to application.
SHEAL R Office of International Programs 79/05/11 is

--7906290718 Executive Branch position re Nissho-Iwai American Corp application for license to export 5 448 kg U-235, contained in 12 kg U-235 enriched to 45 4% in form of U metal.to Japan Wisupporting documentation NOSENZO.L V Defense, Dept of 79/05/01 17pp

#### TOPREP VENDOR REPORTS AND RELATED CORRESPONDENCE

- 7904170494 Responds to 790130 ltr re application of 100FR50 59 to GE reload fuel If reload involves neither Tech Spec change nor unreviewed safety question, prior NRC approval is not required

  CHECKLP 8 Reactor Safety Branch 79/04/02 10
- 7906010191 Forwards comments on NEDC-21673-P dtd Feb 1978, "Multivent Hydrodynamic Model for Calculating Pool Boundary Loads Due to Chugging, Mark I Containments " MAISE.O Brookhaven National Laboratory 79/05/09 9pp
- 790A010231 Details results of transient analysis in response to commitments made at 770426 meeting Analysis conducted to show that TRAP2 (BAM-10128) computer code will predict trend of behavior for sys parameters
  TAYLOR, J H Babcock & Wilcox Co 77/05/25 2pp
- 7906040139 Ack receipt of 790406 ltr describing new OE document control sys for handling revisions to GA rept NEDO-11209-04A Goncurs w/changes Revisions to repts requiring NRC review are subj to fees (RD-8-2 QE)
  MAASS.W P Guelity Assurance Branch 79/05/08 ip
- /906040157 Forwards addl requested info supplementing 790516 submittal re power operated relief valves & loss of feedwater transients
  ANDERSON, T H Hestinghouse Electric Corp NS-TMA-2089 79/05/21
- 7706040178 Responds to DF Ross 770517 ltr on ACR8 recommendations re TMI incident Concerns 5 recommendations resulting from TMI may not relate directly to all reactor types 5 designs 8HERNOOD, 0 0 General Electric Co , Nuclear Energy Products Div MFN-145/79 77/03/23 17pp
- 7906040214 Evaluates BAW-10039P, Suppl 1. "Prototype Vibration Measurement Results for B&W 177-Fuel Assembly Two-Loop Plant " Rept acceptable as ref to describe results of vibration qualification program VAROA:B A Light Water Reactors Branch 4 79/04/04 1p
- 7908040419 Forwards evaluation of WCAP-8986, "Perturbation Technique for Calculating ECCS Cooling Performance," 870LZ,J.F Light Water Reactors Branch 1 79/04/12 2pp
- --7906040422 WGAP-8986 Evaluation of HGAP-8986 Principle of parturbation technique is acceptable # Hestinghouse Electric Corp. 77/02/28 4pp.
- 7906060141 Forwards NEDU-21471-2, "Analytical Model for Estimating Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Remshead Air Discharges Huppl for Mark I T-Guencher Air Discharges from Mark I T-Guencher "

  5080N:L.J General Electric Co MFN-156-79 79/05/31 ip
- ---7906060143 NEDD-21471-2

  "Analytical Model for Estimating Drag Forces on Rigid Submerged Structures Caused by LOCA & Safety Relief Valve Ramshead Air Discharges, Suppl for Mark I T-Guencher Air Discharges from Mark I T-Guencher."

  LASHER, L E General Electric Co. 79/04/30 i3pp
- 7906060149 Forwards GE proprietary rept "Analytical Hodel for T-Guencher Water Jet Loads on Submerged Structures," NEDE-25090-P Rept withheld (ref 100FR2 790) 9880N.L.J General Electric Co., Nuclear Energy Products Div MFN-154-79 79/03/31. Ip
- 7904050166 Forwards NEDE-24537-P. "Mark I Containment Long-ferm Program, Development of Downcomer Lateral Loads From Full Scale Test Facility Data-Task Number 7 3 2." Rept withheld (ref 100FR2 790) 9080N.L.J. General Elect... Co., Nuclear Energy Products Div. MFN-133-79 79/08/31 lp.
- 79040702/1 Clarifies 790814 response to Question 1 3 re testing of cartain transmitters.
  ANDERSON,T M Wastinghouse Electric Corp. 48-TMA-2093. 79/05/28

- --7906070274 Bubmits Items 23.24 & 28 re post-accident functional requirements for radiation monitoring sys.sump level instrumentation & cable/splices W/list of operating plants that ref WCAP-7744, WCAP-7817, WCAP-7821 or WCAP-7829 EICHELDINDER, C Westinghouse Electric Corp N8-CF-1132 75/07/27 4pp
- 7906110260 Forwards NEDE-24640-P. "Off-Centerline 1/4-Scale X-Quencher Test Rept " W/affidavit Rept withheld (ref 10CFR2 790)
  SOBONI J General Electric Co , Nuclear Energy Products Div MFN-155-79 79/05/31 5pp
- 7906110304 Forwards NEDO-24612, "Mark I Containment Program Load Definition " SOBON.L J. General Electric Co., Nuclear Energy Products Div MFN-132-79 79/05/21 ip
- --7906110316 NEDD-24612
  "Mark I Containment Program Vent Header
  Deflector Load Definition "
  KENNEDY, H., KULKARNI, V., LUNDBERG, R. E. Acurez: Alcore 79/04/30
- 7906:10405 Notification of 790524 meeting w/OE in Bethesda, MD to discuss two-loop test apparatus implications for ECCS model & ECCS model errors #MDDGES:W Analysis Branch 79/05/14 ip
- 7906:10438 Notification of 790524 meeting w/OE in Bethesda,MD to discuss two-loop test apparatus implications for ECCS model to ECCS model errors Time changed to 9 00 AM HODGES,W Analysis Branch 79/05/14 1p
- 7906120230 Communts on ACRS recommendations of TMI further small break transient & accident analyses should be performed OMSLEY.0 F Exxon Nuclear Ca , Inc (subs. of Exxon Corp ) 79/03/29 2pp
- 7706120281 Confirms talcons re-schedule for submittal of generic ATH9 info Supports concerted approach proposed by AIF SCHERER: A E Combustion Engineering, Inc. LD-77-035 79/06/04
- 7906120359 Notifies that responsibility for all matters re June 1978 topical rept CASE-tri-1A has been transferred to RF Engimeler of FL Power & Light Co
  DAVIEGR W Baltimore Gas & Electric Co 79/06/07 2pp.
- 7906130237 Responds to MRC request for add1 info re NEDO-21061, "Hark II Containment Dynamic Forcing Functions Info Rept," Revision 3 Forwards relevant info 8000N.L J General Electric Co , Nuclear Energy Products Div MEN-152-79 79/05/30 ip
- --7906130238 NEDD-21061
  App A-3 responses to NRC 780630 third round question to be inserted in App A of NEDD-21061, "Mark II Containment Dynamic Forcing Functions Info Rept, " Revision 3
  \*\* Qeneral Electric Co . Nuclear Energy Products Div. 78/06/30 25o.
- 7906130239 Forwards complete set of responses to first round requests re NEDO-21061, "Mark II Containment Dynamic Forcing Functions Info Rept." Revision 3 Responses to be inserted into App A BBBON.L.J Qeneral Electric Co , Nuclear Energy Products Div MFN-151-79 79/05/29 2pp.
- --7906130243 NEDO-21061
  App A-1: responses to NRC 760612 first round questions to be inserted in App A of NEDO-21061, "Mark II Containment Dynamic Forcing Functions Info Rept," Revision 3.
  \* General Electric Co., Nuclear Energy Products Div 78/06/30 33pp.
- 7906130308 Forwards "Changes to Return Line to Reactor Vessel Control Rod Driveline. Hydraulic Control Sys."

  8HERHOOD. Q G. General Electric Co., Nuclear Energy Products Div. MFN 159-77. 79705/22 1p
- --7906130309 "Changes to Return Line to Reactor Vessel Control Rod Driveline, Hydraulic Control Bys " \* Owneral Electric Co., Nuclear Energy Products Div 79/04/30, Ban.
- 7906140344 Forwards list of plants using analytical technique for piping selamic analyses described in IE Bulletin 79-07 WEBTDYN computer code used prior to 1972 ANDERSON, T. M. Hestinghouse Electric Corp. NB-TMA-2094. 79/06/01. 2pp

- 7906150253 Provides schedule for completion of five NRC benchmark problems using G£ proprietary computer program PISYS QRIDLEY,R L. Oeneral Electric Co., Nuclear Energy Products Div 79/05/30 1p
- 7706150344 Forwards details of info to be provided re PISYS analysis of NRC benchmark problems
  ORIDLEY,R L Gameral Electric Co ,Nuclear Energy Products Div
  RLG-081-7 79/06/06 5pp
- 7906160051 Notification of 790509 meeting w/B&W in Bethesda.MD to review nonsafety-integrated control sys & determine interaction w/safety sys on B&W plants SXVKIEWIEZ.A J Electric. Instrumentation & Control Systems Branch 79/05/07 2pp
- 7906180422 NUREO/CR-0719
  "First Guarter FY79 Progress Rept on Refill Effects
  Program," quarterly progress rept.Oct-Dec 1978
  CROMLEY,C J., ROTHE,P H., CARY,C N. Create, Inc. FIN A-4070
  CREARE TN-292 79/05/31 18pp Available at NTIS
- 7906180483 Forwards "Evaluation of Reactor Vessel Brittle Fasiure Due to Injection of Cold HPI Water During Small LOCA Events" TAYLOR, J. H. Babcock & Wilcor Co. 79/06/13 ip
- --7906180489 "Evaluation of Reactor Vessel Brittle Failure Due to Injection of Cold HPI Water During Small LOCA Events " \* Pateork & Wilcox Co 79/06/13 13pp
- 7906180532 Responds to NRC request for add1 small break analysis re reactor coolant pump assumptions "Worst case break" & "worst time" are undefined Analysis should demonstrate that all breaks b times are covered TAYLOR, J H Babcock & Wilcox Co 79/06/08 ip
- 7906190388 Forwards BAW-10133P.Revision 1, "Mark C Fuel Assembly-LDCA-Seismic Analyses " Withheld (ref 10CFR2 790) Affidavit of JH Taylor encl TAYLOR.J H Babcock & Wilcox Co 79/05/31 2pp
- 7906190421 Forwards OF mag taps 31809, comprised of Sergent & Lundy tapes 2675 & 2649, table of contents of GE tape & microfiche duplicate of info contained on tape W/o tape SGBONL J General Electric Co , Nuclear Energy Products Div MFN-165-79 79/06/12 2pp
- 7906190490 Forwards list of topical repts submitted by GA Co to NRC, describing current status of each FISHER, C R General Atomic Co (subs of Oulf Oil Corp.) 79/06/14 4pp
- 7906200182 Forwards "Mark I Containment Activity Review" for Apr 1979 8080N.L J General Electric Co , Nuclear Energy Products Div HFN-166-79 79/06/15 1p
- ---7906200188 "Mark I Containment Activity Review" for Apr 1979

  \* General Electric Co . Nuclear Energy Products Div 79/04/30
- 790620D198 Forwards June 1979 "ATMS for Westinghouse Plants," to comply w/requirements of Alternative 3 of NUREO-0460, in response to 790215 request ANDERSON, T. M Westinghouse Electric Corp NS-TMA-2096 79/06/08
- --7906200201 "ATWS for Westinghouse Plants" \* Westinghouse Electric Corp 79/06/30 165pp
  - 8 Forwards first draft of apps to Repts BUNPQ-202 & BUNPQ-203 ty performance & safety features of reactor tion pump

- 7906210138 Forwards preliminary rept of joint investigation by Mestinghouse-Mitsubishi Heavy Industries re cracked support pins & flexures in guide tubes in operating Japanese plants Study to be concluded in June 1979
  ANDERSON,T M Hestinghouse Electric Corp NS-TMA-2099 79/06/11 900
- 7906210161 Forwards data re "Two-Loop Test Apparatus (TLTA) Resulta " SHERHDOD:G Q General Electric Co ,Nuclear Energy Producta Div MFN-167-79 79/06/15 102pp
- 7906210184 Notifies that NRC analysis of semiscale small break experiment as requested on 781002 is delayed until 791001 TAYLOR, J H Baccock & Wilcox Co 79/06/15 ip
- 7906210225 Forwards slides presented at 790501 meeting w/NRC to discuss ECCS evaluation model development status for Westinghouse fuel reloads of C-E NSS ANDERSON.T M Westinghouse Electric Corp NS-TMA-2091 79/06/07
- 7906210245 Forward; "ECCS Evaluation Model for Westinghouse Fuel Reloads of C-F NSSS," nonproprietary version ANDERSON,T M Westinghouse Electric Corp NS-TMA-2092 79/06/[L
- --7906210246 MCAP-9529
  "ECCS Evaluation Model for Westinghouse Fuel Reloads of C-E NSSS," nonproprietary version
  FERGUSON.K L. KEMPER,R H., ANDERSON,T M. Westinghouse Electric Corp. 79/06/30 92pp
- 7906210258 Forwards "ECCS Evaluation Model for Westinghouse Fuel Reloads of C-E NSSS," proprietary version Rept withheld (ref 100FR2 790)
  ANDERSON, T M Hestinghouse Electric Corp NS-TMA-2092 79/06/II 11po
- 7906220126 Requests add1 info for review of Revision 3 to 60-70P-1. qubmitted 790427 HAASS.H P Quality Assurance Branch 79/05/21 4pp
- 7906220290 Forwards addl info on WCAP-8859 \$ WCAP-8860 (nonproprietary), in response to NRC 781129 request ANDERSON, T M Westinghouse Electric Corp NS-TMA-2090 79/05/22 2500
- 7906220296 Forwards add1 info on WCAP-8821, "Tranfle Steam Generator Code Description," application for withholding AW-79-19 & affidevit WCAP-8821 add1 info withhold (ref 10CFR2 790) AMDERSON, T M Westinghouse Electric Corp N8-TMA-2090 79/05/22 2pp
- --7906220310 Application for withholding add1 info re WCAP-882L Translo Steam Generator Code Description." (ref 10CFR2. 790) WIESEMANN.R A Westinghouse Electric Corp AW-79-19 79/05/22
- --7906220321 Application for withholding proprietary info from public disclosure (ref 10CFR2 790) W/atlachment to NS-TMA-2090 which is addl info ra WCAP-8821, "Tranflo Steam Generator Code Description"
  WIESEMANN.R A Westinghouse Electric Corp AW-76-45. 79/06/29 900.
- 7906230039 Forwards 790301 proprietary rept BH-4689 "Pressuriser Ref Leg Effervescence Test " Requests rept be withheld (ref 10CFR2 790) W/o encl TAYLDR:J H Babcock & Wilcox Co 79/09/03 1p
- 7906230137 Draft "Decay Heat Removal Problems Associated N/Recovery From Very Small Break LOCA for B&W 205-Fuel-Assembly PWR " \* Babcock & Wilcox Co 77/09/30 48pp
- --7905230140 BAH-10074A
  "Multimode Analysis of Small Breaks for B&W
  205-Fusi-Assembly Nuclear Plants W/Internals Vent Valves "
  JGNES,R C , DUNN,B M , PARKS,C E Babcock & Wilcox Co. 76/03/JL
- --7906230143 Informs of completion of review of BAW-10062, Revision 1: BAK-10074, Revision 1: & BAW-10075, Revision 1: Forwards topical report evaluation BCHMENCER: A Light Water Reactors Branch 2: 76/01/08 4pp
  - 706230145 Topical rept evaluation of BAU-10062, Revision 1: BAU-10074: Revision 1: & BAU-10075, Revision 1: re small break spectrum analyses for B&U 145: 177 & 205-Fuel-Assembly Plants w/internals vent values

    \* Assistant Director for Light Mater Reactors 76/01/98 Spp

- 7906260337 Forwards "Benchmark Analysis for Asymmetric Loop Events 1177 Fuel Assembly Plants) " TAYLOR, J. H. Babcock & Wilcox Co. 79/06/15 ip
- --7906260363 "Benchmark Analysis for Asymmetric Loop Events (177 - Fuel Assembly Plants) " \* Babcock & Wilcox Co 79/06/15 19pp
- 7906260413 Responds to NRC 790613 request for add1 info re control blade life (B4C loss) Info will be forwarded on 790702 GRIBLEY,R L General Electric Co .Nuclear Energy Products Div MPN-168-79 79706/18 1p
- 7906260475 Summarizes 790613 meeting w/NRC in Washington.DC re reactor vestel brittle fracture during small LOGA events TAYLOR.J H Babcock & Wilcox Co 79/06/14 2pp
- 7906270077 Forwards revisions to XN-NF-77-57, "Exxon Nuclear Power Distribution Control for PWRs Phase II " DWSLEY,Q F Exxon Nuclear Co , Inc (subs of Exxon Carp ) 79/04/27 35pp
- 7906270197 Forwards responses to NRC 780601 request for add1 info re HCAP-8977. "Failure Mode & Effects Analysis of ECCS Hestinghouse Type 312,3-Loop PMR " AMDERSON, T M Westinghouse Electric Corp NS-TMA-1876 78/07/21 23pp
- 7906270211 Requests info re review status of BSCO-155215, "Containment Spray Noziles for Nuclear Power Plants" CRAY, E.S. Spraying Systems Co. 79/06/20 1p
- 7906270213 Informs of change in mgt structure Change will be reflected in update of GA topical rept TR-21A scheduled for Aug 1979 PICKFORD, A E C F Braun & Co 79/06/20 1p
- 7906280115 Forwards proposed method for calculation of DND penalty to allow B&W immediate credit for bowed rod critical heat flux (CHF) test TAYLOR,J H Babcock & Wilcox Co 79/06/22 3pp
- 7906290289 Forwards three revised organization charts for Power Div & QA Div of Reading & Jackson Co Reorganization completed to levels shown in Jul 1778 "GA Program for Nuclear Power Plants," GAI-TR-106. Revision to BARKER, N R C(1bert Associates, Inc. 79/06/19 5nn
- 7906290794 Summary of 790330 meeting w/GE & BNL ro resolution of generic BHR feedwater notile cracking problems
  SHAIDER,R P Systematic Evaluation Programs Branch (Pre 790625)
  79/06/06 3pp

# WASTE MOT NUCLEAR WASTE MANAGEMENT

- 7904020240 Comments on 781115 EFA-proposed criteria for radioactive wastes Questions viability of EPA concept of complete (solation of all wastes Notes vagueness of certain criteria H/detailed comments GOSSICKL V Office of the Executive Director for Operations 79/03/13. 8pp
- 7704050286 DOE/EIB-0046-D V1 Forwards DES.Vol 2 App "Mgt of Commercially-Generated Radioactive Wasts." # Energy, Dept of 77/04/30 1p
- --7906050288 DDE/EIS-0046-D V2
  DES/Vol 2 App, "Mgt of Commercially Generated Radioative
  Waste"
  \* Energy, Dept of 79/04/30 600pp
- 7905110020 Bubmits schedule for technical info meetings proposed for 790206 briefing on waste mgt program Also submits proposed agenda for first meeting MEYERS.8 Energy,Dept of 79/03/30 3pp.
- 7906110030 Forwards notice for fourth meeting in series of NRC/DOE meetings re radioactive waste repositories Meeting notice & agende have been sent to those on distribution list M/o encl.

  MALARO-J C. High Level Waste Licensing Management Branch. 79/05/07 Ip
- ---7906110193 Notification of 790523 meeting w/DDE in Silver Spring.MD to giscuss radioactive waste repositories
  MALARG.J C. High Level Waste Licensing Management Branch.
  79/05/07. 2pp.

- 7906:10034 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories
  O'NEIL, J. H. Shaw, Pittman, Potts, & Troubridge, 79/03/26 ip
- 7906110036 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories BROWN.W S Westinghouse Electric Corp 79/03/27 1p
- 7906110038 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories BAKER,B J Hestern Nuclear, Inc. (subs. of Phelps Dodge Corp.) 79/03/27 1p.
- 7906110044 Requests to be placed on distribution list for natices of public meetings on radioactive waste repositories ELLIG, J.L. Gilbert Associates, Inc. 79/03/28 ip
- 7904110047 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories SDINSKI.A J California, State of 79/03/28 ip
- 7906110090 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories BROHN.8 H Hyoming Mineral Corp 79/03/28 1p
- 7706110051 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories PARKLEY, W.A. Consumers Power Co. PARK 9-79 79/03/29 1p
- 7906110034 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories RIEDERR.C F Wiscansin, State of 79/03/29 ip
- 7906110055 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories HARVEY, J.L. South West Nuclear Co. 79/03/30 1p
- 7906110057 Requests to be placed on distribution list for notices of public meatings on radioactive waste repositories QREY.A E EQ & O. Inc 79/04/02 1p
- 7904110069 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories DEBOER.T K. New York. State of. 79/04/02 ip
- 7906110071 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories DARBY, C Affiliation Unknown 79/04/03 ip
- /906110074 Requests to be placed on distribution list for notices of public meetings on redicative waste repositories ZIMMERMAN.D L. General Electric Co , Nuclear Energy Products Div 79/04/03 1g
- 7906110076 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories WARREN.B C Florida. State of 79/04/04 lp
- 7906110078 Requests to be placed on distribution list for notices of public mestings on radioactive waste repositories HALEY J. Affiliation Unknown. 79704/05 1p.
- 7906110079 Requests to be placed on distribution list for notices of public meetings on radicactive waste repositories.

  HANCOCK,D Southwest Research and Information Center. 79/04/05
- 7906110081 Requests to be placed on distribution list for notices of public meetings on redicactive waste repositories BEATTY.T E Edison Electric Institute 79/04/06. 1p
- 7906110082 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories.

  BURTL Massachusetts: State of. 79/04/06 ip.
- 7906110083 Requests to be placed on distribution list for natices of public meetings on radioactive waste repositories BRQOK8-H B. Tennessee Valley Authority 79/04/10 ip
- 7906110087 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories JANDEGIAN.G.V Envirosphere Co 79/04/10 1p
- 7906110089 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories.
  PENROD, D C. Affiliation Unknown. 79/04/13 ip.

- 7906110090 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories BARTLETT-LAGORI Affiliation Unknown 79/04/19 ip
- 7906110092 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories FRANK.T Affiliation Unknown 79/04/21 1p
- 7906110093 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories REIDNER.L J California, State of 79/04/23 ip
- 7906110095 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories NICOLL:R M Tennessee Valley Authority 79/04/24 ip
- 7906110097 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories QEYDON, J. L. Affiliation Unknown 79/04/25 1p
- 7906:10099 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories LEMIS. J Affiliation Unknown 77/04/25 ip
- 7906:10:102 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories THADANI.M. Teknekron. Inc. 79/04/27 ip
- 7906110103 Requests to be placed on distribution list for notices of public meetings on radioactive wasts repositories NIVEN.A L. New England Regional Regulatory Assistance Program 79/04/16 tp
- 7905:10107 Requests to be placed on distribution list for notices of public meetings on radioactive waste repositories CLARK.K. Citizens for Alternatives to Radioactive Dumping 79/04/14 | 1p
- 7906190230 Summary of 790411 meeting w/DDE in Silver Spring. HD re geological exploration program being implemented by DDE to identify sites for nuclear waste repositories BOYLE.R R High Level Waste Licensing Management Branch 79/04/18 2pp
- 7706230160 Bummary of NRC/DDE meeting re geologic exploration for high level waste repository sites Forwards "Program for identifying Bites for Nuclear Waste Repositories" & "Geologic Investigations Basalts of Columbia Plateau "BOYLER R High Level Waste Licensina Management Branch 79/04/11 127pp
- XPORTLIC EXPORT AND IMPORT LICENSES
- 7905230723 NRC conclusions re Transnuclear, Inc application for license to export 10,581 kg U to Belgium License should be issued MODRE, R N Office of International Programs. 79/04/27, 1p
- 7906010087 Executive Branch position re Bosing Co application for amend to license to export 4:000 lb of depleted U to Iran in form of plated mircraft counterweights License should not be granted.
  NOSENTO.L. U. State.Dept of Bureau of Oceans & Internati.Environ. & Scientific Affairs. 79/04/26 19
- 7906010090 Forwards application for Ramsey Engineering Co to export 1 415 mg of Pu-238 to Paru.

  HENDRICK.W.O Ramsey Engineering Company. 79/04/23 ip
- --7906010092 Application by Ramsey Engineering Co for license to export 1.415 mg of Pu-238 to Peru.
  HENDRICK, W O Ramsey Engineering Company. 79/04/23, 2pp.
- 7906010103 Executive Branch position re Bandvic Special Metals Corpapplication for license to export 650 lb of tircaloy-4 tubes to Korea.License should be prented NOSENZO:L V State.Dept.of 79/04/26. 4pp

- 7906010146 SECY-79-297
  Informs Commission of receipt of Transnuclear, Inc 790420
  application for license to export highly enriched U to
  Denmart
  SHEA-J R Office of International Programs 79/04/26 1p
- 7906010172 Forwards FR notice for filing & publication of applications for licenses to export nuclear facilities or matl OPLINGER.0 O Assistant Director for Export/Import & International Safeguards 79/04/27 3pp
- 7906010172 Forwards FR notice for filing & publication of applications for licenses to export nuclear facilities or matl OFLINGER, O O Assistant Director for Export/Import & International Safeguards 79/04/27 Jpp
- 7906020017 Forwards proposed license for US Army Matis & Mechanics Research Ctr to export source matl to United Kingdom Requests review SHEA.J R Office of International Programs 79/04/04 App
- --7906020021 Executive Brauch position re UB Army Matls & Machanics Research Ctr application for license to export 250 kg depleted U alloy to United Kingdom License should be granted NOSENZOL V State.Dept of, Bureau of Oceans & Internat! Environ & Scientific Affairs 79/01/03 2pp
- --7906020023 Application by US Army Matls & Mechanics Research Ctr for license to export 250 kg deplated U alloy to United Kingdom HRIGHT,E S Army Dept of Matls & Mechanics Research Center 79706/12 2pp
- ---7906020027 License for Army Matls & Mechanics Research Ctr to espect 250 kg depleted U to United Kingdom OPLINGER:G O Assistant Director for Expart/Import & International Bafeguards 79/04/04 2pp
- 7906020101 SECY-79-206
  Provides NRC review of Transnuclear, Inc 790103 application for license to import low enriched U as U hexafluoride from France
  SMEA, JR Office of International Programs 79/04/23 3pp
- --7906020103 Application by Transnuclear.Inc for license to import 5:300 kg V.enriched to max of 2 3% U-235.from France MAT5UN,V Transnuclear.Inc 79/01/03 2pp
- ---7906020106 License for Transnuclear. Inc to import max of 5,000 kg U.
  enriched to max of 2 3% U-235, from France

  OPLINGER.9 G Assistant Director for Export/Import &
  International Safeguards 79/01/03 2pp
- 790&02014& Requests Executive Branch position re Edlow Intl Co application for license to export natural U to United Kingdom for conversion to U hexafluoride & subsequent return to US for enrichment OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/10 ip.
- 7905020149 Requests Executive Branch position re OA Co application for license to export SMM to Philippines OPLINGER, O O Assistant Director for Export/Import & Internaliensi Bafeguards 79/05/10 ip
- 7905020152 Requests Executive Branch position re Nissho-Iwai amended application for license to export 14 kg U (increased from 12 kg)

  OPLINGER,0 Q Assistant Director for Export/Import & International Safeguards 79/05/10 lp.
- 7906020136 Executive Branch position re TNS, Inc application for license to export 1.000 kg thorium in form of thorium oxide powder to Caneda License should be granted.
  NOBENZO.L.V State.Dept of 79/05/17 Spp
- 7906020162 Requests Executive Branch position re Transmuclear, Mc application for license to export 22,090 kg Urenriched to 3 33% U-235, to Suitzerland, OPLINGER, G. 0 Assistant Director for Export/Import & International Safeguards 79/05/10 1p.
- 7906020190 Requests Amend 8 to QE export license, changing licenses, ultimate consignee & intermediate consignee.
  HILSON, B B General Electric Co., Nuclear Energy Products Div BDH-790112 79705701 2pp
- 7906020197 Requests amond to Nissho-Iwai export license application changing intermediate consignee, quantity to be shipped & commodity description.
  TSUJI.N Nissho-Iwai American Corp MACPJ-2203-NT. 79/04/30 281-

- 790&020174 Requests Amend 3 to GA Co export license, extending expiration date to 801201 MOMRY, W R General Atomic Co (subs of Gulf Dil Corp ) IEL-1058 79703702 IP
- 7905020194 Requests Amend 3 to GA Co export license, extending expiration date to 801201 MCHRY.W R. General Atomic Co (subs of Gulf Gil Corg ) IEL-1058 79705/02 ip
- 7906020197 Requests immediate action on Consolidated Controls Corpapplication for license to export 20 resistance temp datactors to Italy AMALFITANO, JM. Consolidated Controls Corp (subs of Condec Corp) 79/05/09 App
- 7906040185 Application by Hoke Inc for license to export bollows-scaled instrument isolating valves to Argentina LINDER. T. P. Hoke, Inc. 79/04/16 1p
- 7904040224 Requests Executive Branch position re Reuter-Stokes, Inc application for license to export SNM to India OPLINGER, G G Assistant Director for Export/Import & International Safeguards 79/05/10 ip
- 7906040230 Executive Branch position re Exxon Nuclear Co. Inc application for license to export zircalog tubing, spacer parts & springs, caps. Insulator disks, tie plates & other fuel assembly hardware to Sweden License should be granted NOSENZO.L V State. Dept. of, Bureau of Oceans & Internati Environ & Scientific Affairs 79/05/17 2pp
- 7904040233 Executive Branch position re Isotope Products Labs application for license to export 10 uCi Cm-244 in scaled source to Kenya License shquid be granted MGSENZO, L V State, Dept of, Bureau of Oceans & Internati Environ & Scientific Affairs 79/05/17 1p
- 7704040363 Commissioners have reviewed & agreed w/SJ Chilk recommendation re Exxon Nuclear Co.Inc. application to import 40.000 kg U.enriched to 3 1% U-235.from Soviet Union Requests Exxon be notified CHILK.S J Office of the Sacretary of the Commission 77/04/20 is
- 7906040367 Notifies of Commissioner approval of license for Transnuclear. Inc to import 22 701 kg U.enriched to 73 12X U-235. from France Raquests Transnuclear. Inc he notified CHILK.S J Office of the Secretary of the Commission 79/04/20 ip
- 7706040408 Executive Branch position re Cordis Corp application for license to export 45 g of Pu-23B to Jordan & Saudi Arabia NOSENZO, L. V State, Dept of 77/04/23 2pp
- 7906040408 Executive Branch position re Cordis Corp application for license to export 45 g of Pu-238 to Jordan & Baudi Arabia NDSENZO,L V State, Dept of, 79/04/23 2pp
- 7906040409 Approves Transnuclear, Inc 790103 application for license to export 12,714 kg U to West Germany, based on Executive Branch position & end use statements

  HODRE, R N Office of International Progress 79/04/27 ip
- 7906040435 Executive Branch position re Reuter-Stokes, Inc application to export 16 mg U-235 to India License should be granted Ltr of assurance encl NOSENZO, L. V. State, Dept of 79/05/01, 3pp
- 7706040437 Requests Executive Branch position re Westinghouse application for license to export miscellaneous components & parts to Spain.
  OPLINGER.G.O. Assistant Director for Export/Import & International Safeguards, 79/04/26. 1p.
- 790604043B Responds to 790103 itr requesting amend to export license to extend expiration date to 810301 Due to instability of political situation in Iran, Executive Branch is unable to approve request OPLINGER, O Assistant Director for Export/Import & International Safeguards 79/05/03, 1p.
- 7906040440 Requests expiration date on Licenses JSNM-1698 & ISNM-1699 be extended from 790801.

  MATSON: V. Transnuclear: Inc. 79/04/04. 2pp
- 7906040440 Requests expiration date on Licenses IBNM-1698 & IBNM-1699 be extended from 790801 MATSON, V. Transnuclear, Inc. 79/04/04, 2pp.

- 7906050010 Requests Executive Branch position re GE 790425 application for license to export replacement parts, for use in Tarapur reactor, to India OPLINGER, G G Assistant Director for Export/Import & International Bafeguards 79/05/09 1p
- 7906050015 Requests Executive branch position re GA Co 790501 application for license to export components for use in PRR-i research reactor, to Philippines W/o encl OPLINGER, 0 G Assistant Director for Export/Import & International Bafeguards 79/05/09 1p
- 7906090072 Forwards application to export 1,000 metric tons U.contained in 1,180 metric tons U-308 concentrate to United Kingdom EDLOW.J Edlow International Co 79/03/07 ip
- --7906050077 Application by Edlow Intl Co for license to export 1,000 metric tons U.contained in 1,180 metric tons U-308 concentrate.to United Kingdom EDLON, J Edlow International Co 79/05/07 ip
- 7906090088 Forwards application for license to export startup, intermediate, linear & wide range channels to Philippines MOMRY, W.R. General Atomic Co. (subs. of Gulf Gil Corp.) 79/05/01
- --7906050092 Application by OA Co for license to export Channel Models NLB-4, NLI-5, NP-5, NLH-2 1 NMP-4 to Philippines HOHRY, W R General Atomic Co. (subs of Gulf Oil Corp 79705/Oi 2pp
- 7906090095 Requests new export license for 20,000 kg depieted U parts, dud to accelerated scrap accumulations Requests issuance by 790915 SCHWARTZ.H Aprojet Ordnance Co 79/04/26 ip
- 7906050101 Requests amend to export license to change export parties to Nissho-luai Co, Ltd MATSON,V Transnuclear, Inc 79/05/03 1p
- MATSON, V Transmuclear, Inc 79/05/03 1p
  7906050111 Application by Signa Chemical Co for license to export
- 7906050111 Application by Sigma Chemical Co for license to export compounds containing deuterium, equivalent to 8 kg deuterium oxide liquid, to Mexico
  BTERN, C Bigma Chemical Co (subs of Bigma Aldrich Corp. ).
  77/05/03 ip
- 7906030137 Forwards request for artension of License XCOM-0225 & amond of dollar value; original amount was expressed in Canadian dollars
  LINDNER: T P Hoke, Inc 79/04/09 ip
- --7906050167 Application by Hoke Inc for license to export control valves to South Koree Requests revision in value & extension of encl Dept of Commerce License A301762 LINDNER, TP Hoke Inc 1112 79/05/07 2pp
- 7906050253 License for Cordis Corp to export 45 g Pu.contained in 200 cardiac pacers to Saudi Arabia & Jordan OPLINGER, G G Assistant Director for Export/Import & International Safaguards 79/04/27 2pp
- 7906050257 License for CA Co to export 784 g U-235 contained in 3,940 g U to West Oermany OPLINGER.G G Assistant Director for Export/Import & International Safeguards 79704/30 2pp
- 7906050261 Licensa for OE to export signal amplifiers, electrical penetration modules & raduaste drum cappers to India. OPLINGER.G O Assistant Director for Export/Import & International Safeguards 79/04/30. ip
- '906050264 License for Byron Jackson Pump Div to export seal cartridges; heat axchangers; rotating baffles; elements & coupling assemblies to Buitzerland.
  OPLINGER, 0 0 Assistant Director for Export/Import & International Bafeguards 79/04/27. ip.
- '906050266 License for Hoke, Inc to export 21 control valves & spars parts to Canada. OPLINOER,0 0 Assistant Director for Export/Import & International Safeguards 79/07/01 1p.
- 7906050267 License for Byron Jackson Pump Div to export three pump case accessories specially prepared for use in coolant pumps to Italy.

  OPLINGER, 0, 0 Assistant Director for Export/Import & International Safauards 79/04/27 15.

- 7906050396 License for Eberline Instrument Corp to export 81.6 uCi Pu-239 to Indonesia OPLINGER.G O Assistant Director for Export/Import & International Bafeguards 79/04/27 Zpp.
- '906080402 License for Mitsuiline Travel 8vc of America to export mixcellaneous specially-designed or prepared parts & components to Japan OPLINGER,0 Q Assistant Director for Export/Import & International Bafeguerds 79/04/27 2pp
- '906050404 License for Syron Jackson Pump Div to export seal cartridges heat exchangers, baffles, element coupling assemblies & pump case to Italy GPLINGER, G G Assistant Director for Export/Import & International Safeguards 77/04/27 ip
- '906050408 License for QE to export 16 source range & intermediate range monitors to India.

  OPLINGER, Q G Assistant Director for Export/Import & International Safeguards 79/04/30 ip
- '906060016 Agrees to proposed license for import of low enriched U hexafluoride from Societ Union, provided certain conditions are met addition of NMSS technical review section & rewording of NMSS portion of coordination statement DIRCKS, W. J. Office of Nuclear Material Safety & Safeguards 79/04/10 ip.
- '904060071 SECY-79-233A
  Informs Commissioners of preliminary comments on proposed license for Ediow Inti to export low enriched U to India Recommendations deferred until Executive Branch briefing on pertinent foreign policy developments
  SHEA, J R Office of International Programs 79/04/24 Gpp
- 7906060094 Application by Reuter-Stokes. Inc for license to export 8 34 g U-235 to India W/supporting documentation SKARUPA, J D Reuter-Stokes. Inc 79/04/26 4pp
- 7906070101 SECY-79-241
  Submits add! info re several proposed expert licenses
  Discusses 790316 meeting of Euratom Supply Agency, Delegation
  of Commission of European Communities & NRC Ofc of Inti
  Programs re urgent need for highly enriched U in Europe
  SHEAJ R Office of International Programs 79/03/30 3pp
- 7906070101 EECY-79-241

  Bubmits add1 info reseveral proposed export licenses.

  Discusses 790316 meeting of Euratom Bupply Agency, Delegation of Commission of European Communities & NRC Ofc of IntiPrograms re ungent need for highly enriched U in Europe
  EHEA, J R Office of International Programs 79/03/30 3pp
- 7906070101 BECY-79-241

  Bubmit's addl info re several proposed export licenses.
  Discusses 790316 meeting of Euratem Supply Agency. Delagation of Commission of European Communities & NRC Ofc of Intl Programs re orgent need for highly enriched U in Europe, BHEA: J R Office of International Programs, 79/03/30 Spp
- 7906070101 SECY-79-241
  Submits add1 info re several proposed export licenses.
  Discusses 790316 meeting of Euratom Supply Agency, Delegation of Commission of European Communities & NRC Ofc of Inti Programs re urgent need for highly enriched U in Europe, SHEA-J R Office of International Programs 79/03/30 3pp
- 7906070101 SECY-79-241
  Submits add1 Info re several proposed export licenses
  Discusses 790316 meeting of Euratom Supply Agency, Delegation
  of Commission of European Communities & NRC Offc of Intl
  Programs re urgent need for highly enriched U in Europe
  SHEA-J R Office of International Programs 79/03/30. 3pp
- 7904070101 SECY-79-241
  Submits add info reseveral proposed export licenses
  Discusses 790316 meeting of Euratom Supply Agency, Delegation
  of Commission of European Communities & NRC Ofc of Intl
  Programs re urgent need for highly enriched U in Europe,
  SHEA-J.R. Office of International Programs 79/03/30. 3pp.
- --7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators, as well as conversion & fabrication planning of Nutem GOPPEL, M European Communities, Commission of, 79/03/19. Spp
- --7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators, as well as conversion & fabrication planning of Nukem GOPPEL,M. European Communities. Commission of, 79/03/19 Spp.

- --7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM GOPPEL.M European Communities, Commission of 79/03/19 Spp
- --7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM COPPELM European Communities, Commission of, 79/03/19 Spp
- ---7906070132 Responds to 790316 meeting request for info re research program & fuel cycle schedule of reactor operators as well as conversion & fabrication planning of NUKEM QOPPEL,M European Communities, Commission of 79/03/19 Spp
- 7906070125 Application by Hoke, Inc for license to export needle valves to Booth Korea LIMPINER, T P Hoke, Inc. 79/04/16 ip
- --7906070155 Application by Hoke, Inc for license to export bellows-sealed instrument isolation valves to Bouth Korea LINDNER, T.P. Hoke, Inc. 79/04/16 1p
- --7906070166 Application by Hoke, Inc for license to export bellous-sealed manually & pneumatically operated valves & three valve manifolds to South Korea LINDNER, TP Hoke, Inc 79/04/16 1p
- 7906070264 Application by Hoke, Inc for license to export bellows-scaled instrument isolating valves b spares to Canada LINDNER, T P Hoke, Inc 79/04/05 4pp
- 7906070276 Executive Branch position re Mitsubishi Intl Corpapplication for license to export manipulator crane, for charging \$\fo\$ discharging fuel assemblies to Japan License should be granted MGSENZO.L V State. Dept of 79/05/02. 2pp
- 7906070367 Discusses issuance of license to Consolidated Controls w/o customary 15-day waiting parled Applicant was unawars that license was required for export of detectors to Italy SHEALJ R Office of International Programs 79/05/09 ip
- 7906070382 Executive Branch position re Sandvik Special Metals Corpapplication for license to export 15 lb Zr-2 & Zr-4 rods & strips.for testing of physical properties, to Israel License should be granted W/Itr of assurance NOSENZO.L V State.Dept of 79/05/03 3pp
- 7906120103 Forwards Edlow Intl Co application amend request to remove Reaktor Brennelemente Union GmbH as intermediate consignee Requests amend be considered w/application forwarded 781113 H/o encl PFLINGER.O G Assistant Director for Export/Import & International Safeguards 79/04/23 ip
- 7906120217 Requests license to export fission counter & accompanying reactor instrumentation replacement to Philippines MOMRY.W R General Atomic Co (subs of Oulf Oil Corp ) IEL-1036 79/05/01 1p
- --7906120227 Application by GA Co for license to export Fission Counter ML-6376 containing U-235 to Philippines MOMRY.W R General Atomic Co (subs of Gulf Dil Corp ) 79/05/01. 1p
- 7904130079 Application by Hestinghouse for license to export three compensated ionization chambers to France POCHAL.W F. Westinghouse Electric Corp. 79/03/15. 1p
- 7906140550 Cancels export license applications XMAT-17.XMAT-18 & XMAT-23.per Aldrich Chemical Co 770514 request HEMBY.E D Office of International Programs 77/05/15. 1p
- 7906140550 Cancels export license applications XMAT-17.XMAT-18 & XMAT-23.per Aldrich Chemical Co 790514 request HEMBY.E 0 Office of International Programs 79/05/15. [p
- 7906140580 Cancels export license applications XMAT-17, XMAT-18 & XMAT-23, per Aldrich Chemical Co 770514 request HEMBY.E.D Office of International Programs 79/05/15. 1p
- 7906140560 Forwards application for license to export 80 mC( nickel for use as ionizing source in gas chromatograph electron capture during 2-yr period of license
  MOSLEY, J J Varian Export Corp. 79/03/27 ip.

- --7906140567 Application by Varian Export Corp for license to export 80 mCi nickel for use as ionizing source in gas chromatograph electron capture detector during 2-yr license period MOSLEY, J J Varian Export Corp 79/03/22 2pp
- 7906140575 Forwards two applications to export 126,000 kg U & 22,090 9 kg U to France End use statement encl HATSON,V Transnuclear, Inc 79/05/02 2pp
- 7906140373 Forwards two applications to export 126,000 kg U & 22,090 9 kg U to France End use statement encl
  MATSON,V Transnuclear, Inc. 79/05/02 2pp
- --7905140602 Application by Transnuclear Inc for license to export 125,500 kg U. snriched to 0 35% U-235. & 500 kg U hearljauoride enriched to 0 3% U-235. to France MATBON, V Transnuclear Inc 79/05/03 ip
- 790&140&12 Application by Sigma Chemical Co for license to export compounds containing deuterium to India

  \* Sigma Chemical Co (subs of Sigma Aldrich Corp ) 79/05/01 1p
- 7906140617 Application by Mitsui & Co for license to export enriched U hexafluoride to Japan \* Mitsui & Co., Ltd 79/05/01, 2pp
- 7906130029 Application by GE for license to export six traversing income probe detector assemblies to India SON.B D General Electric Co 79/05/07 ip
- 7906130107 License for Hoke Inc to export motorized & isolating valves & spare parts to South Korea.

  OPLINGER G G Assistant Director for Export/Import & International Safeguards 79703/10 ip
- 7906150107 License for Spex Industries, Inc. to export 0 09025 g U-235 to Japan OPLINGER, Q G Assistant Director for Export/Import & International Bafeguards 79/05/10 2pp
- 7906150111 License for Mitsubishi Intl Corp to export 545 kg U-235 to Japan OPLINGER: O G Assistant Director for Export/Import & International Safeguards 79/05/10 ip
- 7904130117 Amend 8 to license for OE & GE Technical Svc Co. Inc to export components & associated BHR equipment to Japan OPLINGER. O O Assistant Director for Export/Import & International Safeguards 79/08/14 1p
- 7906150119 License for Air Products & Chemicals, Inc. to export 259 P g deuterium as gas to United Kingdom OPLINGER, G G. Assistant Director for Export/Import & International Safeguards 79705/11 2pp
- 7906150122 License for Westinghouse to export 0 0041 g U-235 to Belgium OPLINGER.G O Assistant Director for Export/Import & International Safeguards 79/05/11, 2pp
- 7906150286 Executive Branch position re Wolverine Div application for license to expert Ir guide thimble tubes & instrumentation tubes to France License should be granted NGSENZOL V State: Dept. of 79/05/17 2pp
- 7906:30462 Application by United Kingdom Treasury & Supply Delegation for license to export seamless reactor grade Zircaloy-4 tube to United Kingdom. 79/05/02 1pp
- 7906190471 Requests license to export two pieces of Zircaloy-2 seamless tubing to South Korea
  GLDBRT-Y K. Kawacki Berylca Industries, Inc. 79/05/11 2pp
- 7905150474 Application by GE for license to export replacement parts to India MILEON, B D General Electric Co BDM-79108, 79/04/25 2pp
- 7906160011 Forwards application for license to export minor nuclear math. Ltr of assurance required, W/o encl OPLINGER 0 Q Assistant Director for Export/Import & International Safeguards 79/04/30. 1p
- 7906160012 Requests Executive Branch position re Varian Exports Corpapplication for license to export 80 mCi nickel to various countries listed in Paragraph 110 27 W/o encl OPLINGER.0 0 Assistant Director for Export/Import & International Bateguards 79/04/27 ip.

- 7906160015 License for QE to export miscellaneous specially-designed or prepared parts & components except assembled pressure vessels to Japan OPLINGER O Assistant Director for Export/Import & International Bafeguards 79/05/02 2pp
- 7906160018 License for Transnuclear, Inc to export 3 95 to Canada OPLINGER, 0 0 Assistant Director for Export/Import & International Safeguards 79/03/08 2pp
- 7906160025 License for Sandvik Special Metals Curp to export 450 lb of Zircalou-4 tubing to South Korea OPLINGER.0 6 Assistant Director for Export/Import & International Safeguards 79/05/02 ip
- 7906160028 License for 8W Shattuck Chemical Co to export 5 6 b U to Mexico
  OPLINGER, 0 0 Assistant Director for Export/Import & International Bafeguards 97/05/03 2pp
- 7906160029 License for SN Shattuck Chemical Co to export 4 7 lb U to Mexico. OPLINGER, G O Assistant Director for Export/Import & International Bafeguards 79/05/03 2pp
- 7906160031 License for Garan Precision Engineering & Mfg Corp to export 20,000 diamond springs to India OPLINOER,0 0 Assistant Director for Export/Import & International Bafeguards 79/05/02 ip
- 7906160036 License for Dept of Army to export 250 kg depleted U to United Kingdom OPLINGER.0 G Assistant Director for Export/Import & International Bafeguards 79/05/03 2pp
- 7906160039 License for Reuter-Stokes, Inc. to export 16 mg U-235 to India OPLINGER, O G Assistant Director for Export/Import & International Safeguards 79/05/04 2pp
- 7906160043 Application by Hoke, Inc for license to export bellows-sealed manually & pneumatically operated valves, bleed & drain valves & three valve manifolds to Korea LINDNER.TP Hoke, Inc. 79/04/16 ip
- 7906160057 Notifies of export of one lot of math against license which packaged by Potrocomics Corp, instead of original shipper, United Nuclear Corp EDLOW, J Ediow International Co 79/05/07 ip
- 7906160058 Application by GE for license to export nottle fittings to The Notherlands WILBUN:B D General Electric Co BDW-79115 79/05/03 1p
- /906160059 License for GE & GE Technical Svc Co to export miscellaneous specially-designed or prepared parts & companents to Busden OPLINGER,0 O Assistant Director for Export/Import & International Safeguards 79/03/10 ip
- 7906160061 License for Bandvík Special Metals Corp to export 15 lb tubes made from Ir metal (Zircaloy-2 rod, Zircaloy-4 rod, Zircaloy-2 strip & Zircaloy-4 strip) to Israel, GPLINGER,0 G Assistant Director for Export/Import & Internat' Safeguards 79/05/10 ip /
- 7906160063 Amend 3 to 1 801201. GPLINGER, 0 0

- 7906180072 Application by Hote, Inc for license to export bellows-sealed finetrument isolating valves to Korea + Hake, Inc 79/04/16 ip
- 7906180081 Requests Executive Branch position re QA Co application for license to export miscellaneous components to Egypt DPLINGER, Q Q Assistant Director for Export/Import & International Bafeguards 79/05/03 ip
- 7906180128 Requests Executive Branch position re Monsanto Research Corpapplication for license to export SNM to Turkey.

  OPLINGER. 0 G Assistant Director for Export/Import & International Bafeguards 79/05/04 ip
- Reviews proposed amend to RMI Co license to export math to Canada Amend would extend expiration date for two yrs & increase quantity of depleted U to 135,059 kg Amend should be granted

  BHEA, J R Office of International Pressure 70/04/00 7906180615 SECY-79-310 Office of International Programs 79/04/30 4pp
- --7906180619 License for RMI Co to export 99.250 lb U.contained in 100.000 lb depleted U.to Canada License now referred to as XU-8342 GUHIN, M A Assistant Director for Export/Emport & International 76/12/10 200 Bafequards
- -7906180624 Amend 1. extending expiration date to 801001 & deleting Condition i from license for RMI Co to export source matl to Canada License now referred to as XU-8342 OPLINGER.O G Assistant Director for Export/Import & International Safeguards. 78/07/10 ip
- ---7906180638 Requests extension of export license expiration date to 805001 Also requests increase of matl authorized for export to 135.059 kg depleted U. SCHAEFFER.M R. RMI Go , RMI Titanium 78/07/07 2pp
- --7906180631 Executive Branch position re RMI Co application for amend to export license, increasing quantity of depleted U authorized for export to Canada Amend should be issued ROSENZOL V State. Dept of 79703/14 ip
- --7906180652 Amend 2 to RMI Ca License XU-8342, increasing quantity of mat1 authorized for export to 135,037 kg depleted U b deleting Condition 9 GPLINDER, 0 0 Assistant Director for Export/Import & International Sefectures 79/05/22 ip.
- 7906180739 SECY-79-28C Informs Commissioners of receipt of 790216 application from Edlaw Intl Co for license to export 13,125 kg U to Italy SHEA, J. R Office of International Programs. 79/04/19, 1p
- -- 7906180747 Application by Edlaw Intl Co for license to export 13,125 kg U to Italy HARMON,D H Edlow International Co 79/02/16 1p.
- 7906180754 SECY-79-289 Toleran Sciences of Ediow Intl Co 790416 application for license to export 48,000 kg U-308 to Brazil SHEA, J R - Office of International Programs, 79/04/23 ip
- --7906180761 Application by Ediow Intl Co for license to export 48,000 kg U-308 to Brazil HARMON.D W. Ediow International Co 79/04/16 1g
- --7906180766 Advises that application to export 50 short tons of U-308 is to fulfill requirements of Brazilian Resources Legislation Lists UB suppliers for application HARMON.D.W Ediow International Co 79/04/17, ip
- 7906180759 Executive Branch position re Dresser Atlas Export Sales application for license to export 4 curies Cs-137 to China License should be granted MOSEMZGrL V. State, Degt of 79/05/17 ip
- 7906180771 BECY-79-249A Toforms commissioners of GE 790413 license application amend requesting rescheduling of first shipment date to 790831 SHEA, J. R. Office of International Programs. 79/04/23 tp.
- --- 7906190776 Requests application amend to reschedule first shipment date to 790831. Also asks that DOE ltr requesting assurances be expedited to Enbassy of Japan to meet new schedule requirements.

  HILBON, B.D. General Electric Co., Nuclear Energy Products Div. 1p. 79/04/13.

- 7906180797 Forwards application for amend to export license.increasing amount of SNM for export to Italy HOHRY, H R General Atomic Co (subs of Gulf Oil Corp.) 79/05/08
- --7906180800 Application for amend to OA Co export license, inpreasing amount of SNM to 1 B4 g U.enriched to 93% U-235, for export to Italy HORRY, H B General Atomic Co (subs of Gulf Dil Corp. ) 79/05/08 3pp
- 7906180801 Notifies that license for Kaweki Berylco to export
  Zircaloy-2 seamless tubing to Bouth Korea was issued w/o
  15-day waiting period, due to urgent requirements
  OPLINGER, 9 G Assistant Director for Export/Import & International
  Bafeguards 79/05/14 lp
- 7906180802 SECY-79-282 Forwards Executive Dranch position re Mitsubishi Intl Corg application for license to export 342 kg U-235 to Japan SHEA, J R Office of International Programs 79/04/19 ip
- --7906180804 Executive Branch position re Mitsubishi Intl Corp application for license to export 342 kg U-235, enriched to 285. to Japan License should be granted NDSENZO,L V Btate, Dept of 79/04/16 3pp
- 7906190063 Forwards application for export license RABY, D. J. Sandvik Special Metals Corp. 79/05/11 1p
- ---7906190072 Application by Sandvik Special Metals Corp for license to export 2,100 pieces Zircaloy-2 seamless fuel cladding to Sweden RADY, D J Sandvik Special Metals Corp 79/05/11 1p
- 7906190079 License for Tube Div of Kawecki Beryleo Industries. Inc to export 2 pieces Zircalov-2 seemless tubing to South Korea OPLINGER, G O Assist Assistant Director for Export/Import & International
- 7906190082 License for Isotops Products Lab to export 10 mCi Cm-244 to Canada QPLINGER.Q.Q Assistant Director for Export/Import & International Bafegwards 79/05/15 2pp
- 7906190083 License for Sigma Chemical Co to export 5 kg heavy water to Canada GPLINDER, O D Assistant Director for Export/Import & International Safeguards 79/05/15 2pp.
- 7906190089 Application by Reuter-Stokes.Inc for license to export O 037 g U.enriched to max of 18% U-235, to West Germany \* Reuter-Stokes. Inc 79/05/09 2pp
- 7906190097 Forwards Harubeni America Corp application for license to export 620 g U hexafiuoride to Japan OKUDA.H Harubeni America Corp (subs of Marubeni Corp ) MAI-HO-5858 79705707 Ip
- --7906170100 Application by Marubeni America Corp for license to esport 620 g U hexafloride, enriched to max of 12 18% U-235, to Uapan MAMIYA, B Marubeni America Corp (subs of Marubeni Corp.) 79/05/07 ip
- 7905190107 Forwards application for export license CLARK, E L Rhadia, Inc /Rhade-Paulene, Inc 79/05/08 1p.
- --7906190110 Application by Rhose Poulene, Inc. for license to export 107,502 50 kg thorium, enriched to max of 04%, \$ 10,886 53 kg U.enriched to max of 004% HARRIS.D 0 Rhodia.Inc./Rhode-Paulene, Inc. 79/05/07 ip
- 7906190112 Application by Bigma Chemical Co for license to export compounds containing dauterium to India BTERN, NC Bigma Chemical Co. (subs. of Bigma Aldrich Corp.) 79/03/08 ip
- 7906190184 License for TX Nuclear Div to export 1 415 mg Pu-238 to The Netherlands. Natherlands, OPLINOER.O G Assistant Director for Export/Import & International Bafeguards. 79/03/16 2pp
- 7906190186 License for Mitsubishi Intl Corp to export 250 mCi Ca-252 to Japan OPLINGER, G G Assistant Director for Export/Import & International 79/05/17

- 7906190188 Amend 1 to Cerac, Inc license, increasing quantity of matl for export to 36 49 kg thorium & extending expiration date to 800101

  OPLINOER, O. G Assistant Director for Export/Import & International Safeguards 79/05/15 ip
- 7908200002 SECY-79-200A
  Informs Commissioners of receipt of 790409 amend to application by German Dominquez to export U hexafluoride to Spain
  SHEALJ.R Office of International Programs 79/04/24 1p
- 7905200293 Discusses QA Co application for license to export fission chamber to Italy Quantity of SNN indicated in 790326 ltr has increased to i 84 g U containing 1 72 g U-235
  ODPFEL.H European Communities, Commission of 79/05/11 ip
- /906210082 Forwards application for export license for minor nuclear seatl. Ltr of assurance required DPLINGER, G. O Assistant Director for Export/Import & International Safeguards 79/05/24 ip
- 7905210094 Requests Executive Branch position re Sandvik Special Metals application for license to export Zircaloy-2 seamless tubing to Sweden.
  OPLINGER.G.O Assistant Director for Export/Import & International Safeguards 79/04/23 ip.
- 7906210094 Requests Executive Branch position re Bandvik Special Metals application for license to export Zircalog-2 seamless tubing to Swafen.

  OPLIMEBRO G Assistant Director for Export/Import & International Safeguards 79/04/23 ip
- 7905210239 Forwards request for addendum to application for license to export BMR Zircaloy-4 fuel channels to West Germany BRISTOL-D C Carpenter Technology Corp 79/05/08 1p
- --7706210263 Addendum to license application to export BHR Zircaloy-4 fuel channels to West Germany changing proposed completion of final shipment to Mar 1982 & existing expiration date to 820701 a Carpenter Technology Corp 79/05/08 2pp
- 7906210293 Requests amend to OA Co export license, extending expiration date to 810701
  HILSON, B D. General Electric Co Nuclear Energy Products Div BDW-79121, 79/05/07 ip
- 7905210313 Requests amend to QA Co export license, extending expiration date to 810791

  HELSON, B D General Electric Co., Nuclear Energy Products Div 79/05/07 1p
- 7906210320 Requests amend to OA Co export license extending expiration date to 810701.

  HILSON, B D. General Electric Co., Nuclear Energy Products Div 79/03/07 1p
- 7906210323 Requests amend to QA Co export license, extending expiration date to 810701.

  HILSON, B. D. General Electric Co., Nuclear Energy Products Div BDH-77119 79/03/07. ip.
- 79062:10411 Application by GE for license to export two offgas filter vessels & associated valves to Italy, WILBON B. B. General Electric Co 79/05/07, ipp
- 7906210414 Application by Reuter-Stokes, Inc for license to export U-235, deposited as U exide on internal surface of radiation detector, to Hest Oermany & Reuter-Stokes, Inc. 79/05/09 2pp.
- 7706220172 Application by Sigma Chemical Co for licensa to export compounds containing deuterium to The Netherlands.
  BTERN.H.C. Bigma Chemical Co (subs. of Sigma Aldrich Corp )
  77/03/08, ip.
- 7906220651 Ack receipt of 790415 itr re Westinghouse proposed export of power reactor & components to Philippines Executive Branch views will be considered at requested hearings. HENDRIE, J. M. Commission 79/05/02 19.
- 7906230086 SECY-79-280A
  Forwards Executive Branch position re Ediow Intl Co
  application for license to export 593 kg U-235 to Italy.
  SHEA-J.R Office of International Programs, 79705/02 1p.

- --7906230087 Executive Branch positions re Edlaw Intl Co application for license to export 393 kg enriched U-235 to Italy License should be granted Forwards itr of assurance from Delegation of Commission of European Communities NDBENZO,L V State,Dept of, Bursau of Oceans & Internati Environ & Scientific Affairs 79/04/24 3pp
- 7906230091 BECY-79-077A
  Forwards Executive Branch position re QE application for license to export 331 kg enriched U-235 to Japan 8HEA, J. R Office of International Programs 79/05/11 1p
- ---7906230094 Executive Branch position re GE application for license to export 331 kg enriched U-233 to Japan License should be issued Forwards 790427 ltr of assurance NOSENZO.L V State.Dept of 79/05/11 3pp
- 7906230105 Confirms that SNM will be used in Fukushima I Unit 4 in July 1980 Matl will be exported Bapt 1979 & Dec 1979 KUBO, H Marubeni America Corp. (subs of Marubeni Corp.) MAI-HK-5862 79/05/ii ip
- 7906230105 Confirms that ENM will be used in Fukushima I Unit 4 in July 1980 Hatl will be exported Bept 1979 & Dec 1979 KUBO. H Harubeni America Corp. (subs of Marubeni Corp.) HAE-HK-5862 79/05/11 ip
- 7906250042 Amend 1 to license to export math to West Germany, extending expiration date to 810701 GPLINGER.G O Assistant Director for Export/Import & International Safeguards 79/05/18 ip
- 7906250045 Amend 2 to GE license to export matl to India.extending expiration date to 810701 OPLINGER, G O. Assistant Director for Export/Import & International Bafeguards 79/05/18 ip
- 790625004B License for Aldrich Chemical Co.Inc to export 100 g : deuterium.contained in 533 g compounds, to Turkey OPLINGER.O O Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7906250050 License for Sigma Chemical Co to export 2 kg heavy water to Argentina.
  OPLINGER, 0 © Assistant Director for Export/Import & International Safaguards 79/05/18 2pp
- 7906250052 Amend 1 to QA Co license increasing export to 1.72 g U-235, contained in 1 84 g U enriched to 93% u/o max in one fission chamber to Italy OPLINOER Q Q Assistant Director for Export/Import & International Bafeguards 79/05/18 1p
- 7906230035 License for Aldrich Chemical Co, to expert 19 g deuterium, toms.contained in 100 g compounds.to Israel OPLINGER, O Assistant Director for Export/Import & International Bafeguards 79703/18. 2pp
- 7906230060 Licensa for Wolverins Div to export 8430 lb Zircaloy-4 guide thimble tubes & 500 lb Zircaloy-4 instrumentation tubes to France.

  OPLINGER, 0 Assistant Director for Export/Import & International Safeguerus 79/05/18 ip
- 7906250061 Reviews proposed export of reactor components to Philippines
  OPLINGER, 0 O Assistant Director for Export/Import & International Bafeguards, 79/05/02 2pp
- --7906250062 Responds to 780809 memo re review of export of reactor components to Philippines
  BUNCH:D,F Program Support Branch 78/08/18. 1p
- --7906250065 Ack cooperation in attempt to wave equipment delay on whipment to Philippines.
  RODI.J.P Westinghouse Electric Corp. 78/08/10, 3pp.
- --7906250067 Requests that review of Philippines export license application be restricted to components covered by 100FR110.32 RODL.J.P. Westinghouse Electric Corp. TF0/NRC-2986 79/04/27
- 7906250064 Amend i to Technical Operations, Inc license, increasing export amount to 5,000 kg depleted U in form of solid metal, 10,000 Ci Co-60 & 10,000 Ci Ir-192 to Bulgaria: Hungary, Cichoslovakia: East Germany, China & Boviet Union. OPLINGER, 0 0. Assistant Director for Export/Import & International Safeguards, 79/05/18 ip

- 790625006B Amena 1 to CE license, extending expiration date to 810701 & deleting Condition 1.for Amtl exported to Austria DPLINGER. 0 Assistant Director for Export/Import & International Bareguards 79/05/18 1p
- 7906250073 License for Bigma Chemical Co to export 10 tg heavy water to Israel OPLINGER.O Q Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7906230076 License for Aldrich Chemical Co to export 115 g deuterium. contained in compounds to India OPLINGER, O O Assistant Director for Export/Import & International Safeguards 79/05/18 2pp
- 7906250077 Recommends approval of draft response to Assistant Secretary of State Pictoring re export of nuclear components to Philippines NRC has taken no action to date SHEALUR Office of International Programs 79/04/03 4pp
- 7906250080 Amend 1 to QE license.extending expiration data to 810701 for matl exported to Sweden OPLINGER.O O Assistant Director for Export/Import & International Bafeguards 79/05/18 ip
- 7906230084 License for Aldrich Chemical Co to export 14 g deuterium, containsd in compounds to Venezuela
  OPLINGER O O Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7906250086 License for Sigms Chemical Co to export 10 kg heavy water to Soviet Union OPLINGER, C Q Assistant Director for Export/Import & International Safeguards 79/05/18 2pp
- 7906230087 License for TN Nuclear Specialties, Inc to export 1,000 kg thorium, in form of thorium oxide gowden, to Canada OPLINGER, 0 0 Assistant Director for Export/Import & International Safeguards 79/05/18 1p
- 7906230093 License for Aldrich Chemical Co to export 152 g deuterium. contained in 800 g compounds to Venezuela OPLINGER: 0 Q Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7706250096 License for Dresser Atlas Export Bales to export 4 Ci Cs-137 contained in two stainless steel capsules to China OPLINGER, 0 G Assistant Director for Export/Import & International Safeguards 77/05/18 2p
- 7906280098 License for Aldrich Chemical Co to export 160 g deuterium, contained in compounds to New Zealand
  OPLINGER,G O Assistant Director for Export/Import & International Safeguards 79705/18 2pp
- 7906250102 License for RCA Corp to export 60 aCi Po-210, contained in three Model 906 ionizing air nezries, to Poland OPLINOER, O O Assistant Director for Export/Import & International Safaguards 797/05/18 2pp
- 7906250104 License for Signa Chemical Co to export & to heavy water to Mexico OPLINOER:0 0 Assistant Director for Export/Import & International Safeguards 79/05/19 7pp
- 7906230117 License for Hewlett-Pactard Co to export 0.3 g thorium dioxide, to be deposited on filiments of cathode ray tubes, to Cambodia, Cuba, North Korea, Zimbahwe-Rhodesia, Uganda & Vietnam OPLINGER, 0 Q Assistant Director for Export/Import & International Safeguards 79/05/18 2pp

- 7906230134 License for Air Products & Chemicals, Inc to export 27 2 g deuterium, contained in steel cylinders, to United Kingdom OPLINGER, 0 O Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7906250137 License for Westinghouse to export two compensated ignised chambers. Type WL 23944. to France.
  OPLINGER. 0 Assistant Director for Export/Import & International Safeguards 79/05/18 1p
- 7906230144 License for Varian Export Corp to export 880 mCi Ni-63 contained in electron capture detector to Cambodia,Cuba, North Korea, Zimbabwe-Rhodesia,Uganda & Vietnam CPLINGER,0 Q Assistant Director for Export/Import & International Bafeguards 79/05/18 2pp
- 7906230188 Executive Branch position of Westinghouse application for license to export reactor parts & components to Philippines License should be granted PICKERING, Y R State, Dept of 79/02/15 2pp
- 7908250239 Responds to 780803 license application to expert components for nuclear power plant to Philippines Components not subj to NRC licensing authority GPLINORRO C. Assistant Director for Export/Import & International Safeguards 78/08/23 ip
- --7906230243 Responds to 780809 memo re review of Westinghouse application to export components to Philippines Components in Exhibit A may be exported under general license Components in Exhibit B require special license BUNCH, D F Program Support Branch 78/08/18 ip.
- --790625024B Concurs W/MR Peterson 790105 draft staff paper re propose Westinghouse license to export components to nuclear power plant in Philippines Specifies two deletions to memo to file attachment B DIRCKS, W Office of Nuclear Material Safety & Bafeguards 79/01/16 ip
- --7906250249 Requests raview of Westinghouse list of components to determine which are subj to special license for export to Philippines Action on license will come after final action on related Export License XR-120 OPLINGER, G G Assistant Director for Export/Import & International Safeguards 78/08/09 ip
- --7906250251 Forwards equipment export license application Expedited approval is necessary to assure continued const of plant in Philippines HHITELUR, CINGLLIR J Hestinghouse Electric Corp TFO/NRC-1834 78/08/03 App
- --7906250251 Forwards equipment export license application Expedited approval is necessary to assure continued const of plant in Philippines WHITE, J.R., CINELLI, R.J. Hestinghouse Electric Corp. TFO/NRC-1834 78/08/03 4pp
- --7906280254 Application by Hestinghouse for license to export various components to Philippines List of Philippines project shipments for 1978 enc! RODI.J R Hestinghouse Electric Corp 78/08/03 ip
- --7706230234 Application by Hestinghouse for license to export various components to Philippines List of Philippines project shipments for 1978 encl RODI, J R Westinghouse Electric Corp 78/08/03 ip
- 7906250307 Executive Branch position re Ediow Intl Co application for license to export 129,243 kg U.in form of U-308, to France & United Kingdown License should be granted Ltr of assurance encl
  NOSENZO, L V State, Dept. of 79/05/25 3pp
- 7906250343 License for Sigma Chemical Co to export 4 kg heavy water t Australia License authorizes export only not use, receipt or possession OPLINOER, O G Assistant Director for Export/Import & International Safeguards 79/05/18 Zoo
- 7906260012 Executive Branch position re Transnuclear: Inc application for license to export 740 012 kg U-235 plus 0 34 kg U-235 as sampling matl to Buitzerland via West Germany, License should be granted, Ltr of assurance encl NOSENZO, L. V State, Dept of 79/05/17, 9pp
- 7906260100 Executive Branch position re Unipak Intl application for license to export 900 kg depleted U to South Korea License should be granted William of Oceans & Internati Environ, Beientific Affairs 79/05/25, 2pp.

- 7908280105 Executive Branch position re Ediom Intl Co application for license to export 1.000 metric tons natural U.in form of U-308, to United Kingdom License should be granted Ltr of assurance enci
  MOSENZO.L V State.Dept of, Bureau of Oceans & Internatl Environ & Scientific Affairs 79/05/25 3pp
- 7408280339 Application by Rocky Mountain Nuclear Co for license to export std & remote operated pipe connector to United Xingdom POE.J Rocky Mountain Energy Co 77/01/16 ip
- 7906260362 Ltr of assurance re Westinghouse license to export U dioxide sintered pellets, encapsulated in sealed fuel rods & assembled into fuel assemblies, & four pieces of incore detectors to South Korea

  BHIYOHL, P Korea, Republic of (South Korea) 79/04/17 1p
- 7906270018 Requests amend to Histsubishi Intl Corp export license consignee. Nuclear Fuel Industries. Ltd.
  MATAMABE. N Hitsubishi International Corp (subs of Mitsubishi Corp) HSA-6701-00 79705/15 ip
- 7406270021 Forwards application for license to export minor nuclear mati Ltr of assurance required W/o encl OPLINGER.9 G Assistant Director for Export/Import & International Bafeguards 79/05/24 ip
- 7906270083 Application by Westinghouse for license to export compensated ionization chambers to France SCHNAUTZ.C E , POCHAL,W F Westinghouse Electric Corp 79/05/23 to
- 7906270276 Requests NRC action on component export license filed on behalf of Natl Power Corp of Philippines Oovt Const delays have become critical due to inability to secure authority to export HVLBERT.O C Hestinghouse Electric Corp 79/05/22 2pp
- 7706290385 License for QA Co to export 2.040 kg U-235 contained in 10.200 kg U as fabricated fuel elements to Theiland DPLINGER.0 Q Assistant Director for Export/Import & International Safeguards 79/05/29 2pp
- 7905290496 SECY-79-328
  Informs Commissioners of receipt of GE application for license to export Tarapur reactor replacement parts & components to India BHEAJ R. Office of International Programs 79/03/10 1p
- --7906270511 Application by OE for license to export Tarapur reactor replacement parts & components to India
   General Electric Co 79/04/25 2pp
- 7906290526 License for Sigma Chemical Co to export 2 kg heavy water to The Netherlands
  OPLINGER, 9 G. Assistant Director for Export/Import & International Bafeguards 79/05/30 2pp
- 7906290531 SECY-79-329
  Informs Commissioners of receipt of Mitsul & Co application for license to export U.enriched to 3 95% in 102 kg U-235, to Japan
  SHEA, J.R. Office of International Programs 79/05/11 1p.
- --7706290553 Forwards Mitsui & Co application for license to export U. enricked to 3 95% in 102kg U-235, to Japan MONDEN.T. Mitsui & Co . Ltd 79/05/01, ip

- 7906290571 Informs Commissioners of receipt of Ediow Intl Co license application to export 1,000 metric tons of U,contained in 1,180 metric tens U-308, to United Kingdom SHEA.J R Office of International Programs 79/05/11 ip
- --7906290585 Forwards license application to export 1.000 metric tons U. contained in 1.180 metric tons of U-308.to United Kingdom License is extension of expired License SUB-7952 EDLOWIJ Ediow International Co 79705/07 ip
- 7906270604 SECY-79-268A
  Recommends approval of amend to Aerojet Ordnance &
  Mfg Co license to export 45,043 kg U.contained in 45,360 kg
  dapleted U.to Canada
  SHEA.J R Office of International Programs 79/05/14 4pp
- --7906270612 License for Asrajet Ordnance & Mfg Co to export 45.043 kg U.contained in 45.360 kg depleted U.to Canada OPLINGER.0 O Assistant Director for Export/Import & International Bafeguards 78/09/16 2pp
- --7906290779 Amend i to license for Aerojet Ordnance & Mfg Co, increasing amount of matl authorized for export to 100,000 kg depleted U contained in 100,704 kg depleted U alloy OPLINGER.0 O Assistant Director for Export/Import & International Bafeguards 79/05/14 ip
- 7906290643 Executive Branch position re Radium Chemical Co.Inc application for license to export 150.000 copper tritium to Buitterland NOSENZO.L V State,Dept of 79/05/23 2pp
- 79062790714 BECY-79-014A
  Informs Commissioners of Executive Branch response to pending license application for Nissho~Iwai American Corp to export 5 44B tg U-235 enriched to 45 4% to Japan Forwards applicant 790420 ltr requesting amend to application BHEA.J R Office of International Programs 79/05/11 ip
- --7906290718 Executive Branch position re Niesho-Iwai American Corp application for license to export 5 448 kg U-235 contained in 12 kg U-235 enriched to 45 4% in form of U metal, to Japan. H/supporting documentation NOSENZO.L V Defense, Dept of 79/05/01 17pp
- 7906290749 Requests license for Westinghouse to export reactor pressure tubes. & any other component specially designed or prepared for use in nuclear reactor, to Canada HERSCH.M M Westinghouse Electric Corp 79/05/18 2pp
- 7906290753 Executive Branch position re QA Co application for license to export 2.040 g U-235, fabricated in 18 TRIGA fuel elements to Thailand License should be granted NOSCHYOLL, V State, Dept of 79/05/23 2p
- 7906290737 Executive Branch position re Mitsul & Co (USA) application for license to export 3.511 kg U-235.contained in 197.382 kg U enriched to 2.55% to Japan License should be granted Ltr of assurance encl.
  NOSENIO, L V State, Dept of 79/05/23 2pp
- 7906290769 Corrects number of Aramco Svc Co export license Correct number should be XU-0463 HEMBY, E O Office of International Programs 79/05/30 1p

# PERSONAL AUTHOR INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REFORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
ABSOTTS, J.	7906140104	10CFR		ANDOGNINI, Q C	7906250286	50-293 0	1
ABRAHAM, K	7906260240	50-320 P					
ABRAMS, C. J	7906200251	71-70 C		ANDREHS, R D	7906020108	40-8452 B	
ABRAMB, C J	7906200256	71-70 C		ANDREWS, R D	7906180684	40-8452 C	
ABBTON-D G	7906220302	M 44E-06		ANDREWS, R D	7906250477	40-8452 0	
				ANDREWS, M	7906180267	50-275 G	
ACKERMANN, N. J.	7906060228	50-320 P		ANDREWS R L	7904040290	50-265	
ADAMS, K	7906040148	71-233 0		44400040 # 4		TO	
ADAMS, H E	7906130020 7906210069	50-255 R QA999		ANDREHS, R L	7906050334	50-205 8	
AGEE, J R AGRAHAL, A K	7906210067	RES	7906250043	ANDREWS, R L	7904050320 7904200392	50-285 8 50-320 P	
AUKAMALIA N	/700230043	uco	7740230043	ANDREWS, D. L. ANDRUS, C. D.	7903300586	NUREO	•
AHEARNE, J F	7906260488	50-320 P		ANDRUS, C D	7904210175	50-320 U	1
AHEARNE, J F	7906260523	50-346 P		HILDROSI G D	77002.0175	00-3E0 C	,
AHEARNE, J. F	770606024B	50-320 H		ANO, H P	7906160044	50-369 0	1
AHEARNE, J F	7906260474	50-320 P		ANG, N P	7906070121	50-281 6	
AHEARNE, J	7906140111	10CFR		ANOLIN. D R	7906180357	PR	
				ARBER, K. J.	7906220394	50-304 8	1
AHLFELD, J R	7906260384	50-320 G		ARCHITZEL, R	7906140113	50-293 6	)
ATNOER, K A	7906270164	50-295 B					
ALBERT, W. O.	7906220137	50-460 G		ARLOTTO, Q. A	7706130075	PR	
ALBERT, H Q.	7906260525	50-50B G		ARLOTTO, Q A.	7906230106	RECOD	
ALERICHT, H C	7906010072	71-28 C		ARLOTTO, Q A	0E10704077	FOIA	
		<del>-</del>		ARMSTRÖNG, H H	7906040161	PROJ	
ALDEN, H H	7906190331	50-277 R		ARMSTRONG, W H	7704200558	PROJ	
ALDERKAN, H	7906180592	50-320 0 50-382 8					
ALDERSON, C. E ALDERSON, C. E	7906290528	50-382 8 50-382 8		ARMSTRONG, H. H	7904240505	PROJ	
ALLAN, J. M	7906290535 7906210012	50-320 P		ARNOT, T D	7906140588	PR	-
ALLANI O, FI	1400510015	30-320 F		ARNOT, R H	7906200091	71-9080	
ALLEMANN, R T	7906270243	ACRS		ARNO, N	7906070258	50-592	
ALLEN, R	7906060262	50-320 H	1	ARNOLD.R C	7906260208	50-320 F	
ALLEN, J R	7906200390	50-320 P					
ALLHAN, N C	7906040271	50-272 8		ARNOLD, R C	7906270043	50~320 F	
ALTON, C O	7906190256	50-3		ARNOLD, R C	7906280154	50-320 F	•
	, ,			ARNOLD R C	7706260200	FOIA	
AMALFITANO, J M	7906020197	XPORTLIC		ARNOLD, R C	7906290025	50~320 F	NUREG/CR-0458
AHANO, H	7906210331	GA999		ARNOLD, E H	7906020148	NUREO	MUKEO/CK-0636
ANNERHANN, E. G	7906130183	PR		ADDENIAL TO A	7906260079	50-320 F	
AMMER, A. A	7906220373	50-237 8		ARBENAULT, F J. ARTHUR, J E	7906270195		3
ANDERBON.CR.	7906160056	PR			7906290288		3
		2		ABHENDEN, M. C ABHENDEN, M. C	7706270048		ā
ANDERSON: J M	7906220363	50-329 8		ASHENDEN, H C	7777777	44-510	า
ANDERSON, J M ANDERSON, T M,	7906220377	50-329 E TOPREP	•	£1011=110=(1111 -			
ANDERSON, T H	7906270197 7906210358	PR		ABHER, T R.			
ANDERSON: T. M	7906040157	TOPREP		ABHER, T R			
AUDENOCHI III	7700040407	t est their		ASHELL, D L			
ANDERSON, T M	7906220290	TOPREP		ABHELL, D L			
ANDERSON, T. M	7906220296	TOPREP		ASHELL, D. L			
ANDERSON T M.	7906070271	TOPREP					
ANDERSON, T M	7906140344	TOPREP		ATOR, D.			
ANDERSON, T M	7906210225	TOPREP	•	ATHELLI T L.			
AUBERGON * 4	7004000100	TOPREP		A H WITTELA			
ANDERSON, T. M ANDERSON, T. M	7906200198 7906210138	TOPREP		AUSTINAM A. AUSTINAM A.			
ANDERSON: T. M.	7906210245	TOPREP		MOLLEIN N.			
ANDERSON: T M	7906210258	TOPREP		AUSTIN/ H A			
ANDERSON, T. M	7906210246	TOPREP	WCAP-9529	AUSTIN H A.			
THIO ENGLISH THE	1100210210	1 mi met	mapii reer	AUSTIN, H			
AMDERSON P L.	7906010259	50-309 E	1	A MINITEUA			
ANDEREGNIP L	7906120416	50-307 8		AUSTIN, J. H.			
ANDERBON, R H	7906260476	50-202 0					
ANDERSON, D R	7906260613	REB	7906260613	A H-OLTUA			
ANDERSON, b, Q,	7906230036	GA777		AXELRAD, H			
V.				AXELROD, D			
ANDOGNINI, O C	7904080100	50-293 0		A AUNONYA			
ANDOGNINI, e C	7906070002	50-293		BACH, C. H			
ANDOGNINI, Q C	7906020200	50-293					
ANDOONINI.0 C	7906050435	50-293 (		BACKUS, R A.			
ANDOGNINI, Q. C	7906270106	50-293 6		BACKUS, R A			
***********	WMD ( # 5 5 5 5 -			BACON: J L			
ANDOGNINI, G C.	7906290775	50-293 0		BACON, J.L.			
ANDOGNINI, O C.	7906080258	50-293 (		BAER, T 8			
ANDOGNINI, G C.	7906120434	50-293 F	•	BAER, T S.			
ANDGGNINI, G, C	7906220305	50-293 F		DWELL 1 D'			

AUTHOR	ACCESSION NUMBER	SUBJECT	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
BAER,R L BAER,R L BAER,R L BAER,R L	7706120126 7706230084 7706230163 7706230063	50-395 A 50-382 A 50-445 A 50-437 A		BARNETT, E W BARNETT, E W BARNETT, E W BARNETT, E W	7906020209 7906190140 7906250426 7906280103	50-445 M 50-445 M 50-445 M	-
BAIR.G G BAKER.D A BAKER.S J BAKER.K R BAKER.K R	7906150307 7906230077 7906110038 7906290110 7906290573	50-344 R 50-305 0 WASTE MOT 50-346 0 50-346 0		Barnett, J. E Barney, W S Barney, W S Barnes, D Barnes, I	7906190433 7906210103 7906210104 7906020097 7906160010	70~1621 C 50-320 P 50-320 P NUREG GA999	NUREO/CR-0220
BAKER,K R BAKER,K R BAKER,K R BALDASSARI,J A	7906290141 7906290441 7906290484 7906140609 7906130075	50-346 0 50-346 0 50-346 0 50-315 0 50-320 H		Barnes, I Barnes, I Barnes, I Barnes, I Barnes, I	7906230068 7906290716 7906210344 7906290262 7906290707	GA979 GA999 GA999 GA979 GA999	
BALL.S J BALLARD,J L BALLARD.J L BALLARD.R L BALLARD.R L	7906050277 7906040099 7906040104 7906070358 7906190408	NUREO 71-315 C 71-315 C 50-599 A 50-466 D	NUREO/CR-0716	BARRE, C H BARRE, C H BARTH, C A BARTH, C A BARTH, C A	7906140006 7906140008 7903210453 7906040374 7906040376	71-318 C 71-318 C 50-580 O 50-470 O 50-580 O	
BALLARD.R L BALLARD.R.L BALLARD.R L BALLARD.R.L BALLARD.R.L	7906200295 7906020203 7906020228 7906200556 7906250177	50-395 A 50-502 C 50-395 A 50-456 A 50-452 A		BARTH, C A BARTH, C A BARTH, C A BARTH, C A BARTH, C A	7906050240 7906110009 7906070177 7906020113 7906180693	50-488 Q 50-488 Q 50-400 Q 50-488 Q 50-358 Q	
BALLARD,R L BALLARD,R L BALLARD,R L BALLARD,R L BALLARD,R L	7704050154 7704050158 7704210383 7704270214 7704080284	50-548 D 50-548 D 50-548 A 50-548 D 50-298 8		BARTH, C A BARTH, C A BARTH, C A BARTLETT-LAGORI BABILE, J A	7906080030 7906250229 7906190868 7906110090 7906020216	50-358 0 50-358 0 50-358 0 WASTE MOT RECOD	
BANCROFT,M H BANCROFT,M H BANCROFT,M BANFIELD,E L BANKS,H R	7706140525 7706210400 7906230150 7906020185 7906150197	PR PRH NUREO 71-150 C 50-325 8		BASKIR, E BASKIN, K P BASKIN, K P BASKIN, K P BASSETT, H S	7906020116 7906140622 7906040167 7906150386 7906210077	50-466 H PR 50-206 P 50-361 A 50-320 P	
Banksih R Banksih R Banksih R Banksih R Banksih R	7906040153 7906050259 7906050305 7906050328 7906080316	50-324 8 50-325 8 50-325 8 50-325 8 50-324 8		BATES.B J BATES.T H BATES.A BATES.A BATES.A	7906210076 7906180259 7906290269 7906180583 7906220165	GA999 50-275 G 50-336 B 50-269 G 50-320 G	
Banke, H R Banke, H R Banke, H R Banke, H R Banke, H R	7906070194 7906070251 7906070279 7906070283 7906080249	50-241 8 50-241 8 50-324 8 50-324 8 50-324 8		BATES: J W BAUM.E. A BAUMAN.R C BAUNACK: H H BAUSER: M A	7906190554 7906050323 7906070185 7906120251 7906070225	70-824 C 50-280 P 50-327 A 50-309 G 50-250 C	
BANKE, H R BANKE, H R BANKE, H R BANKE, H R BANKE, H R	7904120422 7904110146 7904110176 7904110189 7904110228	50-324 8 50-261 R 50-325 8 50-325 8 50-324 8		A.M.RJEUAG Q.L.JANYAB Q.L.JANYAB Q.L.JANYAB Q.L.JANYAB	7906200602 7906040232 7906140326 7906040014 7906140508	50-522 G 50-284 S 50-286 G 50-286 G	
Banks, H R Banks, H R Banks, H R Banks, H R Banks, H R	7906120382 7906130167 7906150177 7906150237 7906150245	50-324 B 50-325 8 50-324 B 50-325 B 50-325 B		PAYNE, JP BAYNE, JP P. JAYNE P. JAYNE JP JAYNE, JP	7906120374 7906200368 7906190264 7906260450 7906280110	50-320 G 50-266 R 50-266 B 50-320 G 50-286 S	
Banks, H.R Banks, H.R Banks, H.R Banks, H.R	7906140444 7906140312 7906140527 7906180501 7906180507	50-324 R 50-325 B 50-325 B 50-261 B 50-324 B		BEAN, R M BEANE, V E, BEARD, J T BEATTY, T E BECHHOEFER, C.	7906260613 7906270122 7906070001 7906110081 7906200231	REB 50-280 H 50-320 H WASTE HOT 50-498 Q	E1404240FT
Banks, H R Banks, H R Banks, H R Banks, H R	7906200366 7906220312 7906220316 7906220370 7906220406	50-325 8 50-325 8 50-325 8 50-324 8 50-324 8		RECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C BECHHOEFER, C	7906010257 7906040155 7906060217 7906060193 7906060211	50-358 Q 50-358 Q 50-358 T 50-358 T	
BANKB, H R. BANKS, H R BANKS, H, R, BANKS, H R BANKS, H R	7906220413 7906220284 7906220398 7906270174 7906280129	50-324 8 50-325 8 50-324 9 50-261 8 50-325 \$		BECKHOEFER, C BECKHOEFER, C BECKER, J M BECKMEYER, R R BECKMEYER, R R	7906270250 7906270185 7906180138 7906180762 7906180770	50-358 0 50-387 0 50-574 0 NUREO NUREO	NUREG/CR-0713 NUREG/CR-0714
H RANAB H RANAB H RANAB H RANAB H RANAB H RANAB	7906280084 7906280098 7906290356 7906290345 7906290366	50-325 8 50-325 8 50-324 6 50-325 8 50-325 8		BECKMAN, D A BEDNAR, L F BEELER, T BEEMAN, R P BEERMANN, T	7906070244 7906080252 7906230123 7906220099 7906260007	50-334 G 50-278 B 50-346 G 50-320 P 50-250 H	
BANTA/F L Barandwsky, p w Barber/r n. Barglay/J F, Bard/L.	7904070381 7904280012 7903020022 7906180459 7904040428	50-358 A 50-320 P ORO GAPPP 50-592 Q		BEILMAN, T.P BELANGER, J.L BELIBLE, O.A BELIBLE, O.A BELIBLE, O.A	7906110239 7906180045 7906180408 7906290135 7906290429	50-315 8 50-254 G 50-302 G 50-267 G 50-269 G	
BARDES, CR BARI, R. A BARKER, N. R BARNES, J. N BARNETT, EW	7906250294 7906260017 7906290289 7906010113 7906040417	50-287 J RES TOPREP FOIA 50-445 M	7906260017	BELL, J. A BELL, J. A BELL, N BELL, J. A	7906270480 7906010309 7906040165 7906040168 7906140102	50-269 G 50-482 H 50-344 G 50-344 G 71-285 C	
BARNETT, E, W	7904010260	50-498 M		BENDER, M. B	7906230028 7906150214	94779 50-320 T	

# PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
BENDER.H Benedict,r a Benedict,r a	7906150234 7906110448 7906120133	50-320 T 50-382 A 50-382 A		BONNER, J F BOOK, H E. BOOK, H E.	7906200238 7906010254 7906150355	50-275 Q 50-312 Q 50-141 Q	
BENEDICT, R A BENJAHIN, A S BENTON, R P BENTZ, R BEOCETTO, J A	7906250264 7906260510 7906020172 7906130209 7906230136	50-518 A 50-320 P CONTRACT PRM NUREG		800K.H E 800K.H E 800K.H E	7906150357 7906010250 7906290646 7906290656 7906010069	50-141 G 50-312 G 70-734 C 70-734 C 71-28 C	
BERGER, D. W. BERGER, M. G. BERGER, M. G. BERGER, M. G. BERGH, B. G.	7906130496 7906070311 7906020129 7906190054 7906250116	50-320 P 50-445 M 50-445 M 50-445 N 50-320 P	,	BORDENICK, B M BORDENICK, B M BORDENICK, B M BORDENICK, B M BORER, P J	7906020226 7903210311 7906020223 7906200388 7906130297	50-322 G 50-514 G 50-322 G 50-516 G 50-296 R	
BERIGK, D BERHAN, M BERHSTEIN, M BERRY, D L BERTELL, R	7906140655 7906280020 7906190091 7906260574 7906140012	RECOD NUREG 50-295 O NUREG PR	NUREO/CR-0422 V8 7906260574	BORES, R BORES, R DDROMANN, E A BOROMANN, E A BOROMANN, E A	7906260260 7906210001 7906140520 7906280259 7906260617	50-320 P 50-320 P 50-358 Q 50-358 Q 50-358 Q	
BEBAN, H J BEBECKER, K H BEBECKER, K H BETTENHAUSEN, L	7906210265 7905040336 7906070390 7906180232 7906200426	50-320 P 50-320 P 50-327 Q 50-335 Q 50-320 P		BORGMANN, E A BORGMANN, E A BORGMANN, E A BORYBIAK, M BOBSENMAIER, W S	7906120174 7906190405 7906190446 7906050243 7906010275	50-358 K 50-358 K 50-358 J 50-344 8 50-312 P	
BETTENHAUSEN, L BETTENHAUSEN, L BICKNIT, L BICKNIT, L BICKNIT, L	7906250478 7906260499 7906200623 7906290004 7906070016	50-311 G 50-311 G 50-320 P 50-320 P 50-320 P		BOSTWICK, W E BOUCHER, P BOUKNIGHT, J A BOUKNIGHT, J A BOUKNIGHT, J A	7906020114 7906280155 7906040417 7906040418 7906010260	RES 50-320 P 50-445 M 50-250 M 50-498 M	7906020114
BICKWIT, L BICKWIT, L BICKWIT, L BICKWIT, L	7906070012 7906070027 7906060184 7906070057 7906180116	50-320 T 50-320 T FDIA 50-320 P 8ECY	, SECY-79-303	BOWERS, M B BOWKNIGHT, J A BOWKNIGHT, J A BOWKNIGHT, J A	7906020209 7906250426 7906280105 7906070409 7906020221	50~445 M 50~445 M 50~445 M 50~373 A 40~8722 C	
BICKWIT, L. BIERLY, M BIMBER, R M BINTON, T BIRD, P E.	7906270012 7906260114 7906210040 7906210014 7906200008	RM 50-320 0 REQOD 50-320 T 50-320 H		BOWER:PK BOWERS:CE BOWERS:CE BOWERS:CE BOWERS:CE	7906010305 7906230161 7906140587 7906180642 7906230164	71-326 C 70-820 C 70-820 C 70-820 C 70-820 C	
BIRKEL, R. A BIRKEL, R. A BIRKEL, R. A BIRKEL, R. A BIRKEL, R. A	7906040070 7906180102 7906180131 7906250303 7906250322	50-599 A 50-389 A 50-389 A 50-599 A		BOWERS, E S BOWERS, E S BOWERS, E S BOWERS, E S BOWMAN, E L	7906040451 7906070399 7906070011 7906260067 7906140503	50-488 G 50-445 G 50-445 T 50-275 G 40-8194 C	
BISCHOFF,C A BISHOP,T.H BISSETT.P BISSETT.P BISSETT.P H	7906020030 7906150079 7906050205 7906140218 7906290399	50-592 0 50-397 0 70-364 C 70-135 C 50-320 P		BOYD.R S BOYD.R.S. BOYD.R S BOYD.R S BOYD.R S	7904120090 7904080008 7904070401 7904040013 7904010148	ORO 50~10 U 50~275 H 50~460 A 50~495 A	
BIXEL.D A. BIXEL.D A. BIXEL.D A BIXEL.D A BIXEL.D A	7906020047 7906020163 7906140246 7906230045 7906040189	50-155 Q 50-155 Q 50-155 Q 50-155 G 50-155 F		BOYD, R S BOYD, R S BOYD, R S BOYER, V S	7906010169 7906020118 7906140329 7906190123 7906050197	50-495 A 50-279 Q 50-275 H 50-275 H 50-352 Q	
BIXEL,D A BIXEL,D A BIXEL,D,A BIXEL,D,A	7906120160 7906260188 7906260194 7906260353 7906280163	50-155 S 50-155 P 50-155 P 50-155 P		BOYER,V B BOYER,V B BOYLE,R R BOYLE,R R BOZIAN,R C	7906020211 7906020206 7906230160 7906130230 7906250158	50~352 8 50~352 Q Waste Mot Waste Mot 50~358 Q	
Black, R. L Black, R. L Black, R. L Blahd, N. H Blake, J. N.	7903200326 7903200319 7906250224 7906070174 7906200463	50-341		BRADFORD, W H BRADFORD, P.A BRADFORD, P.A BRADFORD, P.A BRADFORD, P.A	7906150052 7906040403 7906060173 7906060176 7906060179	50-327 Q SECY 50-309 H 50-309 H	
BLAKE, J. J. BLAKE, J. J. BLERHAN, S. R. BLOMOUIST, R. N. BLOND, R. M.	7904070375 7904150039 7904180804 7904180757 7904280007	50-250 G 50-438 G NUREO NUREO 50-320 P	NUREO/CR-0796 NUREO/CR-0923	BRADFORD, P A	7906060252 7906060137 7906060163 7906060167 7906010160 7906140111	50-309 H 50-320 H 50-320 H 50-320 H 50-329 I	
BLUM. B BLUME, M BLUME, M. B. BLUME, M. B BODINE, J. C	7906020098 7906020165 7906040032 7906190147 7906250255	70-2623 C 50-445 M 50-445 M 50-445 M 50-244 B		BRADFORD, P BRADFORD, P BRADFORD, P BRADFORD, P. A BRADY, N. A	7906200305 7906180391 7906230156 7906050188	10CFR 10CFR 10CFR 10CFR 70-1717 C	
SCOTKE, P J BOETTOER, J, T BOODEN, O, BOODN, H B BOODN, M B	7906130031 7906200496 7906160047 7906030383 7906260072	50-255 R REGGD 40-1162 C 50-574 G 50-374 G		BRADY.R J BRADY.R. J BRAHMAVAR.8 M BRAILE:L W BRENNER.L	7906210135 7906130500 7906010063 7906280001 7906120019	50-320 P 50-320 P 70-2684 C RES 50-485 Q	7906280001
BOHANAN:R E BOHN:R J, BOHN:R J BOHN:R.J, BOHN:R.J,	7906290487 7906050306 7906110179 7906190439 7906260425	NUREG 50-367 R 50-367 R 50-367 R 50-367 R		BRENNER, E J BRETTHAUER, E. BRETTHAUER, E BRIGHT, R M BRIGHT, G O	7906290692 7906210028 7906280141 7906120278 7903140067	50-320 P 50-320 U 50-302 P 50-400 T	
BONNER, E J.	790629010B 7906030163	50-367 R 98779		BRIGHT, Q. Q. BRIGHT, Q. Q BRIGHT, Q. Q	7903140059 7903140116 7906060217	30-400 T 30-400 T 30-358 T	

AUTHOR	ACCESSION NUMBER	8UBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	REPORT HUMBER
BRIGHT, O O BRIGHT, O O	7906060193 , 7906060211	50-358 T 50-358 T		BRYANT, J C BRYANT, J C	7906220081 7906250355	50-395 G 50-438 G	
BRIDDY, H W BRISTOL, D C BRITTINOHAM, J C BROADUS, C R BROEHL, D J	7906230011 7906210259 7906020091 7906020115 7906110132	71-157 C XPORTLIC PROJ RES 50-344 P	E69-D0E-13244 7906020115	BRYANT, J C BUCHANAN, J R BUCHORN, P BUCHORN, P BUCK, J H	7906190120 7906290494 7906070223 7906230096 7906290031	50-491 Q NUREQ 50-499 Q 50-498 Q 50-338 T	NUREO/CR-0691
BROCHE, D J BROCHL, D J BROCHL, D J BROCHSON, F BROCKSBANK, R E	7904110136 7906260001 7906260456 7906260626 7906280238	50-344 P 50-344 K 50-344 P PR 50-320 P		BUCK,J H BUCKLEY,C F BUCKLEY,B C BUCKNER,M R	7906290038 7906290090 7906220423 7906080211 7906180762	50-338 T 50-338 T REGOD 50-275 A NUREO	NUREQ/CR-07[3
BROCKS, H B BROCKS, E H BROCKS, E H BROCKS, D J	7706110085 7706200490 7706050382 7906250370 7906050080	HASTE MQT 50-250 Q 50-338 Q 50-324 Q FOIA		BUGGER, R M BULFORD, C BUNCH, D F BUNCH, D F BUNCH, D F	7906290163 7906050041 7906250062 7906250243 7906290832	71-5742 C 50-387 G XPORTLIC XPORTLIC 50-574 A	
9 C.MUORB 9 C.MUORB B M.MUORB H C.MUORB H C.MUORB	7906020067 7906020063 7906110036 7906110050 7906270178	50-275 0 50-275 0 HASTE HOT HASTE HOT 50-346 8		BUNTING,R L BURCH,G L BURDETTE,T E BURKE,D J BURKHARDT,W	7906180707 7906220336 7906220101 7906190213 7906230176	50-295 P 50-346 M 50-395 G 50-280 G 70-364 C	NUREG/CR-0715
BROWN, D H BROWN, R A BROWN, S C BROWN, S C BROWN, S C	7906070272 7906180547 7906140487 7906250240 7906140421	50-346 8 50-346 8 50-339 9 50-339 8 50-339 8		BURNETTE.O W BURNETT.P T BURNETT.R F BURNE,W A BURR,R.P	7906230053 7906030121 7906230065 7906070080 7906230135	RE8 50-302 Q 70-25 C FOIA 50-309 F	7906250050
BROWN, S C BROWN, S C BROWN, S C BROWN, S C	7706140432 7706010268 7906050280 7906050336 7906120178	50-339 8 50-338 P 50-404 A 50-338 P 50-339 8		BURBTEIN, S. BURBTEIN, B. BURBTEIN, B. BURBTEIN, B. BURBTEIN, B.	7906050122 7906200548 7906020133 7906040027 7906060257	50-266 G PR 50-266 G 50-266 G 50-266 S	
BROWN, 8 C BROWN, 8 C. BROWN, 8 C BROWN, 8 C BROWN, 8 C	7906120262 7906150134 7906210233 7906250267 7906270222	50-337 8 50-338 F 50-337 8 50-339 8		BURSTEIN, 6 BURSTEIN, 8 BURSTEIN, 8 BURSTEIN, 8 BURSTEIN, 8	7906060260 7906060250 7906060251 7906080272 7906150216	50-266 8 50-266 8 50-266 8 50-502 A 50-502 C	
BROWN, S. C. BROWN, S. C. BROWN, R. A. BROWN, Q. D. BROWN, R. L.	7906250280 7906270216 7906200373 7906040162 7906220222	50-339 A 50-339 B 50-320 P 50-313 Q GA799		BURSTEIN, B BURSTEIN, S, BURSTEIN, S BURSTEIN, S BURSTEIN, S	7906120147 7906120193 7906190319 7906190315 7906290579	50-502 B 50-502 B 50-266 R 50-266 P 50-502 B	
BROWN, R L BROWN, K H BRUWER, R BRUWNER, E. J BRUWNER, E. J	7906290630 7906280004 7906260010 7906010043 7906120055	QA999 50-320 P 70-2000 C 50-245 Q 50-213 Q		BURSTEIN, 8 BURSTEIN, 8 BURSTEIN, 8, BURSTEIN, 8 SURT, L	7906260409 7906260411 7906260414 7906290257 7906110082	50-502 C 50-502 C 50-502 C 50-266 P WASTE MOT	
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E, J BRUNNER, E J	7906140151 7906070236 7906140096 7906120244 7906140201	50-29 G 50-334 G 50-293 G 50-309 G 50-387 G		BURT,L BURT,L BURT,L BURTT,J D BURWELL,S B	7906010222 7906020251 7906010265 7906260234 7906250319	50-471 Q 50-471 Q 50-471 Q REVIEW QRP 50-445 A	
BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E, J BRUNNER, E, J	7906130491 7906290823 7906050173 7906130478 7906250476	50-320 P 50-219 G 50-336 G 50-320 G		BURWELL, 8 8. BUSH, 8 H. BUTLER, M. C. BUTLER, M. C. BUTZEL, A. K.	7906280323 7906270003 7906110411 7906080007 7906010066	50-445 A ACRS 50-280 U 50-338 U 50-549 Q	
BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J BRUNNER, E. J	7906260057 7906260546 7906260334 7906260171 7906260491	50~20 G 50~245 Q 50~320 Q 50~271 Q 50~311 Q	•	GABA,E C. CAHILL,W J. CAHILL,W J CAHILL,W.J CAHILL,W.J	7906140408 7906040298 7906040284 7906200603 7906020081	50-346 R 50-247 8 50-247 8 PR 50-3 Q	
BRUNNER, E J. BRUNNER, E J BRUNNER, E J BRUNNER, E J BRUNNER, E J	7906260504 7906140143 7906120039 7906070231 7906120232	50-244 G 50-29 G 50-213 G 50-334 G 50-309 G		CAHILLIW J. CAHILLIW J. CAHILLIW J. CAHILLIW J. CAHILLIW J.	7906010215 7906070285 7906080148 7906270850 7906270204	50-247 Q 50-3 Q 50-3 Q 50-3 Q 50-3 Q	
BRUNNER, E.J. BRUNNER, E.J. BRYANT, J.C. BRYAN, J.K. BRYAN, J.K.	7906290613 7906290679 7906190168 7906010128 7906190228	50-217 G 50-220 G 50-395 G 50-483 G		GAHILL, M. J. GAHILL, M. J. CAHILL, M. J GAHILL, M. J GAHILL, M. J.	7906040183 7906070275 7906190462 7906110245 7906190387	50-247 F 50-247 P 50-3 R 50-247 F 50-3 F	
BRYANT, J. C.	7906210110 7906020128 7906160044 7906030117 7906010023	50-390 q 50-369 q 50-369 q 50-366 q 50-566 q		CAHILL, H. J. CAHILL, H. J. CAHILL, W. J. CAHILL, H. J. CAHN, A. L.	7906260004 7906260407 7906210128 7906220303 7906150104	50-3 R 50-3 P 50-3 J RECOD	
BRYANT, J. C. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C. BRYANT, J. C.	7906010034 7906030075 7906030140 7906010314 7906220093	50-327 0 50-390 0 50-416 0 50-338 0 50-390 0		CAIN, J. T, CALDWELL, B Q CALIFANO, J A. CALLIHAN, D. CALLIHAN, D	7906070131 7906290684 7906290020 7906140117 7906060193	30-315 P 50-329 0 FOIA 50-471 T 50~471 T	
BRYANT, J.C. BRYANT, J.C. BRYANT, J.C.	7906070121 7906200364 7906010350	50-281 q 50-387 q 50-349 q		CALLIHAN, D CALLIHAN, D. CALLIHAN, D.	7906180726 7906220109 7906180728	50-471 T 50-471 T 50-471 T	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY *	REPORT NUMBER		AUTHOR	ACCESSION NUMBER	SUBJECT	lΥ	REPORT NUMBER
CALLIHAN, D CALLIHAN, D	7906260548 7906220147	50-471 T 50-471 T			CARTHRIGHT, H R	7906050298 7906050303	50-338 50-338	8	
CALLOWAY, C C. CAMPBELL, D O CAMPBELL, J CAMPBELL, J CANTER, H L	7906180199 7906280238 7906140521 7906220401 7906270263	71-298 C 50-320 P 50-304 B 50-304 S 50-312 Q	•		CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R	7906070245 7906070247 7906110160 7906110162 7906110200	50-338 50-338 50-338 50-338 50-338	8 8 8 8	
CANTER, H L CANTER, H L CANTER, H L CANTRELL, F S CANTRELL, F S	7906200149 7906250472 7906250442 7906200318 7906260271	50-206 G 50-206 G 50-73 G 50-338 G 50-267 G			CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R CARTHRIGHT, H R	7706110202 7706110204 7706110211 7706180544 7906200389	50-338 50-338 50-338 50-338 50-338	5 5 5 5 8	
CANTRELL, F 8	7906180355 7906190213 7906230013 7906260614 7906250375	50-338 G 50-280 G 50-335 G 50-250 G 50-335 G			CARTWRIGHT, W R. CARTWRIGHT, W R CARTWRIGHT, W R CARY, C N CASE, E Q	7906290205 7906290215 7906290239 7906180422 7906010179	50-338 50-338 50-338 TOPREP FOIA	8 8	NUREG/CR-0719 8ECY-77-539
CANTRELL, F B CAPHTON, D L CAPHTON, D L CAPHTON, D L GAPHTON, D, L	7906200279 7906120066 7906140164 7906290704 7906050183	50-269 G 50-213 G 50-29 G 50-220 G 50-336 G			CABE.E G CABE.E G CABJENB.L CABSAN, V J	7906010125 7906130354 7904270234 7906060026 7906010279	FOIA FOIA 50-320 40-8481 50-280	P C P	4ECY-77-561
CAPHTON, D. L. CAPHTON, D. L. CAPRA, R. A. CARBON, M. W. CARBON, M. W. CARBON, M. W.	7906250478 7906260499 7906010241 7906250474 7906050070	50-311 Q 50-311 Q 50-576 A ACRS 50-320 Q			CASTALDO, V F CASTLEBURY, R L CATCHPOLE, Q J CATTON, I CATTON, I	7906040101 7906190235 7906020184 7906270245 7906290843	50-275 50-329 40-8493 ACRB ACRB	H	
H.M. MOBRAD H.M. MOBRAD H.M. MOBRAD W.M. MOBRAD W.M. MOBRAD	7906070136 7906200029 7906230036 7906120076 7906120037	50-320 D 50-320 D ACRB 50-320 T 50-320 U		8	CATTON: I CATTON: I CAVANAUGH, H CAVANAUGH, H CAVANAUGH, H	7906150402 7906270242 7906110145 7906120367 7906190245	50-142 ACR6 50-313 50-313 50-313	P P P	APL-TOP-1A
CARBON, M H CARBON, M H CARBON, M H CARBON, M H CARBON, M H	7906150224 7906150214 7906150234 7906200035 7906200050	50-320 T 50-320 T 50-320 T 50-320 O 50-320 O			CAVANAUGH, W CAVANAUGH, H CERBONE, R CERECEDA, H CERNE, A C	7906150306 7906180468 7906250043 7906220463 7906150195	50-313 50-313 REB REGOD 50-343	P P G	7906250043
CARDONE, T. CARELLI, M D CAREY, W H CARLSON, R T CARLSON, R T	7906210301 7906020080 7906140250 7906070197 7906010036	50-361 A PROJ 50-271 J 50-387 G 50-354 Q			CHAFFEE,R S CHAN,J CHANDLER,L J CHANDLER,L J CHANDLER,L J	7904190525 7906200371 7903210409 7903110360 7906210042	50-133 50-237 50-361 50-445 70-754	8 6 0 0	
CARLSON, R. T CARLSON, R. T CARLSON, R. T CARLSON, R. T CARLSON, R. T	7906030201 7906040182 7906040081 7906040089 7906130190	50-352			CHANDLER, L J CHAPHAN, L D CHAPHAN, L D CHAPHAN, L D CHAPHAN, L D	7906180679 7906260205 7906180689 7906180774 7906260605	50-341 50-445 NUREG NUREG NUREG	0	NUREO/CR-0674 NUREO/CR-0738 NUREO/CR-0731
CARLSON, R T CARLSON, R T CARLSON, R. T CARLSON, R T CARLSON, R T	7906140632 7906140621 7906140574 7906040401 7906260155	50-311 0 50-387 0 50-443 0 50-363 0 50-334 0			CHECK, P S CHEN, P, Y CHERN, H, S, CHERNY, F C CHECKO, R C.	7904170494 7906110056 7906050180 7906200037	TOPREP 50-311 RES 50-320	A P	7906050160
CARLBON, R. T CARLBON, R. T CARLBON, R. T. CARLBON, R. T. CARLBON, R. T.	7906260319 7906050193 7906010130 7906040169 7906020208	50-387			CHILDS W V. CHILDS W V. CHILDS W V.				
CARLEON, R. Y. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T. CARLEON, R. T.	7906130480 7906130179 7906040397 7906070179 7906210034	50-387 8 50-343 0 50-412 8 50-387 0 50-387 8							
Carlson: J Carothers: J Carr Carr Carr Carr	7906290263 7906180333 7906120010 7906120012 7906120021	50-312 G 50-275 Q 50-320 U 50-320 U 50-320 U							
CARRIA V CARREAU.G CARRICK, J CARRIER, H C. CARRIER, H C	7906180712 7906060048 7906290444 7906010193 7906150258	50-344							
CARRIER, W. C CARROLL, J. T. CARROLL, J. T CARROLL, J. T. CARROLL, J. T	7904200432 7906040357 7906060298 7906140352 7906250273	50-320 Q 50-318 B 50-318 B 50-317 B 50-319 B							
CÁRROLL, J T CARROLL, J.T. CARSON, R.T. CARSTENS, A.S. CARTER, R.S.	7906260442 7906200391 7906040078 7906180691 7906200528	50-318 8 50-219 8 50-272 9 50-361 0 REGOD							
Carter, T. Carturight, M. R. Carturight, M. R	7905070032 7906050260 7906030295	50-320 P 50-336 B 50-336 B							

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	AEPORT NUMBER	AUTHOR	ACCESSION NUMBER #	SUBJECT CATEGORY	REPORT NUMBER
CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, B J	7704040369 7904260396 7906120093 7904260386 7904260389 7906260366	XPORTLIC 10CFR ORO 10CFR 10CFR 10CFR		CHRISSOTINGS, N CHRISTOFFER, O M CHRISTOFFER, O CHURCHILL, B W CHURCHILL, B W	7906250026 7906140591 7906260209 7906010311 7906130296	50-254 G 50-2 G 50-87 G 50-502 G 50-346 Q	
CHILK, S J CHILK, S J CHILK, S J CHILK, S J	7906260371 7906260381 7906260393 7906260350 7906260405	10CFR 10CFR 10CFR 10CFR 10CFR		CIMA.T CINELLI.R J CLARK.K CLARK.E L CLARK.R H	7906190091 7906250251 7906110107 7906190107 7906020129	50-295 G XPORTLIC WASTE MOT XPORTLIC 50-445 M	
CHILK,S J CHILK,S J CHILK,S J CHILK,S J	7906040444 7906070233 7906220179 7906260343 7906260357	50-466 0 50-400 0 50-320 8 10CFR 10CFR		CLARK, R H CLARK, R H CLARK, R A CLARK, D L CLARK, A T	7906190054 7906020167 7906200608 7906290487 7906230179	50-445 M 50-445 M RES NUREG 50-201 P	7904200408 NUREQ/CR-0753
CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J	7906260303 7906260307 7906260316 7906260325 7906260379	10CFR , 50-307 P 10CFR 50-400 P 10CFR		CLARK, R A CLAYTON, F L CLAYTON, F L CLAYTON, F L CLAYTON, F L	7906200323 7906290483 7906220247 7906290761 7906290723	50-387 A 50-320 G 50-348 G 50-348 G	
CHILK.S.J CHILK.S.J CHILK.S J CHILK.S J CHILK.S J	7906040224 7906050195 7906080019 7906080081 7906280313	50-269 0 50-312 0 50-320 P PR 100FR		CLAYTON: F L	7906050285 7906040279 7906150326 7906190239 7906190258	50-348 8 50-348 8 50-348 P 50-348 8 50-348 R	
CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J	7906260376 7906070292 7906070299 7906260292 7906260283	100FR 100FR 100FR 50-269 P 100FR		CLAYTON, F L CLAYTON, F L CLAYTON, F L GLAYTON, F L CLAYTON, F L	7906190464 7906250289 7906250250 7906260333 7906220347	50-348 P 50-348 S 50-348 S 50-348 S 50-348 P	
CHILK, S J CHILK, S. J CHILK, S. J CHILK, S. J CHILK, S. J	7906260279 7906260335 7906220096 7906260223 7906260274	50-219 P 10CFR 50-320 D 10CFR 10CFR		CLAYTON, E D CLEMONS, B E, CLEMONS, P E CLEBIKIEHICZ, 8 CLEVELAND, J, C	7906180804 7906130055 7906180653 7906150338 7906050277	NUREO 70-135 C 70-820 C 50-10 R NUREO	NUREG/CR-0796
CHILK, 8. J CHILK, S J CHILK, S J CHILK, S J CHILK, B J	7906260438 7906180799 7906260246 7906260261 7906260266	10CFR 50-320 P 10CFR 10CFR 10CFR		CLIKEMAN, F M CLIKEMAN, F M CLOUGH, R. L. CLUSEN, R. C COATS, R. L	7906080130 7906120180 7906210037 7906280140 7906210365	50-182 Q 50-182 F REVIEW ORP 50-320 U NUREO	NUREG/CR-0335
CHILK, S J CHILK, S J CHILK, S J CHILK, S J CHILK, S J	7906040434 7906260279 7906020060 7906070143 7906260056	50-280 Q 10CFR 50-302 Q 50-344 Q 50-302 Q		COBBLI. COBEAN, W. R COCHRAN, T B COCKRELL, R Q COFFIN, W. S,	7906130438 7906290226 7906070341 7906130220 7906270146	50-320 P 50-320 P 70-2623 C 50-320 D 50-280 H	
CHILK'S 7 CHILK'S 7 CHILK'S 7	7906260219 7906260254 7906070165 7906120030 7906140184	100FR 100FR 50-320 P 50-313 0 50-389 0		COFFIELD, R D. COFFHAN, F D. COHEN, N COHEN, E D COHEN, I COHEN, I.	7906020080 7906130394 7906210362 7906040147 7906140124 7906290391	PROJ 50-320 P PR 50-549 G 70-371 C	
CHILK.S.J CHILK.S J CHILK.S J CHILK.S J CHILK.S J	7906230129 7906270023 7906270093 7906210117 7906260213	50-313 Q 50-302 P 50-320 Q 50-446 Q 10CFR		COHNING COLBERTIR B COLEIR F COLEIR F	7906220462 7906070418 7906010290 7906070011 7906140117	50-416 Q PR 50-549 Q 50-445 T	
CHILK, B J CHILK, B J CHILK, B J CHILK, B J CHILK, S, J,	7906060142 7906260210 7906260189 7906210255 7906260184	50-320 Q 50-313 P 10CFR 50-327 Q 10CFR		COLE, R F COLE, R F COLE, R F COLE, R F	7906060195 7906180726 7906180726 7906220109 7906180728	50-471 T 50-471 T 50-471 T 50-471 T 50-471 T	
CHILK, S. J. CHILK, S. J. CHILK, S. J. CHILK, S. J.	7906260206 7906260169 7906260176 7906260172 7906260174	10CFR 10CFR 10CFR 10CFR 10CFR		COLE, R F COLEMAN, D R COLINS, J, T COLL, N A COLLEY, R, W	7904220147 7904030084 7904280123 7904070225 7904150479	50-471 T NUREQ 50-320 P 50-250 Q	NUREG/CR-0786
CHILK, S. J. CHILK, S. J CHILK, S. J CHILK, S. J. CHILK, S. J	7906260127 7906260154 7906260162 7906260138 7906260147	50-320 P 100FR 100FR 50-219 P 50-334 P		COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, H. E. COLLING, D. H.	7906210200 7906230133 7906220214 7906230132 7906200160	50-320 U NUREG 50-320 P NUREG	
CHILK, B. J. CHILK, B. J. SHILK, B. J CHILK, B. J. CHIRAMAL, M	7904260194 7904270184 7904270191 7904270017 7904070157	50-26Y P 27-39 C 27-39 C 30-320 P 50-320 P		COLLINS, J. T.	7706280180 7706280134 7706270051 7706270286 7706280216	50-320 P 50-320 P 50-320 P 50-320 P	
CHOW, E.T. CHRIBTOPHERBON CHRIBTOPHERBON CHRIBTMAN, J.N. CHRIBTMAN, J.N.	7906200486 7906250232 7906260073 7906050053 7906220219	50-346 G 50-312 G 50-312 H 50-338 G 50-338 G		COLLINS, J. T.	7906210136 7906280218 7906280231 7906280227	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	
CHRISTNER, R S CHRISTENBURY, E. CHRISTENBURY, E CHRISTOFFER, Q. CHRISTOFFER, Q.	7706010233 7706210060 7706230114 7706010079 7706180043	50~334 J 50~320 g 50~471 g 50~294 g 50~284 g		COLLINS, J. T.	7906220205 7906220175 7906210172 7906210233 7906290249	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	

AUTHOR	ACCESSION NUMBER	BUBJECT	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT	REPORT NUMBER
COLOMBOIR W COLOMBOIR W COLOMBOIR W COLOMIT E	7906190254 7906180561 7906190516 7906210291	50-312 R 50-312 S 50-312 S 50-390 G		COPELAND, J O COPELAND, J O COPELAND, J O COPELAND, J O	7906140178 7906180723 7906190015 7906180124	50-466 0 50-466 0 50-466 0 50-466 0	
COLTEN, J D COMMS, T. R COMME, J C COMMLIN, J C COMMON, T E	7906050141 7906060117 7906210139 7906050277 7906010205	NUREO FOIA 50-320 P NUREO 50-416 Q	NUREG/CR-0699 NUREG/CR-0716	COPELAND, J O COPELAND, J. O COPELAND, J. G COPELAND, R L CORNELE, E K	7906220458 7906280262 7906280245 7906080288 7906210114	30-466 0 30-466 0 50-466 0 50-537 F 50-320 P	
COMLON. T. E COMLON. T. E COMLON. T. E COMLON. T. E COMLON. T. E	7906210057 7906070375 7906040387 7906150039 7906200204	50-370 G 50-250 G 50-327 G 50-438 G 50-390 G		CORNELL, E K CORNELL, E K CORNELL, E K CORNELL, E, K CORNELL, E, K	7906210112 7906220173 7906220212 7906220221 7906220217	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	
COMMON, T E COMMON, T E COMMON, T E COMMON, T E,	7906140147 7906210068 7906220242 7906250345 7906260603	50-370 Q 50-387 Q 50-438 Q 50-338 Q 50-281 Q		CORNELL, E K CORNELL, E K CORREA, C CORREA, C CORREA, K A	7906220166 7906260086 7906260419 7906120211 7906190415	50-320 P 50-320 P 50-18 J 50-272 J 50-89 J	
COMMENT E COMMENT B COMMENT B COMMENT B COMMENT B	7906070114 7906010158 7906180656 7906110429 7906010137	50-339 G 50-395 M 50-277 G GRG 50-358 G		CORREA, C CORYELL, O P COSTELLO, O J COSTELLO, J R COSTELLO, J R	7906290414 7906040184 7906180520 7906220222 7906290630	50-70 J 70-143 C 50-280 R 0A999 0A999	
COMMERTE COMMERTE COMMERTE COMMERTE COMMERTE COMMERTE	7906250415 7906230107 7906230110 7906230112 7906230112	50-358 G 50-277 Q 50-277 G 50-277 Q 50-358 G		COSTLE.D M COSTOMIRIB.O H COTA.P C COTE.F H COTNER.H L	7903200106 7906220182 7906030145 7906180453 7906120396	080 50-320 P 50-382 A 50-392 C 50-568 D	
COMMER. H J COMMER. T B COMMELL, T COMMELL, T COMMELL, C.	7904280103 7906220378 7906190424 7906190293 7906200369	50-358 Q 50-416 Q 50-213 J 50-245 J 50-286 R		COTTLE, H COTTLE, H COTTLE, H COTTLE, H	7906290288 7906290174 7906290048 7906290362 7906290135	50-269 Q 50-269 Q 50-269 Q 50-269 Q	
COMMER.E L COMBOY,D COMSTABLE.Q L COMVER.S	7906290033 7906250151 7906260561 7906260186 7906200445	50-334 P 50-317 P 70-33 C 50-298 G 50-320 P		COTTLE.W.T COUGHLIN, J COUGHLIN, J COUGHLIN, J COUNBIL, W O	7906260271 7906230119 7906280025 7906130248 7906120050	50-269 Q 50-546 Q 50-546 K 50-546 B 50-213 Q	
CONVER.8. CONVAY.H.F CONVAY.W F COOK.R J COOK.R J.	7906210075 7906040255 7906040258 7906040411 7906250155	50-320 P 50-271 S 50-271 S 50-329 Q 50-329 Q		COUNBIL, H O COUNBIL, H O COUNBIL, H O	7906050278 7906290732 7906290742 7906050313 7906080262	50-213 Q 50-213 Q 50-213 Q 50-213 P 50-213 P	
COOLEY, D. E COOLEY, H. J COONEY, H. J COONEY, H. J. COONEY, H. J.	7904040340 7904290436 7904040341 7906040345 7906040367	50-272 8 70-734 C 50-171 8 50-171 8 50-277 8		CONNEIL, W C COUNEIL, W C COUNEIL, W C COUNEIL, W C	7906220286 7906150205 7906290784 7906140277 7906210198	80-213 P 50-245 G 50-336 G 50-336 P	
COONEY, H. J COONEY, H. J COONEY, H. J COONEY, H. J COONEY, H. J	7904040368 7906040320 7906040329 7906070210 7906070215	50-277 8 50-277 8 50-277 8 50-277 8 50-277 8		COUNSIL, W. O COUNSIL, W. O COUNSIL, W. O	7706040365 7706040371 7706140528 7706250305 7706220043	50-334 G 50-245 G 50-336 G 50-245 P PR	
COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J. COONEY, M. J.	7906040309 7906040316 7906070252 7906070303 7906080287	50-277 8 50-277 8 50-277 8 50-277 8		COUNBIL, W O. COUNBIL, W. O COUNBIL, W. O COUNBIL, W. O.	7906200535 7906020210 7906080042 7906080076 7906140481	REGOD 50-336 G 50-245 G 50-336 G 50-245 G	
COONEY, M J COONEY, M J COONEY, M J COONEY, H J, COONEY, H J,	7906080289 7906080290 7906110172 7906110174 7906200422	50-277 8 50-277 8 50-277 8 50-277 8		COUNSIL, W O COUNSIL, W O COUNSIL, W O COUNSIL, W O	7906070412 7906140222 7906120128 7906140524 7906290724	50-336 Q 50-245 Q 50-336 Q 50-336 Q	
COONEY, M J. COONEY, M J. COONEY, M J. COONEY, M J. COONEY, M, J.	7906200425 7906190329 7906260272 7906260283 7906260294	50-277 8 50-277 R 50-278 8 50-277 8 50-276 8		COUNSIL, H Q. COUNSIL, H, Q COUNSIL, H, Q COUNSIL, H, Q COUNSIL, H, Q	7904030254 7904050314 7906120339 7904150208 7906150337	50-245 P 50-336 P 50-336 P 50-245 Q 50-245 P	
COONEY, H. J. COONEY, H. J. COONEY, H. J. COOPER, J. COOPER, J.	7906260253 7906280116 7906280118 7906120407 7906120407	50-277 8 50-277 8 50-277 8 50-302 8 50-302 8		COUNBIL, W 0. COUNBIL, W. 0 COURTMEY, J C COUTANT, C C COUTANT, C C	7905180496 7905250282 7905220149 7905210011 7905220183	50-336 G 50-245 G PRM RES REB	7906210011 7906220183
COOPER, J. COOPER, J. COOPER, J. COOPER, J. COPELAND, J. G.	7706190303 7706180308 7706250298 7706280146 7706080183	50-302 8 50-302 8 50-302 8 50-302 8 50-466 0		COHAN, B. Z COHAN, R. L. COHAN, B. Z COX, J. W CRANE, P. A.	7706210361 7706040218 7706040410 7706280079 7706140579	50-574 0 50-10 P 50-437 0 50-599 0 50-133 0	NEDC-24159
COPELAND, J Q COPELAND, J Q COPELAND, J Q COPELAND, J, Q COPELAND, J Q	7906080190 7906020107 7906020009 7906030144 7 <del>9</del> 06020218	50~466 Q 50~466 Q 50~445 M 50~466 Q 50~466 Q		CRANE, P.A. CRANE, P.A. CRANE, P.A. CRANE, P.A. CRANE, P.A. CRANE, P.A.	7906290125 7906130383 7906130416 7906190319 7906190453	50-320 G 50-275 S 50-275 A 50-133 S 50-275 A	
GOPELAND, J Q.	7906080052	50~466 0		CRANE, P. A	7906200464	50-275 A	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
GRANE,PA Grane,PA Grane,PA Greed,JR.	7906200472 7906180521 7906270221 7906220119	50~275 A 50~275 A 50~133 S 50~305 Q		CURTIE,N W CURTIE,N W CURTIE,N W	7906120394 7906120400 7906180438	50-387 A 50-387 A 50-387 A	
CREBWELL, J. S CREWS, E H CREWS, E H CREWS, E H CREWS, J L	7906200486 7906200585 7906140175 7906050296 7906200141	50-346 Q 50-395 Q 50-395 Q 50-395 K 50-206 Q		CURTIB,N W CURTIB,J R CUBTARD,C CUTCHIN,J, M CUTCHIN,J M	7906260380 7906150357 7906260462 7906260158 7906190560	50-387 A 50-141 G 50-572 D 50-569 Q 50-387 G	
CREMB'N F CREMB'N F CREMB'	7906260326 7906200462 7906140190 7906250445 7906260531	50-312 0 50-320 P 50-312 0 50-374 0 50-312 0		CUTCHIN, J H CUTCHIN, J H CUTCHALL, C E CYPHERT, B B	7906190565 7906190572 7906190576 7906180500 7906020167	50-387 G 50-387 G 50-387 G 50-546 G 50-445 M	
CREWS, J L CREWS, J L CROCKETT, J CROCKER, J A. CROCKER, H H	7706250453 7906250438 7906040323 7906040307 7906130055	50-206 0 50-73 0 50-336 8 50-336 8 70-135 C		DAIL, L C DAIL, L C DAIL, L C DAIL, L C DAIL, L C	7906130439 7906130443 7906020154 7906140428 7906180741	50-413 Q 50-489 Q 50-413 Q 50-488 Q 50-413 Q	
CROCKER, H W. CROCKER, H W CROCKER, H W CROCKER, H H	7906260347 7906140608 7906150213 7906210295 7906140643	70-371 C 70-820 C 50-245 G 70-364 C 70-33 C		DAIL, L C DAIL, L C DAIL, L C DALE, L F DALE, L F	7906190114 7906200027 7906140334 7906140648 7906290773	50-491 Q 50-491 Q 50-491 B REGOD 50-416 Q	
CROCKER, L P CROCKER, L P CROCKER, L P GRONEY, S T CRONEBERGER, D K	7906130451 7906270084 7906270075 7906180707 7906290320	50-320 0 50-320 0 50-320 P 50-275 P 50-320 P	NUREG/CR-0715	DALE, L F DALE, L F DALE, L F DALE, L F DALE, L F	7906200469 7906220467 7906120327 7906140365 7906140405	50-416 8 50-416 Q 50-416 A 50-416 B 50-416 S	
CRONEBERGER, D K CROSSHAN, F A CROW, H T CROW, H T CROW, H T	7706270405 7706220241 7706010220 7706220123 7706220155	50-320 P 50-382 Q 70-698 C 70-27 C 70-820 C		DALE,L F DALE,L F DALE,L F DALE,L F DALLY,B J	7906140437 7906140429 7906120335 7906270219 7906080107	50-416 B 50-416 B 50-416 A 50-416 B NUREQ	NUREQ/CR-0704
CROWLH T. CROWLH T. CROWLH T CROWLH T CROWLH T	7906230457 7906220027 7906220113 7906220128 7906270024	70-824 C 70-1100 C 70-1201 C 70-33 C 70-1359 C	•	DALTON,A T DALTROFF,B L DALTROFF,B L DALTROFF,B L DALTROFF,B L	7906050068 7906110026 7906130112 7906270193 7906260334	50-554 G 50-277 G 50-277 G 50-277 G 50-278 P	
CROW, W T CROW, W T CROW, W T CROW, W, T CROW, W T	7906270026 7906270004 7906270033 7906290745 7906270037	70-1359 C 70-708 C 70-143 C 70-143 C 70-36 C		DALY, H DANEERH G DANCE, H C DANCE, H, C DANCE, H C	7906270111 7906230168 7906180714 7906200552 7906180408	50-596 Q 70-27 C 50-259 Q 50-321 Q 50-302 Q	
CROW.W T CROW.W T CROWLEY.C J CROWLEY.J.L	7906290777 7906290733 7906290738 7906180422 7906180588	40-3392 C 70-487 C 70-687 C TOPREP 71-301 C	NUREQ/CR-0719	DANCE, H. C DANCE, H. C. DANCE, H. C. DANCE, H. C. DANCE, H. C	7906140073 7906200341 7906210304 7906250365 7906070075	50-321 G 50-324 G 50-327 G 50-324 G 50-111 G	
CROWLEY, J. L., GROWLEY, B. R. CROWLEY, B. R. GULP. R. H GULP. R. H	7906180584 7906260603 7906250345 7906070307 7906110440	71-301 C 50-281 Q 50-338 Q 50-466 Q		DANIELEON, D H DANIEL, R W DANIEL, R W DANIELEON, D H DANIELEON, D H,	7706130143 7706130127 7706110411 7706030051 7706040052	50-341 Q 50-329 Q 50-260 U 50-263 Q 50-295 Q	
Culp, R. M Cummings, J. J Cummings, J. J Cummingham, R. O. Cunningham, R. O.	7906020107 7906220277 7906220364 7906150277 7906260467	50-466 0 50-346 M 50-346 M 50-5 J 50-5 B		DANIELSON, D H DANIELSON, D H DANIELSON, D H DANIELSON, D H	7906210334 7906260598 7906210317 7906270462 7906250172	50-155 Q 50-341 Q 50-301 Q 50-346 Q 50-237 Q	
CUNNINGHAM, R. O. CUNNINGHAM, R. O. CUNNINGHAM, R. O. CUNNINGHAM, M. B. CUNNINGHAM, G. E.	7906280144 7906290398 7906270231 7906080036 7906150146	50-5 B 50-5 B 50-5 B PR 50-73 P		Danielb, F. T Danielbon, D. H Danielbon, D. H Danielbon, D. H Danielbon, D. H	7906260553 7906250123 7906260583 7906260589 7906260199	50-202 Q 50-461 Q 50-373 Q 50-409 Q 50-358 Q	
Cunningham, O. E. Cunningham, O. E. Cunningham, O. E. Cunningham, L. J. Cunningham, L. J.	7906010289 7906190285 7906220235 7906060197 7906130490	70-754 C 50-70 F 50-73 P 50-320 8 50-320 U		DANIELSON, D. H DANIELSON, D H DARBY, C. DARHITZEL, R, W DARHITZEL, R, W	7906140658 7906140607 7906110071 7906200273 7906260003	50-341 G 50-341 G WASTE MOT 50-73 P 50-73 P	
CUNNINGHAM, A L CUNNINGHAM, A L CUNNINGHAM, R E, CUNNINGHAM, R E, CUNNINGHAM, M	7906070104 7906260521 7906230005 7906120009 7906280014	50-416 Q 50-302 Q 70-143 C 50-320 P 50-320 P		DARMITZEL, R. W DATTILO, T. M. DAUGHERTY, T. M DAVIDSON, D. R DAVIDSON, D. R	7906270117 7906180497 7906210361 7906070048 7906080257	50-73 E 50-546 Q 50-574 Q 50-440 Q 50-440 8	•
CURRAN; J. M CURRAN; J. M CURRAN; J. M. CURRAN; J. M GURRY; J. A.	7906130289 7906220325 7906220404 7906220346 7906020034	50-206 R 50-206 S 50-206 S 50-206 S 50-358 O		DAVIDBON, J J DAVIEB,R W DAVIE,R.L. DAVIE,W K. DAVIE,J F.	7906180722 7906120359 7906010272 7906180575 7906250072	NUREQ TOPREP 50-329 G 50-320 T 50-361 A	NUREG-0525
CURTIE: C. E. CURTIE: N W. CURTIE: N. W. CURTIE: N. W. CURTIE: N. W. CURTIE: N. W.	7906010113 7906210036 7906140369 7906040265 7906040193	FOIA 50-387 8 PRM 50-387 8 50-387 K		DAVIS, S. M. DAVIS, M DAVIS, S. M. DAVIS, W DAVIS, C. E.	7906010207 7906080248 7906260348 7906120287 7906260596	50-318 8 50-317 8 50-318 8 50-568 A NUREO	YAÉC-1175 NUREQ/CR-0686
GURTIB, N. W. GURTIB, N. W.	7904040194 7904040208	50-387 K 50-387 C		DAVIB, C. E DAVIB, J. O. DAVIB, L. D.	7906290673 7906270010 7906220130	NUREO 50-320 P 50-556 G	NUREO/CR-0710

AUTHOR	ACCESSION NUMBER	EUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
OAVIB.J 0 Q L.BIVAD	7906210127 7906290036	50-320 P FOIA		DENTON, H R DENTON, H R	7906270076 7906270090	50-280 H 50-280 H	
O L.BIVAG O L.BIVAG O L.BIVAG O L.BIVAG O V.BIVAG	7906270014 7906290504 7906290078 7906290548 7906260519	50-320 P FOIA FOIA FOIA 50-346 P		DENTON,H R DENTON,H R DENTON,H R DENTON,H R	7906270087 7906270095 7906270109 7906270119	50-280 H 50-280 H 50-280 H	
DAVIS, J Q DAVIS, J Q DAVIS, J Q DAVIS, J Q DAVIS, J Q	7906040110 7906290003 7906290582 7906070212 7906290447	70-895 C 50-320 P FOIA 50-482 A FOIA		DENTON, H R	7906270124 7906270132 7906270143 7906270151 7906270263	50-280 H 50-280 H 50-280 H 50-280 H	
DAVIB, J G DAVIB, J G DAVIS, A B DAVIS, A B	7904040171 7904180180 7904250148 7904240074 7904020055	50-482 G 50-482 A 50-313 G 50-315 G 50-295 G		DENTON, H R DENTON, H R DENTON, H R DENTON, H R, DENTON, H R,	7906270265 7906270267 7906210433 7906250133 7906260077	50~280 H 50~280 H 50~280 H 50~307 P 50~307 O	
DAVIS:A B DAVIS:A B. DAVIS:A B. DAVIS:A B DAVIS:D K	7906260213 7906250121 7906010117 7906050126 7906200097	70-1308 C 50-263 G 50-346 G 70-1308 C 50-320 F		DENTON, H R	7906240821 7906260492 7906260322 7906260328 7906270006	50-280 H 50-320 H 50-320 H 50-320 H	
DAVIS, D.K. DAWSON, D. M. DAWSON, D. M. DAWSON, D. M. DAY, J.	7906290309 7906250226 7906230158 7906250256 7906070419	50-320 A 70-1308 C 70-1308 G 70-1308 C PR		DENTON, H R	7906270009 7906270019 7906290016 7906290138 7906060254	50-320 H 50-320 H 50-320 H 50-320 H	
DEALE.V B DEAN.R B DEANE.E Q. DEANE.E O. DEASON.V A.	7906180612 7906210333 7906290223 7906290211 7906280066	0 928-08 9 168-08 9999 9994D 9994D NUREO	(UREO/CR-0648	DENTON, H R DENTON, H R DENTON, H R DENZER, H. O DEPHILIPPE, A A	7906260278 7906260282 7906280097 7906060086 7906230121	50-424 G 50-424 G 50-424 G GA777 40-8584 C	
DEBELLO, M DEBOER, T. K. DECONCINI, D, DEEO, F H DEHEULLE, E 14	7906040179 7906110069 7906280266 7906070254 7906270264	50-482 0 WASTE MOT COMMIGSION 50-333 J 50-280 H		DERIENIO, P P DERIENIO, P P DETTENMETER, R DEUKMEJIAN, O DEULIN, J	7706270620 7706210435 7706260633 7706210372 7706150222	9A999 50-285 8 50-237 9 PRDJ 50-317 9	
DELTZ, V. R DELANEY, J. C DELANEY, J. C DELAPAZ, A DELAPAZ, A	7906200470 7906260625 7906290733 7906290738 7906050004	FGIA 70-143 C 70-487 C 70-487 C PRM		DEVINGENTIB, J DEVLIN, J W DEVLIN, J W DEVLIN, J W	7906180525 7906210055 7906140193 7906040089 7906140140	50-568 A 70-820 C 50-309 Q 50-272 Q 70-364 C	
DELAPAZ, A DELGEORGE, L O, DELGEORGE, L O OELILLO, J. DELLA RATTA, A.	7906220059 7906140385 7906250284 7906010249 7906210228	PRM 50-373 8 50-373 8 FOIA 50-320 P		DEVLINJ W DEWEABE, H. Q DEWEABE, J Q DEWEABE, J Q DEXTER, W. D	7906260568 7906140322 7906150283 7906150279 7906200244	70-33 C 50-260 S 50-259 R 50-259 R 40-8602 C	
CEHLOH, D. J CENESS, S. J CENKOHSKI, H SENTON, H R DENTON, H R,	7906290678 7906260395 7906150420 7906230304 7906070188	50-327 G 50-84 J 50-275 A 50-579 A FOIA		DEYOUNG, R C	7906070334 7906070065 7906050216 7905290343 7906290331	FDIA 50-443 H NUREO NUREO 50-320 P	
DENTON: HR. DENTON: HR. DENTON: HR. DENTON: HR. DENTON: HR.	7904190012 7906250211 7903300226 7906060118 7906060120	50-320 F 50-574 A 50-250 U 50-334 P FOIA		DIAMOND, D J DIAZ, N J. DICKERBON, M W DIENHART, A V DIENHART, A V	79 7' 7 ?		
DENTON, H R DENTON, H R, DENTON, H R DENTON, H R DENTON, H R	7903300582 7906060136 7906070001 7906080007 7906260519	NUREO FOIA 50-320 H 50-10 U 50-346 P					
DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R. DENTON, H. R.	7906010297 7906260038 7906030039 7906040398 7906110408	50-275 H 50-320 F 50-237 P 8ECY 50-280 U					
DENTON, H. R.	7906020125 7906020130 7906290701 7904040042 7906230047 7906120087 7906120033 7906180395 7906220491 7906270088	50-280 P 50-280 P 50-220 H 50-443 Q 50-280 H ORO 50-352 A 50-352 H 50-275 Q					
DENTON: H. R.	7906200466 7906210418 7906230101 7906270008 7906270020	50-522 0 50-280 H 50-309 P 50-280 H 50-280 H					
DENTON: H. R. DENTON: H. R DENTON: H. R. DENTON: H. R	7906270035 7906270053 7906270060 7906270069	50-290 H 50-290 H 50-290 H 50-290 H					

302

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
DOLAN, J. E DOLAN, J. E DOLAN, J. E DOLAN, J. E DOLAN, J. E	7906270128 7906220257 7906260344 7906080266 7906150329	50-315 0 50-315 9 50-315 0 50-320 9 50-315 8		EARLY, P J EARLY, P J EARLY, P J EARLY, P J	7906120034 7906010186 7906070246 7906120266	50-286 G 50-286 G 50-286 G 50-286 G	
DOLAN, J E DOLAN, J E DOLAN, J E DONAHUE, J F DONAT, T	7906130287 7906210201 7906250291 7906020054 7906210304	50-315 P 50-316 8 50-315 P 50-254 G 50-327 0		EARLY, P J EARLY, P J EARLY, P J EARLY, P J	7906130374 7906190417 7906150275 7906150255 7906190291	50-333 R 50-333 P 50-286 Q 50-333 H 50-286 Q	
DONO, R O DONNELLY, W H DONNELLY, W H DOUGHERTY, 8 B DOUGHERTY, T M	7906250487 7906210262 7906210260 7906200596 7906040410	50-201 P 50-320 U 50-320 U 50-338 0 50-437 0	UCRL-52575	EARLY, P J EARLY, P J EARLY, P J EARLY, P J	7906190364 7906180393 7906190506 7906260445 7906260461	50-286 F 50-286 P 50-286 P 50-333 G 50-286 G	
DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J DOUGHERTY, D J	7906160040 7906160035 7906190181 7906270089 7906130125	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT		EARLY, P J EARLY, P J EARLY, P J EARLY, P J	7906260143 7906260428 7906260423 7906280082 7906280121	50-286 P 50-286 F 50-333 P 50-286 Q 50-333 P	
DOUGHERTY, D J DOUGLASS, R M DOUGLASS, R M DOYLE, M M DOYLE, M M	7906150155 7906040191 7906040354 7906040161 7906260505	CONTRACT 50-317 8 50-318 8 PROJ PROJ		EATON, A M EBNETER, S D ECKART, L E ECKERMAN, M ECONOMOS, N	7906290290 7906260165 7906140627 7906210266 7906070114	RES 50-334 G 50-358 O 50-201 H 50-339 G	7906290250
DOYLE,R J DRAKE,J H DRAKE,J H DRAKE,J H DRAKE,J H	7906020115 7903210415 7906210348 7906220268 7906140468	RES 50-361 0 50-206 0 50-361 A 50-206 P	7904020115	ECONOMOS.N ECONOMOS.N EDELMAN.M R EDGAR.G L EDGAR.G L	7906140147 7906210068 7906070091 7906230184 7906230205	50-370 Q 50-389 Q REGOD 50-556 Q 50-556 Q	
DRAKE, J H DREY, K DROMERICK, A DROMERICK, K A DUBIEL, R H	7906230321 7906080032 7906140225 7906180135 7906290022	50-361 K 50-10 U 50-311 A 50-423 A 50-320 P		EDLON, J EDLOW, J EDLOW, J EDISON, G E	7906280010 7906050072 7906050077 7906160057 7906290585	50-320 P XPORTLIC XPORTLIC XPORTLIC BECY	
DUCK, J R DUCK, J R DUCK, J R DUCK, J R DUDA, E	7906120274 7906190307 7906190419 7906190457 7906110181	50-327 J 50-321 J 50-335 J 50-302 J 50-220 8		EHERTS: R F. EHRENSPERGER, W EKRENSPERGER, W EHRENSPERGER, W EICHELDINGER, G	7706070301 7906050297 7906060284 7906130327 7906070274	50-317 8 50-424 F 50-424 H 50-424 A TOPREP	
DUDA, E DUDA, E DUDA, E DUDA, E DUDA, E	7906110184 7906130006 7906180492 7906220408 7906220417	50-220 8 50-220 8 50-220 8		EILPERIN, S. F EIRCKSON, L. W EISENHUT, D O EISENHUT, D O	7906200399 7906080139 7906230135 7906060128 7906290854	50-320 P 50-344 Q 50-320 U 50-309 H 50-312 H	
DUFLO, M E DUFLO, M E DUFLO, M E DUFLO, M E DUFLO, M E	7904220246 7904050005 7904040040 7904050394 7904040026	50-346 M 50-389 0 50-498 0 50-329 0 50-389 0		EISENHUT, D O EISENHUT, D O EISENHUT, D O EISENHUT, D O	7904240513 7904020182 7904020180 7904250039 7904250070	50-320 P 50-301 Q GEN TEC IS 50-280 P 50-334 P	
DUFLO, H. E. DUFLO, H. E. DUFLO, H. E. DUFLO, H. E. DUFLO, H. E.	7906040430 7906060010 7906070119 7906230181 7906010276	50-466 C PROJ 50-466 G 50-320 G 50-443 O		ELAM, B. D ELAMA B. D ELIASEN, A N ELIN, J O CLLEMAN, T S	7706280150 7706280152 7706120112 7706210347 7706070083	50-320 P 50-320 P REGOD 50-361 Q 50-111 Q	
DUFLO, M E DUFLO, M E DUMAS, D O, DUNBAR, J. DUNBAR, J.	7906210095 7906210367 7906110434 7906190447 7906220291	50-320 Q 50-338 Q 71-6400 C 50-249 B 50-237 B		ELLEHAN, T B. ELLERSHAW, L E, ELLERSHAW, L E ELLERSHAW, L E ELLIS, R. C	7906210354 7906010114 7906060059 7906230049 7906270268	50-111 G GA999 GA999 GA999 SO-280 H	
DUNBAR, J DUNCAN, C F DUNDAB, W J DUNEFELD. M DUNHAM, M. S	7906270158 7906070022 7906070193 7906020168 7906140053	50-249 8 GA999 50-266 J 50-320 P 71-314 C		ELLIB, J. L ELLIB, J. L EMBHWILLER, T. R ENDREB. G. W ENOELDER: T C.	7906070305 7906110044 7906070233 7906020105 7906190544	50-445 Q WASTE MOT FOIA NUREG 70-824 C	NURE0/CR-0426 V2
DUNHAM, M. S. DUNN, B. M. DUNN, C. N DUNN, C. N DUNN, C. N	7906140057 7906230140 7906070235 7906160060 7906270196	71-314 C TOPREP 50-334 Q 50-334 P 50-334 G	BAH-10074A	ENGEL, D.A. ENGELHARDT, T.F ENGELHARDT, T.F ENGELHARDT, T.F ENGELHARDT, T.F,	7906180810 7906010163 7906010307 7906180697 7906070219	50-596 'Q 50-556 H 50-462 H 70-1729 C 10CFR	
DUNN, C. N DUNN, C. N DUNN, C. N. DUNN, C. N DUNN, C. N	7704050282 7704270746 7704050278 7704180601 7704210131	50-334 P 50-334 Q 50-334 R 50-334 Q 50-334 P		ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	7906290214 7903040359 7906130132 7906130135 7906120043	1&E 50-320 S 50-133 G 50-397 G 50-528 G	
DUNN, C K DURR, J P DURR, J, P, DURST, B M DYER, N C	7906220331 7906040188 7906070213 7906180804 7906180707		NUREO/CR-0796 NUREO/CR-0715	ENGELKEN, R. H ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H. ENGELKEN, R. H.	7906120047 7906120048 7906120051 7906120053 7906120057	50-133 G 50-344 G 50-206 G 50-312 G 50-397 G	
DYER, J A DYER, J A, DYKES, V. B, DZURIK, A, A, EAGLETON, T F,	7906200318 7906200428 7906130006 7908230395 7906250459	50-338 Q 50-320 P 70-2623 C 50-320 H 50-482 U		ENGELKEN, R H, ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R, H	7906180492 7906180496 7906180499 7906180442 7906180443	50-360 G 50-74 G 70-1257 C 50-187 G 50-228 G	
EARLY, P. J	7906150227	50-286 P		ENGELKEN, R. H.	7906180447	50-288 G	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
ENGELKEN, R H ENGELKEN, R H	7906180450 7906180451 7906180454 7906180456	50-326		ENGELKEN, R H ENGELKEN, R H	7906180373 7906180374 7906180375	50-133 Q 50-275 Q 50-312 Q	
ENGELKEN, R H	7906180458 7906180459 7906180462 7906180463 7906180467	50-113 0 50-433 0 50-137 0 50-27 0 50-394 0		ENGELKEN,R H ENGLE,L B ENGLE,L B ERB,C M ERBE,H	7906150090 7906200316 7906270097 7906250123 7906250339	50-397 Q 50-368 P 50-320 Q 50-461 Q 50-358 Q	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7906180472 7906180476 7906180479 7906180491 7906180484	50-528 Q 50-344 Q 50-133 Q 50-206 Q 50-312 Q		ERICKSON,L W ERICKSON,P B ESSIG.T H ESSIG.T H ESTEVES,R M	7704070218 7904270440 7904020045 7904250125 7904280157	50-344 0 50-285 P 50-295 0 50-263 0 50-320 P	
ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	7906180488 7906190016 7906190020 7906110070 7906110073	50-397 0 50-89 0 50-70 0 50-133 0 50-344 0		ETHERIDGE, M R ETHERINGTON, H ETHERINGTON, H ETHERINGTON, H ETHERINGTON, H	7906190081 7906260369 7906250474 7906180649 7906120076	9A979 ACR8 ACR8 50-320 D 50-320 T	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7906110075 7906110077 7906180219 7906180221 7906180225	50-206		ETHERINGTON, H ETHERINGTON, H ETHERINGTON, H ETHERINGTON, H ETHERINGTON, H	7906120037 7906150224 7906290663 7906290655 7906290647	50-320 U 50-320 T ACRS ACRS ACRS	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H, ENGELKEN, R. H ENGELKEN, R H	7906180228 7906180231 7906180213 7906080213 7906080214	50-312 8 50-397 8 50-528 8 50-360 0 70-984 C		EVANS, V R EVANS, D J EVENSON, L J EVERETT, R J EVERETT, R J	7906150218 7906180676 7906160050 7906210033 7906010291	90-317 G PROJ PR 90-320 P 90-274 G	
CNGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7904080215 7904080214 7904080218 7904080219 7904080220	50~220 G 50-70 G 70-1257 C 50-89 G 70-734 C		EVRAETB, J C EVRAETB, J C EWALD, S C EWALD, S C EWALD, S C	7906070051 7906140661 7906200160 7906180680 7906200454	PR PR 50-280 Q 50-280 Q 50-320 P	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7904080222 7904080223 7904080224 7904080226 7904080227	70-754 C 50-187 G 50-94 G 70-25 C 50-394 G		FABIAN, B F FABRNER, W J FACOART, J R FAHRNER, W J FAIROBENT, J E	7906220072 7906080264 7906140576 7906080263 7906210269	50-320 H 50-341 8 50-488 H 50-341 8 50-320 P	
ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H ENGELKEN,R H	7906080228 7906080230 7906080232 7906080233 7906080234	50-106 G 50-298 Q 50-113 G 50-224 G 50-326 G		FAIST, C A FAKUNDINY, R H FARMELO, D R FARON, R B FARR, B J	7906200261 7906030226 7906210339 7906130173 7906270167	71-188 C NUREO 50-331 P 50-244 P 50-324 B	NURE9/CR-9644 BCL-585-9
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7906080236 7906080237 7906080238 7906080239 7906080240	50-142 G 50-433 G 50-137 G 50-27 G 50-528 G		FARRAR, M FARRAR, M C FARRAR, M C FARRAR, M C FARANC, A, N	7904040219 7904290031 7904290038 7904290090 7904010039	90-338 T 50-338 T 50-338 T 50-354 G	
ENGELKEN, R H ENGELKEN, R H, ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7904080241 7904080242 7904080249 7904080244 7904080245	50-133 G 50-344 G 50-206 G 50-312 G 50-397 G		FABANDIA N FABANDIA N FATEIM E FAULKENBERRYIB FAULKENBERRYIB	7904260222 7904230478 7904200333 7904260347 7904200149	50-311 Q 50-320 P 50-312 Q 50-206 Q	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R, H ENGELKEN, R H ENGELKEN, R H	7904180241 7904180245 7904180248 7904180273 7904180273	50-528 8 50-193 8 50-344 8 50-204 8 50-312 8		FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAULKENBERRY, B FAY, C W	7906250449 7906260543 7906250472 7906250442 7906130265	50-374 G 50-312 G 50-206 G 50-73 G 50-802 A	
ENGELKEN, R. H. ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H. ENGELKEN, R. H.	7904180280 7904290374 7904130037 7904130041 7904130042	50-397 8 50-320 P 50-528 G 50-275 Q 50-133 Q		FAY.C W FAY.C W. FEARB.K. FEDERICK.W C	7906120421 7906220181 7906280117 7906200361 7906150424	50-502 A 50-266 P 50-502 A 50-361 G 50-275 A	IPS-409
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7904130045 7904130047 7904130051 7904130053 7904130054	50-344		FEIERABEND,C D FEIST,C K FEIST,C K FEIT,R. FELTEN,L D	7906240593 7906130003 7906120293 7906210035 7904020091	50-282 Q 50-445 A 50-445 K REVIEW ORP PROJ	EBG-DDE-13244
ENGELKEN, R. H ENGELKEN, R. H, ENGELKEN, R. H ENGELKEN, R. H ENGELKEN, R. H	7904180335 7904180338 7904180340 7904180347 7904180351	50-528 8 50-133 8 50-344 8 50-312 8 50-397 8		FELTON, J M. FELTON, J M FELTON, J, M FELTON, J M FELTON, J M	7906040199 7906060004 7906260503 7906010246 7906010269	50-266 H FOIA FOIA FOIA	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H	7906180341 7906200049 7906200054 7906200056 7906200058	50-206 S 50-528 G 50-344 G 50-206 G 50-312 G		FELTON, J. M FELTON, J. M FELTON, J. M. FELTON, J. M FELTON, J. M	7906070205 7906070066 7906070229 7906010121 7906010235	FOIA FOIA FOIA FOIA	
ENGELKEN, R H ENGELKEN, R H ENGELKEN, R H ENGELKEN, R, H,	7906200061 7906180361 7906180364 7906180365 7906180368	50-397 G 50-528 S 50-133 S 50-344 B 50-206 S		FELTON, J M FELTON, J M FELTON, J, M FELTON, J, M	7904010243 7904010107 7904010273 7904040069 7904070214	FDIA 50-320 H 50-280 P 50-334 P FDIA	
ENGELKEN, R. H ENGELKEN, R. H	7906180370 7906180371	50-312 8 50-397 8		FELTON, J. H. FELTON, J. H. FELTON, J. M	7906070232 7906010096 7906050078	FOIA FOIA FOIA	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT MUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
FELTON, J. M FELTON, J. M	790401027 <i>7</i> 7904240553	50-349 S FOIA		FLEISCHAKER, D S FLEISCHAKER, D S	7906070327 7906010341	50-275 Q 50-275 Q	
FELTON, J. M FELTON, J M FENDRICK, J E FENDRICK, J E FERGUSON, K L	7906290017 7906220263 7906130446 7906130449 7906210246	FOIA FOIA 71-295 C 71-295 C TOPREP	HCAP-9529	FLEISCHAKER, D8 FLEISCHAKER, D8 FLYNN, P FLYNN, P FLYNN, P	7906280013 7906280015 7906050030 7906030160 7906140278	50-275 0 50-275 0 50-329 0 50-329 0 50-329 0	
FERLAND, E J FERLAND, E J FERMAN, P M FICKIES, R H FIELDER, J	7706040310 7706040321 7706020201 7706050226 7706080227	50-245 S 50-336 8 71-61 C NUREO 50-259 J	NUREO/CR-0644	FLYNN,H FLYNN,JD FOBELR L FOGEL,C M FOLEY,W J	7906180810 7906250362 7906080310 7906280153 7906210333	50-594	
FIELDS, H FINCHER, P L FINCKE, J R FINFROCK, I R FINFROCK, I R	7706250270 7706200418 7706280066 7706040407 7706150185	50-255 P 50-335 P NUREO 50-363 Q	NUREO/CR-0648	FOLSOM, J A FORD D FORD, E. P FORMICA; C	7906140582 7906290362 7906030037 7906290319 7906150420	50-443 Q 50-267 G 50-387 Q 50-269 Q 50-275 A	
FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R FINFROCK, I R	7906020076 7906290820 7906070394 7906070393 7906260567	50-217 G 50-219 G 50-363 G 50-363 G 50-219 G		FOSTER, J D FOSTER, S C FOSTER, J E FOSTER, J E FOSTER, W E	7906140657 7906070133 7906020054 7906130133 7906290236	50-358	
FINFROCK, 1 R FINFROCK, 1 R FINFROCK, 1 R FINFROCK, 1 R FINFROCK, 1 R	7904040174 7906050319 7906070259 7906070262 7906110191	50-219 P 50-219 P 50-219 P 50-219 P 50-219 S		FOSTER,W E FOSTER,W E FOUKE.R L FOX.C J FOX.C J	7904040101 7906230035 7904050234 7903300243 7903300235	QA999 QA999 50-445 G 50-250 U 50-250 U	
FINFROCK, I R FINFROCK, I R FINICLE, D P FINLEY, A Q FINLEY, A Q	7906190189 7906200209 7906290291 7906260312 7906260237	50-217 G 50-217 P RE8 50-243 G 50-368 G	7906290291	FOX.H S, FOX.H S FOX.H S FOX.H S FOX.H S	7906010209 7906120377 7906120329 7906120384 7906130286	50-260 S 50-276 S 50-260 B 50-260 S 50-260 S	
FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q	7906130136 7906130123 7906130130 7906230132 7906190225	50-341 Q 50-327 Q 50-331 Q 50-454 Q		FDX.H S FOX.H S FRALEY.R F FRALEY.R F FRALEY.R F.	7906290142 7906290159 7906250058 7906180646 7906220209	50-260 S 50-260 S 50-320 O 50-320 D 50-320 H	
FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G FIORELLI, G	7706170232 7706220176 7706040404 7706050046 7706010333	50-329 S 50-329 S 50-329 Q 50-263 Q 50-440 G		FRALEY,R F. FRALEY,R F FRALEY,R F FRANK.T FRANKLIN,W J	7906220174 7906220434 7906250071 7906110092 7906040417	50-320 0 50-320 0 50-320 0 WABTE MGT 50-445 M	
FIORELLI.G FIORELLI.G FIORELLI.G FIORELLI.G FIORELLI.G	7906140562 7906140647 7906050054 7906050222 7906050234	50-493 Q 50-341 Q 50-454 Q 50-456 Q 50-373 Q		Franklin, w J Franklin, w J Frank, L Fragcino, p. J Friedman, L	7906020207 7906250426 7906270180 7906260027 7906210232	50-445 M 50-445 M 50-344 P 50-471 G 50-320 P	
FIORELLIO FIORELLIO FIORELLIO FIORELLIO FIORELLIO	7706040045 7706210311 7706210327 7706260572 7706250118	50-295 Q 50-301 Q 50-155 Q 50-341 Q 50-461 Q		FRIEDMAN, L FRIZZLE, C D FROELIGH, R H FUCHKO, J M FULLER, W R	7906290393 7906130010 7906040068 7906190223 7906270042	50-320 P 50-307 P 50-466 Q 50-348 Q 50-280 H	
FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q FIGRELLI, Q	7906250165 7906250150 7906260581 7906260587 7906260621	50-237		FULLER.C FULLER.J K FULLER.J.K FURBUSH,M H FURBUSH,M H	7906150235 7906120196 7906130344 7906040161 7906200358	50-466 0 50-267 P 50-267 G PROJ PROJ	
FIORELLI,0. FIORELLI,0. FIORELLI,0 FIORELLI,0 FIORELLI,0	7904010032 7904070244 7904240192 7904240497 7904010124	50-341 C 50-373 G 50-358 G 50-346 G 50-483 G		FURR: 8 J FURR: 8 J FURR: 8 J. FURR: 8 J. FURR: 8 J	7906150340 7906080151 7906020181 7906040019 7906140491	50-324 S 50-324 Q 50-324 Q 50-261 G 50-324 Q	
FIGRELLI, G FIGRELLI, G, FIGRELLI, G FIGRELLI, G, FIGRELLI, G	7906020134 7906040449 7906230067 7906230074 7906230076	50-454 8 50-341 0 50-329 8 50-373 8 50-341 8		FURR.B J. FURR.B J. Gachik Gahmij H. Gahmij H	7706080278 7706270197 7706180259 7706170302 7706120161	50-324 P 50-324 8 50-275 0 50-267 R 50-267 R	
FIORELLI,0 FIORELLI,0, FIORELLI,0 FIORELLI,0 FIORELLI,0	7906250149 7906260097 7906220175 7906250145 7906290804	50-329 0 50-341 0 50-546 8 50-546 8		GAHM.J.W GAHM.J.W GAHM.J.W GALLAGHER.J.W GALLAGHER.E.J	7706120409 7906120414 7906260437 7906020241 7906250141	50-267 8 50-267 8 50-267 8 50-277 9 50-454 9	
FIDRELLI,Q. FISHER,C R FISHER,C R FISHER,J L FISHER,W L	7906290687 7906210141 7906190490 7906110411 7906260228	50-341 G 50-267 P TOPREP 50-280 U 70-1308 C		CALLACHER, E J CALLEN, K P. CALLEN, K P CALLINA, G D. CALLO, J	7906030037 7906250184 7906250205 7906040089 7906010081	50-454 G 50-556 G 50-556 G 50-272 G 50-556 G	
FITCHTER, J H, FITHIAN, F, J FITZGIBBONS, J E FITZGERALD, J FLACK, E D	7906020202 7906290261 7906290706 7906220221 7906060197	50-358 Q 50-367 U 50-220 H 50-320 P 50-320 8		GALLO, J GALLO, J. GALLO, J. GALLO, J. GALLO, J	7906010089 7906020233 7906020254 7906260490 7906080114	50-554 G 50-554 G 50-554 G 50-554 G 50-554 G	
FLAHERTY, J, FLANDERS, D. Q FLEISCHAKER, D. S	7906210063 7906260479 7906260550	50-358 G FOIA FOIA		GALLO, J. GALLO, R. M. GAMBLE, D. C.	7906200590 7906140628 7906200215	50-556 Q 50-387 G PRM	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEOURY	REPORT NUMBER
GAMMILL.W P	7906270270 7906220433	50-267 P 50-267 P		GILLELAND, J E GILLELAND, J E	7906210089 7906010135	50-370 Q 50-553 Q	
GANLEY.D E GARLEY.D E GARLEY.D E GARFIELD.D K GARNETT.H	7906260331 7906260336 7906260328 7906180363 7906010166	70-371 C 70-371 C 70-371 C PR 50-556 H		OILLELAND, J E OILLELAND, J E. OILLELAND, J E. OILLELAND, J E. OILLELAND, J E.	7906210046 7906070378 7906290503 7906200186 7906190533	50-390 @ 50-259 @ 50-320 @ 50-390 @ 50-391 @	
GARMERIR W DARNERIR W DARNERIE DARNERID J GARSHICKIA	7706050279 7706260031 7706160049 7706140176 7706210023	RES RES 50-312 P 50-313 P REGOD	7906030279 7906260031	OILLELAND, J E OILLELAND, J E, OILLELAND, J E OILLELAND, J E	7906020135 7906220185 7906140450 7906140364 7906210098	50-553 Q 50-438 G 50-257 Q 50-327 B 50-327 Q	
GARY'R J Gary'r J Gary'r J Gary'r J Gary'r J	7906190209 7906200567 7906200604 7906290603 7906120235	50-445 B 50-445 B 50-445 A 50-445 G 50-445 K		OILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E	7906140391 7906140411 7906080277 7906040204 7906140404	50-370 B 50-51B B 50-370 B 50-327 A 50-370 B	
GARY.R J GARY.R J GARY.R J GATES.R S GATES.G	7906120208 7906220200 7906220324 7906260007 7906030338	50-445 B 50-445 A 50-445 B 50-250 H 50-265 S		OILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E. OILLELAND, J E.	7906290715 7906140406 7906140452 7906060296 7906140420	50-259 0 50-553 8 50-370 8 50-438 A 50-438 8	
GAY, OH GEHLEN, PC GEHEN, PC GEHR, AC GEIGER, EL	7706240084 7906180779 7906210325 7906020030 7906200493	50-445 G NUREG NUREG 50-392 G REGGD	NUREG/CR-0825 NUREG/CR-0824	OILLELAND, J E	7906190491 7906010196 7906010282 7906140378 7906060293	50-518 8 50-390 K 50-390 A 50-390 8 50-327 A	
GENDLER.H W GEORGE.H H GERAS.T GERETY.H F GERETY.H F	7906010014 7906130290 7906120324 7906150328 7906210204	50-522 G 50-400 S 50-280 J 50-219 J 50-320 J		OILLELAND. J E OILLELAND. J E OILLELAND. J E OILLELAND. J E OILLELAND. J E	7906080275 7906080284 7906120398 7906130330 7906080261	50-327 8 50-390 0 50-296 P 50-390 8 50-327 F	
GERDB, T GERTZIB M GERUSKY, T M. GETTY, B C GEYDDN, J L	7906120331 7906200429 7906190482 7906150290 7906110097	50-280 J 50-320 R 50-320 H 50-133 R WASTE MQT		GILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E GILLELAND, J E	7906130221 7906200342 7906200438 7906190301 7906200433	50-438 8 50-327 8 50-327 8 50-257 P 50-390 8	
CIBBONS, T D. CIBBON, T CIBBS, M E CIBBS, M E CIBBS, M E	7904050140 7906060145 7906020253 7906020254 7906290810	50-416 Q FOIA 50-556 Q 50-556 Q 50-255 Q		OILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E OILLELAND, J E	7906190381 7906200382 7906220271 7906220384 7906250279	50-553 8 50-327 8 50-390 8 50-390 8 50-438 8	
OIBBS.M E OIBBON, C I. OIBBON, A OIBBON, A OIBBON, O, T.	7906260490 7906260613 7906210002 7906200431 7906200421	50-356 Q RES 50-320 P 50-320 P 50-320 P	7906260613	OILLELAND, J E	7906220369 7906250269 7906210195 7906220245 7906260224	50-257 R 50-227 B 50-257 P 50-353 A 50-553 A	
GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F GIBSON, A F	7906200160 7906070076 7906140634 7906180680 7906070058	50-280 G 50-280 G 50-348 G 50-280 G 50-324 G		GILLELAND, J.E GILLELAND, J.E GILLELAND, J.E GILLELAND, J.E. GILLELAND, J.E.	7906270218 7906270224 7906260463 7906280094 7906280113	50-390 8 50-327 8 50-327 A 50-327 Q 50-439 8	
OIBSCN, A F. OIBSCN, A F. OIBSCN, A F. OIFFORD, H C OIFFORD, H C.	7906200617 7906210422 7906260501 7906010065 7906010063	50-281 G 50-338 G 50-250 G 70-2684 C 70-2684 C		OILLELAND, J E OILLELAND, J E, OILLESPIE, F P OILLESPIE, F P OILLESPIE, F P	7906290294 7906290392 7906190594 7906080169 7906190554	50-327 B 50-390 G 70-27 C 50-538 G 70-824 C	
OILBERT, L D OILBERT, Y K OILDEMEISTER, D OILINSKY, V OILINSKY, V	7906250051 7906150471 7906260007 7906060102 7906060109	50-498 G XPORTLIC 50-250 H FOIA 50-334 P		OILLESPIE,F OILMAN,L OILMAN,M S. OIRARD,E H OIRARD,E,H	7906260314 7906220232 7906030045 7906210037 7906210291	70-27 C 50-320 P 50-358 Q 50-390 Q 50-390 Q	
Offinaka' Offinaka' Offinaka' Offinaka' Offinaka' Offinaka'	7906060127 7906060134 7906180384 7906190044 7906020176	50-334 P FOIA 10CFR 10CFR 10CFR		GLENN, J E GLENN, J E, GODDARD, R J GODDARD, R, J GODDARD, R J	7906290186 7906290410 7903210375 7906210359 7906210337	50-320 P 50-320 P 50-295 Q 50-237 Q 50-237 Q	
OILINSKY, V. OILINSKY, V OILINSKY, V. OILINSKY, V.	7906040017 7906070098 7906180369 7906140107 7906200305	10CFR 10CFR 10CFR 10CFR 10CFR		ODDY, A ODEDE, M R ODLDBERG, H R ODLDBERG, S C ODLDBERG, S C	7904050205 7904070420 7904180244 7903210437 7903210424	70-364 C PR GA999 50-338 Q 50-520 Q	٨
OILINSKY, V OILINSKY, V OILINSKY, V OILINSKY, V	7706020225 7706180391 7706180708 7706180724 7706140101	10GFR 10GFR 10GFR 10GFR 10GFR		ODLDBERG.B.C ODLDBERG.J.R ODLDBERG.J.R ODLDBERG.J.R GOLDBERG.J.R	7906010161 7906290613 7905110359 7906070347 7906180676	50-338 G 50-295 G 50-592 A 50-592 G PRGJ	
OILINSKY, V OILINSKY, V OILINSKY, V OILINSKY, V, OILLETT, W T	7906110114 7906210079 7906110205 7906230156 7906190243	50-320 T 10CFR 50-269 T 10CFR 50-316 R		OOLDBERG, J.R. OOLDBERG, J.R. OOLDBKITH, R. OOLLER, K.R. OOLLER, K.R.	7904080118 7904070037 7904210047 7904070198 7903200100	PRQJ PROJ 50-320 P FOIA GRO	
GILLETT, W T. GILLELAND, J E GILLELAND, J. E	7906190296 7906050422 7906040375	50-315 R 70-2443 C 50-327 G		GOODE, W W GOODHOPE, A C GOODHOPE, A. C.	7906130211 7906040147 7906260348	50-320 C 50-347 G 50-471 T	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
COODSTEIN, B J	7906080085 7906150433	50-352 G 71-294 C		GREGORY, M V	7906180762 7906180770	NUREO NUREO	NUREG/CR-0713 NUREG/CR-0714
6000HIN, C 6000HIN, C 6000HIN, C 6000HIN, C	790&150440 790&040181 790&270005 790&030349 790&060281	71~294 C 50~344 S 50~320 Q 50~344 P 50~344 Q		GRETHIR GREYIA E GREYIR GREYIR GRIDLEYIR L	7904070337 7906110057 7906260504 7906260511 7906150253	50-250 H WASTE MQT 50-596 Q 50-596 G TOPREP	
GOODWIN, C GOODWIN, C GOPPEL, M GOPPEL, M GORDON, D	7906220344 7906260466 7906070132 7906200293 7906120005	50-344 P 50-344 E SECY KPORTLIC 50-320 H		GRIDLEY.R L GRIDLEY.R L GRIER.B H GRIER.B H GRIER.B H	7906150344 7906260415 7906040058 7906130469 7906180383	TDPREP TOPREP 50-443 G 50-320 H 50-412 G	
GORDON, Q K GORE, J W GORSICK, L V GOBSICK, L V	7906040218 7906070079 7906130194 7812050284 7904020240	50-10 P REGOD PR 50-437 A WASTE MOT	NEDC-24159	GRIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	7904180389 7904180394 7904180397 7904180400 7904180405	50-363 Q 50-322 Q 50-423 Q 50-410 Q 50-352 Q	
GOSSICK, L V GOSSICK, L V GOSSICK, L V	7903230294 7904040130 7906210207 7906210124 7906010281	OR <i>0</i> FOIA 50-320 P 50-320 P 50-596 D		ORIER, B H ORIER, B H ORIER, B H GRIER, B H GRIER, B H	7904180407 7906180413 7906180416 7906180417 7906110006	50-387 G 50-311 G 50-443 G 50-485 G 50-293 G	
GOSSICK.L V GOSSICK.L V GOSSICK.L V GOSSICK.L V	7906210188 7906210194 7906210191 7906070234 7906050166	50-320 P 50-320 P 50-320 P 50-320 P 50-402 U		ORIER, BH ORIER, BH ORIER, BH ORIER, BH ORIER, BH	7906110007 7906110009 7906110010 7906110011 7906110012	50-317 Q 50-3 Q 50-213 Q 50-334 Q 50-412 Q	
ODSSICK.L V GDSSICK.L V GDSSICK.L V GDSSICK.L V	7704080005 7704240107 7704240341 7704240382 7704240382	50-10 U 50-437 U 50-269 U PR 50-250 U		GRIER, BH GRIER, BH GRIER, BH GRIER, BH	7906110013 7906110014 7906110015 7906110016 7906110019	50-363 G 50-217 G 50-322 G 50-287 G 50-245 G	
GOSSICK, L V GOSSICK, L V GOSSICK, L V GOUDE, M J	7906220136 7906270245 7906290271 7906290228 7906020144	FOIA 50~367 U 50~498 U 50~275 U 50~553 Q		ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	7904110021 7906110022 7906110024 7906110027 7906110029	50-410 Q 50-220 Q 50-286 Q 50-333 Q 50-277 Q	
GOUGE, M J GOUGE, M J GRADISON, B GRAHAM, W E GRAHAM, P D	7906180764 7906260247 7906250175 7906080177 7906030183	50-413 Q 50-566 Q 50-358 U 50-261 J 50-336 Q		GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906110031 7906110033 7906110037 7906110039 7906110041	50-352 Q 50-387 Q 50-311 Q 50-272 Q 50-443 Q	
GRAHAM, M J GRAHAM, M J, GRAHT, J E GRANT, J B	7906180018 7906030121 7906200490 7906010122 7906070417	50-324 Q 50-302 Q 50-250 Q 50-346 G PR		ORIER, B H ORIER, B H ORIER, B H ORIER, B H	7906110042 7906110045 7906110046 7906110048 7906110049	50-485 Q 50-244 Q 50-271 Q 50-307 Q 50-29 Q	
GRANT, J S ORANT, J S GRANT, J S GRANT, J S GRANT, J S	7906190555 7906140631 7906010308 7906020240 7906140249	50-344 Q FR 50-344 Q 50-346 Q 50-346 Q		GRIER, 11 H GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 8 H	7706020142 7906030006 7906130161 7906130162 7906130163	50-219 P 50-219 Q 50-293 Q 50-219 G 50-322 Q	
GRANT, J B GRANT, J B GRANT, J B GRANT, J B GRANT I B	7906060232 7906060291 7906250140 7906250119 7906230037	50-346 Q 50-346 Q 50-346 Q 50-346 Q 50-346 Q		GRIER. 8 H GRIER. 8 H GRIER. 8 H GRIER. 8 H. GRIER. 8 H	7906130164 7906130165 7906130167 7906130168 7906130170	50-245 G 50-220 Q 50-410 G 50-333 G 50-277 G	
				GRIER, B H GRIER, B H GRIER, B H, GRIER, B H GRIER, B H	7906130172 7906130173 7906130174 7906130177 7906140395	50-352 Q 50-387 Q 50-354 Q 50-271 Q 50-219 P	
				ORIER, B H ORIER, B H ORIER, B H ORIER, B H ORIER, B H	7906120149 7906120150 7906120152 7906120154 7906120156	50-293 G 50-317 G 50-3 G 50-213 G 50-412 G	
				GRIER, B. H ORIER, B. H GRIER, B. H GRIER, B. H GRIER, B. H	7906120158 7906120162 7906120163 7906120166 7906120169	50-334 Q 50-217 Q 50-363 Q 50-322 Q 50-320 Q	
				GRIER, B H GRIER, B H GRIER, B H GRIER, B, H GRIER, B, H	7906120171 7906120176 7906120177 7906120182 7906120185	50-307 G 50-245 G 50-220 G 50-410 G 50-333 G	
				GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906120187 7906120188 7906120189 7906120192 7906120194	50-286 G 50-277 G 50-352 G 50-387 G 50-311 G	
				GRIER, B H. GRIER, B H GRIER, B H	7906120197 7906120198 7906120201	50-272 Q 50-443 Q 50-244 Q	

AUTHOR	ACCESSION REMOVA	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
GRIER. B H GRIER. B H	7906120202 7906120203	50-485 G 50-271 G		GRIER, B. H GRIER, B. H GRIER, B. H	7906080037 7 <del>90</del> 6080039 7 <del>90</del> 6080041	50-134 G 70-135 C 70-1100 C	
ORIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906120206 7906130043 7906130268 7906110115 7906110116	50~29 Q 70~135 C 70~364 C 50~293 Q 50~317 Q		GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906080043 7906080045 7906080046 7906080050 7906080053	70-33 C 50-54 Q 70-820 C 70-371 C 50-22 Q	
GRIER.B.H GRIER.B H GRIER.B H GRIER.B H ORIER.B H	7906110118 7906110119 7906110120 7906110122 7906110135	50-3 Q 50-213 Q 50-334 Q 50-219 Q 50-289 Q		GRIER, 8 H GRIER, 8 H GRIER, 8 H GRIER, 8 H	7906080055 7906080059 7906080066 7906080049 7906080071	70-1143 C 50-293 Q 50-317 Q 50-3 Q 50-213 Q	
GRIER, 8 H GRIER, 9 H GRIER, 8 H GRIER, 8 H	7906110137 7906110138 7906110142 7906110143 7906110144	50-307 Q 50-245 Q 50-220 Q 50-333 Q 50-284 Q		GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906080079 7906080084 7906080087 7906080088 7906080091	50-334 @ 50-217 @ 50-320 @ 50-309 @ 50-245 @	
GRIER.B.H GRIER.BH GRIER.BH GRIER.BH GRIER.BH	7906110146 7906110148 7906110149 7906110150 7906110153	50-277 G 50-272 G 50-244 G 50-271 G 50-27 G		ORIER, B H GRIER, B H ORIER, B H GRIER, B H	7906080096 7906080097 7906080098 7906080102 7906080104	50-220 G 50-286 G 50-333 G 50-277 G 50-272 G	
GRIER.B H GRIER.B H GRIER.B H GRIER.B H	7906200307 7906260023 7906260026 7906260029 7906260030	50-320 G 50-193 G 50-184 G 50-47 G 50-170 G		ORIER, B H GRIER, B H GRIER, B. H GRIER, B. H ORIER, B H	7904080106 7904080111 7904080112 7906290432 7906220085	50-244 G 50-271 G 50-27 G 50-320 F 50-320 P	
GRIER, B H GRIER, B H GRIER, B H GRIER, B H GRIER, B H	7906260034 7906260035 7906260038 7906260040 7906260044	70-135 C 70-820 C 70-371 C 50-201 G 70-1143 C		ORIER, B H ORIER, B. H GRIFFITH, R ORIFFITH, J ORIFFIN, D H	7905220141 7905270011 7905150240 7905230043 7905010115	50-320 G 50-320 G 50-466 G 71-9079 G FOIA	
GRIER, B. H GRIER, B H GRIER, B H GRIER, B H, GRIER, B H	7906260046 7906260046 7906260051 7906260053 7906260059	50-54 9 70-1100 C 50-22 9 70-33 C 50-20 9		GRIFFIN.WR ORIFFITHB.R ORIMES.B ORIMES.B GRIMES.BK	7906260027 7906260368 7906180348 7906050180 7906020233	50-471 G 50-272 J GEN TEC IS 50-39 P 50-72 P	
ORIER, B H	7906260060 7906260062 7906260063 7906260063 7906260066	50-57 G 50-166 G 50-134 G 50-225 G 50-5 G		ORIHES, B K GRIMES, C I GRIMES, C I GROCE, R H GROCE, R H	7906260252 7906290192 7906190118 7906130119 7906050322	50-271 P GEN TEC IS GEN TEC IS 50-309 G 50-309 P	
GRIER, B K ORTER, B. H ORTER, B H ORTER, B H ORTER, B H	7906260068 7906260070 7906260075 7906260078 7906260080	50-208 G 50-223 G 50-97 G 50-77 G 50-199 G		ORGCE, R H GROCE, R H GROCE, R H GROCE, R H GROCE, R H	7906150162 7906220196 7906130114 7906140533 7906290096	50-309 P 50-309 P 50-271 Q 50-271 Q	
ORIER. BH ORIER. BH ORIER. BH ORIER. BH ORIER. BH	7906260091 7906260093 7906260098 7906260099 7906260101	50-293 G 50-317 G 50-3 G 50-219 G 50-334 G		GROCE, R H GROCE, R H GROCE, R H GROCE, R H	7906130106 7906050276 7906080271 7906220193 7906290408	50-27 G 50-29 P 50-29 P 50-27 P 50-29 P	
GRIER, B H ORIER, B H, ORIER, B H ORIER, B H ORIER, B H	7906260104 7906260112 7906260115 7906260117 7906260121	50-412 G 50-219 G 50-322 G 50-320 G 50-309 G		OROTENHUIS, M OROTENHUIS, M OROTENHUIS, M OROVE, W R ORUJAN, R A	7906250317 7906250056 7906290540 7906200430 7906010063	50-338 P 50-264 P 50-250 P 50-320 P 70-2684 C	
GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH GRIER, BH	7906260124 7906260128 7906260131 7906260132 7906260136	50-245 G 50-220 G 50-410 G 50-286 G 50-333 G		ORUSH, W. H ORUSKIN, B N GUHIKI M A GUMBLE, F H GUMBLE, F H	7906290278 7906210372 7906180619 7906040318 7906040349	RE8 PROJ BEGY 50-286 8 50-286 8	7906290278
ORIER, BH ORIER, BH ORIER, BH GRIER, BH GRIER, BH	7906260139 7906260145 7906260149 7906260151 7906260156	50-277 @ 80-387 @ 50-272 @ 50-311 @ 50-443 @					
GRIER, B H GRIER, B H GRIER, B. H GRIER, B. H, GRIER, B H	79062601 97 7906260160 7906260163 7906260164 7906210236	50-485 G 50-244 G 50-271 G 50-27 G 50-320 P					
GRIER, B H GRIER, B H ORIER, B H, ORIER, B H ORIER, B H	7706080011 7706080012 7706080014 7706080015 7706080018	50-170 Q 50-47 Q 50-184 Q 50-77 Q 50-208 Q					
ORIER, B H GRIER, B H GRIER, B H GRIER, B. H. GRIER, B H	7906080021 7906080022 7906080024 7906080027 7906080027	50-97 G 50-199 G 50-20 G 50-5 G 50-225 G					
GRIER. B. H. GRIER. B. H.	7906080031 7906080034	50-223 G 50-166 G					

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
HAIRSTON, H Q HALE, C J. HALE, C J	790625025 <i>2</i> 7906220222 7906290630	50-348 8 97979 97970		HAYNES, J Q HAYNES, J Q HAYNES, J Q	7906120286 7906220358 7906200345	50-361 A 50-206 P 50-206 B	
HALE,C J HALE,S M HALL,H J HALL,R T	7906230036 7906110078 7906169048 7906060095 7906290668	GA999 HASTE MOT REGOD FOIA NUREG	NUREG/CR-0356	Haynes, R C Haynes, R C, Haynes, R C Kaynes, R C Kaynes, R C	7906140215 7906220137 7906150079 7906260525 7906210347	50-361 Q 50-460 G 50-377 G 50-508 Q 50-361 Q	
HALL-R E HALL-R E HALL-R E HALL-R E HALL-R E	7906260022 7906260023 7906290685 7906210015 7906220328	50-409 F 50-277 F 50-277 P RES 50-317 F	7906260022 7906260023 7906210015	HAZLE, A J HAZLE, A J HEARNE, T HEATH, R A HEGNER, J	7906290803 7906290698 7906260403 7906180271 7906130427	PROJ PROJ 50-482 G 40-4492 G 50-320 P	
HALL, R E HALL, R E HALL, R E HALL, R E HALL, R E	7905280136 7905200524 7905220241 7905250051 7905210032	50-263 F 50-445 Q 50-382 Q 50-498 Q 50-482 Q		HEIDER, LH HEILE, WP HEILE, WP HEISHMAN, RF HEISHMAN, RF	7905290058 7906280031 7906290520 7906020011 7906260571	50-29 P 50-358 G 50-358 Q 50-254 G 50-346 G	
HALL:RE HALLENBECK.CA HALLER:N HAMMOND:EL HAMMOND:EL	7906210018 7906270210 7906210071 7906200248 7906250299	50-285 Q 50-148 J 50-320 P 50-331 R 50-331 8		HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF	7906250017 7906200482 7906050033 7906140586 7906140611	50-254 G 50-346 G 50-331 G 50-373 G 50-155 G	
HANAVER, S H	7904020192 7904210501 7904050314 7904160286 7904130347	50-301 G 50-500 A 50-437 A 50-327 E 50-327 A		HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF, HEISHMAN, RF HEISHMAN, RF	7906250128 7906250147 7906250176 7906260309 7906260321	50-409 Q 50-10 Q 50-255 Q 50-409 Q 50-282 Q	
HANAUER, B H HANAUER, B H HANAUER, S. H HANCOCK, D. HANES, T B	7904180077 7906200076 7906060008 7906110079 7906220455	50-382 A 50-320 P FOIA WASTE MGT 71-74 C		HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF HEISHMAN, RF	7906260945 7906260639 7906140603 7906260630 7906260196	50-282 Q 50-344 Q 50-315 Q 50-237 Q 50-407 Q	
N , NONNAH N , NONNAH N L , NONNAH N L , NONNAH D , NUNNAH	7904050147 7906250300 7906250201 7906260095 7906190246	50-324 P 50-293 Q 50-324 P 50-293 P 50-254 R		HEIGHMAN, R F HEIGHMAN, R F HEIGHMAN, R F HEIGHMAN, R F HEIGHMAN, R F	7904190550 7904230079 7906240034 7906260337 7906250109	50-346	
HANSELL, D HANSEN, D B. HANSON, W N HANSON, W A HARGETT, D J	7906270047 7906260476 7906270248 7906140570 7906260130	50-10 P 50-292 Q 71-89 C 50-483 Q CONTRACT		HEISHMAN, R F HELLER, B J HELLER, H J HELTEMES, C, J HELTEMES, C J.	7906290649 7906040340 7906040170 7906270001 7906010171	50-282 G 50-272 S 50-272 S 50-320 G 50-495 A	
HARGETT, D HARGETT, D HARGETT, D HARGETT, D HARLOH, & L	7906270102 7906180288 7906250336 7906260140 7906010148	CONTRACT CONTRACT CONTRACT CONTRACT 50-438 A		HELTEMES, C.J. HELTEMES, C.J. HELTEMES, C.J. HEMBY, E. O. HEMBY, E. O.	7906270044 7906270022 7906270189 7906140550 7906290769	50-320 0 50-320 0 50-320 P XPORTLIC XPORTLIC	
HARMON, D W HARMON, D W HARMEY, D B HARMEY, D G	7906180747 7906180761 7906180766 7906290372 7906190110	SECY SECY SECY GA999 XPORTLIC		HENDERBON, D, K HEKDRICK, H O HENDRICK, H O HENDRICK, J M HENDRICK, J M	7906230147 7906010090 7906010092 7906020041 7908290465	NUREO XPORTLIC XPORTLIC COMMISSION COMMISSION	
HARRIBON'S W Harrib'J L, Harrib'J.L Harrib'H E	7906060294 7906020129 7906190034 7906020037 7906110411	50-597 A 50-443 M 50-445 M 50-445 M 50-280 U		HENDRIE, J, H HENDRIE, J H HENDRIE, J H HENDRIE, J H HENDRIE, J H	7904040065 7906130423 7906150231 7905300552 7906180384	COMMISSION 50-320 P 50-320 U COMMISSION 10CFR	
Harrington, J. Harrington, J. Harrington, J. Harrington, J Harrington, J	7906080259 7906120279 7906120402 7906120379 7906190288	50-548 A 50-548 A 50-548 A 50-548 A		HENDRIE, J K HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J, M	7906190044 7906020176 7906040017 7906220129 7906220451	10CFR 10CFR 10CFR 50~320 H XPORTLIC	
HARRISON: F HARRISON: F HARRIS: J. R. HARRIS: P HART: O	7906260620 7906260616 7906010023 7906280048 7906150231	RES RES 50-566 Q REVIEW ORP 50-320 U	7906260620	HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M, HENDRIE, J M	7906070098 7906180369 7906140107 7906140111 7906200305	10CFR 10CFR 10CFR 10CFR 10CFR	
HARVEY, J. L HABELTINE, J. D, HABTINOS, W HATCH, O G. HAUGHNEY, C. T	7706110055 7906010134 7906010076 7906050104 7906220142	WASTE MOT 50-443 Q 50-344 Q 40-8698 C 50-201 H		HENDRIE: J. M HENDRIE: J. M. HENDRIE: J. M. HENDRIE: J. M. HENDRIE: J. M.	7906020225 7906180391 7906180708 7906180724 7906110319	10CFR 10CFR 10CFR 10CFR COMMISSION	
HAUGHNEY, C. J. HAUGHNEY, C. J HAUGHNEY, C. J HAUGHNEY, C. J HAUPT, C. A	7906230182 7906230049 7906230069 7906220471 7906230199	70-1193 C 50-201 P 50-201 P 50-201 H 50-437 A		HENDRIE: J. M HENDRIE: J M HENDRIE: J. M HENDRIE: J. M HENDRIE: J. M	7906110323 7906110332 7906110335 7906110336 7906110338	COMMISSION COMMISSION COMMISSION COMMISSION	
Haverkamp, D. R Hawkins, F. C Hayes, D. W. Hayes, D. W Hayes, D. W	7906200339 7906010336 7906010336 7906050057 7906260502	50-320 Q 50-440 Q 50-440 Q 50-454 Q 50-346 Q		HENDRIE, J. M HENDRIE, J. M HENDRIE, J. M. HENDRIE, J. M HENDRIE, J. M	7906110341 7906140101 7906110114 7906210079 7906230042	COMMISSION 10CFR 50-320 T 10CFR 50-592 G	
HAYNES, J Q. HAYNES, J Q.	7904060289 7904060271	20-509 b		HENDRIE, J. K HENDRIE, J. M	7906110205 7906110300	20-574 L 20-574 L	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
HENDRIE, J M HENDRIE, J M HENDRIE, J M	7906210197 7906110367 7906110378	50-320 U 50-280 U 50-280 U		HIND, J A HIND, J A. HIND, J A.	7906220119 7906220110 7906010079	50-305 Q 50-305 Q 50-294 Q	
Hendrie, J M. Hendrie, J M Hendrie, J M Hendrie, J H Hendrie, J M	7904110380 7904110382 7904110385 7904110387 7904110390	50-280 U 50-280 U 50-280 U 50-280 U 50-280 U		A C.ONIH A C.ONIH A C.ONIH A C.ONIH A C.ONIH	7906140591 7906140585 7906140200 7906140194 7906050120	50-2 0 50-2 0 50-264 0 50-264 0 50-266 0	
HEADRIE, J H	7906110394 7906110397 7906110400 7906280257 7906280264	COMMISSION COMMISSION COMMISSION		HINDAU A. HINDAU A. HINDAU A HINDAU A. HINDAU A.	7906080123 7906180045 7906080093 7906180039 7906260305	50-182 G 50-254 G 50-155 G 50-254 G 50-263 G	
HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M HENDRIE, J M	7906270163 7906280244 7906280251 7906270107 7906270116	COMMISSION COMMISSION COMMISSION COMMISSION		HIND, J A HIND, J A HIND, J A, HIND, J A, HIND, J A.	7906260312 7906200569 7906260209 7906260237 7906260203	50-263 Q 50-409 Q 50-87 Q 50-368 Q 50-87 Q	
HENDRIE, J M. HENDRIE, J M. HENDRIE, J M. HENDRIE, J M HENDRIE, J M	7906270123 7906270129 7906270133 7906270144 7906270150	COMMISSION COMMISSION COMMISSION COMMISSION		HINDERSTEIN, C. HINDERSTEIN, C HINDS, J A. HINDS, J A HINDS, J A	7904010082 7904010083 7904070100 7904070147 7904200575	50-466 0 50-466 0 FOIA FOIA 70-1308 C	
HENDRIE, J M HENIFIN, E E HENRY, T P HENRY, T P HENRY, B O	7706060087 7706050035 7706210441 7706220279 7706230124	FOIA 71-225 C 50-280 H 50-320 P RES 7	906230124	Hinde, J A Hinee, E Hinee, E Hinee, E Hinee, E	7906260231 7906040455 7906260108 7906140454 7906270694	50-348 0 50-341 0 50-341 0 50-341 0 50-341 0	
Henry, J C. Hensler, D A Hensley, K. D Hensley, K. D Herbein, J. O	7906130155 7906160005 7906250209 7906250309 7906040326	FR GA779 70-143 C 70-143 C 50-289 S		HINES, E HINES, E. HINKLEY, D G HIRATA, Y HIRATA, Y	7904280225 7906140601 7906140093 7906290264 7906290243	50-341 G 50-341 G 50-321 G GA999 GA999	
HERBEIN, JOHERBEIN, JO	7906040241 7906070237 7906270141 7906190531 7906010212	50-287 8 50-287 0 50-320 P 50-320 B 50-287 F		HIRBCHBERD, 8 M HITCHENS, D HOAGLAND, R O HOCK, D D HODDES, J. W	7906180572 7906220403 7906180779 7906220340 7906260514	71-220 C 50-346 B NUREO 50-267 J 70-27 C	NUREG/CR-0825
Herbeln, J o Herbeln, J o Herbeln, J. o Herbeln, J. o Herbeln, J o	7906010213 7906060264 7906120372 7906120373 7906150324	50-320 P 50-289 F 50-289 I 50-289 F 50-287 G	•	HODGES, W HODGES, W HOEFLING, R K HOEFLING, R K HOEFLING, R K.	7906110405 7906110438 7906070365 7903210425 7903210397	TOPREP TOPREP 50-322 H 50-322 O 50-322 O	
HERBEIN, J. O HERBEIN, J. O HERBEIN, J. O HERBEIN, J. O HERDT, A. R	7906260455 7906270234 7906280077 7906290608 7906010143	50-320 P 50-320 P 50-320 P 50-287 P 50-553 G		HOEFLING, R K HOEFLING, R. K HOEFLING, R K HOEFLING, R K HOEFLING, R, K	7906040141 7906040143 7906040361 7906070336 7906070336	70-2623 C 70-2623 C 50-322 O 70-2623 C 70-2623 C	
HERDT, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R. HERDT, A.R.	7906070302 7906020144 7906140645 7906040366 7906250146	50-471 Q 50-553 Q 50-438 Q 50-369 Q 50-281 Q		HOEFLING, R K HOEFLING, R K HOEFLING, R K HOEFLING, R K HOEFLING, R K	7906070367 7906070376 7906210116 7906210120 7906010319	70-2623 C 70-2623 C 70-2623 C 70-2623 C 70-2623 C	
HERDT, A R HERDT, A R HERDT, A R HERDT, A R	7906140654 7906180098 7906070162 7906210409 7906210078	50-416 G 50-424 G 50-327 G 50-281 G 50-416 G		Hoefling, R K Hoefling, R K Hoefling, R K Hoefling, R K Hoefling, R, K	7906010325 7906010331 7906010338 7906010339 7906010342	70-2623 C 70-2623 C 70-2623 C 70-2623 C 70-2623 C	
HERDY, A R HERDY, A R HERDY, A R HERDY, A R HERDY, A R	7906220230 7906180764 7906260201 7906260527 7906260247	50-348		Hoefling, R. K Hoffman, D. P Hoffman, D. P Hoffman, D. P Hoffman, D. P	7906010349 7906020160 7906290778 7906010239 7906080308	70-2623 C 50-255 G 50-255 G 50-255 S 50-255 S	
HERDTIA R. HERDTIA R HERINOIR F HERRIMANIC.P HERBCHIM M	7906220101 7906180731 7906220293 7906270028 7906270749	50-375 Q 50-327 Q 50-315 P 50-280 H XPORTLIC		HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P. HOFFMAN, D.P.	7906060236 7906110165 7906110140 7906120172 7906130002	50-255 P 50-255 P 50-255 P 50-255 P 50-255 P	
HERSEY, R HEBS, T HICKEY, C. R, HICKEY, C. R	7904080260 7904150420 7906240378 7906290083 7906290006	50-568 A 50-275 A 50-463 G NUREO N 50-320 R	VUREO-0468	HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P HOFFMAN, D. P.	7906150137 7906140375 7906190174 7906200172 7906220267	50-255 P 50-255 P 50-155 P 50-155 F 50-255 8	
Hickey, C. R. Hickle, B. J Higgins, J. C. Higgins, J. C. Higgins, J. C.	7906270110 7906120336 7906060197 7906140164 7906050183	50-320 P 50-285 R 50-320 8 50-29 G 50-334 G		HOFFMAN, D P HOFFMAN, D P HOLAHAN, G, M, HOLEMAN, G R HOLLAND, P	7906220190 7906260181 7906220157 7906140573 7906050248	50-255 P 50-255 P 50-320 P PRM 50-237 8	
HIGHFILL, K. L. HILLER, D HILL IARD, C. L. HINCKLEY, D. O HIND, J. A	7905160435 7903200326 7906220203 7906200388 7906080101	ORG 50-341 0 50-320 P 50-320 P 50-155 G		HOLLAND, P HOLMAN, J J HOLMBERG, R. L. HOLODY, D. J HOOD, D. S.	7906050269 7906140559 7906050351 7906210223 7906140623	50-237 8 50-369 A 71-316 C 50-320 P 50-329 A	
HEND, J. A. HIND, J. A.	7904020048 7904010078	50-254 0 50-274 0		HOOPER, F F	7906290626 7906060217	50-329 A 50-358 T	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
HOOPER, F F HOOPER, F F HOPPER, C M	7906060193 7906060211 7906130126	50-358 T 50-358 T 70-33 C		IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A	7906210349 7906210353 7906040053	50-271 P 50-271 P 50-260 P	1
HOPPERIC M HORN, H C HORN, H C HORN, A HORN, A	7906250310 7906070322 7906210372 7906290184 7906290071	70-33 C PROJ PROJ 50-312 G 50-312 Q		IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A IPPOLITO.T A	7906020171 7906140539 7906070386 7906070391 7906070404	50-331 P 50-331 P 50-324 P 50-324 P 50-324 P	
HORN, A HORN, A HORNBERGER, K D HORST, T H HOSEY, G M	7906290543 7906290120 7906140581 7906290481 7906140634	50-312 Q 50-302 Q PR NUREO 50-348 Q	NUREO/CR-0629	IPPOLITO, T A	7906250074 7906250079 7906250083 7906190134 7906190139	50-277 P 50-277 P 50-277 P 50-259 P 50-259 P	
HOVETON,R W HOWELL,8 H HOWELL,8 H HOWELL,8 H	7705220152 7705200021 7705050214 7705070253 7705150265	50-320 P 50-329 Q 50-329 K 50-329 A 50-329 A		IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A	7906190160 7906250088 7906250094 7906250103 7906250377	50~257 P 50~259 P 50~259 P 50~259 P 50~333 P	
HOWELL, S H HOWELL, S H HOWELL, J. C HOWELL, J. C	7906220353 7906220371 7906280161 7906080101 7906140200	50-329 B 50-329 B 50-329 A 50-155 G 50-264 G		IPPOLITO, Y A IPPOLITO, T A.	7906250380 7906260126 7906260133 7906260148 7906270665	50-333 P 50-278 P 50-278 P 50-277 P	
HOYLE, J C HOYLE, J C HOYLE, J C HOYLE, J C	7706020034 7706040220 7704230125 7706220105 7706180702	50-358 Q ACRS 50-592 A 50-320 D 50-320 D		IPPOLITO, T A IPPOLITO, T, A IPPOLITO, T A IPPOLITO, T A IPPOLITO, T A IVERSON, W	7906290670 7906290700 7906290227 7906290318 7906050115	50-277 P 50-277 P 50-320 A 50-320 A 50-522 G	
HOYT,W B. HOYT,W B. HSU,Y Y HUBACEK,W G HUDDLESTON,W D	7706050370 7706250220 7706250376 7706250051 7706270058	50-201 P 50-201 P NUREG 50-498 G 50-546 U	NUREO/CP-DODA	JABLON,R A JABLON,R A JABLONSKI,F J JABLONSKI,F J JACKIW,I N	790620119 7906200500 7906140570 7906260502 7906050040	50-445 M 50-445 M 50-483 Q 50-346 Q 50-331 Q	
HUEHMER, H HUFHAM, J W HUFHAM, J W HUFHAM, J W ,	7706170328 7706150463 7706250097 7706270104 7706260521	50-443 [ 50-390 0 50-320 P 50-416 0 50-302 Q		JACKSON: F D JACKSON: F D JACKSON: O JACKSON: T J JACKSON: L L	7906200059 7906020123 7906210302 7906210224 7906200617	40-4492 C 40-4492 C 70-1510 C 50-320 P 50-281 Q	
HUFMAN, J W HUGHES, B J HUGHES W J HULBERT, G C HUMPHREYS, L L	7906260074 7906160002 7906280261 7906270276 7906220036	70-1201 C 71-320 C COMMISSION XFORTLIC 50-458 S		JACKBON; L. L. JACKBON; R. E. JACKBON; R. E. JACKBON; R. E. JACKBON; R. E.	7906200402 7906130376 7906140565 7906180733 7906290636	50~320 P 50~320 P 50~400 A 50~553 A 50~423 A	
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	7904140010 7904210059 7904230048 7904230048 7904210344	94799 94799 94799 94799 94799		JACOBSON, N. H JACOBSON, A. JACOBSON, J. P JACOBSON, J. P JAMES, D. K.	7906050236 7906130182 7906210285 7906120408 7906120344	50-445 G PR 50-317 P 50-568 A 50-250 B	YAEC-1149
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M, HUNNICUTT, D M	7906060101 7906290282 7906290707 7906010114 7906290236	GA999 GA999 GA999 GA999 GA999		JAMEB, D.K. JAMACEK, R.F. JAMACEK, R.F JAMDEGTAN, O.V JAMECEK, R.F	7906120352 7906030369 7906050371 7906110087 7906040216	50-250 8 50-10 F 50-237 P HABTE HGT 50-10 P	
HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M HUNNICUTT, D M	7906070031 7906040059 7906230049 7906230035 7906290391	GA999 GA999 GA999 GA999		JANECEK, R F JANECEK, R F JANEN, S M JANKUS, B JANSEN, T	7906210190 7906270236 7906050403 7906130218 7906120385	50-237 P 50-10 P 50-498 Q 50-592 A 50-237 B	
A ADATEMUH A ADATEMUH A ADATEMUH A ADATEMUH A ADATEMUH	7906030317 7906140234 7906140239 7906120368 7906220362	50-304 8 50-282 R 50-282 R 50-304 S 50-282 S		JAPE, F. JAPE, F JAPE, F JAPE, F JAPE, F	7906270519 7906270087 7906270598 7906270456 7906200279	50-269 Q 50-269 Q 50-269 Q 50-269 Q	
HUNSTAD, A A FIUNT, M D HUNT, M D HUNT, M, D, HUNT, R, D, HUNTER, R S	7906270165 7906040365 7906180098 7906220230 7906260421	50-282 8 50-369 0 50-424 0 50-348 0 50-315 P	,	JAPE, F. JAPE, F JARVEB, S JEFFERB, J. JENCKES, T. A	7906270068 7906270406 7906070135 7906120349 7906130216	50-320 P 50-320 P FOIA 50-295 R PRM	
HUNTER, V H HUNTER, V H HUNTER, V, H HUNTINOTON, M HURNEY, T F	7906210086 7906210322 7906210406 7906050210 7906220349	GA979 GA979 GA979 80-387 G 50-346 M		JENGKES, T A JENKINS, O P JENKINS, O R, JENS, H H JENSEN, H L.	7906200498 7906200617 7906210422 7906050284 7906270148	REGOD 50-281 G 50-338 G 50-341 A 50-320 P	
HUTSON, T W HUTTON, P H INDYKE, C M INGRAM, F L, INGRAM, F	7906260525 7906210020 7906050413 7906220067 7906210281	50~508 G RES ,50~594 G 50~320 P	7906210020	JERNIOAN, E.P. JOHNSON, F. JOHNSON, F. JOHNSTON, J. H JOHNSTON, A.	7906260323 7906230151 7906140576 7906220068 7906200291	50-387 G 50-445 M 50-488 H 50-320 G 50-592 G	
INGRAM, F INGRAM, F IPPOLITO, T. A IPPOLITO, T A IPPOLITO, T A	7906220236 7906220276 7906250029 7906250032 7906250040	50-320 P 50-320 P 50-220 P 50-220 P		JOHNSON, B, JOHNSON, B JOHNSON, M, JOHNSON, M JOHNSON, N, P.	7906050445 7906050125 7906150427 7906150430 7906120282	50-454 G 50-454 A 71-291 C 71-291 C 50-309 G	
IPPOLITO, T A IPPOLITO, T. A.	7906210327 7906210345	50-271 P 50-271 P		JOHNSON, R G. JOHNSON, R G	7906130312 7906210237	20-585 J	

AUTHOR	ACCESSION REMUN	SUBJECT REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
H 9,008/80X, ORNESON, R H ORNESON, R H	7906070360 7906070362 7906180719	50-344	KAMMERER, C KAMMERER, C KAMMERER, C	7906280062 7906260465 7906260470	50-320 U 50-320 U 50-320 U	
JOHNSON, R. W. JOHNSON, R. W. JOHNSON, W. P. JOHNSON, M. C. JOHNSON, M. C.	7906180712 7906190473 7811090147 7906190152 7906220071	50-344 0 50-344 P 50-443 8 50-395 Q 50-395 Q	KAMMERER, C KAMMERER, C KANE, H F KAPILOFF, L, KAPLAN, A. L	7906050198 7906280237 7906270187 7906180259 7906280358	50-320 U 50-358 U 50-320 P 50-275 G 70-1113 C	
JOHNSON, K. C JOHNSON, K. C JOHNSON, H. C JOHNSON, H. P	7904220086 7904290380 7906220300 7906180034 7904200302	30-395 G 30-395 G 30-395 B REGOD REGOD	KAPLANIA L KAPLANIA L KAPPLEIA H KAPPLEIA H KAPPLEIA.H	7906230155 7906250312 7906050294 7906050291 7906050304	70-1113 C 70-1113 C 50-272 8 50-272 8 50-272 8	
JOHNSON, A. H. JOHNSON, J. R. JOHNSON, W. D. JOHNSON, W. D. JOHNSON, W.	7906050382 7906210226 7906150055 7906290534 7906290113	50-338	KAPPLE, A W KAPPLE, A W KAPPLE, A W KAPPLE, A W KARMAN, M	7906030340 7906110231 7906180593 7906200414 7906200625	50-272 8 50-272 8 50-272 8 50-272 8 50-456 9	
OHKBON' Y D OKKBON' Y K OKKBON' E H OHKBON' M D	7906290381 7906290147 7906260186 7906290391 7906260547	50-313	KARMAN, M KAROLY, D KASUN, D J KATHREN, R L KATZENSTEIN, R L	7906230124 7906230123 7906230197 7906140546 7906270266	50-454 0 50-346 0 Nureo Prm 50-280 H	NUREQ-0561
JOHNSON: A JOHNSON: A JOHNSON: A JOHNSON: A	7906290184 7906290071 7906200149 7906290120 7906290387	50-312 Q 50-312 Q 50-302 Q 50-302 Q	KAWULA:L Keane:B E Keane:B E Keaten:R W Kee:E J	7906260006 7906230075 7906230077 7906260329 7906290278	50-3 R 50-305 Q 50-305 Q 50-320 P RES	7906290278
JOHNSON, P JOHNSON, A JOHNSON, A JOHNSON, A	7906290153 7906290445 7906290489 7906290638 7906290471	50-312	Keene. J P Keeney, W P Keilhan, T J Keimig, R R	7906180414 7906180168 7906290833 7906200511 7906210241	40-8681 C 71-6717 C 50-219 Q 71-77 C 50-320 P	
JOHNSON, A, D, JOHNSON, A JOHNSON, A, V JOHNSON, H, V JOLLY, J	7906140205 7906250449 7906260543 7906210027 7906110274	50-312 Q 50-394 G 50-312 O REVIEW ORP 71-59 C	KEIMIGIR R KEIMIGIR R KEIMIGIR R KELHERIG N KELLERIG R	7706070244 7706200337 7706260509 7706210115 7706280001	50-334 Q 50-320 Q 50-244 Q 50-320 P RES	7906280001
Jonas, J. W. Jonas, J. W. Jones, T. Jones, R. L. Jones, R. P.	7506020175 7506020170 7506120419 7506260394 7506040427	71-162 C 71-162 C 50-320 H 50-382 Q 50-596 G	KELLEY, W D KELLEY, W D KELLEY, W D KELLEY, W D	7906210099 7906270627 7906180670 7906210322 7906230052	GA777 50-313 G GA779 GA777 GA777	
JONES, R. C JONES, R. H JONES, K. C JONES, C. L	7906230140 7906010292 7906010224 7906010226 7906220092	TOPREP BAW-10074A 70-754 C 71-902 C 71-302 C 50-920 P	KELLEY, H. D KELLEY, G. KELLEY, J. KELLOOO, R	7906190074 7906090182 7906270108 7906230103 7906050321	0A777 0A777 50-320 P SECY 50-285 S	SECY-78-120A
JONES, O, L, JONES, D E JONES, D C JONES, D C JONES, O, C	7906230146 7906070033 7906070040 7906230169 7906230173	NUREQ FOIA FOIA RCS 7904230149 RES 7904230173	KELLDOO, P. J KELLDOO, P. J KELLY, J. L. KELMON, R. M KEMPER, R. M	7904200447 7906130052 7906080054 7906260032 7906210246	50-320 P 50-327 G 50-305 G 50-471 G TOPREP	SECY-A-79-31 WCAP-9529
JONES, E W JONES, C E, JONES, R J JOSTEN, J	7906140140 7906260568 7906030228 7906050048 7906140418	70-364 C 70-33 C 50-456 G NUREQ 50-275 B	KENDRICK, J R KENNA, W. B KENNA, W. B KENNA, W. B KENNA, W. B	7906040410 7906190547 7906190589 7906080157 7906210389	50-437	
JOOSTEN, J. K JORDAN, W. H JORDAN, W. JORGENSEN, B. L. JOYNER, J. H	7906270208 7906290069 7906290077 7906250183 7906050205	50-295 B 50-396 T 50-596 T 50-255 G 70-364 C	KENNA, W B KENNA, W B KENNA, W. B KENNA, W B KENNA, W B.	7906190218 7906070384 7906130042 7906210351 7906180183	50-348 Q 50-327 G 70-143 C 50-111 Q 50-335 G	
JOYNER, J. H. JOYNER, J. H. JOYNER, J. H. JULTAN, C. A. JULTAN, C.	7906140124 7906010041 7906140218 7906020191 7906180018	70-371 C 50-311 G 70-135 C 50-124 G 50-324 G	KENNA, W. B KENNA, W. B KENNA, W. B KENNA, W. B.	7906190215 7906190370 7906080155 7906190542 7906260512	50-346 Q 70-27 C 50-538 Q 70-824 C 70-27 C	
Julian, C. A Kahle, J. B. Kahle, J. B. Kalivianakib, N. Kalivianakib, N	7906070075 7906070323 7906200458 7906060240 7906220381	50-111 0 70-1201 C 50-320 P 50-254 E 50-265 E	KENNEDY, H KENNEY, D. KENNEDY, R. T KENNEDY, R. T KENNEDY, R. T	7706110316 7706130322 7706060103 7706060112 7706060122	TOPREP 50-599 C FOIA FOIA FOIA	NEDO-24612
Kalivianakis, n. Kalivianakis, n. Kalivianakis, n. Kalhan, g Kalhan, g	7906220359 7906270215 7906270202 7906120066 7906290704	50-245 8 50-245 8 50-254 8 50-213 0 50-220 0	KENNEDY, R T KENNEDY, R T KENNEDY, R T, KENNEDY, R T KENNEDY, R, T	7906070086 790607008B 7906070092 7906070093 7906070064	COMMISSION COMMISSION COMMISSION COMMISSION	
KAMERER, D. J KAMMERER, C KAMMERER, G. KAMMERER, G. KAMMERER, C.	7706180328 7706060176 7706060174 7706070003 7706060177	50-275 G 50-320 U 50-320 U 50-320 U FOIA	KENNEDY, R. T KENNEDY, R. T. KENNEDY, R. T. KENNEDY, R. T. KENNEDY, R. T.	7906070096 7906070097 7906070102 7906070106 7906070067	COMMISSION COMMISSION COMMISSION COMMISSION	
KAMMERER, C. Kammerer, C.	7906260593 7906070308	50-250 U 50-275 H	KENNEDY, R. T KENNEDY, R. T	7906070293 7906180384	COMMISSION 10CFR	

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUHUR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
KENNEDY, R T KENNEDY, R T KENNEDY, R T	7906190044 7906020176 7906040017	IOCFR IOCFR IOCFR		KEPPLER, J. O KEPPLER, J. G KEPPLER, J. G	7906190092 7906190094 7906190095	50-341 G 50-331 G 50-441 G	
KENNEDY, R T KENNEDY, R T KENNEDY, R, T KENNEDY, R T KENNEDY, R T	7906076098 7906070294 7906180369 7906140107 7906070289	10CFR COMMISSION 10CFR 10CFR COMMISSION		KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7904190094 7904190098 7904190099 7904190101 7904190102	50-367 Q 50-484 Q 50-263 Q 50-546 Q 50-346 Q	
KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T	7906020225 7906070107 7906180708 7906180724 7906070078	19CFR COMMISSION 19CFR 19CFR COMMISSION		KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O,	7906170104 7906190106 7906190108 7906230097 7906230098	50-493 Q 50-266 G 50-305 Q 50-123 Q 50-186 G	
KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T	7906070084 7906070070 7906070074 7906070082 7906140101	COMMISSION COMMISSION COMMISSION COMMISSION		KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7906190229 7906200523 7906200235 7906200239 7906200245	50-358 8 50-344 F 50-409 P 50-10 P 50-305 P	
KENNEDY, R T KENNEDY, R T KENNEDY, R T KENNEDY, R T	7706110114 7906210079 7906110205 7906230156 7906260082	50-320 T 10CFR 50-267 T 10CFR 50-320 U		KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	7906200250 7906200443 7906200451 7906200460 7906200533	50-331 P 50-346 P 50-263 P 50-315 P 70-1308 C	
KENNEKE, A KENNY, P J KENTCHEN, E Q KENTCHEN, E Q	7904210256 7906260005 7906080136 7906140441 7906290206	50-269 0 50-471 0 50-497 0 70-2623 0 50-320 0		KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7906200538 7906200543 7906210134 7906210140 7906210324	70-36 C 40-3392 C 50-135 P 50-327 A 50-266 P	
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	7904230128 7904130455 7906070018 7904230115 7904240634	50-346 Q 50-320 P 50-263 Q 50-346 Q 50-346 Q		KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7706080126 7706080131 7706080132 7706080134 7706080137	70-8 C 40-3392 C 70-36 C 50-264 G 70-1308 C	
KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	7906130138 7906120083 7906120093 7906120097 7906120098	50-263 0 50-10 0 50-358 0 50-440 0 50-155 0		Keppler. J o Keppler. J o Keppler. J, o Keppler. J, o Keppler. J, o	7904080140 7904080142 7904080147 7904080170 7904080172	70-1487 C 70-925 C 50-87 Q 50-116 0 50-294 0	
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7906120100 7906120104 7906120106 7906120109 7906120111	50-329 Q 50-409 Q 50-341 Q 50-331 Q 50-461 Q		KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	7706080174 7906080176 7906080178 7906080181 7906080184	50-150 Q 50-182 Q 70-152 C 50-151 Q 50-2 Q	
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O	7906120114 7906120118 7906120119 7906120121 7906120123	50-315 Q 50-367 Q 50-484 Q 50-263 Q 50-546 Q		KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O KEPPLER, J O	7906080184 7906080188 7906080191 7906080196 7906080200	50-123	
KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O KEPPLER.J O.	7906120125 7906120127 7906120132 7906120134 7906020138	50-346 G 50-483 G 50-266 G 50-305 G 50-373 A		KEPPLER, J G REPPLER, J G. KEPPLER, J G. KEPPLER, J G KEPPLER, J G.	7904080201 7904080202 7904080203 7904080204 7904080205	50-409 Q 50-331 Q 50-315 Q 50-263 Q 50-346 Q	
KEPPLER, J Q, KEPPLER, J Q, KEPPLER, J Q, KEPPLER, J Q	7906110094 7906110096 7906110098 7906110101	50-315 G 50-155 G 50-409 G 50-10 G		KEPPLER, J O. KEPPLER, J O. KEPPLER, J O. KEPPLER, J O.	7904080207 7904080209 7904200517 7904130079 7904130082	50-266 q 50-305 q 50-263 P 50-315 q 50-10 q	
				REPPLER, J O PPLER, J O PPLER, J O PPLER, J O PPLER, J O	790613008B 7906130090 7906130093 7906130094 7906130097	50-358 G 50-440 G 50-327 G 50-155 G 50-407 G	
				PPLER, J. O PPLER, J O PPLER, J O PPLER, J O PPLER, J. O	7906130098 7906130100 7906130103 7906130104 7906130109	50-341	
				PLER, J. G PLER, J G. PLER, J G. PLER, J G	7706130111 7906130113 7906130116 7906130116 7906130120	50-484 Q 50-546 Q 50-346 Q 50-483 Q 50-266 Q	
				PLER, J O	7906130121 7906260049 7906200075 7906200080 7906200099	50-305 Q 50-331 Q ORQ 50-10 Q 50-358 Q	
				PLER, J O. PLER, J O. PLER, J G. PLER, J, G. PLER, J, G.	7906200101 7906200103 7906200109 7906200116 7906200118	50-440 Q 50-155 Q 50-929 Q 50-409 Q 50-341 Q	
				PLER, J Q. PLER, J Q	7906200121 7906200125	50-331 0 50-441 0	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	RÉPORT NUMBER
KEPPLER, J Q KEPPLER, J Q KEPPLER, J Q	7906200126 7906200128 7906200131	50-315 G 50-367 G 50-263 G	1	KONKLIN, J E KONNERTH, C J KOPPELMAN, R	7906250141 7906120276 7906070240	50-454 Q 50-54 P 50-127 P	
KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER. J O KEPPLER, J O	7906200132 7906200134 7906200137 7906200139 7906200142	50-484 Q 50-546 Q 50-346 Q 50-483 Q 50-266 Q		KOPPELMAN, R KORCHYNSKY, M KORNBLITH, L, KOBIK, L B KOBIK, L B	7906190251 7906190432 7906070011 7906030131 7906220066	50-127 P 50-249 B 50-449 T 50-358 0 50-358 0	
KEPPLER, J O KEPPLER, J O KERM, N KERR, J KERR, H	7906200143 7906290629 7906260542 7906290691 7906200448	50-305 Q 50-331 Q ACRS 50-599 Q 50-320 P		KOSIK,L S KOTTAN,J,J, KOTTON,J J KOTON,J J KOYACH,B L	7906220070 7906220304 7906200499 7906290842 7906280143	50-358 0 50-320 P 50-320 P 50-333 0 50-320 P	NUCQN 616616/01
KERR.W O KERR.O W KERR.O K KERR.IGAN.J KERR.IGAN.S	7906200453 7906290321 7906290363 7906260324 7906260343	50-320 P 50-320 P 50-320 P 50-320 P		KOVACH, J L KOVACH, F B KOVLOVRIH, O E KOWALHKI, J O KOWALHKI, J O	7906290457 7906020224 7906270135 7906050024 7906050020	50-320 P 71-77 C 50-280 H 71-36 C 71-36 C	
KETCHEN, E O XETCHEN, E O KETCHEN, E O KETCHEN, E O KETCHEN, E O	7906260278 7903210228 7903210231 7903210234 7903210237	70-2623 C 70-2623 C 70-2623 C 70-2623 C 70-2623 C		KRAFT, S KRAMER, D S, KRANER, J F, KRANER, J F, KRANISH, A	7906280125 7906210262 7906040125 7906040132 7906220259	50-320 P 50-320 U 71-110 C 71-110 C FOIA	
KETCHEN, E O KETCHEN, E O KETCHEN, E O KETCHEN, E O KETCHEN, E O	7904250218 7904010325 7904010338 7904010339 7904010342	70-2423 C 70-2623 C 70-2623 C 70-2623 C 70-2623 C		KRAUBS,R W KRAUCZAK,A T KRAUCZAK,A T KREIDER,H Q KRETZBCHMAR,W	7906270026 7906060226 7906140396 7906120164 7906270155	50-320 8 50-304 8 50-304 8 50-324 P 50-280 H	
XETCHEN.E O KETZLACH.N KETZLACH.N KETZLACH.N KETZLACH.N	7906010349 7906220030 7906220134 7906250143 7906260627	70-2623 C 70-1100 C 70-33 C 70-1201 C 70-33 C		KRISTOVICH, S KRISTOVICH, S KROES, R J. KROMMENHOEK, D J KROOT, I B	7906070327 7906010341 7906200344 7906210139 7906200592	50-275	
KETZLACH,N KEY,H J KEY,H J KIDD,M.S KIMBALL,J	7904290818 7904050040 7904130133 7904180355 7904230124	70-1201 C 50-331 G 50-331 G 50-338 G RES	7906230124	KROOT, I B KRUEGEL, R E KUBO, H KULKARNI, V KULYNYCH, O, E.	790627027B 7906040074 7906230105 7906110316 7906280182	50-338 0 71-319 C XPORTLIC TOPREP 50-320 P	NEDO-24612
KINNEY, H. KINNEY, H. KINNEY, H. KINNEY, H.	7906220189 7906220097 7906290118 7906260347 7906140608	50-320 P 50-320 P 50-320 P 70-371 C 70-820 C		KURTZ,R J KVAMMEN,B KYGER,J A LAATS,E.T. LAATS,E.T	7906210020 7906180588 7906050200 7906050086 7906290505	REB 71-301 C NUREQ NUREG REB	7906210020 NUREG/CR-0547 NUREG/CR-0786 7906290503
XINNEY, N N XINTIOH, A E KINTIOH, A E KINTIOH, A E,	7906140643 7906120247 7906120433 7906220342 7906260229	70-33 C 50-596 A 50-596 F 50-596 A 50-596 C		LAFLEUR, J D, LAGIENSKI, J S LAGOMARSIND, R J LAGRANGE, R G LAINAS, O	7906250110 7906050265 7906080199 7906250037 7906040400	50-320 P 50-318 S 50-275 U GEN TEC IS 50-317 P	
KINTKER, L. L KIRK, H F KIRK, I A. KIRKPATRICK, D KISTER, H B	7906010316 7906200275 7906210081 7906130362 7906290833	50-341 A 70-371 C 50-320 P 50-320 P 50-217 Q		Lainab, o Lainab, o Lainab, o Lampley, C. M. Lame, C. D.	7906120094 7906290642 7906070077 7906280011 7906190085	50-282 P 50-280 P 50-329 A NUREO 50-596 G	NUREG/CR-0781
KISTER, H B KLEINSORGE, W. P KLINE, J KLINGER, G. R KLINK, P H	7906120251 7906150039 7906040111 7906270260 7906290178	50-309 Q 50-438 Q 50-275 H 50-334 P RES	7906290178	LANGER, B. LANGER, R. R. LANNING, D. D. LANNING, W. D. LARK, R. E.	7906030083 7906200600 7906020097 7906070004 7906250212	FOIA PRM NUREO 50-320 P 70-2623 C	NUREO/CR-0220
KNIESER, 9 W. KNICHTON, 0, W. KNICHTON, 0, K KNICHTON, 0, KNCP, R. C	7906190046 7906120002 7906260297 7906260304 7906040411	0A999 50-320 P 50-320 0 50-320 0 50-329 0		LARKINS, J LARKINS, J T LARUE, H A LASHER, L E LASHER, D R.	7906280003 7906210121 7906140023 7906060143 7904100243	50-320 P 50-320 P 40-8032 C TOPREP 50-327 A	NEDO-21471-2
KNOP,R C KNOP,R,C KNOP,R C KNOP,R C KNOP,R,C,	7906050228 7906250141 7906250155 7906050238 7906140570	50-456 Q 50-454 Q 50-329 Q 50-373 Q 50-483 Q		Lahrence, M Lahrence, M, Lahroski, 8, Lahroski, 8, Lahroski, 8	7906070164 7906070171 7906260569 7906150214 7906150234	71-322 C 71-322 C ACRB 50-320 T 50-320 T	
KNOTT, K, KNOTTS, J. B. KNOTTS, J. B. KNOTTS, J. B. KNOTTS, J. B.	7906070297 7906060030 7906020255 7906190043 7906020250	COMMISSION 50-445 M 50-445 M 50-445 M		LAZARUS, N LAZO, R. M. LAZO, R. M LAZO, R. M. LAZO, R. M.	7906260010 7906270081 7906110430 7906040057 7906180803	70-2000 C 50-295 9 BECY 50-592 9 50-592 0	8ECY-A-79-30
KNOTTE, J B. KNOTTE, J B. KNOTTE, J. B. KNOX, J. KNOESTER, O. L.	7906200576 7906040122 7906290596 7906040035 7906200546	50-445 M 50-445 M 50-445 M 50-373 F 50-482 G		LAZO,R M. LAZO,R.M LAZZARI.A. LEABE,R.S. LEATHERS,F H.	7906290622 7906280260 7906260500 7906190296 7906060075	70-1308 C 50-471 Q 50-320 H 50-315 R QAY79	
KOESTER, O.L. KOESTER, O.L. KOESTER, O.L. KOESTER, O.L. KOESTER, O.L.	7906050064 7906050090 7906130033 7906140172 7906210300	50-482 Q 50-482 Q 50-482 Q 50-482 Q 50-482 Q		LEAVITT, J B. LEBLANG, L. P. LEBO, C. D. LEBO, C. D. LEBO, C. D.	7906080173 7906140638 7906160032 7906150152 7906190176	50-255 J 50-510 Q CONTRACT CONTRACT	
KOESTER. G. L. KOMES, J. M.	7906110159 7906110267	50-482 A 50-482 A		Lee, B. W.	7906260629 7906130143	PR 50-341 Q	

AUTHOR	ACCESSION NUMBER	SUBJECT REPORT NUMBER		ROHYUA	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
LEE,E # LEE,J LEE.T	7906260583 7906130457 7906150047	50-373 Q 50-320 P 70-143 C	LE	EWIS.R C EWIS.R C EWIS.R C	7906190198 7906200534 7906050107	50-280 G 50-324 G 50-302 G	
LEECH.K LEED.R M LEEDS.J V LEEDS.J V	7906270205 790601001 4 7906020229 7903140067 7903140059	50-254 S 50-522 0 50-522 G 50-400 T 50-400 T	LE LE L¢	EMIB, R C EMIS, R C EMIS, R C EMIS, R C EWIS, R C	7906200350 7906200487 7906140150 7906210299 7906250361	50-348 G 50-250 G 50-348 G 50-327 G 50-324 G	
LEEDS, J V LEEPER, C S LEFEVER, D E LEFEVRE, H E LEGROW, P A	7903140116 7906070338 7906290091 7906290637 7906220116	50-400 T 50-395 M 30-320 0 50-566 A 50-471 G	LE Le Le	EMIS.R C EMIS.R C EMIS.R C EMIS.R C EMIS.R C	7906250367 7906260611 7906250372 7906050074 7906200270	50-324 Q 50-250 Q 50-335 Q 50-366 Q 50-269 Q	
LEMANOWICA, I LEMANOWICA, I LEMPOES, T E LEMPOES, T E LEMPOES, T E	7706190130 7706190013 7706220405 7706220412 7706220424	90-387 0 50-387 0 50-220 S 50-220 S 50-220 S	LE LE LE	EWIS.R C EWIS.R C EWIS.R C EWIS.R C EWIS.R C	7906180305 7906230002 7906030065 7906210399 7906180359	50-338 Q 50-335 Q 50-302 G 50-259 G 50-302 G	
LENABURG.S D LENAHAN, J J LENT, N F LEONARD, J D LEONARD, J D	7906180274 7906010314 7906260544 7906040222 7906040305	50-275 0 50-336 0 50-249 U 50-333 8 50-333 8	LE LE LE	EMIS.R C EMIS.R C EMIS.R C EMIS.R C EMIS.R C	7906080146 7906200522 7906190191 7906260602 7906070087	50-324 G 50-321 G 50-280 G 50-250 G 50-111 Q	
LEONARD. J D. LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D	7906040276 7906080095 7906290743 7906290830 7906080231	50-333 S 50-333 G 50-333 G 50-333 G 50-333 S	LI: LI: LI:	WIS.R C BRIZZI.F P BRIZZI.F P BRIZZI.F P BRIZZI.F P	7906070081 7906040336 7906040268 7906040275 7906060270	50-111 Q 50-272 8 50-272 8 50-272 8 50-272 P	
LEONARD.J D LEONARD.J D LEONARD.J D LEONARD.J D LEONARD.J D	7906120365 7906150273 7906180563 7906180474 7906180574	50-333 R 50-333 B 50-333 B 50-333 S	LII LII LII	BRIZZI,F P BRIZZI,F P BRIZZI,F P, BRIZZI,F P BRIZZI,E P	7904050283 7904050289 7904050301 7904050339 7904110224	50-272 8 50-272 8 50-272 8 50-272 8 50-272 8	
LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D LEONARD. J D	7906190271 7906190410 7906250274 7906250269 7906250275	50-333 8 50-333 8 50-333 8 50-333 8	L11 L11 L14	BRIZZI,F P BRIZZI,F P BRIZZI,F P CHTENBERGER,H CITRA,E	7904180585 7904190201 7904200407 7904240008 7904200319	50-272 8 50-272 P 50-272 8 70-1100 C 50-528 A	
LEGNARD, J D LESSOR, L C LESSOR, L C LESSOR, L C LESSOR, L C	7906260535 7906080251 7906080255 7906080253 7906080309	50-333	L1( L1)	CITRA,E A CITRA,E A CK,I DIAK,E G EBERMAN,J	7904200324 7904230190 7904270249 7904280001 7904230145	50-592 I 50-498 A 50-516 G RES 50-305 G	7704280001
LESSOR, L C LESSOR, L C LESSY, R LESSY, R P LESSY, R P,	7906080280 7906130294 7906020165 7906070034 7906190147	50-278 S 50-278 R 50-445 M 50-445 M 50-445 H	LI! LI! L!!	ENINGER, V KE, I M, T, H M, T H MROTH, D F	7906260010 7906040093 7906120353 7906120351 7906220145	70~2000 C 50~516 Q 50~224 R 50~224 R 50~320 F	
LESTYK, JA LEVIN, JA LEVIN, C LEVIN, C LEVIN, C	7906200607 7906070330 7906070290 7906290672 7906070288	PR 50-334 0 50-315 U 50-319 U 50-315 U	L11 L11 L11	NDBLAD,W J NDBLAD,W J NDER,T P NDER,F NDER,F	7906200481 7906220230 7906040185 7906140456 7906020198	50-514 R 50-514 A XPORTLIC 50-409 B 50-409 Q	
Levine. 8 Levine. 8 Levine. 8 Levine. 8	7906120136 7906180729 7906010337 7906260601 7906270063	RES 7906120136 RES 7906180729 RES 7906010337 NUREO SO-320 P	LII LII LII	NDER. F NDER. F NDER. F NDER. F NDER. F	7904020189 7904200573 7904140148 7904120341 7904040245	50~409 Q 50~409 Q 50~409 Q 50~409 P 50~409 B	
LEVY, PF LEWALD, GH LEWIS, PF LEWIS, J LEWIS, EE	7906290185 7906290165 7906270082 7906110099 7906180757	50-471 0 50-471 0 50-280 H WASTE MOT NUREO NUREO/CR-0823	L.11 L.11 L.11	NDER.F NDER.F NDER.F, NDER.F NDER.F	7906120417 7906150217 7906150225 7906150310 7906270192	50-409 R 50-409 P 50-409 F 50-409 B 50-409 B	
Lehis, s Lehis, s Lehis, s Lehis, s R Lehis, s	7906200219 7906180810 7906130324 7906260533 7906290323	PR 50-596 0 50-269 8 50-270 8 50-269 8	LII LII LII	NDER.F NDNER.T.P NDNER.T.P NDNER.T.P NDNER.T.P	7906260212 7906070264 7906050157 7906070125 7906070155	50-409 P XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
Lemis, 8 h Lemis, 8 h Lemis, 8 h Lemis, 8 h.	7703210244 7903210406 7906010070 7906070032 7906230180	50-263 0 50-549 0 50-549 0 50-263 0 50-261 0	L11 L11 L11	NDNER, T P NDNER, T P, NDNER, T P NEHAN, J J NEHAN, J J	7906070166 7906160043 7906050167 7906150140 7906010295	XPORTLIC XPORTLIC XPORTLIC 40-299 C 40-8452 C	
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	7906240259 7906230008 7906200311 7906180710 7906020183	50-249 0 50-335 0 50-338 0 50-259 0 50-124 0	L]] L]] L]]	NEHAN, J, J NEHAN, J J PINSKI, W C PINSKI, W C PINSKI, R	7906150262 7906290799 7906270007 7906130199 7906260318	40-8452 C 40-4492 C 50-572 A 50-320 D 50-320 P	
LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C LEWIS.R C	7906050194 7906180372 7906150050 7906180013 7906050376	50-346	են եր եր	PPINCOTT.E P STER.D B TTLE.L W TTLE.L.W TTLE.L.W	7906180742 / 7906010129 7906260554 7906260558 7906290560	NUREO 70-1200 C 50-295 T 50-295 T 30-295 T	NUREQ/CR-0551
LEWIS, R. C LEWIS, R. C	7906180315 7906140085	50-338 Q 50-321 Q		TTLE, L W TTLE, L W	7906290047 7906290082	50-295 T 50-295 T	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
LITTLE, II B LIV, L LIV, L	7906250138 7906020232 7906260606	50-409 Q 50-331 Q 50-331 Q		HACDONALD, C E HACDONALD, C E HACDONALD, C E HACDONALD, C E	7906140659 7906180153 7906210412 7906070068	71-310 C 71-4949 C 71-325 C 71-3 C	
CIU, L CIU, L CIU, L LIVERHORE, H H LIVERHORE, D H	7906010204 7906120272 7906150199 7906260589 7906260624	50-331 P 50-331 P 50-331 F 50-409 Q 50-282 Q		MACDONALD, C E	7906150469 7906150476 7906180043 7906180052 7906190559	71-6574 C 71-9044 C 71-5364 C 71-5364 C 71-6717 C	
LLGYD. R D LGOAN, E LGNO, R L LGNO, F J. LGPATA, J R.	7906200336 7906210139 7906180608 7906180232 7906140474	50-346 J 50-320 P 50-320 O 50-335 G ORO		MACDONALD, C E	7906190563 7906200123 7906200133 7906220211 7906180682	71-6375 C 71-6400 C 71-6058 C 71-258 C 71-195 C	
LOPEZ, I LOPEZ, A LOSS, F J LOMERRE, R. W LOY, R W	7906180772 7906110109 7906140127 7906030082 7906070414	50-466 0 WASTE MOT RES 50-466 0 PR	7906140127	MAGDONALD, C E. HAGDONALD, C E. HAGDONALD, C E HAGDONALD, C E HAGDONALD, C E	7906180793 7906200072 7906200074 7906200100 7906200104	71-275 G 71-5908 C 71-5908 C 71-6639 C 71-6601 C	
LOYALKA, B K LUBENAU, J. O LUEBBERB, T A LUEBBERB, T A LUNDBERG, R, E	7906020244 7906210100 7906280031 7906290520 7906110316	NUREO 50-320 P 50-358 0 50-358 0 TOPREP	NUREO/CR-0780 NEDO-24612	MACDONALD, C E	7906200108 7906200112 7906200129 7906220191 7906200066	71-240 C 71-240 C 71-9080 C 71-6375 C 71-137 C	
LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E LUNDVALL, A E	7906020199 7906120285 7906220058 7906140458 7906010247	50-317 Q 50-317 Q PR 50-317 Q 50-317 P	,	MACDONALD, C E	7906230009 7906230044 7906260258 7906290041 7906290053	71-4375 C 71-225 C 71-188 C 71-9010 C 71-9010 C	
LUNDVALL: A E LUNDVALL: A E LUNDVALL: A E, LUNDVALL: A E LUNDVALL: A E	7906040248 7906120265 7906150366 7906150368 7906220231	50-317 P 50-317 P 50-317 Q 50-317 Q 50-317 P		MACDONALD, C E	7906290735 7906270049 7906270050 7906210085 7906210087	71-9070 C 71-6387 C 71-6387 C 71-10 C 71-18 C	
LUNDVALL: A E LUNDVALL: A E LUTON: E. LUTON: E. LUTON: E	7906220315 7906280135 7906040145 7906040384 7906050175	50-317 P 50-317 P 50-295 0 50-133 0 50-502 0		MACDONALD, C E MACDONALD, C E MACDONALD, C E MACDONALD, C, E MACFARLAND, C R	7906210090 7906210092 7906290334 7906290734 7906070162	71-208 C 71-208 C 71-5805 C 71-5805 C 50-327 G	
LUTON, E LUTON, E LUTON, E LUTON, E	7906040041 7906060214 7906140117 7906060195 7906180726	50-471 G PROJ 50-471 T 50-471 T 50-471 T		MACKENZIE, V V MACVAUGH; R W MADDEN, W MADDEN, W MADDEN, W J	7906270253 7906070148 7906140140 7906210055 7906290403	50-392 Q 71-287 C 70-344 C 70-820 C 50-320 P	
LUTON, E LUTON, E LUTON, E LUTON, E	7906220109 7906180728 7906280434 7906260214 7906280104	50-471 T 50-471 T 50-471 O 50-295 O 50-471 O		MADEDA, T J MADEDA, T J MADEDA, T J MADEDA, T J MADISON, W R	7906080101 7906020054 7906140200 7906220119 7906180493	50-155 G 50-254 G 50-264 G 50-305 G 50-338 R	
LUTON, E LYNCH, D A HA, B H HACARTOR, J. D HACARTOR, J. D	7906220147 7905240422 7906250487 7906010140 7906040388	50-471 T 10CFR 50-201 P 50-272 G 50-272 G	UCRL-52975	Madben, O. L Madben, G. L Madben, O. L Madben, G. L Madben, O. L	7906210022 7906040156 7906150023 7906160132 7906010285	50-285 Q 50-313 Q 50-313 Q 50-267 Q 50-274 Q	
HACARTHUR, T.C. HACDGUGALL, R E HACDDUGALL, E A HACDGNALD, G, E HACDGNALD, G E	7906190463 7906260022 7906260023 7906190488 7906190493	50-390 Q 50-409 F 50-277 F 71-47 C 71-47 C	7906260022 7906260023	Madsen, o L Madsen, o L, Madsen, g. L Madsen, g. L, Madsen, g. L,	7906010291 7906210010 7906260186 7906260180 7906040149	50-274 G 50-285 G 50-298 G 50-298 G 50-313 G	
HACDONALD, C E HACDONALD, C, E HACDONALD, C, E HACDONALD, C E HACDONALD, C E	7906050390 7906070014 7906070017 7906070020 7906140015	71-9126 C 71-9128 C 71-9128 C 71-9128 C 71-4949 C		Madsen, G. L. Madsen, G. L. Madsen, G. L. Madsen, G. L. Madsen, G. L.	7906180142 7906180145 7906180146 7906180148 7906270038	50-313 8 50-298 5 50-285 8 50-267 8 50-320 9	
HACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E. MACDONALD, C. E.	7906140019 7906190479 7906010329 7906050411 7906070039	71-9117 C 71-47 C 71-5942 C 71-279 C 71-96 C		Madsen, G. L Madsen, G. L. Madsen, G. L Madsen, G. L Madsen, G. L Madsen, G. L	7906180196 7906180198 7906180192 7906180202 7906250041	50-298 8 50-285 8 50-313 8 50-267 8 50-267 H	
HACDONALD, C. E. HACDONALD, C. E. HACDONALD, C. E. HACDONALD, C. E. HACDONALD, C. E.	7906080083 7906180687 7906010093 7906010093 7906010097	71-190 C 71-195 C 71-90 C 71-90 C 71-56 C		Madeen, G L Madeen, G L Madeen, O L Madeen, G L Madeen, O L	7906250095 7906260530 7906250115 7906180291 7906180295	50-348	
HACDONALD, C. E HACDONALD, C. E HACDONALD, C. E HACDONALD, C. E HACDONALD, C. E.	7906010101 7906050027 7906050029 7906180798 7906010143	71-36 C 71-202 C 71-202 C 71-275 C 71-207 C		MADSEN, O.L. MADSEN, O.L. MAISE, O. MAJOR, R.K. MAJOR, R.K.	7906180297 7906180301 7906010191 7906180622 7906260103		
HACDONALD: C. E. HACDONALD: C. E HACDONALD: C. E HACDONALD: C. E HACDONALD: C. E.	7906010147 7906010149 7906010154 7906010187 7906070253	71-207 C 71-174 C 71-174 C 71-115 C 71-3926 C		MAJOR, R. K MALARO, J. C. MALLARO, J. C MALLAY, J. F. MALLONE, O. G.	7904130264 7904110030 7904110193 7904290298 7904240333	50-320 O Waste Hot Waste Hot 50-320 A 50-463 O	
HACDONALD, C. €.	7906070260	71-5926 C	•				

AUTHOR	ACCESSION NUMBER	GUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REFORT NUMBER
MALONEY, O P MALONE, F MAMIYA, B MANCINI, B MANN, J R	7906140500 7906130372 7906190100 7906190294 7906140358	50-315 G 50-320 P XPDRTLIC 50-10 S PRM		MARTIN,R D MARTIN,R D MARTIN,R D MARTIN,R D MARTIN,R D	7906050100 7906200359 7906140157 7906050382 7906020191	50-366 G 50-348 G 50-348 G 50-338 G 50-124 G	
HANRY, M HANRY, M HANRY, M HANRY, M HANRY, M	7906060221 7906150296 7906070377 7906040004 7906060224	50-321 8 50-346 8 50-321 8 50-321 P 50-366 8		MARTIN, R D MARTIN, R D MARTIN, R D MARTIN, R D MARTIN, J	7906180018 7906030121 7906200490 7906230370 7906130441	50-324 G 50-302 G 50-250 G 50-324 G 50-320 P	
Manry, M Manry, M Manry, M Manry, M Manry, M	7906040299 7906040233 7906140358 7906140414 7906060210	30-321 8 50-366 8 50-321 8 50-366 8 50-321 8		MARTIN, J MARTIN, J A MARTIN, R E MASCIULLI MASDONALD, C E	7904250316 7906130390 7906290240 7906040291 7906050385	50-320 P 50-320 P 50-320 H 50-247 8 71-9126 C	
Manry, M Manry, M Manry, M Manry, M Manry, M	7906140355 7906140467 7906060215 7906060243 7906140341	50-366 8 50-366 5 50-321 6 50-366 8		MASON, R E MASRI, B MASTBAUM, D MASTBAUM, D MASTBAUM, D	7906020153 7906020195 7906020243 7906290815 7906120270	REB NUREO 50-592 G 50-592 O 50-592 D	7906020153 NUREG/CR-0793
Manry, M Manry, M Manry, M Manry, M Manry, M	7706140501 7706140517 7706140542 7706140526 7706140419	50-366 8 50-366 8 50-321 S 50-366 8 50-366 B		MATERS, B R MATHENS, E R MATHENS, E R MATHENS, H R MATHENS, E R	7906190378 7906120299 7906230116 7906220487 7906060203	50-341 A 50-305 G 50-305 G 50-305 G 50-305 E	
HANRY, M MANRY, M MANRY, M MANRY, M MANRY, M	7906140255 7906140447 7906200444 7906120426 7906130021	50-366 8 50-366 8 50-366 8 50-366 R 50-321 R		MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R MATHEWS, E R	7906080314 7906200281 7906180503 7906190401 7906280075	50-305 G 50-305 J 50-305 P 50-305 J 50-305 8	
MANRY, M HANRY, M MANRY, M MANRY, M MANRY, N	7906190324 7906190361 7906190436 7906190431 7906190483	50-321 8 50-366 6 50-366 9 50-321 6 50-366 8		MATHIASMIER,R L MATHIB,C J MATHIB,W M MATHIB,W M MATHIS,W	7906030096 7906040217 7906120305 7906060189 7906290647	50-482 Q 50-293 B 50-293 B ACRB ACRB	
HANRY: M HANRY: M HANRY: M HANRY: M HANRY: M	7906190385 7906190496 7906190509 7906210167 7906210165	50-366 8 50-366 8 50-366 8 50-366 8 50-321 8		MATIAB, T R MATIAB, T R MATIAS, T R MATSON, Y MATSON, Y	7906290060 7906290054 7906200582 7906020103 7906040440	50-596 T 50-596 T 50-596 G SEGY XPORTLIC	
HANRY, H MANRY, M MANGER, W C. MANTHE, M E MANUS, R.	7906220179 7906290297 7906040175 7906160046 7906200616	50-321 8 50-321 8 70-143 C REGOD PRM		MATBON, V MATBON, V. MATTIMOE, J MATTIMOE, J MATTIMOE, J	7906140373 7906030101 7906140602 7906020092 7906020090	XPORTLIC XPORTLIC XPORTLIC 50-312 Q 50-312 Q	
MARCELLO,R A MARCUS,G.H MARCALITH,J MARCALITH,J MARGALITH,J	7906120287 7906210424 7906220075 7906220069 7906220063	50-568 A 50-280 H 50-320 P 50-320 P 50-320 P	YAEG-1175	MATTIMOE, J J MATTIMOE, J, J MATTIMOE, J, J MATTIMOE, J, J MATTIMOE, J, J	7906290154 7906020088 7906290132 7906060287 7906070144	50-320 Q 50-312 Q 50-320 Q 50-312 P 50-312 J	
MARICICHIR J MARKIJ C MARKIJ C. MARKIJ C MARKIJ C	7906290699 7906060189 7906260542 7906290663 7906290655	50-399 G ACRS ACRS ACRS ACRS		MATTIMOE, J J MATTIMOE, J J MATTIMOE, J J, HATTIMOE, J J MATTIMOE, J, J,	7906040279 7906190441 7906180559 7906190510 7906220345	50-312 P 50-312 P 50-312 8 50-312 P	
HARKEY HARKEY HARKEY MARPLE,W W MARRIOTT,P W	7906120010 7906120012 7906120021 7906270099 7906260469	50-320 U 50-320 U 50-320 U 50-280 H 50-320 P		HATTIA, H J, HATTIA, H, J HATTIA, H J, HATTIA, H J HATTIA, H, J,	7906270096 7906140208 7906020172 7906160030 7906180049	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
MARRIOTT MARBCHALL, C. H. MARBHALL, J. A MARBH, L. MARBH, R. J.	7906120015 7906210325 7906230004 7906140553 7906260598	50-320 U NUREG 40-8384 C PR 50-341 Q	NUREO/CR-0824	MATTIA,M J. MATTIA,M J MATTIA,M J MATTIA,H J MATTIA,H J	7906150133 7906130076 7906070352 7906150161 7906150130	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
MARBHIR J MARTINID.L. MARTINIJE MARTINIA MARTINIA	7906210277 7906160013 7903200101 7906130419 7906130486	50-320 P REGOD ORG 50-320 P 50-320 P		MATTIA.M.J MATTIA.M.J. MATTIA.M.J. MATTIA.M.J. MATTIA.M.J	7906150169 7906180738 7906180744 7906180751 7906130091	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
MARTIN,T J MARTIN,N G. MARTIN,N MARTIN,N,G. MARTIN,N G.	7704040261 7704010040 7704210002 7704140185 7704050179	50-354 Q 50-311 Q 50-320 P 50-307 Q 70-364 C		MATTIA: H. J. MATTIA: H. J. MATTSON: C. W. MATTSON: R. J. MATTSON: R. J.	7906130084 7906030212 7906290091 7906270170 7906070007	CONTRACT 50-352 G 50-320 Q 50-320 P 50-320 P	
MARTIN, U. O. MARTIN, H. O. MARTIN, H. O. MARTIN, H. O. MARTIN, H. O.	7906140119 7906150222 7906140134 7906150219 7906140212	70-371 C 50-317 Q 70-364 C 50-317 Q 70-135 C		MATTSON, R. J. MATTSON, R. J. MAUR, F. J. MAXWELL, D. G. MAY, T. J.	7904230131 7904070124 7904230124 7904180515 7904240032	50-320 U 50-320 P RES 50-249 B 50-471 0	7906230124
MARTIN, W. Q. MARTIN, W. Q. MARTIN, W. Q. MARTIN, W. Q. MARTIN, W. Q.	7906210052 7906140180 7906260365 7906130215 7906260398	70-820 C 50-309 & 70-33 C 50-317 Q 70-33 C		MAYER, V. A. MAYER, L. O. MAYER, L. O. MAYER, L. O. MAYER, L. O.	7906020202 7906080290 7906080290 7906080316 7906120364	50-358 Q 50-282 P 50-306 8 50-263 P 50-306 8	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCEBBION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
MAYER, L. O MAYER, L. O MAYER, L. O MAYER, L. O MAYER, L. O	7906120375 7906140443 7906130202 7906190342 7906140229	50~263 R 50~262 P 50~263 F 50~282 P 50~282 R		MCGARRY, J M MCGARRY, J M MCGARRY, J M MCGAUGHY, J P MCGAUGHY, J P	7904070170 7904020109 7904200597 7904050127 7904230023	70-2623 C 70-2623 C 70-2623 C 50-416 Q 50-416 Q	
MAYER, L O MAYER, L O MAYER, L O MAYER, L O MAYMARD, C J	7906220357 7906220356 7906260471 7906270161 7906070178	50-282 P 50-282 8 50-282 0 50-282 8 FOIA		MCOAUGHY, R H MCOAUGHY, R H MCOAUGHY, R H MCOAUGHY, R H MCOAUGHY, R H	7906120253 7906220150 7906210160 7906200505 7906210239	50-416 A 50-320 P 50-320 P 50-320 G 50-320 P	
MAIETIS, © R MCARTHUR, S C MCBREARTY, R MCBREARTY, R A MCBRIDE, M S.	7906130388 7906070142 7906050212 7906140382 7906180029	50-320 P 50-83 J 50-352 G 50-443 G PR		MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W MCGAUGHY, R W	7906050212 7906040188 7906150195 7906010039 7906140635	50-352 Q 50-322 Q 50-363 Q 50-354 Q 50-311 Q	
MCBRIDE, J. A MGBRIDE, G E MCBRIDE, G E MCCABE, E G MCCABE, E G	7906110105 7906140091 7906140100 7906260175 7906210017	HABTE MGT 71-289 C 71-289 C 50-271 G 50-320 P		MCOAUGHY, R W MCODEY, R MCODEY, R MCODEY, R MCODEY, R J	7906140582 7906220132 7906290315 7906280236 7906280158	50-443 G 50-320 P 50-320 P 50-320 P 50-320 P	
MCCABERE C MCCABERE C MCCABERE C MCCABERE C MCCABERE C.	7906010047 7906140113 7906140207 7906260061 7906260531	50-245 G 50-293 G 50-387 G 50-20 G 50-245 G		MCOGNAGLE, W F MCORATH, E. J MCORATH, P. E MCORATH, P E MCOREGOR, L O	7906270091 7906010320 7906289009 7906280005 7906260330	50-280 H PROJ 50-320 P 50-320 P 50-282 0	
MCGABE,E C MCGARTHY,K J MCGARTHY,E L MCGARTHY,O R MCGARDELL,R K	7906210217 7906180333 7906130406 7906210170 7906260031	50-320 P 50-275 G PRM 50-568 D RES	7904260031	MCQUIRE, J R MCQUIRE, P J MCQUIRE, P J MCQUIRE, P J MCQUIRE, D R	7906150229 7906040212 7906120300 7906190248 7906180232	50-522 A 50-273 8 50-273 8 50-273 R 50-233 Q	
MCCLANAHAN, H H MCCLAIN, C M, MCCLELLAND, B J MCCLINTOCK, R D MCCLINTOCK, R D	7706200514 7706210156 7706230137 7706010132 7706130305	71-230 C 50-219 R NUREG 70-1200 C 70-510 C		MCGURREN, H J MCGURREN, H J MCGURREN, H J MCHENRY, T J. MCHENRY, T J	7906070175 7906190032 7906260394 7906070095 7906290302	50-382 0 50-478 0 50-392 0 50-111 0 50-302 0	
MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O MCCLINTOCK, R O	7906260011 7906010123 7906140506 7906140516 7906010075	70-2000 C 70-1200 G 40-8194 C 40-8194 C 70-2684 C		MCHENRY, T J MCHENRY, T J MCHENRY, T J MCHENRY, T J MCHENRY, T J	7905290169 7905290055 7906290510 7906290099 7906290557	50-302 @ 50-302 @ 50-312 @ 50-302 @ 50-302 @	
MCCLENTOCK, R O MCCLENTOCK, R O MCCLENTOCK, R O MCCLENTOCK, R O MCCLENTOCK, R. O.	7906260009 7906140497 7906010037 7906290171 7906190224	70-2000 C 40-8194 C 70-2684 C 70-1710 C 70-2880 C		MCHENRY, T. J MCHENRY, T. J MCHENRY, T. J MCHENRY, T. J MCHENRY, T. J	7906290130 7906290436 7906290473 7906290619 7906290450	50-302 G 50-302 G 50-302 G 50-302 G	
MCCLINTOCK, R. G MCCLINTOCK, R. O MCCLINTOCK, R. O. MCCLUME, L., L. MCCONNELL, J.F	7906050184 7906190221 7906290145 7906220053 7906280149	70-1717 C 70-2880 C 70-1710 C 50-320 P 50-320 P		MCKEGHN, L M MCKINNEY, R E. MCKINLEY, J, C MCLAUGHLIN, D. MCLEAN, R B	7906240568 7906130262 7906130215 7906070201 7906210011	70-33 C 50-320 D 50-320 D 40-8698 C RES	7906210011
HCCONNELL, J. F. HCCOQL, W B HCCORKLE, B. HCCORKLE, B. HCCORK, O W.	7906270014 7906130184 7906010082 7906010083 7905240706	50-320 P BECY 50-466 G 70-1426 C	9ECY-R-338	HCLEAN, R. B HCNAIR, R. C. HCNEILL, W. H HCNEILL, W. H HCNEIL, W. M	7906220183 7906200376 7906050208 7906060113 7806130028	RE8 50~219 \$ GA779 GA779 GA779	7906220183
HCCORKLE, O H HCCORKLE, O H HCCORKLE, O, H HCCORKLE, O, H HCCORKLE, O, H	7906040380 7906220441 7906220444 7906010227 7906040064	70-8 C 70-143 C 70-734 C 70-143 C 70-1308 G		641 411 114 115 148			
MCCRELESS, T O MCCRELESS, T O MCCRELESS, T Q, MCDERMOTT, D MCDERMOTT, R, J,	7906130270 7906130283 7906180600 7906150252 7906250106	50-320 0 50-320 0 50-320 0 50-325 H 50-280 P		10 10 14 15 16 18			
HCDIARMID, R.C. HCDIARMID, R.C. HCDIARMID, R.C. HCDIMALD HCDUFFIE, M.A.	7906050410 7906020137 7906040201 7906290099 7906290787	PROJ 50-445 M 50-414 M 50-302 Q 50-400 Q		H H H H			
HCDUFFIE, M.A. HCDUFFIE, M.A. HCDUFFIE, M.A. HCDUFFIE, M.A. HCDUFFIE, M.A.	7904010192 7904120428 7904150319 7904140285 7904150249	30-400 G 50-400 A 50-400 A 50-400 A 50-400 A		M M P			
HCELROY: W N HCFARLAND: D. HCFARLAND: J E HCFARLAND: G. R HCFARLAND: G R	7906180742 7906130235 7906220213 7906180731 7906180764	NUREO 50-466 Q GA999 50-327 G 50-413 G	NUREG/CR-0551	P P P			
MCFARLAND, C.R. MCGARRY, J. M. MCGARRY, J. M. MCGARRY, J. M. MCGARRY, J. M.	7906260527 7906020219 7906020212 7906140552 7906010126	50-939 Q. 70-2623 C 70-2623 C 71-6698 C 50-488 Q		P e !			

AUTHOR	ACCESSION NUMBER	SUBJECT CAYEODRY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
MEYER.R H MEYER.M B MEYERS, S	7906020112 7906290179 7906110023	50~358 Q 50~471 G WASTE MOT		MILLEAP, W J MILETEAD, W C MILETEAD, W	7906290401 7906280043 7905240245	50-320 P 50-320 B 50-320 P	
MEYER.R J MEYER.R O MICA.D A	7906070187 7908070088 7906260890	50-267 P 50-320 P 50-250 U		MINARCIN, P MINER, S MINOGUE, R B MINOGUE, R B	7906010109 7906250315 7906110313 7906070329	50-320 H 50-387 A COMMISSION FOIA	8ECY-78-415
HICHEL,C J HICHEL,C J HICHEL,C J MICHEL,G J HIDURA,H J	7906230183 7906040024 7906280473 7906290840 7906070268	70-143 C 71-6400 C 70-143 C 70-143 C 50-272 8		Minoque.r B Minoque.r B Minoque.r B Minoque.r B Minoque.r B	7906020227 7903300537 7906200301 7906070075 7906070152	10CFR PR PR FOIA FOIA	SECY-79-114
MIDURA.H G MIDURA.H J MIDURA.H J MIDURA.H J MIERNICKI.M J	7906260417 7906150150 7906260418 7906260349 7906040357	50-272 R 50-272 R 50-272 R 50-272 R 50-318 S		Miraolia, f J Miraolia, f J Miraolia, f J Miraolia, f J Miraglia, f J	7906060144 7906130452 7904270331 7905040321 7905040635	50-320 U 50-320 Q 50-320 P 50-320 P 50-320 P	
MIERNICKI, M J MIERNICKI, M J MIERNICKI, M J MIERNICKI, M J MIERNICKI, M J	7904010207 7904050265 7904080248 7904260348 7906260442	50-318 8 50-317 8 50-318 8 50-318 8		MIRAGLIA,F J MIRAGLIA,F J MIRAGLIA,F J MIRAGLIA,F J MITCHELL,D G	7905070029 7906250100 7906250107 7906220226 7906040331	50-320 P 50-320 P 50-320 P 50-320 P 50-289 8	
MIKULA,E J MIKULA,E J MILES,C MILHOLLIN,O L MILHOLLIN,O L	7906130148 7906130284 7906220229 7906030420 7906050345	FR 50-452 D 50-320 P 50-272 T 50-272 O		MITCHELL, D G MITTL, R L MOBLEY, J D MOBLEY, M H HODENOS, L	7906040244 7906140389 7906140038 7906160055 7906050117	50-287 8 PR 71-321 C PR 50-366 Q	
MILHOLLIN, 0 L MILHOLLIN, 0 L MILHOLLIN, 0 L MILHOLLIN, 0 L	7904070344 7906010284 7906020032 7906190004 7906220465	50-237		MODENOS, L MOERKE, N H MOERKE, N H MOFFETT, T MONDEN, T	7906200364 7906290671 7906290631 7906270157 7906290553	50-389 G GAPPP GAPPP COMMISSION SECY	
MILLAR,P A MILLAR,P A MILLER,P C MILLER,W R MILLER,W,C	7904040077 7904040080 7906070405 7906020034 7906130012	71-308 C 71-308 C 50~275 H 50-358 G 50-445 A		MONTANA-DURN, B. HONTGOHERY, C R HONTGOHERY, D H HONTGOHERY, D H HONTI, H. A	7906130152 7906120297 7906210013 7906290389 7906190476	50-322 0 50-146 J 50-320 P 50-320 P 50-3	
HILLER, M I MILLER, O M MILLER, L C MILLER, R L MILLER, T D	7906210247 7906220202 7906210076 7906230057 7906210307	50-255 Q 50-320 B GA799 GA799 GA797		HOODY, D E HOODY, D E HOODY, D E HOODY, D E	7906120241 7906270105 7906190306 7906050281 7906140328	50-309 G 50-309 G 50-309 R 50-271 G	
MILLER, T. J MILLER, O P MILLEN, C K MILLEN, C. K MILLER, L K	7906250420 7906070130 7906290419 7906290426 7906150153	50-579 0 50-320 P 50-247 P 50-247 P 50-272 R		HODDY, D E HODDY, D E HODDY, D E HODDY, D E MODDY, D E.	7906290806 7906050258 7906260564 7906190305	50-271 G 50-271 F 50-271 G 50-271 R	
MILLER, M E	7906040396 7906040434 7906040426 7906130107 7906210403	50-344 0 50-445 M 50-327 0 70-2623 C 50-445 M		MOODY, D E MOODY, D E MOON, R T	7906290737 7906290737 7906190313 7906190227 7906290135	50-29 G 50-29 R 50-29 R 50-29 F 50-269 G	
MILLER, M E HILLER, M E MILLER, M E MILLER, M E MILLER, M E MILLER, M, E	7906040159 7906060214 7906070312 7906070315 7906220479	70-2623 C PROJ 50-445 H 50-445 H PROJ		MOON, B,  MOON, B T  MOORE, G H  MOORE, G H  MOORE, J P	7906290429 7906290480 7906010132 7906120325 7906260270	50-269 Q 50-269 Q 50-334 R 50-334 R 50-320 P	
MILLER, M E MILLER, M E MILLER, M E MILLER, M, E MILLER, M E MILLER, M E	7906020141 7906020096 7906130418 7906220038 7906180736	PROJ 50-445 H 50-445 M 70-2623 G 50-445 T		MODRE, J B MODRE, J B MODRE, J B MODRE, J B MODRE, J B MODRE, J, B	7906200134 7906220314 7906220335 7906270237 7906270237 7906240404	50-206 8 50-206 8 50-206 8 50-361 8 50-361 8	
MILLER, W O MILLER, W O MILLER, W O O	7904270044 7906070044 7906020078 7906040144 7906110040	50-320 P 70-27 C 50-3 F 50-286 P 50-267 P		MOORE, R. N. MOORE, R. N. MOORE, J. E. MOORE, J. E. MOORE, J. E. MOORE, D. E.	7905230723 7906040409 7906180807 7906180816 7906190594	30-361 8 XFORTLIC XFORTLIC 50-272 0 50-272 0 70-27 C	
	7906040146 7906230061 7906180796 7906230072 7906260552	50-312 P 71-4986 C 50-250 P 50-29 P 40-8714 C		MOORE, DE MORGANELLO, M. M MORRISON, H. P. MORRIS, A. B	7706150047 7706230012 7706070338 7706260375	70-143 C 71-117 C 50-395 M 50-463 Q	
	7906290789 7906270275 7906260347 7906290343 7906290120	40-8027 C 50-271 P 50-312 Q 50-312 Q 50-302 Q		MORRILL, P  MORTON, K. V  MORTON, K, V.  MOSBY, H R  MOSELEY, N, C.	7906290471 7906150175 7906030002 7906290311 7902210141	50-312 G CONTRACT CONTRACT REB 1&E	7906290311
	7906290587 7906290153 7906290445 7906290489 7906250442	50-312 Q 50-312 Q 50-312 Q 50-312 Q 50-73 Q		HOSELEY, N C	7904270043 7902130354 7904130485 7904290440 7904270072	50-320 P 1&E 50-320 P 50-320 F 50-320 P	
J	7906070076 7906070191 7906220339	50-280 G 50-390 K 50-327 K		MOSELEY, N. C. MOSELEY, J. J. MOSELEY, J. J	7906260090 7906140567 7906140560	50-320 P 50-320 P XPORTLIC XPORTLIC	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
MOURY, U. R. MOURY, U. R. MOURY, U. R.	7906130200 7906050088 7906050092	PRH XPORTLIC XPORTLIC		MURPHY, T D MURRAY, T D MURRAY, T D MURRAY, T D	7906290244 7906080283 7906040237 7906050242	50-320 P 50-346 S 50-346 S 50-346 S	
NOVERY, H R NOVERY, H R NOVERY, H R NOVERY, H R	7906120217 7906120227 7906020194 7906180797 7906180800	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	7906070202 7906070269 7906080303 7906140394 7906180346	50-346 8 50-346 F 50-346 R 50-346 R	
MOYNIKAN, D MUDGE, J E MUDGE, J E MUELLER, R. MULGEN, R	7906150231 7906290007 7906290194 7906040294 7906280021	50-320 U 50-320 R 50-320 U 50-285 8 50-320 P		MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D MURRAY, T D	7906180547 7906220383 7906220397 7906250257 7906270175	50-346 8 50-346 8 50-346 8 50-346 8	
MULEY.NE MULER.R MULER.R MUNITIONL K MUREPHY.C E	7906230113 7906130254 7906180006 7906130189 7906070368	50-471		MURRAY, T D MURRAY, J P MURRAY, B MURRI, E L MYKYTA, L.	7906230122 7906040034 7906040162 7906290023 7906200603	50-346 0 50-443 0 50-313 0 50-320 P 71-260 C	
HERPHY, C E HURPHY, C E HURPHY, C E HURPHY, C E HURPHY, C, E	7906210051 7906070284 7906220234 7906020139 7906260197	50-390 Q 50-491 Q 50-438 Q 50-553 Q 50-281 Q		MYNATT, F R MYNATT, F. R MYNATT, H A MYRABD, A L. NAPUDA, G	7906220215 7906230172 7906050001 7906120378 7906290833	RES RES CONTRACT 50-263 R 50-219 G	7906220213 7906230172
HURPHY, CE HURPHY, CE HURPHY, CE HURPHY, CE	7906210084 7906040377 7906010138 7906210105 7906020124	50-390 G 50-327 G 50-553 G 50-390 G 50-369 G		NARBUT.P P MARDACCI.G A NARDACCI.G A NARDACCI.G A NARROH.L	7906140215 7906270112 7906270113 7906290011 7906010039	50-341 0 50-320 P 50-320 P 50-320 R 50-354 0	
HURPHYICE HURPHYICE HURPHYICE HURPHYICE	7906010195 7906160037 7906150034 7906040362 7906140641	50-416 Q 50-369 Q 50-498 Q 50-369 Q 50-498 Q		Natron, L Natale, V Naughton, H F Naughton, H F Naughton, H F	7906130193 7906220100 7906010238 7906080276 7906070270	50-363 Q 71-6058 C 50-577 A 50-579 A	
HURPHY, C E HURPHY, C E HURPHY, C E HURPHY, C, E HURPHY, C, E	7906140649 7906230137 7906010018 7906010029 7906010322	50-416 Q 50-281 Q 50-566 Q 50-327 Q 50-518 Q		NAUCHTON, W F NAUCHTON, W F NAUCHTON, W F NAUCHTON, W F NAYLOR, R W	7904130225 7904130380 7904220352 7904220380 7904180351	50-599 A 50-599 A 50-599 A 50-599 G 50-346 B	
MORPHYICE MURPHYICE MURPHYICE MURPHYICE	7906030113 7906180090 7906030063 7906030133 7906200193	50-366 Q 50-424 Q 50-390 Q 50-416 Q 50-390 Q		NEIGHBORB.JD NEIGHBORB.JD NEIGHBORB.JD NEIGHBORB.JD NEIGHBORB.JD	7706260331 7706260110 7706250174 7706270557 7706270559	50-280 P 50-280 P 50-280 P 50-280 P 50-373 Q	
MURPHY: C E. MURPHY: C E MURPHY: C E MURPHY: C E	7906140142 7906070118 7906070136 7906210064 7906210402	50-370 0 50-281 0 50-327 0 50-389 0 50-281 0		NELSON, H D NELSON, C NELSON, C NELSON, J NELSON, C. C	77040502047 7704180704 7704180704 7704220403 7704140052	NUREG 50-320 P 50-320 P 50-344 B 50-309 P	NUREO/CR-0959 NUREO/CR-0958
MARPHY, C E MARPHY, C E MARPHY, C. E. MARPHY, C. E.	7906220084 7906220248 7906200362 7906210286 7906180752	50-390 G 50-348 G 50-389 G 50-390 G 50-413 G		NELSON, G C NEWMARK, N M NEWMARK, N M NEWMAN, J. R NEWMAN, J. R	7906180971 7906060074 7906060075 7906180723 7906070307	50-302 P 50-309 P FOIA 50-466 G 50-466 Q	
MAPHY, CE MAPHY, CE MAPHY, CE MAPHY, CE MAPHY, CE	7906010348 7906220074 7906230341 7906250352 7906040370	50-367 G 50-375 G 50-338 G 50-438 G 50-327 G		NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R. NEWMAN, J. R.	7904080183 7904080190 7904110440 7904020107 7904070304	50-466 G 50-466 G 50-466 G 50-466 G	
MARPHY, C E Murphy, C E Marphy, C E, Marphy, C E,	7906160024 7906260324 7906260241 7906260399 7906190162	50-369 0 50-339 0 50-366 0 50-281 0 50-395 0		NEWMAN, J. R. NEWMAN, J. R. NE!	7906080032	50-466 9	
MURPHYLCE HURPHYLCE MURPHYLCE MURPHYLCE MURPHYLCE	7906220091 7906190116 7906070332 7906010133 7906010190	50-375 Q 50-491 Q 50-250 Q 50-553 Q 50-416 Q					
HURPHY, C. E MURPHY, C. E MURPHY, C. E MURPHY, C. E	7906220244 7906210041 7906140116 7906190527 7906200174	50-348 Q 50-390 Q 50-370 Q 50-391 Q 50-390 Q					
MURPHY.C E. HURPHY.C E. HURPHY.C E. HURPHY.C E. HURPHY.C.E.	7906220169 7906020120 7906180734 7906020131 7906250122	50-438 G 50-349 G 50-413 G 50-553 G 50-281 G					
MURPHY, C. E MURPHY, C. E MURPHY, C. E. MURPHY, C. E MURPHY, C. E	7906250163 7906290568 7906290475 7906180720 7906210073	50-367					
MURPHY, C. E	7906070108	50-339 G					

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORDERHAUG, L R NORELIVS.C E	7706160042 7706160043 7706270641 7706270632 7706230117	50-275 G 70-2217 C 70-754 C 70-734 C 50-346 G		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J, P	7706250443 7706250446 7706250450 7706250450 7706250455	50-269 Q 50-413 Q 50-302 Q 50-250 Q 50-321 Q	
NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	7906290718 7906180651 7906180806 7906040409 7906010103	SECY SECY SECY XPORTLIC XPORTLIC		O'REILLY, J P O'REILLY, J P O'REILLY, J. P O'REILLY, J. P	7906250458 7906250460 7906260563 7906110058 7906110059	50-375 Q 50-375 Q 50-416 Q 50-348 Q 50-261 Q	
NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V NOSENZO, L V	7906040435 7906070276 7906070382 7906230094 7906020136	XPORTLIC XPORTLIC XPORTLIC SECY XPORTLIC		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P	7904110040 7904110041 7904110043 7904110045 7904110044	50-269 Q 50-302 Q 50-250 Q 50-321 Q 50-259 Q	
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	7906150256 7906180759 7906260012 7906290643 7906290753	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, P, D	7906110068 7906260242 7906190173 7906250111 7906210066	50-280 Q 50-269 Q 50-518 A 50-261 Q FOIA	
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V	7906290757 7906250307 7906020021 7906230087 7906010087	XPORTLIC XPORTLIC SECY SECY XPORTLIC		CAKEB, D L OBERG, C R DESTHANN, M J OESTHANN, M J GHANIAN, M J	7906010280 7906210032 7906020065 7906230125 7906190286	50-348 8 50-482 G 50-298 G 50-263 G 50-83 P	
NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOSENZO, L. V NOVAK, T. M	7906040230 7906040233 7906260100 7906260105 7906280173	XPORTLIC XPORTLIC XPORTLIC XPORTLIC 30-320 P		OKRENT, D OKRENT, D OKRENT, D OKRENT, D OKRENT, D	7706260569 7906120076 7906120037 7906150224 7906260542	ACR8 50-320 T 50-320 U 50-320 T ACR8	
NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P NOVARRO, J P	7906110421 7906060285 7906060290 7906120218 7906010201	50-322 A 50-322 A 50-322 A		OKUDA: H OLLER: R E OLLER: R E OLMBTEAD: H J OLMSTEAD: H J	7906190097 7906210059 7906070031 7906230021 7906230016	XPORTLIC GA979 GA979 50-329 G 50-329 G	
NOWICKI, 8 J. NOWICKI, 8 J. NUGENT, E L. NUGENT, E L NUNN, D. E	7906010235 7906250320 7906050232 7906040120 7906130236	50-219 P 50-219 P 40-2259 C 40-2259 C 50-361 B		OLMSTEAD, W J OLMSTEAD, W J OLSEN, A F, OLSEN, A F OLSEN, A F	7906230026 7906230029 7906250313 7906200094 7906220100	50-329 G 50-329 G 70-624 C 70-824 C 71-6058 C	
NUTE, L F NYMAN, G J, G'ERIEN, J M. G'ERIEN, G M G'CONNOR, L A	7706010272 7706120415 7706130171 7706080026 7706170376	50-327 0 50-27 P PRM 50-10 U 50-213 I		OLBEN, A F OLBEN, C B OLBHAN, L, N OLBHAN, L, N OLBHAN, L, N	7906010185 7906270542 7906250033 7906260092 7906260176	70-824 C RES 50-247 P 50-305 P 50-334 P	7906290542
O'CONNOR, L. A O'DONNELL, E P O'HANLON, J P O'MALIA, R. J O'NEIL, J H	7906200374 7906200345 7906080298 7906250356 7906110034	50-245 I REGOD 50-313 B 71-85 C WASTE MGT		OLSHAN, L N OLSHAN, L, N ONISHI, Y ONSDORF, K A ONSDORFF, K A	7906110441 7906230090 7906020148 7906010099 7906200611	50-247 P 50-247 G NUREO 50-272 G 50-272 G	NUREQ/CR-0&38
O'NEILL, J J, O'REILLY, J P O'REILLY, J P O'REILLY, J P O'REILLY, J P,	7906070208 7906290220 7906200540 7906180205 7906200146	50-346 8 14E 50-321 G 50-335 G 50-280 G		OPEKA.J F OPEKA.J F OPEKA.J F OPEKA.J F OPEKA.J F	7904040353 7904040234 7904040295 7904120357 7904120395	50-245 8 50-245 8 50-336 8 50-245 8 50-336 8	
O'REILLY, J P. O'REILLY, J P O'REILLY, J P O'REILLY, J P	7906070021 7906290809 7906010304 7906130141 7906130144	50-321 Q 50-437 Q 50-338 Q 50-321 Q 50-416 Q		OPEKA.J.F OPEKA.J.F OPEKA.J.F OPEKA.J.F OPEKA.J.F	7904140398 7904120345 7904180522 7904180495 7906250278	50-245 8 50-336 R 50-245 R 50-336 8 50-245 8	
O'REILLY, J P O'REILLY, J P. O'REILLY, J, P. O'REILLY, J, P. O'REILLY, J P.	7906130146 7906130147 7906130151 7906130154 7906020174	50-553		DPEKA, J F DPEKA, J F. OPEKA, J, F OPLINGER, G G OPLINGER, G G	7906290260 7906290242 7906290277 7906180624 7906250249	50-336 8 50-245 8 50-396 8 SECY XPORTLIC	
O'REILLY, J P.	7906200615 7906250386 7906250413 7906250414 7906250417	50~400 A 50~437 Q 50~160 Q 50~111 Q 50~538 Q		OPLINGER, O. Q OPLINGER, O. O OPLINGER, G. O OPLINGER, Q. O OPLINGER, Q. O	7906290612 7906250238 7906020106 7906290838 7906020027	SECY XPDRTLIC SECY 50-574 A SECY	
O'REILLY, J. P.	7906250418 7906250421 7906250422 7906250422 7906250425	50-127 0 50-124 0 50-83 9 50-62 9 50-406 0		OPLINGER, 0, 0, OPLINGER, 0, 0 OPLINGER, 0, 0 OPLINGER, 0, 0 OPLINGER, 0, 0	7906120103 7906210094 7906040437 7906010172 7906050253	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
G'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	7906250427 7906250428 7906250429 7906250430 7906250430	70-1432 C 70-1319 C 70-1201 C 70-143 C 70-1113 C		OPLINGER, O. O OPLINGER, O. O OPLINGER, O. O OPLINGER, O. O OPLINGER, O. O	7906050264 7906050267 7906050396 7906050402 7906050404	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P. O'REILLY, J.P.	7906250433 7906250435 7906250436 7906250437 7906250440	50-332		oplinger, 0. 0 oplinger, 0 0. oplinger, 0. 0 oplinger, 0. 0. oplinger, 0. 0.	7906160012 7906050257 7906050261 7906050408 7906160011	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	

AUTHOR	ACCESSION NUMBER	BUBJECT REPORT CATEGORY NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
DPLENGER. 0 0 DPLENGER. 0 0 DPLENGER. 0 0 DPLENGER. 0 0 DPLENGER. 0 0	7906160015 7906160025 7906160031 7906250061 7906040438	XPORTLIC XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	OHSLEY, 0 F OHSLEY, 0 F OZMUN.R V PADOETT, 0 PAGEL, J W	7906270077 7906120230 7906230157 7906180193 7906180337	TOPREP TOPREP 71-146 C 71-298 C PR	
OPLINGER. 0. 0	7906160029 0600616097 1800816097 0600616097	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PALLADINO, N J PAOL INA, R PAPPAS, H PAPPAS, H, PAPPAB, H	7906130285 7906260499 7906120222 79060201•5 7906260015	50-320 0 50-311 0 ORG ORG ORG	
OPLINGER, Q 0 OPLINGER, Q 0. OPLINGER, Q 0. OPLINGER, Q 0. OPLINGER, Q 0	7706160018 7706050010 7706050015 7706020146 7706020149	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PAPPAS, H PAPPAS, H PAPWORTH, L O PAPWORTH, L O PAPWORTH, L O	7906080120 7906120250 7906120427 7906150318 7906270194	0RG 0RQ 50~407 R 50~407 S 50~407 B	
OPLINGER, G 0	7906020132 7906020162 7906040226 7906150107 7906150109	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARCELL PARCELL PARIS,O PARIS,O PARKER,O A	7906050353 7906200409 7906290069 7906290077 7906220334	50-237 8 50-237 8 50-576 T 50-576 T 50-528 9	
GPLINGER, O. O. OPLINGER, O. O.	7906150111 7906160059 7906160061 7906160063 7906160064	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKERBON, L PARKER, W O PARKER, W O PARKER, W O PARKER, W O	7706010258 7706260250 7706020121 7706140529 7706160033	FDIA 50-269 G 50-369 G PR 50-369 G	
GPLINGER.O 0 GPLINGER.O 0 GPLINGER.O 0 GPLINGER.O 0 GPLINGER.O 0	7906160065° 7906180022 7906180025 7906150119 7906150122	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER W O	7906110062 7906020245 7906040360 7906140615 7906160062	50-269 0 70-2623 C 50-369 0 RECOD 71-6698 C	
OPLINGER, O O	7906150117 7906180801 7906190079 7906290779 7906190082	XPORTLIG XPORTLIG XPORTLIG GECY XPORTLIG	PARKER, W O	7906220061 7906120291 7906140122 7906040421 7906260244	PRM 50-267 G 50-370 G 50-267 G 50-269 G	
OFLINGER, 0 0 OPLINGER, 0 0 OPLINGER, 0 0 OPLINGER, 0 0 OPLINGER, 0 0	7906190083 7906190188 7906190184 7906190186 7906250042	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKER, W O. PARKER, W O. PARKER, W O. PARKER, W O PARKER, W O	7706250057 7706250170 7706200265 7706010346 7706140181	70~2623 C 50~369 G 50~269 G 50~369 G	
oplinger, g. g. Oplinger, g. g Oplinger, g. g Oplinger, g. g Oplinger, g. g	7906250045 7906250048 7906250050 7906250052 7906250055	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O PARKER, W. O.	7906290829 7906010244 7906260284 7906060229 7906070238	50-269 G 50-370 B 50-369 G 50-267 P 50-269 P	
OPLINGER, G O	7906250060 7906250064 7906250069 7906250073 7906250076	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	7906050327 7706120225 7706130320 7906150280 7906150267	50-269 P 50-269 G 50-269 G 50-369 J 50-269 P	
OPLINGER, 0 0 OPLINGER, 0 0, OPLINGER, 0, 0, OPLINGER, 0 0 OPLINGER, 0 0	7906250080 7906250084 7906250086 7906250089 7906250093	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARKER, W O PARKER, W O PARKER, W O PARKER, W O PARKER, W O	7906190261 7906210149 7906220283 7906260529 7906280148	50-269 P 50-269 R 50-269 P 50-270 B 50-269 R	
OFLINGER, 0 0. OFLINGER, 0.0 OFLINGER, 0 0 OFLINGER, 0 0. OFLINGER, 0 0.	7906250096 7906250098 7906250102 7906250104 7906250117	XPORTLIG XPORTLIG XPORTLIG XPORTLIG XPORTLIG XPORTLIG	PARKER, W O PARKINGON, T F PARKH, C E PARMLEY, W A PARR, O D	7906290314 7906020178 7906230140 7906110051 7906200520	50-249 8 50-124 G TOPREP WASTE MOT 50-338 P	BAH-10074A
OPLINGER. 0 0	7904250120 7904250126 7904250131 7904250134 7904250139	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	PARRIO D PARRIO D PARRIO D PARRIO D PARRIO D	7906070313 7906070325 7906060020 7906110414 7906130504	50-338 P 50-338 P 50-339 A 50-498 A 50-387 A	
OPLINGER: Q Q OPLINGER: Q Q OPLINGER: Q Q OPLINGER: Q Q OPLINGER: Q Q	7906250144 7906250343 7906180652 7906210082 7906270021	XPORTLIC XPORTLIC SECY XPORTLIC XPORTLIC	PARR, Q. D PARR, Q. D PARR, Q. D PARR, Q. D. PARR, Q. D.	7906190003 7906150105 7906180767 7906180781 7906230162	50-568 I 50-387 A 50-338 P 50-400 A 50-387 A	
Oflinger, 0, 0, Oflinger, 0 Q Oflinger, 0 Q Oflinger, 0, 0 Orser, W 8	7906290385 7906290526 7906050266 7906160028 7906080294	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC 50-344 B	PARR, Q D. PARR, Q D. PARR, Q D. PARR, Q D PARRIS, H. G	7906290851 7906250075 7906290841 7906290755 7906010278	50-596 A 50-498 A 50-398 P 50-387 F 50-259 J	
OSENBAUGH, E M OST, P OSTER, J. OSTER, J. OSTER, J.	7906280420 7906060275 7906070256 7906120260 7906200290	50-599 0 50-295 8 50-10 J 50-10 J 50-295 J	PARSONT, M A PARTLON, J. Q PARTLON, J. Q. PARTLON, J. Q. PARTLON, J. Q.	7905250222 7906050237 7906010163 7906040115 7906040386	DR0 70-1151 C 70-820 C 70-1151 C 70-734 C	
OTT.L J. OTTHOFF.F H OUSRE.R.P. OUSRE.R.F. OUZTS.J.E.	7906050134 7906260024 7906120268 7906120326 7906250365	NUREO NUREO/CR-0610 50-466 0 80-312 P 50-312 P 50-324 Q	PARTLOH, J. 0 PARTLOH, J. 0 PARTLOH, J. 0 PARTLOH, J. 0	7906040044 7906040066 7906040071 7906040075	70-1151 C 70-143 C 70-371 C 70-1113 C	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGGRY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEOGRY	REPORT NUMBER
PARTLOW, J Q PARTLOW, J Q PARTLOW, J Q PARTLOW, J Q PARTLOW, J Q	7706050102 7706200307 7706250001 7706250002 7706250005	70-364 C 70-1201 C 70-1100 C 70-1100 C 70-36 C		PLESSET.M 8 PLITCH, L W PLUMBTED, H C POBUTKIEHICZ, S POCHAL, H F	7906130274 7906070222 7906200284 7906040227 7906130099	50-320 O FOIA 71-120 C 50-333 S XPORTLIC	
PARTLOH, J @ PARTLOH, J @ PARTLOH, J C PARTLOH, J @ PARTLOH, J @	7906250011 7906210070 7906290789 7906290741 7906260570	70~36 C 70~1151 C 70~143 C 70~143 C 70~143 C		POCHAL.4 F FOE, J POIRER.M R POLK.P J POLK.P J	7906270083 7906260539 7906020137 7906110032 7906050109	XPORTLIC XPORTLIC 50-445 M 50-333 P 50-333 P	
PARTLOH, J Q PARTLOH, J Q PARTLOH, J Q PASTERNAK, R J PASUPATHI, V	7905250372 7905290796 7905290207 7905040225 7905210339	70-1201 C 70-734 C 70-371 C 50-333 S 50-331 P	BCL-585-9	POLLOCK, R POOLE, R D PORSE, L PORT, 8 PORTER, 8 W	7906210400 7906040187 7906260483 7906210208 7906280130	PRM 50-10 J NUREG 50-320 P 50-320 P	NUREG-0534
PATE.R J PATON.H D PATTERSON.J P PATTERSON.J P PAUL.R	7906210347 7906020033 7906260312 7906260237 7906210043	50-361 0 50-387 0 50-263 0 50-368 0 PR		PORTER. 9 W PORTER. 8 W PORTER. 8 W PORTER. 8 W PORTER. 8 W	7906220207 7906290423 7906210111 7906260281 7906220062	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P	
PAULUS,R C. PAULUS,R C. PAULUS,R C. PAULUS,R C. PAULUS,R C	7904040178 7904040181 7904050041 7904220153 7904270031	50-320 S 50-320 S 50-320 S 50-320 S 50-320 S		PORTERA, C PORTER, B J PORTER, W L PORTER, W E PORTER, W L	7906160019 7906200553 7906120016 7906030399 7906040037	71-72 C PR 70-2623 C 70-2623 C 70-2623 C	
PAULUS,R C PECK.B O PECK.L J PECK.C C PEEBLES,L	7906270027 7906290204 7906020094 7906260228 7906140465		7906290204 NUREG-0482	PORTER, W L PORTER, W L PORTER, W L PORTER, B W PORTER, B W	7906210126 7906050391 7906280008 7906270413 7906210202	70-2623 C ORQ 70-2623 C 50-320 P 50-320 P	
PEELERIG B. PEEPLESIW P PEERYIW W PERRYIW W PERRODID C	7906290505 7906180149 7906150463 7906290386 7906110089	RES PR 50-390 G 50-320 P Waste Mot	7906290505	PORTER, 8 W PORTER, 8 W PORTER, 8 W PORTOR, W L POTAPOV8, U	7906210205 7906210192 7906210196 7906080121 7906160009	50-320 P 50-320 P 50-320 P 70-2623 C GA999	
PEPPER.C PERKINS.T J PERLMUTTER.C B PERLMAN.J PERLMAN.J	7906070045 7906010214 7906070071 7906180282 7906250335	50-250 U 50-220 E FOIA CONTRACT CONTRACT		POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906160006 7906210080 7906160004 7906210058 7906210061	GA979 GA979 GA979 GA979 GA979	
PERLMAN, J PERLMAN, J PERLMAN, J PERNY, C D PEROVICH, J	7906260123 7906260135 7906270100 7906080169 7906220243	CONTRACT CONTRACT CONTRACT 50-538 G 50-252 J		POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906210093 7906210074 7906210088 7906210335 7906290268	9A777 9A777 9A777 9A777	
PERROTTI.D J PERROTTI.D J PERROTTI.D J PERROTTI.D J PERRY.J C	7906210144 7906210282 7906260074 7906210009 7906040350	50-320 P 50-320 P 70-1201 C 50-320 P 50-344 8		POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906180663 7906210312 7906290690 7906290682 7906180251	GA777 GA777 GA777 GA777	
PERSIANI.P J PETERS.H PETERSON.C.E PETRICK.N A PETRICK.N A	7906130205 7906180284 7906250420 7906120146 7906120263	50-320 D 50-275 G 50-599 O 50-483 A 50-482 A		POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U, POTAPOVS, U	7906010110 7906010112 7906070023 7906050198 7906070028	GA777 GA777 GA777 GA777 GA777	
PETTIJOHN, R PHILBRICK, S PHILLIPS, J. R PHILLIPS, J. R PHILLIPS, D. L	7906050141 7906260632 7906070327 7906010341 7906080256	NUREO ACRS 50-275 Q 50-275 G 50-298 B	NUREO/CR-0699	POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U POTAPOVE, U	7906180654 7906210326 7906060052 7906060080 7906060104	GA979 GA999 GA999 GA999 GA999	
PHILLIPS,H,S PHOENIX,W C PHOENIX,W C PICKERING,T R PICKFORD,A E	7906050238 7906280048 7906260234 7906250188 7906270213	50-373 Q REVIEW GRP REVIEW GRP XPORTLIC TOPREP		POTAPOVS: U POTAPOVS: U POTAPOVS: U POTAPOVS: U POTAPOVS: U	7906220216 7906230069 7906190067 7906230048 7906230051	9A999 9A999 9A999 9A999	
PICKLE:J J PICKLEBIMER:M PIEPEL:O F. PILANT:J M PILANT:J.M	7906070049 7906260473 7906180717 7906040205 7906110093	50-498 U 50-320 R NUREG 50-298 Q 50-298 Q	NUREO/CR-0683	POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906210297 7906050174 7906190052 7906050168 7906210401	GA979 GA979 GA979 GA979 GA999	
PILANT, J M. PILANT, J. M PILANT, J M PILANT, J M. PILANT, J M. PILANT, J H	7906290341 7906070373 7906110043 7906030270 7906060148	50-320 G 50-298 G 50-298 G 50-298 P 50-298 P		POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906290576 7906290621 7906180238 7906120022 7906290251	GA999 GA999 GA999 GA999	
PILANT, J H. PILANT, J H PILANT, J H PILANT, J, M PILANT, J, M,	7906050272 7906120237 7906190392 7906260337 7906290281	50-298 P 50-298 P 50-298 P 50-298 J 50-298 P		POTAPOVS, U. POTAPOVS, U. POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906290219 7906290662 7906230036 7906060070 7906230032	GA777 GA777 GA777 GA777	
PILLARDIC H PLANJEIT J. PLASKONIR E PLASKONIR.E. PLESSETIM S	7906130188 7906240622 7906290794 7906290808 7906250474	PR 50-123 Q 50-514 Q 50-514 Q ACRS	1	POTAPOVS: U POTAPOVS: U. POTAPOVS: U POTAPOVS: U POTAPOVS: U.	7706010105 7706060044 7706050157 7706050165 7706050186	GA797 GA777 GA777 GA777 GA777	

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U POTAPOVS. U.	7906070019 7906190030 7906190039 7906190080 7906230025	GA777 GA777 GA777 GA777 GA777		REEVES, E. A REEVES, E. REOAN, W H REOAN, W H REOAN, W H	7906260179 7906250260 7906180785 7906010085 7906040372	50-348 P 50-348 P 50-404 0 50-329 A PROJ	
POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U POTAPOVS, U	7906290563 7906290614 7906290238 7906290633 7906290676	GA797 GA797 GA797 GA797 GA797		REGAN, W H REGAN, W H REGAN, W H REGAN, W H REGNIER, J.	7906060005 7906060003 7906290853 7906290199 7906130492	50-471 D 50-471 D 50-596 A 50-338 P 50-320 P	
POTAPOVS, V POTAPOVS, V POTATOVS, V POTTER, R C POTTER, J P	7906290200 7906290225 7906220210 7906140460 7906040184	9A999 9A999 9A999 50-329 9		REKM, T A. REKM, T A REID, R E REID, R E REID, R W	790605000B 7906200283 790614006B 7906140073 7903210263	COMMISSION COMMISSION 71-303 C 71-303 C 50-289 P	
POTTER, J.P. POTTHOFF, F.H. POWELL, J.E. POWERS, M. B.	7906070323 7906210249 7906250431 7906210365 7906290781	70-1201 C 50-466 0 50-466 0 NUREO 1 40-8722 C	NUREO/CR-0335	REID, R W REID, R W REID, R W. REID, R W REID, R W	7906030094 7906030097 7906030146 7906030132 7906040033	50-313 P 50-313 P 50-59 P 50-59 P 50-285 P	
PRATTIC K PRENDERGAST, W B PRICE, S PRICE, D B PROFFITT, N L	7906050225 7906130175 7906080274 7906290450 7906050251	PRM PR 50-241 J 50-302 G 50-339 A		REID, R W REID, R W REID, R W REID, R, W REID, R W	7906020230 7906020236 7906230082 7906230156 7906270257	50-72 P 50-72 P 50-336 P 50-302 P 50-336 P	
PROFFITT, W.L. PROON, B.C. PRZEKOF, P.J. GUALFE, H.A. GUEENSR, D. B.	7906190338 7906280126 7906040314 7906060202 7906290188	50-339 A 50-320 J 50-245 S 50-320 H NUREO N	NUREO/CR-0692 V6	REID.R W REID.R W REID.R.W REID.R W REID.R W	7906270258 7906270261 7906230054 7906250054 7906200296	50-336 P 50-336 P 50-134 P 50-346 P 50-287 P	
GUESENSERRY, B. V GUESENSERRY, B. V GUICK, D. R GUICK, D. R GUICK, D. R	7904080225 7904080221 7904180408 7904290302 7904290149	50-592		REID.R W REID.R W REID.R W REID.R W REID.R W	7904250152 7704270274 7904270272 7904270300 7904270308	50-287 P 50-302 P 50-313 P 50-313 P 50-313 P	
GUICK, D.R. GUICK, D.R. GUIGLEY, E. GUIMBY, L. GUITISCHREIBER	790629055 7906290510 7906210380 7906270066 7906180617	50-302 G 50-312 G 70-1308 C 50-280 H 50-320 D		REIS, H F. REIS, H F REIS, H F. REIS, H F REIS, H, F	7906070307 7906080193 7906080190 7906110440 7906070304	50-466 G 50-466 G 50-466 G 50-466 G 50-498 G	
RADER, R. H. RADER, R. H. RADER, R. H. RADER, R. H. RADER, R. H.	7906080141 7906040393 7906050156 7906070046 7906190124	50-478 H 50-478 M 50-375 H 50-445 H 50-445 H		REIS.H F REIS.E J REIS.E J REIS.E J REIS.E J	7904220458 7904040203 7904180743 7904230178 7904210248	50-466	
RADER, R M RADER, R M RADY, D J RADY, D J RAGAN, K M	7906260021 7906280232 7906190063 7906190072 7906010270	50-358 Q S0-498 M XPORTLIC XPORTLIC FOIA		REISS, J REISS, J REITLER, E K REIZEN, M. S REKEMEYER, P C	7906250232 7906260073 7906290817 7906230141 7906020179	50-312 0 50-312 H 27-47 C NUREO 40-299 C	
RANDALL, H, S RANDALL, J D RATTA, A D RAUCH, B RAUSCH, J K	7906290785 7906190270 7906140124 7906260623 7906070302	50-320 H 50-128 P 70-371 C 50-338 P 50-491 Q	7906260623	REKITO,N REMICK,F J REMICK,F J REMICK,F J REMICK,F J	7906120066 7906260554 7906260558 7906290560 7906290047	50-213 Q 50-275 T 50-275 T 50-275 T	
RAUSCHIJK RAUSCHIJK RAUSCHIJK RAYIMJ RAYMONDIHJJ	7906210078 7906140654 7906070302 7906150320 7906140207	50-414 G 50-416 G 50-491 G 50-594 A 50-387 G		REMICK.F J RENBERGER.D L RENBERGER.D L RENBERGER.D L RENBERGER.D L	7906290082 7906130085 7906080301 7906080312 7906120356		
RAYHOND: H J. RAYHOND: H J. READ: J READ: J B REAMO: J,	7706260551 7706260507 7706130372 7706260476 7706170071	50-245 G 50-244 G 50-320 P 50-320 P 50-275 G		RENBERGER, D. L RENBERGER, D. L RENZETTI, J. L REVELEY, H. T REYEB, L.	7706190469 7706270123 7706200368 7706180669 7706290623		
REAVIE, J. A REDEKER, S. J. REED, C REED, C REED, C	7906210153 7906270223 7906020014 7906070273 7906270493	50-267 R 50-133 8 50-254 Q 50-373 Q 50-320 Q		REYEB, L REYEB, L. A REYEB, L. A. REYEB, L. A REYNIER, R. H	7706270462 7706250153 7706260633 7706140616 7706140477		
REED, C REED, C REED, C REED, C REED, C,	7906140253 7906070241 7906180784 7906220158 7906260238	50-275 Q 50-454 Q 50-373 Q 50-496 Q 50-373 Q		REYNIER, R. H REYNOLDB, J REYNOLDB, H REYNOLDB, N B REYNOLDB, N B,	7906180602 7906180309 7906200613 79060389 7906250483		
riced.C. Reed.C Reed.C Reed.C. Reed.C.	7904120240 7906200335 7906250293 7906270179 7906260150	50~295 F 50-249 P 50-295 P 50-295 P 50-599 C		REYNOLDS, N S REYNOLDS, L E. REYNOLDS, L, E REYNOLDS, L E. REYNOLDS, L E.	7906260494 7906020173 7906180789 7906200228 7906220419		
Reed, C Reed, A. Reed, P. Reethof, Q	7906230118 7906200166 7906180770 7906280018 7906260637	50-295 Q 50-266 F NUREO 50-320 P ACRS	NUREO/CR-0714	RHODE, Q. K RHODE, Q. K. RHODE, Q. K. RIB, L. N	7906270198 7906270166 7906260400 7906210121		

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER
RIB, L N	7906210125	50-320 P		ROISMAN, A Z ROISMAN, A Z	7906250087 7906210357	70-2623 C 50-237 G	
RECCIO, T J RICHARDS, W J RICHARDSON, H D RICHMOND, J 8 RICKARD, C L	7908130191 7908270127 7908050424 7903200106 7908050198	PR 30-280 H PR DRG GA777		ROISHAN, A Z ROLLINS, J D ROLLINS, J D ROMNEY, K. M ROOD, H	7906210357 7906050415 7906210306 7906140352 7906040356	50-237 0 71-6678 C 70-1510 C 50-317 8 50-361 F	
RIDEN, M D RIDEN, M D RIDEN, M D RIDEN, M D RIDEN, M D	7906250026 7906290527 7906290573 79062901 41 7906260579	50-254 G 50-346 G 50-346 G 50-346 G		ROOD: H ROOD: H ROOD: H ROOD: H ROOD: H	7906010245 7906250206 7906250059 7906250078 7906250264	50-566 A 50-361 A 50-361 A 50-361 A 50-518 A	
RIDGWAY,K B RIEDERER,C F RIEDLINGER,B A RIGBERG,B RILEY,B H	7906260313 7906110054 7906290656 7906010119 7906200541	50-409 G HASTE MOT 70-734 C 50-359 G 50-324 G		ROOD, H ROOMEY, V L ROOMEY, V L ROOMEY, V L ROOT, L D	7906250314 7906010055 7906140324 7906250388 7906290150	50-361 A 50-271 P 50-298 P 50-333 P 50-331 F	
RILEY, B W RIECHLING, J L RITSHER, J A RITSHER, J A RITSHER, J A	7906250365 7906010197 7906080282 7906060246 7906190317	50-324 Q 50-316 8 50-443 A 50-443 I 50-443 I		ROREM. B.L. ROBENSTEIN. M ROBENSTHAL. A.S ROBENSTHAL. A.S ROSENSTHAL. A.S	7906210380 7906180704 7906220270 7906220320 7906060219	70-1308 C 50-320 P 50-346 M 50-346 M PROJ	NUREG/CR-0558
RITSHER, JA RITTS, F, H RITTS, F, H RITTS, F, H RITTS, F, H RIVARD, J, B	7906250344 7906040136 7906040150 7906040154 7906010344	50-443 I 50-445 K 50-445 K 50-445 K RES	NUREO/CR-0263	RDSENTHAL, A S ROSENTHAL, A S ROSENTHAL, A S ROSENBERG, A B ROSENBERG, A B	7906290031 7906290038 7906290090 7906210032 7906210018	50-338 T 50-338 T 50-338 T 50-482 Q 50-285 Q	
E L.GRAVIR E L.GRAVIR E L.GRAVIR W V.STRIBBOR M V.STRIBBOR	7904010351 7904230111 7904290792 7904230027 7904230019	RES NUREO NUREO 71-227 C 71-154 C	NUREG/CR-0421	RDSS.D A ROSS.D A RDSS.D A ROSS.D.A ROSS.D.A	7906040251 7906040253 7906110195 7906210155 7906200397	50-217 8 50-217 8 50-217 8 50-217 R 50-217 8	
ROBERTS.R M ROBERDS.H W ROBERDS.H W ROBERDS.H W ROBERDS.H W	7904290015 7904140010 7906230068 7906290716 7906290707	FOIA QAYYY QAYYY QAYYY QAYYY		ROSS: D A ROSS: D A ROSS: D A. ROSS: D A ROSS: D A	7906200400 7906200412 7906200419 7906280119 7906280122	50-217 8 50-219 8 50-219 8 50-219 6 50-219 8	
ROBERTS: H W ROBERTS: J F ROBERTSON: D D ROBINSON: G J ROBINSON: J K	7906290591 7906010009 7906280022 7906200572 7906110411	GA777 PROJ 30-320 P PRM 30-280 U		ROBS. E. E ROBS. D. F ROSS. D. F ROSS. D. F ROSS. D. F	7704020110 7704180427 7704180637 7704180631 7706260216	RES 50-320 0 50-320 0 50-320 0 50-339 A	7906020110
ROBINSON, H B ROCH, J RODI, J R RODI, J P RODI, J P	7906140494 7906210292 7906250254 7906250065 7906290845	50-261 8 50-320 F XPORTLIC XPORTLIC 50-574 A		ROSS. D ROSS. D F ROSS. D F ROSS. D. F	7906250101 7906270032 7906270149 7906270153	50-280 P 50-320 Q 50-320 P 50-320 P	
RODI, J P RODI, J P RODRIGUEZ, J P, RODRIGUEZ, R, J RODRIGUEZ, R, J	7906250067 7906250030 7906130291 7906120315 7906190335	XFORTLIC 50-574 A 50-206 R 50-312 P 50-312 P		ROSS, D F ROSS, D F ROSS, D F. ROSS, D, F	7906270154 7906070053 7906070055 7906070056 7906070061 7906250091	50-320 P 50-320 D 50-320 D 50-320 D 50-320 P	
RODRIGUEZ, R J RODRIGUEZ, R J ROE, D B ROE, D B ROE, L E	7906120275 7906190252 7906020243 7906290815 7906230127	50-312 P 50-312 R 50-592 G 50-592 G 50-346 G		ROSS.D F ROSS.D F ROSS.D F ROSS.D F ROSS.D F	7706270103 7706270136 7706270136 7706070062 7706270071 7706110018	50-280 P 50-320 P 50-320 P 50-320 D 50-320 P 50-320 D	
ROE, L. E ROE, L. E ROE, L. E ROE, L. E ROE, L. E	7906020036 7906070300 7906060280 7906060235 7906060272	50-346 F 50-346 F 50-346 F 50-346 F 50-346 F		ROSS, D F ROSS, D F ROSS, D F ROSS, D F ROSS, D F.	7906110025 7906110028 7906110035 7906110032 7906270015	50-320 G 50-320 G 50-320 G 50-320 G 50-320 P	
ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E. ROE, L. E.	7906210218 7906220298 7906260431 7906250342 7906270225	30-346 P 50-346 P 50-346 P 50-346 P 50-346 P		ROSE D F ROTH J ROTH J ROTH J ROTHE P H	7906110017 7906210221 7906210229 7906260347 7906180422	50-488 Q 50-320 P 70-344 C 70-371 C	
RDEDER, J. R RDEDER, J. R RDGERS, C. S RDGERS, M. RDGERS, M	7906050014 7906230007 7906040379 7906210055 7906150222	71-5790 C 71-9506 C 50-956 0 70-820 C 50-317 Q		ROUSE, L. C. ROUSE, L. C ROUSE, L. C ROUSE, L. C	7906230038 7906210261 7906210250 7906250485	70-1908 C 50-201 H 70-364 C 50-201 P	
ROGERS, M E ROGERS, R F ROGERS, L ROGERS, L ROGERS, L	7906290403 7906200332 7906070123 7906070163 7906070138	50-320 P 50-321 Q FOIA FOIA FOIA		ROUSE, L. C.  RUBY, L.  RUDOLPH, J J.  RUFF, A B.  RUFF, A. B.	7906210129 7906200223 7906220389 7906050140 7906220093	PRM 50-346 8 50-416 0 50-390 0	
ROHRER, E. ROISMAN, A Z ROISMAN, A Z ROISMAN, A Z ROISMAN, A Z	7706040239 7706010131 7706070333 7706070341 7706040065	50-346 8 50-237 0 70-2623 C 70-2623 C 70-2623 C	,	RUFF, A. B RUFF, A. B RUHLMAN, N. A. RUITER, G. H RUITER, G. H.	7906210110 7906190168 7906290383 7906060208 7906060220	50-395 G 50-320 P 50-305 S 50-305 S	
ROISMAN, A. Z ROISMAN, A. Z ROISMAN, A. Z.	7906020099 7906220194 7906250082	70-2623 C 70-2623 C 70-2623 C		RUITER, Q.H. RUITER, Q.H. RUBBELL, L B	7906280080 7906280086 7906040202	50-305 8 50-305 8 50-317 8	

AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
Russell, L. B Russell, L. B Russell, L. B	7904010200 7904050263 7904040289	50-318 8 50-318 8 50-318 8		SCHWEIDER, R R SCHWEIDER, R R	7906020239 7906060131	50-220 Q 50-220 Q	
Russell, L B Russell, L B Russell, L B Russell, L B Russell, L B	7906070296 7906080247 7906140348 7906250271 7906260338	50-317 8 50-317 8 50-317 8 50-318 8 50-318 8		SCHNEIDER, R R SCHNEIDER, R R SCHNEIDER, R R SCHNEIDER, R R SCHNEIDER, R, R	7906040029 7906290686 7906290800 7906050207 7906110178	50-220 Q 50-220 Q 50-220 R 50-220 B	
RUSSELL, H RUSSELL, H T PUSSELL, H T RYAN, C R RYAN, R Q	7904260439 7904130026 7905250074 7906070230 7904290770	50-318 B 50-280 P PR FOIA 50-320 H		8CHNEIDER, R BCHNEIDER, R BCHNEIDER, F W 8CHNEIDER, F, W 8CHNEIDER, F, W 8CHNEIDER, F, W	7906130005 7906180487 7906040079 7906120081 7906020193	50-220 S 50-220 S 50-272 Q 50-272 Q 50-272 Q	
Sabolia R Saccole. Sacchir O Sageril Salava. J	7906070184 7906200304 7906050200 7906260351 7906070214	50-387 Q PR NUREQ N' 50-463 Q 50-482 A	UREG/CR-0547	SCHNEIDER: F, W SCHNEIDER: F W SCHNEIDER: F W SCHNEIDER: F W	7906070389 7906270206 7906290774 7906220361 7906200394 7906150194	50-272	
SALAZAR, E A SALTZKAN, J SALTZKAN, J SALTZKAN, J SALTZKAN, J	7906210037 7906290177 7906010206 7906130343 7906190371	REVIEW ORP 50-320 J 50-294 J 50-112 J 50-129 J		SCHNELL, D F SCHOP IELD, R B SCHOP PHAN, H A SCHOP PHAN, H A SCHOP PHAN, H A	7906270265 7906120363 7906180511 7906180498	RES 50-250 S 50-251 S 50-335 S	7906270265
SALTIKAN, J SALIKAN, R, SAMPELB, M. D SAMPELB, M. D SAMPELB, M. D	7906200455 7906060219 7906070317 7906020255 7906190043	50-15: J PROJ 50-445 H 50-445 M 50-445 M		SCHOPPMAN, M A SCHOPPHAN, M A SCHOPPHAN, M, A SCHOPPHAN, M A SCHON, R B	7906180507 7906180555 7906180558 7906180620 7906230120 7906050115	50-335 8 50-335 8 50-250 8 40-9722 C	
SAMPELS, M D SAMPELS, M D SAMUELS, T K SAMUELS, T K SAMUELS, T K	7906020250 7906200576 7906280048 7906260234 7906120415	50-445 M 50-445 M REVIEW GRP REVIEW GRP 50-27 P		SCHULTZ, S SCHULTZ, W B SCHULTZ, R T SCHULTZ, D M BCHWAB, J C	7906140104 7906020188 7906230159 7906290512	50-522 0 10CFR 71-103 C 70-820 C 50-579 0	
SANDERS, F D BASSER, J SATTERFIELD, D E SATTERFIELD, R K SATTERFIELD, R.	7906130331 7906270168 7906110411 7904210346 7904160279	50-267 J COMMISSION 50-280 U 50-327 A 50-390 A		SCHNARTZ, H BCHWAB, O BCHWAB, O BCHWARTZ, B, A BCHWARTZ, B A	7906050095 7906230062 7906230060 7906290050 7906290054	XPORTLIC GA999 GA999 50-596 T 50-596 T	
SAUER M SAUER R C. SAUNDERS, J A. SAVOLATNEN, A W SCARAND, R A.	7906020202 7906020191 7906270073 7906220088 7906010324	50-358		SCHWARTZ, SA SCHWEIKER, RS SCHWENDIMAN, L SCHWENK, E, B, SCHWEITZER, DQ	7906210267 7906290285 7906290481 7906210020 7906040413	50-320 P 50-478 U NUREO RES	NUREO/CR-0629 7906210020 7906040413
SCARANO, R A SCARANO, R A SCARANO, R, A SCARANO, R A SCARANO, R A	7906010335 7906040358 7906140123 7905240076 7906010293	PROJ 40-8681 C 40-4492 C 40-8502 C 40-4492 C		SCHWEITZER, D. SCHWENGER, A. SCHWENGER, A. SCHWENGER, A. SCHWENGER, A.	7906260013 7906250351 7906200559 7906030419 7906200303	RES 50-280 P 50-295 P 50-3 P 50-344 F	7906240013
SCARAND, R A SCARAND, R A SCARAND, R A SCARAND, R. A. SCARAND, R. A.	7906050387 7906180786 7906020214 7906130509 7906180404	40-8722 C 40-8452 C PRGJ 40-3453 C 40-8681 C		BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A BCHWENCER, A	7906200298 7906020246 7906020247 7906020247 7906180782	50-261 P 50-250 P 50-250 P 50-250 P 50-275 P	
SCARANDIR A SCARANDIR A SCARANDIR A SCARANDIR A SCHADLERIT E,	7906040432 7906260634 7906180674 7906180677 7906210063	40-6659 C 40-8584 C 40-8681 B 40-8681 B 50-358 G		BCHHENCER, A BCHHENCER, A BCHHENCER, A BCHHENCER, A BCHHENCER, A	7906180790 7906010100 7906020205 7906040126 7906040130	50-275 P 50-348 F 50-250 F 50-261 P	
BCHADE, A R BCHADE, A R SCHAEFER, J, SCHAEFFER, M R. SCHAFER, J F	7906010242 7906150207 7906050043 7906180638 7906260209	PROJ PROJ 50-237 P BEGY 50-87 Q		BCHWENCER: A BCHWENCER: A BCHWENCER: A BCHWENCER: A BCHWENCER: A			
SCHEER, J. L. SCHEFFER, J. C. SCHELL, T. A. SCHENDEL, K. R. SCHERER, A. E.	7906080254 7906140591 7906190497 7906200233 7906070277	50-298 8 50-2 G ' 71-213 C 40-8502 C 50-470 A		SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A SCHWENCER, A			
Bicherer, A. E. Bicherer, A. E. Bichierling, H. Bichierling, H. Bichmidt, A. D.	7906120281 7906110290 7906130381 7906200022 7906120338	TOPREP 50~309 P 50~320 P 50~320 P 50~250 S		SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A			
Schildt, A.D. Schildt, A.D. Schildt, A.D. Schildt, A.D. Schildt, A.D.	7906120348 7906120354 7906180510 7906180494 7906180304	50-250 8 50-250 8 50-251 8 50-335 8 50-335 8		SCHMENGER: A SCHMENGER: A. SCHMENGER: A. SCHMENGER: A. SCHMENGER: A			
Schidt, a d. Schildt, a d. Schildt, a d Schileder, J R. Schileder, J R	7906180554 7906180557 7906180613 7906070204 7906130122	50-335 8 50-335 8 50-250 6 50-286 0		SCHMENCER, A SCHMENCER, A SCHMENCER, A SCHMENCER, A SCHMENCER, A			
BCHRITT, R. P BCHNAUTZ, C. E. BCHNEIDER, S	7906140434 7906270083 7906070337	50-344 S XPORTLIC 50-250 H		SCHWENCER: A SCHWENCER: A SCHWENCER: A SCHWENCER: A			

AUTHOR	ACCEBSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
SCINTO, J F	7906210047	50-320 G		SEYFRIT, K V			
SCINTO, J F	7906290301	50-320 P		SEYFRITIK V SEYFRITIK V	7906120070 7906120071 7906120072	50-298	3 3 3
SCOFIELD, N R SCOFIELD, N R SCOTT, L W SCOTT, J M	7904050086 7904290505 7904150235 7904040383	NUREO RES 50-464 0		SEYFRIT, K V SEYFRIT, K V	7904120075 7904120079	50-267 (	3
SCOTT, J H	7906040390	50-466 0		SEYFRIT, K V SEYFRIT, K V	7906230055 7906110083	0A999 50-313 (	
SCOTT, J H SCOTTIE, C, D	7906040394 7906290457	50-446 Q 50-320 P		SEYFRIT, K V SEYFRIT, K V	7904110084 7906110086	50-298 ( 50-285 (	
SCOTT.W J SCROOGINS.R M	7904210395 7904290326	50-320 P 70-1308 C 50-320 P		SEYFRIT, K V	7906110088 7906250003	50-267 ( 50-131 (	1
SCROGGINS, R M SCROGGINS, R M	7906270190 7906270139	50-320 P 50-320 P		SEYFRIT, K V SEYFRIT, K V	7906250004 7906250006	50-274 0 50-188 0	
SECKMAN, P E SEELINGER, J L SEGER, R K	7906150316 7906070366 7906270241	50-331 J 50-289 S 50-245 J		SEYFRIT, K V SEYFRIT, K V	7906250007 7906250000	50-148 0 50-262 0	1
SEGER, A M	7906280091	50-245 J		SEYFRIT, K V SEYFRIT, K V	7904250009 7906250010	50-252 G 50-284 G	ı
SEGER,R M SEHMEL,G A SEIDE,P SEIDLE,W C	7906260480 7906290481 7906020175	U E1S-08 NUREO OBRUN	NUREO/CR-0629 NUREO/CR-0793	SEYFRIT, K V	7706250012 7706250013 7706250014	50-192 G 50-39 G 50-112 G	1
	7906050056	50-482 G		SEVFRIT, K V SEVFRIT, K V	7906250015 7906250016	50-72 G 50-313 G	
SEIDLE, H C	7906050073 7906220223	50-482 G		SEYFRIT, K V	7906250018 7906250019	50-458 G 50-498 G	
SEIDLE, W C SEIDLE, W C, SEIDLE, W C	7906250044 7906210025 7906200474	50-498 Q 50-482 Q 50-445 Q		SEYFRIT, K V SEYFRIT, K V	7906250021 7906250022	50-482 G	
SEIDLE, W C SEIDLE, W C	7906180152	50-458 \$		SEYFRIT.K V SEYFRIT.K V	7906250023 7906250024	50-298 G 50-285 G	
SEIDLE, W C SEIDLE, W C SEIDLE, W C	7906180156 7906180160 7906180161	50-498 8 50-482 8 50-382 8		SEYFRIT, K V	7906250025 7906250027	50-267 G 50-445 G	
SEIDLE, W C	7906180163	50-445 8		SEYFRIT, K V	7906130065 7906130067	30-458 G 50-498 G	
SEIDLE, W. C SEIDLE, W. C	7906120143 7906130027	50-382 Q 50-482 Q		SEYFRIT.K V	7906130069 7906130071	50-482 G	
SEIDLE, W.C SEIDLE, W.C	7906140165 7906120138	50-482 Q 50-498 Q		SEYFRIT.K V	7906130073	50-445 Q	
SEIDLE, W C	7906180174	50-45B B		SEYFRIT, K V	7906200039 7906200041	50-313 G 50-298 G	
SEIDLE, W C SEIDLE, W C	7904180176 7904180177	50-498 S 50-482 S		SEVFRITIK V BHA.W T	7906200043 7906050098	50-267 Q NUREQ	NUREG/CR-0001
SEIDLE, H C	7906180182 7906180184 7906180241	50-382 8 50-445 8 50-458 8		SHACKLETON, D C SHAFER, W D	7906150079 7906140205	50-397 Q 50-312 Q	
SEIDLE, H C	7906180243 7906180245	50-498 8		SHALLER, D V SHALLER, D V	7906010194 7906110235	50-314 S 50-315 S	
SEIDLE, W C. SEIDLE, W C. SEIDLE, W C	7906180247 7906180250 7906180318	50~482 S 50~382 S 50~445 S 50~458 S		SHALLER, D V SHALLER, D V SHALLER, D. V.	7906120219 7906130334	50-315 R 50-315 B	
SEIDLE, W C	7906180320	50-498 8		SHALLER, D V SHALLER, D V	7906190297 7906190295	50-316 B	
SEIDLE, W C SEIDLE, W C SEIDLE, W C	7906180324 7906180326 7906180331	50-482 8 50-382 8 50-445 8		SHALLER, D V SHAO, L	7906190241 7906190292 7906060089	50-316 R 50-315 R FOIA	
SEIDLE, W C	7906290589	50-445 Q		SHAPAR, H K SHAPAR, H K	7906290368 7903240402	50-320 J 10CFR	
SEKULER, S N SEKULER, S N	7906070342 7906080128	27-39 C 30-295 G		SHAPAR, H K SHAPAR, H K	7905250062 7905250071	10CFR 10CFR	
SEKULER, S N SEKULER, S N SEKULER, S N	7906010266 7906280159 7906290613	50-275 G 50-275 G 50-275 G		SHAPAR, H K SHAPAR, H K	7905250075 7905250083	10CFR 10CFR	
SELLS, D E SEMKEN, R S.	7906010274 7906260031	50-396 D		SHAPAR, H K	7905230068 7903040311	10CFR 50-320 P	
SENOSTAKEN, D J SERNE, R J SERPAN, C Z	7906290031 7906290545 7906020148 7906270172	RE8 30-382 B NURE0 50-320 P	7905260031 NUREO/CR-0658	SHAPAR, H K, SHARP, D A	7906180116 7906180749	BECY NUREO	SECY-79-305 NUREO/CR-0712
SEHELL, R B	7906200319	40-7869 C		SHAUB, E T SHAUB, E T	7906210203 7906290418	50-320 P	
SEWELL, R B SEWELL, R B SEWELL, R B	7906010156 7906190131 7906220135	40-8698 C 40-8698 C 40-8698 B		SHAM, D T SHEA, K H SHEA, J R	7906020102 7906150405 7906270819	NUREG 50-331 J 50-574 A	NUREG/CR-0799
SEYFRIT, K V	7906290232	I&E		ehea. J r Shea. J r	7904070101 7906250077	BECY XPORTLIC	SECY-79-241
SEYFRIT, K V SEYFRIT, K V	7904290237 7904140008	1&E GA799		SHEA, J R SHEA, J R	7904020017 7906180739	SECY SECY	SECY-79-280
SEYFRIT, K V	7906230063 7906290708 7906060097	0A999 0A999 0A999		SHEA, J R SHEA, J R	7904180802 7904020101	BECY	8ECY-79-282 8ECY-79-286
SEYFRITIK V. SEYFRITIK V.	7906060094	9A999		SHEA, JR SHEA, JR	7906180754 7906180771	SECY SECY	8ECY-79-289 8ECY-79-249A
BEYFRIT, K, V BEYFRIT, K, V BEYFRIT, K, V.	7904290695 7904230030 7904210029 7904110001	GA799 GA799 50-320 P 50-458 G		SHEA, JR SHEA, JR SHEA, JR	7906060071 7906200002	BECY	8ECY-79-233A 8ECY-79-200A
SEYFRIT, K V	7906110002	50-498 G		SHEA, J R	7906010146 7906180615	BECY	8ECY-79-297 8ECY-79-310
SEYFRIT, K V. SEYFRIT, K V	7906110003 7906110004	50-482 Q 50-382 Q		SHEA, J R SHEA, J R	7904040074 7904040078	SECY	8ECY-79-307 8ECY-79-306
SEYFRIT, K V SEYFRIT, K V	7906110005 7906210109	50-445 Q		SHEA, J R	7906180050	BECY	SECY-79-308
SEYFRIT, K V.	7906130137			BHEA, J R BHEA, J R	7906250034 7906060067	30-574 A BECY	8ECY-79-157B
SEYFRIT, K V SEYFRIT, K V	7906120063 7906120063	30-313 G		SHEA, J. R SHEA, J. R	7906230086 7906070367	SECY XPORTLIC	SECY-79-280A
SEYFRIT, K V BEYFRIT, K. V	7906120067 7906120068	50-498 Q		SHEA: J. R	7906290496	BECY,	SECY-79-328
, , , , ,	. , va LEWVOO	50~482 Q		SHEA, J. R	7906230091	SECY	8ECY-79-077A

AUTTUA	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	8UBJECT CATEGORY	REPORT NUMBER
SHEA, JR SHEA, JR SHEA, JR SHEA, JR	7906290531 7906290571 7906290714 7906290604	BECY BECY BECY BECY	BECY-79-329 BECY-79-014A BECY-79-248A	SLATER, M SLICKER, F K SLOBODIEN, M J.	7906120006 7906190034 7906070006	50-510 D 50-445 M 50-320 P	
SHEA, J J SHEA, J J SHEALY, H O SHEDLOSKY, J T. SHEDLOSKY, J T	7904020166 7906260087 7906070354 7906010047 7906260551	50-245 P 50-244 P 27-47 C 50-245 Q 50-245 Q	GEO!=// KIGH	SLOBODIEN, M J SLOBODIEN, M J SLOBODIEN, M J SLOBODIEN, M J SLOBODIEN, M J	7906200413 7906200408 7906220124 7906210212 7906200410	50-320 P 50-320 P 50-320 P 50-320 P	
SHELLEY, H J SHEPARD, A M SHEPHERD, R E SHEPHERD, R E	7906200581 7906290782 7906290667 7906140193 7906250308	40-8027 C 50-443 Q 50-443 Q 50-309 Q 70-33 C		SLOBODIEN, M J SLOBODIEN, M J SKEAL, L P SKEAL, L P	7904220078 7906220279 7906220082 7906200220 7906200226	50-320 P 50-320 P 50-320 P 71-223 C 71-223 C	
SHERMAN, F SHERMAN, F L SHERMOOD, O O. SHERMOOD, O O. SHERMOOD, O O.	7904260561 7904200087 7904180358 7904130308 7904040178	70-33 C 70-33 C PR TOPREP TOPREP		SMITH, D N SMITH, R SMITH, T SMITH, T SMITH, G	7906270013 7906140078 7906140080 7906260557 7906070110	50-280 H 71-292 C 71-292 C 40-8492 C COMMISSION	
SHERHOOD, G O SHEWHON, P G SHEER, H SHEER, H	7904210161 7906290663 7906290655 7906260042 7906060269	TOPREP ACRS ACRS RES 50-407 S	7906260042	SHITH, O L. SHITH, R I SHITH, I W SHITH, I W	7904120313 7906060247 7906210339 7903140067 7903140059	50-237 8 50-311 A 50-331 P 50-400 T 50-400 T	BCL-585-7
SHIMSHAX.R E SHIPLER.D B SHIVELY.C N SHIVELY.C N SHIVELY.C N	7906200380 7906020105 7906180568 7906180576 7906180587	50-409 P NUREQ 50-368 8 50-368 B 50-368 B	NUREG/CR-0424 V2	SHITH, I. W SHITH, I W SHITH, I W SHITH, I W SHITH, B H	7703140114 7704010142 7704270277 7704270473 7703200314	50-400 T 50-400 O 50-305 O 50-400 O 50-471 O	
SHEVELY, C N SHEVELY, C N SHEVELY, C N SHEVELY, C N SHEYOR, P	7904180607 7904190265 7904190273 7904250266 7906260562	50-313 B 50-313 R 50-348 R 50-313 S XPORTLIC		SHITH, GH SKITH, GH SKITH, GH SKITH, GH	7904050011 7904010144 7904220317 7904040225 7904040241	50-471 C 50-471 C 50-320 P 50-320 H 50-320 P	
SHON, F J SHORB, E K SHORB, E K SHORB, T E SHORB, T E	77040403B7 7706060063 7706230040 7706050355 7706050346	50-556 G 50-367 G 50-367 G 50-285 P 50-285 P		SMITH, 0 H SMITH, 0 H SMITH, T H SMITH, G H SKITH, G H	7904200494 7904040203 7904140164 7904130048 7904220045	50-320 P 50-320 P 50-29 Q 70-135 C 50-320 H	
SHORT, TE SHORT, TE SHORT, TE SHORT, TE SHORT, TE	7906060278 7906060275 7906130011 7906120224 7906120387	50-265 P 50-265 P 50-265 P 50-265 P 50-265 P		SMITH, GH SMITH, R. H. SMITH, GH SMITH, GH SMITH, GH	7906220311 7906210215 7906220151 7906220332 7906260340	50-320 P 50-320 P 50-320 H 50-320 P 70-371 C	
SHORT, TE SHORT, TE SHORT, TE SHORT, TE SHORT, TE	7906130316 7906120335 7906150313 7906190491 7906250288	50-285 1 50-285 R 50-285 P 50-285 Q 50-285 P		SHITH, OH BHITH, OH BHITH, OH BHITH, OH	7906140592 7906150209 7906180648 7906210288 7906210289	70-820 C 50-245 Q 70-820 C 70-364 C 70-364 C	
SHORT, T E. SHORT, T E. SHORT, T E. SHRIVER, B L. SHUTT, R	7906220368 7906260168 7906260173 7906220239 7906200619	50-285 Q 50-285 P 50-285 F 50-62 8 50-576 Q		8HITH, Q H 8HITH, G H 8HITH, G H 8HITH, G H 8HITH, G H	7906140639 7906290837 7906180141 7906180171 7906140579	70-33 C 50~333 G 50-27 G 50-29 G 70-820 C	
SIDEBOTTOM. H J SIESS. C P SILBERO. J A. SILBERO. J, A SILBERO. J, A	7906260364 7906060189 7906230107 7906230110 7906230112	50-463 G AGRB 50-277 G 50-277 G 50-277 G		EMITH, GH EMITH, GH EMITH, GH EMITH, T	7706150200 7706180621 7706210024 7706210005 7706270704	50-245 G 70-820 C 50-320 P 50-320 P 50-220 G	
SILDER, R. SILVER, R. D. SIHON, L. SIHON, L. SIHON, R. E.	7906180293 7906020155 7906280156 7906080303 7906230050	50-275 Q 50-255 P 71-9132 B 50-346 F 50-280 H		C C'HLINS C'HLINS C'HLINS C'HLINS C'HLINS	7906010041 7906290181 7906290044 7906290527 7906290110	0 44E-05 50-344 0 45C-05 50-344 0 44E-05	
Sinclair i Sinclair i k Sink, J. E Sink, J. E Sinkin, L. A	7906250409 7906140572 7906140044 7906140048 7906070169	50-255 Q FR 71-313 C 71-313 C 50-478 Q		D, HTIMB D, HTIMB D, HTIMB D, L, HTIMB D, L, HTIMB	7906290573 7906290141 7906290441 7906290484 7906280330	50-346 G 50-346 G 50-346 G 50-346 G 50-282 G 40-7455 C	
SINKIN, S.A. SINKIN, L.A. SJOGREN, R. M. SJOGREN, R. H. SJOGREN, R. M.	7906200601 7906260035 7906190308 7906190311 7906190314	50-498 G 50-498 G 50-309 R 50-271 R 50-27 R		SMITH, R D SMYLIE, J, H SNAIDER, R P SNAIDER, R P SNAIDER, R P	7904150148 7904220240 7904240107 7904200280 7904290754 7904080297	50-320 P 50-280 P 50-320 P TOPREP	
SKARUPA, J. D. SKILLHAN, M SKINNER, L. W. SKOLOS, J. L. SKOVHOLT, D. J.	7706060084 7706180185 7706010078 7706270381 7706250114	XPORTLIC 50-482 A FOIA 50-320 P 50-280 P		BNEDECOR: E BNIEZEK: J H BNOOKS: J H BNOOK: B A BNOOK: B, A	7906130489 7906120408 7906050438 7906020061	50-344 J 50-320 P 50-568 A 50-244 S	YAEC-1149
Skrutski, R. M. Skrutski, R. H. Skrutski, R. H. Skrutski, R. M. Slabackil, A	7906190132 7906190007 7906130430 7906200562 7906290428	50-498 G PRDJ 50-498 G 50-338 G 50-320 P		EMON, BA BNYDER, HL BNYDER, OL, BNYDER, OL, BNYDER, OL	7906290195 7906220494 7906070379 7906130089 7906210003	50-244 B 71-306 C 50-320 H 50-320 H 50-146 H	
SLACK, B. T. SLACK, S. T.	7906070240 7906190251	50-127 P 50-127 P		SNYDER: 8 SNYER: H L. SOBEL: P	7906020234 7906220493 7906210301	10CFR 71-306 C 50-361 A	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOGRY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
8080N'F 7	7906060141 7906110304	TOPREP TOPREP		STALLINGS, C M	7906110207	50-338 B	
8080N.L J 8080N.L J 8080N.L J 8080N.L J	7906130239 7906130237 7906060149 7906060166 7906110260	TOPREP TOPREP TOPREP TOPREP TOPREP		STALLINGS, C M STALLINGS, C M STALLINGS, C M STALLINGS, C M STALLINGS, C M	7906180491 7906180517 7906180543 7906180536 7906200386	50-338 R 50-280 R 50-338 S 50-280 G 50-338 S	
BOBON.L J BOBON.L J BOHINKI.S M BOHINKI,S H	7906190421 7906200182 7906030062 7906010301 7906200509	TOPREP TOPREP 50-592 0 50-592 0 50-466 0		STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M STALLINGS.C M	7906200398 7906210210 7906210235 7906250261 7906250311	50-280 B 50-280 P 50-338 P 50-338 P 50-280 P	
SOHINKI, S H SOHINKI, S H SOHINKI, S H SOHINKI, S H SOINSKI, A J	7906040114 7906070326 7906250259 7906230175 7906110047	50-466 0 50-466 0 50-437 0 50-466 0 WASTE MOT		STALLINGS, C M STALLINGS, C M STANCIL, R STANCIL, R STARKEY, R B.	7906270121 7906290196 7906120429 7906130023 7906070200	50-280 G 50-338 8 50-366 R 50-321 R 50-261 8	
SOLBERO, D SOMERVILLE, Q V SON, B D SOONG, A L SOUCY, A R	7906280019 7906020237 7906150029 7906040395 7906250267	50-320 P 40-8714 C XPORTLIC 40-8027 C 50-29 I		STARKEY, R B STARKEY, R B STARKEY, R B STARKEY, R B STEARNS, C F	7906070265 7906140494 7906180506 7906270176 7906290416	50-261 8 50-261 8 50-261 8 50-261 8 50-320 P	
BOUTHERS, R L SPANGLER, R G SPANGLER, R G SPANGLER, R G SPARKS, E	7906070207 7906290467 7906150035 7906290627 7906190476	71-284 C 50-313 G 50-313 G 50-313 G 71-47 C		STELLO, V STELLO, V STELLO, V STELLO, V	7703120401 7706130481 7704270001 7706040372 7706010211	GEN TEC IB 50-320 P 50-320 P GEN TEC IB ORG	
SPEIS.T P SPEIS.T SPENCER.T L SPENCER W C SPENCER.W C	7906050417 7906280035 7906040277 7906160070 7906070295	50-247 P 50-320 P 50-272 E 50-338 G 50-280 P		STELLO, V STEPENSON, B B STEPHEN, W R STEPHENSON, B B	7906290709 7906200370 7906200297 7906200294 7906050350	50-280 P 50-237 B 71-39 C 71-39 C 50-237 B	
SPENCER, W C SPENCER, W C SPENCER, W C SPENCER, W C SPENCER, W C	7706110174 7706130352 7706150160 7706200102 7706220268	30-280 P 30-280 P 30-280 P 30-280 P 30-280 P		STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B	7906050245 7906050268 7906120310 7906200404 7906120376	50-237 8 50-237 8 50-237 8 50-237 8 50-237 8	
SPENCER, W C, SPENGER, O S SPENCER, O S SPENCER, O. S SPENCER, O. S	7906290327 7906220133 7906150058 7906140210 7906210342	50-280 P 50-460 G 50-397 Q 50-361 G 50-361 G		STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B STEPHENSON, B B	7906180512 7906150336 7906190418 7906190437 7906210220	50-249 8 50-10 R 50-249 8 50-249 8 50-237 P	
BPENCER, O. 8 SPESBARD, R. L. SPESBARD, R. L. SPESBARD, R. L. SPESBARD, R. L.	7906260520 7906250026 7906250153 7906260579 7906260539	50-508 Q 50-254 G 50-10 Q 50-346 Q 50-346 Q		STEPHENSON: 8 B STEPHENSON: 8, B STEPHENSON: 8 B STEPHENSON: 8 B STEPHENSON: N A	7906190289 7906220282 7906220365 7906270152 7906200271	50-10 8 50-237 8 50-237 8 50-249 8 50-302 R	
SPESBARDIR L SPITALNYIB S, SPITALNYIB S, SPOREIT W SPRATLEYIW A	7906140596 7906040098 7906210120 7906290178 7906050221	50-373 0 70-2623 C 70-2623 C RES NUREO	7906290178	STEPTOE, P STEPTOE, P STERN, W C STERN, W C STERN, W C	7906210252 7906210387 7906050111 7906190112 7906220172	50-237 Q 50-599 Q XPORTLIC XPORTLIC XPORTLIC	
SPREADBURY, W N STACK, D W. STADE, K L STADE, R E STADE, R E	7906140470 7906260608 7906270822 7906180062 7906020215	50-510 O NUREO 50-466 G REGOD REGOD	NUREG/CR-0465	STERNBERT, D M STETKA, T F STETKA, T F STEVENSON, H M STEVENS, J. R.	7906260478 7906260061 7906260175 7906160066 7906190010	50~320 P 50~20 G 50~271 G 50~362 G 50~568 I	
BTAFFA, R. W STAFFA, R. W STAFFA, R. W STAFFA, R. W STAFFA, R. W	7906200527 7906050085 7906050003 7906050108 7906140081	50-321		STEVENSON: R L STEVENSON: R L STEVENSON: R L STEWART: W P STEWART: W. P.	7906250046 7906270030 7906260638 7906180366 7906110064	70-820 C 70-1151 C 70-1113 C 50-302 Q 50-302 Q	
STAFFA,R W STAFFA,R W. STAFFA,R W. STAFFA,R W. STAHLE,G.R.	7906140436 7906180077 7906200532 7906140230 7906060007	50-321 Q 50-424 Q 50-321 Q 50-424 Q 50-390 A		STEWART, W.P STEWART, W.P STEWART, W.P STEWART, W.P. STEWART, W.P.	7906030164 7906290146 7906290739 7906290726 7906290730	50-302 Q 50-320 Q 50-302 Q 50-302 Q	
STALLINGS, C M STALLINGS, C M STALLINGS, C, M STALLINGS, C, M, STALLINGS, C M	7906250347 7906250130 7906260143 7906180312 7906190194	50-280 P 50-281 Q 50-280 Q 50-338 Q 50-280 Q		STEWART, W.P. STEWART, W.P. STEWART, W.P. STEWART, W.P. STEWART, W.P.	7706110152 7706120399 7706130014 7706120236 7706180505	50-302 P 50-302 8 50-302 B 50-302 P 50-302 8	
STALLINOS, C. M STALLINOS, C. M, STALLINOS, C. M STALLINOS, C. M STALLINOS, C. M	7906010237 7906290552 7906130224 7906050255 7906050293	50-338 P 50-280 G 50-280 P 50-338 B 50-338 B		STEWART, W.P. STEWART, W.P. STEWART, W.P. STEWART, W.P. STEWART, W.P.	7706190298 7906200267 7906220201 7906220204 7906260220	50-302 B 50-302 R 50-302 Q 50-302 F 50-302 F	
STALLINGS, C. M STALLINGS, C. M STALLINGS, C. M STALLINGS, C. M, STALLINGS, C. M,	7906030309 7906030318 7906030363 7906060124 7906070306	50-280 8 50-281 P 50-280 P 50-280 Q 50-280 J		STEWART, W P. STEWART, W P STEWART, W P. STEWART, W P. STEWART, W P.	7906250296 7906280120 7906260515 7906280093 7906080285	50-302 B 50-302 P 50-302 G 50-302 P	
8 (ALLINGS, C.M. STALLINGS, C.M STALLINGS, C.M. STALLINGS, C.M.	7906140415 7906070242 7906110196 7906110198	50-281 8 50-338 8 50-338 8 50-338 8		STEWART, W.P. STEWART, W.P. STEWART, W.L. STEWART, W.L.	7906120386 7906280142 7906050312 7906190399	50-302 P 50-302 S 50-280 S 50-280 S	

AUTHOR	ACCESSION NUMBER	SUBJECT CATEOURY	REPORT NUMBER	AUTHOR	ACCEBBION NUMBER	SUBJECT CATEGORY	REP DRT NUMBER
STENART. W L. STENART. R B STENART. R C STORR. J P STORR. J P STORR. J P	7706200405 7706180717 7706220241 7706270134 7706210243 7706220192	50-280 8 NUREG 50-382 0 50-320 P 50-320 P 50-320 F	NUREG/CR-06B3	TAM, P TAM, P TAM, P TAM, P TAMELING, T	7906150442 7906180003 7906190197 7906220186 7906290280	ACRS ACRB 50~320 D FDIA 50~346 Q	
STOKR, JP STOKR, JP STOKR, JP STOKR, JP.	7906220057 7906210148 7906210152 7906200385 7906210158	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P		TAMBLING, T TAMBLING, T TAMBLING, T TAMBLING, T	7906290044 7906290527 7906290110 7906290623	50~346 Q 50~346 Q 50~346 Q 50~346 Q	
STOKE, J P STOKE, J P STOKE, J P STOKE, J P.	7906260232 7906200391 7906210164 7906210169 7906210176	50-320 G 50-320 G 50-320 P 50-320 P 50-320 P		TAMBLING, T TAMPLIN, A R TAPIA, J. I TAPIA, J. I TAYLOR, V.	7906260639 7906070341 7906200324 7906210018 7906220170	50~346 G 70~2623 C 50~445 G 50~265 G	
STOHR, JP STOHR, JP STOLZ, JF STOLZ, JF	7906210181 7906220287 7906290842 7906230125 7906040419	50-320 P 50-320 P 50-333 Q 50-346 Q TOPREP		TAYLOR, J H TAYLOR, J H TAYLOR, J H TAYLOR, J, H TAYLOR, J, H	7906130301 7906230089 7906010231 7906080306 7906120246	50-320 P TOPREP TOPREP 50-313 P 50-312 P	
STOLZ, J F STOLZ, J F STOLZ, J F. STOKE, H A STOODLEY, D Q	7906250113 7906250081 7906250160 7906210076 7906290165	50-275 A 50-358 A 50-275 A GA777 50-471 G		TAYLOR, J H	7906190388 7906180532 7906180483 7906190452 7906260478	TOPREP TOPREP TOPREP 50-320 P	
STOREY, K STRACCIA, F P STRATFORD, R J. STRATMAN, R A	7906210380 7906290831 7906120366 7906120401 7906180499	70-1308 C 71-9070 C 50-116 J 50-336 S 50-336 S		TAYLOR. J.H YAYLOR. J.H TAYLOR. J.H TAYLOR. R TAYLOR. R	7906210184 7906260359 7906280115 7905310008 7906200524	TOPREP TOPREP TOPREP 70-597 C	
STRATHAN.R A  STRAUSS, P L  STREETER, J F  STREETER, J F.	7906250482 7906210143 7906200486 7906260330	BECY 50-320 P 50-346 G 50-282 G	SECY-A-77-24	TEDESCOIR L TEDESCOIR L TEDESCOIR L TEDESCOIR L	7906290189 7906230177 7906260166 7906200073	50-320 A 50-446 G 50-568 G 50-320 P	
STREETER, J.F. STREETER, J.F. STREETER, J.F. STREEU, R.R. STURGES, B.R.	7906230117 7906260633 7906140616 7906020008 7906180768	50-346 G 50-237 G 50-155 G PR PR		TEDESCO.R L TEDESCO.R L TELFORD, J T TEMPEST, L TENZER, B E	7906280265 7906060191 7906050187 7906190035	50-320 P 50-320 P 40-3453 C GA999	
SUERHANN, J F. SUERKE, K E SUERKE, K E SUERKE, K E	7906120347 7906050057 7906290248 7906290259 7906290273	50-336 R 50-454 Q 50-320 A 50-320 A 50-320 A		TERFILAK, M. B TEGTERMAN, T F THADANI, M THADANI, A C THADANI, A C THADANI, A C	7906190504 7906180137 7906110102 7905250210 7905230087 7906290170	50-267 Q WASTE HOT 50-285 P 50-285 P	
SULTIVAN, J. F SULLIVAN, T. J SULLIVAN, T. J. SULLIVAN, R. F. SULZER, R. C.	7906270036 7906270036 7906070416 7906130204 7906180714 7906230171	50-320 A 50-280 H PR PRM 50-259 Q 71-34 C		THARP, W E THAYER, D. W. THOMAS, E B. THOMAS, D. Q THOMAS, R D	7906160007 7906200346 7906290584 7906290673 7906010254	GA799 71-145 C 50-220 P NUREO 50-312 G	NUREO/CR-0710
SUTHERLAND, J. T GUTHERLAND, J. T. GUTHERLAND, J. T. SUTHERLAND, J. T. SUTHERLAND, J. T.	7906070072 7906070079 7906140626 7906180673 7906040177	50-280 Q 50-414 Q 50-348 Q 50-280 Q 70-143 C		THOMAS, CO THOMPSON, JF THOMPSON, D. THOMPSON, D THOMPSON, D	7906270078 7906050098 7906060178 7906060181 7906050061	50-320 0 NURE0 50-320 8 50-320 8	NUREO/CR-0001
SUTHERLAND, J T SUTHERLAND, J T SUTHERLAND, J. T SUTHERLAND, J. T SUTHERLAND, J. T	7906150457 7906070318 7906200609 7906070050 7906260516	50-390 Q 70-1201 C 50-281 Q 50-324 Q 50-302 Q		THOMPSON, D THOMPSON, D THOMPSON, D THOMPSON, D	7906220153 7906130446 790/	50-320 B 50-320 P	
SUTHERLAND, J T SUTHERLAND, J T SUTHERLAND, J T SUTHERLAND, J, T SUTHERLAND, J T	7906210419 7906260493 7906040172 7906260088 7906200138	50-338					
SUTHERLAND, J. T SUTHERLAND, J. T SUTHERLAND, J. T SUTTON, J. N. SUTTON, J. N.	7906260513 7906260354 7906290537 7906180263 7906070026	50-302					
H L'HOTTUB W L'HOTTUB A E'HOEBREYB E H'HAND E H'HAND	7906230073 7906050177 7906190296 7906010328 7906220081	QA779 QA777 50-315 R 50-518 Q 50-395 Q					
Smanbon, D. T. Smanbon, E. R Smart, F. E. Smart, F. E Smart, F. E	7906220125 7906250138 7906070182 7906190336 7906190395	50-338 0 50-409 0 50-267 0 50-267 P 50-267 F					
SHART, F.E. BHICK, C.R. SHITZER, D.G SZUKIEHIEZ, A.J. TALHAR, B.	7906290267 7906140610 7906290812 7906160051 7906020087	50-267 P REDOD 50-213 G TOPREP PROJ	0EFR-003V2				

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REJ NUI
TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C	7906070282 7906070291 7906080250 7906120424	50-324 8 50-324 8 50-324 8 50-324 8		TURNAGE, K. Q. TURNAGE, K. Q. TURNER, J. Q.	7906260596 7906290673 7906070221	NUREG NUREG 10CFR	NUREG/CR- NUREG/CR-
TOLLISON, A C	7904110188 7906110192 7906110232 7906120388 7906150174	50-325 8 50-325 8 50-324 8 50-324 8 50-325 8		TURNER, J G TURNER, E A TURNER, E A TURNER, E A TURNER, E A	7905240131 7906210107 7906120141 7906120390 7906120430	10CFR 50-498 G 50-478 G 50-498 8 50-498 8	
TOLLISON, A C	7906150183 7906150201 7906150241 7906150250 7906140314	50-324 S 50-325 S 50-325 S 50-325 S 50-325 S		TURNER, E A TURNER, E A TURNER, E A TUTHILL, B J TUTHILL, B J	7906130007 7706130314 7906220367 7906260043 7906290637	50-498 6 50-498 K 50-498 8 50-331 Q 50-331 Q	
TOLLISON A C TOLLISON A C TOLLISON A C TOLLISON A C TOLLISON A C	7906140533 7906180514 7906200367 7906220330 7906220375	50-325 6 50-324 6 50-325 8 50-325 8 50-324 8		TUTHILL:8 J THITE:0 M UGOLINI:D J UGOLINI:D J UHRIO:R E	7906260094 7906020204 7906140561 7906220453 7906070226	50-331 Q PR 50-304 8 50-304 8 50-250 9	
TOLLISON, A C TOLLISON, A C, TOLLISON, A C TOLLISON, A C TOLLISON, A, C	7906220409 7906220420 7906220294 7906220400 7906270169	50-324 8 50-325 8 50-324 8 50-324 8		UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E UHRIG, R E	7904070363 7904130434 7904180195 7906230142 7906050019	50-250 Q 50-250 Q 50-335 Q NUREO 50-250 P	
TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C TOLLISON, A C	7706270201 7706280131 7706280088 7706280101 7706270362	50~324 8 50~325 8 50~325 8 50~325 8 50~324 8		UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE UHRIO, RE	7904020184 7906050451 7904200491 7904250129 7904230006	50-250 G 50-335 G REOOD PRM 50-335 G	
TOLLISON: A C TOLLISON: A C TOLMAN: E L TOMPKINS: P E TONEATTI: V. W	7906290353 7906290371 7906290250 7906040008 7906050170	50-325 8 50-325 8 REB 71-37 C QA999	7904290250	UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R, E	7906120025 7906260358 7906010262 7906260288 7906260290	50-335 P 50-250 G 50-250 R 50-387 G 50-250 G	
TOTH, A D TOTH, A D TOH, D E TOY, H L, TRAMMELL, C M,	790604018B 7906140635 7906130410 7906230170 7906230312	50-322 Q 50-311 Q PR 70-8 C 50-266 P		UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	7706260273 7706050307 7706060135 7706060274 7706060277	50-335 Q 50-335 P 50-251 P 50-250 P 50-250 P	
TRAMMELL.C M TRAMMELL.C M TRAMMELL.C M TRIBLE.P 8 TRIGILIO.A 0	7906200330 7906260190 7906260193 7906110411 7906230031	50-266 P 50-261 P 50-344 P 50-280 U 71-9079 C		UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E UHRIO, R E	7906080296 7906050315 7906130207 7906130235 7906190266	50-251 P 50-335 P 50-250 P 50-250 P 50-250 P	
TRIGILIO, O TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C TRIMBLE, D C	7906230043 7906040152 7906050213 7906070374 7906040209	71-9079 C 50-313 Q 50-313 Q 50-313 Q 50-313 Q		UHRIO, R.E. UHRIO, R.E. UHRIO, R.E. ULLRICH, H.T. ULLRICH, H.T.	7906220184 7906220309 7906250349 7906040246 7906040256	50-250 P 50-335 P 50-250 P 50-277 8 50-277 8	
TRIMBLE, D.C. TRIMBLE, D.C. TRIMBLE, D.C.	7906070181 7906270041 7906290513	50-313 Q 50-320 Q 50-313 A		ULLRICH, H T ULLRICH, H T ULMAN, M B ULRICH, H T UTLEY, E, E	7906070370 7906040034 7906190032 7906270064 7906210096	50-277 8 50-277 8 50-498 9 50-277 8 50-324 0	
				UTLEY, E E UTLEY, E E UTLEY, E E UTLEY, E E,	7906290719 7906120190 7906230017 7906010240 7906040221	50-324 G 50-324 P 50-324 G 50-324 P 50-324 Q	
				UTLEY, E E.	7904080315 7904080245 7904080291 7904120157 7904120393	50-324 P 50-324 P 50-324 P 50-324 P	
				UYLEY, E E UTLEY, E E UTLEY, E E UTLEY, E E VAHRENHALD, J	7906120231 7906200348 7906200356 7906260538 7906060245	50-261 F 50-324 P 50-261 P 50-261 P 50-254 B	
				VAHRENHALD, J VALENTINE, K VALLISH, E J VALLISH, E, J VALLISH, E J	7906220386 7906130311 7906010034 7906030075 7906190120	50-265 B 50-20 J 50-327 Q 50-390 G 50-491 G	
				VALLISH, E J Valdre, C Van Brunt, E, E Van Brunt, E, E Van Brunt, E E	7904250355 7904180441 7904040264 7904050302 7904200338	50~438 G 50~272 O 50~528 A 50~592 C 50~592 D	
				VAN BRUNT, E E VAN DOORN, P, K VAN NESB, B C VAN ROOYEN, D VAN SICKEL, J	7906260459 7906200204 7906010099 7906260037 7906200259	50-392 C 50-390 Q 50-272 C RES 50-331 R	7906260037
				VAN WINKLE, W VANDRUNT, E. E. VANDERVELDEN, M.	7906210031 7906160053 7906260073	REB PR 50-312 H	7906210031

AUTHOR	ACCESSION NUMBER	BUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
VANDENBUROH, D VANDENBUROH, D	7906150243 7906120316	50-271 P 50-27 P		WALKER, R S	7906260391 7906210365	50-463 Q	NUREO/CR-0335
VANDENBURGH, D VANDOORN, P. K VANDOORN, P. K VANSICKEL, J. V	7906130370 7906040387 7906010205 7906220242 7906250301	50-29 P 50-327 Q 50-416 Q 50-438 Q 50-331 8		WALKER.R D WALKER.R D WALLACE.J A WALLACE.J A	7906030040 7906140574 7906230018 7906220432	50-331 0 50-373 0 50-331 0 50-331 0	
VARACALLE, D J VARELA, A A VARGA, B A VARGA, B A VARGA, B A	7906050279 7906260165 7906040214 7906190001 7906270034	RES 50-334 G TOPREP 50-322 A 50-320 G	7906050279	WALSH, W P WALTER, M C. WALTERS, D K WALTERS, D K	7906080260 7906080061 7906040218 7906020128 7906010350	50-568 A PR 50-10 P 50-349 0 50-349 0	NEDC-24159
VAROA, S A VAROA, S A VAROA, S A VAROA, S A	7906290156 7906270002 7906280016 7906270025	50-454 A 50-320 Q 50-390 A 50-320 Q		WALTON, R F WALTON, O A WAMBACH, T V WAMBACH, T V WAMPLER, W C	7906180426 7906260323 7906250185 7906200272 7906110411	CONTRACT 50-387 G 50-213 P 50-219 P 50-280 U	
VARGA, S.A. VARGA, S.A. VARSALLO, D.B. VASSALLO, D.B. VASSALLO, D.B.	7906260267 7906260267 7906020207 7906070319 7906010059	50-327 G 50-400 A 50-338 P 50-275 G		WANDKE, N E WANDKE, N E WANDKE, N E WANDKE, N E	7906060273 7906060282 7906060292 7906060223 7906140554	50-304	
VASSALLO, D. B VASSALLO, D. B VASSALLO, D. B VENTO	7904020242 7904050047 7904130140 7904180172 7904120015	50-320 P 50-322 Q 50-275 H 50-320 U		HANDKE, N.E HANDKE, N.E HANDKE, N.E HANDKE, N.E	7906140367 7906140511 7906140389 7906140416 7906290122	50-304 8 50-304 8 50-304 8 50-275 8 50-275 R	
VERDERY, E H VERDERY, E H VIEBROCK, J M, VIŁLFORTH, J C VIOLETTE, J. B	7906260614 7906210296 7906290027 7906070069	50-250 @ 70-1510 C FOIA REGOD		WANDKE, N E WANDKE, N E WANDKE, N E. WANDKE, N E.	7906220355 7906220390 7906220399 7906120343 7906270207	50-304 8 50-304 8 50-304 8 50-295 R 50-295 8	
AIRRING'O 8 AIRRING'O 8 AIRRING'O 8 AIRRING'O 8	7906180140 7906160054 7906220076 7906110443	50-262 J 50-313 P 50-346 P 50-313 P 50-313 P		WANDKE, N E WANDKE, N E WANG, C, H WANNINGER, A WARD, E C	7906270212 7906270162 7906280132 7906230134 7906030324	50-275 8 50-275 8 50-243 8 NUREO 50-282 R	
VITO.D J VITO.D J VITTI.J A VOOEL.C.E. VOOLER.B H VOOT-LOWELL.R.	7906140353 7906140360 7906020091 7906250360 7906180676 7906030100	50-269 8 PROJ 70-1151 C PROJ 50-366 G	ESG-DOE-13244	WARD, E. C. WARD, K. D. WARD, K. D. WARD, K. D. WAREMBOURG, D.	7906140369 7906260598 7906260589 7906260624 7906010217	50-282 8 50-341 0 50-409 0 50-282 0 50-267 R	
VOOT-LOHELL, R J VOOLER, J. E VOTCHT, H H VOTCHT, H H VOTCHT, H H	7906200359 7906230117 7906040164 7906180565 7906230107	50-348 0 50-346 0 50-546 0 50-546 0 50-277 0		WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D. WAREMBOURG, D.	7906060206 7906120405 7906120155 7906120342 7906120410	50-247 P 50-247 B 50-247 R 50-247 P 50-247 S	
VOTOHTAH H VOTOHTAH H VOTOHTAH H VOTOHTAH H	7906230110 7906230112 7906010233 7903200326	50-277 G 50-277 G 50-341 K 50-341 O 50-315 H		HAREMBOURG, D. HAREMBOURG, D. HAREMBOURG, D. HAREMBOURG, D HAREMBOURG, D	7906190501 7906220295 7906190299 7906220308 7906260443	50-267 P 50-267 P 50-267 R 50-267 P 50-267 P	
VOITA, J F VOLLHER, R H VOLLHER, R H VOLLHER, R H, VOLLHER, R H, VOLLHER, R H	7706050409 7706260204 7706290138 7706290145 7706220103 7706180348	50-320 F 50-320 U 50-320 P 50-320 P GEN TEC IB		HAREMBOURG, D. HAREMBOURG, D. HARNICK, R. F. HARNICK, R. F. HARNICK, R. F.	7906260433 7906270189 7906260315 7906260553 7906250183	50-267 8 50-267 F 50-409 G 50-282 G 50-255 G	
VOLLHERIR H VOLLHERIR H VOLLHERIR H VOLLHERIR H. VOLLHERIR H.	7906070010 7906290307 7906250332 7906280222 7906260286	50-237 P 50-320 P 50-280 P FOIA 50-320 P		WARNICK, R. F. WARREN, M. C. WARREN, M. C. WARREN, B. C. WATANABE, N	7906140609 7906290705 7906290683 7906110076 7906270018	GA779 GA779 HASTE MOT XFORTLIC	
VOLLHERIR H VOLLHERIR H VOLLHERIR H VOLLHERIR H VOLLHERIR H	7904270046 7904270040 7904070161 7904290018 7904210187	50-10 P 50-320 P 50-320 P 50-245 P 50-320 P		HATERHOUSE, H. HATEORD, H. HATSON, J. HATSON, C. HAXMAN, H. A.	7906040111 7906110167 7906120003 7906250340 7906110309	50-275 H 50-261 R 50-320 R CONTRACT COMMISSION	
VON CHRENFRIED VON CHRENFRIED VON CHRENFRIED VORESS, H. E.	7906220437 7906220430 7906220447 7906130259	PR PR PR 50-320 D 50-592 Q		HEAVER J W. HEAVER HEAVER HEAVER WEAVER	7906260369 7906120010 7906120012 7906120015 7906120021	50-463 0 50-320 U 50-320 U 50-320 U 50-320 U	 
VOSS, H. A.  HACHTER, L. J.  HACHTER, L. J.  HACHTER, L. J.  SACHTER, L. J.	7906200178 7906060093 7906040062 7906020157 7906270029 7906020150	50-282 Q 50-282 Q 50-263 Q 50-263 Q 50-263 Q		HEBB, H A. HEBB, F. HEBER, S. HEBER, N. K.	7906180455 7906070371 7906220246 7906270111 7906270272	50-272 6 F01A 50-553 6 50-596 6 50-596	
Hachter, L. J. Hachter, L. J. Hachter, L. J. Hachter, L. J.	7906020151 7906040378 7906140171 7906290675	50-263 Q 50-263 Q 50-282 Q 50-282 Q		WEBSTER WEBSTER, E. H. WEBSTER, E. H. WEBSTER, E. H. WEED, R. A.	7906180317 7906200318 7906230013 7906250375 7906290551	50-275 6 50-336 6 50-335 6 30-335 6 NUREO	
HACHTER, L., J. HACHTER, L., J. HADEKAMPER, D. HACHER, A. Q. HALTS, B. L.	7906290752 7906050292 7906010299 7906140157 7906050203	50-282 P 50-282 P 50-275 H 50-348 0 50-358 0		WEEKB, E. D. WEGRIYN, J. WEGST, W.F. WEIDNER, L. J.	7906150298 7906020102 7906070060 7906140363 7906110093	50-133 f NUREG PR PRM WASTE MOT	NUREO/CR-0799

#### PERSONAL AUTHOR INDEX

AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	BUBJECT CATEODRY	REPORT NUMBER
WEIGAND, J Q WEIGAND, J Q, WEINER, B H WEINGARIEN, V WEINO, J F	7906120392 7906130004 7906220116 7906020195 7906190575	50-458 8 50-458 A 50-471 9 NURE9 70-27 C	NUREQ/CR-0793	WHITESELL, D E WHITESELL, D E WHITESELL, D E WHITESELL, D E	7904210099 7906180670 7906210322 7906180263	GA777 GA777 GA777 GA777	
WEINHOLD, E H WEISEL, H A WEISER, J L WEISS, E R WEISS, E R	7906050034 7906070287 7906260314 7906220164 7906220168	30-443 Q COMMISSION 50-320 R 50-249 Q 50-249 G		WHITESELL, DE WHITESELL, DE WHITESELL, DE WHITESELL, DE	7906070026 7906050208 7906060115 7906230073 7906230052	GA999 GA999 GA999 GA999 GA999	
Weiss.8 Weiss.er Weiss.er Weiss.er Weiss.r	7906210333 7906010243 790601011B 7906210254 7906260505	50-331 P 50-498 M FOIA 50-269 G PROJ		WHITESELL, DE WHITESELL, DE WHITESELL, DE WHITESELL, DE WHITESELL, DE	7906190074 7906050182 7906050177 7906120028 7906050274	0A999 0A999 0A999 0A999 50-321 F	
Weiss, D, Weiss, D Weiss, D Weissberg, 8 Weiss, B H	7706030442 7906030449 7906220197 7906220274 7906130342	70-364 C 70-143 C 70-135 C 50-320 G 50-320 P		WHITHER, C F WHITHER, C F WHITHER, C F WHITHER, C P WHITNEY, Q C	7904080246 7904080295 7904110135 7904080268 7904190230	50-321 P 50-321 P 50-366 P 50-321 G 50-273 R	
WELLIVER, G W WELLB, R A WENNERHOLM, J WENNER, S WENNER, B	7706140632 7706020113 7706060286 7706200382 7706060214	50-397 0 RE8 50-304 S 50-576 0 PRDJ	7906020115	WHITTEMORE, W L WHITTAKER, R WIDOFF, M P HIENER, R WIEBEMANN, R A	7906150094 7906050172 7906260388 7906050115 7906070281	REGGD 50-482 U 50-463 G 50-522 G 50-247 P	
Wenner, 8 Wenner, 8, Wenner, 9 Wenglawski, F Wenzinger, e c	7906020141 7906290069 7906290077 7906130359 7906280045	PROJ 30-396 T 50-396 T 50-320 P 50-320 B		HIESEMANN, R A HIESEMANN, R A HIGGINS, E HIGGINS, E HIGGINS, E	7906220310 7906220321 7906020169 7906190397 7906150165	TOPREP TOPREP CONTRACT CONTRACT CONTRACT	
WERLING, J A	7906040245 7906040249 7906260397 7906290328 7906290333	50-334 S 50-334 S 50-334 S 50-334 S		Higolus, E Higolus, E, J Higoluson, D Higoluson, D Higoluson, D	7906180042 7906130078 7904130312 7906010288 7906290550	CONTRACT CONTRACT 50-334 P 50-334 P 50-334 P	
HERLING, J. A HERTS, R. W HEBSHAN, R. H HEGTERHAN, T. F HEBTFALL, R. M	7906290339 7906260211 7906200434 7906150055 7906180218	50-334 8 50-320 F 50-320 P 50-313 0 RES	7906180218	WILCOX, T D WILCOX, J, D WILCOXEK, J WILKING, T, D	7906250146 7906210409 7906260201 7906190222 7906190354	50-281 G 50-281 G 50-281 G 70-2880 C 70-824 C	
HESTFALL,R M WETHY,C M HETHY,C M HETMORE,J B WETTERHAHN,M J	7906190049 7906140376 7906200418 7906130512 7906010298	RES 50-335 S 50-335 P 50-407 P 27-39 C	7906190049	Willemsen, B Williams, C H Willis, C, A. Williams, P R Williams, D H	7906270217 7906150246 7906220041 7906130304 7906220100	50-265 8 50-510 H PRM PRM 71-6058 C	
HETTERHAHN, M J WETTERHAHN, M J HETTERHAHN, M J WETTERHAHN, M J, WETTERHAHN, M J	7904080193 7904050028 7904080210 7904050089 7904020252	50-358 0 50-510 0 50-358 0 50-358 0 50-272 0		HILLIB, E HILLIAMB, R L. HILLIAMB, J L HILLIFORD, R, E HILLIAMB, O H	7906140449 7906260310 7906200167 7906020097 7906210396	50-324 R 50-320 P 71-327 C NUREQ 50-111 Q	NUREG/CR-0220
HETTERHAHN, M J WETTERHAHN, M J, WETTERHAHN, M J, WETTERHAHN, M J WETTERHAHN, M J	7906080141 7906020072 7906250410 7906250411 7906070046	50-498 M 50-272 Q 50-358 Q 50-358 O 50-445 M		HILLIAMS, C C HILLIAMS, C C HILLIAMS, C C HILLIAMS, C C HILLIAMS, F J	7906050051 7906130133 7906210317 7906140607 7906270098	50-263 0 50-331 0 50-301 0 50-341 0 50-320 0	
METTERHAHN, M J, METTERHAHN, M J METTERHAHN, M, J METTERHAHN, M J METTERHAHN, M J,	7906280232 7906290375 7906280103 7906280165 7906280169	50-498 M 50-358 Q 50-358 Q 50-510 Q		HILLIAMS:F J HILLIAMS:F J HILLIAMS:F J HILLIAMS:F J HILLIAMS:F J	7906270101 7906270137 7906270140 7906270126 7906270131	50-320 G 50-320 G 50-320 G 50-320 G	1
WETTERAU, L W WHITESELL, D. E WHITE, T. WHITE, S. O. WHITE, J R	7906070174 7906210406 7906290834 7906200299 7906250251	REGOD GA999 50-482 O 50-445 M XPORTLIC		HILLIAMS, F J, HILLIAMS, F J HILLSEY, H, B HILLSEY, H B, HILLSEY, H B,	7906290355 7906270120 7906150335 7906140221 7906140455	50-320 Q 50-320 Q 50-277 R 50-277 R 50-277 R	
WHITEHURBT, O. W WHITE, L. D WHITE, L. D WHITE, L. D. WHITE, L. D	7906110411 7906080143 7906020217 7906070261 7906270200	50-280 U 50-244 Q 50-244 Q 50-244 Q 50-244 Q		WILLSEY, W. B WILMARTH, A. E WILSON, J. H. WILSON, W. E. WILSON, W. E.	7906140243 7906290091 7906270209 7906120415 7906070249	50-277 R 50-320 Q 50-160 J 50-27 P 50-27 D	
HHITE, L. D. HHITE, L. D. HHITE, L. D. HHITE, L. D. HHITE, L. D.	7906050359 7906120406 7906130198 7906190368 7906190493	50-244 P 50-244 P 50-244 P 50-244 J 50-244 P		WILSON: WE, WILSON: WE, WILSON: WE, WILSON: WR, D.	7906270184 7906120412 7906270183 7906290762 7906200285	50-27 K 50-27 P 50-27 K 50-498 M PR	
WHITE, L. D WHITE, L. D WHITE, L. D. WHITE, L. D. WHITE, L. D.	7906220272 7906210193 7906250253 7906270160 7906290434	50-244 F 50-244 P 50-244 B 50-244 P 50-244 P		GILSON, R. GILSON, B. D. GILSON, B. D. GILSON, B. D.	7906180778 7906150474 7906160058 7906210411 7906180776	REGOD XPORTLIC XPORTLIC XPORTLIC BECY	
WHITESIDES, Q. E. WHITESIDES, Q. E. WHITE, J. D. WHITE, J. R. WHITENER, H	7906180218 7906190049 7906290487 7906200477 7906210304	RES RES NUREQ 50-320 P 50-327 Q	7906180218 7906190049 NUREQ/CR-0783	GILSON, B. D. WILSON, B. D. WILSON, B. D. WILSON, B. D. WILSON, B. D.	7906020190 17906210293 17906210310 17906210320 17906210320 179062	XPORTLIC XPORTLIC XPORTLIC XHORTLIC XPORTLIC	
WHI TEBELL, D. E.	7906210086	QA999		WILBON, R F	7906260327	50-320 P	

AUTHOR	ACCESSION NUMBER	SUBJECT	REPORT NUMBER	AUTHOR	ACCESSION NUMBER	SUBJECT CATEGORY	REPORT NUMBER
WILSON, R F WILSON, R F WILSON, R F WILSON, R F	7906280164 7906280167 7906280170 7906280162	50-320 P 50-320 P 50-320 P 50-320 P		WU.T Y WULLER, Q E HYLIE, H B YACKLE, T R	7906290763 7906140464 7906150141 790629017B	ACRS 50-461 G 50-317 P RES	7906290178
WILSON, RF WILSON, RF WILSON, RF WILSON, JN WINCEK, MA	7906280160 7906290255 7906290274 7906020085 7906180717	50-320 P 50-320 P 50-320 P 50-322 A NUREQ	NUREO/CR-0483	YAEGER, M K YAEGER, M K YBARRONDO, L, J YBARRONDO, L, J, YEAGER, F 8	7906140384 7906200365 7906020114 7906030110 7906030414	50-251 8 50-250 6 RES NUREQ 50-466 Q	7906020114 NUREO/CR-0739
Wilno, J Wilnoate, 8 Winterhalter, J Winters, C E Withers, B D	7906290498 7906140576 7906220121 7906180360 7906180143	NUREO 50-488 H 50-320 R PR 71-9108 C	NUREG-0570	YIN, I T YIN, I T YIN, I T YIN, I T YIN, I T	7906210334 7906210334 7906130127 7906250172 7906260199	50-295 Q 50-155 Q 50-327 Q 50-237 Q 50-358 Q	
Withers, B. D Withers, B. D Withers, B. D Withers, B. D. Witi, K	7906040347 7906080292 7906140425 7906150302 7906140205	50-344 8 50-344 8 50-344 8 50-344 R 50-312 Q		YIN, I T  YORE, J R YDUNG, Q YOUNGDAHL, R C YOUNG, R H	7906140658 7906250166 7906230144 7906290533 7906120362	50-341 Q 50-358 U NUREQ 50-329 T 50-245 8	
MOFFORD, A H MOHLSEN A B MOLF, R MOLF, J F MOLF, J	7706040176 7706270032 770604011B 7706220452 7706260554	50-322 G 50-320 P 70-875 C 50-241 G 50-295 T		YOUNG, RH YOUNG, RH YOUNG, RH YOUNG, FYOUNG, FYOUNG, HH,	7706140401 7706180527 7706270253 7706060237 7906070049 7906210021	50-245 8 50-245 8 50-245 8 50-320 H 50-320 P	
HOLF, J HOLF, J HOLF, J HOLF, S J	7906260558 7906290560 7906290047 7906290082 7906220180	50-295 T 50-295 T 50-295 T 50-295 T 50-437 G		YUHASI Q. P YUHASI Q. P YUSKO, J. Q YUSKO, J. G YUSPEHI A. R	770621000B 7706150213 7706210416 770614061B 7706070189	50-320 P 50-289 P 50-245 Q REGOD REGOD 50-382 Q	
Molfers J Molfers J. Molfers J. Molfers J.	7906040385 7906040389 7906040445 7906040412 7906050105	50-556 0 50-556 0 50-466 0 50-556 0 50-466 0		ZABLDCKI.C. J ZAFFIRO.C ZAHN.L. L ZAHN.L. L.	7906280249 7906210113 7906050130 7906000584 7906010247	COMMISSION 50-320 P 70-1309 C 70-1308 C 50-247 Q	
HOLFE:8 J HOLFE:8 J HOLFE:5 J HOLFE:5 J	7906070248 7906040024 7906070109 7906130429 7906190022	50-466 Q 50-556 Q 50-466 Q 50-466 Q 50-556 Q		ZARAKAS, P ZARAKAS, P ZARAKAS, P ZAVADOSKI, R W ZAVADOSKI, R W ZAVADOSKI, R W	7706010247 7706170253 7706170253 7706070076 7706210016 7706260501	50-247 P 50-247 C 50-280 G 50-320 P 50-250 G	
HOLFE, S J HOLFF, O N HOLFF, O N HOLIVER, J	7906250171 7906180736 7906210395 7906120033 7906010139	50-556 Q 50-445 T 70-1308 C 50-358 Q 50-358 Q		ZAVADOSKI,R W ZEBRAK,I L ZECH,G.O ZEFF.D W ZEFF.D W	7906290379 7906200619 7906250196 7906250164 7906260185	50-320 P 50-576 Q 50-272 P 70-1201 C 70-1201 C	
HOLLETT'S A HOLTWER'E HOOD'R HOOD'E C	7906150171 7906290421 7906250153 7906200078 7906010256	CONTRACT 50-320 P 50-10 Q 50-255 Q 50-309 8		ZEITLIN.H ZELAG.R E ZELLER.H D ZIEMANN.D L ZIEMANN.D L	7706280163 7706130186 7706120337 7706230028 7706040424	50-320 H PR 50-553 R 50-255 P 50-206 P	
HOODE C HOODE C MOODE C, C, HOODARD, B H HOODERAD, C P,	7906010184 7906120411 7906120322 7906180768 7906020132	50-309 G 50-309 B 50-309 S 50-466 Q 50-510 Q		ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L. ZIEMANN, D. L.	7906070351 7906060023 7906070008 7906070015 7906030450	50-237 P 50-409 P 50-237 P 50-237 P 50-155 Q	
HOGOMAN N P HOGOMUFF, R L HOGOMUFF, R, L, HOOLEVER, E, J, HOOLEVER, E, J,	7906270114 7906070323 7906210026 7906130134 7906180299	50-280 H 70-1201 C 50-320 P 50-334 Q 50-334 Q		ZIEMANN, D L. ZIEMANN, D L ZIEMANN, D L ZIEMANN, D L	7906050227 7906050231	50-255 P 50-409 P	
HOOLEVER, E. J. HOOLEVER, E. J. HOOLEVER, E. J. HOOLEVER, E. J. HOOLEVER, E. J.	7904270203 7904090300 7906130340 7906150312 7906200155	50-412 Q 50-412 8 50-412 A 50-334 P 50-334 P		Z IEM/			
SHOREHBOURG, D. W. SHORRELL, R. B. SHOREHAM, J. I. SHOREHAM, J. I. SHOREHAM, I.	7906180534 7906260608 7906070317 7906020255 7906190043	50-267 F NUREQ 50-445 M 50-445 M 50-445 M	NUREQ/CR-0465	2 2 2 2 2			
NORSHAM, J. I. HORSHAM, J. I. HRAY, J. R HRAY, J. H. HR EGHT, B	7906020250 7906200576 7906180680 7906260501 7906140644	50-445 M 50-445 M 50-280 G 50-250 G 50-510 G		2 2 2 2 1			
SAR IGHT, F. 8, SAR EGHT, F. 8, SAR IGHT, F. 8 SAR IGHT, J. L, SAR IGHT, E. 8	7906120008 7906010264 7906010265 7906260301 7906020023	50-471 Q 50-471 Q 50-471 Q 50-320 U BECY		7			
Hright, R. L. Hright, R. W. Hright, R. W. Hright, R. W. Hright, Q. G.	7906120107 7906010143 7906020144 7906140645 7906140596	REGGD 50-553 G 50-553 G 50-438 G 50-373 G					

	i		
	•		
r			
		3.	

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

AUTHOR AFFILIATION NUMBER CATEGORY CITIIEN GROUP/INDIVIDUAL/MEDIA Bisbee Anti-Nuclear Group Citizens Against Nuclear Dangers 7906200291 000 50-592 50-367 7906190130 7906190013 7906110107 SO-387 ( Citizens for Alternatives to Radioactive Dumping Citizens Association for Bound Energy 50-445 7904070305 CES News. CBS. Inc 7906220075 50-320 7906220069 7906220083 50-320 50-320 Camenton Civic Association 7906010111 7906010106 50~549 Concerned Citizens Against Proliferation 7906070201 of Uranium Haste Concerned Citizens of Lake County, IL 7906190091 7906050403 40-8698 C 30-498 7906070169 7906200601 G G 50-498 50-498 50-341 50-445 50-338 Cátizens for Energy & Employment Cátizens for Fair Utility Regulation Cátizens Energy Forum 7703200326 7904050236 7904200592 7906270278 50-338 Citizens for Befe Environment Classhell Alliance Center for Law in the Public Interest 000 50-320 50-443 7906040069 7906070327 7906260550 FOIA 50-275 7906010341 Center for Law & Social Policy Critical Mass Energy Project Ecology Action of Oswego Environmental Defense Fund 7906010113 FOIA PRM 50-594 50-592 7906210400 7904270111 7906290815 7906120270 50-312 50-312 50-255 Friends of the Earth 7906250232 7904240073 Great Lates Energy Alliance lows Public Interset Research Group 7906290512 Jo Davies County Ad Hoc Committee on Nuclear Energy Information Lake Michigan Federation ٥ 7906280079 50-579 50-237 p 7906050043 50-454 50-454 50-358 League of Homen Voters of Rockford, IL 7906050125 7906010119 7906070230 A Hiami Valley Power Project Hothers & Others Mobilizing for Survival FOIA 50-275 Q Herthern California Ecumenical Council 7906020067 50-275 ø 50-275 FOIA 50-237 70-2623 70-2623 New England Regional Energy Project Natural Resources Defense Council 7904070222 7906010131 7906070333 7906070341 70-2623 70-2623 70-2623 70-2623 70-2623 7906040065 7906020099 7906220194 7906250082 70-2629 50-237 50-237 50-237 0000 7906210357 7906210357 7906210357 7906050049

Muclear Vote

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

AUTHOR	ACCESSION	SUBJECT	
AFFILIATION	NUMBER	CATEGORY	1
	~		
	****	50 . HO !	G
Diwego County Farm Bureau	7906270272 7906140525	50-596 PR	u
Public Citizen Litigation Group	7906210400	PRM	
	7906230150	NUREQ	
Pennsylvania Illustrated, Inc.,	7906010107	50-320	H
Decis des Evenes Progress	7906270016	PR	
Paople for Energy Progress Public Interest Research Group	7906140104	10CFR	
otomac Alliance	7906200596	50-338	G
Skagitonians Concerned About Nuclear Plants	7906010014	50-522	G
Texas Public Interest Research Group	7906040383	50-466	G
•	7906040390	50-466	G
	7906040394	30-466	٥
Trends Publishing, Inc	7906220259	FOIA	_
Union of Concerned Scientists	7906220170	50-269	0
	7906220168	50-269	·
	7906220164	50-269 FOIA	0
The Wall Street Journal	7906070233 7906070214	50-482	Α
Holf Greek Nuclear Opposition, Inc.		50-492	Ä
Homen's International League for Peace & Freedom	,,00140100		
	iree		
ENOINEERINO/CONSTRUCTION/CONSULTANTS/SERV			
American Airlines, Inc	7906160056	PR 71-295	С
Acurezi Alcore	7906150446	71-295	Č
	7906150449 7906110316	TOPREP	¥
Alaska Industrial X-Ray	7906040077	71-308	C
,	79060400B0	71-308	С
Applied Engineering Co	7906150433	71-294	C
Arthur D Little, Inc	7905150650	PT21	
al site is a second of the sec	7905150657	PT21	
Bechtal Power Corp (subs of Bechtel	7906070069	REGOD	
Corp )	7906180062	RECOD	
	7906020215	REGGD	
	7906150104	REGOD	
	7906110267	50-462	A
	7906220363	4112	
Bell G			
OH Bets.		71_47	C
Capitol International Airways, Inc.	7906190476 7906070148	71-47 71-287	Ğ
Garson Nondestructive Testing	7906070159	71-287	č
	7904270213	TOPREP	_
C. F Braun & Co Chavron Industries, Inc., Chavron	7906070221	10CFR	
Resources Co Div			
Contingency Planning Associates	7905250395	50-320	н
Grears, Inc.	7906180422	TOPREP	_
CTL Engineers, Inc	7906180588	71-301 71-301	C
Daedalean Associates, Inc	79061805B4 7906200620	REB	·
	7906200284	71-120	c
Daniel International (subs. of Fluor Corp.)			_
	790620028B 7906150427	71-120 71-291	C
DJ Inspection Services, Inc.	7906150430	71-291	Č
Ebasco Services, Inc. (subs of Enserch	7906190035	94977	
Carp. }	7906020175	71-162	c
	7906200345	RECOD	

### Productions   Productions	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	EO & Q, Inc	7904180424 7904180433 7904290245 7904290311 7904290291 7904180707 7904110057	CONTRACT CONTRACT RES_ RES RES SO-275 WASTE HO	ρ	Radsey Enginearing Company Rocky Mountain Energy Co Rolf Jensen & Associates, Inc	7904010070 7904010072 7904240339 7904020108 7904180484 7904230477 7904070371	XFORYLIC XFORTLIC XFORTLIC 40-8452 B 40-8452 C 40-8452 C FOIA
Processories		7906030086 7906030279 7906290178 7906290204 7906290230 7906290230 7906290202 7906200310 7906200210	NUREO REB REB REB RES RES WASTE MO 40-4492 40-4492 40-4492	CCC	Smith-Emery Co Snyder Drilling-Well Servicing Steel Tank Construction Co  S M Stoller Corp (subs of Arthur D Little, Inc.)	7706220213 7706140053 7706140057 7706220493 7706220494 7706180179 7706180179 7706101007 7706010203 7706200158	6A999  71-314 C 71-314 C 71-306 C 71-306 C 71-298 C VABTE MOT  50-322 A 50-334 P
700.220182   50-320   P   700.220182   700	F. M. Fox & Associates	7906200212 7906200355 7906200355 7906200357 7906200306 7906200306 7906200059 7906180271 7906110044	40-4492 40-4492 40-4492 40-4492 40-4492 40-4492 WASTE MO	C C C C C	Terredate Geophysical, Inc Theyer Inspection Service, Inc Todd Shigyards Twin City Testing & Engineering Laboratory, Inc	7906110102 7906140091 7906140100 7906200346 7906180360 7906020188	WASTE MGT 71-289 C 71-289 C 71-145 C PR 71-103 C
Olbe X-Ray Services. Inc 7706230137 71-146 C Behave Carp. 1 7706230137 71-146 C Behave Young Univ 7706230333 30-262 71-146 C Behave Young Univ 770623033 30-262 71-146 C Behave Young Uni		7906220182 7906220121 7906290289 7905160435 7906040074	50-320 50-320 TOPREP ORO 71-317	P R	(subs of Raytheon Co )	7906180732 7906260027 7906120164	NUREO 50-471 0 50-324 P
Type	Globe X-Ray Services. Inc H J Gruy & Associates, Inc Ichthyological Associates, Inc	7706270820 7706210435 7706230157 7706130012 7706270112 7706270113	0A999 50-285 71-146 50-445 50-320 50-320	8 C	Stephen F Austin State Univ Brigham Young Univ	7906200353 7906070060 7906140563 7906290763	50-262 J PR PRM AGRE
Memphis Testing Services, Inc	Intermountain Testing Co International Structural Engineers, Inc G R Johnson Associates, Inc Kinetic Research, Inc.	7906140080 7906190497 7906020195 7906110105 7906010258	71-292 71-213 NUREO WABTE MO FOIA	C C	Michigan State Univ Mississippi State Univ Massachusetts Institute of Technology North Carolina State Univ	7906290444 7906080274 7906130311 7906070083 7906210354 7906180757	50-274 8 50-241 J 50-20 J 50-111 G 50-111 G NUREO
Nuclear Energy Services   Inc	Midstate Testing Laboratory, Inc	7906140068 7906140073 7906200511 7906050415	71-303 71-303 71-77 71-6698	c c c	Oregon State Univ Pennsylvania State Univ,	7706260637 7906150277 7706260467 7706280144 7706270378	50-5 J 50-5 S 50-5 S 50-3 S
NUS Corp	N M Newmark Consulting Engineering Services	7906210296 7906200215 7906060074 7906060095 7906280143	PRM 50-309 FOIA 50-320	P	Rensselmer Polytechnic Inst.	7906280001 7906080130 7906120180 7906080173 7906020102	RES 50-182 G 50-182 F 50-255 J NUREO
Porter-Gertz Consultants, Inc. 790621020B 50-320 P 790620395 50-84 790620395 50-84 790620395 790620395 790620395 7906270245 ACRE 7906270242 50-320 P 790620325 790620325 PR 790620311 50-320 P 790620311 50-320 P 79062031 50-320 P California, Univ. of, Santa Barbara 790620314 50-320 P 79	, obsolets code Parameter, Inc	7906180453 7906200518 7906180446 7906260002 7906210333	50-592 REGOD 50-437 50-437 50-331	C A A P	Texas A & M Univ. Arkansas, Univ. of	7906190270 7906040118 7906200223 7906120353	50-128 P 70-895 C PRM 50-224 R
7906200429 50-320 R Fiorida, Univ. of. Qainesville 7906070142 50-83		7906210208 7906280130 7906220207 7906290423 7906210111 7906260251	50-320 50-320 50-320 50-320 50-320 50-320	P P P P		7906260395 7906270245 7906070085 7906070051 7906290843 7906150402	50-84 J ACRE REGGD PR ACRE 50-142 P
7906140048 71-313 C 7906140287 30-83 Princeton Gamma-Tech 790610129 70-1200 C Kenses, Univ of 7906270210 30-14E Plateau Resources, Ltd. 7906200319 40-7869 C Louisville, Univ of 7906130182 PR	Pleteau Resources, Ltd.	7906200427 7906140048 7906140048 7906010127 7906200317 7906190131 7906220135	50-320 71-313 71-313 70-1200 40-7849 40-8698 40-8698	R C C C C C C C C C C C C C C C C C C C	Fiorida, Univ. of. Cainesville  Kanses, Univ of Louisville, Univ of Haryland, Univ of Michigan, Univ of	7906070142 7906190286 7906190287 7906270210 7906130182 7906130319 7906230124	50-83 P 50-83 P 50-148 J PR 50-166 J RE9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	ŘΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
New Herico, Univ of Pennsylvania, Univ of Pittsburgh, Univ of	7906260622 7906290163 7906220243 7906270251	50-123 71-5942 50-252 50-5	8 C G		7906050089 7906020252 7906080141 7906020072 7906040393	50-358 9 50-272 0 50-498 M 50-272 0 50-498 H
Southern California, Univ of Teres, Univ of Virginia, Univ of Vanderbilt Univ.	7904280001 7906180713 7906280001 7906220239 7906180357	res Nureo Res 50-62 Pr	8		7906180656 7906110429 7906010137 7906050156	50-277 Q ORQ 50-358 Q 50-395 M
Virginia Polytechnic Institute & State Univ Vashington State Univ	790602017B	50-124	G .		7906250410 7906250411	50-358 0 50-358 0
Passington deate unit	7906120415 7906070249 7906270184 7906120412	50-27 50-27 50-27 50-27	P D K P		7906250415 7906070046 7906190124 7906070046	50-358 Q 50-445 H 50-445 H 50-445 H
West Virginia Univ Yale Univ	7906270183 7906070240 7906190251 7906140573	50-27 50-129 50-129 FRM	K P P		7706190124 7706070046 7706190124 7906070046 7906190124	50-445 H 50-445 H 50-445 H 50-445 H 50-445 H
FOREIGH OGVERNHENTS AND AGENCIES					7906070046	50-445 M
Canada European Communities, Commission of Italy	7906250116 7906070132 7906200293 7906210113	50-320 SECY XPORTLIC 50-320			7706190124 7706230107 7706230110 7706230112	50-445 M 50-277 G 50-277 G 50-277 G
Rores, Republic of (Bouth Kores)  Philippines	7906260562 7906220041	XPORTLIC PRM			7906230107 7906230110 7906230112	50-277 0 50-277 0 50-277 0
United Kingdom	7906150462	XPORTLIC	:		7906230112 7906230110	50-277 Q 50-277 Q
LEGAL/LAW FIRMS/INSURANCE COMPANIES	W224		Ų.		7906230112 7906260021	50-277 0 50-358 0
Arent, For, Kintner, Plotkin & Kahn Akin, Gump, Hauer & Fald American Nuclear Insurers	7906290091 7906230151 7906010173	50-920 50-445 50-920	H O		7906280232 7906290575 7906280103	50-498 M 50-358 G 50-358 G
	7906150258 7906190256 7906200432 7906250294 7906280126	50-320 50-3 50-320 50-289 50-320	1000		7706280165 7906280169 7906280165 7906280169 7906220378	50-510 9 50-510 9 50-510 0 50-510 0 50-416 9
Asher, T. R. PC Baker & Botts	7906050383 7906260072 7906080183 7906080190 7906040417	50-574 50-574 50-466 50-466 50-445	0 0 0 0 M	Conover & Associates, Inc. Insurance Dalton, A.T. Dattilo, T.M Valentine 8 Deals Debevoise & Lieberman	7906190433 7906050068 7906180497 7906180612 7906020219	70-1621 C 50-556 9 50-546 9 50-329 9 70-2623 C
	7906020107 7906020009 7906030144 7906020009 7906070304	50-466 50-445 50-466 50-445 50-498	0 N 0 M 0		7904040030 7904020255 7904020212 7904190043 7904020250	50-445 M 50-445 M 70-2623 C 50-445 M 50-445 M
	7904020009 7906070304 7906010260 7906020209 7906020218	50-445 50-498 50-498 50-445 50-466	M O M M		7906200576 7906140552 7906040122 79060503B9	50-445 M 71-6698 C
	7706080052 7906140178 7906180723 7906190018 7906010243	50-466 50-466 50-466 50-466 50-478	0 0 0 0 M			
	7906020209 7906010243 7906180124 7906190140 7906220458	50-445 50-498 50-466 50-445 50-466	M K O M Q			
Blue & Shelley	7906250426 7906280262 7906280105 7906280245 7906020098	50-443 50-466 50-445 50-466 70-2623	M 0 H 0 C			
Suttel & Kass Barley, Snyder, Cooper & Barber Cabill, Gordon & Reindel Cherry, H. K./Cherry, Flynn & Kanter	7906010066 7906290091 7906070338 7906140286 7906050160	50-549 50-320 50-395 50-329 50-329	0 0 H 0 0			
California Indian Logal Services	7704140278 7704050140 7704140278 7704080225 7704080221	50-329 50-329 50-329 50-592 50-592	0 0 0			
Conner, Moore & Curber	7904010158 7904010298 7904080193 7904050028 7904080210	50-395 27-39 50-258 50-510 50-358	H C Q Q			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO:		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	łΥ
	7906210252 7906260490 7906210387	50-237 50-556 50-599	G G		7906040150 7906040154 7906040136	50-445 50-445 50-445	H H
Kosik, L. S Leed, Rager M	7906050131 7906220066 7906220070 7906020229	50-358 50-358 50-358 50-522	0 0 0	D'Neil, Backus, Spielman	7706040136 7706040150 7706040154 7706050136 7706050138	50-445 50-445 50-443 50-443	M H O
Leva, Hawes, Symington, Martin & Oppenhetmer LeBoauf, Lamb, Leiby & MacRas	7906020008 7906040164 7906180365	PR 50-546 50-546	0	Perkins, Coie, Stone, Olsen & Williams Raymier, Crocker, Allebach & Reber, P. C	7906030136 7906050138 7906220122 7906280017 7906140479	50-443 50-443 50-522 50-522 50-332	0000
	7906230107 7906230110 7906230112 7906230107 7906230110	50-277 50-277 50-277 50-277 50-277	0 0 0	Ropes & Gray	7906290165 7906080282 7906060246 7906190317	50-471 50-443 50-443 50-443	Q A I I
	7906230112 7906230107 7906230110 7906230112 7906010233	50-277 50-277 50-277 50-277 50-341	6 6 K	Steel, Hector & Davis Sheldon, Harmon & Roisman Spiegel & McDiarmid	7906250344 7906070225 7906010118 7906210254 7906050410	50-443 50-250 FOIA 50-269 PROJ	0
Lowenstein, Newman, Reis, Axelrad & Toll	7904130193 7906290584 7906070225 7906070307 7906180712	50-244 50-220 50-250 50-466 50-344	P 0 0 0		7906020119 7906200299 7906200500 7906200299 7906200500	50-445 50-445 50-445 50-445 50-445	н н н
	7904080183 7904080190 7904110440 7904040417 7904040418	50-466 50-466 50-466 50-445 50-250	0 0 M H		7906200299 7906200300 7906200299 7906200300 7906200299	50-445 50-445 50-445 50-445 50-445	# # #
	7906020107 7906070304 7906010260 7906020209 7906080052	50-466 50-478 50-478 50-445 50-466	0 N N 0	Small & Wilmer	7904200500 7904020137 7904040201 7904020030 7904110034	50-445 50-445 50-416 50-572 WARTE HG	н н е
,	7704020209 7704200402 7704220458 7704230426 7904280242	50-445 50-522 50-466 50-445 50-466	0 0 14 0	Shaw. Pittman, Potts, & Trombridge	7906070189 7906010311 7906210274 7906230107 7906230110	50-362 50-502 50-241 50-277 50-277	
Mutual Atomic Energy Liability Underwrit	7904280105 7904280245 7906150405 7906120324 7906120331	50-445 50-466 50-331 50-280	r c c c s		7906230112 7906230107 7906230110 7906230112	50-277 50-277 50-277 50-277	0 000
	7906120324 7906120331 7906120324 7906120331 7906120324	50-280 50-280 50-280 50-280 50-280	יררר י	•	7906230107 7906230110 7906230112 7906230107 7906230110 7906230112	50-277 50-277 50-277 50-277 50-277 50-277	00 0000
	7906120331 7906120324 7906120331 7906120324 7906120331	50-280 50-280 50-280 50-280 50-280	רררר		7906230110 7906230112 7906230107 7906230110 7906230112	50-277 50-277 50-277 50-277 50-277	0000
March & McLenon, H & H Nuclear Conquitan ts, Inc Div	7906120324 7906120331 7906260419 7906080229	50-280 50-280 50-18	7 7 7		7906230107 7906230110 7906230112 7906230107 7906230110	50-277 50-277 50-277 50-277 50-277	0 000
	7906120211 7906080229 7906120211 7906120274 7906190457 7906190307	50-272 50-259 50-272 50-327 50-302 50-321	יייייי ני	Sager & Sager Associates Valore, C	7906230112 7906260374 7906130276 7906260351 7906180441	50-277 50-382 50-346 50-463 50-272	0 0000
	7906190419 7906190307 7906190419 7906190415	50-335 50-321 50-335 50-87	3 3 3 3	West Texas Legal Services Horsham, Forsythe & Sampels	7906260084 7906070317 7906020255 7906190034 7906190043	50-445 50-445 50-445 50-445 50-445	10 HHH
McGrath, E J McGutchen, Dayle, Brown & Emerson	7906200336 7906290414 7906010320 7906040161 7906200558	50-346 50-70 PROJ PROJ PROJ	3		7906190034 7906190043 7906190034 7906190043	50-445 50-445 50-445 50-445	H H H
Montoe & Lemann Morgan, Lewis & Bockius	7906260303 7906160066 7906250184 7906250203 7906250184	PROJ 50-382 50-356 50-356 50-356	0 0 0		7906190034 7906190043 7906190034 7906190043 7906020250	50-445 50-445 50-445 50-445 50-445	H H H
Matthews, Nowlin, Mecfarlane & Barrett Northcutt Ely	7906250205 7906290762 7906040136	50-356 50-498 50-445	м н о	Holiver, J D	7906200576 7906120033 7906010139	50-445 50-358 50-358	М О

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
LOCAL GOVERNMENT AND AGENCIES	7905280031 7905290520	50-358	0		7906130496 7906130301 7906190544 7906230168	50-320 50-320 70-824 70-27	P C C
Elizabethtown, PA Lancaster, PA	7906260114 7906290032 7906260308	50-320 50-320	Q P Q		7906180164 7906250215 7906230166	70-1201 70-364 70-364	B
Pesico, NY Middletoun, PA Gawego, NY	7906050076 7906050069 7906220202 7906290706 7906040427	50-574 50-320 50-220	0 0 8 H 0	•	7906260185 7906130038 7906230089 7906280182	70-1201 70-135 TOPREP 50-320	C
Pottstown, PA Siffalk County, NY	7904180602 7904040093 7906270269	50-516	H 9 0		7906160021 7906160019 7906190575 7906250313	71-72 71-72 70-27 70-824	C C C
MEDICAL INSTITUTIONS/LABORATORIES					7906200094 790622043B 7906200514	70-824 71-135 71-230	CCC
Allegan General Hosp Allegheny General Hosp Begstate Hedical Center MA/SP Celvert Kenorial Hosp FR/Maryland	7906210416 7906140618 7906010065 7906010063 7906210285	REGGD REGGD 70-2484 70-2484 50-317			7906200515 7906220436 7906230171 7906230174	71-230 71-135 71-34 71-34	c. c c c
Campbell County Memorial Hosp Clinton Regional Hosp Hisp. of Philadelphia lowa Methodist Medical Center Manchester Kemorial Hosp	7906080061 7906070414 7906070419 7906070420 7906130148	PR PR PR PR PR			7906220100 7906010231 7906010185 7906120246 7906080306	71-6058 TOPREP 70-824 50-312 50-313	C P P
Wilson.R D MD Marcy Hosp MA/SP Missouri Delta Community Hosp Miunt Sinai CT/HA Nabraska, Univ of, Radiation Health Center	7906200285 7906190222 7906070418 7906260010 7906060202	PR 70-2880 PR 70-2000 50-320			7904190388 7904180532 7904180483 7904180489 7904190452 7904240473 7904240473	TOPREP TOPREP TOPREP TOPREP 50-320 TOPREP TOPREP	P
Norwalt Hosp Roswell Part Memorial Inst St Mary's Hosp WA.Connecticut	7904050189 7904050188 7904050080 7904040142	70-1717 70-1717 FOIA 70-1710 PR	c	Babcock & Wilcox Co , Nuclear Material	7906260359 7906260363 7906280115 7906080217	TOPREP TOPREP TOPREP 70-135	c
St Mary: Hosp MO/KA  St Anthony Hosp WI/MI Trinity Lutheran Hosp Vst Admin Hosp LA: California Vst Admin Hosp WR: Massachusetts Vst Admin Hosp MR:Massachusetts Vst Admin Hosp MR:MA	7906140581 7906160046 7906080056 7906070174 7906130410 7906020204	REGOD PR REGOD PR PR		Div  Combustion Engineering. Inc	7704210263 7704170081 7704240041 77042100076 7704240008 7704070277	70-364 GA999 50-320 GA999 70-1100 50-470	C G C A
Vet Admin Hosp. SA, Virginia	7906130183	PR		C-E Power Systems	7906120281 7906040250	TOPREP 50-317	P
HANDFACTURERS/EQUIPMENT AND SUPPLIES	700/10004/	GA999		Carboline Co	7906110290 7906110293 7906140474	50-309 50-309 ORG	P
Anchor/Darling Valve (subs of Anchor/Darling Industriet, Inc.) Aeroset Ordnance Co Allied Chemical Corp. Astrotech, Inc. Atwood & Horrill Co., Inc. (subs of Foster Wheeler Corp.)	7706050095 7706140063 7706200605 7706050170	XPORTLIC 71-324	c c	Carpenter Technology Corp Chevron Oil Co (subs of Standard Oil Co. of California) Cleyeland-Cliffs Iron Co.	7906210259 7906210263 7905240131 7906020238	XPORTLIC XPORTLIC 10CFR 40-8714	1
Eectman Instruments, Inc. Bingham-Hillamette Co. Pandiz Corp	7906180363 7906160007 7906160005 7906290705	PR GA777 GA777 GA777		Chem-Nuclear Bystems, Inc.	7906020237 7906020173 7906180789 7906220419 7906220228	40-8714 27-47 71-6244 71-321 71-6244	C
Borg-Herner Corp	7906290683 7906010072	GA999 71-28	C	Consolidated Controls Corp. (subs of Condec Corp.)	7906020197 7906230028	XPORTLIC QA999	;
Borg Harner Corp , Byron Jackson Pump Div	7906010069 7906200227 7906200221	71-28 TOPREP TOPREP	C	Cooper Industries, Inc., Cooper Energy Bervices Div Consumer Fuels, Inc. Control Components, International (subs	7906220053 7906070164	50-320 71-322	PC
Boston Insulated Wire & Cable Co	7906200218 7906210023 7906020221	TOPREP REGOD 40-8722	c	of Babcock & Wilcox)	7904070171	71-322	G
Brush-Wellman, Inc	7906230120 7906290781	40-8722		Cotter Corp Crosby Valve & Oage Co. Dow Chemical Co.	7706260557 7706210091 7706200600	40-8692 QA999 PRN	
Buckeye international, Inc., Steel Castings Div.	7906040125	71-110	C G		7906010272 7906290684	50-329 50-329	Ģ
Bucyrus-Erie Co	7906040132 7906110427 7906110425	71-110 71-310 71-310	G G	Diamond Power Specialty Corp. (subs. of Babcock & Wilcox)	7906010108	GA997	
Burndy Husty Bebcack & Hilcox Co	7906070381 7906070022 7906290298	50-358 GA999 50-320 50-320	A A	Dow Corning Gorp Dravo Corp	7906130304 7906230062 7906230060 7906230057	PRH GA777 GA777 GA777	
	7906290248 7906290259 7906290273 7906290287	50-320 50-320 50-320	A A	Dresser Industries, Inc Eberline Instrument Corp. Edlow International Co.	7906290572 7906200493 7906180747 7906180761	GATTT RECOD SECY BECY	
	7906230140 7906230149 7906230148 7906230137	TOPREP 50-320 50-320 TOPREP	c U		7906180766 7906030072 7906030077 7906290383	SECY XPORTLI XPORTLI BECY	
	7906250157	70-364	C		7906140057	XPORTLI	C

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Exxon Nuclear Co . Inc (40bs of Exxon Corp )	7906010315	70-1257 C		7906130237 7906150253	TOPREP TOPREP
Exam Co	7906140536 7906180778 7906270077 7906120230 7906140038	PR REGOD TOPREP TOPREP 71-321 C		7906060149 7906060166 7906110260 7906150344 7906170285	TOPREP TOPREP TOPREP TOPREP 50-70 F
Federal American Partners Foster Wheeler Corp.	7906140040 7906020123 7906020224	71-321 C 40-4492 C 71-99 C		7906190421 7906200273 7906200182 7906210161	TOPREP 50-73 P TOPREP TOPREP
Foxboro Ca	7903300243 7903300235 7906060086 7906060075	50-250 U 50-250 U GA999		7906260415 7906220235 7906260003	TOPREP 50-73 P 50-73 P
Froshling & Robertson, Inc General Atomic Co (subs. of Quif Gil Gorp.)	7906230011 7906150094	71-157 C RECOD		7906270117	50-73 E
	7906050196 7906050088 7906050092	GA999 XPORTLIC XPORTLIC	Culf Ressarch & Davelopment Co Hirata Valve Industry Co., Ltd , Kawaski Div.		40-8032 C QA999
	7906120217 7906120227 7906200607 790620194	XPORTLIC XPORTLIC PR XPORTLIC	Hittman Nuclear & Davelopment Corp (subs of Hittman Corp )	7906290243 7906230031 7906230043	9A999 71-9079 € 71~9079 €
Quruma Field Co	7906180797 7906180800 7906210141 7906190490 7906200251	XPORTLIC XPORTLIC 50-267 P TOPREP 71-70 C	Hoke, Inc	7904070244 7904050157 7904040185 7904070125	XPORTLIC XPORTLIC XPORTLIC XPORTLIC
Oeneral Electric Co	7906200256 7906020087 7906040218 7906010292	71-70 C PROJ 50-10 P 70-754 C		7906070155 7906070166 7906160043 7906180072 7906050167	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC
	7906070100 7906250226 7906050130 7906150474 7906290511	FOIA  70-1308 C 70-1308 C XPORTLIC SECY	<pre>Industrial Heat Treating Ingersoll-Rand Co Ishikawajima - Harima Heavy Industries Co .Ltd. Isomedix, Inc (subs of Maesfield</pre>	7906010305 7906230015 7906230012 7906210331 7906040137	71-326 C 71-119 C 71-119 C 9A999
	7906160058 7906150029 7906150029 7906210411 7906110274 7906220462	TOPREP  XPORTLIC XPORTLIC XPORTLIC 71-59 C 50-416 Q	Enterprises, Inc }  Johnson Controls, Inc,  Kawecki Berylco Industries, Inc Kerr-McGee Corp	7906060034 7906010224 7906010226 7906150471 7906200381	71-5595 C 71-302 C 71-302 C XPORTLIC 40-8027 C
	7906060141 7906150147 7906150146	TOPREP 50-73 P 50-73 P	Lesile Co LFE Gorp	7906050163	QA999
General Dynamics Corp	7906180 <b>5</b> 78 7906180 <b>57</b> 2	71-220 C 71-220 C	Limitorque Corp  Harubeni America Corp (subs. of Marubeni	7906130175 7906130424 7906130420 7906170097	PR 50-275 A 50-275 A XPORTLIC
General Dynamics Corp , Guincy Shipbuild ing Div.	7906230022	71-154 C	Carp )	7906190100	XPORTLIC
Osmeral Electric Co , Nuclear Emergy Products Div.	7906070167 7906200289 7906200292	FOIA 50-73 P 50-73 P	Marathon Gil Co Maynard Steel Casting Co	7906230105 7906140006 7906140008 7906200261	XPORTLIC 71-318 C 71-318 C 71-188 C
	7706200282 7706130238 7706130243 7706200278 7706010289	50-73 P TDPREP TDPREP 50-73 P 70-754 C	Mitsui & Co , Ltd Mitsubishi International Corp (subs. of	7906200263 7906140617 7906290353 7906270018	71-188 G XPORTLEC BECY XPORTLEC
	7906200286 7906110074	50-73 P WASTE MOT	Mitsubishi Corp ) Nuclear Engineering Co , Inc (subs of Teledyne, Inc )	7904140606 7906270052	71-6038 C 27-48 C
	7906250360 7906180776 7906250358	70-1151 C SECY 70-1113 C	New England Nuclear Corp Nuclear Fuel Services, Inc. (subs. of	7906110434 7906040175	71-6400 C 70-143 C
	7906180358 7906230158 7906130309 7906200188	PR 70-1308 C TOPREP TOPREP	Qetty Gil Co. )	7906250209 7906230183 7906250473	70-143 C 70-143 C 70-143 C
	7906020190 7906200384 7906230135 7906230312 7906210323 7906210313	XPORTLIC  70-1308 C  70-1113 C  70-1113 C  XPORTLIC  XPORTLIC	Niswho-Iwai American Corp.  Nuclear Packaging, Inc.	7906060024 7906250309 7906250840 7906180060 7906020192 7906280156	71-6400 C 70-143 C 70-143 C 8ECY XPORTL1C
	7904210320 7904210293 7904250254 7904250053	XPORTLIC XPORTLIC 70-1308 C REB TOMBEE	Nuclear Welding, Inc.  Ogle Patroleum, Inc.  O'Neill Tank Co , Inc	7906220455 7906220459 7906020184 7906040148	71-74 C 71-74 C 40-8693 C 71-233 C
	7906110304 7906130308 7906040178 7906130239	TOPREP TOPREP TOPREP TOPREP	Offshore Power Systems (subs. of Hestinghouse Electric Corp.)	7906040151 7906210038 7906040410 7906110171	71-233 C REGOD 50-437 Q 50-437 A

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Pathfinder Hines Corp	7906050232 7906050246 7906040120	40-2259 C 40-2259 C		7906230167 7906070281 7906250067 7906250234 7906050071	70-1151 C 30-247 P XPORTLIC 70-478 C 71-9010 C
Picter Corp Fittsburg - Des Moines Steel Co Process Equipment Co , Inc Fadiography Inspections	7906200091 7906160002 7906160003 7906060048	71-9080 C 71-320 C 71-320 C 9A999		7906130196 7906250030 7906160016 7906130099 7906290749	PRM 50-574 A 71-5450 C XPORTLIC XPORTLIC
Paytheon Ca. Reuter-States: Inc.	7906040104 7906080260 7906040084 7906190089	71-315 C 50-568 A XPORTLIC XPORTLIC		7904040157 7904220290 7904220294 7904220310 7904270274	TOPREP TOPREP TOPREP TOPREP XPORTLIC
Akadia.Inc /Rhade-Paulene, Inc Active   International Corp #M  Co . RMI Titanium	7906210414 7906190110 7906190107 7906020091 7906180638	XPORTLIC XPORTLIC XPORTLIC PROJ BECY		7906270083 7906210361 7906070271 7906140344	XPORTLIC 50-574 Q TOPREP TOPREP
Sandwit Special Metals Corp  Senjamin F Bhaw Co (subs of Blount, inc.)	7906190063 7906190072 7906200220	XPORTLIG XPORTLIC 71-223 C		7906210225 7906200198 7906210138 7906210245 7906210258	TOPREP TOPREP TOPREP TOPREP TOPREP
Sigms Chemical Co. (tubs of Bigma Aldrich Corp )	7906140612	XPORTLIC		7906200480 7906220321	SO-275 A
SMAPPS-Standardized Nuclear Unit Power Plant System	7906050111 7906190112 7906220172 7906120146	XPORTLIC XPORTLIC XPORTLIC 50-483 A	Western Nuclear, Inc (subs of Phelps Dodge Corp )	7906200201 7906210246 7906110038	TOPREP TOPREP WASTE MOT
Spraying Systems Co	7906120263 7906270211	50-492 A TOPREP	Word Industries Pipe Fabricating, Inc.	7906160047	40-1162 C 71-229 C
Southwest Fabricating & Welding Co (subs of IV International Corp.)	7906290671 7906290651	QA979 QA979	Myoming Mineral Corp Yarway Corp	7906110050 7906200233 7906180659	WASTE MOT 40-8502 C QA979
South Hest Nuclear Go Teras Instruments, Inc	7906110055 7906130126	HASTE MOT 70-33 C	Yuba Heat Transfer Corp Zurn Industries, Inc	7906130406 7906290545	PRM 50-382 B
	7906250310 7906250308 7906260361 7906200087 7906110255	70-33 C 70-33 C 70-33 C 70-33 C 50-247 P	PROFESSIONAL/INDUSTRIAL INSTITUTIONS, BOC	IETIES	
Transamerica Delaval, Inc	7906290223 7906290211	GA777 GA777	Atomic Industrial Forum  American National Standards Institute	7906070079 7906200350 7906220423	REGGD PR REGGD
Fransnuclear, Inc	7906020103 7906040440 7906140575	SECY XPORTLIC XPORTLIC	American Society of Mechanical Engineers American Society of Quality Control	7906160013	REGOD REGOD
	7906050101 7906140602	XPORTLIC XPORTLIC	Edison Electric Institute Health Physics Society	7904110081 7904260624 7904200219 7904130200	NASTE MOT PR PR PRM
Chemetron Corp : Tube Turns Div Union Carbide Corp	7906130290 7906020179 7906290831	50-400 8 40-299 C 71-9070 C	Industry Advisory Group International Brotherhood of Electrical	7906260469	50-320 P PR
United Nuclear Corp	7906120276 7906230161	50-54 P 70-820 C	Workers National Academy of Engineering	7904130191 7904180575	PR 50-320 T
	7906230159 7906260331 7906140587 7906180642	70-820 C 70-371 C 70-820 C 70-820 C	National Council on Radiation Protection & Measurements New England Regional Regulatory		PR WASTE MOT
	7906260336 7906160001	70-371 C	Assistance Program Power Engineering Boclety	7906200496	REGOD
	7906260020 7906200275 7906200277 7906260328	70-820 C 70-371 C 70-371 C 70-371 C	Special Instrument Group	791	
Union Hinerals US Steel Gorp Varian Esport Corp.	7906230164 7906230004 7905240422 7906140567 7906140560	70-820 C 40-8384 C 10CFR XPORTLIC XPORTLIC	Arkanses, State of California, State of		
Welworth Co (subs. of IU International Corf 1	7906200297	71-39 C			
Hestinghouse Electric Corp	7906200294 7906070274 7906040422 7906270197	71-39 C Toprep Toprep Toprep	Colorado, State of		
	7906250251 7906250254 7906250065 7906020080 7906020082	XFORTLIC XPORTLIC XFORTLIC PROJ PROJ	Delawara, State of Florida, Stata of Iowa, Stata of Illinois, State of		
	7906290845 7906290817 7906110036 7906210307 7906210358	30-574 A 27-47 C Wabte Mot Ga999 Pr			

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
Kentucky, State of	7906210395 7906060294 7906130322 7906230144	70-1308 C 50-599 A 50-599 C NUREO	7	7906040011 7906200568 7906020201 7906250356 7906270248	PRM 71-61 71-85	C C C
Louisiana, State of Massachusetts, State of	7906200353 7906110082 7906120008	PR WASTE MOT 50-471 0 50-471 0 50-471 0	Energy, Dept of	7904290448 7903020022 7904110023 7904070033 7904070040	NUREO ORQ HABTE HOT FOIA FOIA	†
	7906020251 7906010264 7906010265 7906290179 7906260005	50-471 0 50-471 0 50-471 0 50-471 0		7906050014 7906010115 7906020069 7906020071	71-5790 FOIA PROJ PROJ	c
michigan, State of	7906230141 7906070151 7906290678 7906130284	NUREQ 50-315 P 50-327 Q 50-452 D		7906020073 7906020074 7906020077 7906050286	PROJ PROJ PROJ HASTE MOT	
Missourí, State of Montana, Batto of New Jersey, State of New York, State of	7906260403 7906200579 7906010099 7906200611 7906040147	50-482 0 FRM 50-272 0 50-272 0 50-549 0		7906050288 7906230007 7906080288 7906280140	50-320	
	7906290060 7906050370 7906290054 7906110069	50-596 T 50-201 P 50-596 T Waste Mot	Justice, Dept of	7903300586 7906210175 7906070311 7906020129	30-445 50-445	H A
	7906010281 7906230138 7906050413 7906250220	50-596 D NUREO 50-596 G 50-201 F		7906190054 7906020037 7906020167 7906020037	50-445 50-445 50-445 50-445	 H H
	7904180810 7904180812 7904180810 7904180812	50-576 0 50-576 0 50-576 0 50-576 0		7906020167 7906020037 7906020167 7906020037	50-445 50-445 50-445 50-445	н н н
	7906030226 7906200382 7906260306 7906260311	NUREO 50-596 0 50-596 0 50-596 0	State, Dept of	7906020167 7906020037 7906020167 7906250188 7906180651	50-445 50-445 50-445 XPORTLIC SECY	H
	7906260506 7906260511 7906190085 7906140553	50-596 0 50-596 0 50-596 0 PR		7906180806 7906040408 7906010103 7906040435	SECY XPORTLIC XPORTLIC XPORTLIC	
Uhio, State of Oklahoma, State of Oregon, State of Pennsylvania, State of	7906030221 7906040379 7906270180 7906200618 7906260388 7906190482	NUREQ 50-556 0 50-344 P 50-320 H 50-463 0		7906070110 7906070276 7906070382 7906230094 7906020156 7906150256	COMMISSI XPORTLIC XPORTLIC BECY XPORTLIC XPORTLIC	
	7906070330 7906130211 7906260378 7906230147	50-334 Q 50-320 Q 50-463 Q NUREQ		7906180759 7906260012 7906290643 7906290753	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
Rhods Idland, State of South Carolina, State of	7906260301 7906220092 7906210392 7906070354 7906250212	50-320 U 50-320 P 50-568 A 27-47 C 70-2623 C		7906250307 7906020021	XPORTLIC XPORTLIC SECY	
Tennessee, State of Yesas, State of Utah, State of	7906160055 7906050082 7906060026 7906050187	PR 50-466 0 40-8681 C 40-3453 C 40-8681 C		7906230087 7906010087 7906040230 7906040233	XPORTLIC XPORTLIC	; ;
Virginia, State of Washington, State of Wisconsin, State of	7906180414 7906230146 7906230139 7906110054	NUREO NUREO WASTE MOT 40-8602 C	Transportation, Dept of Environmental Protection Agency	7906260100 7906260105 7906210170 7903200106	XPORTLIC XPORTLIC 50-568 ORO	
US FEDERAL GOVERNMENT AND AGENCIES	7906200244			7903200101 7906130492 7906130495 7906210028 7906010148	50-320 50-320 50-320 50-320 50-438	P P A
Agriculture, Dept. of Gommerce, Dept of National Oceanographic & Atmospheric Adminstration	7906210104	50-568 D 50-320 P 50-320 P		7906180704 7906280141 7906120337 7906130218	50-320 50-320 50-553 50-592	P U Ř
Defense, Dept, of Army, Dept of	7906290718 7906050004 7906200586 7906230121	PRM PRM 40-8584 C	Federal Bureau of Investigation  HEW.Dapt.of. Food & Drug Administration	7906260498 7906260498 7906260485 7906260479 7906200234	FOIA FOIA FOIA FOIA 50-320	R
Army Dept. of Electronics Research & Development Command	7906140503	40-8194 C		7906160704	50-320	P
Army.Dept of, Corps of Engineers Army.Dept of, White Bands Missile Range Army.Dept.of, Matls & Mechanics Rasearc: Conter Navy.Dept.of	7906070238 7906220039 7906020023 7906040008	50-392 A PRM BEGY 71-37 C	Health, Education & Welfare, Dept of	7903200106 7906200430 7906130419 7906130486 7906290020	080 50-320 50-320 50-320 FOLA	P P
••		•				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
:€W.Dept of. US Public Health Service Hause of Rep	7906180704 7906290015 7906260462 7906290027 7906260391 7906050172 7906110411 7906180267	50-320 P F01A 50-592 D F01A 50-463 Q 50-482 U 50-280 U 50-275 Q		7906060238 7906130214 7906130145 7906120367 7906190240 7906190245 7906190240	50-313 P 50-313 R 50-313 P 50-313 P 50-313 P 50-313 P
	7906280261 7906080026 7906280590 7906290261 7906210043 7906050007 7906260544	COMMISSION 50-10 U 50-250 U 50-367 U FR-338 U 50-269 U		7906190245 7906150306 7906180598 7906180598 7906180507 7906180560	50-313 P 50-313 P 50-313 P 50-313 S 50-314 S 50-348 S
hause of Rep , Foreign Affairs	7906080199 7906070043 7906070045 7906250175 7906280249	50-275 U 50-478 U 50-250 U 50-358 U COMMISSION		7906180376 7906180387 7906200360 7906190262	50-348 8 50-348 8 50-313 P 50-313 R
Hause of Rep , Government Operations Hause of Rep , Interstate & Foreign Commerce	7906270157 7906280254 7906110309	COMMISSION		7906190765 7906210227 7906190273 7906210229 7906190268	50-313 R 50-313 Q 50-348 R 50-313 Q 50-368 R
House of Rep , Interior & Insular Affairs	7906120012 7906120015 7906120021	50-320 U 50-320 U 50-320 U		7906200214 7906270147 7906200214 7906270147 7906250265	50-313 P 50-313 F 50-313 P 50-313 F 50-313 8
House of Rep : Science & Technology Libyary of Congress Commercs,Dept.of, National Bureau of	7906290097 7906210262 7906210260 7906200528	50-320 U 50-320 U 50-320 U REGOD	AZPS - Arizona Public Service Co	7906250266 7906270115 7906160053 7906060266	50-313 S 50-313 P PR 50-528 A
Standards Prasident of US & Executive Offices Senate	7906120003 7906270168 7906280266 7906290285	50-920 R COMMISSION COMMISSION 50-478 U		7906180486 7906050302 7906050325 7906050302 7906050325	50-572 C 50-572 C 50-572 C 50-572 C 50-572 C
	7906050104 7906250459 7906070290 7906290672 7906070290	40-8498 C 50-482 U 50-315 U 50-315 U 50-315 U	AECO - Boston Edison Co	7906260459 7906260459 7906040212 7906040217 7906080100	50-592 D 50-592 C 50-293 B 50-293 B 50-293 Q
Senste, Environment & Public Works	7906290672 7906070288 7906270058 7906150231	50-315 U 50-315 U 50-544 U 50-320 U		7906070002 7906020200 7906050435 7906260027 7906260032	50-273 0 50-273 0 50-273 0 50-471 0 50-471 0
UTILITIES/HOLDING COMPANIES/INVESTOR ABBOC				7904290145	50-471 Q
AEP - Amarican Electric Power Co , Inc. ALPR - Alabama Power Co	7906040049 7906260421 7906290483 7906220247 7906290761	50-315 G 50-315 P 50-320 G 50-348 G 50-348 Q		7906270106 7906220116 7906290773 7906080258 7906120300	50-273 Q 50-471 0 50-273 Q 50-273 Q 50-273 S
	7906290723 7906050285 7906050287 7906040279 7906040283	50-348 Q 50-348 S 50-348 S 50-348 S 50-348 S		7906120303 7906120434 7906190250 7906220305 7906250286	50-293 S 50-293 P 50-293 R 50-293 F 50-293 G
	7906190260 7906150326 7906190239 7906190242 7906190258	50-348 R 50-348 P 50-348 8 50-348 8 50-348 R	BQE ~ Reitimore Que & Electric Co.	7906040191 7906040202 7906040354 7906040357 7906020199	50-317 8 50-317 8 50-318 8 50-318 5 50-317 0
	7906190464 7906250289 7906250292 7906250250 7906250252	50-348 P 50-348 B 50-348 S 50-348 S 50-348 S		7906190194 7906150218 7906120285 7906220058 7906140458	PR 50-317 G 50-317 G PR 50-317 G
APL - Arianses Power & Light Co.	7906260333 7906220347 7906040152 7906050213	50-348		7904010200 7904010207 7904050243 7904050245	50-318 8 50-318 8 50-318 8 50-318 8
	7906080298 7906250105 7906070374 7906040209 7906070181	50-313 8 50-368 0 50-313 0 50-313 0		7906010247 7906040248 7906070296 7906070301 7906060288	50-317 P 50-317 P 50-317 8 50-317 8 50-318 8
	7906270041 7906040209 7906220100 7906290513 7906040267 7906070138	50-320		7906060289 7906070296 7906070301 7906080247 7906080248 7906120265	50-318 8 50-317 8 50-317 8 50-317 8 50-317 8 50-317 P
	. 100010100	ar ara t		.,	1

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGORY
	7906120359 7906140349 7906140352 7906150141 7906150366 7906150368	TOPREP 50-317 S 50-317 S 50-317 P 50-317 Q		7906040334 7906040337 7906110126 7906110133 7906140389	50-304 8 50-304 8 50-304 8 50-304 8 50-304 8
	7706150366 7706150369 7706220231 7706250262	50-317 G 50-317 G 50-317 P 50-317 R		7706140376 7706270122 7706270127 7706150338 7706120310	50-304 B 50-295 R 50-275 R 50-10 R 50-237 B
	7706220231 7706250262 7706250263 7706250215	50-317 P 50-317 R 50-317 R 50-317 R 50-317 S		7906120313 7906200404 7906200409 7906190246 7906220355	50-237 8 50-237 8 50-237 8 50-254 R 50-304 8
	7906250273 7906280135 7906260338 7906260348	50-318 8 50-317 P 30-318 8 50-318 8		7906220453 7906120240 7906140385 7906140393	50-304 8 50-295 F 50-373 8 50-373 B
BHEC - Bangor Hydro-Electric Co CEIL - Commonwealth Edison Co	7906260439 7906260442 7906280135 7906060263 7906230134	50-318 8 50-318 8 50-317 P 50-443 I NUREO		7906140395 7906140393 7906130225 7906130380 7906130225	50-373 B 50-373 B 50-599 A 50-599 A 50-579 A
	7906020014 7906260629 7906070273 7906210230 7906290493	50-254		7706130380 7706120260 7706120376 7706120385 7706180512	50-599 A 50-10 J 50-237 8 50-237 8 50-249 8
	7906140253 7906060273 7906140253 7906070241 7906180784	50-275		7906180315 7906120260 7906220390 7906220394 7906220399	50-249 8 50-10 J 50-304 8 50-304 9
	7906060240 7906060245 7906060282 7906060286 7906060292	50-254 S 50-254 S 50-304 G 50-304 S 50-295 S		7906220401 7906120343 7906120349 7906120343 7906130336	50-295 R 50-295 R 50-295 R 50-295 R 50-10 R
	7906060293 7906060223 7906060226 7906010238 7906040216	50-275 8 50-304 8 50-304 9 50-577 A 50-10 P		7906200370 7906200371 7906190418 7906190432 7906190437	50-237 8 50-237 8 50-249 8 50-249 8
	7906220158 7906250350 7906260238 7906050353 7906080276	50-456 @ 50-237 8 50-373 G 50-237 B 50-599 A		7906190447 7906220381 7906220386 7906220389 7906220339	50-249 6 50-265 8 50-265 9 50-275 J 50-265 8
	7906040187 7906140554 7906140561 7906040187 7906030369	50-10 J 50-304 S 50-304 B 50-10 J 50-10 F		7906210220 7906200335 7906270215 7906270217 7906200335	50-237 P 50-247 P 50-265 B 50-265 8 50-249 P
	7906070256 7906050245 790605024B 790605026B 7906050269	50-10 J 50-237 S 50-237 S 50-237 S		7906190289 7906190294 7906210190 7906220282 7906220291	50-10 8 50-237 P 50-237 B 50-237 B 50-237 B
	7906030371 7906070270 7906140367 7906140372 7906140311	50-237 P 50-599 A 50-304 8 50-304 8 50-304 8		7906220365 7906220373 7906210190 7906270202 7906270203	50-237 8 50-237 P 50-254 8 50-254 8
	7906140521 7906130227 7906130230 7906130227 7906130230	50-304 S 50-577 A 50-577 A 50-577 A 50-577 A	-	7906210190 7906270207 7906270208 7906250284 7906270152	50-237 P 50-295 B 50-295 B 50-373 B 50-249 B
	7906040278 7906040293 7906040297 7906040301 7906040319	50-237 9 50-237 8 50-237 8 50-237 8 50-249 8		7906270188 7906230284 7906220352 7906280293 7906270212	50-249 8 50-373 8 50-599 A 50-295 P 50-295 8
	7906040325 7906040327 7906040330 7906110129 7906140416	50-295 8 50-295 8 50-295 6 50-295 8		7906270214 7906270293 7906220380 7906270179 7906270162	50-295 H 50-295 P 50-397 C 50-275 P 50-275 B
	7706140418 7706270122 7706270127 7706040333	50-275 8 80-275 R 50-295 R 50-394 G		7906270164 7906270236 7906260180	50-295 B 50-10 P 50-599 C

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	<u>.</u>	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODRY
CENCY - Consolidated Edison Co. of New	7906260159 7906260150 7906260159 7906040278	50-599 50-599	C C C		7906130020 7906130031 7906130140 7906120160 7906120172	50-255 R 50-255 R 50-255 P 50-155 B 50-255 P
Yarê	7906040284 7906140259 7906200603 7906020081	50-3 PR 50-3	8 R G		7906130002 7906150137 7906150197 7906150285 7906140375	30-235 P 50-255 P 50-325 B 50-327 A 50-255 P
	7906070285 7906010215 7906080148 7906290850 7906270204	50-247 50-3 50-3 50-3	G G G		7906290533 7906190448 7906190174 7906250290 7906200172	50-329 F 50-329 K 50-155 P 50-255 P 50-155 F
	7906010267 7906040183 7906190466 7906070275 7906190257	50-247 50-3 50-247 50-247	G P R P C		7906220267 7906220269 7906220190 7906220353 7906220371	50-255 8 50-255 8 50-255 P 50-329 5 50-329 9
	7906060129 7906060129 7906060133 7906190462 7906260006	30-247 50-247 50-3	R P P R R		7906220353 7906220371 7906260188 7906260194 7906260353	50-329 8 50-329 8 50-155 P 50-155 P 50-155 8
	7906110245 7906040291 7906190478 7906190387 7906260004	50-247 50-3 50-3	P 8 R F R		7906260377 7906260181 7906260188 7906280161 7906280163	50-155 B 50-255 P 50-155 P 50-327 A 50-155 P
	7906260407 7906260004 7906260407 7906190253 7906210128	50-3 50-3 50-247	f f f c p	CPL ~ Carolina Power & Light Co	7906150340 7906150341 7906080151 7906080181 7906040019	50-324 8 50-324 8 50-324 9 50-324 9 50-261 9
CGEC - Cincinnati Gas & Electric Co	7906220303 7906210128 7906220303 7906080197 7906250362	50-3 50-3 50-358	0 6 1		* 7906210096 7906140491 7906290787 7906290719 7906120190	50-324 Q 50-324 Q 50-400 Q 50-324 Q 50-324 P
	7906080206 7906140520 7906280258 7906260617 7906120174	50-358 50-358 50-358	а а а К		7906040153 7906230017 7906010192 7906010240 7906040221	50-324 8 50-324 G 50-400 C 50-324 P 50-324 G
CLEI — Cleveland Electric Illuminating Co	7906120181 7906190408 7906190446 7906070091 7906070048	50-358 50-358 REGOD	K K J		7906080315 7906140297 7906140351 7906140391 7906040221	50-324 P 50-324 B 50-324 B 50-324 B 50-324 Q
CLP — Connecticut Light & Power Co CMPC — Central Maine Power Co CPA — Cooperative Power Association CPC — Consumers Power Co	7906080257 7906200377 7906060267 7906220206 7906070178	50-440 50-245 50-443	B I I	ć'	7906050259 7906050262 7906080315 7906140297 7906140351	50-325 8 50-325 9 50-324 P 50-324 8 50-324 8
	7906070185 7906110051 7906070416 7906020047 7906130204	HASTE MGT	A a		7706140391 7906010192 7906080291 7906080293 7906080263	50-324 B 50-400 C 50-261 P 50-261 P 50-324 P
	7906020163 7906020160 7906140246 7906080310 7906200021	50-155 50-255 50-155 50-255	G G G E	•	7706120157 7706080265 7706120157 7706080177 7706050305	50-324 P 50-324 P 50-324 P 50-261 J 50-325 S
	7906290778 7906290075 7906230045 7906010239 7906010248	50-255 50-155 50-255 50-255	0 9 8 8		7906080316 7906050308 7906050328 7906050332 7906080316	50-324 8 50-325 8 50-325 8 50-325 8 50-324 8
	7906040189 7906070133 7906290522 7906080308	50-155 50-255 50-327 50-255	F J T 8		7906070194 7906070200 7906070265 7906110167 7906140494	50-261 8 50-261 8 50-261 8 50-261 R 50-261 8
	7906050214 7906050220 7906070263 7906290317 7906050214	50-329 50-329 50-329 50-329	K K A T K		7906070279 7906070282 7906070291 7906080250 7906080278	50-324 8 50-324 8 50-324 8 50-324 8 50-324 P
	7906030220 7906070263 7906290317 7906060236 7906110165	50-329 50-329 50-255	K A Y P P		7906140449 7906080278 7906140449 7906070283	50-324 R 50-324 P 50-324 R 50-324 B

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCEBSION NUMBER	SUBJECT CATEGORY
	7906070251 7906080249 7906120428	50-261 8 50-324 8 50-400 A		7906290732 7906290812 7906290742 7906050313	50-213 0 50-213 0 50-213 0 50-213 P
	7906120393 7906120428 7906120231 7906120422	50-324 P 50-400 A 50-261 F 50-324 S		7906080262 7906150389 7906150391 7906190424	50-213 P 50-213 R 50-213 R 50-213 J
	7906120424 7906110166 7906110228	50-324 B 50-261 R 50-324 S		7906200106	50-213 Q
	7906110232 7906120382 7906120388	50-324 8 50-324 8 50-324 S	DAYP - Dairyland Power Cooperative	7906190396 7906220286 7906140456 7906020198	50-213 T 50-213 P 50-409 S 50-409 Q
	7906150177 7906150183 7906110176	50-324 8 50-324 8 50-325 8		7906020189 7906200373 7906140168 7906120341	50-409 Q 50-409 Q 50-409 Q 50-409 P
	7906110188 7906110189 7906110192 7906150167 7906150174	50-325 8 50-325 8 50-325 8 50-325 8		7906060269 7906060265 7906120427 7906120417	50-409 8 50-409 8 50-409 R 50-409 R
	7906150201 7906150237 7906150241 7906150245 7906150250	50-325 8 50-325 8 50-325 8 50-325 8 50-325 8		7906150217 7906150225 7906150310 7906150318	50-409 F 50-409 S 50-409 S
	7906150319 7906140444 7906150319 7906140285	50-400 A 50-324 R 50-400 A 50-400 A		7906200380 7906270192 7906270194 7906260212	50-409 F 50-409 S 50-409 F
	7906140312 7906140314 7906140327	50-325 8 50-325 8 50-325 8	DE - Detroit Edison Co	7903200326 7906040455 7906260108 7906140434	50-341 0 50-341 0 50-341 0 50-341 0
9	7906140533 7906140285 7906180501 7906180506	50-400 A 50-261 B 50-261 B		7906290694 7906280225 7906050284 7906080263 7906080264	50-341 Q 50-341 Q 50-341 A 50-341 B 50-341 B
	7906180509 7906180514 7906200348 7906150249	50-324 8 50-324 8 50-324 P 50-400 A	OL - Duqueene Light Co	7906010236 7906190378 7906040245 7906040249	50-341 K 50-341 A 50-334 B 50-334 B
	7906200356 7906200366 7906220370 7906220375 7906220406	50-261 P 50-325 8 50-324 8 50-324 8 50-324 8		7906040402 7906070235 7906130134 7906180249	50-412 8 50-334 0 50-334 0 50-334 0
	7906220409 7906220413 7906220420 7906200367	50-324 8 50-324 8 50-324 8 50-325 8		7906160040 7906270790 7906270203	50-334 P 50-334 Q
	7906220312 7906220316 7906220327 7906220330 7906150249	50-325 8 50-325 8 50-325 8 50-400 A		7906270196 7906050282 7906290746 7906010152	50-334 Q 50-334 P 50-334 Q 50-334 R
•	7906220398 7906220400 7906220284 7906220294	50-324 8 50-324 8 50-325 8 50-325 8		7906010253 7906050275 7906080300 7906080304 7906130340	50-334 J 50-334 R 50-412 8 50-412 8 50-412 A
	7906260538 7906270167 7906270169 7906270199	50-261 P 50-324 8 50-324 8 50-324 8		7906120328 7906120325 7906150312 7906200155	50-334 R 50-334 R 50-334 P 50-334 P 50-334 G
	7906270201 7906270174 7906270176 7906280129	50-324 8 50-261 8 50-261 8		7906180601 7906210131 7906260397 7906280351	50-334 9 50-334 P 50-334 B 50-334 P 50-334 S
	7906280131 7906290356 7906290362 7906280084	50-325 8 50-324 8 50-324 8 50-325 8		7906290328 7906290333 7906290339 7906290600	50-334 B 50-334 B 50-220 P
	7706280088 7706280098 7706280101 7706290345	50-325 8 50-325 8 50-325 8 50-325 8	DPC - Duke Power Co	7906010126 7906260250 7906070170	50-488 0 50-269 0 70-2623 C
CVPBC - Central Vermont Public Service	7906290353 7906290366 7906290371 7906060256	50-325 8 50-325 8 50-325 8 50-443 I		7906120016 7906070105 7906140329 7906020121 7906050399	70-2623 C FOIA PR 50-367 G 70-2623 C
Corp CYAP - Connecticut Yankee Atomic Power Co.	7906200110	50-213 0		7906080121 7906040037	70-2623 C 70-2623 C
	7906120050 7906050278	50-213 Q 50-213 Q		7906160033 7906130443 7906130439	50-369 Q 50-488 Q 50-413 Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	, 
	7906130443 7906110062 7906140615 7906040360 7906020245	50~488 Q 50~269 Q REQQD 50~369 Q 70~2623 C		7906180508 7906120236 7906180305 7906190298 790620267	50-302 50-302 50-302	8 P 8 R
	7906140428 7906020154 7906140428 7906160062 7906220061	50-489 G 50-419 G 50-488 G 71-6698 C PRM		7906250278 7906220201 7906220204 7906280146 7906260220	50-302 50-302 50-302	5 0 P 8 P
	7906020109 7906120291 7906140122 7906210126 7906050391	70-2623 C 50-269 G 50-370 G 70-2623 C ORO	FPL - Florida Power & Light Co	7906230296 7906280120 7906070226 7906250350 7906070363	50-302 50-250 50-250	S P O P O
	7906040421 7906260244 7906140353 7906180741 7906250057	50-269 Q 50-269 Q 50-269 B 50-413 Q 70-2623 C		7906130434 7906180195 7906230142 7906050019 7906240515	50-335 NUREG 50-250	G G
	7906280008 7906250170 7906190114 7906200265 7906200027	70-2623 C 50-367 Q 50-491 Q 50-269 Q 50-491 Q		7906030019 7906020186 7906030451 7906200491 7906250129	50-250	P Q: Q:
	7906140334 7906140336 7906010346 7906140181 7906290829	50-491 8 50-491 8 50-369 0 50-369 0 50-269 0		7706230006 7706120025 7706260358 7706010262 7706260609	50~335 50~250	Ot P Ot R Ot
	7706260284 7706010244 7706010251 7706260284 7706140360	50-369 Q 50-370 S 50-370 S 50-369 Q 50-269 B		7906140384 7906280093 7906260290 7906260293 7906260288	50-251 50-302 50-250 50-335 50-389	\$ @ @ @
	7904040229 7904200597 7904070238 7906050329 7906280151	50-287 P 70-2623 C 50-269 P 50-269 P 50-269 R		7906030307 7906120338 7906120344 7906120348 7906120352	50-335 50-250 50-250 50-250 50-250	P 8 8 8
	7906030329 7906280131 7906050329 7906280131 7906050327	50-269 F 50-269 R 50-269 F 50-269 R 50-269 F		7906140376 790606077 79060677 7906120354 7906120363	50-335 50-250 50-250 50-250 50-230	8 P 8 8
	7906120225 7906130320 7906130324 7906130320 7906130324	50-269 G 50-269 B 50-269 B 50-269 B 50-269 B		7706060135 7706060274 7706060277 7706080276 7706050315	50-251 50-250 50-250 50-251 50-335	P P P P
	7906150280 7906130331 7906150267 7906170261 7906210149	50-369 J 50-249 J 50-269 F 50-269 F 50-269 R		7704080285 7704200418 7704200345 7704180510 7704180511	50-251 50-250 50-251 50-251	P # 8 8 8
	7906210153 7906210149 7906210153 7906210149 7906210153	50-269 R 50-269 R 50-269 R 50-269 R 50-269 R		7706   20386 7706   80474 7706   80478 7706   80304 7706   80307	50-302 50-335 50-335 50-335 50-335	9 8 8
	7906220283 7906260529 7906260533 7906280148 7906290314	50-269 P 50-270 8 50-270 8 50-269 R 50-269 8		7906180554 7906180555 7906180557 7906180558 7906130207	50-335 50-335 50-335 50-335 50-250	8 8 8 P
EAS? - Eastern Utilities Associates FGEL - Fitchburg Oas & Electric Light Co.	7906280148 7906290314 7906280148 7906190340 7906190343	50-267 R 50-267 B 50-267 R 50-443 I 50-443 I		7906130235 7906180613 7906180620 7906190266 7906220184	50-250 50-250 50-250 50-250 50-250	P 8 8 P P
FPC - Florida Pawer Corp.	7904180366 7906110064 7906030164 7906290146 7906290739	50-302 0 50-302 0 50-302 0 50-320 0 50-302 0		7906250349 7906220309 7906280142 7906060221 7906150296	50-250 50-335 50-302 50-321 50-366	P 8 8 8
	7906290726 7906290730 7906200271 7906120407 7906130017	50-302 Q 50-302 Q 50-302 R 50-302 S 50-302 S		7906150304 7906040010 7906070377 7906040004 7906200527	50-364 50-321 50-321 50-321 50-321	8 P R P G
	7904110152 7904190303 7904120278 7904120399 7904130014	50-302 P 50-302 S 50-302 P 50-302 S 50-302 S		7906050085 7906050003 7906140081 7906140436	50-366 50-321 50-321 50-321	9 9 9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	7906050108 7906140081 7906140436 7906190077 7906200532	50-366 Q 50-321 Q 50-321 Q 50-424 Q 50-321 Q	ОМРС - Green Mountain Power Corp GPU - GPU Service Corp	7706260208 7706060257 7706120380 7706180608 7706260327	50-320 50-443 50-289 50-320 50-320	F I I
	7706140230 7706060224 7706060227 7706040297 7706040304 7706060222	50-424 0 50-366 8 50-366 8 50-321 8 50-321 8 50-321 8		7906290320 7906260329 7906260332 7906280164 7906280167 7906280170	50-320 50-320 50-320 50-320 50-320	P Q P P
	7906140358 7906060233 7906060239 7906140414 7906050297	50-321 8 50-366 8 50-366 8 50-366 8 50-424 F		7706290408 7706280162 7706280239 7706280240 7706280140 7706280160	50-320 50-320 50-320 50-320 50-320 50-320	P P P P P
	7906060210 7906140355 7906140467 7906050274 7906060215 7906060215	50-321 8 50-364 8 50-366 8 50-321 F		7906290255 7906290274 7906280127 7906290315 7906260310 7906260314	50-320 50-320 50-320 50-320 50-320 50-320	P P P P R
	7906140542 7906140551 7906060243 7906060249 7906140341 7906140346	50-321 8 50-321 8 50-366 8 50-366 8 50-366 8 50-366 8		7706280149 7706280238 7706270043 7706280150 7706280154	50-320 50-320 50-320 50-320 50-320	P
	7906140301 7906140309 7906140317 7906140332 7906060284 7906140326	50-366 8 50-366 8 50-366 8 50-424 H 50-366 8		7904280152 7906280155 7906280157 7906280158 7906260270 7906260200	50-320	P P P
	7906140531 7906140419 7906140424 7906050300 7906130327 7906050300	50-366 8 50-366 8 50-366 8 50-424 F 50-424 A 50-424 F	OBU - Quif States Utilities Co HELCO - Hartford Electric Light Go	7906150328 7906210204 7906220036 7906120392 7906130004 7906200376	50-219 50-320 50-458 50-458 50-458 50-245	3 8 8 E
	7906130327 7906130023 7906130023 7906120429 7906080246 7906080295	50-424 A 50-321 R 50-326 R 50-321 P 50-321 P	HLP - Houston Lighting & Power Co	7906210107 7906120141 7906120390 7906120430 7906130007 7906130008 7906120390	50-498 50-498 50-498 50-498 50-498	99 88888
	7906140447 7906150270 7906200444	50-366 8 50-366 8 50-366 8		7706120430 7706130007 7706130008 7706130314 7706130315	50-478 50-478 50-478 50-478	8 8 K K
				7906130314 7906130315 7906120397 7906220367 7906120397 7906220367	50-498 50-498 50-498 50-498	8 8 8 8 8
			HULP — Hudsan Light & Power Dept. IELP — Iaww Electric Light & Power Ca	7906190328 7906260043 7906290637 7906260034 7906260232 7906260606	50-443 50-331 50-331 50-331 50-331 50-331	1 0 0 0
				7906230018 7906220432 7906010204 7906120272 7906150199 7906150316	50-331	9 9 9 5 7
				7906200248 7906200259 7906250299 7906250301 7906270150	50-331 50-331 50-331 50-331 50-331	R R 8 8
			ILPR - Illinois Power Co.  [MPR - Indiana & Michigan Power Co.	7906150204 7906130185 7906140464 7906140500 7906140500 7906270128 7906220287	PR 50-461 50-315 50-315 50-315	F 0 0

•

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	٩Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGOR	
	7906260344 7906010194 7906010197 7906260344 7906110235 7906110239	50-315 50-316 50-316 50-315 50-315	G 8 8 9 8		7904010218 7904070346 790429007 7904290022 7904290025 7904290226	50-320 50-289 50-320 50-320 50-320 50-320	P 8 8 8 8 9
•	7906190296 7906190243 7906120219 7906080266 7906080267	50-315 50-316 50-315 50-320 50-320	R R G		7706010227 7706070237 7706270141 7706270428 7706270413	50-320 50-289 50-320 50-320 50-320	ያ 0 ታ የ
	7904080266 7904080267 7904080266 7904080267	50-320 50-320 50-320 50-320	G G G		7906290014 7906220099 79062200510 7906290023	50-320 50-320 50-320 50-320	P P P
	7906150329 7906130287 7906150334 7906130287 7906150334	50-315 50-315 50-315 50-315 50-315	8 9 8 9		7904210202 7904210205 7904070150 7904190531 7904190535	50-320 50-320 50-320 50-320 50-320	P P B B
	7906190297 7906190295 7906190292 7906190241 7906210201	50-316 50-316 50-315 50-316 50-316	8 R R		7906220145 7906010212 7906010213 7906220072 7906040231	50-320 50-287 50-320 50-320 50-320	F P H P
JCPL - Jersey Central Power & Light Co.	7906220293 7906250291 7906040251 7906040253 7906040407	50-315 50-315 50-219 50-219 50-343	P		7906060264 7906040231 7906210192 7906210196	50-269 50-320 50-320 50-320	F P P
	7706150185 7706020076 7706270820 7706070374 7706070375	50-363 50-219 50-219 50-363 50-363	G G G		7906040306 7906040311 7906290194 7906120372 7906120373	50-297 50-297 50-320 50-289 50-289	8 U I F
•	7906260367 7906040174 7906050319 7906070259 7906070262	50-217 50-217 50-217 50-217 50-217	9 P P		7906120372 7906150324 7906260455 7906260458 7906270235	50-269 50-269 50-320 50-320 50-320	I G P P
	7706110171 7706110175 7706150189 7706210156 7706200371	50-219 50-219 50-219 50-219 50-219	8 9 9 8	MKHE — Massachusetts Municipal Hholesale Co.	7906270234 7906280077 7906290608 7906190351	50-320 50-320 50-289 50-443	P P I
	7906200396 7906210155 7906200209 7906200397	50-219 50-219 50-219 50-219	8 R P 8	MPL - Mississippi Power & Light Co.	7906140648 7906050127 7906290773 7906290468 7906230023	RECOD 50-416 50-416 50-416 50-416	0 0 8
	7906200400 7906200412 7906200419 7906280119 7906280122	50-219 50-219 50-219 50-219 50-219	8 8 8 8		7906230467 7906230467 7906120327 7906140365	30-416 30-416 30-416 50-416	9 8 8
#SOE - Kaneas Gas & Electric Co	7902120222 7906200346 7906030040 7906030070 7906130033 7906140172	50-492 50-492 50-492 50-492 50-482 50-482	G G G		7906140437 7906140365 7906140405 7906140407	50-416 50-416 50-416 40-416	8 8
LAPL - Louisiana Power & Light Co.	7906210300 7906110159 7906120145 7906140262 7906140265	50-482 50-482 50-382 50-382 50-382	K G G				
LIL - Long Island Lighting Co.	7906260404 7906040176 7906110421 7906290794 7906060285	50-382 50-322 50-322 50-514 50-322	G A G A	MPAG - Myap -			
MEED - Hetropolitan Edison Go.	7906060290 7906120218 7906010201 7906290808 7906040326	50-322 50-322 50-322 50-516 50-289	A A G B				
	7706040331 7706040241 7706040244 7706120380 7706270008	50-289 50-289 50-289 50-289 50-320	8 8 1 8				
	7706290010 7706150440 7706290011 7706210420	50-320 71-294 50-320 50-320	R G R				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
NEGEA - New England Gas & Electric Assoc NENE - Northeast Nuclear Energy Co (Northeast Ufilities)	7906190374 7906040310	50~443 I 50~245 8		7906110179 7906110173	50-367 R 50-437 A
	7906040314 7906040321	50-245 8 50-334 8		7906190439 7906260425 7906290108	50-367 R 50-367 R 50-367 R
	7906040323 7906150205 7906290784 7906140277	50-336 8 50-245 0 50-336 0 50-336 0	NMP — Niagara Hohawk Power Corp	7906020239 7906060131 7906040029	50-220 G 50-220 G 50-220 G
NENP - New England Power Co.	7904170293 7904210198 7904270241 7904250385	50-245 J 50-336 P 50-245 J 50-443 I		7906290686 7906290800 7906270198 7906010214	50-220 4 50-410 G 50-220 8
	7906250389 7906250385 7906250389 7906190010	50-443 I 50-443 I 50-449 I 50-568 I		7906050207 7906050211 7906110181 7906110184 7906130006	50-220 R 50-220 R 50-220 B 50-220 B 50-220 B
	7906120408 7906120297 7906080259 7906120279	50-568 A 50-568 A 50-568 A		7906110178 7906130005 7906150408 7906180487	50-220 8 50-220 8 50-220 0 50-220 6
	7906120402 7906120379 7906180525 7906190288	50-568 A 50-568 A 50-568 A 50-568 A		7906180492 7906220408 7906220417	50-220 8 50-220 8 50-220 8
NEUT - Northeast Utilities	7906180325 7906190288 7906040353 7906040234	50-568 A 50-568 A 50-245 S 50-245 B		7906220405 7906220412 7906220424 7906270166	50-220 9 50-220 8 50-220 8 50-410 8
	7906040307 7906040295 7906190323 7906250306	50-336 B 50-336 B 50-443 I 50-245 P	NPPD - Nebraska Public Power District	7906260400 7906290390 7906270171 7906040205	50-220 G 50-220 P 50-410 B 50-278 G
	7906040371 7906040365 7906250305 7906140528	50-245 Q 50-336 Q 50-245 P 50-336 Q		7906110053 7906290341 7906070373 7906110043	50-278 G 50-320 G 50-278 G 50-278 G 50-278 S
	7906250305 7906220043 7906200535 7906080042	50-245 P PR REGGD 50-245 Q		7906080251 7906080252 7906080255 7906080256	50-298 8 50-298 8 50-298 8
	7906140481 7906020210 7906080076 7906140222	50-245		7906080253 7906080254 7906080309 7906080311	50-278 8 50-278 8 50-278 8 50-278 8
	7906070412 7906120128 7906140524 7906290724	50-336		7906080280 7906080286 7906050270 7906050271	50-276 8 50-276 9 50-276 P 50-278 P
	7906050254 7906050314 7906120357 7906120362	50-245 P 50-336 P 50-245 B 50-245 B		7906060148 7906050272 7906120257 7906130294	50-298 P 50-298 P 50-298 P 50-298 R
	7906120395 7906120401 7906150208 7906120339	50-336 8 50-336 8 50-245 9 50-336 P		7906130297 7906060151 7906060155 7906060159	50-298 R 50-298 P 50-298 P 50-298 P
	7906140398 7906140401 74E0214097	50-245 8 50-245 8 50-336 R	NSP - Northern States Power Co	7906190392 7906260537 7906290281 7906060093	30-298 J 50-298 J 50-298 P 50-282 G
	7906150337 7906180527 7906120345 7906180522 7906180496	50-245 P 50-245 R 50-336 R 50-245 R 50-236 Q		7906040062 7906020157 7906270029	50-263 Q 50-263 Q 50-263 Q
	7906250278 7906180495 7906180499	50-245 B 50-336 B 50-336 B		7906020150 7906020151 7906040378 7906260476	50-263 0 50-263 0 50-282 0
	7906200374 7906280282 7906200374 7906290290	50-245 I 50-245 G 50-245 I 50-336 B		7906220001 7906140171 7906290675 7906290752 7906290675	50-484 0 50-282 0 50-282 0 50-282 0 50-282 0
	7906200374 7906280091 7906260480 7906290253	50-245 I 50-245 J 50-213 J 50-245 B		7906290752 7906290020 7906290046 7906040922	50-282 Q 50-484 Q 50-484 Q 50-282 B
	7906290269 7906290269 7906290242	50-336 6 50-336 8 50-245 8		7906030290 7906030292	50-282 P 50-282 P
NIPS - Northern Indiana Public Service Cq.	7906290277 7906060063	50-336 8 50-367 0		7906050324 7906140234 7906140367 7906140448	50-282 R 50-282 R 50-282 B 50-282 P
	7906230040 7906050306	50-367 Ø 50-367 Ø		7906140451	50-282 P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR'		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGORY
	7906040338 7906050290 7906050292 7906050316 7906050317 7906050324 7906140234	50-282 50-292 50-306 50-306 50-282 50-282	\$ P P B B B B B B B B B B B B B B B B B		7906130122 7906130227 7906120034 7906140508 7906180567 7906290743 7906010186	50-286
	7906140239 7906140369 7906140448 7906140451 7906120378 7906120340	50-282 50-282 50-282 50-282 50-263 50-263	R 8 P R P		7904040313 7904040315 7904290830 7904070244 7904070254	50-286 8 50-333 8 50-333 0 50-286 0
	7906120375 7906130312 7906140443 7906130339 7906120364	50-263 50-282 50-282 50-282 50-306 50-306	R J P S S		7906200369 7906080231 7906080235 7906120266	50-286 R 50-333 B 50-333 B 50-286 G
	7906120368 7906130312 7906140443 7906130339 7906130202	50-282 50-282 50-282 50-263	Ј Р Б		7904120365 7904130374 7904190417 7904150275 7906200463 7906190291	50-333 R 50-333 R 50-333 P 50-286 G
	7906190349 7906190349 7906190349 7906190349 7906140229	50-282 50-282 50-282 50-282 50-282	P P P R		7706170274 7706190364 7706150255 7706150273 7706150278 7706180393	50-286 F 50-333 H 50-333 S 50-333 S
	7906210237 7906220357 7906220356 7906220362 7906260471 7906270161	50-282 50-282 50-282 50-282 50-282 50-282	8 8 8 8 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9		7906180410 7906180563 7906190506 7906200368 7906200378	50-284 P 50-333 8 50-286 P 50-286 R 50-333 P
NYEQ - New York State Electric & Gas Corp	7906270165 7906150320	50-282 50-394	8 A		7906190264 7906190267 7906180474 7906180482	50-286 8 50-286 8 50-333 8
very	7706120247 7706120433 7706220342 7706260229	50-596 50-596 50-596 50-596	A F A		7906180574 7906180580 7906190271 7906190275	50-333 8 50-333 8 50-333 8 50-333 8
DEC - Dhio Edison Co	7906260233 7906260229 7906260233 7906110124	50-596 50-596 50-596 50-580	C C B		7906190410 7906190414 7906260450 7906260461 7906260450	50-333 8 50-333 8 50-320 9 50-286 9 50-320 9
OPPD - Omaha Public Power District	7906110128 7906110124 7906110128 7906040294 7906050355	50-580 50-580 50-580 50-285 50-285	8 8 8 8		7906250274 7906250277 7906260445 7906260143 7906260128	50-333 8 50-333 8 50-333 0 50-286 P 50-286 F
	7906050346 7906040290 7906050334 7906050338 7906060278	50-285 50-285 50-285 50-285	P 8 8 9		7906250268 7906250270 7906250275 7906250274	30-333 8 30-333 8 50-333 8
	7906050320 7906050321 7906060275 7906130011 7906120224	50-285 50-285 50-285 50-285 50-285	8 8 P P			
	7906120387 7906130316 7906120335 7906120336 7906150313	50-285 50-285 50-285 50-285	G 1 R R P	PECO - Philadelphia		
	7906190491 7906250288 7906220368 7906260168 7906260173	50-285 50-285 50-285 50-285 50-285	g g g F			
PASM - Power Authority State of New York	7906040225 7906040222 7906040227 7906040305 7906040276	50-333 50-333 50-333 50-333	8 8 8 8			
	7906040288 7906040232 7906040318 7906040349 7906010279	50-333 50-286 50-286 50-286 50-309	8 8 8			
	7906090095 7906070204 7906140326 7906040014	50-333 50-284 50-284 50-284	a a a			

Tribution   Trib	AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJEC.	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
TROUGHOUSE SE-STY 0  TROUGHOUS		7906020241 7906140247	50-277 50-277	e R		7906180143 7906200481	71-9109 50-514	C R
Production   St.   Production   St.   Production   St.   St.   Production   St.   St.   St.   Production   St.		7906130112 7906020206 7906270193 7906270064	50-277 50-352 50-277 50-277	@ @ & \$		7906080139 7906270005 7906200167	50-344 50-320 71-327	0 0 C
Total (1922)   Tota		7906040316 7906260341 7906070252	50-277 50-279 50-277	9 8		7906030349 7906080292 7906080294	50-344 50-344 50-344	۴ 8 8
Trickeleager   10-277   10		7906140235 7906140228 7906140235	50-277 50-277 50-277	R R R		7906080297 7906140425 7906140434 7906150302	50-344 50-344 50-344 50-344	J 8 8
Prodeing		7906080290 7906080287 7906080289	50-277 50-277 50-277	8 8		7706110132 7706110136 7706170473 7706220230	50-344 50-344 50-344 50-514	P P P
7004 (40450		7906110172 7906110174 7906150335	50-277 50-277 50-277	8 B R	PPC - Pennsylvania Power & Light Co	7906260466 7906260001 7906260456 7906210036	50-344 50-344 50-344 50-387	E K P
700,200,423		7906140459 7906140463 7906140466 7906200422	50-277 50-277 50-277 50-277	R R R		7906070184 7906040265 7906040193 7906040196	50-397 50-387 50-387 50-387	8 K
7705400422 50-277 6 705400402 50-277 8 705400402 50-277 8 705400402 50-277 8 705410040 50-277 8 705420030 50-277 8 705420030 50-277 8 705420030 50-277 8 705420030 50-277 8 705420030 50-277 8 705420030 50-277 8 705420040 50		7906140221 7906140455 7906140459 7906140469	50-277 50-277 50-277 50-277	R R R		7906040193 7906040196 7906040208	50-387 50-387 50-387	K K C
790.1903.29 50-277 R 790.1003.20 30-267 R 790.1003.		7906200422 7906200425 7906190331 7906140243	50-277 50-277 50-277 50-277	G G R R	PSC - Public Syrvice Co of Colorado	7906120400 7906180438 7906260380	50-387 50-387 50-387	A
7906260272 30-278 S 7706260273 30-277 B 7706260273 30-267 P 7706260273 30-277 B 7706260273 S 7706260273 30-277 B 7706260273 30-287 R 7706260273 30		7906140243 7906190329 7906190248 7906260283	50-277 50-277 50-293 50-277	R R R		7906010217 7906010223 7906120346 7906060206	50-267 50-267 50-267 50-267	R R P
SO-275 A		7906260294 7906260253	50-278 50-277 50-277 50-277	S 8 8		7906120196 7906120405 7906120409 7906070182	50-267 50-267 50-267 50-267	9 8 9 0
PRM REOPD PROJ PROJ PROJ PROJ PROJ PROJ PROJ PROJ			50-275 CONTRACT 50-344 PROJ	. A		7706130344 7706120342 7706120410 7706120414	50-267 50-267 50-267 50-267	0 P B
\$0-275   \$0   \$790629395   \$0-267   \$0   \$0   \$0   \$0   \$0   \$0   \$0   \$			PRM REPOD PROJ 50~320			7906180534 7906190501 7906220295 7906190336	50-267 50-267 50-267 50-267	P P
S0-133   S			50-275 50-133 50-275 50-133	R B R	•	7906190395 7906220340 7906220308 7906260443	50-267 50-267 50-267 50-267	P P
50-275 A P8EG - Public Service Electric % Gas Co. 7906040336 50-272 B 50-275 A of New Jersey /906040340 50-272 S 50-133 S 7906040275 50-272 S 50-275 A 7906040275 50-272 S 50-275 A 7906040277 50-272 S 50-314 R 50-344 0 790604077 50-272 S 50-344 0 790604077 50-272 S			50-133 50-275 50-275	8 8 A A		7906260437 7906290419 7906290426	50-267 50-267 50-267	93 P P
50-193 8					PSEO - Public Service Electric & Gas Co.	7906040336	50-272	B
50-514 R 50-344 0 7906040271 50-272 8 50-344 0 7906040079 50-272 Q 7906040170 50-272 S			50-275 50-133 50-133	8		/706040340 7906040268 7906040275	50-272 50-272 50-272	8 8 8
The second secon			50-314	R		7906040271 7906040079	50-272 50-272	8

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEQUI	RY	AUTHOR AFFILIATION	ACCERSION NUMBER	SUBJEC CATEGO	
	7906120081 7906020193 7906070389 7906270206	50-272 50-272 50-272 50-272	a a a		7903210421 7906140622 7906230136 7906120290	50-341 PR NUREO 50-341	o A
	7906060270 7906290774 7906060270	50-272 50-272 50-272	g P		7906200134 7906210348 7906060283 7906060271 7906120286	50-204 50-204 50-206 50-206 50-341	0 0 P P A
	7906030294 7906030283 7906040303 7906060261	50-272 50-272 50-272 50-354	8 8 8 8 A		7906040167 7906130236 7906130289 7906130291 7906220288	50-204 50-361 50-204 50-204 50-361	P B R R
	7904030289 7904030291 7904030301 7904030304 7904030339	50-272 50-272 50-272 50-272 50-272	8 8 8		7906140472 7906140468 7906150386 7906200347 7906220314	50-206 50-206 50-361 50-206 50-206	P A S B
	7906090340 7906070268 7906110226 7906110231 7906260417	50-272 50-272 50-272 50-272 50-272	8 5 8 B R		7905220325 7905220358 7905200345 7905220402 7905220404	50-206 50-206 50-206 50-206 50-206	8 P 8 6
	7906150150 7906150153 7906260418 7906180585 7906180593	50-272 50-272 50-272 50-272 50-272	RRR		7906250321 7906250324 7906250321 7906250324 7906220335	50-361 50-361 50-361 50-361 50-206	K K K
	7906190201 7906190216 7906220361 7906200394 7906200407 7906200414	50-272 50-272 50-272 50-272	P P G B S		7906220346 7906270239 7906270246 7906290404 7906290411	50-206 50-361 50-361 50-361 50-361	8 8 8 8
FSIN - Public Service Co of Indiana, Inc	7706200314 7706260349 7706260368 7706230119	50-272 50-272 50-272 50-272 50-272	9 8		7906270239 7906270246 7906290404 7906290411 7906250338	50-361 50-361 50-361 50-361 50-361	8 8 8 K
	7904280027 7904280030 7904280027 7904280030	50-546 50-546 50-546 50-546	K K K	SCEO - South Carolina Electric & Gas Co	7906200565 7906140175 7906190152 7906220071 7906220086	50-395 50-395 50-395 50-395 50-395	0 0 0 0
PSEEL - Public Service Go of New Hampshire	7906280025 7906130248 7906250381 7811090147	50-546 50-546 50-443 50-443	K B I		7906290580 7906080270 7906050296 7906050299 7906220300	50-395 50-395 50-395 50-395 50-395	01 K K S
	7906230382 7906010134 7906290782 7906290667 7906060233	50-443 50-443 50-443 50-443	1 0 0	8HUD - Bacramento Municipal Utility District	7906020092 7906020090 7906290134 7906020088 7906290132	50-312 50-312 50-312 50-320	G G G G
PSOK - Public Service Co of Oklahoma	7906020216 7906130209 7906080114 7906200590 7906200333	REGGD FRM 50-556 50-556	0 0		7906120320 7906120315 7906190335 7906010275 7906040287	50-312 50-312 50-312	PPPP
PSPL - Puget Sound Power & Light Co RGE - Rochester Oas & Electric Corp ) ;	7905310385 7906150261 7906050438 7906020061 7906080143	50-522 50-522 50-244 50-244	A B B		7906070144 7906060279 7906120268 7906120326 7906120326	50-312 50-312 50-312 50-312	J P P R
	7906020217 7906070261 7906270195 7906290195 7906270200	50-244 50-244 50-485 50-244	G G S S		7906120275 7906190441 7906190252 7906180559 7906180561	50-312 50-312 50-312 50-312 50-312	P R 8
	7906050359 7906050360 7906120406 7906130198 7906190368	50-244 50-244 50-244 50-244	4 4 4	SNEC — Barton Nuclear Experimental Corp TAML — Taunton Municipal Lighting Plant	7906190510 7906190516 7906220345 7906120297 7906060268	50-312 50-312 50-312 50-146 50-443	8 8 9 J
	7906190493 7906220272 7906210193 7906250253 7906250258	50-244 50-244 50-244 50-244	P	TOED - Taledo Edison Co	7906230127 7906230123 7906270178 7906070272 7906010122	50-346 50-346 50-346 50-346 50-346	0 8 8 0
SCE - Southern Celifornie Edison Co.	7906270160 7906270494 7906200351 7909210415 7906250330	50-244 50-244 50-206 50-361	P B G K		7906070417 7906190855 7906140631 7906010308 7906020036	PR 50-346 PR 50-346 50-346	

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBUECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7706020240 7706140249 7706060232 7706060291 7706250140	50-346 G 50-346 G 50-346 G 50-346 G 50-346 G		7906140387 7906140381 7906140387 7906220246 7906140411	50-390 8 50-390 8 50-390 8 50-353 A 50-518 8
	7706230118 7706230119 7706080283 7706230037 7706070300	50-295		7706080277 7706040204 7706270715 7706040204 7706140404	50-370 8 50-327 A 50-259 Q 50-327 A 50-370 S
	7906060280 7906040237 7906040239 7906060255 7906050242	50-346 P 50-346 8 50-346 B 50-346 P 50-346 S		7706140410 7706040204 7706140404 7706140410 7706010209	50-390 8 50-327 A 50-390 8 50-390 8 50-260 9
	7906050243 7906060272 7906070208 7906070202 7906070269	50-346 8 50-346 P 50-346 8 50-346 8 50-346 8		7906010210 7906140452 7906140406 7906190431 7906190442	50-260 8 50-390 8 50-553 9 50-518 8 50-518 8
	7706080303 7706140394 7706140408 7706180546 7706180547	50-346 F 50-346 R 50-346 R 50-346 8 50-346 8		7706060276 7706140420 7706140423 7706060276 7706140420	50-438 A 50-438 B 50-438 B 50-438 A 50-438 B
	7906180549 7906180551 7906220383 7906220389 7906210218	50-346 8 50-346 8 50-346 8 50-346 8 50-346 P		7706140423 7706190431 7706190442 7706190431 7706190442	50-438 8 50-518 8 50-518 8 50-518 8
	7906220298 7906220397 7906220403 7906260431 7906250342	30-346 P 50-346 B 30-346 B 50-346 P 50-346 P		7706170431 7706170442 7706170431 7706170442 7706170431	50-518 8 50-518 8 50-518 8 50-518 8
	7706250346 7706250257 7706250258 7706270175 7706230122	50-346 P 50-346 S 50-346 S 50-346 S 50-346 G		7706170442 7706170431 7706170442 7706170431 7706170442	50-518 8 50-518 8 50-518 8 50-518 8 50-518 8
TU - Texas Utilities Co. TUGC - Texas Utilities Generating Co	7906270225 7906190209 7906200567 7906200604 7906290603	50-346 P 50-445 8 50-445 8 50-445 A 50-445 Q		7906010278 7906010196 7906010198 7906010282 7906140378	50-259 J 50-370 K 50-370 K 50-370 A 50-390 S
	7906120235 7906120239 7906120235 7906120239 7906120208	50-445 K 50-445 K 50-445 K 50-445 K 50-445 B		7706010176 7706010178 7706010282 7706140378 7706140322	50-390 K 50-390 K 50-390 A 50-390 B 50-260 B
TUS - Texas Utilities Services, Inc TVA - Tennessee Valley Authority	7706220200 7706220324 7706130003 7706120243 7706220374	50-445 A 50-445 B 50-445 A 50-445 K 50-259 R		7704040273 7704150283 7704080275 7704080281 7704080275	50-327 A 50-259 R 50-327 S 50-327 S 50-327 S
	7906050422 7906040375 7906210089 7906010135 7906110085	70-2443 C 50-327 G 50-390 G 50-553 G Waste Mot		7904080281 7904080307 7904080284 7904120398 7904130330	50-327 8 50-390 6 50-390 9 50-296 P 50-390 8
	7906210046 7906110095 7906070378 7906290503 7906070378	50-370 @ Waste Mot 50-230 @ 50-320 @ 50-237 g		7706130337 7706130330 7706130337 7706120377 7706120381	50-390 6 50-390 6 50-390 6 50-296 8 50-296 6
	7906290503 7906070378 7906290503 7906290186 7906190533	50-320 q 50-259 q 50-320 q 50-390 q 50-391 q		7706070191 7706120329 7706120330 7706120384 7706120389	50-390 K 50-260 8 50-260 8 50-260 8 50-260 8
	7906220185 7906020135 7906140442 7906140450 7906210199	50-438 G 50-553 G 50-327 B 50-259 G 50-259 P		7906080261 7906130286 7906130288 7906130221 7906130279	50-327 F 50-260 9 50-260 8 50-439 6 50-259 R
	7906140450 7906210199 7906140450 7906210199 7906210098	50-239 G 50-239 P 30-239 G 30-239 P 50-327 G		7906200342 7906200438 7906200342 7906200438 7906190301	50-327 8 50-327 8 50-327 8 50-327 8 50-259 P
	7906140364 7906210098 7906140364 7906210098 7906140381	50-927 B 50-927 Q 50-927 S 50-927 Q 50-390 S	•	7906200433 7906190381 7906200382 7906200383 7906200382	50-370 8 50-553 8 50-327 8 50-327 8 50-327 8

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	<u>′</u> _	AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	
	7706200383 7706220271 7706220384 7706220387 7706220271	50-390 50-390 50-390 50-390	\$ 6 6 6 8		7706050251 7706050236 7706050280 7706050236 7706050280	50-339 50-404 50-338 50-404	A PAPA
	7906220384 7906220387 7906250279 7906250281 7906250279 7906250279	50-370 50-370 50-438 50-438 50-438 50-439	***************************************		7906050336 7906050323 7906050309 7906050323 7906050363 7906060124	50-238 50-280 50-280 50-280 50-280	6 8 8
	7706220349 7706220339 7706230249 7706230272	50-259 50-327 50-327 50-327	8 K K		7906070306 7906050318 7906050323 7906060124 7906070306	50-280 50-281 50-280 50-280 50-280	7 P G J
	7906220339 7906250269 7906250272 7906210195	50-327 50-327 50-327 50-259	K 8 8		7906140415 7906050255 7906050260 7906050273	50-281 50-339 50-339 50-338	8 8 8
	7906220245 7906260224 7906220245 7906260224 7906270224	50-553 50-553 50-553 50-553 50-327	A A A B		7906050298 7906050298 7906050303 7906050323 7906050312	50-338 50-338 50-338 50-280 50-280	8 8888
	7906270226 7906270224 7906270226 7906270224 7906270226	50-327 50-327 50-327 50-327	8 8 8		7906070242 7906070245 7906070247 7906180520 7906110160	50-338 50-338 50-338 50-280 50-338	5 B R 6
	7906270218 7906270220 7906270224 7906270226 7906270218	50-390 50-390 50-327 50-327 50-390	8 8		7906110162 7906180493 7906070295 7906070298 7906070295	50-338 50-338 50-280 50-280 50-280	R P P
	7906270220 7906270224 7906270226 7906280094 7906260463	50-370 50-327 50-327 50-327 50-327	8 8 9 A		7906070298 7906110156 7906190399 7906110198 7906110200	50-260 50-338 50-338 50-338	P 9 9 9 9 9 9 9 9
	7906260094 7906260463 7906260094 7906260113 7906260114	50-327 50-327 50-327 50-439 50-439	G A G B B		7906110202 7906110204 7906110207 7906120178 7906120262	50-338 50-338 50-338 50-339 50-339	8 9 8 8 8
	7906290294 7906290316 7906290294 7906290316 7906290392	50-327 50-327 50-327 50-327 50-390	8 8 8 8		7706110211 7706110174 7706110197 7706130352 7706210214	50-338 50-280 50-280 50-280 50-280	8 P P
UNE - Union Electric Co	7906290142 7906290152 7906290159 7906290167 7906010128	50-240 50-240 50-240 50-240 50-483	8 8 8 9		7906110194 7906110197 7906130352 7906210214 7906150134	50-280 50-280 50-280 50-280 50-338	PPP
UNIT - United filuminating	7906150194 7906190228 7906250392 7906190367 7906250394	50-493 50-483 50-443 50-443 50-443	A Q I I I		7906150160 7906180544 7906180517 7906180491 7906180343	50-280 50-338 50-338 50-338	# B R R 8
VEPC - Virginia Electric & Power Co.	7906190367 7906250394 7906250347 7906250130 7906200143	50-443 50-443 50-280 50-281 50-280	1 1 P Q Q		7906180536 7906180536 7906180536 7906180536 7906180536	50-260 50-260 50-260 50-260 50-260	G G G
	7906180312 7906160070 7906140475 7906050367 7906190194	50-338 50-338 50-338 50-280 50-280	G G S P G		7906180536 7906180536 7906180536 7906180536 7906180538	50-280 50-280 50-280 50-280 50-260	9 999
	7706220220 7706140487 7706250240 7706210216 7706140421	50-338 50-337 50-337 50-280 50-337	0 8 P 6		7904190338 7904200102 7904200398 7904200405 7904210210	50-337 50-280 50-280 50-280 50-280	A P 8 8 P 0
	7906140432 7906290552 7906010237 7906010268 7906010237	50-339 50-280 50-338 50-338 50-338	8 9 P P		7906200398 7906200405 7906210210 7906200386 7906200389	50-280 50-280 50-280 50-338 50-338	8 9 9 8 8
	7906010268 7906030336 7906130224 7906030336	50-339 50-338 50-280 50-338	ե ե ե		7906210233 7906220268 7906210235	50-339 50-280 50-338	e P P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	
	7906250311	50-280			7906260411	50-502	c
	7906250261 7906250287 7906270222	50-338 50-339 50-339	բ 8		7906260414 7906260409 7906260411 7906260414	50-502 50-502 50-502 50-502	0000
	7906250280 7906270216 7906270121 7906290327	50-339 50-339 50-280 50-280	A 8 0 P		7906220181 7906280117 7906290257 7906120151	50-266 50-502 50-266 50-502	P A P B
	7904270121 7904290327 7904290194	50-280 50-280 50-338	0 P S	NMEC - Western Hassachusetts Electric Co HPPS - Washington Public Power Supply	7906200375 7906130220	50-245 50-320	1
VTEG - Varmont Electric Cooperative, Inc.	7906290205 7906290215 7906290237 7906190346	50-338 50-338 50-338 50-443	8 8 8	Bys tem	7906150085 7906080301 7906080305 7906080312	50-397 50-397 50-397 50-397	9 8 8
VTEP - Vermont Electric Power Co , Inc VYNP - Vermont Yankes Nuclear Power Corp.	7906190379 7906040258 7906040255	50-443 50-271 50-271	1 8 8		7906080313 7906120356 7906120469	50-397 50-397 50-397	8 F
	7906050281 7906140328 7906130114 7906140535	50-271 50-271 50-271 50-271	Q Q Q		7906270125 7906270130 7906270125	50-508 50-508	Ā
	7906290806	50-271	à		7906270130	50-508	A
	7906050258 7906260564 7906140250 7906150243	50-271 50-271 50-271 50-271	F Q J P	HPSC - Hisconsin Public Bervice Corp	7906120299 7906230116 7906220487	50-305 50-305 50-305	9
WIEP - Wisconsin Electric Power Co	7904190305 7904190311 7904290094 7904050122	50-271 50-271 50-271 50-266	R R G		7906040205 7906040208 7904040220 7904080314 7904200281	50-305 50-305 50-305 50-305 50-305	8 8
	7906200548 7906020133 7906040027 7906020133	PR 50-266 50-266 50-266	0 G		7706180503 7706170401 7706280075 7706280080	50-305 50-305 50-305 50-305	P J 9 8
	7906040027 7906060257 7906060260	50-266 50-266 50-266	8	YAE - Yankes Atomic Electric Co	7906280086 7906140146 7906120383	50-29 50-568	g A
,	7904040257 7904040260 7904040250 7904040251	50-266 50-266 50-266	8 8 8		7906120408 7906120383 7906120408 7906180034	50-568 50-568 50-568 REOOD	A
	7906080272 7906150216 7906080272 7906150216	50-502 50-502 50-502 50-502	A C A G		7905290058 7906200502 7906120287 7906130106	50-27 REGOD 50-568 50-29	P A G
	7906080272 7906150216 7906080272 7906150216	50-502 50-502 50-502 50-502	Å c		7906290737 7906050276 7906080271 7906120258	50-29 50-29 50-29	G P P
•	7906080272 7906150216 7906080272	50-502 50-502 50-502	A C A		7906120316 7906130370 7906190313 7906190314	50-29 50-29 50-29 50-29	P R R
	7906150216 7906080272 7906150216	50~502 50~502 50~502	C A C		7906190227 7906220193	50-29 50-29	þ
	7906070193 7906120147	50-266 50-502	B		7906250267 7906290408	50-29 50-29	Į P
	7906120193 7906120200 7906130265 7906190321 7906120421	50-502 50-502 50-502 50-266 50-502	B B A R	Argonne National Laboratory	7906050098 7906050200 7906270007 7906130205 7906130199	MUREO NUREO 50-572 50-320 50-320	Á D O
	7906190319 7906200166 7906190315	50-266 50-266 50-266	R F	Argonne National Laboratory - Argonne	7906180168	71-6717	c
	7906290579 7906260409	50-202 50-502	B C	West Battelle Memorial Institute, Columbus Laboratories	7906210339	50-331	P
	7906260411 7906260414 7906260409	50-502 50-502 50-502	C C C		7906230170 7906180779 7906210325	70-B NUREO NUREO	С
	7906260411 7906260414	50-502 50-502	c c	Wattelle Memorial Institute, Pacific Northwest Laboratory	7904020105	NUREO NUREO	
	7906260409 7906260411 7906260414 7906260409	50-502 50-502 50-502 50-502	с с с		7906020097 7906020148 7906270243 7906270093	NUREO ACRB ACRB	
	7906260411 7906260414 7906260409 7906260411 7906260414	50-502 50-502 50-502 50-502 50-502	G C C C		7906180717 7906180804 7906290481 7906210020 7906200608	NURED NURED NURED REB REB	
	7906260409	50-502	Č.		7906260613	RES	

AUTHOR AFFILIATION	ACCESSION NUMBER			AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Brasshaven National Laboratory	7906260023 7906290685 7906240023 7906290685	50-277 50-277 50-277 50-277	F P F	Uak Ridge National Laboratory	7906050035 7906040441 7906160230	71~225 RE8 RE8	С
	7906260022 7906210015 7906040413 7906230169 7906230173	50-409 RES RES RES RES	F		7906050180 7906220215 7906180218 7906190049 7906050134	RES RES RES RES NUREO	
	7906250043 7906260042 7906010191 7906260037 7906260013	RES RES TOPREP RES RES			7904050277 7904230172 7904220100 7904210318 7904240594	NUREG RES 71-4058 NUREG NUREG	С
and the second	7906260017 7906220328 7906280136	RE8 50-317 50-263	F F		7906290188 7906290487 7906290494 7906290551 7906290673	NUREO NUREO NUREO NUREO NUREO	
invironmental Policy Institute Franklin Institute Manford Engineering Development Laboratory	7906140655 7906140613 7906260623 7906180742	REGOD REGOD 50-338 NUREG	P		7906210139 7906210011 7906210031 7906220183	50~320 RES RES	P
Idako Mational Engineering Laboratory	7906010242 7906150207 7906150211 7906290342 7906020115	PROJ PROJ PROJ RES RES		Sandia Laboratories	7704010344 7704010351 7704210365 7704280020	RES RES RES NUREO NUREO	
	7906280066 7906020110 7906020114 7906260031	NUREG REB REB REB			7904180689 7904260574 7904230111 7904290792	NUREO NUREO NUREO NUREO	
Finetic Research, Inc	7906290505 7906010270	FOIA			7904180774 7904260605 7906260510	NUREO NUREO 50-320	P
Exalla Atomic Power Laboratory Las Alsacs Scientific Laboratory Lawrence Livermore Laboratory	7906210139 7906080107 7906250487 7906260620 7906260616	50-320 NUREQ 50-201 REB REB	P	Bavannah River Ecology Laboratory	7906210037 7906260608 7906180749 7906180762 7906180770	REVIEW O NUREO NUREO NUREO NUREO	RP
Mayr Dept of, Naval Research Laboratory	7906140127 7906200470	RES FOIA		SRI International Southwest Research and Information Center	7906050141 7906110079	NUREO WASTE MO	τ

1				
1				
1				

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

11

AUTHUR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
Cresistion	7906040403 7906020041 7906060102	BECY COMMISSION FOIA		7906070084 7906070070	COMM (88 TON
	7906060105 7906060109	FOIA 50-334 P		7906070074	COMMISSION
	7708080107	50-334 P		7906110319	COMMISSION
	7906060112	FOIA		7906110323	CONHIBSION
	7905290465 <u>7</u> 906060122	COMMISSION FOIA		7906110332 7906110335	COMMISSION
	7904040065	COMMISSION		7906110336	COMMISSION
	7906060127	50-334 P		7906110339	COMMISSION
	7906040134	FOIA		7904110341	COMMISSION
	7906060145	FOIA		7906070082 7906140101	COMMISSION
	7904070086	COMMISSION		7700140101	10CFR
	7906060173 7906260488	50-307 H 50-320 P		7906210079	10CFR
	7700200100	50-320 P		7906110114	50-320 T
	7906260523	50-346 P		7906230042	50-572 G
	7906260488	50-320 P		7906110300 7906110205	COMMISSION 50-269 T
	7904240523	50-346 P		7700110202	30-207
	790607008 <del>8</del> 7906070092	COMMISSION		7906210197	50-326 U
	7708070072	COMMITTER		7906110367	50-280 U
	7906060176	50-309 H		7906110378	50-280 U
	7906070093	COMMISSION		7706110380	50-280 U
	7906060248 7906060179	90-320 H		7906110302	50-280 U
	7906070064	50-307 H COMMISSION		7906110305	50-280 U
	, , , , , , , , , , , , , , , , , , , ,	doi il i a da a gis		7906110397	50-280 U
	7906070096	COMMIBBION		7906110390	50-280 U
	7906070097	COMMIBBION		7906110394 7906110397	50-280 U 50-280 U
	7906130423 7906070102	50-320 P COMMISSION		/10011037/	Ju-may u
	7706060252	50-309 H		7906110400	50-280 U
		50 507 (1		7906230196	10CFR
	7906150231	50-320 U		7906110367 7906110378	50-280 U 50-280 U
	7906060137 7906060163	50-320 H 50-320 H		7906110378	50~280 U 50~280 U
	7904040147	50-320 И 50-320 И	1		
	7906070106	COMMISSION		7906110392 7906110395	50-280 U 50-280 U
	7904070047	COMMISSION		7906110387	50-280 U
	7906010160	50-327 I		7906110370	50-280 U
	7906070293	COMMIBBION		7706110374	50-280 U
	7905300552 7906260474	COMMISSION 50-320 P		7906110397	50-280 U
	7708E60474	30-320 P		7906110400	50-280 U
	7706010050	NUREO		7906110367	50-280 U
	7906020143	NUREO		7906110378 7906110380	50-280 U 50-280 U
	7906180384	10CFR		. 100114100	23 KHO 0
	7906190044 7906020176	10CFR 10CFR		7906110382	50-200 U
	7700040170	A VGF IK		7906110385	50-280 U
	7906010219	NUREO		7906110387 7906110390	50-260 U 50-260 U
	7906040017	10CFR		7906110394	20-280 U
	7906220129 7906220451	50-320 H XPORTLIC			
	7906070098	10CFR		7906110397	50-280 U
				7906110400 7906110380	50-280 U 50-280 U
	7906070294	COMMISSION		7906110367	50-280 U
	7906180369 7906140107	10CFR 10CFR		7906110378	50-280 Ü
	7906140107	LOCFR		200///000-	80.000
	7906130077	PR		7904110382 7904110385	50-280 U 50-280 U
		1		7906110387	20-580 C
	7906200303	10CFR		7906110370	50-280 U
	7904070289 7904020225	COMMISSION 10CFR		7906110394	50-280 U
	7906070107	COMMISSION			
	7906180391	10CFR		7404110397	50-200 U
	750/100760	*******		7706110400	50-280 U
	7906180708 7906180724	10CFR 10CFR		7906110367	50-280 U 50-280 U
	7906070078	COMMISSION		7906110378 7906110380	50-280 U 50-280 U
		,			

AUTHOR AFFILIATION	ACCESS I DN NUMBER	BUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEO	
	7906110382 7906110385 7906110387 7906110390 7906110394	50-280 50-280 50-280	บ บ บ บ บ		7906260386 7906260389 7906260366 7906260371 7906260371	LOCFR LOCFR LOCFR LOCFR LOCFR	
	7906110397 7906110400 7906280257 7906280264 7906260343	COMM18910 COMM18910			7906260393 7906260350 7906260405 7906260345 7906260345	10CFR 10CFR 10CFR 10CFR 10CFR	
	7906060187 7906270163 7906280244 7906280251 7906220147	COMMISSIO COMMISSIO COMMISSIO	М		7906220199 7906070255 7906040444 7906260303 7906260316	50-320 50-400 50-466 10GFR 10GFR	8
	7906270107 7906270116 7906270123 7906270129 7906270133	COMMISSIO COMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISSIO COMMISS	14 14 14		7904240399 7904240307 7904240323 7904080081 7904240313	10CFR 50-309 50-400 PR 10CFR	P P
ffice of Congressional Affairs	7906270150 7906270144 7906060196 7906060194 7906070003	50-320			7906260376 7906040224 7906050193 7906080019 7906070292	10CFR 50-267 50-312 50-320 10CFR	0 0 P
	7906060199 7906260593 7906070308 7906280062 7906260465	50-275 50-320	ឋ អ ប ប		7904070299 7904240292 7904240292 7904240333 7904240299	10CFR 50-249 10CFR 10CFR 50-219	P
ffice of the General Counsel	7906260470 7906060198 7906280237 7906250482 7906080054	50-320 50-358 SECY	0 U 0		7906220096 7906260223 7906260274 7906260438 7906260246	50-320 10CFR 10CFR 10CFR 10CFR	٥
	7906230103 7906070016 7906070012 7906070027 7906060184	50-320	P T		7906260261 7906260266 7906180799 7906260279 7906040434	100FR 100FR 30-320 100FR 50-280	P
	7906070057 7906180116 7906220221 7906140465 7906200399	8ECY 50-320 NRC	P P		7906260219 7906260254 7906020060 7906260056 7906070145	10CFR 10CFR 50-302 50-346	0
ffice of Inspector & Auditor	7906270012 7906220302 7906220277 7906220349 7906210014	50-440 50-500	Н Н Н Т		7706270023 7706120030 7706220129 7706070165 7706270093	50-302 50-313 50-313 50-320 50-320	P 0 P 0
ffice of Public Affairs	7906220364 7906220067 7906220229 7906210281 7906220236	50-320 50-320 50-320	М Р Р Р		7906270023 7906270093 7906140184 7906260215 7906210117	50-302 50-320 50-389 10CFR 50-444	P 0 0
ffice of Policy Evaluations	7906220276 7906200050 7906200035 7906020234 7906120110	50-320	P 0 0		7906260210 7906060142 7906260189 7906260184 7906260206	50-313 50-320 10CFR 10CFR 10CFR	P 0
ffice of the Secretary of the Commission	7906260082 7906210256 7906010127 7906260452 7906260449		u o		7906210233 7906260169 7906260178 7906260174 7906260172	50-329 10CFR 10CFR 10CFR 10CFR	q
	7906260427 7906260430 7906260434 7906290176 7906260424	10CFR 10CFR 10CFR 50-320 10CFR	P		7906260154 7906260127 7906260162 7906260138 7906260138	10CFR 50-320 10CFR 50-219 50-269	P P
	7906220439 7906260422 7906260416 7906260420 7906260413	10CFR 10CFR 10CFR	O P	Dockating & Services Branci	7906260147 7906270186 7906270191 7906030079 7906270017	50-334 27-39 27-39 50-596 50-320	P C C O P
	7906250066 7906250085 7906040415 7906210279 7906210272	50-320 50-280 50-320	0 0 0 P P	Public Document Branch Atomic Energy Commission (Pre	7906060117 1975) 7906290318 7906060008 7906130184 7906130189	FOIA 50-320 FOIA SECY SECY	٨
	7906260410 7906040363 7906040369 7906260396 7906120093	10CFR XPORTLIC XPORTLIC 10CFR ORG			7906290309 7906070075 7906070080 7906070123 7906070130	50-920 FDIA FOIA FOIA FDIA	٨

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	ЖY	AUTHOR AFFILIATION	ACCESSION NUMBER	BU9JECT CATEGOR	
	7906070135 7906070152 7906070163 7906070158	FOIA FOIA FOIA FOIA			7906010276 7906190007 7906130430	50-443 PRDJ 50-478	0
stomic Energy Commission, Directorate of Licensing (Pre-1775) Alcels Energy Commission, Deputy Director for Technical Review (Pre-1975)	7906060089 7906060087	FOIA			7906200562 7906060219 7906210095 7906220180 7906210095	\$0-338 PROJ \$0-320 \$0-437	0 000
NR: Three Hitz Island Task Force	7906290331	50-320	P		7906210367 7906270081	50-320 50-336 50-295	0 0
ACRS - Advisory Committee on Reactor Sifeguards	7906260578	ACRE			7904290031 7904290038 7904290090	50-338 50-338 50-338	Ť
	7906290173 7906290175 7906280023 7906040220 7904230125	ACRE ACRE ACRE ACRE 50-592	A	Atomic Safety and Licensing Board Panel	7903140067 7903140039 7903140116 7906040147 7906050420	50-400 50-400 50-400 50-549 50-272	TTGGT
	7906290759 7906260569 7906130285 7906250058	ACRB ACRB 50-320 50-320	0		7906110430 7906040385 7906040389	SECY 50-554 50-554	
	7906250127 7906250474 7906180646 7906210276 7906220161	50-320 AGR8 50-320 50-320 50-320	0 0 P T		7906040396 7906040451 7906040445 7906040412 7906050345	50-344 50-488 50-466 50-556 50-272	00000
	7906220209 7906130262 7906130270 7906130274	50-320 50-320 50-320 50-320	H 0 0		7906070346 7906010290 7906040454 7906040145 7906040454	50-237 50-549 50-445 50-295 50-445	OGEOF
	7906180600 7906270242 7906130215 7906130254	50-320 50-320 ACRB 50-320 50-320	0 0 0		7904200231 7904200592 7904050105 7904040424 7904070248	50-498 50-596 50-466 50-329 50-466	00000
	7906120107 7906180592 7906180617 7906180622 7906180583	50-320 50-320 50-320 50-320 50-287	0 0 0 0		7906040024 7906130107 7906210405 7906040384 7906210405	50-556 70-2623 50-445 50-133 50-445	GCEOE
	7906260103 7906150442 7906130259 7906180006 7906180649	50-320 ACRB 50-320 50-320 50-320	0 0 0		7906050175 7906010142 7906070399 7906040041 7906040057	50-502 50-400 50-445 50-471 50-572	00000
	7906180003 7906180266 7906220178 7906290811 7906220105	50-320 50-320 ACR8 50-320	0 P		7904010257 7904040155 7904070109 7904040159 7904010284	50-358 50-358 50-466 70-2623 50-272	00000
	7906220322 7906220329 7906220165 7906220174 7906230056	50-320 50-320 50-320 ACRB	0 0 0		7904070312 7904040214 7904020052 7904070313 7904220479		K O M
	7906050070 7906070136 7906200029 7906130197 7906180702	50-320 50-320 50-320 50-320 50-320	0 0 0 0		7906020052 7906070315 7906020141 7906190006 7906020096	80-237 80-445 PROJ 80-272 50-445	O M
	7906060189 7906120076 7906120037 7906150224 7906260542	50-320 50-320 50-320 ACRE	T U T	•	7906180803 7906060217 7906130429 7906130418 7906060193	50-445	0 0 H T
	7906150214 7906150234	20-320	T T		7906070011 7906130418 7906070011	30-445 30-445 30-445	T H T
	7906290663 7906290655	ACRE			7906130418 7906190022		M Q
Afcaic Safety and Licensing Appeal Panel	7906270647 7906220266 7906220270 7906220320 7906050005	50-440 50-440 50-440 50-387	H H O	·	7906290069 7906060211 7906290077 7906220038 7906140117	30-596 70 <b>-262</b> 3	T T C T
	7906040040 7906050394 7906040026 7906040430	50-498 50-329 50-389 50-466	0		7906220452 7906060195 7906220465 7906250166 7906180726	50-261 50-471 50-237 50-358 50-471	G T Q U T
	7906040010 7906190132 7906070119 7906230181	PROJ 50-498 50-466 50-320	0		7906250171 7906220109 7906180736 7906180728	50-556 50-471 50-445 30-471	Q T T

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
	7906180736 7906260214 7906250434 7906260067	50-445 T 50-275 G 50-471 Q 50-275 Q		7906070349 7906180581 7906150130 7906130072	CONTRACT CONTRACT CONTRACT CONTRACT	
	7906270277 7906260067 7906270250 7906290622 7906270185	50-305 0 50-275 0 50-358 0 70-1308 C 50-387 0		7906150165 7906150169 7906180738 7906180744 7906180751	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
	7906280104 7906280260 7906260554 7906260548	50-471 Q 50-471 Q 50-275 T 50-471 T		7906160027 7906180042 7906270092 7906130086 7906130091	CONTRACT CONTRACT CONTRACT CONTRACT	
	7906260558 7906290560 7906290047 7906290082	50-295 T 50-295 T 50-295 T	Purchasing Section	7906130078 7906230337 7906130084 7906180282	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
Office of the Executive Director for Operations	7812050284 7904020240 7903230294 7906060130	50-437 A Waste Mgt Org Foia	Bassard Carbusta Bassal	7906250335 7906260123 7906260135 7906270100	CONTRACT CONTRACT CONTRACT CONTRACT	
	7906220434 7906270010 7906210207 7906210124	50-320 P 50-320 P 50-320 P 50-320 P	Research Contracts Branch  Technical Assistance Contracts Branch	7906050001 7906150175 7906050002 7906150171	CONTRACT CONTRACT CONTRACT	
	7906010281 7906210198 7906210194 7906250071	50-596 D 50-320 P 50-320 P 50-320 D	Technical Residence Currences Branch	7906160032 7906160038 7906150125 7906150152 7906150155	CONTRACT CONTRACT CONTRACT CONTRACT CONTRACT	
	7906210191 7906070234 7906210114 7906210112 7906220173	50-320 P 50-320 P 50-320 P 50-320 P	Technical Information & Document	7906150123 7906190176 7906270086 7906210265	CONTRACT CONTRACT CONTRACT	,
	7906020166 7906220212 7906220221 7906020182	50-482 U 50-320 P 50-320 P 50-321 Q	_ontrol  License Fee Management Branch	7906220088 7905040336 7906290167 7904270044	50-320 P 50-320 P NUREO 50-320 P	3
	7906220217 7906080005 7906050008 7906220166	50-320 P 50-10 U COMMIBSION 50-320 P		7906070044 7906210302 7906020078 7906040144	70-27 C 70-1510 C 50-3 F 50-286 P	
	7906260109 7906260541 7906200203 7906260302 7906260302	50-437 U 50-269 U COMMISSION PR 50-302 U		7906110040 7906050449 7906050442 7906040146 7906230061 7906230072	50-267 P 70-143 C 70-364 C 50-312 P 71-4986 C 50-29 P	
	7906220136 7906290245 7906290271 7906290228 7906260086	F01A 50-367 U 50-498 U 50-275 U 50-320 P		7906180796 7906260552 7906220197 7906290789 7906290827	50-250 P 40-8714 C 70-135 C 40-8027 C 50-412 A	
Office of Administration	7906210133 7906180753 7906080090 7906130372	50-320 P 50-259 P 50-259 P 50-320 P CONTRACT	Division of Organization and Personnel Division of Rules and Records	7906270275 7906200008 7906040199 7906060004 7906260503	50-271 P 50-320 H 50-266 H FOIA FOIA	
				7906010246 7906070203 7906010269 7906070066 7906070229	FOIA FOIA FOIA FOIA	
				7906010121 7906010255 7906010263 7906010273 7906070216	FOIA FOIA FOIA 50-307 P FOIA	
				7906010273 7906010107 7906010273 7906060069 7906010273	50-280 F 50-320 H 50-309 P 50-334 P 50-309 P	ı
				7906070232 7906010096 7906030078 7906010277 7906260555	FOIA FOIA FOIA 50-348 8 FOIA	
			Division of Security	7906290017 7906220263 7906220285 7906220336 7906130500	FOIA FOIA 50-440 H 50-320 P	ı
			Division of Accounting	7906220203	50-320 P	

				•		
AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	
Pfice of International Programs	7906290819 7906070101 7906250077 7906020017	50-574 A SECY XPORTLIC SECY		7906150122 7906150117 7906180801	XPORTLIC XPORTLIC XPORTLIC	
	7906180737 7906180802 7906020101	SECY SECY SECY		7906190079 7906290779 7906190082 7906190083	XPORTLIC SECY XPORTLIC XPORTLIC	
	7906180754 7906180771 7906060071 7906200002	BECY BECY BECY		7906190188 7906190184 7906190186 7906250042	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7906010146 7905230723 7906040409 7906250110	SECY XPORTLIC XPORTLIC 50-320 P		7905250045 7905250048 7905250050 7905250052	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7906180615 7906060076 7906060078 7906180050	SECY SECY SECY SECY		7906250055 7906250060 7906250064	XPORTLIC XPORTLIC XPORTLIC	
	7906250034 7906060067 7906230086 7906070367	50-574 A BECY BECY XPORTLIC		7906250068 7906250073 7906250076 7906250080	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7906290496 7906230091 7906290331	BECA BECA BECA		7906250084 7906250086 7906250089 7906250093	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7906290571 7906290714 7906290604 7906140350	SECY SECY SECY XPORTLIC		7906250096 7906250098 7906250102 7906250104	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
Assistant Director for Export/Import &	7906290769 7906180619	XPORTLIC BECY		7906250117 7906250120	XPORTLIC XPORTLIC	
International Safeguarda	7906180624 7906250249 7906290612	SECY SECY		7904250124 7906250131 7906250134 7906250139	XPORTLIC XPORTLIC XPORTLIC XPORTLIC	
	7904250238 7904020104 7904290838	SECY 50-574 A		7906250144 7906250343	XFORTLIC XPORTLIC	
	7906020027 7906120103 7906210094	SECY XPORTLIC XPORTLIC		7906180652 7906210082 7906270021 7906290385	SECY XPORTLIC XPORTLIC XPORTLIC	
	7906040437 7906010172 7906050253 7906050264	XPORTLIC XPORTLIC XPORTLIC XPORTLIC		7906290526 7906050266 7906160028	XPORTLIC XPORTLIC XPORTLIC	
	7906050267 7906050396 7906050402 7906050404 7906160012	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Office of the Executive Legal Director	7906290368 7905240402 7905250062 7905250071 7905250075	50-320 LOCFR LOCFR LOCFR LOCFR	J
	7904050257 7904050241 7904050408 7904140011 7904140015	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		7905250083 7905250068 7905040311 7906180116 7906010163	BECY	P H
	7904140025 7904160031 7904250041 7904040438 7904140029	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Deputy Executive Lagar Director	7906200560 7906180138 7906010307 7906180697 7906070219	50~574 50~482	T Q H C
	7906160036 7906180081 7906160039 7906180128 7906160018	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Hearings Division	7906210060 7906230114 7906210060 7906210047 7905140018	50-471 50-320 50-320	00000
	7706050010 7706050015 7706020146 7706020149 7706020152	XFORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC	Branch 1	7906290301 7903200326 7903200319 7903210409 7905110360	50-341 50-341 50-361	P 0 0 0
	7906020162 7906040226 7906150107 7906150109 7906150111	XPORTLIC XPORTLIC XPORTLIC XPORTLIC XPORTLIC		7906070175 7906210062 7906180679 7906190032		Q Q
	7906160059 7906160061 7906160063 7906160064	XPORTLIC XPORTLIC XPORTLIC XPORTLIC		7906220125 7906250224 7906260205 7906220473 7906260394	50-338 50-522 50-445 50-400 50-382	.0000
	7906160065 7906180022 7906180025	XPORTLIC  XPORTLIC  XPORTLIC	Branch 2	7903210375 7903210244 7903200314 7903210437	50-275 50-263 50-471 50-338	00000
	7906150119	XPORTLIC		7903210426	90-520	•

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	\$Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGOR	RY
	7903210406 7903210453 7906010070 7906070032 7906010161	50-549 50-580 50-549 50-243 50-338	0 0 0		7906010325 7906010331 7906010338 7906010339	70-2623 70-2623 70-2623 70-2623	C
	7906210359 7906050011 7906010144 7906180807 7906180816	50-237 50-471 50-471 50-272 50-272	0	uperations & Administrative Division Rulemaking & Enforcement Division	7906010342 7906010349 7906190032 7906040054 7906230165	70-2623 70-2623 50-498 50-443 50-305	0000
	7906230180 7906210337 7906250124 7906200625	50-261 50-237 50-454 50-456	0 0 0	Anti-Trust Division	7905110359 7906070347 7906020165 7906070034 7906180676	50-592 50-592 50-445 50-445 PROJ	A G M H
Branch 3	7906290613 7906290613 7906040203 7906020132 7906030240	50-471 50-295 50-266 50-510 50-488	о н о		7906070034 7906050118 7906070037 7906040032 7906190147	50-445 PROJ PROJ 50-445 50-445	H
	7906110009 7906050240 7906110009 7906040374 7906050240	50-488 50-488 50-490 50-488	e e e	Office of Hanagement and Program Analysis	7906200445 7906210077 7906210075 7906210081	50-320 50-320 50-320 50-320	e e e
	7906040376 7906040374 7906110009 7906050062 7906120019 7906010301	50-580 50-490 50-488 50-592 50-485 50-592	0		7906210071 7906050273 7906020094 7906290616	50-320 NUREO NUREO NUREO	P
	7706070365 7706070177 7706020113 7706180693 7706200507	50-322 50-400 50-488 50-358 50-466	н о о	Office of State Programs	7906060237 7906220274 7906210200 7906200448 7906200453	50-320 50-320 50-320 50-320 50-320	H 0 U P P
	7906080030 7906040114 7906070326 7906180743 7906230178	50-358 50-466 50-466 50-359 50-437	0 0 0	Assistant Director for Emergency Preparadness	7906210100 7906070049 7906290770 7906230133	50-320 50-320 50-320 NUREQ	P <i>P</i> ዝ
	7904250259	50-437	ø	· reparedites	7906220214	50-320	P
	7906230229 7906230173 7906260138	50-358 50-466 50-568	G G	Assistant Director for Program Development	7906230132 7906210267	10-320	P
	7906190568 7906210248	50-358 50-358	G O	Assistant Director for State Agreements Programs	7906290321	50-320	P.
	7906230021 7906260298 7906190560 7906190565	50-339 70-2623 50-367 50-387	0000		7906290363	50-320	P
	7906190572 7906190576 7906190560 7906190565 7906190572	50-387 50-387 50-387 50-387 50-387	0	Office of Inspection & Enforcement	7902210141 7902130358 7906210127 7906130415 7906260069	1&E 1&E 50-320 50-320 50-320	P P
	76 26 25 28	50-387 50-322 50-322 70-2623 70-2623	0 0 0 C C		7906130362 7906130427 7906290036 7906290504 7906270014	50-320 50-320 FOIA FOIA 50-320	P P
	;	70-2623 70-2623 50-322 50-514	C C O		7906290078 7906290348 7906130342 7906220317	FOIA FOIA 50-320 50-320	P P
	1	70-2623 70-2623 50-322 70-2623	COC		7906260519 7906060225 7906060153 7906070006 7906290582	50-346 50-320 1&E 50-320 FOIA	P H P
	;	70-2623 70-2623 70-2623 30-322 70-2623 70-2623	G C C C C C C C C C C C C C C C C C C C		7906290003 7906040110 7906070212 7906290447 7906210223	50-320 70-895 50-482 FOIA 50-320	P C A P
		70-2623 70-2623 50-516 50-556 50-329	C G G		7906040171 7906180180 7905040360 7906060241 7906200494	50-482 50-482 50-133 50-320 50-320	0 A B P P
		50-329 50-329 50-329 50-329 50-329	9		7906210203 7906290035 7906290106 7906210228 7906060158	50-320 50-320 50-320 50-320 14E	6 6
		50-327 50-389 70-2623	C		7906210224 7906210280	50-320 50-320	P P

AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEGOR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY
	7906060161 7905110048 7906210221 7906060178	1&E 1&E 50-320 50-320	P		7906140506 7906140516 7906010040 7906140506	40-8194 C 40-8194 C 50-311 Q 40-8194 C
1	7906270065 7906220150 7906260360 7906270065	50-320 50-320 50-320 50-320	P G P		7906140316 7906010075 7906010077 7906010077 7906010075	40-8194 C 70-2484 C 70-2484 C 70-2484 C 70-2484 C
	7906060172 7906260367 7906060161 7906060165 7906060197	1&E 50-320 50-320 1&E 50-320	G 8		7904010077 7904010075 7904010077 7904290825	70-2684 C 70-2684 C 70-2684 C 50-219 Q
	7906060203 7906270134 7906060164	50-320 50-320 I&E	P P		7906290833 7906010075	50-219 Q 70-2684 C
	7906050061 7906060168	50-320 I&E	S		7906010077 7906040058 7906260009	70-2684 C 50-443 0 70-2000 C
	7906250148 7906220153 7906070187 7906130446 7906290214	50-313 50-320 50-267 50-320 1&E	0 8 P P		7906290697 7906210295 7906260009 7906050183	50-220 q 70-364 c 70-2000 c 50-336 q
	7906270031 7906270027	50~320 50~320	6		7906130469 7906200413	50-320 H
	7906220107 7906290220 7906290232 7906290237	50~320 I&E I&E I&E	v		7906130469 7906130052 7906130055 7906260061 7906130048	50-320 H 70-135 C 70-135 C 50-20 Q 70-135 C
Eivision of Fuel Facility & Materials Safaty	7906130489 7906130490	50~320 50~320	P U		7706180413 7706200408	50-311 G 50-320 P
Division of Reactor Operations Inspections	7902150354 7906270260	1&E 50~336	P		7906180394 7906180405 7906180413	50-322 Q 50-352 Q 50-311 Q
Region 1. Philadelphie, Office of the	7906130485 7906290440 7906270072 7906140193	50-320 50-320 50-320 50-307	P F P Q		7906180389 7906180407 7906180400 7906180383	50-363 q 50-387 q 50-410 q 50-412 q
Birectar	7906010132	70~1200	c		7906180397 7906180416	50-423 Q 50-443 Q
	7906010136 7906010132 7906010136 7906030206 7906030212	70~1200 70~1200 70~1200 50~352 50~352	C C G G		7906180417 7906180394 7906260175 7906070379	50-485 @ 50-322 @ 50-271 @ 50-320 H
	7906050206 7906050212 7906040188 7906070213 7906070197	50-352 50-352 50-322 50-367 50-387	œ œ œ œ œ		7906130089 7906200426 7906210232 7906290359 7906290842	20-320 b 20-350 b 20-350 b
'	7906070206 7906070197 7906070206 7906140159 7906140164	50-367 50-367 50-367 50-29 50-29	0 0 0 0 0	9	7906260168 7406070379 7406130089 7406070379 7406130089	50-334 q 50-320 H 50-320 H 50-320 H 50-320 H
	7906130305 7906040089 7906130305 7906070244	70-510 50-272 70-510 50-334	C Q C			
	7906070239 7906260011 7906260014 7906010039	50-334 70-2000 70-2000 50-354	0 C C G			
	7906260011 7906260014 7906010047 7906140140 7906010043	70-2000 70-2000 50-245 70-364 50-245	C C G C			
	7906010036 7906190226 7906140113 7906190226 7906030203	50-354 70-2880 50-293 70-2880 70-364	@ G C C			
	7906140124 7906010123 7906120248 7906120251 7906010123	70-371 70-1200 50-307 50-307 70-1200	c c a c			
	7906140218 7906140207 7906210055 7906140516 7906140506	70-135 50-387 70-820 40-8194 40-8194	C C C			
	7906140516	40-8194	Ç			

The second secon

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	₹ <b>Y</b>	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOOR	
	7906110015 7906020142 7906020124 79060260260 7906050006 7906130162 7906130165	50-322 50-219 50-320 50-320 50-219	9 P P 9		7906260046 7906260078 7906260078 7906260073 7906260063 7906260063	50-54 50-57 50-77 50-97 50-134 50-97	G G G G
	7906130183 7906130164 7906130177 7906130170	50-220 50-245 50-271 50-277	0 0 0		7906260062 7906260030 7906260026	50-166 50-170 50-184	G G G
	7906130161 7906210219 7906130163	50-273 50-320 50-322	Q P Q		7904240025 7904240080 7904240040	50-193 50-199 50-201	a a
	7906130168 7906130172 7906130174	50~333 50~352 50~354	G G		790626006B 7906110119 7906260099 7906110122	50-208 50-213 50-213 50-217	@ @ @
	7906130173 7906130167 7906140595 7906210143 7906220065	50-387 50-410 50-219 50-320	G G P P		7906260112 7906110142 7906260128 7906260070 7906260065	50-220	@ @ @
	7906290391 7906220311 7906210017 7906210243	50-320 50-320 50-320 50-320	P P P		7906110149 7906260160 790611013B 7906260124	50-244 50-244 50-245 50-245	q q q
	7906210144 7906210282 7906120152 7906120206 7906120154	50-320 50-320 50-3 50-29 50-213	ዮ G G		7706110118 7706260078 7706110150 7706260163 7706110148	50-3 50-271 50-271 50-272	0 0 0 0
	7906120162 7906120177 7906120201 7906120176 7906120152	50-219 50-220 50-244 50-245 50-3	Q Q Q Q		7906260149 7906110146 7906260139 7906110146 7906260139	50-272 50-277 50-277 50-277 50-277	0 0 0
	7906120205 7906120197 7906120188 7906120187 7906120169	50-271 50-272 50-277 50-284 50-320	9 9 9		7906110144 7906260132 7906110135 7906260119 7906110115	50-284 50-289 50-289 50-320 50-293	9 9 9
	7906220189 7906120149 7906120171 7906120194 7906120150	50-320 50-293 50-309 50-311 50-317	e a a a		7906260091 7906110137 7906260121 7906260151 7906110116	50-293 50-309 50-311 50-317	0 0 0 0
	7904120169 7906210145 7906210212 7906210215 7906220189	50-320 50-320 50-320 50-320 50-320	Q Р Р Р		7906260093 7906110116 7906260093	50-317 50-317 50-317	a a
	790&1201&6 790&120185 790&120188	50-322 50-333 50-334	Q Q Q		7906200507 7906220151 7906220332 7906260119	50-320 50-320 50-320 50-320	G H P G
	7906120176 7906120189 7906120194 7906120163	50-245 50-352 50-311 50-363	0 0 0		7906290418 7906260115 7906110143 7906260136	50-320 50-322 50-333 50-333	6 6
	7906120192 7906120182 7906120156 7906120176	50-387 50-410 50-412 50-245	G G G		7706110120 7706260101 7706110138 7706260124 7706260151	50-334 50-334 50-245 50-245 50-311	0 0 0 0
	7906120198 7906120202 7906120166 7906140497 7906250405	50-443 50-485 50-322 40-8174 50-217	a a c		7906260112 7906260145 7906260131 7906260104 7906260124	50-219 50-387 50-410 50-412 50-245	0 0
	7906140497 7906220192 7906010037 7906210001	40-8174 50-320 70-2684 50-320	C F C P		7906260156 7906260157 7906260115 7906260053	50-443 50-485 50-322 70-33	9 9 9 0
	7906260372 7906290421 7906130043 7906210268	50-320 50-320 50-320 70-135 70-364	P C C		7906260034 7906260038 7906260035 7906260040 7906260048	70-135 70-371 70-820 50-201 70-1100	0 0000
	7904010057 7904110118 7904240098 7904240044 7904240059	70-2484 50-9 50-3 50-5 50-20	C Q Q Q		7906260044 7906220057 7906290186 7906210148	70-1143 50-320 50-320 50-320	C P P
	7706260051 7706110153 7706260164 7706260027	50-22 50-29 50-29 50-47	9 9 9		7906210152 7906210236 7906200385 7906210158	50-320 50-320 50-320 50-320	P P P

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	Y
	7906260232 7906200381 7906210008	50-320 50-320 50-289	G G P		7906150192 7906150195 7906150190 7906010039	50-363 50-363 50-363 50-354	0 0 0
	7904210140 7904220304 7904080049 7904080027 7904080024	50-320 50-320 50-3 50-5 50-20	P Q Q		7906140635 7906140628 7906140632 7906140621 7906140582	50-311 50-387 50-311 50-387 50-443	G G G
	7906080053 7906080112 7906080012 7906080045 7906080015	50-22 50-29 50-47 50-54 50-77	G G G		7906140574 7906040401 7906260323 7906260155 7906260319	50-443 50-363 50-387 50-334 50-387	0 0 0 0
	7706080021 7706080037 7706080021 7706080034 7706080011	50-97 50-134 50-97 50-166 50-170	0 0 0 0		7906090193 7906040078 7906010130 7906040169 7906200473	50-352 50-272 50-443 50-322 50-320	0 0 0 p
	7905080014 7906080022 7906080018 7906080071 7906080084	50-184 50-179 50-208 50-213 50-219	a a a a	1	7906020208 7906130179 7906130480 7906070179 7906040397	50-352 50-363 50-387 50-387 50-412	8 0 8
	7906080096 7906080031 7906080029	50~220 50~223 50~225	G G	Region 1, Philadelphia, Fuel Facility & Materials Bafety Branch	7906210034 7906260342	50-387 70-371	6 C
	7906080106 7906080091 7906080069	50~244 50~245 50~3	G G		7906260347 7906260340 790614060B	70-371 70-371 70-820	C C
	7906080111 7906080104 7906080102 7906080097	50~271 50~272 50~277 50~286	G G		7906150210 7906150213 7906150210 7906150213 7906290171	50-245 50-245 50-245 50-245 70-1710	G G G
	7904080087 7904080059 7904080088 7904080044 7904080087	50-320 50-293 50-309 50-317 50-320	0 0 0 0		7906180653 7906140592 7906140598 7906180650	70-920 70-920 70-920 70-820	0000
	7906200499 7906200505	50-320 50-320	P		7906180653	70-920	C
	7906210239 7906080078 7906080079 7906080091	50-320 50-333 50-334 50-245	P Q Q		7906290171 7906150209 7906180648 7906190224	70-1710 50-245 70-820 70-2880	0000
	7706080043 7706080037 7706080050 7706080046	70-33 70-135 70-371 70-820	C C C		7906210288 7906210289 7906210293 7906140639 7906140643	70-364 70-364 70-364 70-33 70-33	0000
	7906080041 7906080035 7906220097 7906220118 7906210002	70-1100 70-1143 50-320 50-320 50-320	6 G & & &		7705270842 7705270837 7705270143 7705170221 7705180141	50-333 50-333 70-1710 70-2880 50-29	0 C C
	7906290432 7906210164 7906210169 7906210176 7906260090	50-320 50-320 50-320 50-320 50-320	4444		7906180171 7906180141 7906180171 7906180141 7906180171	50-27 50-29 50-29 50-29 50-29	0 0 0 0
	7906210181 7906220085 7906200410 7906210241 7906220287	50-320 50-320 50-320 50-320 50-320	<b>P</b> P P		7906290145 7906050184 7906190221 7906150200 7906210024	70-1710 70-1717 70-2880 50-245 50-320	CCCGP
	7906290393 7906290416 7906220141 7906220078 7906200431	50-320 50-320 50-320 50-320	P		7906150200 7906140579 7906180621 7906210005 7906200477	50-245 70-820 70-820 50-320 50-320	G C P P
7 7 7 7 7 7 Region 1, Philadelphia, Reactor 7 Construction & Engineering Support Branch 7 7	7906220299 7906260222 7906270011	50-320 50-320 50-320	P G G	Region 1, Philadelphia, Reactor	7906290410 7906120061	50-320 50-213	ğ
	7906210003 7906210012	50-146 50-320	H	Operations Nuclear Support Branch	7906120066 7906140164 7906120055	50-213 50-29 50-213	Q Q
	7906050201	50-320 50-352 50-352	P Q Q		7906140151 7906070244 7906070236	50-29 50-334 50-334	9
	7906040188 7906040182	50-322 50-322	a		7906010047	50-245	9
	7906040186 7906070213 7906040081 7906040083	50-322 50-387 50-272 50-272	0 0 0		7906140113 7906140098 7906120251	50-293 50-293 50-309	9
	7906040089	50-272	a		7906120244 7906140207	50-309 50-387	9

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEODE	
	7906140201 7906130491 7906290823 7906290704 7906050183	50-387 50-320 50-219 50-220 50-334	G P G G		7906210051 7906180321 7906180321 7906180321 7906180355	50-390 50-338 50-338 50-338	9 9
	7906050173 7906130478 7906290692 7906260061 7906250478	50-336 50-320 50-220 50-20 50-311	0 0 0 0		7706020187 7706020191 7706180396 7706180408 7706180018	50-338 50-124 50-124 50-302 50-302 50-324	9 9
	7906250057 7905260546 7906260551 7906250476 7906260546	50-20 50-245 50-245 50-211 50-245	a a a a		7704180731 7704180205 7704050091 7704050100 7704140041	50-327 50-335 50-366 50-366 50-369	G G G
	7905260551 7905260339 7905260499 7905260504	50-245 50-320 50-311 50-320 50-244	0 0 0 0		7906160044 7906160041 7906160044 7906080169 7906040366	50-369 50-369 50-369 50-369 50-369	9
	7906260309 7906260171 7906200334 7906260491 7906200334	50-244 50-271 50-320 50-311 50-320	G G G		7706200146 7706200152 7706200146 7706200152 7706070114	50-280 50-280 50-280 50-280 50-337	9 9
	7906210217 7906140143 7906120039 7906070231 7906270813	50-320 50-29 50-213 50-334 50-219	G G G G		7906070104 7906180680 7906250142 7906250146 7906190223 7906150463	50-416 50-280 50-281 50-291 50-348	9 9 9 9
Region I, Philadelphia, Safeguarde Branch	7906290679 7906140193	50-220 50-209	a a		7906050117	50-390 50-366	a
	7906140185 7906040089	50-209 50-272	a a		7906180098 7906040180 7906040184	50-424 70-143 70-143	G C
	7906140140 7906030199 7906030203 7906140124	70-364 70-364 70-364 70-371	C C C		7906190347 7906190354 7906190213 7906010328	70-924 70-924 50-290 50-518	COO
	7906010041 7906140218 7906140119 7906150222 7906150219	50-311 70-135 70-371 50-317 50-317	0 C C Q		7906070090 7906070095 7906070090 7906070095 7906010034	50-111 50-111 50-111 50-111 50-327	0 0 0
	7906140134 7906140212 7906210052 7906260568 7906140180	70-364 70-135 70-820 70-33 50-309	c c c a		7904010328 7904010023 7904140093 7904230010 7904140093 7904050075	50-518 50-566 50-321 50-335 50-321	0 0
	7906260365 7906150215 7906080101 7906290403 7906260336	70-33 50-317 50-155 50-320 70-33	C G G P C		7706030140 7706230008 7706230176 7706200204 7706200176	50-390 50-416 50-335 50-390 50-390 50-390	0 0 0
Region 2. Atlantm, Office of the Director	7906260478 7906260264 7906260259 7906210396 7906200344	50-320 50-269 50-269 50-111 50-321	# G G Q		7906200204 7906070302 7906010314 7906140144 7906140147	50-370 50-491 50-338 50-370 50-370	9
	7906200552 7906200544 7906200552 7906210396 7906040387	50-321 50-321 50-321 50-111 50-327	G G G G		7906070302 7906190208 7906200341 7906220093 7906070284 7906070323	50-491 50-280 50-324 50-390 50-491 70-1201	9 9990
	7906180232 7906010141 7906010143 7906010141 7906010143	50-335 50-553 50-553 50-553 50-553	G G G G		7904290288 7904290302 7904250097 7904290174 7904290149	50-287 50-302 50-320 50-287 50-302	0 0 0
	7906040382 7906070372 7906010202	50-327 50-250 50-416	0 0		7906290048	50-287	G
	7906010205 7906010202	50-414 50-414	a a		7906200617 7906290048 7906290055 7906070058	50-281 50-269 50-302 50-324	9000
•	7906010205 7906070368 7906200540 7906210057	50-416 50-250 50-321 50-390	Q Q Q		7906290519 7906070121 7906210409 7906290519	50-324 50-281 50-281 50-269	9 9
	7706210054 7706200160 7706020126 7706020128	50-390 50-290 50-369 50-369	g g g		7906050114 7906050121 7906260517	50-302 50-302 50-302	Q Q

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEOUR	Y	AUTHOR AFFILIATION	ACCESSION NUMBER	6UBJECT CATEODRY	
	7906290510 7906070162 7906210068 7906190589	50-312 50-327 50-389 70-27	a a c		7906250446 7906250452 7906250455 7906250436 7906250424	50-250 50-321 50-13	Q Q Q Q
	7906190394 7906290087 7906290099 7906200364	70-27 50-287 50-302 50-389 50-416	c G G G		7906250422 7906250436 7906250414 7906020174 7906250421	50-13 50-111 50-124	G G G
	7906290362 7906200490 7906290562 7906290557	50-287 50-250 50-269 50-302	9 9 9 9		7906250418 7906250413 7906250452 7906250440 7906250443	50-160 50-250 50-261	Q Q Q Q
	7906200359 7906220249 7906220250 7906220249	50-348 50-348 50-348 50-348	G G G		7906250413 7906250443 7906250414 7906250450	50-160 50-269 50-111 50-302	a a a
	7906220230 7906210291 7906220234 7906220238 7906220234	50-348 50-370 50-438 50-438 50-438	a a a		7906250455 7906250440 7906250433 7906250452 7906250437	50-261 50-332 50-250 50-348	9 9 9
	7906220238 7906290135 7906290130 7906180758 7906180764	50-438 50-297 50-302 50-413 50-413	G G G G		7906250453 7906250443 7906250452 7906250458	50-321 50-269 50-250 50-395	Q Q Q
	7906180758 7906180764 7906020139 7906020140	50-413 50-413 50-553 50-553	Q Q Q		7906250440 7906250424 7906260615 7906250440	50-375 50-62 50-400 50-261	Q Q A
	7906020139 7906020139 7906020140 7906020144 7906290429	50-553 50-553 50-553 50-553 50-267	G G G		7906200615 7906250440 7906200615 7906250440 7906200615	50-400 50-261 50-400 50-261 50-400	A G A
	7906290436 7906070021 7906290480 7906070375	50-302 50-321 50-267 50-250	Q Q Q		7906250440 7906250425 7906250446 7906260363 7906250455	50-261 50-406 50-413 50-414 50-321	a a a
	7906290480 7906290473 7906200318 7906210422 7906200318	50-249 50-302 50-338 50-338 50-338	a a a		7906230455 7906230386 7906230446 7906230417	50-321 50-437 50-413 50-536 70-27	G G G
	7906210422 7906140157 7906270809 7906270598	50-338 50-348 50-437 50-287	Q Q Q		7906250430 7906250436 7906250432 7906250429	70-143 50-13 70-1113 70-1201	0000
	7906290619 7906290398 7906290619 7906010350 7906200421	50-302 50-267 50-302 50-369 50-320	0 0 0		7906250428 7906250427 7906110063 7906110066 7906110059	70-1319 70-1432 50-250 50-259 50-261	0
	7906200311 7906290456 7906260495 7906260612	50-238 50-287 50-250 50-250	Q Q Q		7906110060 7906260242 7906110060 7906260242 7906110069	50-247 50-247 50-249 50-249 50-280	0 0 0
	7906260495 7906260612 7906290456 7906290450 7906290467	50-250 50-250 50-269 50-302 50-313	a a a		7906110040 7906260242 7906110066 7906110061 7906110065	50-269 50-269 50-259 50-302 50-321	0 0 0
	7906200434 7906260094 7906260197 7906260603	50-320 70-1201 50-281 50-281	P C G		7906110059 7906110063 7906110068 7906110058	50-261 50-250 50-260 50-348	G G G
	7906070390 7906010304 7906200279 7906190120	50-327 50-338 50-269 50-491	a a a		7906110065 7906210084 7906270068 7906190173 7906290406	50-321 50-390 50-320 50-318 50-320	Q P A P
	7906130147 7906130151 7906130141 7906130154 7906130141	50-518 50-257 50-321 50-324 50-321	a a a a	Region 2, Atlanta, Reactor Constructi	7906250111 7906290528 7906290535	50-261 50-362 50-382 50-327	0 8 8
	7906130144 7906130147 7906130146 7906200615	50-416 50-518 50-553 50-400	a a A	on & Engineering Support Branch	7906210108 7906210110 7906040377 7906210105	50-390 50-390 50-327 50-390	0
	7906250440 7906250443	50-261 50-269	a		7906010138	50-553	Q.

AUTHOR AFFILIATION	ACCESSION NUMBER	EUBJEC CATEGO		AUTHOR AFFILIATION	ACCEBSION NUMBER	EUBJECT CATEGOR	
	7904020128 7904020124	50-369 50-369	0		7906220074 7906220081 7906250355	50-395 50-395 50-438	G G
	7904010195 7904140037 7904140037 7904140037 7904140044	50-416 50-369 50-369 50-369 50-369	0 0 0		7904190148 7904250352 7904240527 7904240403 7904040370	50-395 50-438 50-339 50-281 50-327	g g g
	7904140445 7706180714 7904150039 7904180710 7706040364	50-438 50-259 50-438 50-259 50-369	a a a a		7906260524 7906260527 7906160024 7906260524 7906260527	50-339 80-339 50-349 50-339 50-339	9
	7706150034 7706040362 7706250146 7706250137 7706050117	50-438 50-369 50-281 50-281 50-366	a a a		7906260524 7906260527 7906260579 7906200428 7906260241	50-339 50-339 50-281 50-320 80-846	0 0 0 P 0
	7906140649 7906140654 7906140649	50-416 50-416 50-416	G G		7906260247	50-546	q
	7906140654 7906180098	50-416 50-424	G G		7906260241 7906260247 7906190162 7906220091	50-544 50-544 50-395 50-395	9 0 0
	7706140641 7706010322 7706010029 7706010034 7706010029	50-438 50-518 50-327 50-327	0 0 0 0		7706220101 7706190116 7706190120 7706190116 7706190120	50-395 50-491 50-491 50-491 50-491	99999
	7706010034 7706050113 7706180070 7706010322 7706010018	50-327 50-366 50-424 50-518	G G G G		7706170116 7706170120 7706070332 7706010133 7706220244	50-491 50-491 50-250 50-553 50-348	99999
	7906010023 7906010018 7906010023 7906050063	50-566 50-566 50-566 50-370 50-370	Q Q Q		7906010190 7906200447 7906210041 7906140116 7906190527	50-416 50-320 50-370 90-370 50-371	9999
	7906050063 7906050075 7906050133 7906050140	50-390 50-390 50-416 50-416	0 0 0		7906200174 7906220169 7906020120 7906180734	50-370 50-438 50-367 50-413	0 0 0
	7906050133 7906050140 7906200193 7906200204 7906200193	50-416 50-416 50-390 50-390 50-390	G G G		7706250122 7706020131 7706250163 7706270368 7706270475	50-281 50-553 50-367 50-375 50-413	0 0 0
	7906200204 7906010314 7906140147 7906070302 7906220093	50-370 50-336 50-370 50-471 50-370	Q Q Q Q	Region 2, Atlanta, Fuel Facility & Materials Safaty Branch	7706200160 7706070104 7906070072 7706070076	50-280 50-416 50-280 50-280	a a a
•	7906140142 7906070118 7906070121 7906210409 7906070156	50-370 50-281 50-281 50-281 50-327	G G G G		7906180673 7906180680 7906070072 7906070076	50-280 50-280 50-280 50-280	0 0 0
	7906070162 7906070156 7906070162	50-327 50-327 50-327	Q Q		7906180673 7906180680 7906140626	50-280 50-280 50-348	0 0
	7906210068 7906210402 7906220248	50-389 50-281 50-348	Q Q		7906140634 7906070099 7906150457 7906040177	50-349 50-416 50-390 70-143	0 0 0
	7906200364 7906210064 7906220084 7906210078	50-389 50-389 50-390 50-416	a a a		7706070318 7706070323 7706200609 7706200617 7706070058	70-1201 70-1201 50-281 50-281 50-324	0000
	7906220250 7906200362 7906210286 7906210281 7906210286	50-348 50-389 50-390 50-390 50-390	о о о		7906260516 7906260521 7906070050 7906210419 7906210422	50-302 50-302 50-324 50-338 50-338	00000
	7906210291 7906220242 7906180752 7906180754 7906180752	50-390 50-438 50-413 50-413 50-413	9 9		7906210419 7906210422 7906200392 7906200402 7906210026	50-338 50-338 50-320 50-320 50-320	0 P P
	7906180764 7906010350 7906010348 7906200388 7906230345	50-413 50-369 50-369 50-320 50-338	G G P G		7906210016 7906260501 7906260094 7906260493 7906210013	50-320 50-250 70-1201 50-250 50-320	POCOP
	7906260201 7906250341	50-281 50-338	9		7906210006	50-320	P

AUTHOR AFFILIATION	ACCEBBION NUMBER	SUBJECT CATEGOR		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATEOOR	
	7906210009 7906210021 7906040172 7906260088	50-320 50-320 70-143 70-1201	P C C		7906070108 7906070114 7906190218 7906190223 7906190554	50-339 50-339 50-348 50-348 70-824	0 0 0
	7906200454 7906200458 7906200390 7906200393 7906290389	50-320 50-320 50-320 50-320 50-320	P P P		7906070095 7906070087 7906190594 7906070384	50-111 50-111 70-27 50-327	G G C
	7906200138 7906290386 7906290401 7906290379 7906260513	50-280 50-320 50-320 50-320 50-302	Q P P Q		7906070390 7906070081 7906150042 7906150047 7906210351	50-327 50-111 70-143 70-143 50-111	0 0 0 0
	7906260354	50~250	G		7906180183 7906190215	50-335 50-348	a a
Rejion 2, Atlanta, Reactor Operations Loirar Support Branch	7906290537 7906260271 7906200552	50-280 50-269 50-321	G G		7906190570 7906080155 7906190542 7906260514	70-27 50-538 70-824 70-27	9000
	7906050382	50-338	Q	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1	7906260512	70-27	C
	7906150052 7906180355 7906020183 7906020191 7906180372	50-327 50-338 50-124 50-124 50-302	а а а а	Region 3, Chicago, Office of the Virector	7906230128 7906250026 7905310008 7906040411	50-346 50-254 70-597 50-329	9 0 0
	790&180408 790&180018 790&180731 790&030194 790&180013	50-302 50-324 50-327 50-364 50-324	G G G		7706200484 7706200486 7706020054 7706030051 7706020054	50-346 50-346 50-254 50-263 50-254	0 0 0 0
	7906150050 7906180720 7906050376 7906180315 7906190213	50-327 50-327 50-338 50-338 50-280	G G G		7906010336 7906020048 7906020068 7906030040 7906050228	50-440 50-254 50-275 50-331 50-456	0 0 0 0
	7906140085 7906140093 7906230013 7906140085 7906140093	50-321 50-321 50-335 50-321 50-321	G G G		7906040052 7906130139 7906130143 7906290280 7906270181	50-295 50-341 50-341 50-346 50-346	G G G
	7906190198 7906200541 7906200534 7906050121 7906050107	50-280 50-324 50-324 50-302 50-302	0 0 0		7906130455 7906290044 7906130136 7906290527 7906290110	50-320 50-346 50-341 50-346 50-346	P Q Q Q
	7906210073 7906200490 7906210304 7906200350 7906220242	50-416 50-250 50-327 50-348 50-438	G G G		7906290373 7906290141 7906070018 7906290441 7706290484	50-346 50-346 50-263 50-346 50-346	0 0 0
	7706200487 7706200439 7706210299 7906140150	50-250 50-320 50-327 50-348	о Н О		7906210334 7906260598 7906290629 7906210317	50-155 50-341 50-346 50-301	9 9 9
	7906260614	50-250	Q		7906130133 7906290623	50-331 50-346	Gi Ci
	7906250370 7906260611 7906250361 7906250365	50-324 50-250 50-324 50-324	0 0 0		7906130127 7906230136 7906230141 7906230136	50-329 50-454 50-454 50-454	0 0 0
	7906250367 7906250361 7906250365 7906250367 7906250375	50-324 50-324 50-324 50-324 50-335	G G G	,	7906250141 7906260326 7906260330 7906260326 7906260330	50-454 50-282 50-282 50-282 50-282	0 0 0 0
	7906250372 7906050074 7906200279 7906200270 7906180305	50-335 50-344 50-269 50-269 50-338	G G G		7906130123 7906130130 7906260394 7906230117 7906290462	50-327 50-331 50-341 50-346 50-346	G G G
	7906210224 7906230002 7906210399 7906050065 7906290383	50-320 50-335 50-259 60-302 50-320	P G G G P		7906260315 7906250132 7906250138 7906250172 7906260553	50-409 50-454 50-409 50-237 50-282	0 0 0
	7906180359 7906290381 7906080146 7906200522 7906190191	50-302 50-320 50-324 50-321 50-280	G P G G		7906250183 7906250125 7906250153 7906250155 7906230115	50-255 50-263 50-10 50-327 50-346	@ @ @
Region 2, Atlanta, Bafeguards Branch	7906240602 7906180232 7906080137 7906080169 7906210389	50-250 50-335 50-338 50-538 50-111	Q Q Q Q	•	7406260577 7406260579 7406230123 7406020011 7406260624	50-346 50-346 50-461 50-254 50-282	0 0 0 0

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO		AUTHOR AFFILIATION	ACCEBBION NUMBER	CATEGO	
	7905260571 7905260583 7905260589 7905010078 7906010079	50-346 50-373 50-409 50-294 50-294	G G G		7906190078 7906110110 7906190106 7906110101 7906190078	50-10 50-266 50-266 50-10 50-10	<b>a</b> <b>a</b> <b>a</b> <b>a</b>
	7906260636 7906260639 7906260199 7906130138 7906120222	50-346 50-346 50-358 50-263 ORG	a a a		7906110112 7906190108 7906110106 7906190099 7906110094	50-305 50-305 50-263 50-263 50-315	0 0 0
	7906260633 7906140200 7906210277 7906050057 7906050238	50-237 50-264 50-320 50-454 50-373	0 0 0 0		7906190076 7906110094 7906190076 7906190087 7906110104	50-315 50-315 50-315 50-329 50-331	0 0 0
	7904020147 7904120083 7904120098 7904120083 7904120098	ORG 50-10 50-135 50-10 50-135	9 9		7906190094 7906190092 7906110108 7906190102 7906190062	50-331 50-341 50-346 50-346 50-151	a a a a
	7704120121 7704120083 7704120132 7704120121 7704120083	50-263 50-10 50-266 50-243 50-10	0 0 0		7906190084 7906190096 7906190078 7906110098 7906190090	50-358 50-367 50-10 50-407 50-409	0 0 0 0
	7906120132 7906120083 7906120134 7906120121 7906120114	50-266 50-10 50-305 50-263 50-315	0 0 0	i	7904190084 7904190078 7904190095 7904190104 7904190098	50-440 50-10 50-461 50-483 50-484	Q Q Q
	7706120100 7706120107 7706120106 7706120125 7706120073	50-329 50-331 50-341 50-344 50-358	0 0 0		7706170104 7706170101 7706170025 7706170036 7706170045	50-483 50-546 70-8 70-36 70-152	9 9 9
	7906120118 7906120083 7906120104 7906120097 7906120083	50-367 50-10 50-409 50-440 50-10	a a a a		7906190029 7906190033 7906190027 7906260015 7906190225	70-925 70-1220 70-1489 DRO 50-546	C C
	7906120111 7906120127 7906120119 7906120127 7906120123 7906020138	50-461 50-483 50-483 50-483 50-346 50-373	G G G		7906190229 7906200523 7906200239 7906200543 7906200239	50-358 50-346 50-10 40-3372 50-10	8 P C P
	7906020145 7906180045 7906020138 7906260306	DRO 50-254 50-373 50-263	G A G		7906210134 7906200239 7906210134 7906200451 7906200239	50-155 50-10 50-155 50-263 50-10	ቦ P P P
	7904110101 7904190078 7904190037 7904190058 7904110101	50-10 50-10 40-3372 50-2 50-10	9 9 9		7906210324 7906200451 7906200239 7906210324 7906200239	50-266 50-263 50-10 50-266 50-10	P P P P
	7906190078 7906190040 7906190064 7906230097 7906190048	50-10 50-97 50-116 50-123 50-150	G G G		7906200245 7906220119 7906200451 7906200460 7906190232	50-305 50-305 50-263 50-315 50-327	Р С Р В
	7906190062 7906110096 7906190088 7906190056 7906190051	50-151 50-155 50-155 50-156 50-182	G G G		7906210140 7906190232 7906210140 7906200250 7906200443	50-329 50-329 50-329 50-331 50-346	A B A P P
	7906230098 7906110101 7906190078 7906110101 7906190078	50-196 50-10 50-10 50-10 50-10	G G G		7906200239 7906200235 7906200538 7906200533 7906080120	50-10 50-407 70-36 70-1308 080	PFGG
	7906110101 7906190078 7906110096 7906190088 7906110106	50-10 50-10 50-135 50-135 50-243	G G G		7906080196 7906080131 7906080184 7906080196 7906080147	50-10 40-3372 50-2 50-10 50-87	0 0 0
	7906190099 7906190042 7906110101 7906190078 7906110110	50-243 50-264 50-10 50-10 50-266	G G G		7906080170 7906080186 7906080174 7906080181 7906080200	50-116 50-123 50-150 50-151 50-155	0 0 0
	7904190104 7904110106 7904190099 7904190060 7904110101	50-246 50-263 50-243 50-294 50-10	0 0 0 0		7906080176 7906080176 7906080188 7906080196	50-154 50-162 50-186 50-10	G G G

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJEC CATEGO	
	7906080200 7906080204 7906200517	50-263	Q Q P		7906200080 7906200125 7906200139	50-10 50-461 50-483	G G
	7906200517 7906080134 7906080196 7906080207	50-264 50-10	Q Q Q	Region 3, Chicago, Reactor Constructi	7906200132 7906200139 7906200136 7906040404	50-484 50-483 50-546 50-329	G G G
	7906080204 7906080172 7906080196 7906080207	50-294 50-10	Q Q Q Q	on & Engineering Support Branch	7906050046 7906140658	50-263 50-341	o G
	7906080196 7906080209 7906220110 7906080204	50-10	G G G G		7906140570 7906140647 7906140651 7906010333	50-483 50-341 50-341 50-440	0 0 0
	7904080203 7906220174 7904080202	50-315 50-329 50-331	G E Q		7906140562 7906140564 7906050234 7906050054	50-483 50-483 50-373 50-454	G G
	7906080205 7906080181 7906080201 7906080126	50-346 50-151 50-409 70-8	G G C		7906050222 7906140607 7906040045 7906140601	50-456 50-341 50-295 50-341	Q Q Q
	7906080132 7906080178 7906080142 7906080137 7906080140	70-36 70-152 70-925 70-1308 70-1489	c c c		7906210329 7906210311 7906260592 7906250165	50-153 50-301 50-341 50-237	0 0 0
	7906130082 7906130094 7906130082	50-10 50-155 50-10	Q Q Q		7906250118 7906250150 7906260621	50-441 50-327 50-282	0 0 0
	7906130094 7906130109 7906130082 7906130120	50-155 50-263 50-10 50-266	G G G		7906260502 7906260581 7906260587 7906010052	50-346 50-373 50-407 50-341	G C
	7906130107 7906130082 7906130120	50-263 50-10 50-266	Q Q		7906260497 7906260192 7906070266 7906010124	50-346 50-358 50-373 50-483	0 0 0
	7906130082 7906130121 7906130109 7906130079	50-10 50-305 50-243 50-315	0 0 0		7906020134 7906040449 7906230067	50-454 50-341 50-329 50-329	S G S
	7906130093 7906130100 7906130098 7906130116	50-329 50-331 50-341 50-346	a a a		7906250149 7906230067 7906250149 7906230076	50-329 50-329 50-341	9 G 8
	7906130088 7906130104 7906130082	50-358 50-367 50-10	a a		7906260097 7906230074 7906250145 7906220175	50-341 50-373 50-546 50-546	0 8 8
	7906130097 7906130090 7906130082 7906130103	50-407 50-440 50-10 50-461	a a a	Ragion 3, Chicago, Fuel Facility &	7906250145 7906290804 7906290687 7906020055	50-546 50-546 50-341 50-275	8
	7906130118 7906130111 7906130118 7906130113 7906260074	50-483 50-484 50-483 50-546 50-315	a a e e	Haterials Safety Branch	7r		
	7906260049 7906120230 7906200075 7706200080 7906200103	50-331 ORO ORQ 50-10 50-155	a a	Region 3, Chicago, Nuclear Bupport Bran			
	7906200080 7906200103 7906200131 7906200080 7906200142	50-10 50-155 50-263 50-10 50-266	0 0 0 0 0				
	7906200131 7906200080 7906200142 7906200080 7906200145	50-263 50-10 50-266 50-10 50-305	a a æ æ				
	7906200131 7906200126 7906200109 7906200121 7906290629	50-263 50-315 50-329 50-331 50-331	G G G G				
	7906200118	50-341	Q.				
	7906200137 7906200099 7906200128 7906200080	50-346 50-358 50-367 50-10	0 0 0				
	7906200116 7906200101	50-409 50-440	Q G				

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEGO	
Region 3, Chicago, Safeguards Branch	7906260337 7906270649 7906250109 7906140591	50-315 50-282 50-346 50-2	G G G		7904050056 7904050073 7904210109 7904130137 7904120075	50-482 50-482 50-498 50-298 50-267	Q: Q: Q: Q:
	7906010079 79061405B5 7906140200 7906140194 7906080123	50-274 50-2 50-264 50-264 50-182	0 0 0		7906120072 7906120071 7906120063 7906120070 7906120079	50-265 50-298 50-313 50-362 50-445	G G G
	7906180045 7906050120 7906080123 7906080093 7906180039	50-254 50-266 50-182 50-155 50-254	G G G		7906120065 7906120068 7906120067 7906210074 7906230055	50-458 50-482 50-498 GA799 GA799	G G
	7906260305 7906260312 7906200575 7906200569 7906260209	50-243 50-243 70-1308 50-409 50-87	Q Q Q Q		7904250013 7906250015 7906250014 7906250013 7906250003	50-59 50-72 50-112 50-59 50-131	G: G: G: G:
Region 4, Dailas, Office of the Director	7906260237 7906260203 7906260231 7906160009	50-368 50-87 50-368 GA999	G G	,	7906250007 7906250006 7906250012 7906250009	50-148 50-188 50-192 50-252	Q Q Q
	010001400PT 80000140PT	94999 94999			7906250008 7906110088	50-262 50-267	a
	7906230063 7906230066 7906290708 7906290711	94999 94999 94999			7906250025 7906250004 7906250010 7906110086	50-267 50-274 50-284 50-285	0 0 0
	7906210338 7906060097 7906290276 7906060094	0A999 0A999 0A999 0A999			7906250024 7906110084 7906250023 7906110083 7906250016	50-295 50-298 50-298 50-313 50-313	9 9
	7706210316 7906040160 7906040162 7906040160 7906040162	GA999 50-313 50-313 50-313	0 0 0		7904110083 7906250016 7906250022 7906250015 7906250027	50-313 50-313 50-382 50-72 50-445	9 9 9
	7906180255 7906160006 7906210083 7906210086 7906210080	GA777 GA777 GA777 GA777 GA777			7904250018 7904250021 7904250019 7904210088 7904240574	50-458 50-462 50-478 0A979 70-1257	0 0 0
	7906290229 7906290236 7906160004 7906220218 7906210059	GA797 GA797 GA797 GA797 GA797			7906130071 7906130073 7906130065 7906130069 7906130067	50-382 50-445 50-458 50-462 50-478	0 0 0
	7906210058 7906270695 7906210061 7906210069 7906210097	GA999 GA999 GA999 GA999 GA999			7906210033 7906200043 7906200041 7906200039 7906220223	50-320 50-247 50-278 50-313 50-382	P
	7906210099 7906150055 7906210093 7906150045 7906190137	0A999 50-313 0A999 50-313 50-267	9 9 9		7906220241 7906250044 7906250051 7906250044	50-382 50-498 50-498 50-498	Q Q Q
	7904230030 7904230033 7904290067 7904290534 7904290113	99999 99942 816-08 816-08 816-08	Q Q Q		7906250051 7906210025 7906210032 7906210018	50-498 50-492 50-482 50-285	0 0
	7906210029 7906220228	50~320 50~382	P		7906200474 7906210022	50-445 50-285	Q
	7906220241 7906230047 7906230051 7906230047	50-382 50-498 50-498	9		7906180161 7906180163 7906180152 7906180160	50-382 50-445 50-458 50-482	8 8
	7906250051 7906290583 7906290624 7906290581	50-498 50-498 GA999 GA999 50-313	a a		7906180156 7906120143 7906130027 7906140165 7906180182	50-498 50-392 50-492 50-492 50-392	8 9 9 8
	7906290147 7906210032 7906290627 7906200524 7906110004	50-313 50-482 50-313 50-445 50-382	0 0 0		7906180184 7906180174 7906180177 7906120138 7906180176	50-445 50-458 50-482 50-478 50-478	8 8 8 8
	7906110005 7906110001 7906110005 7906110003 7906110002	50-445 50-458 50-445 50-482 50-498	G G G		7906120138 7906180176 7906180247 7906180250 7906180241	50-498 50-498 50-382 50-445 50-458	8 8 8

#### 375

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT	RY		AUTHOR AFFILIATION	ACCESSION NUMBER	BUBJECT CATECORY	
	7906180245 7906180243 7906180326 7906180331 7906180318 7906180324	50-482 50-498 50-382 50-445 50-458	8 6 8 8 8 8 8			7906190074 7906230048 7906230049 7906230051 7906030179 7906050182	GA777 GA777 GA777 GA777 GA777	
Figlen 4, Dailas, Fuel Facility & Wirlels Befety Branch Figlen 4, Dallas, Reactor Operations Eclear Support Branch	7906180320 7906290389 7906040162 7906040156	50-498 50-445 50-313 50-313	8 G G			7706210297 7706230035 7706050171 7706050174 7706050177	0A999 0A999 0A999 0A999 0A999	
	7906150023 7906180132 7906010283 7906010291 7906210010	50-313 50-267 50-274 50-274 50-285	G G G			7906190052 7906210406 7906050168 7906210401 7906290591	GA999 GA999 GA999 GA999 GA999	
	7906260186 7906260180	50-298 50-298	G G			7906290576	9A777	
	7906040149 7906180148	50-313	Q 8			7906290630 7906290621 7906120028	9A777 9A779 9A777	
	7906180146 7906180145 7906180140 7906270038	50-285 50-278 50-313 50-320	8 8 9			7906180238 7906120022 7906290251 7906290219 7906290662 7906230036	QA999 QA999 QA999 QA999 QA999	
(	7906180198 7906180196 7906180202 7906180192 7906250041	50-285 50-298 50-267 50-313 50-267	8 8 8 8			7904040070 7904040032 7904010103 7904040044 7904050159	QA999 GA999 GA999 GA999 GA999 GA999	
	7906260330 7906230075 7906260330 7906250115 7906180301	50-313 50-348 50-313 50-278 50-267	9 9 9 8			7906050165 7906050186 7906070019 7906190030 7906190039	GA777 GA777 GA777 GA777 GA777	
Region 4. Dallas, Vendor Inspection Proch	7906180297 7906180293 7906180291 7906230068	50-285 50-278 50-313 GA999	8 8 8			7704190080 7906220210 7906230025 7906290363	QA979 QA979 QA999 QA999	
	7906210344 7906060101 7906210335 7906290282 7906290268	GA999 GA999 GA999 GA999 GA999				7906290614 7906290238 7906290633 7906290676 7906290200 7906290223	GA779 GA779 GA779 GA779 GA779 GA779	
	7906180670 7906180663 7906180666 7906210322 7906210312	GA799 GA799 GA799 GA799 GA799		Region 3: Director	San Francisco, Office of the	7906260547 7906150357 7906130359	50-312 q 50-141 q 50-320 P	
	7906290690 7906290707 7906180263 7906290682 7906180231	GA999 GA999 GA999 GA999 GA999				7906290263 7906290184 7906290071 7906290543 7906200141	50-312 0 50-312 0 50-312 0 50-312 0 50-204 0	
	7906070025 7906070026	GA999 GA999				7906200144 7906200149	50-206 G	
	7906010114 7906010110	QA999 QA999				7906290120 7906140213		
	7906010112 7906050204	GA999 GA999				7		
	7906050208 7906290236 7906070023	QA999 QA999 QA999						
	7906070031 7906030198 7906070028 7906180634 7906210326	GA999 GA999 GA999 GA999 GA999						
	7906060053 7906060059 7906060108 7906060115 7906230073	GA777 GA777 GA777 GA777 GA777						
	7906060032 7906060080 7906060104 7906220216 7906220222	GA999 GA999 GA999 GA999						
	7706230052 7706230069 7706230071 7706170067	QA799 QA799 QA799 QA799						

AUTHOR AFFILIATION	ACCEBBION NUMBER	BUBJECT CATEGORY	-	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOORY	
	7906120048 7906120051 7906120057	50-397 0	G G		7906080240 7906080226 7906080220 7906080222	50-528 Q 70-25 C 70-734 C 70-754 C	
	7906120043 7906180488 7906190020 7906180463 7906190020	50-397 0 50-70 0 50-27 0	9 9 9		7906080214 7906080222 7906080218 7906180280 7906180265	70-784 C 70-754 C 70-1257 C 50-397 B 50-133 B	
	7906190016 7906180436 7906180451 7906180458	50-94 6 50-106 6 50-113 6	3 3 3		7906180273 7906180265	50-20& \$	
	7906180479 7906180462		a G		7906180275 7906290376 7906180265	50-312 8 50-320 P 50-133 8	
	7906180484 7906190016 7906180442 7906180481	50-89 0 50-187 0	9 9 9 9		7906180268 7906180273 7906180280 7906180261 7906130054	50-344 8 50-206 8 50-397 8 50-528 8 50-397 0	
	7906180456 7906180443 7906180451 7906180479 7906180447	50-228 6 50-104 6 50-133 6 50-208 6	Q Q Q Q Q		7904180351 7904180342 7904180338 7904130047 7904180341	50-397 8 50-133 9 50-133 9 50-204 9	
	7906180484 7906180479 7906180450 7906180476 7906180432	50-133 6 50-326 6 50-344 6 50-360 6	a a a a		7906130041 7906180338 7906130033 7906180347 7906130041	50-275 0 50-133 8 50-312 0 50-312 8 50-275 0	
	7706180481 7706180436 7706180467 7706180488 7706180489	50-94 0 50-394 0 50-397 0 50-433 0	3 3 3 3		7906180338 7906130045 7906180340 7906130051 7906180341	50-133 8 50-344 0 50-344 8 50-361 0 50-206 8	
	7906180488 7906180472 7906180436 7906190016 7906190020	50-528 6 50-74 6 50-89 6 50-70 6	a a a a a		7906130051 7906180341 7906130054 7906130054 7906130054	50-361 G 50-206 B 50-397 G 50-397 B 50-397 G	
	7906190432 7906190020 7906190439 7906110070 7906110075	50-70 6 70-1257 6 50-133 6	9 9 9 9 9		7906180351 7906130054 7906180351 7906130054 7906180351	50-397 8 50-397 0 50-397 8 50-397 0 50-397 8	
	7906110077 7906110073 7906180231 7906180219 7906180225	50-344 0 50-397 8 50-133 8 50-206 8	8		7906130054 7906180351 7906180335 7906180335 7906130037	50-397 Q 50-397 8 50-528 Q 50-528 8 50-528 Q	
	7906180219 7906180228 7906180219	50-312 E	3 8 9		7906180335	50-528 8	
	7906180221 7906180225 7906180231 7906180213	50-206 E 50-397 E	8 5 9		7906130037 7906180335 7906200061 7906200036	50-528 G 50-528 S 50-397 G 50-206 G	
	7704080245 7704080239 7704080214 7704080219	50-397 ( 50-27 ( 50-70 (	G G G		7906200038 7906200034 7906200036 7906200061 7906200049	50-312 G 50-344 G 50-206 G 50-397 G 50-528 G	
	7906080224 7906080228 7906080232 7906080241	50-106 50-113 50-133	a a a		7906180371 7906180364 7906180368 7906180364	50-397 8 50-133 8 50-206 8 50-133 8	
	7906080238 7906080236 7906080219 7906080223 7906080243	50-142 50-89 50-187 50-206	0 0 0		7906180370 7906180364 7906180365 7906180368 7906180371	50-312 E 50-133 E 50-344 E 50-206 E 50-397 E 50-328 E	
	7906080233 7906080215 7906080228 7906080221 7906080230	50-228 50-106 50-133 50-288	Q Q Q Q		7906180361 7906180373 7906180374 7906180374 7906180374	50-133 Q 50-275 Q 50-312 Q 50-275 Q	
	7906080244 7906080241 7906080234 7906080242 7906080213	50~133 50~326 50~344	a a a a	Region 5, Gan Francisco, Reactor Construction & Engineering Support S	7706150063 ranch 7706150079 770615005B 7706150063	50-397 G 50-397 G 50-397 G 50-397 G	
	7906080243 7906080224 7906080227 7906080225 7906080237	50-94 50-394 50-397 50-433	a a a a		7906150079 7906150058 7906150063 7906150079 7906150058	50-397 Q 50-397 Q 50-397 Q 50-397 Q 50-397 Q	
	7906080245	50-397	a		7906150063	50-397 9	

AUTHOR AFFILIATION	ACCEBBION NUMBER	GUBJECT CATEODRY	_	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEÇT CATEGORY
	7906130079 7906140210 7906140215 7906140210 7906140215	50-361 (	1 9 9 9		7906210281 7906250049 7906250069 7906010009 7906210120	50-201 H 50-201 P 50-201 P PROJ 70-2623 C
	7906260525 7906210342 7906210347 7906210342	50-361 50-361 50-361	G G G G		7906220471 7906210250 7906230176 7906250485 7906250489	50-201 H 70-364 C 70-364 C 50-201 P 50-201 P
	7906210347 7906260320 7906150090 7906150355	50-508 50-397	G G G	Radioisotopes Licensing Branch (Pre /90501)	7906260638 7906210129 7906290733 7906290738	70-1113 C 50-201 P 70-687 C 70-687 C
& Materials Safety Branch	7906150357		Q.		7906140123	40-4492 C
	7906010250 7906290646 7906290656 7906260547	70-734 70-734	a c c	Transportation Branch	7904040358 7904190488 790414075 7904190485 7906190495	AD-B681 C 71-47 C 71-47 C 71-47 C 71-47 C
Opprátions Nuclear Bupport Branch	7906260526 7906200462	50-312 50-320	Q P		7906050379 7906050385 7906050390 7906070014	71-9126 C 71-9126 C 71-9126 C 71-9128 C
	7906200149 7906140190 7906250445	50-312	Q Q Q		7906070017	71-9128 C
	7906250449 7906260543 7906260531	50-394 50-312 50-312	G G		7906070020 7906140015 7906140019 7906190479 7906010329	71-9128 C 71-4949 C 71-9117 C 71-47 C 71-5942 C
	7906250472 7906250453 7906250442 7906250438	50-204 50-206 50-73 50-73	Q Q Q		7906030411 7906070039 7906080083	71-279 C 71-96 C 71-190 C
Region 5: San Francisco, Safaguards Stanch	7906140031		C		7906180687 7906010097	71-195 C 71-56 C
	7906180157 7906010164 7906160042 7906160045	70-1738 50-326 50-275 70-2217	c a c		7906010101 7906010093 7906010095 7906050027	71-36 C 71-90 C 71-90 C 71-202 C 71-202 C
	7906290641 7906290632	70-754 70-734	C C		7906050029 7906180795	71-275 C
Office of 18E, Executive Officer for Management & Analysis Office of 1 % C Executive Officer for Operations Support	7906210186	50-320 50-320	P P		7906010187 7906010149 7906010154 7906010145	71-115 C 71-174 C 71-174 C 71-207 C
Office of Nuclear Material Safety & Safeguards	7906130405 7906250248	50-320 XPORTLIC			7906010147 7906140659	71-207 C 71-310 C
	7906020083 7906050362 7906060016 7906050128	COMMIBBI 50-201 XPORTLIC 40-8681	P :		7906180153 7906070253 7906070260 7906210412	71-4949 C 71-5926 C 71-5926 C 71-325 C
Division of Fuel Cycle & Material Bafety	7906290197 7906010324 7906230005 7905070052 7906120009	NUREQ 40-1341 70-143 50-320 50-320	C C P P		7906130469 79060" 79061 7904	71-6574 C
Fuet Process, & Fab. Branch	7906010335 7906010220 7906220123 7906250046 7906040375	PROJ 70-698 70-27 70-820 40-8027	C C C		;	
	7906220155 7906250457 7906220128 7906220134 7906220027	70-820 70-824 70-33 70-33 70-1100	C C C C			
	7906220030 7906220113 7906250143 7906270024 7906270026	70-1100 70-1201 70-1201 70-1359 70-1359	G C			
	7906220142 7906270004 7906150140 7906230179 7906230038	50-201 70-708 40-299 50-201 70-1308	H			
	7906260625 7906260627 7906270033 7906290745 7906290777	70-143 70-33 70-143 70-143 40-3372	C C C C			
Fuel Reprocess & Recycle Branch	7906270037 7906270030 7906290818 7906230182 7906040098	70-36 70-1151 70-1201 70-1193 70-2623	C			

AUTHOR ' AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGR		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC	
Assistant Director for Waste Hanagement (Pre 790501)		71-208 71-208 71-5805 71-5805 40-8502	c c c c c		7706260519 7706210231 7706210270 7706010277 7706070013 7706020248	50-346 50-320 50-320 50-275 50-237 50-250	P P H P P
Low Level Waste Branch (Pre 790501) Division of Safeguards	7906150148 7906230065 7906180722 7906280019 7906280004	40-7455 70-25 NUREO 50-320 50-320	C C P P		7706260058 7706050151 7706050037 7706040398 7706020220	50-320 50-59 50-237 SECY NUREO	P P
Haterial Control Licensing Branch	7906050237 7906010183 7906040115 7906040386 7906040066	70-1151 70-820 70-1151 70-734 70-143	c c c c		7906210376 7906280242 7906110408 7906130062 7906280173	NUREO 50-320 50-280 50-282 50-320	P U P P
	7906040071 7906040075 7906040044 7906010080 7906050102	70-371 70-1113 70-1151 70-371 70-364	C C C C		7706110408 7706010216 7706020235 7706270701 7706020125	50-280 ORG 50-72 50-220 50-280	V Р Н
	7906200307 7906250005 7906250011 7906250001 7906250002	70-1201 70-36 70-36 70-1100 70-1100	C C C C		7906020130 7906020125 7906020130 7906290701 7906020125	50-280 50-280 50-280 50-220 50-280	P P H P
	7706210070 7906290788 7906290741 7906260570 7906260572	70-1151 70-143 70-143 70-143 70-1201	C C C		7904020130 7906290701 7906040042 7906230047 7906120087	50-280 50-220 50-443 50-280 0R0	P H O H
Physical Security Licensing Branch	7906290796 7906290207 7905240706 7906040380 7906220441	70-734 70-371 70-1426 70-8 70-143	G G G G		7906120090 7906280033 7906210102 7906220491 7906270088	ORO 50-352 50-250 50-275 50-320	Á P O
Assistant Director for Operations & Evaluations High Level Waste Licensing Management	7906220444 7906010227 7906040064 7906280022 7906230160	70-734 70-143 70-1308 50-320 WASTE MQ	C C C P		7906220491 7906180395 7906270088 7906210418 7906230101	50-275 50-352 50-320 50-280 50-309	Q H Q H ₽
Branch Uranium Recovery Licensing Branch	7906150230 7906110030 7906110193 7906010295 7906010293	WASTE MG WASTE MG WASTE MG 40-8452 40-4492	T T		7906210418 7906200466 7906270008 7906270020 7906270033	50-280 50-522 50-280 50-280 50-280	H H H
	7906050387 7906180786 7906020214 7906150262 7906130509	40-8722 40-8452 PROJ	c c		7906270053 7906270060 7906270069 7906270076 7906270080	50-280 50-280 50-280 50-280 50-280	H H H
	7906180404 7906040432 7906260634 7906290799 7906180674	40-8681 40-6639 40-8584 40-4492 40-8681	C C C C		7906270087 7906270098 7906270109 7906270119 7906270124	50-280 50-280 50-280 50-280 50-280	H H H
	7906180677	40-8681	В		7906270132 7906270143 7906270151 7906270263 7906270265	50-280 50-280 50-280 50-280 50-260	H H H
Uffice of Nuclear Reactor Regulation	7906250304 7906010179 7906010125 7906070188 7904100012	50-599 FOIA FOIA FOIA 50-320	F		7906270267 7906270008 7906270020 7906270035 7906270053	50-280 50-280 50-280 50-280 50-280	H H H
	7906250211 7903210496 7903300226 7906230154 7906060118	30-374 NUREQ 30-230 50-245 50-334	A U P P		7906270060 7906270069 7906270076 7906270080 7906270087	50-280 50-280 50-280 50-280 50-280	H H H
	7906060120 7903300582 7906060136 7906060242 7906130356	FOIA NUREQ FOIA 50-320 FOIA	Р		7706270075 7706270107 7706270119 7706270124 7706270132	50-280 50-280 50-280 50-280 50-280	H H H H
	7906040144 7906120136 7906070030 7906070007 7906070001	50-320 RE8 50-320 50-10 50-320	V Р И Н		7906270143 7906270151 7906270263 7906270265 7906270267	50-280 50-280 50-280 50-280 50-280	H H H H
	7906130452 7906130026 7904270234 7906070054	50-320 50-280 50-320 50-320	О Р Р		7906270008 7906270020 7906270035 7906270053	50-260 50-260 50-260 50-260	H H H

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEGORY	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOGRY
	7906270060 7906270069 7906270076 7906270080 7906270087	50-260 H 50-260 H 50-260 H 50-260 H 50-260 H		7906270019 7906290016 7906290138 7906210388 7906060254	50-320 H 50-320 H 50-320 H 50-305 P 50-320 H
	7906270095 7906270109 7906270119 7906270124 7906270132	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906050176 7906180765 7906280176 7906050176 7906050162	50-568 D NUREQ 50-320 P 50-568 D 50-568 D
	7906270143 7906270151 7906270263 7906270265 7906270267	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906030176 7906030162 7906030176 7906220073 7906220093	50-568 D 50-568 D 50-368 D 50-320 P 50-320 F
	7906270008 7906270020 7906270033 7906270053	50-280 H 50-280 H 50-280 H 50-280 H		7906260278 7906260282 7906260097 7906260278 7906260282	50-424 0 50-424 0 50-424 0 50-424 0 50-424 0
	7906270060 7906270069 7906270076 7906270080 7906270087	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H	Antitrust & Indemnity Group	7906280097 7906290177 7906010206 7906290816 7906150343	50-424 Q 50-320 J 50-294 J 50-443 M 50-112 J
	7904270095 7904270109 7904270119 7904270124 7906270132	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H	Program Support Branch	7906190371 7906200455 7906250062 7906250243 7906290832	30-129 J 50-151 J XPGRTLIC XPGRTLIC 50-574 A
	7906270143 7906270151	50-280 H 50-280 H	Technical & Administrative Support Branch	7905040321	50-320 P
	7906270263 7906270265 7906270267 7906270008	50-280 H 50-280 H 50-280 H 50-280 H	Division of Site Safety & Environmental Analysis	7905040635 7905070029 7906290083	50-320 P 50-320 P NUREO
	7906270020 7906270035	50-280 H		7906070334 7906130441	FDIA 50-320 P
	7906270053 7906270060 7906270069 7906270076	50-280 H 50-280 H 50-280 H 50-280 H		7906250316 7906130457 7906070065 7906050216	50-320 P 50-320 P 50-443 H NUREG
	7906270080 7906270087 7906270095 7906270109 7906270119	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906130392 7906040068 7906220186 7905290343 7906290244	50-320 P 50-466 G FOIA NUREO 50-320 P
	7906270124 7906270132 7906270143 7906270151 7906270263	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H	Assistant Director for Site Analysis Accident Analysis Branch	7906290498 7906260204 7906280138 7906280145 7906130390	NUREG 50-320 F 50-320 U 50-320 P 50-320 P
	7906270265 7906270267 7906270008 7906270020 7906270035	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H	Effluent Treatment Systems Branch	7906130331 7906200022 7906220162 7906260496 7906280134	50-320 P 50-320 P 50-320 P 50-320 P 50-320 P
	7906270053 7906270060 7906270069 7906270076 7906270080	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906280123 7906290051 7906290296 7906290286	50-320 P 50-320 P 50-320 P 50-320 P
	7906270087 7906270095 7906270109 7906270119 7906270124	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906280216 7906210136 7906280218 7906280231 7906280227	50-320 P 50-320 P 50-320 P 50-320 P
	7906270132 7906270143 7906270151 7906270263 7906270265	50-280 H 50-280 H 50-280 H 50-280 H 50-280 H		7906220205 7906220195 7906210172 7906210253 7906290249	
	7906270267 7705270347 7706210433 7906250133 7906210433	50-280 H NUREO 50-280 H 50-307 P 50-280 H	Environmental Projects Branch 1	7906050145 7906190408 7906070358 7906120006	
	7906260141 7906260324 7906290821 7906260077 7906290821	50-278 P 50-320 P 50-280 H 50-307 G 50-280 H			
	7906260492 7906260522 7906260528 7906270006 7906270009	50-320 H 50-320 H 50-320 H 50-320 H			

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	łΥ	AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT ROOSTAD	?Y
Environmental Projects Branch 2	7906050158 7906210383 7906290216 7906010274 7906180785	50-548 50-548 50-548 50-574 50-404	D A D D		7906190160 7906190134 7906190139 7906190145 7906190160	50~259 50~259 50~259 50~259 50~259	PPPP
veosciences Branch	7906010083 7906040372 7906040003 7906040003 7906290853 7906290199 7906210301	PROJ 50-471 50-471 50-596 50-388 50-361	A D A P		7906250094 7906250098 7906250094 7906250099 7906250103 7906250088	50-259 50-259 50-259 50-259 50-259 50-259	6 6 6
GOOGLERGES BEEREN	7906130376 7906140545 7906180733 7906290657	50-320 50-400 50-553 50-566	P A A A		7906250094 7906250099 7906250103 7906250088	50-259 50-259 50-259 50-259	P P P
Hydrology Meteorology Branch Environmental Specialists Branch	7906270636 7906210269 7906270006 7906270110	50-423 50-320 50-320 50-320	A P R P		7906250094 7906250099 7906250103 7906250300	50-259 50-259 50-259 50-293	P P Q
Division of Operating Reactors	7903120401 7906220237 7906130481 7904270001 7906040392	GEN TEC 50-320 50-320 50-320 GEN TEC	0 P P		7906250201 7906250201 7906250377 7906250380 7906250384	50-293 50-324 50-333 50-333 50-333	P P P
	7906230135 7906060191 7906130394 7906060128 7906010211	50-320 50-320 50-320 50-309 ORG	U P H		7906250388 7906290665 7906290670 7906290677	50-333 50-277 50-277 50-277	P P P
Assistant Director for Engineers &	7906290709 7906220103 7906290854 7906120002 7906180348	50-280 50-320 50-312 50-320 GEN TEG	Р Н Р		7906290645 7906290645 7906290670	50-277 50-277 50-277 50-277	P P P
Projects (Pre 790623)	7906250100 7906250107 7906220226	50-320 50-320 50-320	P P	Operating Reactors Branch 4 (Pre	7906290700 7906260126 7906260133 7906260148 7903210263	50-277 50-278 50-278 50-278 50-289	P P P
Engineering Branch	7906050150 7906020233 7906260252 7905220068	50-59 50-72 50-271 ORO	P P	790625)	7906050094 7906050097 7906050146 7906050152	50-313 50-313 50-59 50-59	P P P
Operating Reactors Branch 3 (Pre 790625)	7906250037 7906260297 7906260304 7906250029	GEN TEC 50-320 50-320 50-220	0 0 P		7906040033 7906180571 7906160052 7906180140 7906020230	50-295 50-302 50-309 50-313 50-72	5 5 5
	7906250032 7906250036 7906250040 7906210327	50-220 50-220 50-220 50-271	P P P		7906020236 7906160054 7906160049 7906160014	50-72 50-344 50-312 50-346	P P P
	7706210345 7706210349 7706210353 7706040053	50-271 50-271 50-271 50-260 50-271	P P P		7906140176 7906250156 7906250162 7906230082	50-313 50-302 50-302 50-336	P P P
	7906020171 7906050147 7906110032 7906140324	50-331 50-324 50-333 50-298	P P P		7906270257 7906270258 7906270259 7906270261	50-336 50-336 50-336 50-336	P P P
	7906140539 7906050109 7906070396 7906070391 7906070400	50-331 50-333 50-324 50-324 50-324	P P P	,	7906230054 7906220076 7906250054 7906290028 7906200296	50-134 50-313 50-346 50-346 50-289	P P S
	7906070404 7906070386 7906070391 7906070400	50-324 50-324 50-324 50-324	የ የ የ		7706250152 7706110443 7706270033 7706270660	50-267 50-313 50-336 50-265	P P P
	7906250074 7906250074 7906250079 7906250083 7906250074	50-324 50-277 50-277 50-277 50-277	P P P		7906270274 7906290292 7906290300 7906290304 7906290308	50-302 50-313 50-313 50-313 50-313	PPP
	7906250079 7906250083 7906190139 7906190134	50-277 50-277 50-259 50-259	P P P		7906230151 7906290019 7906200323 7906180348	50-317 50-245 50-387 GEN TEC	р А 18
	7906190139 7906190145 7906190160 7906190134 7906190139	50-259 50-259 50-259 50-259 50-259	P P P P	ag ,	7905250074 7904260513 7906070010 7906290307	PR 50-320 50-237 50-320	P P
·	7906190145	50-259	è	•	7906020182	50-301	Q

AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJECT CATEOR	łY	AUTHOR AFFILIATION	AGCESSION NUMBER	CATEOC	
	7904020180 7904250332 7904250333 7904250332	0EN TEC 50-280 50-280 50-280	18 P P		7906250334 7906260110 7906250331 7906250334	50-260 50-260 50-260 50-260	P P P
	7906250333 7906260222	50-280 FOIA	P		7906260110	50-280	P
	7906270046 7906260286	50-10 50-320	P P		7906200317 7906200321 7906250317	50-305 50-305 50-338	P P
	7906270040 7906250039	50-320 50-280	P		7906250180 7906250187	50-348 50-348	P
	7906250070 7906070161 7906290018	50-334 50-320 50-245	P P P		7706230325 7706250326 7706250327 7706250328	50-320 50-320 50-320 50-320	<u>ե</u> Ե
Plant Systems Branch	7906210187 7904210301 7906070001 7906040400 7906040405	50-320 50-500 50-320 50-317 50-317	P A H P P		7906250194 7906260107 7906250325 7906250326 7906250328	50-280 50-280 50-320 50-320 50-320	6 6 6
	7906040400 7906040405 7906120094 7906120101 7906120094	50-317 50-317 50-282 50-282 50-282	P P P		7906250325 7906250326 7906250327 7906250328 7906250033	50-320 50-320 50-320 50-320 50-247	ቴቴቴ ቴ
	7906120101 7906290192 7906290642 7906070157 7906070077	50-282 0EN TEC 50-280 50-320 50-329	P 18 P P A	,	7906210101 7906250033 7906260092 7906250028 7906200330	50-250 50-247 50-305 50-255 50-266	4 4 4
Operating Reactors Branch 1 (Pre 190823)	7906250351 7904130312	50-280 50-334	P		790625003B 7906200330	50-266 50-262	۶ P
	7906200359 7906200365 7906200359	50-275 50-275 50-275	P P		7406250141 7406250038 7406260176	50-305 50-282 50-334	P P
	7906200565 7906050419 7906200303 7906010288 7906200298	50-275 50-3 50-344 50-334 50-261	P P F P		7905260179 7905250056 7906110441 7906250090 7906260190	50-348 50-266 50-247 50-247 50-261	6 6 6
	7706200300 7706020246 7706020247 7706020249 7706020246	50-261 50-250 50-250 50-250 50-250	P P P		7906110446 7906250090 7906260193 7906290559 7906290540	50-280 50-247 50-344 50-290 50-250	6 6 6 6
	7906020247 7906020249 7906180782 7906180790 7906180782	50-250 50-250 50-295 50-295 50-295	ե Ե Ե	Operating Reactors Branch 2 (Pre	7906290550 7906250260 7906250196 7906040484	50-934 50-948 50-272 50-206	р Р Р
	7906180790	50-295	P	790625)	7904020166	50-245	þ
	7906020205 7906040126 7906040130 7906040133	50-250 50-261 50-261 50-261	F P P		7906070301 8000703097 8000703097 8200404097	50-237 50-237 50-237 50-409	թ 6
	7906050416 7906010100 7906130157 7806130057	50-344 50-348 50-261 50-282	P P		7906030450 7906050233 7906260087 7906080227	50-155 50-204 50-244 50-235	Q P P
	7906130061 7906130066 7906130057	50-282 50-282	P P		7906030231 7906130312	50-409 50-409	b b
	7906130061 7906130066	50-292 50-292	P P		7906190017 7906070385 7906020135 7906050224	50-407 50-10 50-235 50-213	ρ F P
	7906290312 7906290080 7906290088 7906290092 7906290100	50-266 50-315 50-315 50-315 50-315	P P P		7904010223 7904010235 7904250185 7904050058	50-219 50-10 50-213 50-244	P P
	7906290080 7906290088 7906290092 7906290100 7906250391	50-315 50-315 50-315 50-315 50-250	р Р Р		7906250031 7906250035 7906210368 7906210371	50-255 50-255 50-409 50-409	P P F
	7906280395 7906250401 7906280403	50-250 50-250 50-250	P P		7906210976 7906290702 7906200272	50-409 50-29 50-213	F P
	7906250391 7906250395 7906250401	50-250 50-250 50-250	P P		7906290320 7906280263 7906290634 7906290639	50-219 50-237 50-409 50-409	P P P
	7706250403 7706250403 7706210378 7706210385 7706210393	50-305 50-305 50-305	P P P		7906290630 7906290024 7906290012	50-407 50-29 50-245	P P
	7906250331	50-2 <del>9</del> 0	P		7904230152 7904230152	50-245 50-245	P

AUTHOR AFFILIATION	ACCESS ION NUMBER	NUMBER CATEGORY		AUTHOR AFFILIATION	ACCESSION NUMBER	SUBJEC CATEOO	
Reactor Safety Branch	7906290645 7904170494	50-409 TOPREP	ρ		7904250113 7904250081	50-275 50-358	Â
Bystematic Evaluation Programs Branch (Pre 790625)	7906200097 7906200280 7906290754	50-320 50-320 TOPREP	P	Light Water Reactors Branch 2	7706230160 7706230143 7906040356 7906040070	50-275 TOPREP 50-361 50-599	A F A
Division of Project Management	7706080008 7706130451 7706180627 7706180637 7706180631	50-10 50-320 50-320 50-320 50-320	0 0 0		7704180102 7704180101 7704010245 7704110448 7704120124 7704200520	50-389 50-389 50-566 50-392 50-395 50-338	A A A A A
	7906070401 7906270098 7906070401 7906270098 7906060013	50-275 50-320 50-275 50-320 50-460	H G H		7706120133 7706250319 7706250206 7706250059 7706250078	50-382 50-445 50-361 50-361 50-361	A A A A
	7906270145 7906260216 7906020118 7906140329 7906270084	50-320 50-339 50-275 50-275 50-320	0 4 9 11 0		7906250059 7906250078 7906230084 7906250323 7906250264	50-361 50-361 50-392 50-445 50-518	A A A
-	7906020118 7906140329 7906010168 7906010169 7906270101	50-275 50-275 50-495 50-495 50-320	H A A		7906250314 7906230163 7906250063 7906250303 7906250322	50-361 50-445 50-437 50-599 50-369	A A A A
	7906270137 7906250101 7906270032 7906270140 7906270032	50-320 50-307 50-320 50-320 50-320	G P G G	Light Water Reactors Branch 3	7906070313 7906070321 7906070325 7906070313 7906070321	50-338 50-338 50-338 50-338 50-338	P P P
	7906270140 7906270149 7906250101 7906020207 7906270126	50-320 50-320 50-309 50-400 50-320	G P A G		7906070325 7906010241 7906060020 7906140225 7906070409	50-338 50-594 50-339 50-311 50-373	P A A A
	7906270131 7906270133 7906270131 7906020207 7906270134	50-320 50-320 50-320 50-400 50-320	G P G A		7906180195 7906110414 7906130504 7906190003 7906200319	50-423 50-498 50-387 50-568 50-528	A A I A
	7906290335 7906190123 7906270170 7906290355 7906190123	50-320 50-275 50-320 50-320 50-275	e H P Q		7906200326 7906150105 7906180781 7906180767	50-592 50-387 50-400 50-338	I A A P
	7906250091 7906070053 7906070055 7906070056	50-309 50-320 50-320 50-320	0 0 H		7906180781 7906230162 7906290851 7906250315 7906250075	50-400 50-387 50-596 50-387 50-498	A
	7906070061 7906230091 7906270120 7906270103 7906270120	50-320 50-307 50-320 50-320	D P G	Light Water Reactors Branch 4	7906290841 7906250190 7906290755 7906140623 7906040214	50-338 50-478 50-387 50-329 TOPREP	P A F A
	7906270075 7906270136 7906070062 7906270071 7906110018	50-320 50-320 50-320 50-320	b 0 b 0		7906020085 7906190001 7906060007 7906270034 7906290156	50-322 50-322 50-390 50-320 50-454	* * * * *
	7906110025 7906110028 7906110035 7906110052 7906270015	50-320 50-320 50-320 50-320 50-320	0 0 0 P		7906290626 7906290156 7906270002 7906280016 7906270025	50-329 50-454 50-320 50-370 50-320	* **
Assistant Director for Light Water Reactors	7906230145	TOPREP 50-338	p		7906270271 7906260267	50-397 50-327	A
	7906010039 7906050067 7906010039	50-275 50-320 50-275	P	Assistant Director for Quelity Assurance & Operations Operator Licensing Branch	7906250114 7906270188	50-309 50-320	P
Light Water Reactors Branch 1	7906020242 7906130140 7906180172 7906230125 7906040419	50-338 50-322 50-275 50-346 TOPREP	Р О Н О	Quality Assurance Branch	7906140559 7906040139 7906250106 7906250112 7906220126	50-369 TOPREP 50-309 50-309 TOPREP	P P
	7906010314 7906080211	50-341 50-275	A	Assistant Director for Standard & Advanced Reactors	7906070192 7906270270	50-295 50-267	P
	7906270104 7906270097 7906200316	50-320 50-320 50-368	0 0 P	Advanced Reactors Branch	7906220433 7906050417	50-267 50-267	P P
	7906270097	50-320	0	Standardization Branch	7906270001 7906010171 7906270044	50-320 50-495 50-320	A
	7906250113 7906270078	50-275 50-320	ô		7906270022	50-320	۵

AUTHOR AFFILIATION	ACCESSION NUMBER	CATEGO	RY	AUTHOR AFFILIATION	ACCESSION NUMBER	CATEG	
	7906270187	50-320	P		7903300537	PR	
	7906210066	FOIA	•		7906070340	FOIA	
	7906270189	50-320	ps.		7906070348	FOIA	
Division of Bystems Safety	7906070007	50-320	P		7904020222	RECOD	
	7906290240	50-320	н		7906130179	RECOD	
	7906020168	50-320	₽		7906130180	RECOD	
	7906260318	50-320	P		7906200301	PR	
	7906230131 7906070126	50-320 50-320	U P		7906180748 7906290835	REGOD Regod	
	7906280043	50-320	E	Division of Engineering Standards	7906130075	PR	
Mechanical Engineering Branch	7906110096	50-311	Ä	attended to Language and a series as	7406230108	REGOD	
	7906200037	50-320	P		7906230106	RECOD	
Assistant Director for Plant Systems	7906290189	50-320	A		7906260483	NUREO	
·	7904050314	50-437	A	Reactor Systems Standards Branch	7905280045	50-320	8
	7904160286	50-329	E	Division of Siting, Health & Bafaguards	7906070195	FOTA	
	7904130347	50-327	Ą	Standards	2020224444	000	
	7904180077 7906190118	SO-382 GEN TEC	.A	Maddalanias Harlik Chandanda Basnah	7903200100 7906210067	089 50-320	P
	7906200076	50-320	P	Radiological Health Standards Branch	7905250222	DRQ	
Containment Systems Branch (Pre 790101)	7905240245	50-920	P	Safeguards Standards Branch	7906050048	NUREO	
Electric, Instrumentation & Control Systems Branch	7906290227	50-320	A	Office of Nuclear Regulatory Research	7906180729 7906010337	RES	
•	7904100243	50-327	A		7906260601	NUREO	_
	7904210346	50-329	۸		7906270063	50-320	ř
	7904160279	50-370	A	Administrative and Resource Control Staff	7906290326	50-320	-
	7906160051	TOPREP			7906270190	50-320	Р
Power Bystems Branch	7906040035	50-373	F		7906270139	50-320	è
Assistant Director for Reactor Safety	7906230177	50-466	Q	Program Coordination Branch	7906280003	50-320	è
	7906260166	50-568	Q	Probabilistic Analysis Branch	7906280010	50-320	P
	7906110017	50-488	G	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	7906280012	50-320	þ
	7906200073	50-320	P P		7906280014	50-320	ρ
	7906270142 7906280265	50-320	P		7906280009	50-320	P
	7700200400	20-380	•		7906280007	50-320	P
			_		7906260507	50-320	P
Analysis Branch	7706270148	50-320	₽		7906280003	50-320	P
	7906110405	TOPREP			7704260079	50~320	р
	7906110438 7906220157	TOPREP 50-320	ρ	Division of Bafeguards. Fuel Cycle &	/10020071	30-0#c	
Core Performance Branch	7905070088	50-320	þ	Environmental Research	7906280021	50-320	Ρ
OOI T TELLOTIMATICE BLATICIT	7703070000	30- GEO	F	Environmental Effects Research Branch	7906260018	50-320	P
Reactor Systems Branch	7905250210	50-285	Р	Division of Reactor Bafety Research	7906280048	REVIEW	
	7905230087	50-285	P	Red Trend mt Danesat amind Danamien	7906260234	REVIEW	
	7906270108	50-320	P				
	7906290170	50-320	P		7706260628	REVIEW	
	7906130388	50-320	P		7906070004	50-320	P
					7906260473	50-320	R
Division of Reactor Licensing (NRR-1975	7906280035 7906290233	20-350 20-350	A	Assistant Director for Advanced Reactor	7906210035 7906210121	80-320	ORP P
only) Office of Standards Development	7906270173	COMMISS	ON	Safaty Research			
	7906270177	COMMIRE			7906210125	50-320	P
	7906110313	COMMISS			7906210115	50-320	P
	7906070329	FOIA		Experimental Gas-Cooled Reactor Bafety	7906210121	50-320	P
	7906020227	10CFR		Research Branch Fuel Behavior Branch	7906210027	REVIEW	
	7906020231	10CFR		Metallurgy & Materials Branch	7906270172	50-320	P

,*		
To		
3i -		

#### REPORT NUMBER INDEX

The subject category column in this index gives the docket number and the symbol for the category of information within that docket; for example, 50-320 P. The docket subject categories are defined in Appendix A.

Subject categories for nondocketed items are also entered in this column by symbol; for example, ACRS. These categories are defined in Appendix B and listed in the Contents.

REPORT MANGER	ACCESSION NUMBER	BUBJECT CATEGORY	OTHER REPORT NUMBER	REPORT NUMBER	ACCESSION NUMBER	EUBJECT CATEGORY	OTHER REPORT NUMBER
E457	7906110173	50-437 A		SYEOO-RASO	7906020087	PROJ	UC-798
P36010337	7906010337	REB		IPS-409	7906150424	50-275 A	
906020110	7906020110	RES	CAAP-TR-046	NEDC-24137	7906040218	50-10 P	7BNED295
706020114	7906020114	REB					
956020115	7904020115	RES		NEDE-12610	7906200278	50-73 P	
100000000		•••		NEDE-12610	7906200282	50-73 P	
706020153	7906020153	REB	CDAP-TR-053	NEDE-12610	7906200286	50-73 P	
926040411	7906040441	RES	ORNL/ED/EI8-87	NEDE-12610	7906200289	50-73 P	
936040413	7906040413	RES		NEDE-12610	7906200292	50-73 P	
P26050190	7906050180	RES					
936050279	7906050279	REB	TF8P-TR-315	NEDO-12724	7906150147	50-73 P	
				NEDO-21061	7706130238	TOPREP	
P06120138	7906120136	REB		NEDD-21061	7706130243	TOPREP	
1906140127	7906140127	RES	6390-66M-FJL SA	N€0D-214/1-2	7906060143	TOPREP	
1936180218	7906180218	REB	ORNL/CGD/INF-79	NEDO-24185	7906290600	50-220 P	79NED266
1906190230	7906180230	RES	ORNL/ED/EI8-89				
1936180729	7906180729	REB		NEDO-24612	7906110316	TOPREP	
				NUCON 610616/01	7906280143	50-320 P	
7936190049	7906190049	REB	ORNL/CED/INF-79	NUREQ-0020 V3 N4	7906010050	NUREO	
M06500908	7906200608	REB		NUREG-01/0 V1	7906270173	COMMISSION	
795200620	7906200620	RES		NUREQ-0170 V2	7906270177	COMMISSION	
F36210011	7906210011	REB		Mines and	20044002	W India	600-0477-1A
1906210015	7904210015	REB		NUREC-0246	7906180732	NUREO	CDG-2477-10
				NUREO-0278	7906010219	NUREO	
M36210020	7906210020	REE		NUREG-03JO	7903210496	NUREO	
7736210031	7906210031	RES		Beed-Darun	7906180765	NUREO	
N08220183	7906220183	REB		NUREQ-0380 V3 N3	7906050273	NUREO	
706220215	7906220215	REB	DRNL/NUREG/TM-3	hiidaa 0000 Ha H/	7001000111	Manera	
79362301:24	7906230124	REB	UMGK-NUREO-79-0	NUREQ-DERON NA	7906290616	NUREO	
				NUREG-0468	7906290083	NUREO	
7936230169	7906230169	REB		NUREQ-0482	7906020094	NUREO	
MOS2301/2	7906230172	REB		NUREQ-0525	7906180722 7906030162	NUREQ 50-568 D	
795230173	7906230173	REB		NUREQ-0529	\4000010X	50-568 D	
906250043	7906230043	REB				MARKA	
766250653	7906250053	REB		NUREQ-0540 V1 N4	7906290167	NUREQ	
				NUREO-0548	7906020143	NUREO	
M29590013	7904260013	REG		NUREO-0549	7906030176	50-548 D	
MC6260017	7906260017	REB		NUREQ-0554	7906260483 7905290349	MUREQ	
1906560055	7906260022	50-409 F		NUREQ-0555	7401340144	MINPL	
M39590453	7906260023	50-277	•	AULTONIA ART.			
1909560031	7906260031	RE8		NUREO-0556			
				NUREO-0561			
1936260037	7706260037	RES		NUREO-03/0			
7936260042	7904260042	RES		NUREO-75/087 13.1.2			
79%260574	7906260574	NUREO	8AND78-1373	NUREO/CP-0006			
79%260613	7906260613	REB		AHIDEO (68 -000)			
1439590950	7904260620	REB		NUREO/CR-0001			
				NUREO/CR-0220			
7906260623	7906260623	50-338	•	NUREO/CR-0263			
7726280001	7906280001	RES		NUREO/CR-0335 NUREO/CR-0421			
1936290176	7906290178	RES	ANAN WG ARK	MANEAL CU.AST			
7906290204	7906290204	REG	CDAP-TR-055	NUREQ/CR-0422 VB			
7906290250	7906290250	RES	LTR 20-99	NUREC/CR-0426 V2			
7936290265	7906290265	RES		NUREQ/CR-0465			
79%290278	790629027B	REG		NUREQ/CR-0507 V3 NUREQ/CR-0547			
1976290241	7906290291	RES		NUMER/CH-034/			
19762903 § E	7906290311	REB		NUMEO/CROSS			
1906290505	7906290505	REB		NUREQ/CR-0551 NUREQ/CR-0556			
				NUREO/CR-0558			
1956290542	7906290542	RES		NUREO/CR-U610			
MS [/ASM: N45, 2 5	7906230109	REGOD	_				
AL-TOP-LA	7904190245		P	NUREQ/CR-Q629			
JAN-10074A	7906230140	TOPREP	_	NUREQ/CR-0644			
IAV-1539	7906010229	50-320	P	NUREQ/CR-0648			
			_				
KQ-563-Y	7906210339		P	NUREQ/CR-0658			
IN68-505	7906200221	TOPREP		NUREO/CR-0678			
MP6-203	7906200227	TOPREP	_	NUREG/CR-0483			
CDE-SEE(H)-NP	7906040250		P	ARRIGO (AR. A.M.)			
XXE/EE8-4046-D VI	7904050284	WARTE MOT		NUREO/CR-0486 NUREO/CR-0489			
XE/E18-0044-0 V2	7904050288	WASTE HOT	10 707	NUREC/CR-0691 NUREC/CR-0692 VA			
199-50E-1:3244	7906020091	PROJ	UC-79E	MURCU/UNTUOTE YO			

#### REPORT NUMBER INDEX

REPORT NUMBER	ACCESSION NUMBER	SUBJECT CATEGORY	OTHER REPORT NUMBER	TROQER REEMUN	ACCESSION NUMBER	SUBJECT CATEGOR	
NUREG/CR-0694	7906180689	NUREG	8AND79-0535	8ECY-79-077A	7906230091	SECY	
NUREG/CR-0699 NUREG/CR-0704	7904050141 7904080107	NUREG NUREG	LA-7732-SR	SECY-79-114 SECY-79-1578	7906020227 7906060067	10CFR SECY	
NUREG/CR-0710	7906290673	NUREO	DRNL/NUREG/TH-3	SECY-79-200A	7904200002	SECY	
MUREG/CR-0712	7906180749	NUREQ	DPST-NUREO-76-1	SECY-79-233A	7906060071	SECY	
NUREG/CR-0713	7906180762	NUREG	DPST-NUREO-78-2	SECY-79-241	7906070101	SECY	
NUREG/CR-0714 NUREG/CR-0715	7906180770 7906180707	NUREG 50-295 P	DPST-NUREO 78-3	SECY-79-249A SECY-79-268A	7906180771 7906290604	SECY SECY	
NUREG/CR-0716	7906050277	NUREG	DRNL/NUREG/TM-3	SECY-79-280	7906180739	BECY	
NUREO/CR-0719	7906180422	TOPREP	CREARE TN-292	SECY-79-280A	7706230086	BECY	
NUREQ/CR-073B	7906180774	NUREQ	SAN079-0651	8ECY-79-282	7904180802	SECY	
NUREG/CR-0739	7906050110	NUREO	TREE-1299	SECY-79-284	7906020101	SECY	
NUREG/CR-0751	7906260605	NUREG	SAND79-0754	SECY-79-289	7906180754	SECY	
NUREQ/CR-0753	7906290487	NUREG	C-MT\QBRUN/JNRQ	SECY-79-297	7906010146	BECY	
NUREG/CR-0780	7906020244	NUREO		SECY-79-305	7906180116	BECY	
NUREQ/CR-0781	7906280011	NUREG	FRA-T7901	BECY-79-306	7904060078	BECT	
NUREG/CR-0786	7906050086	NUREO	TREE-1352	SECY-79-307	7906060076	SECY SECY	
NUREO/CR-0793	7906020195	NUREO		SECY-79-J08 SECY-79-310	7906180050 7906180615	SECY	
NUREG/CR-0796	7906180804	NUREO	PNL-2827	SECY-79-328	7906290496	SECY	
NUREO/CR-0797	7906020102 7906180757	NUREG		SECY-79-329	7706270531	BECY	
NUREO/CR-0823	1409180191	W NUKEO		and to 77 Car	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
NUREG/CR-0824	7906210325	NUREO	BM-2026	8ECY-A-7/-24	7906250482	SECY	
NUREG/CR-0825	7904180779	NUREO	BM1-2025	5ECY-A-79-30	7906110430	SECY	
OPE-21-5/9	7906260341	50-278 P	DRF-813-109-40	6ECY-A-74-31	7906080054	50-305	Q
RH-79-3-8F2	7906220374	50-259 R		6ECY-R-338	7906130184	BECY	
8ECY-77-539	7906010179	FOIA		UCRL-525/5	7906250487	50-201	P
SECY-77-361	7906010125	FOIA		WCAP-8986	7906040422	TOPREP	
8ECY-78-120A	E010E24097	SECY		WCAP-9529	7906210246	TOPREP	
SECY-78-415	7906110313	COMMISSION		YAEC-1149	7906120408	50-568	A
5ECY-79-014A	7906290714	SECY		YAEC-1175	7906120287	50-568	A

#### APPENDIX A

#### **DEFINITIONS OF DOCKET 50 CATEGORIES**

#### A. Application/Construction Stage Documents and Correspondence

This category follows the application from submission to the day preceding the issuance of an operating license. It includes all correspondence and documents with substantive technical content that do not fall into other specific categories. Included are:

- 1. Correspondence and documents relating to unresolved design and construction issues.
- 2. Meeting announcements and summaries of meeting discussions on issues of item 1.
- 3. Correspondence regarding Preliminary and Final Safety Analysis Reports.
- 4. NRC questions, requests for additional information, and applicant responses.
- 5. Applicant's Quality Assurance Manual.
- 6. Correspondence and documentation on generic technical matters highlighted by an event at another facility which may affect the subject facility; not covered by an IE Bulletin.
- 7. Federal Register notices that do not apply to other categories.
- 8. Information on laws and changes in regulations or policy that affect the status of the application (NEPA, Water Quality Improvement Act, Water Pollution Control Act, etc.).
- 9. Scheduling of license application submission or review.
- 10. Reports of site visits.
- 11. Backup technical documents (i.e., topical reports) submitted in support of the application.
- 12. Early site review information.
- 13. Construction Permit, amendments and correspondence relating to construction permit.
- 14. Environmental review information.
- 15. Construction permit.

#### B. Utility Preliminary Safety Analysis Report (PSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence is filed in Category A.

į

- 1. Preliminary Safety Analysis Report (PSAR) submitted by the utility.
- 2. Amendments and changes to the PSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt.
- 5. Hazards Summary Report submitted by utility (now designated PSAR).

- 6. Safety Analysis Report submitted by utility (now designated PSAR).
- 7. Certificates of Service of PSAR.

#### C. Utility Environmental Report (ER), Amendments and Correspondence

- 1. Environmental Report (ER) submitted by the utility.
- 2. Amendments and supplements to the ER.
- 3. Transmittal letters.
- 4. Information on scheduling of submittal or review of ER.
- 5. NRC questions, requests for additional information, and applicant responses.
- 6. Federal Register notice citing availability of items 1 and 2.
- 7. Correspondence relating to the review of ER.
- 8. Meeting announcements or reports of meetings where the primary subject of discussion is the ER.

### D. NRC Draft and Final Environmental (Impact) Statements (DES and FES), Supplements and Correspondence

- 1. Draft and Final Environmental (Impact) Statements (DES and FES).
- 2. Supplements to DES and FES.
- 3. Correspondence relating to the DES or FES.
- 4. Comments from other federal, state, and local government agencies.
- 5. Transmittal letters,
- 6. Documents related to NRC review of environmental issues or of ER obtained for purposes of writing the environmental statements.
- 7. Backup technical documents submitted in connection with above.
- 8. Notices of availability of above.
- 9. Draft of detailed statement.

#### E. NRC Safety Evaluation Report (SER), Supplements and Correspondence

- 1. Safety Evaluation Report (SER).
- 2. Supplements to SER.
- 3. Correspondence relating to SER.

- 4. Notices advising of the availability of 1 and 2.
- 5. Information on scheduling of SER submittals and review.
- 6. Requests for additional information for use in preparing SER; responses to such requests.
- 7. Meeting announcements or reports of meetings where the primary subject of discussion is the safety review or safety evaluation.
- 8. Transmittal letters.
- 9. Comments from other agencies relative to safety review.
- 10. NRC-AEC Hazard Analysis Reports (now designated SER).

#### F. Security, Medical, Emergency, and Fire-Protection Plans

All plans in this category are submitted separately. Information submitted for the PSAR or FSAR is excluded.

- 1. Correspondence relating to plans.
- 2. Supplements, changes, and revisions to plans.
- 3. Fire Hazard Protection Plan and Surveys.

#### G. Adjudicatory Correspondence

This category contains all documents on hearings, Atomic Safety and Licensing Board (ASLB) review, and opposition except word-for-word transcripts of ASLB hearings (Category T) and antitrust hearings (Category N).

- 1. ASLB hearing and review documents.
- 2. Correspondence to and from intervenors.
- 3. Correspondence to and from persons writing in opposition to the facility. Those writing for information or in support of the facility are in category H.
- 4. Board orders and decisions.
- 5. Requests to make appearances at hearings.
- 6. Transmittal of supporting documents (i.e., SER, FES) to the board.
- 7. Federal Register notices regarding hearings.
- 8. Requests for a hearing.
- 9. Petitions from participants (including petition for request for extension).
- 10. Corrections to transcripts.
- 11. Professional qualifications, if presented at a hearing.

- 12. Memorandums and orders authorizing issuance of license, changes, and other issuances by the Atomic Safety and Licensing Board.
- 13. Hearing index.

#### H. General correspondence

This category includes documents with little or no bearing on the status of the application or license. Items that have no substantive technical content or meaning for the status of the license or application are included.

- 1. Qualification statements of new employees.
- 2. Change of address notifications.
- 3. Changes in organization.
- 4. Changes in service lists, "Certificate of Service" documents (without a document attached).
- 5. NRC requests to applicant for additional copies of documents.
- 6. Correspondence from the public in support of or requesting information about the facility.
- 7. Letters of "concern" (NOT "opposition") and response thereto.
- 8. Correspondence on strictly administrative matters.
- 9. Correspondence regarding the local Public Document Room.
- 10. Memoranda to Public Document Room regarding withholding a document (unaccompanied by that document).
- 11. Press releases from applicant.
- 12. Any other material that fits the criteria given above.
- 13. Professional qualifications (resumes).

#### I. Financial Information

- 1. Company annual reports.
- 2. Separately submitted financial information and related correspondence.

#### J. Insurance and Idemnity Information

- 1. All correspondence and documentation regarding indemnity and insurance.
- 2. Endorsements to insurance policies.
- 3. NELPIA Nuclear Energy Liability Property Insurance information.

#### K. Utility Final Safety Analysis Report (FSAR) and Amendments

This category is strictly limited to the items listed below. All related correspondence falls in category A or P.

- 1. Final Safety Analysis Report (FSAR).
- 2. Amendments and changes to the FSAR.
- 3. Transmittal letters.
- 4. Letters acknowledging receipt of items.
- 5. Hazards Final Summary Report (now designated FSAR).
- 6. Certificates of Service of FSAR.

#### L. Limited Work Authorization and Related Correspondence

This category is limited to items issued before the construction permit is granted.

- 1. Limited Work Authorizations.
- 2. Environmental exemptions.
- 3. Correspondence relating to 1 and 2.
- 4. All information concerning site preparation prior to the issuance of a construction permit.

#### M. Antitrust Correspondence

- 1. All material concerning antitrust except hearing transcripts (category N)
- 2. All material marked with an A immediately following the docket number. The A signifies antitiust proceedings.

#### N. Antitrust Hearing Transcripts

This category contains only word-for-word transcripts of hearings in antitrust matters. In most cases they will be marked with an A following the docket number. Related correspondence falls in category M.

#### O. Advisory Committee on Reactor Safeguards (ACRS) Reports and Correspondence

- 1. Correspondence and letter reports relating to ACRS reviews
- 2. Correspondence from ACRS
- 3. Announcements of ACRS meetings

- 4. Transmittal letters to ACRS
- 5. ACRS reports.

#### P. Operating License Stage Documents and Correspondence

This file assumes the position of the application file for general technical items dated on or after the issuance of the operating license. It includes:

- 1. Operating license, amendments, proposed amendments, and changes.
- 2. Technical specifications and changes.
- 3. Announcements of issuance of 1 and 2.
- 4. Transmittal letters.
- 5. All general technical correspondence relating to technical specifications or operating license,
- 6. License conditions.
- 7. Operator licenses or administrative information bearing on the licensing of operators.
- 8. Meeting announcements or summaries of discussions where the main subject is technical specifications, operating license, or any technical issue arising after the issuance of the operating license.
- 9. Correspondence regarding codes (ASME), regulations, laws, or changes in policy that may affect plant operation or bear on the operating license.
- 10. Information on the Standard Review Plan (SRP).
- 11. Results of surveys or tests conducted in accordance with the technical specifications (NOT periodic reports, which fall in category R).
- 12. Requests for issuance of operating license.
- 13. Requests for copies of items 1 and 2 and responses.
- 14. Correspondence on generic technical issues.
- 15. Owner's group meeting announcements and reports.
- 16. Orders for modification of license.
- 17. Requests for extension date of license or license modification.
- 18. Quality assurance information.
- 19. Environmental matters (technical).
- 20. Emergency core cooling system.
- 21. Radioactive waste information.

#### Q. Inspection Reports, IE Bulletins and Correspondence

- 1. Inspection reports.
- 2. Bulletins and Circulars of NRC Office of Inspection and Enforcement (IE).
- 3. Responses by applicant to IE correspondence.
- 4. Applicant's determination of proprietary nature of inspection reports.
- 5. Letters concerning areas of noncompliance.
- 6. Any correspondence relating to inspection and enforcement that does not specifically relate to incidents as defined in category S.
- 7. In-service inspections.
- 8. Regulatory Operations (RO) Bulletins.

#### R. Periodic Operating Reports and Related Correspondence

This category includes periodic reports of a routine nature.

- 1. Monthly, semiannual, or annual reports (other than financial).
- 2. Periodic environmental monitoring, effluent testing, or similar reports.
- 3. Gray Book Information.
- 4. Operational Logbooks:

Logbooks on Environmental Data Logbooks of Radiological Data Operations Log on Plant Systems Core Plant Status Summary Sheets

5. Correspondence or other documents relating to the above listed Items.

#### S. Reportable Occurrences, LERs and Related Correspondence

This category contains all materials relating to abnormal, unusual, reportable, nonroutine, or 10 CFR 50.55e occurrences. This includes:

- 1. All 24-hour, 10-day, 30-day, interim, final, and followup reports on these events.
- 2. Other related documents.

NOTE: Also called licensee event reports, incident reports, etc.

#### T. Hearing Transcripts on Non-Antitrust Matters

This category contains word-for-word transcripts, corrections to the transcript, attachments and Vu-Graphs. Examples of non-antitrust matters include:

- 1. ASLB hearings.
- 2. Commission Meetings.
- 3. Commission Briefings.
- 4. Telephone conversations.

#### U. Congressional/Executive Correspondence

- 1. Testimony before Congress.
- 2. Preparatory and backup documents for Congressional testimony.
- 3. Letters to and from Congress and the Executive Branch.
- 4. Responses to letters from members of Congress and the Executive Branch.
- 5. Correspondence to and from the NRC Office of Congressional Affairs.

#### V. Operator Examinations

- 1. NRC Examination Results.
- 2. Power Plant Examination Summary Sheet.
- 3. Related correspondence.

#### APPENDIX B

#### DEFINITIONS OF NONDOCKETED CATEGORIES

#### 10CFR - Commission Meeting Records

This category contains documentation pertaining to open and closed Commission meetings. It includes:

- 1. Sunshine Act Federal Register notices.
- 2. Full, written explanation of closed meetings.
- 3. Certification of General Counsel on closed meetings.
- 4. Commission Determination Statements regarding the public disclosure of transcripts of Commission meetings.
- 5. Verbatim unofficial and official transcripts or portions of transcripts of open and closed Commission meetings made publicly available in accordance with provisions of 10CFR Part 9, the Sunshine Act, and Commission policies.
- 6. Enclosures to released transcripts, including applicable viewgraphs, staff papers, and staff correspondence.
- 7. Staff requirements memoranda for open meetings; memoranda to record; record of votes of Commissioners on items under consideration at meetings.

#### ACRS - Advisory Committee on Reactor Safeguards

This category contains documentation pertaining to the responsibilities of the Advisory Committee on Reactor Safeguards. ACRS serves as an independent advisory committee to the Commission in safety-related areas. The committee provides advice with respect to the hazards of new or existing nuclear facilities and the adequacy of related safety standards. The documents in this category are:

- 1. Verbatim transcripts of ACRS subcommittee and full committee meetings relating to facility license applications and safety-related matters.
- 2. ACRS meeting announcements; description of meeting agendas.
- 3. ACRS-generated reports, memoranda and correspondence that are publicly available.
- 4. ACRS consultant reports, comments and related correspondence.
- 5. ACRS and NRC technical correspondence pertaining to safety matters under review by the Advisory Committee on Reactor Safeguards.

#### AGREEMENT - State Agreements and Programs

This category contains records that pertain to the Commission's activities and interaction with State governments. Areas covered include: (1) the State Agreements Program, whereby States may assume certain of the NRC's regulatory authority over nuclear materials; (2) the Agency's role in assisting State and local governments in planning responses to radiological emergencies; and (3) a wide range of liaison and cooperative activities regarding such functions as licensing and siting. It includes:

- 1. Correspondence between and among NRC Office of State Programs and State officials, mostly State liaison officers, regarding.
  - a. cooperative programs in such technical areas as radiation control, emergency response planning to radiological incidents, water quality and transportation surveillance.
  - b. technical assistance to Agreement States in reviewing applications, compliance actions, developing regulations, and other areas.
- 2. Agendas, reports and transcripts of regional workshops and training programs on current matters of policy and regulations; i.e. decommissioning and facility siting.
- 3. State Legislative Reports.
- 4. Agreement State Licensing Statistics Reports.

NOTE: For specific uranium milling and mining projects in which the Agency is providing technical assistance to States, see the Projects category.

#### COMMISSION - NRC Commissioners

This category contains documentation pertaining to the daily conduct of Commission business in the Office of the Commissioners, including:

- Incoming and outgoing correspondence to and from the Commissioners relating to official NRC business, including reports and other enclosures.
- 2. Travel vouchers, telephone logs and official appointment calendars of individual Commissioners.
- Weekly Information Reports (SECY series number) prepared by the Executive Director for Operations (EDO) for the Commissioners, providing a summary of key events and items of interest undertaken by individual staff and program offices.

NOTE: For transcripts of Commission meetings, see 10CFR category. For all other staff papers with a SECY series designation prepared for Commission review, see SECY category.

#### CONTRACT - NRC Contracts and Modifications

This category contains documentation pertaining to AEC and NRC contracts and Interagency Agreements, including:

ace of request for proposal (RFP) and invitations for bid (IFB).

IFB) issued by the NRC.

act execution, specifying contract number, project title, contractor funding, and period of performance.

ts and contract modifications, if any.

#### mation Act Requests and Releases

lests for agency records and records released in accordance with the of Information Act (FOIA). Documents in this category include:

- 1. Requests made by any member of the public (assigned an identifying number YY-NNN for last two digits of the year—numerical sequence) for NRC records made in accordance with the provisions of the Freedom of Information Act.
- 2. Correspondence between the NRC and the requester relevant to the processing, appeal, denial or granting of an FOIA request.
- 3. Records or portions of records released in response to specific requests made under FOIA.

#### GEN TECH IS - Generic Technical Issues

This category contains records pertaining to unresolved safety issues of a generic nature that are being analyzed by the Division of Nuclear Reactor Regulation.

- 1. Draft reports of action plans to accomplish generic tasks in the regulatory program.
- 2. Correspondence with industry and internal correspondence regarding the methodologies, analyses, and programmatic and technical aspects of issues.
- 3. Meeting notifications and minutes.
- 4. Interim findings and status reports on generic tasks addressing related aspects of generic technical issues.

#### I&E - Inspection and Enforcement

This category contains bulletins, circulars and information notices that are issued by the Office of Inspection and Enforcement. These issuances describe particular events that occur at a facility that may require some follow-up action on the part of licensees. Also included in this category are preliminary notifications of events (PNOs).

- 1. I&E Circulars, which describe an event at a licensed facility and are informational in nature.
- 2. I&E Information Notices, which are similar to circulars but are preliminary in nature and issued shortly after an event has occurred.
- 3. I&E Bulletins, which describe an event at a licensed facility and request all recipients to perform certain actions as a result of this event.
- 4. Preliminary Notifications of Events (PNOs), which provide updated information of an event of safety or public interest significance.

NOTE: For letters forwarding the above issuances, utility responses to such issuances, and related correspondence, see Category Q of individual docket categories.

#### NUREG - NUREG Reports and Related Correspondence

These documents are formal reports issued by the U.S. Nuclear Regulatory Commission which carry the NUREG series code and correspondence pertaining to those reports. NUREG reports are accounts of work performed either by the NRC staff or by NRC contractors.

1. These reports are normally final work products and are characterized by the following criteria:

- a. They are predecisional documents which present information to be considered in Commission licensing and policy decisions.
- b. They present the results of Commission licensing and policy decisions.
- c. They present the results of technical research conducted for the Commission.
- 2. Correspondence from industry, government and interested members of the public commenting on reports or requesting clarification or interpretation.
- 3. Internal NRC memoranda summarizing meetings or discussions pertaining to the content of the reports.

#### ORG - Correspondence with Other Organizations

This category contains correspondence with professional organizations and associations; records other than Regulatory Guides that pertain to the activities of NRC's Office of Standards Development; and emergency petitions not assigned Petition for Rulemaking (PRM) numbers that request the Commission to take immediate action on some issue. Included are:

- 1. Meeting summaries and technical correspondence between NRC and professional associations and international bodies, such as the Atomic Industrial Forum and the International Atomic Energy Agency.
- 2. Correspondence between NRC's Office of Standards Development and other government agencies in which both parties have joint regulatory responsibility; e.g., EPA has authority to control all radioactive pollutants emitted into the air.
- 3. Internal memoranda, correspondence between NRC and Congress, and other technical correspondence dealing with the role and activities of the Office of Standards Development.
- 4. Statements, motions, orders and correspondence dealing with emergency petitions filed by parties on such topics as fire protection and re-analysis of the capacity of operating U.S. plants to withstand earthquakes.

NOTE: For Regulatory Guides and comments to Regulatory Guides issued by the NRC Office of Standards Development, see the REGGD category.

For petitions for rule makings filed by the public to amend, rescind or change an NRC regulation, see the PRM category.

#### PR - Proposed Rule

This category contains records dealing with NRC staff proposals to adopt, amend or repeal a Commission regulation. Proposed Rules (PRs) are normally the result of a Commission determination that sufficient grounds exist for it to proceed with a petition for change in an NRC regulation (PRM) filed by an outside party or person. The documents in this category are:

- 1. Federal Register notices stating the terms or substance of the proposed rule or a specification of the subject and issues involved.
- 2. Text of the Proposed Rule (PR).
- 3. Comments, statements, information, opinions or arguments on the proposed change to a part of the Code of Federal Regulations, Title 10.

4. Requests from the nuclear industry, organizations and other parties for written interpretations of the PR.

#### PRM - Petition for Rulemaking

This category contains records dealing with petitions filed with the Commission by an outside party to issue, amend or rescind an NRC regulation. Included are:

- 1. Petitions filed by any interested person or party to issue, amend or rescind an NRC regulation.
- 2. Federal Register cause notices of the filing of the petition.
- 3. Correspondence between NRC and the petitioner regarding the status and substance of the petition.
- 4. Comments from the nuclear industry, professional associations, public interest groups and others in favor of or in opposition to the PRM.

NOTE: For staff recommendations to the Commissioners on whether the PRM should be denied or issued as a Proposed Rule, see the SECY category.

For Commission review of staff recommendations, see the 10CFR category.

#### PROJ - Projects-Predocket Licensing

This category contains records pertaining to two classes of projects: (1) commercial nuclear power plants for which NRC has full licensing responsibilities; and (2) government-owned reactors for which NRC provides technical expertise and occasional review. Both classes are identified with a "P" prefix, followed by a series of numbers.

1. "Pre-docketed" commercial nuclear power plants

This category contains all documentation up until the time that the NRC considers the application and the Preliminary Safety Analysis Report (PSAR) is submitted by the utility for staff review. The unit is then assigned a docket number, and transferred to the Docket 50 category.

These documents are grouped together in categories, designated by alphabetic characters. These are the same categories as those used for the Docket 50 series.

#### A. Application/Construction Stage

- 1. Application submitted by the utility.
- 2. Meeting notices, summaries and correspondence discussing the completeness and adequacy of the PSAR.
- 3. Applicant's Quality Assurance Manual.
- 4. Early site review information.
- 5. Backup technical documents submitted in support of the application.
- 6. Early site visits.

#### B. Utility PSAR and Amendments

- 1. PSARs submitted by the utility.
- 2. Amendments and changes to the PSAR.
- Transmittal letters.
- 4. Letters acknowledging receipt of the PSAR.

#### G. Adjudicatory Correspondence

1. Motions, briefs, orders, et al. pertaining to pre-hearing conferences, if any.

#### M. Antitrust Correspondence

1. Submittals and related material pertaining to the antitrust review.

#### Q. Inspection Reports

- 1. Inspection reports of the applicant's quality assurance program.
- 2. Notices of deviations.
- 3. Follow-up correspondence resolving deviations cited.

#### 2. Government-owned reactors

Meeting summaries and technical correspondence between NRC and other government technical personnel related to test reactors, critical experiments, and DOD reactors on navy ships and other sites.

#### PT21 - Noncompliance Reports and Related Correspondence

Deficiency reports are performed in compliance with Part 21 of Title 10 of the Code of Federal Regulations and include:

- 1. Reports by firms involved in the nuclear industry concerning noncompliance with NRC regulations or the existence of defects which could create a substantial safety hazard.
- Correspondence pertaining to the NRC review of reports to assess the possibility of generic defects.
- 3. NRC inspection reports of defects cited.
- 4. Correspondence specifying appropriate follow-up actions taken by the Agency.

#### QA999 - Quality Assurance Inspections

This category contains inspection reports of vendors' quality assurance programs and follow-up correspondence. Each vendor facility is assigned a docket number and is part of the QA999 series.

Vendors are defined here as companies, both U.S. and foreign, that are engaged in the design or the manufacture of nuclear components for plants licensed by NRC. QA comprises all those planned and systematic actions necessary to provide adequate confidence that a structure, system or component being manufactured will perform satisfactorily once it is put in service. The controlling

criteria are 10 CFR Part 50, Appendix B, vendor QA topical reports, and the PSAR and FSAR submitted by utilities for specific facilities. Documents in this category include:

- 1. NRC inspection reports, conducted on a quarterly or semi-annual basis, of vendor sites. Inspections may cover the design, fabrication, construction and testing of structural systems and components.
- 2. Notices of deviations.
- 3. Vendor corrective actions and other follow-up correspondence associated with the resolution of inspection findings.

#### REGGD - Regulatory Guides

This category contains new and revised regulatory guides issued by the Commission and related correspondence. These guides describe for the industry and the public methods acceptable to the NRC staff for implementing specific parts of the NRC's regulations. They also delineate techniques used by the staff in evaluating specific problems or postulated accidents, or provide guidance to applicants. Included are:

- 1. Federal Register notices announcing the issuance and availability of a proposed regulatory guide.
- 2. Revised or newly issued Regulatory Guides.
- 3. NRC value/impact assessment and industry codes, when applicable, that pertain to the issuance of a specific Regulatory Guide.
- 4. Comments submitted by the nuclear industry and interested members of the public regarding a proposed Regulatory Guide.
- 5. Summary of meetings held in the NRC to discuss proposed Regulatory Guides.

NOTE: For documentation pertaining to other work products and activities of the NRC Office of Standards Development, see the Organization category.

#### RES - Research and Technical Assistance Reports

This category contains reports, generally of an interim nature, submitted by NRC contractors providing research and technical assistance to the Commission. It also includes documentation pertaining to research activities of the Commission. Included are:

- 1. Project description documents.
- 2. Letter reports of accomplishments and data reports; for example,
  - a. model documentation reports
  - b. code documentation reports
  - c. code verification reports
- 3. Pre-test prediction reports.
- 4. "Quick look" reports.
- 5. Informal experimental data reports and post-irradiation examination analyses.
- 6. Conceptual design descriptions.

- 7. Letter reports of foreign travel and site visits by contractors.
- 8. Letter, monthly, quarterly, interim or annual status or progress reports on other research projects contracted for by the NRC.
- Meeting summaries and correspondence dealing with technical matters relating to research and technical assistance contracts.
- 10. Staff Research Information Letters (RILs) transmitting the documented results from completed research programs.

NOTE: For final reports of research conducted by contractors, see also NUREG reports.

#### REVIEW GRP - NRC Research Review Groups

This category contains records pertaining to the activities of NRC Research Review Groups. Such groups provide a broad base of technical expertise to aid management in reviewing research in defined technical areas. They review and comment on research plans and predicted results of major experiments, the validity and applicability of research results, the possible redirection of research projects, new research projects, and priorities within the technical areas covered by the research review group. Documents in this category are:

- 1. Agendas for quarterly review group meetings.
- Summary minutes of review group meetings representing views expressed, including dissenting views.
- 3. Research plans and predicted results of major experiments; presentations by research contractors.
- 4. Comments on meetings from attendees, including representatives from contractors, universities, vendors and other agencies.
- 5. Internal memoranda relating to topics under discussion.

#### RM - Rulemakings

This category contains records pertaining to public hearings held on proposed changes (PRs) to the Commission's regulations. Hearings are instituted at the discretion of the Commission based on the importance and the magnitude of the subject under consideration. Documents in this category include:

- 1. Designations of the presiding officer and any special directions for the conduct of the hearing,
- 2. Notifications of hearing board meetings.
- 3. Petitions, motions, testimony and statements submitted by parties to the hearings.
- 4. Hearing board orders and rulings.
- 5. Technical reports submitted as evidence in the proceeding.
- 6. Reports, if any, of the special board to the Commission regarding a rulemaking proceeding.

#### SECY - Position Papers Before the Commission

This category consists of staff papers prepared for the information or approval of the Commissioners which are assigned a SECY report series code. Included are:

- 1. Commission Action papers, which normally include alternatives and recommendations by the staff on a given issue and require Commission action.
- 2. Consent Calendar items and Policy Session items.

NOTE: For Weekly Information Reports prepared by EDO to the Commissioners providing a summary of key events and items of interest undertaken by staff and program offices, see the NRC Commissioners category.

#### TOPREP - Vendor Reports and Related Correspondence

This category contains topical reports, generally of a technical generic nature, submitted by vendors, and correspondence pertaining to the NRC review of these reports. General vendor related correspondence that is not docket specific is also included in this category.

- 1. Topical reports, dealing with such technical matters as specifications, testing and safety submitted by architect, engineers and other vendors.
- 2. Revisions, modifications and amendments to topical reports.
- 3. Correspondence between NRC and vendors pertaining to the review of submittals,
- 4. Meeting agendas, summaries, minutes and correspondence pertinent to vendor activities, programs, methodologies and design criteria.

NOTE: For reports submitted by utilities that are written by vendors on their behalf and that relate to docketed cases, see the categories for the Docket 50 series.

#### WASTE MGT - Nuclear Waste Management

This category is topical in nature and contains records dealing with the activities of the NRC Division of Waste Management. Each topic has been assigned a number, with the series designated by a WM prefix. These documents deal primarily with NRC's interaction with DOE and its future role in licensing and regulating DOE facilities designed for the disposal of high-level waste in geologic repositories. This category will be enlarged later to include records dealing with low-level waste issues and tasks. The documents in this category are:

- 1. Meeting agenda and minutes of DOE/NRC meetings in which DOE presents information on their geological exploration program to identify sites for nuclear waste repositories.
- Briefings by DOE on research being conducted on spent fuel storage and nuclear waste management.
- 3. Correspondence pertaining to NRC's advisory role in providing DOE with technical assistance in the Waste Isolation Pilot Plan (WIPP) for burial of defense wastes.
- 4. NRC draft staff guides for developing positions on the content and format of environmental reports for geological repositories.

#### XPORTLIC - Export and Import Licenses

This category contains records relating to the issuance of licenses to export or import nuclear facilities and materials. Included are:

- 1. License applications and amendments to export or import special nuclear material, source material, byproduct material, reactors, nuclear facility components or reactor materials.
- 2. Correspondence between NRC and applicant or licensee pertaining to the review or status of a pending application or license amendment.
- 3. Commission letters requesting Executive Branch views.
- 4. Review and findings of the Executive Branch on whether issuance of a license would be inimical to U.S. common defense and security.
- 5. Correspondence from foreign governments, international organizations, and members of the public.
- 6. Staff position papers (SECY series code) prepared for Commissioners review of import or export licenses.
- 7. Filings pursuant to hearing requests or intervention petitions, if any,
- 8. Hearing records and decisions.
- 9. Memoranda from the Office of the Secretary to the Executive Director for Operations regarding the Commission decision on issuance of a proposed license.
- 10. Licenses, license amendments and license renewals for types specified in item 1.

NOTE: For transcripts of Commission meetings and papers submitted for Commissioner consideration or information, see 10CFR category.

BIBLIOGRAPHIC DATA SHEET		NUREG-0540 Vol. 1 No.6			
4. TITLE AND SUBTITLE (Add Volume No., if appropriate)		2 (Leave blank)			
Title List of Documents Made Publicly Availa	ble	3. RECIPIENT'S ACCESSION NO.			
7. AUTHOR(S)		5. DATE REPORT COMPLETED			
		MONTH YEAR			
		August 1979			
9. PERFORMING ORGANIZATION NAME AND MAILING ADDRESS (Inc.	lude Zıp Code)	DATE REPORT ISSUED			
Division of Taskutasi Tufamatian and Danma	mt Comtuol	MONTH YEAR			
Division of Technical Information and Docume	nt control	August 1979			
U.S. Nuclear Regulatory Commission	6. (Leave blank)				
Washington, D.C. 20555		8. (Leave blank)			
12. SPONSORING ORGANIZATION NAME AND MAILING ADDRESS (Inc.	dude Zio Code)				
	add Lip Cods,	10, PROJECT/TASK/WORK UNIT NO			
same as #9		11. CONTRACT NO.			
13. TYPE OF REPORT	PERIOD COVE	RED (Inclusive dates)			
Monthly	June 1	1 - 30, 1979			
15. SUPPLEMENTARY NOTES		14. (Leave blank)			
This document is a monthly publication information received and generated by includes (1) docketed material associplants and other uses of radioactive material received and generated by NR regulatory agency. The docketed informerely issued through U.S. DOE's Tech the title Power Reactor Docket Informore replaces PRDI, which will no longer be Personal Author Index, Corporate Sour	the U.S. NRC ated with cive materials and C pertinent to mation included nical Information (PRDI). e prepared. I	vilian nuclear power I (2) nondocketed To its role as a Hes information for- tion Center under This document t is indexed by a			
17. KEY WORDS AND DOCUMENT ANALYSIS	17a. DESCRIPTO	PRS			
17b. IOENTIFIERS/OPEN-ENDED TERMS					
	19				
18. AVAILABILITY STATEMENT					
Unlimited	20. SECURI	TY CLASS (This page) 22. PHII \$			